

ILLINOIS DEPARTMENT OF PUBLIC HEALTH  
AHERA THREE YEAR REINSPECTION  
ASBESTOS ABATEMENT PROGRAM  
SCHOOL INFORMATION FORM

**SECTION I**

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299  
SCHOOL ID NUMBER: 14-016-2990-2396  
SCHOOL NAME: Pasteur School  
ADDRESS OF SCHOOL: 5825 S. Kostner  
CITY: Chicago, IL, 60629

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **3/29/2013**

**If the address on this form is different than the address of the building, submit a written explanation.**

**SECTION II** (Please type or print)

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 4/11/2016 ENROLLMENT 757  
IDPH INSPECTOR LICENSE NUMBER: 100-00249  
IDPH LICENSED INSPECTOR NAME (Please Print): John Feely  
IDPH MP LICENSE NUMBER: 100-19466  
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Evan Christian

DESIGNATED PERSON (Please Print): Robert Christlieb PHONE: (773) 553-3197



4/11/2016

*Signature of Designated Person*

*Date*

**SECTION III**

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: \_\_\_\_\_

School has been closed. Date closed: \_\_\_\_\_

School building has been demolished. Date: \_\_\_\_\_

School building is asbestos free since last reinspection: \_\_\_\_\_

**Please explain in writing why the school building is now asbestos free and include the supporting documentation.**

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

**Explain in writing if the address of the building is different than the address on this form:**

**THREE-YEAR REINSPECTION**

**CHICAGO SCHOOL DIST 299**

**Pasteur School**

5825 S. Kostner  
Chicago, IL, 60629

Unit: 24851  
Building ID: 5310

IDPH ID Number: 14-016-2990-2396

**REPORT DATE:**

Monday, April 11, 2016

**Prepared for:**

**Chicago Public Schools**  
**125 S. Clark Street**  
**Chicago, IL 60603**

**Prepared by:**

**Carnow, Conibear and Associates**

600 West Van Buren St., Ste 500

Phone (312) 762-2900

Fax (312) 782-5145

**DO NOT REMOVE FROM SCHOOL  
REQUIRED BY FEDERAL LAW**



## **Environmental Notification to Occupants**

To: Faculty, Staff and Parents  
From: Chicago Public Schools  
Date: March 24, 2016

RE: Pasteur School, Unit 24851  
5825 S. Kostner  
Chicago, IL, 60629

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2016 asbestos three year re-inspection has been completed at Pasteur School , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at Pasteur School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Robert Christlieb, the designated Local Education Authority's Designated Person at (773) 553-3197 .

## **Table of Contents**

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

### **APPENDICES:**

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

## SCHOOL AND INSPECTION INFORMATION

### 1. School Information

School: Pasteur School Unit: 24851 Region: 05  
Address: 5825 S. Kostner Chicago, IL, 60629  
IDPH ID: 14-016-2990-2396 Building ID: 5310  
Contact: Rangel, Marcos Phone: 773-269-7105

### 2. Description of Facility

Original Construction: 1996 Additional Construction: 1927,1996,1996  
Total Square Footage: No of Floors:  
Current Occupancy: 757

### 3. LEA Designated Person

Contact: Robert Christlieb Phone: (773) 553-3197  
Address: 125 South Clark Street, 17th Floor  
Chicago, IL 60603

### 4. Managing Environmental Consultant

MEC: Carnow, Conibear and Associates  
Contact: Dan Juneau  
Address 600 West Van Buren St., Ste 500  
Phone: (312) 762-2900 Fax: (312) 782-5145

### 5. Inspector

Inspector Name: John Feely

Inspector IDPH license # 100-00249

Signature:  
Date: 3/24/2016

### 6. Management Planner

Management Planner Name: Evan Christian

Management Planner IDPH license # 100-19466

Signature:  
Date: 04/11/2016

### 7. Review Date: 04/11/2016

### 8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature: 

Date: 4/11/2016

Name: Robert Christlieb

## II. EXECUTIVE SUMMARY

Carnow, Conibear and Associates was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Pasteur School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 5310:

V Pipe fittings

B. The following new homogenous areas have been identified for Building 5310:



C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

T	Mag pipe insulation
003	Plaster
004	Terrazzo
020D	12"x 12" Beige w/Brown Floor Tile
020E	12"x 12" Beige w/Brown Floor Tile
021D	12"x 12" Beige w/Brown Floor Tile Mastic
021E	12"x12" Beige w/Brown Floor Tile Mastic
023A	12x12 offwhite / tan specks ft
023B	12x12 white/ green & white dark green speck ft
023C	12x12 blue ft
023D	12x12 beige speckled ft
024B	Linoleum
024C	Linoleum
025B	Linoleum Adhesive
025C	Linoleum Adhesive
028	12x12 white floor tile
029	2'x4' Pinhole and Fissure Ceiling Tile
030	Insulation in Fire Doors
031	Insulation in Fire Doors
033	Rolled Flooring
034	Rolled Flooring Adhesive
035	12"x12" Beige Floor Tile
B	12" x 12" blue floor tile part of pattern
C	12" x 12" light blue floor tile part of pattern
D	12" x 12" pink floor tile part of pattern
E	12" x 12" gray floor tile part of pattern
F	2' x 2' ceiling tile
G	Drywall
G-2	Drywall
G-2A	Drywall Compound
G-3	Drywall
G-3A	Drywall Comound
G-4	Drywall
G-4A	Drywall Compound
G-5	Drywall
G-5A	Drywall Compound
H	Floor tile mastic
I	Gray base board
I-2	Light Brown Baseboard
I-3	Lightr Brown Baseboard
J	Gray base board mastic
J-2	Light Brown Baseboard Adhesive

J-3	Light Brown Baseboard Adhesive
K	Drywall joint compound
L	12" x 12" vft, cream speck
L-2	12"x12" Beige Floor Tile
M	mastic beneath 12" x 12" vft, cream speck
M-1	12"x12" Beige Floor tile Adhesive
M-2	12"x12" Beige Floor Tile Adhesive
N	Cream texture transite texture wall
O-1	4' x 8' textured ceiling panels
P-1	Cream base board
Q-1	cream base board mastic
R	Aircell pipe insulation
S	Cementitious Pipe Joint Insulation
W	Chalkboard
X	Chalkboard Adhesive
Y	Chalkboard
Z	Chalkboard Adhesive

The following areas were deemed to be inaccessible:

021A	mastic beneath 9"x9" vft, orange
021B	9x9 dark brown ft mastic
021C	mastic beneath 9"x9" vft, tan
021D	12" x 12" Beige w/Brown Floor Tile Mastic
021E	12"x12" Beige w/Brown Floor Tile Mastic
022A	mastic beneath 12"x12" vft, off-white/tan streaks
022B	12x12 white/green & dark green specks ft mastic
022C	12x12 blue ft mastic
022D	12x12 beige ft mastic
025B	Linoleum Adhesive
025C	Linoleum Adhesive
026	gray carpet mastic
027	green carpet mastic
030	Insulation in Fire Doors
031	Insulation in Fire Doors
034	Rolled Flooring Adhesive
J-2	Light Brown Baseboard Adhesive
J-3	Light Brown Baseboard Adhesive
M-1	12"x12" Beige Floor tile Adhesive
M-2	12"x12" Beige Floor Tile Adhesive
X	Chalkboard Adhesive
Z	Chalkboard Adhesive

Materials were also listed as "assumed" if they were in good condition and sampling was not

conducted to avoid damage.

This reinspection was conducted by John Feely, IDPH License # 100-00249. The Management Plan was updated by Evan Christian, IDPH License # 100-19466. Inspector and Management Planner Licenses are included in Appendix B.

### **III. METHODOLOGY**

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

### **IV. ABATEMENT HISTORY**

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

### **V. REASSESSMENTS AND RECOMMENDATIONS**

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

### **VI. CONCLUSIONS**

The Pasteur School Building 5310 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

**Table I**  
**Inspector's Reinspection Findings**

---

# Chicago Public Schools

School Pasteur School Unit 24851 Building ID 5310

Address 5825 S. Kostner Region 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
A	12 X 12 Cream Floor Tile- abated			Throughout Annex	ABATED	MISC								
T	Mag pipe insulation	100	LF	Boiler room and tunnels	ASSUMED	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
001	Acoustical Wall Plaster			Auditorium	NO ACBM	SURFACE		None						
002	Plaster Walls and Ceilings			Throughout Facility	NO ACBM	SURFACE								High
003	Plaster	400	SF	Engineer Office and Washrooms in Boiler House	ASSUMED	SURFACE	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
004	Terrazzo	1,900	SF	Throughout Corridors, Stairways, Janitor Closets, 114B, 208	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
020A	9"x9" vft, orange speckled	720	SF	room 120	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
020B	9x9 dark brown ft	100	SF	engineers office & toilet	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
020C	9"x9" vft, tan	150	SF	main office, storage room	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
020D	12"x 12" Beige w/Brown Floor Tile	1,564	SF	501/502	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
020E	12"x 12" Beige w/Brown Floor Tile	1,564	SF	503/504	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
021A	mastic beneath 9"x9" vft, orange	720	SF	room 120	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
021B	9x9 dark brown ft mastic	100	SF	engineers office & toilet	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
021C	mastic beneath 9"x9" vft, tan	150	SF	main office, storage room	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
021D	12"x 12" Beige w/Brown Floor Tile Mastic	1,564	SF	501/502	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
021E	12"x12" Beige w/Brown Floor Tile Mastic	1,564	SF	503/504	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
022A	mastic beneath 12"x12" vft, off-white/tan streaks	15,925	SF	1st&2nd fl corridors, rooms: 112, 114, 116, 117, 118, 210, 212, 213, 216, 217, 219, 220	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
022B	12x12 white/green & dark green specks ft mastic	3,870	SF	main office, lunchroom, rooms 108, 215, 218	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
022C	12x12 blue ft mastic	2,640	SF	rooms 110, 224, 222, 211	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
022D	12x12 beige ft mastic	40	SF	storage room in	CHR	MISC	N	NONE	0		No	ACBM with the		LOW

# Chicago Public Schools

School Pasteur School Unit 24851 Building ID 5310

Address 5825 S. Kostner Region 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				lunch room								potential for damage		
023A	12x12 offwhite / tan specks ft	15,925	SF	1st&2nd fl corridors, rooms: 112, 114, 116, 117, 118, 210, 212, 213, 216, 217, 219, 220	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
023B	12x12 white/ green & white dark green speck ft	3,170	SF	main office, lunchroom, rooms 108, 215, 218	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
023C	12x12 blue ft	2,640	SF	rooms 110, 224, 222, 211	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
023D	12x12 beige speckled ft	40	SF	storage room in lunchroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
024	linoleum, brown			auditorium under seating on 1st floor	ABATED	MISC		None						Low
024B	Linoleum	238	SF	501/502	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
024C	Linoleum	238	SF	503/504 Washroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
025	linoleum mastic			auditorium under seating area on 1st floor	ABATED	MISC		None						
025B	Linoleum Adhesive	238	SF	501/502 Washroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
025C	Linoleum Adhesive	238	SF	503/504 Washroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
026	gray carpet mastic	1,626	SF	main office, library, room 214	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
027	green carpet mastic	730	SF	room 114, teachers lounge, 2nd floor mens teacher toilet	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
028	12x12 white floor tile	12,720	SF	Annex, 120, main office, storage room, eng. office and toilet, lunchroom...	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
029	2'x4' Pinhole and Fissure Ceiling Tile	82,000	SF	All classrooms, offices and corridors	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
030	Insulation in Fire Doors	84	SF	501/502	ASSUMED	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
031	Insulation in Fire Doors	84	SF	503/504	ASSUMED	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW

# Chicago Public Schools

School Pasteur School Unit 24851 Building ID 5310

Address 5825 S. Kostner Region 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
032	Aircell Pipe Insulation	40	LF	Room 108 Storage Access-South	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
033	Rolled Flooring	728	SF	Annex Washroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
034	Rolled Flooring Adhesive	728	SF	Annex Washroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
035	12"x12" Beige Floor Tile	600	SF	401/402 Modular Unit	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
B	12" x 12" blue floor tile part of pattern	10	SF	Annex	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
C	12" x 12" light blue floor tile part of pattern	10	SF	Annex	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
D	12" x 12" pink floor tile part of pattern	10	SF	Annex	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
E	12" x 12" gray floor tile part of pattern				ASSUMED	MISC		None						Low
F	2' x 2' ceiling tile	13,500	SF	Throughout annex	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
G	Drywall	350	SF	On all interior new load bearing walls	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
G-2	Drywall	1,319	SF	401/402	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
G-2A	Drywall Compound	1,319	SF	401/402	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
G-3	Drywall	1,319	SF	403/404	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
G-3A	Drywall Comound	1,319	SF	403/404	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
G-4	Drywall	1,319	SF	501/502	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
G-4A	Drywall Compound	1,319	SF	501/502	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
G-5	Drywall	1,319	SF	503/504	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
G-5A	Drywall Compound	1,319	SF	503/504	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
H	Floor tile mastic	13,500	SF	Throughout annex	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
I	Gray base board	1,600	SF	Throughout annex	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
I-2	Light Brown Baseboard	306	LF	501/502	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
I-3	Light Brown Baseboard	306	LF	503/504	ASSUMED	MISC	N	NONE	0		No	ACBM with the		LOW



# Chicago Public Schools

School Pasteur School Unit 24851 Building ID 5310

Address 5825 S. Kostner Region 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
												potential for damage		
J	Gray base board mastic	1,600	SF	Throughout annex	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
J-2	Light Brown Baseboard Adhesive	306	LF	501/502	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
J-3	Light Brown Baseboard Adhesive	306	LF	503/504	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
K	Drywall joint compound	350	SF	Throughout annex	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
L	12" x 12" vft, cream speck	1,200	SF	throughout N & S modulars	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
L-2	12"x12" Beige Floor Tile	600	SF	403/404 Modular Unit	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
M	mastic beneath 12" x 12" vft, cream speck	1,200	SF	Throughout N & S modulars	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
M-1	12"x12" Beige Floor tile Adhesive	600	SF	401/402 Modular Unit	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
M-2	12"x12" Beige Floor Tile Adhesive	600	SF	403/404 Modular Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
N	Cream texture transite texture wall	960	SF	Throughout North modulars	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
O-1	4' x 8' textured ceiling panels	1,200	SF	Throughout North and South modulars	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
P-1	Cream base board	160	LF	Throughout North & South modulars	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
Q-1	cream base board mastic	160	LF	Throughout North & South modulars	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
R	Aircell pipe insulation	1,660	LF	Boiler room and tunnels	ASSUMED	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
S	Cementitious Pipe Joint Insulation	150	LF	Boiler room and tunnels	ASSUMED	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
U	Boiler tank jacket	2,400	SF	boiler room	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
V	Pipe fittings	100	LF	Pipe Chases in Bathrooms	CHR	TSI	Y	NONE	0		Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
W	Chalkboard	104	SF	401/402	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
X	Chalkboard Adhesive	104	SF	401/402	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
Y	Chalkboard	104	SF	403/404	ASSUMED	MISC	N	NONE	0		No	ACBM with the		LOW

# Chicago Public Schools

School Pasteur School Unit 24851 Building ID 5310

Address 5825 S. Kostner Region 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

---

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
Z	Chalkboard Adhesive	104	SF	403/404	ASSUMED	MISC	N	NONE	0		No	potential for damage ACBM with the potential for damage		LOW

# Chicago Public Schools

School Pasteur School Unit 24851 Building ID 5310

Address 5825 S. Kostner Region 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

Reinspection Date <b>3/24/2016</b>
Inspector Name <b>John Feely</b>
<b>100-00249</b> <b>5/15/2016</b>
Inspector's IDPH License Number / Expiration Date

### Inspector's Comments

HA Number:	Inspector Comments:
A	
T	
001	
002	
003	
004	
020A	
020B	
020C	
020D	
020E	
021A	
021B	
021C	
021D	
021E	
022A	
022B	
022C	
022D	
023A	
023B	
023C	
023D	

# Chicago Public Schools

School Pasteur School Unit 24851 Building ID 5310

Address 5825 S. Kostner Region 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
024	
024B	
024C	
025	
025B	
025C	
026	
027	
028	
029	
030	
031	
032	
033	
034	
035	
B	
C	
D	
E	Not observed 2016
F	
G	
G-2	
G-2A	
G-3	
G-3A	
G-4	
G-4A	
G-5	

# Chicago Public Schools

School Pasteur School Unit 24851 Building ID 5310

Address 5825 S. Kostner Region 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
G-5A	
H	
I	
I-2	
I-3	
J	
J-2	
J-3	
K	
L	
L-2	
M	
M-1	
M-2	
N	
O-1	
P-1	
Q-1	
R	
S	
U	
V	
W	
X	
Y	
Z	

# Chicago Public Schools

School Pasteur School Unit 24851 Building ID 5310

Address 5825 S. Kostner Region 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

---

**Table II**

**Management Planner's Review**

---

# Chicago Public Schools

School Pasteur School  
Address 5825 S. Kostner

Unit 24851  
Chicago, IL, 60629

Building ID 5310  
Region 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
A	12 X 12 Cream Floor Tile- abated			Throughout Annex	Abated						
T	Mag pipe insulation	100	LF	Boiler room and tunnels	Assumed	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
001	Acoustical Wall Plaster			Auditorium	No ACBM	SURFACE					
002	Plaster Walls and Ceilings			Throughout Facility	No ACBM	SURFACE					
003	Plaster	400	SF	Engineer Office and Washrooms in Boiler House	Assumed	SURFACE	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
004	Terrazzo	1,900	SF	Throughout Corridors, Stairways, Janitor Closets, 114B, 208	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
020A	9"x9" vft, orange speckled	720	SF	room 120	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
020B	9x9 dark brown ft	100	SF	engineers office & toilet	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
020C	9"x9" vft, tan	150	SF	main office, storage room	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
020D	12"x 12" Beige w/Brown Floor Tile	1,564	SF	501/502	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
020E	12"x 12" Beige w/Brown Floor Tile	1,564	SF	503/504	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
021A	mastic beneath 9"x9" vft, orange	720	SF	room 120	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
021B	9x9 dark brown ft mastic	100	SF	engineers office & toilet	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
021C	mastic beneath 9"x9" vft, tan	150	SF	main office, storage room	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
021D	12"x 12" Beige w/Brown Floor Tile Mastic	1,564	SF	501/502	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
021E	12"x12" Beige w/Brown Floor Tile Mastic	1,564	SF	503/504	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
022A	mastic beneath 12"x12" vft, off-white/tan streaks	15,925	SF	1st&2nd fl corridors, rooms: 112, 114, 116, 117, 118, 210, 212, 213, 216, 217, 219, 220	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
022B	12x12 white/green & dark green specks ft mastic	3,870	SF	main office, lunchroom, rooms 108, 215, 218	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
022C	12x12 blue ft mastic	2,640	SF	rooms 110, 224, 222, 211	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
022D	12x12 beige ft mastic	40	SF	storage room in lunch room	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
023A	12x12 offwhite / tan specks ft	15,925	SF	1st&2nd fl corridors, rooms: 112, 114, 116, 117, 118, 210, 212, 213, 216, 217, 219, 220	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
023B	12x12 white/ green & white dark green speck ft	3,170	SF	main office, lunchroom, rooms 108, 215, 218	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
023C	12x12 blue ft	2,640	SF	rooms 110, 224, 222, 211	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
023D	12x12 beige speckled ft	40	SF	storage room in lunchroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
024	linoleum, brown			auditorium under seating on 1st floor	Abated	MISC					
024B	Linoleum	238	SF	501/502	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan



# Chicago Public Schools

School Pasteur School  
Address 5825 S. Kostner

Unit 24851  
Chicago, IL, 60629

Building ID 5310  
Region 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
024C	Linoleum	238	SF	503/504 Washroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
025	linoleum mastic			auditorium under seating area on 1st floor	Abated	MISC					
025B	Linoleum Adhesive	238	SF	501/502 Washroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
025C	Linoleum Adhesive	238	SF	503/504 Washroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
026	gray carpet mastic	1,626	SF	main office, library, room 214	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
027	green carpet mastic	730	SF	room 114, teachers lounge, 2nd floor mens teacher toilet	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
028	12x12 white floor tile	12,720	SF	Annex, 120, main office, storage room, eng. office and toilet, lunchroom...	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
029	2'x4' Pinhole and Fissure Ceiling Tile	82,000	SF	All classrooms, offices and corridors	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
030	Insulation in Fire Doors	84	SF	501/502	Assumed	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
031	Insulation in Fire Doors	84	SF	503/504	Assumed	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
032	Aircell Pipe Insulation	40	LF	Room 108 Storage Access-South	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
033	Rolled Flooring	728	SF	Annex Washroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
034	Rolled Flooring Adhesive	728	SF	Annex Washroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
035	12"x12" Beige Floor Tile	600	SF	401/402 Modular Unit	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
B	12" x 12" blue floor tile part of pattern	10	SF	Annex	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
C	12" x 12" light blue floor tile part of pattern	10	SF	Annex	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
D	12" x 12" pink floor tile part of pattern	10	SF	Annex	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
E	12" x 12" gray floor tile part of pattern				Assumed	MISC					Follow O&M Plan
F	2' x 2' ceiling tile	13,500	SF	Throughout annex	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
G	Drywall	350	SF	On all interior new load bearing walls	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
G-2	Drywall	1,319	SF	401/402	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
G-2A	Drywall Compound	1,319	SF	401/402	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
G-3	Drywall	1,319	SF	403/404	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
G-3A	Drywall Compound	1,319	SF	403/404	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
G-4	Drywall	1,319	SF	501/502	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
G-4A	Drywall Compound	1,319	SF	501/502	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
G-5	Drywall	1,319	SF	503/504	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Pasteur School  
**Address** 5825 S. Kostner

**Unit** 24851  
Chicago, IL, 60629

**Building ID** 5310  
**Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
G-5A	Drywall Compound	1,319	SF	503/504	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
H	Floor tile mastic	13,500	SF	Throughout annex	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
I	Gray base board	1,600	SF	Throughout annex	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
I-2	Light Brown Baseboard	306	LF	501/502	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
I-3	Lightr Brown Baseboard	306	LF	503/504	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
J	Gray base board mastic	1,600	SF	Throughout annex	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
J-2	Light Brown Baseboard Adhesive	306	LF	501/502	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
J-3	Light Brown Baseboard Adhesive	306	LF	503/504	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
K	Drywall joint compound	350	SF	Throughout annex	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
L	12" x 12" vft, cream speck	1,200	SF	throughout N & S modulars	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
L-2	12"x12" Beige Floor Tile	600	SF	403/404 Modular Unit	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
M	mastic beneath 12" x 12" vft, cream speck	1,200	SF	Throughout N & S modulars	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
M-1	12"x12" Beige Floor tile Adhesive	600	SF	401/402 Modular Unit	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
M-2	12"x12" Beige Floor Tile Adhesive	600	SF	403/404 Modular Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
N	Cream texture transite texture wall	960	SF	Throughout North modulars	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
O-1	4' x 8' textured ceiling panels	1,200	SF	Throughout North and South modulars	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
P-1	Cream base board	160	LF	Throughout North & South modulars	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
Q-1	cream base board mastic	160	LF	Throughout North & South modulars	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
R	Aircell pipe insulation	1,660	LF	Boiler room and tunnels	Assumed	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
S	Cementitious Pipe Joint Insulation	150	LF	Boiler room and tunnels	Assumed	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
U	Boiler tank jacket	2,400	SF	boiler room	Chrysotile	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
V	Pipe fittings	100	LF	Pipe Chases in Bathrooms	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
W	Chalkboard	104	SF	401/402	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
X	Chalkboard Adhesive	104	SF	401/402	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
Y	Chalkboard	104	SF	403/404	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
Z	Chalkboard Adhesive	104	SF	403/404	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Pasteur School  
**Address** 5825 S. Kostner

**Unit** 24851  
 Chicago, IL, 60629

**Building ID** 5310  
**Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

*Management Planner's Comments Summarized at the End of the Report*

Review Date	4/11/2016
Manager Planner Name	Evan Christian
100-19466	5/15/2016
Manager IDPH License No/Expiration	

HA Number	Management Comments
A	If identified follow O&M plan.
T	
001	
002	
003	
004	
020A	
020B	
020C	
020D	
020E	

# Chicago Public Schools

**School** Pasteur School  
**Address** 5825 S. Kostner

**Unit** 24851  
 Chicago, IL, 60629

**Building ID** 5310  
**Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
021A	
021B	
021C	
021D	
021E	
022A	
022B	
022C	
022D	
023A	
023B	
023C	
023D	
024	If identified follow O&M plan.
024B	
024C	
025	If identified follow O&M plan.
025B	
025C	
026	
027	
028	
029	
030	
031	
032	
033	

# Chicago Public Schools

**School** Pasteur School  
**Address** 5825 S. Kostner

**Unit** 24851  
 Chicago, IL, 60629

**Building ID** 5310  
**Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
034	
035	
B	
C	
D	
E	If identified follow O&M plan.
F	
G	
G-2	
G-2A	
G-3	
G-3A	
G-4	
G-4A	
G-5	
G-5A	
H	
I	
I-2	
I-3	
J	
J-2	
J-3	
K	
L	
L-2	
M	

# Chicago Public Schools

**School** Pasteur School

**Unit** 24851

**Building ID** 5310

**Address** 5825 S. Kostner

Chicago, IL, 60629

**Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
M-1	
M-2	
N	
O-1	
P-1	
Q-1	
R	
S	
U	
V	
W	
X	
Y	
Z	

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**  
SCHOOL NAME: **Pasteur School** INSPECTION DATE: **3/24/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **A**  
MATERIAL DESCRIPTION: **12 X 12 Cream Floor Tile- abated**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Annex**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **03/24/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Pasteur School** REVIEW DATE: **4/11/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

HOMOGENEOUS AREA: **A**

MATERIAL DESCRIPTION: **12 X 12 Cream Floor Tile- abated**

MATERIAL LOCATION: **Throughout Annex**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

If identified follow O&M plan.

Management Planner's Signature: \_\_\_\_\_ Date: **04/11/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**  
SCHOOL NAME: **Pasteur School** INSPECTION DATE: **3/24/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **T**  
MATERIAL DESCRIPTION: **Mag pipe insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Boiler room and tunnels**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 03/24/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Pasteur School** REVIEW DATE: **4/11/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

HOMOGENEOUS AREA: **T**  
MATERIAL DESCRIPTION: **Mag pipe insulation**  
MATERIAL LOCATION: **Boiler room and tunnels**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/11/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**  
SCHOOL NAME: **Pasteur School** INSPECTION DATE: **3/24/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **001**  
MATERIAL DESCRIPTION: **Acoustical Wall Plaster**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Auditorium**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **03/24/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Pasteur School** REVIEW DATE: **4/11/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

HOMOGENEOUS AREA: **001**

MATERIAL DESCRIPTION: **Acoustical Wall Plaster**

MATERIAL LOCATION: **Auditorium**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/11/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**  
SCHOOL NAME: **Pasteur School** INSPECTION DATE: **3/24/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **002**  
MATERIAL DESCRIPTION: **Plaster Walls and Ceilings**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **High**

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **03/24/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Pasteur School** REVIEW DATE: **4/11/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

HOMOGENEOUS AREA: **002**

MATERIAL DESCRIPTION: **Plaster Walls and Ceilings**

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/11/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**  
SCHOOL NAME: **Pasteur School** INSPECTION DATE: **3/24/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **003**  
MATERIAL DESCRIPTION: **Plaster**  
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Engineer Office and Washrooms in Boiler House**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 03/24/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Pasteur School** REVIEW DATE: **4/11/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

HOMOGENEOUS AREA: **003**  
MATERIAL DESCRIPTION: **Plaster**  
MATERIAL LOCATION: **Engineer Office and Washrooms in Boiler House**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/11/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **24851**    BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **John Feely**  
SCHOOL NAME: **Pasteur School**    INSPECTION DATE: **3/24/2016**  
ADDRESS: **5825 S. Kostner**    IDPH LICENSE NO: **100-00249**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **004**  
MATERIAL DESCRIPTION: **Terrazzo**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout Corridors, Stairways, Janitor Closets, 114B, 208**  
MATERIAL QUANTITY: **1900**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY:    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 03/24/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Pasteur School** REVIEW DATE: **4/11/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

HOMOGENEOUS AREA: **004**  
MATERIAL DESCRIPTION: **Terrazzo**  
MATERIAL LOCATION: **Throughout Corridors, Stairways, Janitor Closets, 114B, 208**  
MATERIAL QUANTITY: **1900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/11/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**  
SCHOOL NAME: **Pasteur School** INSPECTION DATE: **3/24/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **020A**  
MATERIAL DESCRIPTION: **9"x9" vft, orange speckled**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **room 120**

MATERIAL QUANTITY: **720**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 03/24/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Pasteur School** REVIEW DATE: **4/11/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

HOMOGENEOUS AREA: **020A**

MATERIAL DESCRIPTION: **9"x9" vft, orange speckled**

MATERIAL LOCATION: **room 120**

MATERIAL QUANTITY: **720**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/11/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**  
SCHOOL NAME: **Pasteur School** INSPECTION DATE: **3/24/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **020B**  
MATERIAL DESCRIPTION: **9x9 dark brown ft**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **engineers office & toilet**

MATERIAL QUANTITY: **100**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 03/24/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Pasteur School** REVIEW DATE: **4/11/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

HOMOGENEOUS AREA: **020B**  
MATERIAL DESCRIPTION: **9x9 dark brown ft**  
MATERIAL LOCATION: **engineers office & toilet**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/11/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**  
SCHOOL NAME: **Pasteur School** INSPECTION DATE: **3/24/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **020C**  
MATERIAL DESCRIPTION: **9"x9" vft, tan**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **main office, storage room**

MATERIAL QUANTITY: **150**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 03/24/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Pasteur School** REVIEW DATE: **4/11/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

HOMOGENEOUS AREA: **020C**  
MATERIAL DESCRIPTION: **9"x9" vft, tan**  
MATERIAL LOCATION: **main office, storage room**  
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/11/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**  
SCHOOL NAME: **Pasteur School** INSPECTION DATE: **3/24/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **020D**  
MATERIAL DESCRIPTION: **12"x 12" Beige w/Brown Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **501/502**  
MATERIAL QUANTITY: **1564** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 03/24/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Pasteur School** REVIEW DATE: **4/11/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

HOMOGENEOUS AREA: **020D**

MATERIAL DESCRIPTION: **12"x 12" Beige w/Brown Floor Tile**

MATERIAL LOCATION: **501/502**

MATERIAL QUANTITY: **1564**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/11/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**  
SCHOOL NAME: **Pasteur School** INSPECTION DATE: **3/24/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **020E**  
MATERIAL DESCRIPTION: **12"x 12" Beige w/Brown Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **503/504**  
MATERIAL QUANTITY: **1564** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 03/24/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Pasteur School** REVIEW DATE: **4/11/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

HOMOGENEOUS AREA: **020E**

MATERIAL DESCRIPTION: **12"x 12" Beige w/Brown Floor Tile**

MATERIAL LOCATION: **503/504**

MATERIAL QUANTITY: **1564**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/11/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**  
SCHOOL NAME: **Pasteur School** INSPECTION DATE: **3/24/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **021A**  
MATERIAL DESCRIPTION: **mastic beneath 9"x9" vft, orange**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **room 120**

MATERIAL QUANTITY: **720**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 03/24/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Pasteur School** REVIEW DATE: **4/11/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

HOMOGENEOUS AREA: **021A**

MATERIAL DESCRIPTION: **mastic beneath 9"x9" vft, orange**

MATERIAL LOCATION: **room 120**

MATERIAL QUANTITY: **720**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/11/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**  
SCHOOL NAME: **Pasteur School** INSPECTION DATE: **3/24/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **021B**  
MATERIAL DESCRIPTION: **9x9 dark bown ft mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **engineers office & toilet**

MATERIAL QUANTITY: **100**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 03/24/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Pasteur School** REVIEW DATE: **4/11/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

HOMOGENEOUS AREA: **021B**  
MATERIAL DESCRIPTION: **9x9 dark bown ft mastic**  
MATERIAL LOCATION: **engineers office & toilet**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/11/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**  
SCHOOL NAME: **Pasteur School** INSPECTION DATE: **3/24/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **021C**  
MATERIAL DESCRIPTION: **mastic beneath 9"x9" vft, tan**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **main office, storage room**

MATERIAL QUANTITY: **150**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 03/24/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Pasteur School** REVIEW DATE: **4/11/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

HOMOGENEOUS AREA: **021C**

MATERIAL DESCRIPTION: **mastic beneath 9"x9" vft, tan**

MATERIAL LOCATION: **main office, storage room**

MATERIAL QUANTITY: **150**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/11/2016**

# Chicago Public Schools

## Carnow, Conibear and Associates 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**  
SCHOOL NAME: **Pasteur School** INSPECTION DATE: **3/24/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **021D**  
MATERIAL DESCRIPTION: **12"x 12" Beige w/Brown Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **501/502**  
MATERIAL QUANTITY: **1564** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 03/24/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Pasteur School** REVIEW DATE: **4/11/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

HOMOGENEOUS AREA: **021D**  
MATERIAL DESCRIPTION: **12"x 12" Beige w/Brown Floor Tile Mastic**  
MATERIAL LOCATION: **501/502**  
MATERIAL QUANTITY: **1564** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/11/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**  
SCHOOL NAME: **Pasteur School** INSPECTION DATE: **3/24/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **021E**  
MATERIAL DESCRIPTION: **12"x12" Beige w/Brown Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **503/504**  
MATERIAL QUANTITY: **1564** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 03/24/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Pasteur School** REVIEW DATE: **4/11/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

HOMOGENEOUS AREA: **021E**  
MATERIAL DESCRIPTION: **12"x12" Beige w/Brown Floor Tile Mastic**  
MATERIAL LOCATION: **503/504**  
MATERIAL QUANTITY: **1564** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/11/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**  
SCHOOL NAME: **Pasteur School** INSPECTION DATE: **3/24/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **022A**  
MATERIAL DESCRIPTION: **mastic beneath 12"x12" vft, off-white/tan streaks**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st&2nd fl corridors, rooms: 112, 114, 116, 117, 118, 210, 212, 213, 216, 217, 219, 220**

MATERIAL QUANTITY: **15925** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **03/24/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Pasteur School** REVIEW DATE: **4/11/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

HOMOGENEOUS AREA: **022A**  
MATERIAL DESCRIPTION: **mastic beneath 12"x12" vft, off-white/tan streaks**  
MATERIAL LOCATION: **1st&2nd fl corridors, rooms: 112, 114, 116, 117, 118, 210, 212, 213, 216, 217, 219, 220**  
MATERIAL QUANTITY: **15925** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/11/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**  
SCHOOL NAME: **Pasteur School** INSPECTION DATE: **3/24/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **022B**  
MATERIAL DESCRIPTION: **12x12 white/green & dark green specks ft mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **main office, lunchroom, rooms 108, 215, 218**

MATERIAL QUANTITY: **3870**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 03/24/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Pasteur School** REVIEW DATE: **4/11/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

HOMOGENEOUS AREA: **022B**  
MATERIAL DESCRIPTION: **12x12 white/green & dark green specks ft mastic**  
MATERIAL LOCATION: **main office, lunchroom, rooms 108, 215, 218**  
MATERIAL QUANTITY: **3870** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/11/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**  
SCHOOL NAME: **Pasteur School** INSPECTION DATE: **3/24/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **022C**  
MATERIAL DESCRIPTION: **12x12 blue ft mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **rooms 110, 224, 222, 211**  
MATERIAL QUANTITY: **2640** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 03/24/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Pasteur School** REVIEW DATE: **4/11/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

HOMOGENEOUS AREA: **022C**  
MATERIAL DESCRIPTION: **12x12 blue ft mastic**  
MATERIAL LOCATION: **rooms 110, 224, 222, 211**  
MATERIAL QUANTITY: **2640** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/11/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**  
SCHOOL NAME: **Pasteur School** INSPECTION DATE: **3/24/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **022D**  
MATERIAL DESCRIPTION: **12x12 beige ft mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **storage room in lunch room**

MATERIAL QUANTITY: **40**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 03/24/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Pasteur School** REVIEW DATE: **4/11/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

HOMOGENEOUS AREA: **022D**  
MATERIAL DESCRIPTION: **12x12 beige ft mastic**  
MATERIAL LOCATION: **storage room in lunch room**  
MATERIAL QUANTITY: **40** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/11/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **24851**    BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **John Feely**  
SCHOOL NAME: **Pasteur School**    INSPECTION DATE: **3/24/2016**  
ADDRESS: **5825 S. Kostner**    IDPH LICENSE NO: **100-00249**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **023A**  
MATERIAL DESCRIPTION: **12x12 offwhite / tan specks ft**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st&2nd fl corridors, rooms: 112, 114, 116, 117, 118, 210, 212, 213, 216, 217, 219, 220**

MATERIAL QUANTITY: **15925**    MATERIAL UNITS: **SF**

DAMAGE QUANTITY:    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **03/24/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Pasteur School** REVIEW DATE: **4/11/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

HOMOGENEOUS AREA: **023A**  
MATERIAL DESCRIPTION: **12x12 offwhite / tan specks ft**  
MATERIAL LOCATION: **1st&2nd fl corridors, rooms: 112, 114, 116, 117, 118, 210, 212, 213, 216, 217, 219, 220**  
MATERIAL QUANTITY: **15925** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/11/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**  
SCHOOL NAME: **Pasteur School** INSPECTION DATE: **3/24/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **023B**  
MATERIAL DESCRIPTION: **12x12 white/ green & white dark green speck ft**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **main office, lunchroom, rooms 108, 215, 218**

MATERIAL QUANTITY: **3170**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 03/24/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Pasteur School** REVIEW DATE: **4/11/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

HOMOGENEOUS AREA: **023B**  
MATERIAL DESCRIPTION: **12x12 white/ green & white dark green speck ft**  
MATERIAL LOCATION: **main office, lunchroom, rooms 108, 215, 218**  
MATERIAL QUANTITY: **3170** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/11/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**  
SCHOOL NAME: **Pasteur School** INSPECTION DATE: **3/24/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **023C**  
MATERIAL DESCRIPTION: **12x12 blue ft**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **rooms 110, 224, 222, 211**  
MATERIAL QUANTITY: **2640** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 03/24/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Pasteur School** REVIEW DATE: **4/11/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

HOMOGENEOUS AREA: **023C**  
MATERIAL DESCRIPTION: **12x12 blue ft**  
MATERIAL LOCATION: **rooms 110, 224, 222, 211**  
MATERIAL QUANTITY: **2640** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/11/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**  
SCHOOL NAME: **Pasteur School** INSPECTION DATE: **3/24/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **023D**  
MATERIAL DESCRIPTION: **12x12 beige speckled ft**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **storage room in lunchroom**

MATERIAL QUANTITY: **40**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 03/24/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Pasteur School** REVIEW DATE: **4/11/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

HOMOGENEOUS AREA: **023D**  
MATERIAL DESCRIPTION: **12x12 beige speckled ft**  
MATERIAL LOCATION: **storage room in lunchroom**  
MATERIAL QUANTITY: **40** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/11/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **24851**    BUILDING ID: **5310**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **John Feely**  
SCHOOL NAME: **Pasteur School**    INSPECTION DATE: **3/24/2016**  
ADDRESS: **5825 S. Kostner**    IDPH LICENSE NO: **100-00249**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **024**  
MATERIAL DESCRIPTION: **linoleum, brown**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated**    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **auditorium under seating on 1st floor**

MATERIAL QUANTITY:    MATERIAL UNITS:

DAMAGE QUANTITY:    DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **03/24/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Pasteur School** REVIEW DATE: **4/11/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

HOMOGENEOUS AREA: **024**  
MATERIAL DESCRIPTION: **linoleum, brown**  
MATERIAL LOCATION: **auditorium under seating on 1st floor**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

If identified follow O&M plan.

Management Planner's Signature: \_\_\_\_\_ Date: **04/11/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **24851**    BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **John Feely**  
SCHOOL NAME: **Pasteur School**    INSPECTION DATE: **3/24/2016**  
ADDRESS: **5825 S. Kostner**    IDPH LICENSE NO: **100-00249**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **024B**  
MATERIAL DESCRIPTION: **Linoleum**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **501/502**  
MATERIAL QUANTITY: **238**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY:    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 03/24/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Pasteur School** REVIEW DATE: **4/11/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

HOMOGENEOUS AREA: **024B**

MATERIAL DESCRIPTION: **Linoleum**

MATERIAL LOCATION: **501/502**

MATERIAL QUANTITY: **238**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/11/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**  
SCHOOL NAME: **Pasteur School** INSPECTION DATE: **3/24/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **024C**  
MATERIAL DESCRIPTION: **Linoleum**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **503/504 Washroom**  
MATERIAL QUANTITY: **238** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 03/24/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Pasteur School** REVIEW DATE: **4/11/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

HOMOGENEOUS AREA: **024C**  
MATERIAL DESCRIPTION: **Linoleum**  
MATERIAL LOCATION: **503/504 Washroom**  
MATERIAL QUANTITY: **238** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/11/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**  
SCHOOL NAME: **Pasteur School** INSPECTION DATE: **3/24/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **025**  
MATERIAL DESCRIPTION: **linoleum mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **auditorium under seating area on 1st floor**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **03/24/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Pasteur School** REVIEW DATE: **4/11/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

HOMOGENEOUS AREA: **025**  
MATERIAL DESCRIPTION: **linoleum mastic**  
MATERIAL LOCATION: **auditorium under seating area on 1st floor**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

If identified follow O&M plan.

Management Planner's Signature: \_\_\_\_\_ Date: **04/11/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**  
SCHOOL NAME: **Pasteur School** INSPECTION DATE: **3/24/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **025B**  
MATERIAL DESCRIPTION: **Linoleum Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **501/502 Washroom**  
MATERIAL QUANTITY: **238** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 03/24/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Pasteur School** REVIEW DATE: **4/11/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

HOMOGENEOUS AREA: **025B**  
MATERIAL DESCRIPTION: **Linoleum Adhesive**  
MATERIAL LOCATION: **501/502 Washroom**  
MATERIAL QUANTITY: **238** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/11/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **24851**    BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **John Feely**  
SCHOOL NAME: **Pasteur School**    INSPECTION DATE: **3/24/2016**  
ADDRESS: **5825 S. Kostner**    IDPH LICENSE NO: **100-00249**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **025C**  
MATERIAL DESCRIPTION: **Linoleum Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **503/504 Washroom**  
MATERIAL QUANTITY: **238**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY:    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 03/24/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Pasteur School** REVIEW DATE: **4/11/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

HOMOGENEOUS AREA: **025C**

MATERIAL DESCRIPTION: **Linoleum Adhesive**

MATERIAL LOCATION: **503/504 Washroom**

MATERIAL QUANTITY: **238**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/11/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**  
SCHOOL NAME: **Pasteur School** INSPECTION DATE: **3/24/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **026**  
MATERIAL DESCRIPTION: **gray carpet mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **main office, library, room 214**

MATERIAL QUANTITY: **1626**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 03/24/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Pasteur School** REVIEW DATE: **4/11/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

HOMOGENEOUS AREA: **026**  
MATERIAL DESCRIPTION: **gray carpet mastic**  
MATERIAL LOCATION: **main office, library, room 214**  
MATERIAL QUANTITY: **1626** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/11/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**  
SCHOOL NAME: **Pasteur School** INSPECTION DATE: **3/24/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **027**  
MATERIAL DESCRIPTION: **green carpet mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **room 114, teachers lounge, 2nd floor mens teacher toilet**

MATERIAL QUANTITY: **730** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **03/24/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Pasteur School** REVIEW DATE: **4/11/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

HOMOGENEOUS AREA: **027**  
MATERIAL DESCRIPTION: **green carpet mastic**  
MATERIAL LOCATION: **room 114, teachers lounge, 2nd floor mens teacher toilet**  
MATERIAL QUANTITY: **730** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/11/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**  
SCHOOL NAME: **Pasteur School** INSPECTION DATE: **3/24/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **028**  
MATERIAL DESCRIPTION: **12x12 white floor tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Annex, 120, main office, storage room, eng. office and toilet, lunchroom...**  
MATERIAL QUANTITY: **12720** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 03/24/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Pasteur School** REVIEW DATE: **4/11/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

HOMOGENEOUS AREA: **028**  
MATERIAL DESCRIPTION: **12x12 white floor tile**  
MATERIAL LOCATION: **Annex, 120, main office, storage room, eng. office and toilet, lunchroom...**  
MATERIAL QUANTITY: **12720** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/11/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**  
SCHOOL NAME: **Pasteur School** INSPECTION DATE: **3/24/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **029**  
MATERIAL DESCRIPTION: **2'x4' Pinhole and Fissure Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **All classrooms, offices and corridors**  
MATERIAL QUANTITY: **82000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 03/24/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Pasteur School** REVIEW DATE: **4/11/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

HOMOGENEOUS AREA: **029**  
MATERIAL DESCRIPTION: **2'x4' Pinhole and Fissure Ceiling Tile**  
MATERIAL LOCATION: **All classrooms, offices and corridors**  
MATERIAL QUANTITY: **82000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/11/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **24851**    BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **John Feely**  
SCHOOL NAME: **Pasteur School**    INSPECTION DATE: **3/24/2016**  
ADDRESS: **5825 S. Kostner**    IDPH LICENSE NO: **100-00249**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **030**  
MATERIAL DESCRIPTION: **Insulation in Fire Doors**  
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **501/502**  
MATERIAL QUANTITY: **84**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY:    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 03/24/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Pasteur School** REVIEW DATE: **4/11/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

HOMOGENEOUS AREA: **030**  
MATERIAL DESCRIPTION: **Insulation in Fire Doors**  
MATERIAL LOCATION: **501/502**  
MATERIAL QUANTITY: **84** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/11/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**  
SCHOOL NAME: **Pasteur School** INSPECTION DATE: **3/24/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **031**  
MATERIAL DESCRIPTION: **Insulation in Fire Doors**  
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **503/504**  
MATERIAL QUANTITY: **84** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 03/24/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Pasteur School** REVIEW DATE: **4/11/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

HOMOGENEOUS AREA: **031**

MATERIAL DESCRIPTION: **Insulation in Fire Doors**

MATERIAL LOCATION: **503/504**

MATERIAL QUANTITY: **84**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/11/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**  
SCHOOL NAME: **Pasteur School** INSPECTION DATE: **3/24/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **032**  
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 108 Storage Access-South**  
MATERIAL QUANTITY: **40** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 03/24/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Pasteur School** REVIEW DATE: **4/11/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

HOMOGENEOUS AREA: **032**  
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**  
MATERIAL LOCATION: **Room 108 Storage Access-South**  
MATERIAL QUANTITY: **40** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/11/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**  
SCHOOL NAME: **Pasteur School** INSPECTION DATE: **3/24/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **033**  
MATERIAL DESCRIPTION: **Rolled Flooring**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Annex Washroom**  
MATERIAL QUANTITY: **728** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 03/24/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Pasteur School** REVIEW DATE: **4/11/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

HOMOGENEOUS AREA: **033**  
MATERIAL DESCRIPTION: **Rolled Flooring**  
MATERIAL LOCATION: **Annex Washroom**  
MATERIAL QUANTITY: **728** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/11/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**  
SCHOOL NAME: **Pasteur School** INSPECTION DATE: **3/24/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **034**  
MATERIAL DESCRIPTION: **Rolled Flooring Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Annex Washroom**

MATERIAL QUANTITY: **728**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 03/24/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Pasteur School** REVIEW DATE: **4/11/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

HOMOGENEOUS AREA: **034**  
MATERIAL DESCRIPTION: **Rolled Flooring Adhesive**  
MATERIAL LOCATION: **Annex Washroom**  
MATERIAL QUANTITY: **728** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/11/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**  
SCHOOL NAME: **Pasteur School** INSPECTION DATE: **3/24/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **035**  
MATERIAL DESCRIPTION: **12"x12" Beige Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **401/402 Modular Unit**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 03/24/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Pasteur School** REVIEW DATE: **4/11/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

HOMOGENEOUS AREA: **035**  
MATERIAL DESCRIPTION: **12"x12" Beige Floor Tile**  
MATERIAL LOCATION: **401/402 Modular Unit**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/11/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**  
SCHOOL NAME: **Pasteur School** INSPECTION DATE: **3/24/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **B**  
MATERIAL DESCRIPTION: **12" x 12" blue floor tile part of pattern**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Annex**

MATERIAL QUANTITY: **10**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 03/24/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Pasteur School** REVIEW DATE: **4/11/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

HOMOGENEOUS AREA: **B**

MATERIAL DESCRIPTION: **12" x 12" blue floor tile part of pattern**

MATERIAL LOCATION: **Annex**

MATERIAL QUANTITY: **10**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/11/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **24851**    BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **John Feely**  
SCHOOL NAME: **Pasteur School**    INSPECTION DATE: **3/24/2016**  
ADDRESS: **5825 S. Kostner**    IDPH LICENSE NO: **100-00249**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **C**  
MATERIAL DESCRIPTION: **12" x 12" light blue floor tile part of pattern**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Annex**  
MATERIAL QUANTITY: **10**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY:    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **03/24/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Pasteur School** REVIEW DATE: **4/11/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

HOMOGENEOUS AREA: **C**

MATERIAL DESCRIPTION: **12" x 12" light blue floor tile part of pattern**

MATERIAL LOCATION: **Annex**

MATERIAL QUANTITY: **10**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/11/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**  
SCHOOL NAME: **Pasteur School** INSPECTION DATE: **3/24/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **D**  
MATERIAL DESCRIPTION: **12" x 12" pink floor tile part of pattern**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Annex**

MATERIAL QUANTITY: **10**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 03/24/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Pasteur School** REVIEW DATE: **4/11/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

HOMOGENEOUS AREA: **D**

MATERIAL DESCRIPTION: **12" x 12" pink floor tile part of pattern**

MATERIAL LOCATION: **Annex**

MATERIAL QUANTITY: **10**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/11/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **24851**    BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **John Feely**  
SCHOOL NAME: **Pasteur School**    INSPECTION DATE: **3/24/2016**  
ADDRESS: **5825 S. Kostner**    IDPH LICENSE NO: **100-00249**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **E**  
MATERIAL DESCRIPTION: **12" x 12" gray floor tile part of pattern**  
HISTORICAL AHERA DAMAGE CATEGORY: **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION:

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2016**

Inspector's Signature: \_\_\_\_\_ Date: **03/24/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Pasteur School** REVIEW DATE: **4/11/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

HOMOGENEOUS AREA: **E**

MATERIAL DESCRIPTION: **12" x 12" gray floor tile part of pattern**

MATERIAL LOCATION:

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

If identified follow O&M plan.

Management Planner's Signature: \_\_\_\_\_ Date: **04/11/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**  
SCHOOL NAME: **Pasteur School** INSPECTION DATE: **3/24/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **F**  
MATERIAL DESCRIPTION: **2' x 2' ceiling tile**  
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout annex**  
MATERIAL QUANTITY: **13500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 03/24/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Pasteur School** REVIEW DATE: **4/11/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

HOMOGENEOUS AREA: **F**  
MATERIAL DESCRIPTION: **2' x 2' ceiling tile**  
MATERIAL LOCATION: **Throughout annex**  
MATERIAL QUANTITY: **13500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/11/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**  
SCHOOL NAME: **Pasteur School** INSPECTION DATE: **3/24/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **G**  
MATERIAL DESCRIPTION: **Drywall**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **On all interior new load bearing walls**  
MATERIAL QUANTITY: **350** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 03/24/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Pasteur School** REVIEW DATE: **4/11/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

HOMOGENEOUS AREA: **G**  
MATERIAL DESCRIPTION: **Drywall**  
MATERIAL LOCATION: **On all interior new load bearing walls**  
MATERIAL QUANTITY: **350** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/11/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**  
SCHOOL NAME: **Pasteur School** INSPECTION DATE: **3/24/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **G-2**  
MATERIAL DESCRIPTION: **Drywall**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **401/402**  
MATERIAL QUANTITY: **1319** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 03/24/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Pasteur School** REVIEW DATE: **4/11/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

HOMOGENEOUS AREA: **G-2**  
MATERIAL DESCRIPTION: **Drywall**  
MATERIAL LOCATION: **401/402**  
MATERIAL QUANTITY: **1319** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/11/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **24851**    BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **John Feely**  
SCHOOL NAME: **Pasteur School**    INSPECTION DATE: **3/24/2016**  
ADDRESS: **5825 S. Kostner**    IDPH LICENSE NO: **100-00249**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **G-2A**  
MATERIAL DESCRIPTION: **Drywall Compound**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **401/402**  
MATERIAL QUANTITY: **1319**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY:    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 03/24/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Pasteur School** REVIEW DATE: **4/11/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

HOMOGENEOUS AREA: **G-2A**  
MATERIAL DESCRIPTION: **Drywall Compound**  
MATERIAL LOCATION: **401/402**  
MATERIAL QUANTITY: **1319** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/11/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**  
SCHOOL NAME: **Pasteur School** INSPECTION DATE: **3/24/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **G-3**  
MATERIAL DESCRIPTION: **Drywall**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **403/404**  
MATERIAL QUANTITY: **1319** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 03/24/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Pasteur School** REVIEW DATE: **4/11/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

HOMOGENEOUS AREA: **G-3**  
MATERIAL DESCRIPTION: **Drywall**  
MATERIAL LOCATION: **403/404**  
MATERIAL QUANTITY: **1319** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/11/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**  
SCHOOL NAME: **Pasteur School** INSPECTION DATE: **3/24/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **G-3A**  
MATERIAL DESCRIPTION: **Drywall Comound**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **403/404**  
MATERIAL QUANTITY: **1319** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 03/24/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Pasteur School** REVIEW DATE: **4/11/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

HOMOGENEOUS AREA: **G-3A**

MATERIAL DESCRIPTION: **Drywall Comound**

MATERIAL LOCATION: **403/404**

MATERIAL QUANTITY: **1319**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/11/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**  
SCHOOL NAME: **Pasteur School** INSPECTION DATE: **3/24/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **G-4**  
MATERIAL DESCRIPTION: **Drywall**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **501/502**  
MATERIAL QUANTITY: **1319** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 03/24/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Pasteur School** REVIEW DATE: **4/11/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

HOMOGENEOUS AREA: **G-4**  
MATERIAL DESCRIPTION: **Drywall**  
MATERIAL LOCATION: **501/502**  
MATERIAL QUANTITY: **1319** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/11/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **24851**    BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **John Feely**  
SCHOOL NAME: **Pasteur School**    INSPECTION DATE: **3/24/2016**  
ADDRESS: **5825 S. Kostner**    IDPH LICENSE NO: **100-00249**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **G-4A**  
MATERIAL DESCRIPTION: **Drywall Compound**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **501/502**  
MATERIAL QUANTITY: **1319**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY:    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 03/24/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Pasteur School** REVIEW DATE: **4/11/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

HOMOGENEOUS AREA: **G-4A**

MATERIAL DESCRIPTION: **Drywall Compound**

MATERIAL LOCATION: **501/502**

MATERIAL QUANTITY: **1319**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/11/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**  
SCHOOL NAME: **Pasteur School** INSPECTION DATE: **3/24/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **G-5**  
MATERIAL DESCRIPTION: **Drywall**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **503/504**  
MATERIAL QUANTITY: **1319** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 03/24/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Pasteur School** REVIEW DATE: **4/11/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

HOMOGENEOUS AREA: **G-5**  
MATERIAL DESCRIPTION: **Drywall**  
MATERIAL LOCATION: **503/504**  
MATERIAL QUANTITY: **1319** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/11/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**  
SCHOOL NAME: **Pasteur School** INSPECTION DATE: **3/24/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **G-5A**  
MATERIAL DESCRIPTION: **Drywall Compound**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **503/504**  
MATERIAL QUANTITY: **1319** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 03/24/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Pasteur School** REVIEW DATE: **4/11/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

HOMOGENEOUS AREA: **G-5A**  
MATERIAL DESCRIPTION: **Drywall Compound**  
MATERIAL LOCATION: **503/504**  
MATERIAL QUANTITY: **1319** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/11/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **24851**    BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **John Feely**  
SCHOOL NAME: **Pasteur School**    INSPECTION DATE: **3/24/2016**  
ADDRESS: **5825 S. Kostner**    IDPH LICENSE NO: **100-00249**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **H**  
MATERIAL DESCRIPTION: **Floor tile mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout annex**  
MATERIAL QUANTITY: **13500**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY:    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 03/24/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Pasteur School** REVIEW DATE: **4/11/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

HOMOGENEOUS AREA: **H**  
MATERIAL DESCRIPTION: **Floor tile mastic**  
MATERIAL LOCATION: **Throughout annex**  
MATERIAL QUANTITY: **13500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/11/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**  
SCHOOL NAME: **Pasteur School** INSPECTION DATE: **3/24/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **I**  
MATERIAL DESCRIPTION: **Gray base board**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout annex**  
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 03/24/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Pasteur School** REVIEW DATE: **4/11/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

HOMOGENEOUS AREA: **I**

MATERIAL DESCRIPTION: **Gray base board**

MATERIAL LOCATION: **Throughout annex**

MATERIAL QUANTITY: **1600**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/11/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**  
SCHOOL NAME: **Pasteur School** INSPECTION DATE: **3/24/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **I-2**  
MATERIAL DESCRIPTION: **Light Brown Baseboard**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **501/502**  
MATERIAL QUANTITY: **306** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 03/24/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Pasteur School** REVIEW DATE: **4/11/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

HOMOGENEOUS AREA: **I-2**  
MATERIAL DESCRIPTION: **Light Brown Baseboard**  
MATERIAL LOCATION: **501/502**  
MATERIAL QUANTITY: **306** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/11/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**  
SCHOOL NAME: **Pasteur School** INSPECTION DATE: **3/24/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **I-3**  
MATERIAL DESCRIPTION: **Lightr Brown Baseboard**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **503/504**  
MATERIAL QUANTITY: **306** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 03/24/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Pasteur School** REVIEW DATE: **4/11/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

HOMOGENEOUS AREA: **I-3**  
MATERIAL DESCRIPTION: **Lightr Brown Baseboard**  
MATERIAL LOCATION: **503/504**  
MATERIAL QUANTITY: **306** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/11/2016**

# Chicago Public Schools

## Carnow, Conibear and Associates 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**  
SCHOOL NAME: **Pasteur School** INSPECTION DATE: **3/24/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **J**  
MATERIAL DESCRIPTION: **Gray base board mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout annex**  
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 03/24/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Pasteur School** REVIEW DATE: **4/11/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

HOMOGENEOUS AREA: **J**  
MATERIAL DESCRIPTION: **Gray base board mastic**  
MATERIAL LOCATION: **Throughout annex**  
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/11/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**  
SCHOOL NAME: **Pasteur School** INSPECTION DATE: **3/24/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **J-2**  
MATERIAL DESCRIPTION: **Light Brown Baseboard Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **501/502**  
MATERIAL QUANTITY: **306** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 03/24/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Pasteur School** REVIEW DATE: **4/11/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

HOMOGENEOUS AREA: **J-2**

MATERIAL DESCRIPTION: **Light Brown Baseboard Adhesive**

MATERIAL LOCATION: **501/502**

MATERIAL QUANTITY: **306**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/11/2016**

# Chicago Public Schools

## Carnow, Conibear and Associates 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **24851**    BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **John Feely**  
SCHOOL NAME: **Pasteur School**    INSPECTION DATE: **3/24/2016**  
ADDRESS: **5825 S. Kostner**    IDPH LICENSE NO: **100-00249**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **J-3**  
MATERIAL DESCRIPTION: **Light Brown Baseboard Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **503/504**  
MATERIAL QUANTITY: **306**    MATERIAL UNITS: **LF**  
DAMAGE QUANTITY:    DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 03/24/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Pasteur School** REVIEW DATE: **4/11/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

HOMOGENEOUS AREA: **J-3**  
MATERIAL DESCRIPTION: **Light Brown Baseboard Adhesive**  
MATERIAL LOCATION: **503/504**  
MATERIAL QUANTITY: **306** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/11/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**  
SCHOOL NAME: **Pasteur School** INSPECTION DATE: **3/24/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **K**  
MATERIAL DESCRIPTION: **Drywall joint compound**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout annex**  
MATERIAL QUANTITY: **350** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 03/24/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Pasteur School** REVIEW DATE: **4/11/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

HOMOGENEOUS AREA: **K**  
MATERIAL DESCRIPTION: **Drywall joint compound**  
MATERIAL LOCATION: **Throughout annex**  
MATERIAL QUANTITY: **350** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/11/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**  
SCHOOL NAME: **Pasteur School** INSPECTION DATE: **3/24/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **L**  
MATERIAL DESCRIPTION: **12" x 12" vft, cream speck**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **throughout N & S modulars**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 03/24/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Pasteur School** REVIEW DATE: **4/11/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

HOMOGENEOUS AREA: **L**  
MATERIAL DESCRIPTION: **12" x 12" vft, cream speck**  
MATERIAL LOCATION: **throughout N & S modulars**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/11/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**  
SCHOOL NAME: **Pasteur School** INSPECTION DATE: **3/24/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **L-2**  
MATERIAL DESCRIPTION: **12"x12" Beige Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **403/404 Modular Unit**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 03/24/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Pasteur School** REVIEW DATE: **4/11/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

HOMOGENEOUS AREA: **L-2**  
MATERIAL DESCRIPTION: **12"x12" Beige Floor Tile**  
MATERIAL LOCATION: **403/404 Modular Unit**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/11/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**  
SCHOOL NAME: **Pasteur School** INSPECTION DATE: **3/24/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **M**  
MATERIAL DESCRIPTION: **mastic beneath 12" x 12" vft, cream speck**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Throughout N & S modulars**

MATERIAL QUANTITY: **1200**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 03/24/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Pasteur School** REVIEW DATE: **4/11/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

HOMOGENEOUS AREA: **M**  
MATERIAL DESCRIPTION: **mastic beneath 12" x 12" vft, cream speck**  
MATERIAL LOCATION: **Throughout N & S modulars**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/11/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**  
SCHOOL NAME: **Pasteur School** INSPECTION DATE: **3/24/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **M-1**  
MATERIAL DESCRIPTION: **12"x12" Beige Floor tile Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **401/402 Modular Unit**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 03/24/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Pasteur School** REVIEW DATE: **4/11/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

HOMOGENEOUS AREA: **M-1**  
MATERIAL DESCRIPTION: **12"x12" Beige Floor tile Adhesive**  
MATERIAL LOCATION: **401/402 Modular Unit**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/11/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **24851**    BUILDING ID: **5310**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **John Feely**  
SCHOOL NAME: **Pasteur School**    INSPECTION DATE: **3/24/2016**  
ADDRESS: **5825 S. Kostner**    IDPH LICENSE NO: **100-00249**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **M-2**  
MATERIAL DESCRIPTION: **12"x12" Beige Floor Tile Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **403/404 Modular Building**  
MATERIAL QUANTITY: **600**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY:    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 03/24/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Pasteur School** REVIEW DATE: **4/11/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

HOMOGENEOUS AREA: **M-2**  
MATERIAL DESCRIPTION: **12"x12" Beige Floor Tile Adhesive**  
MATERIAL LOCATION: **403/404 Modular Building**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/11/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**  
SCHOOL NAME: **Pasteur School** INSPECTION DATE: **3/24/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **N**  
MATERIAL DESCRIPTION: **Cream texture transite texture wall**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout North modulars**  
MATERIAL QUANTITY: **960** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 03/24/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Pasteur School** REVIEW DATE: **4/11/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

HOMOGENEOUS AREA: **N**

MATERIAL DESCRIPTION: **Cream texture transite texture wall**

MATERIAL LOCATION: **Throughout North modulars**

MATERIAL QUANTITY: **960** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/11/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **24851**    BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **John Feely**  
SCHOOL NAME: **Pasteur School**    INSPECTION DATE: **3/24/2016**  
ADDRESS: **5825 S. Kostner**    IDPH LICENSE NO: **100-00249**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **O-1**  
MATERIAL DESCRIPTION: **4' x 8' textured ceiling panels**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout North and South modulars**  
MATERIAL QUANTITY: **1200**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY:    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 03/24/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Pasteur School** REVIEW DATE: **4/11/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

HOMOGENEOUS AREA: **O-1**  
MATERIAL DESCRIPTION: **4' x 8' textured ceiling panels**  
MATERIAL LOCATION: **Throughout North and South modulars**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/11/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**  
SCHOOL NAME: **Pasteur School** INSPECTION DATE: **3/24/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **P-1**  
MATERIAL DESCRIPTION: **Cream base board**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Throughout North & South modulars**

MATERIAL QUANTITY: **160**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 03/24/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Pasteur School** REVIEW DATE: **4/11/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

HOMOGENEOUS AREA: **P-1**  
MATERIAL DESCRIPTION: **Cream base board**  
MATERIAL LOCATION: **Throughout North & South modulars**  
MATERIAL QUANTITY: **160** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/11/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**  
SCHOOL NAME: **Pasteur School** INSPECTION DATE: **3/24/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **Q-1**  
MATERIAL DESCRIPTION: **cream base board mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Throughout North & South modulars**

MATERIAL QUANTITY: **160**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 03/24/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Pasteur School** REVIEW DATE: **4/11/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

HOMOGENEOUS AREA: **Q-1**  
MATERIAL DESCRIPTION: **cream base board mastic**  
MATERIAL LOCATION: **Throughout North & South modulars**  
MATERIAL QUANTITY: **160** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/11/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**  
SCHOOL NAME: **Pasteur School** INSPECTION DATE: **3/24/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **R**  
MATERIAL DESCRIPTION: **Aircell pipe insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Boiler room and tunnels**  
MATERIAL QUANTITY: **1660** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 03/24/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Pasteur School** REVIEW DATE: **4/11/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

HOMOGENEOUS AREA: **R**  
MATERIAL DESCRIPTION: **Aircell pipe insulation**  
MATERIAL LOCATION: **Boiler room and tunnels**  
MATERIAL QUANTITY: **1660** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/11/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**  
SCHOOL NAME: **Pasteur School** INSPECTION DATE: **3/24/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **S**  
MATERIAL DESCRIPTION: **Cementitious Pipe Joint Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Boiler room and tunnels**  
MATERIAL QUANTITY: **150** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 03/24/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Pasteur School** REVIEW DATE: **4/11/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

HOMOGENEOUS AREA: **S**  
MATERIAL DESCRIPTION: **Cementitious Pipe Joint Insulation**  
MATERIAL LOCATION: **Boiler room and tunnels**  
MATERIAL QUANTITY: **150** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/11/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**  
SCHOOL NAME: **Pasteur School** INSPECTION DATE: **3/24/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **U**  
MATERIAL DESCRIPTION: **Boiler tank jacket**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **boiler room**  
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 03/24/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Pasteur School** REVIEW DATE: **4/11/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

HOMOGENEOUS AREA: **U**  
MATERIAL DESCRIPTION: **Boiler tank jacket**  
MATERIAL LOCATION: **boiler room**  
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/11/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **24851**    BUILDING ID: **5310**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **John Feely**  
SCHOOL NAME: **Pasteur School**    INSPECTION DATE: **3/24/2016**  
ADDRESS: **5825 S. Kostner**    IDPH LICENSE NO: **100-00249**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **V**  
MATERIAL DESCRIPTION: **Pipe fittings**  
HISTORICAL AHERA DAMAGE CATEGORY: **7 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile**    FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Pipe Chases in Bathrooms**  
MATERIAL QUANTITY: **100**    MATERIAL UNITS: **LF**  
DAMAGE QUANTITY:    DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 03/24/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Pasteur School** REVIEW DATE: **4/11/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

HOMOGENEOUS AREA: **V**  
MATERIAL DESCRIPTION: **Pipe fittings**  
MATERIAL LOCATION: **Pipe Chases in Bathrooms**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/11/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **24851**    BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **John Feely**  
SCHOOL NAME: **Pasteur School**    INSPECTION DATE: **3/24/2016**  
ADDRESS: **5825 S. Kostner**    IDPH LICENSE NO: **100-00249**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **W**  
MATERIAL DESCRIPTION: **Chalkboard**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **401/402**  
MATERIAL QUANTITY: **104**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY:    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 03/24/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Pasteur School** REVIEW DATE: **4/11/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

HOMOGENEOUS AREA: **W**  
MATERIAL DESCRIPTION: **Chalkboard**  
MATERIAL LOCATION: **401/402**  
MATERIAL QUANTITY: **104** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/11/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**  
SCHOOL NAME: **Pasteur School** INSPECTION DATE: **3/24/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **X**  
MATERIAL DESCRIPTION: **Chalkboard Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **401/402**  
MATERIAL QUANTITY: **104** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 03/24/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Pasteur School** REVIEW DATE: **4/11/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

HOMOGENEOUS AREA: **X**

MATERIAL DESCRIPTION: **Chalkboard Adhesive**

MATERIAL LOCATION: **401/402**

MATERIAL QUANTITY: **104**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/11/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**  
SCHOOL NAME: **Pasteur School** INSPECTION DATE: **3/24/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **Y**  
MATERIAL DESCRIPTION: **Chalkboard**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **403/404**  
MATERIAL QUANTITY: **104** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 03/24/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Pasteur School** REVIEW DATE: **4/11/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

HOMOGENEOUS AREA: **Y**  
MATERIAL DESCRIPTION: **Chalkboard**  
MATERIAL LOCATION: **403/404**  
MATERIAL QUANTITY: **104** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/11/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **24851**    BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **John Feely**  
SCHOOL NAME: **Pasteur School**    INSPECTION DATE: **3/24/2016**  
ADDRESS: **5825 S. Kostner**    IDPH LICENSE NO: **100-00249**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **Z**  
MATERIAL DESCRIPTION: **Chalkboard Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **403/404**  
MATERIAL QUANTITY: **104**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY:    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 03/24/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Pasteur School** REVIEW DATE: **4/11/2016**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-00249**

---

HOMOGENEOUS AREA: **Z**  
MATERIAL DESCRIPTION: **Chalkboard Adhesive**  
MATERIAL LOCATION: **403/404**  
MATERIAL QUANTITY: **104** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/11/2016**

# **Chicago Public Schools**

**Carnow, Conibear and Associates**

***2016 AHERA REINSPECTION***

# APPENDIX B

## Inspector and Management Planner Licenses

---

**ASBESTOS INSPECTOR**  
 Issued by  
**STATE OF WISCONSIN**  
 Dept. of Health Services  
 John Charles Feely  
 9513 Lawton Ave  
 Oak Lawn, IL 60453-2999

Alt-369	Exp: 07/11/2016	250 lbs	5' 11"
		07/13/1963	Male

Training due by: 07/11/2016

LEAD DIVISION OF PUBLIC HEALTH  
**IDPH**  
 ASBESTOS PROFESSIONAL LICENSE

ID NUMBER 100 - 00249  
 ISSUED 3/2/2015  
 EXPIRES 05/15/2016

**JOHN C FEELY**  
 9513 SOUTH LAWTON AVENUE  
 OAK LAWN, IL 60453  
 Environmental Health

2016



**OCCUPATIONAL TRAINING & SUPPLY, INC.**

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900

# Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

**John Feely**


has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Course Date: 1/6/2016

Exam Date: 1/6/2016

Expiration Date: 1/6/2017


Certificate Number: BIR1601060019

  
Kathy DeSalvo, Director



# Evan Christian

Illinois Licensed Project Manager, and Air Sampling Professional



ENDORSEMENTS	TC EXPIRES
PROJECT MANAGER AIR SAMPLING PROFESSIONAL	12/12/2015
<b>Alteration of this license shall result in legal action</b> This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	

**CARNOW  
CONIBEAR**

2015



**OCCUPATIONAL TRAINING & SUPPLY, INC.**

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900

# Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

**Evan Christian**

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 12/2/2015

Exam Date: 12/2/2015

Expiration Date: 12/2/2016

Certificate Number: BIR1512024159

  
Katy DeSalvo, Director

**Reliable**  
**Environmental**  
**Solutions, Inc.** **RES**

*This is to certify that* **Evan Christian**

*has on January 28 & 29, 2016, in Springfield, Illinois,  
completed the requirements for asbestos accreditation under Section 206 of TSCA Title II*

**Asbestos Management Planner Initial Training**

*as accredited by the State of Illinois and approved by the U.S.E.P.A. under 40 CFR 763 (AHERA)  
and passed the associated examination with a score of 70% or higher*

Course Date: January 28 & 29, 2016

Examination Date: January 29, 2016

Expiration Date: January 29, 2017

Certificate Number: MP/0103

*William S. Williams*

Training Program Manager, William S. Williams

4211 Westgate Drive, Springfield, Illinois ☐ 217.787.9800 ☐ 217.787.9801 FAX ☐ [www.ReliableEnv.com](http://www.ReliableEnv.com)

# APPENDIX C

## Laboratory Accreditations

---

# APPENDIX D

## Laboratory Results

---

# APPENDIX E

## Chain of Custody Forms

---

## Three-Year Reinspection Key to Terms

	<b>CODE</b>	<b>KEY</b>
<b>MATERIAL</b>		
	ACBM	Asbestos Containing Building Materials
<b>MATERIAL CATEGORY</b>		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
<b>MATERIAL UNITS</b>		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
<b>DAMAGE TYPE</b>		
	Loc	Localized
	Dist	Distributed