

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM**

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-2405
SCHOOL NAME: Pirie School
ADDRESS OF SCHOOL: 650 E 85th Street
CITY: Chicago, IL, 60619

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **4/3/2013**

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II *(Please type or print)*

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 5/31/2016 ENROLLMENT 288
IDPH INSPECTOR LICENSE NUMBER: 100-08023
IDPH LICENSED INSPECTOR NAME (Please Print): Tommy Thompson
IDPH MP LICENSE NUMBER: 100-04019
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Arturo Saenz

DESIGNATED PERSON (Please Print): Robert Christlieb PHONE: (773) 553-3197



5/31/2016

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Pirie School

650 E 85th Street
Chicago, IL, 60619

Unit: 24971
Building ID: 5440

IDPH ID Number: 14-016-2990-2405

REPORT DATE:

Tuesday, May 31, 2016

Prepared for:

Chicago Public Schools
125 S. Clark Street
Chicago, IL 60603

Prepared by:

GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone (312) 733-6262

Fax (312) 733-5612

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

March 22, 2016

Mr. R. Kent Cook
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2016 Three-Year Reinspections

Dear Mr. Cook:

GSG Consultants, Inc., Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 1,2,6 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 24971 Region: 06 IDPH ID: 14-016-2990-2405

School: Pirie School Building ID: 5440

Address: 650 E 85th Street
Chicago, IL, 60619

Building Contact: Barnotes, Raymond Contact Phone: 7736174901

Current Building Owners: Chicago Public Schools

Review Date: 05/28/2016

Inspector: Tommy Thompson Inspector IDPH License: 100-08023
Management Planner: Arturo Saenz Management Planner IDPH License: 100-04019

If you have any questions or comments, please contact us at (312) 733-6262

Sincerely,
GSG Consultants, Inc.



Arturo Saenz
100-04019

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: March 22, 2016

RE: Pirie School, Unit 24971
650 E 85th Street
Chicago, IL, 60619

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2016 asbestos three year re-inspection has been completed at Pirie School, following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at Pirie School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Robert Christlieb, the designated Local Education Authority's Designated Person at (773) 553-3197 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Pirie School
Address: 650 E 85th Street
IDPH ID: 14-016-2990-2405
Contact: Barnotes, Raymond

Unit: 24971
Chicago, IL, 60619
Building ID: 5440
Phone: 7736174901

Region: 06

2. Description of Facility

Original Construction:
Total Square Footage: 4947
Current Occupancy: 288

Additional Construction:
No of Floors:

3. LEA Designated Person

Contact: Robert Christlieb
Address: 125 South Clark Street, 17th Floor
Chicago, IL 60603

Phone: (773) 553-3197

4. Managing Environmental Consultant


MEC: GSG Consultants, Inc.
Contact: Arturo Saenz
Address 855 W. Adams St., Ste. 200
Phone: (312) 733-6262

Fax: (312) 733-5612

5. Inspector

Inspector Name: Tommy Thompson


Inspector IDPH license # 100-08023


Signature:
Date: 3/22/2016

6. Management Planner

Management Planner Name: Arturo Saenz

Management Planner IDPH license # 100-04019


Signature:
Date: 05/28/2016

7. Review Date: 05/28/2016

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature:



Date: 5/31/2016

Name: Robert Christlieb

II. EXECUTIVE SUMMARY

GSG Consultants, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Pirie School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 5440:

B. The following new homogenous areas have been identified for Building 5440:

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

05	Duct Sleeve (Vibration Dampener)
10	Carpet Mastic
11	1 x 1 Ceiling Tile
12	Brown, Tan and White Ceramic Tile Grout
13	Brown, Tan and White Ceramic Tile Adhesive
14	Insulation Inside Vault Door
15	Peach, Blue, Yellow and White Ceramic Tile Grout
16	Peach, Blue, Yellow and White Ceramic Tile Adhesive
17	Grey, Yellow and White Ceramic Tile Grout
18	Grey, Yellow and White Ceramic Tile Adhesive
19	Blue Ceramic Tile Grout
22	12 x 12 Tan Floor Tile
22M	12 x 12 Tan Floor Tile Mastic
23	Yellow Ceramic Tile Grout
24	Yellow Ceramic Tile Adhesive
25	Blue and White Ceramic Tile Grout
26	Blue and White Ceramic Tile Adhesive
27	5 x 3 Ceiling Tile
28	12 x 12 Aqua/Design Floor Tile
28M	12 x 12 Aqua/Design Floor Tile Mastic
29	2 x 2 Ceiling Tile
30	12 x 12 Tan Floor Tile
30M	12 x 12 Tan Floor Tile Mastic
31	Tan Baseboard
32	Blue Vinyl Flooring
33	Blue Vinyl Floor Adhesive
34	Pink Vinyl Floor
35	Pink Vinyl Floor Mastic
36	Tan Baseboard Mastic
37	12" x 12" Beige Streaked VFT
37A	12" x 12" Beige Streaked VFT Mastic
38	12" x 12" Gray with Blue Streaked VFT
38A	12" x 12" Gray with Blue Streaked VFT Mastic
I	Incinerator Insulation (Fire Brick) - REMOVED
J	Roofing Panels
K	Various Styles 1 x 1 Ceiling Tile
L	2 x 4 Ceiling Tile
M	Plaster Ceiling
N	Fiberglass Pipe Insulation and Assumed Wrap

The following areas were deemed to be inaccessible:

10	Carpet Mastic
13	Brown, Tan and White Ceramic Tile Adhesive
16	Peach, Blue, Yellow and White Ceramic Tile Adhesive
18	Grey, Yellow and White Ceramic Tile Adhesive
22M	12 x 12 Tan Floor Tile Mastic
24	Yellow Ceramic Tile Adhesive
26	Blue and White Ceramic Tile Adhesive
28M	12 x 12 Aqua/Design Floor Tile Mastic
30M	12 x 12 Tan Floor Tile Mastic
33	Blue Vinyl Floor Adhesive
35	Pink Vinyl Floor Mastic
36	Tan Baseboard Mastic

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Tommy Thompson, IDPH License # 100-08023. The Management Plan was updated by Arturo Saenz, IDPH License # 100-04019. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Pirie School Building 5440 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Pirie School Unit 24971 Building ID 5440

Address 650 E 85th Street Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
01A	9x9 Salmon Floor Tile - ABATED			N.E. Corridor	ABATED	MISC								Moderate
01B	9x9 White w/Black Streaks FloorTile - ABATED			All Corridors Except N.E. Corridor	ABATED	MISC								Moderate
01C	9x9 Light Blue w/Blue & White Streaks Floor Tile	4,200	SF	Rooms 111, 112 Lunch Room	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
01D	9x9 Gray Floor Tile - ABATED			Kitchen	ABATED	MISC		None						Low
01E	9x9 Light Green w/Black & White Streaks Floor Tile - ABATED			Room 101	ABATED	MISC								
01F	9x9 Tan w/Beige Streaks Floor Tile	11,500	SF	All Classrooms, Offices, Stage	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
05	Duct Sleeve (Vibration Dampener)	25	SF	Boiler Room	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
07A	9x9 Salmon Floor Tile Mastic - ABATED			N.E. Corridor	ABATED	MISC								
07B	9x9 White w/Black Streaks FloorTile Mastic - ABATED			All Corridors Except N.E. Corridor	ABATED	MISC								
07C	9x9 Light Blue w/Blue & White Streaks Floor Tile	4,200	SF	Rooms 116, 111	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
07D	9x9 Gray Floor Tile Mastic - ABATED			Kitchen	ABATED	MISC		None						Low
07E	9x9 Light Green w/Black & White Streaks Floor Tile Mastic - ABATED			Main Office & Principal's Office	ABATED	MISC								
07F	9x9 Tan w/Beige Streaks Floor Tile Mastic	11,500	SF	All Classrooms, Offices, Stage (Except Rooms 111,112) and Engineer Office	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
08A	12x12 Aqua Floor Tile - ABATED			South Entrance	ABATED	MISC								
08B	12x12 Beige w/Tan Streaks Floor Tile - ABATED			NE and NW Entrances & Patches in Corridors	ABATED	MISC								
09A	12x12 Aqua Floor Tile Mastic - ABATED			South Entrance	ABATED	MISC		None						Low
09B	12x12 Beige w/Tan Streaks Floor Tile Mastic - ABATED			NE and NW Entrances & Patches in Corridors	ABATED	MISC		None						Low
10	Carpet Mastic	3,740	SF	Room 111 and Book Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
11	1 x 1 Ceiling Tile	33,536	SF	Throughout Classrooms except Gym, Kitchen, Boys and Girls Restrooms	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
12	Brown, Tan and White Ceramic Tile Grout	79	SF	Principal's Office Toilet, Library Toilet and Room 126 Toilet	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
13	Brown, Tan and White Ceramic Tile	79	SF	Principal's Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the		LOW

Chicago Public Schools

School Pirie School Unit 24971 Building ID 5440

Address 650 E 85th Street Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
	Adhesive			Toilet, Library Toilet and Room 126 Toilet								potential for damage		
14	Insulation Inside Vault Door	1	EA	Main Office	ASSUMED	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
15	Peach, Blue, Yellow and White Ceramic Tile Grout	49	SF	Councilor's Toilet and Room 116 Toilet	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
16	Peach, Blue, Yellow and White Ceramic Tile Adhesive	49	SF	Councilor's Toilet and Room 116 Toilet	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
17	Grey, Yellow and White Ceramic Tile Grout	308	SF	South Boys Restroom	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
18	Grey, Yellow and White Ceramic Tile Adhesive	308	SF	South Boys Restroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
19	Blue Ceramic Tile Grout	616	SF	South Girls Restroom and North Boys Restroom	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
20	12 x 12 White with Blue Streaks Floor Tile - ABATED			SW Entrance	ABATED	MISC		None						Low
20M	12 x 12 White with Blue Streaks Floor Tile Mastic - ABATED			SW Entrance	ABATED	MISC		None						Low
22	12 x 12 Tan Floor Tile	1,232	SF	Room 115 (Library)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
22M	12 x 12 Tan Floor Tile Mastic	1,232	SF	Room 115 (Library)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		Low
23	Yellow Ceramic Tile Grout	332	SF	North Girls Restroom and Room 126 Womens Toilet	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
24	Yellow Ceramic Tile Adhesive	332	SF	North Girls Restroom and Room 126 Womens Toilet	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
25	Blue and White Ceramic Tile Grout	252	SF	Lunchroom Restroom	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
26	Blue and White Ceramic Tile Adhesive	252	SF	Lunchroom Restroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
27	5 x 3 Ceiling Tile	6,000	SF	Gym, boiler Room, Elec. Room	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
28	12 x 12 Aqua/Design Floor Tile	160	SF	Table in Storage Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
28M	12 x 12 Aqua/Design Floor Tile Mastic	160	SF	Table in Storage Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
29	2 x 2 Ceiling Tile	4,280	SF	Throughout Modular Bldg Except	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Pirie School Unit 24971 Building ID 5440

Address 650 E 85th Street Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Restrooms										
30	12 x 12 Tan Floor Tile	4,280	SF	Throughout Modular Bldg Except Restrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
30M	12 x 12 Tan Floor Tile Mastic	4,280	SF	Throughout Modular Bldg Except Restrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
31	Tan Baseboard	600	LF	Throughout Modular Bldg Except Restrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
32	Blue Vinyl Flooring	192	SF	Boys Restrooms in Modular Bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
33	Blue Vinyl Floor Adhesive	192	SF	Boys Restrooms in Modular Bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
34	Pink Vinyl Floor	192	SF	Girls Restroom in Modular Bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
35	Pink Vinyl Floor Mastic	192	SF	Girls Restroom in Modular Bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
36	Tan Baseboard Mastic	600	SF	Throughout Modular Bldg Except Restrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
37	12" x 12" Beige Streaked VFT	3,000	SF	Corridors and Vestibules	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
37A	12" x 12" Beige Streaked VFT Mastic	3,000	SF	Corridors and Vestibules	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
38	12" x 12" Gray with Blue Streaked VFT	3,500	SF	Lunchroom, Kitchen, Main Office and Principals Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
38A	12" x 12" Gray with Blue Streaked VFT Mastic	3,500	SF	Lunchroom, Kitchen, Main Office and Principals Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
B	MJP E/F/V on Fiberglass Pipe Insulation	300	EA	In Corridors - Above 2x4 Drop In Ceiling Panels	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
C	Aircell Pipe Insulation	1,500	LF	Throughout Corridors, Lunchroom Storage, Copy Room, & Book Room	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
D	MJP E/F/V on Aircell Pipe Insulation	175	EA	Throughout Corridors	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
E	Cardboard Pipe Insulation	2,500	LF	In Corridors - Above	CHR	TSI	Y	NONE	0		No	ACBM with the		LOW

Chicago Public Schools

School Pirie School Unit 24971 Building ID 5440

Address 650 E 85th Street Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				2x4 Drop In Ceiling Panels and at Classroom Induction Units								potential for damage		
F	MJP E/F/V on Cardboard Pipe Insulation	150	EA	In Corridors - Above 2x4 Drop In Ceiling Panels	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
H	Boiler Gaskets			Boiler Room	NO_ACBM	TSI					No			
I	Incinerator Insulation (Fire Brick) - REMOVED			Inaccessible- Door Welded Shut	ASSUMED	MISC					No			
J	Roofing Panels	1,000	SF	Boiler Room and Gym	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
K	Various Styles 1 x 1 Ceiling Tile	26,000	SF	Throughout Classrooms, Including: Pre-Kindergarten, Classroom in Core of Building	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
L	2 x 4 Ceiling Tile	5,000	SF	Throughout Corridors	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
M	Plaster Ceiling	3,000	SF	Rooms 110, 111, 112, 113, 114, 115, 116, 107, 108 and 109	ASSUMED	TSI	N	NONE	0		No	ACBM with the potential for damage		LOW
N	Fiberglass Pipe Insulation and Assumed Wrap	400	LF	Boiler Room, Slop Sink Room and Lunch Room	ASSUMED	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Pirie School Unit 24971 Building ID 5440

Address 650 E 85th Street Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

Inspector's Comments are Summarized at the End of the Report

Reinspection Date 3/22/2016
Inspector Name Tommy Thompson
100-08023 2/13/2017
Inspector's IDPH License Number / Expiration Date

Inspector's Comments

HA Number:	Inspector Comments:
01A	
01B	
01C	
01D	
01E	
01F	
05	
07A	
07B	
07C	
07D	
07E	
07F	
08A	
08B	
09A	
09B	
10	
11	
12	
13	
14	
15	
16	

Chicago Public Schools

School Pirie School Unit 24971 Building ID 5440

Address 650 E 85th Street Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
17	
18	
19	
20	
20M	
22	
22M	
23	
24	
25	
26	
27	
28	
28M	
29	
30	
30M	
31	
32	
33	
34	
35	
36	
37	
37A	
38	
38A	
B	
C	

Chicago Public Schools

School Pirie School Unit 24971 Building ID 5440

Address 650 E 85th Street Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
D	
E	
F	
H	
I	
J	
K	
L	
M	
N	

Table II

Management Planner's Review

Chicago Public Schools

School Pirie School
Address 650 E 85th Street

Unit 24971
Chicago, IL, 60619

Building ID 5440
Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
01A	9x9 Salmon Floor Tile - ABATED			N.E. Corridor	Abated	MISC					
01B	9x9 White w/Black Streaks FloorTile - ABATED			All Corridors Except N.E. Corridor	Abated	MISC					
01C	9x9 Light Blue w/Blue & White Streaks Floor Tile	4,200	SF	Rooms 111, 112 Lunch Room	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
01D	9x9 Gray Floor Tile - ABATED			Kitchen	Abated	MISC					
01E	9x9 Light Green w/Black & White Streaks Floor Tile - ABATED			Room 101	Abated	MISC					
01F	9x9 Tan w/Beige Streaks Floor Tile	11,500	SF	All Classrooms, Offices, Stage	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
05	Duct Sleeve (Vibration Dampener)	25	SF	Boiler Room	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
07A	9x9 Salmon Floor Tile Mastic - ABATED			N.E. Corridor	Abated	MISC					
07B	9x9 White w/Black Streaks FloorTile Mastic - ABATED			All Corridors Except N.E. Corridor	Abated	MISC					
07C	9x9 Light Blue w/Blue & White Streaks Floor Tile	4,200	SF	Rooms 116, 111	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
07D	9x9 Gray Floor Tile Mastic - ABATED			Kitchen	Abated	MISC					
07E	9x9 Light Green w/Black & White Streaks Floor Tile Mastic - ABATED			Main Office & Principal's Office	Abated	MISC					
07F	9x9 Tan w/Beige Streaks Floor Tile Mastic	11,500	SF	All Classrooms, Offices, Stage (Except Rooms 111,112) and Engineer Office	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
08A	12x12 Aqua Floor Tile - ABATED			South Entrance	Abated	MISC					
08B	12x12 Beige w/Tan Streaks Floor Tile - ABATED			NE and NW Entrances & Patches in Corridors	Abated	MISC					
09A	12x12 Aqua Floor Tile Mastic - ABATED			South Entrance	Abated	MISC					
09B	12x12 Beige w/Tan Streaks Floor Tile Mastic - ABATED			NE and NW Entrances & Patches in Corridors	Abated	MISC					
10	Carpet Mastic	3,740	SF	Room 111 and Book Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
11	1 x 1 Ceiling Tile	33,536	SF	Throughout Classrooms except Gym, Kitchen, Boys and Girls Restrooms	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
12	Brown, Tan and White Ceramic Tile Grout	79	SF	Principal's Office Toilet, Library Toilet and Room 126 Toilet	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
13	Brown, Tan and White Ceramic Tile Adhesive	79	SF	Principal's Office Toilet, Library Toilet and Room 126 Toilet	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
14	Insulation Inside Vault Door	1	EA	Main Office	Assumed	TSI	Yes	0	EA	6 ACBM with the potential for damage	Follow O&M Plan
15	Peach, Blue, Yellow and White Ceramic Tile Grout	49	SF	Councilor's Toilet and Room 116 Toilet	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
16	Peach, Blue, Yellow and White Ceramic Tile Adhesive	49	SF	Councilor's Toilet and Room 116 Toilet	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
17	Grey, Yellow and White Ceramic Tile Grout	308	SF	South Boys Restroom	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Pirie School
Address 650 E 85th Street

Unit 24971
Chicago, IL, 60619

Building ID 5440
Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
18	Grey, Yellow and White Ceramic Tile Adhesive	308	SF	South Boys Restroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
19	Blue Ceramic Tile Grout	616	SF	South Girls Restroom and North Boys Restroom	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
20	12 x 12 White with Blue Streaks Floor Tile - ABATED			SW Entrance	Abated	MISC					
20M	12 x 12 White with Blue Streaks Floor Tile Mastic - ABATED			SW Entrance	Abated	MISC					
22	12 x 12 Tan Floor Tile	1,232	SF	Room 115 (Library)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
22M	12 x 12 Tan Floor Tile Mastic	1,232	SF	Room 115 (Library)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
23	Yellow Ceramic Tile Grout	332	SF	North Girls Restroom and Room 126 Womens Toilet	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
24	Yellow Ceramic Tile Adhesive	332	SF	North Girls Restroom and Room 126 Womens Toilet	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
25	Blue and White Ceramic Tile Grout	252	SF	Lunchroom Restroom	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
26	Blue and White Ceramic Tile Adhesive	252	SF	Lunchroom Restroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
27	5 x 3 Ceiling Tile	6,000	SF	Gym, boiler Room, Elec. Room	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
28	12 x 12 Aqua/Design Floor Tile	160	SF	Table in Storage Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
28M	12 x 12 Aqua/Design Floor Tile Mastic	160	SF	Table in Storage Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
29	2 x 2 Ceiling Tile	4,280	SF	Throughout Modular Bldg Except Restrooms	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
30	12 x 12 Tan Floor Tile	4,280	SF	Throughout Modular Bldg Except Restrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
30M	12 x 12 Tan Floor Tile Mastic	4,280	SF	Throughout Modular Bldg Except Restrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
31	Tan Baseboard	600	LF	Throughout Modular Bldg Except Restrooms	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
32	Blue Vinyl Flooring	192	SF	Boys Restrooms in Modular Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
33	Blue Vinyl Floor Adhesive	192	SF	Boys Restrooms in Modular Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
34	Pink Vinyl Floor	192	SF	Girls Restroom in Modular Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
35	Pink Vinyl Floor Mastic	192	SF	Girls Restroom in Modular Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
36	Tan Baseboard Mastic	600	SF	Throughout Modular Bldg Except Restrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
37	12" x 12" Beige Streaked VFT	3,000	SF	Corridors and Vestibules	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
37A	12" x 12" Beige Streaked VFT Mastic	3,000	SF	Corridors and Vestibules	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
38	12" x 12" Gray with Blue Streaked VFT	3,500	SF	Lunchroom, Kitchen, Main Office and Principals Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Pirie School
Address 650 E 85th Street

Unit 24971
 Chicago, IL, 60619

Building ID 5440
Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
38A	12" x 12" Gray with Blue Streaked VFT Mastic	3,500	SF	Lunchroom, Kitchen, Main Office and Principals Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
B	MJP E/F/V on Fiberglass Pipe Insulation	300	EA	In Corridors - Above 2x4 Drop In Ceiling Panels	Chrysotile	TSI	Yes	0	EA	6 ACBM with the potential for damage	Follow O&M Plan
C	Aircell Pipe Insulation	1,500	LF	Throughout Corridors, Lunchroom Storage, Copy Room, & Book Room	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
D	MJP E/F/V on Aircell Pipe Insulation	175	EA	Throughout Corridors	Chrysotile	TSI	Yes	0	EA	6 ACBM with the potential for damage	Follow O&M Plan
E	Cardboard Pipe Insulation	2,500	LF	In Corridors - Above 2x4 Drop In Ceiling Panels and at Classroom Induction Units	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
F	MJP E/F/V on Cardboard Pipe Insulation	150	EA	In Corridors - Above 2x4 Drop In Ceiling Panels	Chrysotile	TSI	Yes	0	EA	6 ACBM with the potential for damage	Follow O&M Plan
H	Boiler Gaskets			Boiler Room	No ACBM	TSI					
I	Incinerator Insulation (Fire Brick) - REMOVED			Inaccessible- Door Welded Shut	Assumed	MISC					
J	Roofing Panels	1,000	SF	Boiler Room and Gym	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
K	Various Styles 1 x 1 Ceiling Tile	26,000	SF	Throughout Classrooms, Including: Pre-Kindergarten, Classroom in Core of Building	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
L	2 x 4 Ceiling Tile	5,000	SF	Throughout Corridors	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
M	Plaster Ceiling	3,000	SF	Rooms 110, 111, 112, 113, 114, 115, 116, 107, 108 and 109	Assumed	TSI	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
N	Fiberglass Pipe Insulation and Assumed Wrap	400	LF	Boiler Room, Slop Sink Room and Lunch Room	Assumed	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Pirie School
Address 650 E 85th Street

Unit 24971
 Chicago, IL, 60619

Building ID 5440
Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG Consultants, Inc.
 855 W. Adams St., Ste. 200
 Phone: (312) 733-6262

Fax: (312) 733-5612

Management Planner's Comments Summarized at the End of the Report

Review Date	5/28/2016
Manager Planner Name	Arturo Saenz
100-04019	1/19/2017
Manager IDPH License No/Expiration	

HA Number	Management Comments
01A	
01B	
01C	
01D	
01E	
01F	
05	
07A	
07B	
07C	
07D	
07E	
07F	
08A	
08B	
09A	

Chicago Public Schools

School Pirie School
Address 650 E 85th Street

Unit 24971
Chicago, IL, 60619

Building ID 5440
Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
09B	
10	
11	
12	
13	
14	
15	
16	
17	
18	
19	
20	
20M	
22	
22M	
23	
24	
25	
26	
27	
28	
28M	
29	
30	
30M	
31	
32	

Chicago Public Schools

School Pirie School
Address 650 E 85th Street

Unit 24971
Chicago, IL, 60619

Building ID 5440
Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
33	
34	
35	
36	
37	
37A	
38	
38A	
B	
C	
D	
E	
F	
H	
I	
J	
K	
L	
M	
N	

Chicago Public Schools

GSG Consultants, Inc.

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Pirie School** INSPECTION DATE: **3/22/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **01A**
MATERIAL DESCRIPTION: **9x9 Salmon Floor Tile - ABATED**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Moderate**

MATERIAL LOCATION: **N.E. Corridor**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____



Date: 03/22/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Pirie School** REVIEW DATE: **5/28/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **01A**

MATERIAL DESCRIPTION: **9x9 Salmon Floor Tile - ABATED**

MATERIAL LOCATION: **N.E. Corridor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/28/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Pirie School** INSPECTION DATE: **3/22/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **01B**
MATERIAL DESCRIPTION: **9x9 White w/Black Streaks FloorTile - ABATED**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Moderate**

MATERIAL LOCATION: **All Corridors Except N.E. Corridor**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____



Date: 03/22/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUILDING ID: **5440**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Pirie School** REVIEW DATE: **5/28/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **01B**
MATERIAL DESCRIPTION: **9x9 White w/Black Streaks FloorTile - ABATED**
MATERIAL LOCATION: **All Corridors Except N.E. Corridor**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/28/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Pirie School** INSPECTION DATE: **3/22/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **01C**
MATERIAL DESCRIPTION: **9x9 Light Blue w/Blue & White Streaks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Rooms 111, 112 Lunch Room**
MATERIAL QUANTITY: **4200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/22/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Pirie School** REVIEW DATE: **5/28/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **01C**
MATERIAL DESCRIPTION: **9x9 Light Blue w/Blue & White Streaks Floor Tile**
MATERIAL LOCATION: **Rooms 111, 112 Lunch Room**
MATERIAL QUANTITY: **4200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/28/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Pirie School** INSPECTION DATE: **3/22/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **01D**
MATERIAL DESCRIPTION: **9x9 Gray Floor Tile - ABATED**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **Kitchen**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____



Date: 03/22/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Pirie School** REVIEW DATE: **5/28/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **01D**
MATERIAL DESCRIPTION: **9x9 Gray Floor Tile - ABATED**
MATERIAL LOCATION: **Kitchen**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/28/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Pirie School** INSPECTION DATE: **3/22/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **01E**
MATERIAL DESCRIPTION: **9x9 Light Green w/Black & White Streaks Floor Tile - ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 101**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/22/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Pirie School** REVIEW DATE: **5/28/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **01E**
MATERIAL DESCRIPTION: **9x9 Light Green w/Black & White Streaks Floor Tile - ABATED**
MATERIAL LOCATION: **Room 101**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/28/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Pirie School** INSPECTION DATE: **3/22/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **01F**
MATERIAL DESCRIPTION: **9x9 Tan w/Beige Streaks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **All Classrooms, Offices, Stage**
MATERIAL QUANTITY: **11500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/22/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Pirie School** REVIEW DATE: **5/28/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **01F**
MATERIAL DESCRIPTION: **9x9 Tan w/Beige Streaks Floor Tile**
MATERIAL LOCATION: **All Classrooms, Offices, Stage**
MATERIAL QUANTITY: **11500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/28/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Pirie School** INSPECTION DATE: **3/22/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **05**
MATERIAL DESCRIPTION: **Duct Sleeve (Vibration Dampener)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Boiler Room**
MATERIAL QUANTITY: **25** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/22/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Pirie School** REVIEW DATE: **5/28/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **05**
MATERIAL DESCRIPTION: **Duct Sleeve (Vibration Dampener)**
MATERIAL LOCATION: **Boiler Room**
MATERIAL QUANTITY: **25** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/28/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUILDING ID: **5440**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Pirie School** INSPECTION DATE: **3/22/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **07A**
MATERIAL DESCRIPTION: **9x9 Salmon Floor Tile Mastic - ABATED**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **N.E. Corridor**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/22/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Pirie School** REVIEW DATE: **5/28/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **07A**
MATERIAL DESCRIPTION: **9x9 Salmon Floor Tile Mastic - ABATED**
MATERIAL LOCATION: **N.E. Corridor**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/28/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Pirie School** INSPECTION DATE: **3/22/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **07B**
MATERIAL DESCRIPTION: **9x9 White w/Black Streaks FloorTile Mastic - ABATED**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **All Corridors Except N.E. Corridor**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____



Date: 03/22/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Pirie School** REVIEW DATE: **5/28/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **07B**
MATERIAL DESCRIPTION: **9x9 White w/Black Streaks FloorTile Mastic - ABATED**
MATERIAL LOCATION: **All Corridors Except N.E. Corridor**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/28/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Pirie School** INSPECTION DATE: **3/22/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **07C**
MATERIAL DESCRIPTION: **9x9 Light Blue w/Blue & White Streaks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 116, 111**
MATERIAL QUANTITY: **4200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/22/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Pirie School** REVIEW DATE: **5/28/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **07C**
MATERIAL DESCRIPTION: **9x9 Light Blue w/Blue & White Streaks Floor Tile**
MATERIAL LOCATION: **Rooms 116, 111**
MATERIAL QUANTITY: **4200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/28/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Pirie School** INSPECTION DATE: **3/22/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **07D**
MATERIAL DESCRIPTION: **9x9 Gray Floor Tile Mastic - ABATED**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **Kitchen**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____



Date: 03/22/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Pirie School** REVIEW DATE: **5/28/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **07D**
MATERIAL DESCRIPTION: **9x9 Gray Floor Tile Mastic - ABATED**
MATERIAL LOCATION: **Kitchen**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/28/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Pirie School** INSPECTION DATE: **3/22/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **07E**
MATERIAL DESCRIPTION: **9x9 Light Green w/Black & White Streaks Floor Tile Mastic - ABATED**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Main Office & Principal's Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/22/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUILDING ID: **5440**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Pirie School** REVIEW DATE: **5/28/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **07E**
MATERIAL DESCRIPTION: **9x9 Light Green w/Black & White Streaks Floor Tile Mastic - ABATED**
MATERIAL LOCATION: **Main Office & Principal's Office**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/28/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Pirie School** INSPECTION DATE: **3/22/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **07F**
MATERIAL DESCRIPTION: **9x9 Tan w/Beige Streaks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **All Classrooms, Offices, Stage (Except Rooms 111,112) and Engineer Office**
MATERIAL QUANTITY: **11500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/22/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUILDING ID: **5440**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Pirie School** REVIEW DATE: **5/28/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **07F**
MATERIAL DESCRIPTION: **9x9 Tan w/Beige Streaks Floor Tile Mastic**
MATERIAL LOCATION: **All Classrooms, Offices, Stage (Except Rooms 111,112) and Engineer Office**
MATERIAL QUANTITY: **11500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/28/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Pirie School** INSPECTION DATE: **3/22/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **08A**
MATERIAL DESCRIPTION: **12x12 Aqua Floor Tile - ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **South Entrance**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/22/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUILDING ID: **5440**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Pirie School** REVIEW DATE: **5/28/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **08A**

MATERIAL DESCRIPTION: **12x12 Aqua Floor Tile - ABATED**

MATERIAL LOCATION: **South Entrance**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/28/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Pirie School** INSPECTION DATE: **3/22/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **08B**
MATERIAL DESCRIPTION: **12x12 Beige w/Tan Streaks Floor Tile - ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **NE and NW Entrances & Patches in Corridors**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/22/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUILDING ID: **5440**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Pirie School** REVIEW DATE: **5/28/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **08B**
MATERIAL DESCRIPTION: **12x12 Beige w/Tan Streaks Floor Tile - ABATED**
MATERIAL LOCATION: **NE and NW Entrances & Patches in Corridors**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/28/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Pirie School** INSPECTION DATE: **3/22/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **09A**
MATERIAL DESCRIPTION: **12x12 Aqua Floor Tile Mastic - ABATED**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **South Entrance**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____



Date: 03/22/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Pirie School** REVIEW DATE: **5/28/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **09A**
MATERIAL DESCRIPTION: **12x12 Aqua Floor Tile Mastic - ABATED**
MATERIAL LOCATION: **South Entrance**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/28/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Pirie School** INSPECTION DATE: **3/22/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **09B**
MATERIAL DESCRIPTION: **12x12 Beige w/Tan Streaks Floor Tile Mastic - ABATED**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **NE and NW Entrances & Patches in Corridors**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____



Date: 03/22/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Pirie School** REVIEW DATE: **5/28/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **09B**
MATERIAL DESCRIPTION: **12x12 Beige w/Tan Streaks Floor Tile Mastic - ABATED**
MATERIAL LOCATION: **NE and NW Entrances & Patches in Corridors**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/28/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Pirie School** INSPECTION DATE: **3/22/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10**
MATERIAL DESCRIPTION: **Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 111 and Book Room**
MATERIAL QUANTITY: **3740** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/22/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Pirie School** REVIEW DATE: **5/28/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **10**
MATERIAL DESCRIPTION: **Carpet Mastic**
MATERIAL LOCATION: **Room 111 and Book Room**
MATERIAL QUANTITY: **3740** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/28/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Pirie School** INSPECTION DATE: **3/22/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11**
MATERIAL DESCRIPTION: **1 x 1 Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout Classrooms except Gym, Kitchen, Boys and Girls Restrooms**
MATERIAL QUANTITY: **33536** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/22/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUILDING ID: **5440**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Pirie School** REVIEW DATE: **5/28/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **11**
MATERIAL DESCRIPTION: **1 x 1 Ceiling Tile**
MATERIAL LOCATION: **Throughout Classrooms except Gym, Kitchen, Boys and Girls Restrooms**
MATERIAL QUANTITY: **33536** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/28/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Pirie School** INSPECTION DATE: **3/22/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12**
MATERIAL DESCRIPTION: **Brown, Tan and White Ceramic Tile Grout**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Principal's Office Toilet, Library Toilet and Room 126 Toilet**
MATERIAL QUANTITY: **79** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/22/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Pirie School** REVIEW DATE: **5/28/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **12**
MATERIAL DESCRIPTION: **Brown, Tan and White Ceramic Tile Grout**
MATERIAL LOCATION: **Principal's Office Toilet, Library Toilet and Room 126 Toilet**
MATERIAL QUANTITY: **79** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/28/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Pirie School** INSPECTION DATE: **3/22/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13**
MATERIAL DESCRIPTION: **Brown, Tan and White Ceramic Tile Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Principal's Office Toilet, Library Toilet and Room 126 Toilet**
MATERIAL QUANTITY: **79** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/22/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Pirie School** REVIEW DATE: **5/28/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **13**
MATERIAL DESCRIPTION: **Brown, Tan and White Ceramic Tile Adhesive**
MATERIAL LOCATION: **Principal's Office Toilet, Library Toilet and Room 126 Toilet**
MATERIAL QUANTITY: **79** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/28/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Pirie School** INSPECTION DATE: **3/22/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14**
MATERIAL DESCRIPTION: **Insulation Inside Vault Door**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Main Office**
MATERIAL QUANTITY: **1** MATERIAL UNITS: **EA**
DAMAGE QUANTITY: DAMAGE UNITS: **EA**

COMMENTS:

Inspector's Signature: _____



Date: 03/22/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Pirie School** REVIEW DATE: **5/28/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **14**

MATERIAL DESCRIPTION: **Insulation Inside Vault Door**

MATERIAL LOCATION: **Main Office**

MATERIAL QUANTITY: **1**

MATERIAL UNITS: **EA**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **EA**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/28/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Pirie School** INSPECTION DATE: **3/22/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15**
MATERIAL DESCRIPTION: **Peach, Blue, Yellow and White Ceramic Tile Grout**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Councilor's Toilet and Room 116 Toilet**
MATERIAL QUANTITY: **49** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/22/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Pirie School** REVIEW DATE: **5/28/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **15**
MATERIAL DESCRIPTION: **Peach, Blue, Yellow and White Ceramic Tile Grout**
MATERIAL LOCATION: **Councilor's Toilet and Room 116 Toilet**
MATERIAL QUANTITY: **49** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/28/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Pirie School** INSPECTION DATE: **3/22/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16**
MATERIAL DESCRIPTION: **Peach, Blue, Yellow and White Ceramic Tile Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Councilor's Toilet and Room 116 Toilet**
MATERIAL QUANTITY: **49** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/22/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Pirie School** REVIEW DATE: **5/28/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **16**
MATERIAL DESCRIPTION: **Peach, Blue, Yellow and White Ceramic Tile Adhesive**
MATERIAL LOCATION: **Councilor's Toilet and Room 116 Toilet**
MATERIAL QUANTITY: **49** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/28/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Pirie School** INSPECTION DATE: **3/22/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17**
MATERIAL DESCRIPTION: **Grey, Yellow and White Ceramic Tile Grout**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **South Boys Restroom**
MATERIAL QUANTITY: **308** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/22/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUILDING ID: **5440**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Pirie School** REVIEW DATE: **5/28/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **17**
MATERIAL DESCRIPTION: **Grey, Yellow and White Ceramic Tile Grout**
MATERIAL LOCATION: **South Boys Restroom**
MATERIAL QUANTITY: **308** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/28/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Pirie School** INSPECTION DATE: **3/22/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18**
MATERIAL DESCRIPTION: **Grey, Yellow and White Ceramic Tile Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **South Boys Restroom**
MATERIAL QUANTITY: **308** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/22/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Pirie School** REVIEW DATE: **5/28/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **18**
MATERIAL DESCRIPTION: **Grey, Yellow and White Ceramic Tile Adhesive**
MATERIAL LOCATION: **South Boys Restroom**
MATERIAL QUANTITY: **308** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/28/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Pirie School** INSPECTION DATE: **3/22/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19**
MATERIAL DESCRIPTION: **Blue Ceramic Tile Grout**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **South Girls Restroom and North Boys Restroom**
MATERIAL QUANTITY: **616** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/22/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUILDING ID: **5440**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Pirie School** REVIEW DATE: **5/28/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **19**
MATERIAL DESCRIPTION: **Blue Ceramic Tile Grout**
MATERIAL LOCATION: **South Girls Restroom and North Boys Restroom**
MATERIAL QUANTITY: **616** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/28/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUILDING ID: **5440**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Pirie School** INSPECTION DATE: **3/22/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**
MATERIAL DESCRIPTION: **12 x 12 White with Blue Streaks Floor Tile - ABATED**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **SW Entrance**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____



Date: 03/22/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Pirie School** REVIEW DATE: **5/28/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **20**

MATERIAL DESCRIPTION: **12 x 12 White with Blue Streaks Floor Tile - ABATED**

MATERIAL LOCATION: **SW Entrance**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/28/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Pirie School** INSPECTION DATE: **3/22/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20M**
MATERIAL DESCRIPTION: **12 x 12 White with Blue Streaks Floor Tile Mastic - ABATED**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **SW Entrance**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____



Date: 03/22/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Pirie School** REVIEW DATE: **5/28/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **20M**
MATERIAL DESCRIPTION: **12 x 12 White with Blue Streaks Floor Tile Mastic - ABATED**
MATERIAL LOCATION: **SW Entrance**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/28/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Pirie School** INSPECTION DATE: **3/22/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22**
MATERIAL DESCRIPTION: **12 x 12 Tan Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 115 (Library)**
MATERIAL QUANTITY: **1232** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/22/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Pirie School** REVIEW DATE: **5/28/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **22**
MATERIAL DESCRIPTION: **12 x 12 Tan Floor Tile**
MATERIAL LOCATION: **Room 115 (Library)**
MATERIAL QUANTITY: **1232** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/28/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Pirie School** INSPECTION DATE: **3/22/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22M**
MATERIAL DESCRIPTION: **12 x 12 Tan Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**
MATERIAL LOCATION: **Room 115 (Library)**
MATERIAL QUANTITY: **1232** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/22/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Pirie School** REVIEW DATE: **5/28/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **22M**
MATERIAL DESCRIPTION: **12 x 12 Tan Floor Tile Mastic**
MATERIAL LOCATION: **Room 115 (Library)**
MATERIAL QUANTITY: **1232** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/28/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Pirie School** INSPECTION DATE: **3/22/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23**
MATERIAL DESCRIPTION: **Yellow Ceramic Tile Grout**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **North Girls Restroom and Room 126 Womens Toilet**
MATERIAL QUANTITY: **332** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/22/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Pirie School** REVIEW DATE: **5/28/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **23**
MATERIAL DESCRIPTION: **Yellow Ceramic Tile Grout**
MATERIAL LOCATION: **North Girls Restroom and Room 126 Womens Toilet**
MATERIAL QUANTITY: **332** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/28/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Pirie School** INSPECTION DATE: **3/22/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **24**
MATERIAL DESCRIPTION: **Yellow Ceramic Tile Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **North Girls Restroom and Room 126 Womens Toilet**
MATERIAL QUANTITY: **332** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/22/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Pirie School** REVIEW DATE: **5/28/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **24**
MATERIAL DESCRIPTION: **Yellow Ceramic Tile Adhesive**
MATERIAL LOCATION: **North Girls Restroom and Room 126 Womens Toilet**
MATERIAL QUANTITY: **332** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/28/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Pirie School** INSPECTION DATE: **3/22/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25**
MATERIAL DESCRIPTION: **Blue and White Ceramic Tile Grout**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Lunchroom Restroom**
MATERIAL QUANTITY: **252** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/22/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Pirie School** REVIEW DATE: **5/28/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **25**
MATERIAL DESCRIPTION: **Blue and White Ceramic Tile Grout**
MATERIAL LOCATION: **Lunchroom Restroom**
MATERIAL QUANTITY: **252** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/28/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Pirie School** INSPECTION DATE: **3/22/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26**
MATERIAL DESCRIPTION: **Blue and White Ceramic Tile Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Lunchroom Restroom**
MATERIAL QUANTITY: **252** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/22/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Pirie School** REVIEW DATE: **5/28/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **26**
MATERIAL DESCRIPTION: **Blue and White Ceramic Tile Adhesive**
MATERIAL LOCATION: **Lunchroom Restroom**
MATERIAL QUANTITY: **252** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/28/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Pirie School** INSPECTION DATE: **3/22/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27**
MATERIAL DESCRIPTION: **5 x 3 Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Gym, boiler Room, Elec. Room**
MATERIAL QUANTITY: **6000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/22/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Pirie School** REVIEW DATE: **5/28/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **27**
MATERIAL DESCRIPTION: **5 x 3 Ceiling Tile**
MATERIAL LOCATION: **Gym, boiler Room, Elec. Room**
MATERIAL QUANTITY: **6000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/28/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Pirie School** INSPECTION DATE: **3/22/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28**
MATERIAL DESCRIPTION: **12 x 12 Aqua/Design Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Table in Storage Room**
MATERIAL QUANTITY: **160** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/22/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Pirie School** REVIEW DATE: **5/28/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **28**
MATERIAL DESCRIPTION: **12 x 12 Aqua/Design Floor Tile**
MATERIAL LOCATION: **Table in Storage Room**
MATERIAL QUANTITY: **160** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/28/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Pirie School** INSPECTION DATE: **3/22/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28M**
MATERIAL DESCRIPTION: **12 x 12 Aqua/Design Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Table in Storage Room**
MATERIAL QUANTITY: **160** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/22/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Pirie School** REVIEW DATE: **5/28/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **28M**
MATERIAL DESCRIPTION: **12 x 12 Aqua/Design Floor Tile Mastic**
MATERIAL LOCATION: **Table in Storage Room**
MATERIAL QUANTITY: **160** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/28/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Pirie School** INSPECTION DATE: **3/22/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **29**
MATERIAL DESCRIPTION: **2 x 2 Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout Modular Bldg Except Restrooms**
MATERIAL QUANTITY: **4280** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/22/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Pirie School** REVIEW DATE: **5/28/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **29**
MATERIAL DESCRIPTION: **2 x 2 Ceiling Tile**
MATERIAL LOCATION: **Throughout Modular Bldg Except Restrooms**
MATERIAL QUANTITY: **4280** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/28/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Pirie School** INSPECTION DATE: **3/22/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **30**
MATERIAL DESCRIPTION: **12 x 12 Tan Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout Modular Bldg Except Restrooms**
MATERIAL QUANTITY: **4280** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/22/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Pirie School** REVIEW DATE: **5/28/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **30**
MATERIAL DESCRIPTION: **12 x 12 Tan Floor Tile**
MATERIAL LOCATION: **Throughout Modular Bldg Except Restrooms**
MATERIAL QUANTITY: **4280** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/28/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Pirie School** INSPECTION DATE: **3/22/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **30M**
MATERIAL DESCRIPTION: **12 x 12 Tan Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout Modular Bldg Except Restrooms**
MATERIAL QUANTITY: **4280** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/22/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Pirie School** REVIEW DATE: **5/28/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **30M**
MATERIAL DESCRIPTION: **12 x 12 Tan Floor Tile Mastic**
MATERIAL LOCATION: **Throughout Modular Bldg Except Restrooms**
MATERIAL QUANTITY: **4280** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/28/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Pirie School** INSPECTION DATE: **3/22/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **31**
MATERIAL DESCRIPTION: **Tan Baseboard**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout Modular Bldg Except Restrooms**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____



Date: 03/22/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUILDING ID: **5440**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Pirie School** REVIEW DATE: **5/28/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **31**
MATERIAL DESCRIPTION: **Tan Baseboard**
MATERIAL LOCATION: **Throughout Modular Bldg Except Restrooms**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/28/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Pirie School** INSPECTION DATE: **3/22/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **32**
MATERIAL DESCRIPTION: **Blue Vinyl Flooring**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Boys Restrooms in Modular Bldg**
MATERIAL QUANTITY: **192** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/22/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Pirie School** REVIEW DATE: **5/28/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **32**
MATERIAL DESCRIPTION: **Blue Vinyl Flooring**
MATERIAL LOCATION: **Boys Restrooms in Modular Bldg**
MATERIAL QUANTITY: **192** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/28/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Pirie School** INSPECTION DATE: **3/22/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **33**
MATERIAL DESCRIPTION: **Blue Vinyl Floor Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Boys Restrooms in Modular Bldg**
MATERIAL QUANTITY: **192** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: **03/22/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Pirie School** REVIEW DATE: **5/28/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **33**
MATERIAL DESCRIPTION: **Blue Vinyl Floor Adhesive**
MATERIAL LOCATION: **Boys Restrooms in Modular Bldg**
MATERIAL QUANTITY: **192** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/28/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Pirie School** INSPECTION DATE: **3/22/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **34**
MATERIAL DESCRIPTION: **Pink Vinyl Floor**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Girls Restroom in Modular Bldg**
MATERIAL QUANTITY: **192** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/22/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Pirie School** REVIEW DATE: **5/28/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **34**
MATERIAL DESCRIPTION: **Pink Vinyl Floor**
MATERIAL LOCATION: **Girls Restroom in Modular Bldg**
MATERIAL QUANTITY: **192** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/28/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Pirie School** INSPECTION DATE: **3/22/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **35**
MATERIAL DESCRIPTION: **Pink Vinyl Floor Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Girls Restroom in Modular Bldg**
MATERIAL QUANTITY: **192** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/22/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Pirie School** REVIEW DATE: **5/28/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **35**
MATERIAL DESCRIPTION: **Pink Vinyl Floor Mastic**
MATERIAL LOCATION: **Girls Restroom in Modular Bldg**
MATERIAL QUANTITY: **192** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/28/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Pirie School** INSPECTION DATE: **3/22/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **36**
MATERIAL DESCRIPTION: **Tan Baseboard Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout Modular Bldg Except Restrooms**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/22/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUILDING ID: **5440**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Pirie School** REVIEW DATE: **5/28/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **36**
MATERIAL DESCRIPTION: **Tan Baseboard Mastic**
MATERIAL LOCATION: **Throughout Modular Bldg Except Restrooms**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/28/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Pirie School** INSPECTION DATE: **3/22/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37**
MATERIAL DESCRIPTION: **12" x 12" Beige Streaked VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Corridors and Vestibules**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/22/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Pirie School** REVIEW DATE: **5/28/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **37**
MATERIAL DESCRIPTION: **12" x 12" Beige Streaked VFT**
MATERIAL LOCATION: **Corridors and Vestibules**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/28/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Pirie School** INSPECTION DATE: **3/22/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37A**
MATERIAL DESCRIPTION: **12" x 12" Beige Streaked VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Corridors and Vestibules**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/22/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Pirie School** REVIEW DATE: **5/28/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **37A**
MATERIAL DESCRIPTION: **12" x 12" Beige Streaked VFT Mastic**
MATERIAL LOCATION: **Corridors and Vestibules**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/28/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Pirie School** INSPECTION DATE: **3/22/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **38**
MATERIAL DESCRIPTION: **12" x 12" Gray with Blue Streaked VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Lunchroom, Kitchen, Main Office and Principals Office**
MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/22/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Pirie School** REVIEW DATE: **5/28/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **38**
MATERIAL DESCRIPTION: **12" x 12" Gray with Blue Streaked VFT**
MATERIAL LOCATION: **Lunchroom, Kitchen, Main Office and Principals Office**
MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/28/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Pirie School** INSPECTION DATE: **3/22/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **38A**
MATERIAL DESCRIPTION: **12" x 12" Gray with Blue Streaked VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Lunchroom, Kitchen, Main Office and Principals Office**
MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/22/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Pirie School** REVIEW DATE: **5/28/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **38A**
MATERIAL DESCRIPTION: **12" x 12" Gray with Blue Streaked VFT Mastic**
MATERIAL LOCATION: **Lunchroom, Kitchen, Main Office and Principals Office**
MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/28/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Pirie School** INSPECTION DATE: **3/22/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **B**
MATERIAL DESCRIPTION: **MJP E/F/V on Fiberglass Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **In Corridors - Above 2x4 Drop In Ceiling Panels**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **EA**
DAMAGE QUANTITY: DAMAGE UNITS: **EA**

COMMENTS:

Inspector's Signature: _____



Date: 03/22/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Pirie School** REVIEW DATE: **5/28/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **B**
MATERIAL DESCRIPTION: **MJP E/F/V on Fiberglass Pipe Insulation**
MATERIAL LOCATION: **In Corridors - Above 2x4 Drop In Ceiling Panels**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **EA**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/28/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Pirie School** INSPECTION DATE: **3/22/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **C**
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout Corridors, Lunchroom Storage, Copy Room, & Book Room**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____



Date: 03/22/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Pirie School** REVIEW DATE: **5/28/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **C**
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**
MATERIAL LOCATION: **Throughout Corridors, Lunchroom Storage, Copy Room, & Book Room**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/28/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Pirie School** INSPECTION DATE: **3/22/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **D**
MATERIAL DESCRIPTION: **MJP E/F/V on Aircell Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout Corridors**
MATERIAL QUANTITY: **175** MATERIAL UNITS: **EA**
DAMAGE QUANTITY: DAMAGE UNITS: **EA**

COMMENTS:

Inspector's Signature: _____



Date: 03/22/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Pirie School** REVIEW DATE: **5/28/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **D**
MATERIAL DESCRIPTION: **MJP E/F/V on Aircell Pipe Insulation**
MATERIAL LOCATION: **Throughout Corridors**
MATERIAL QUANTITY: **175** MATERIAL UNITS: **EA**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/28/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Pirie School** INSPECTION DATE: **3/22/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **E**
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **In Corridors - Above 2x4 Drop In Ceiling Panels and at Classroom Induction Units**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**
COMMENTS:

Inspector's Signature: _____



Date: **03/22/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Pirie School** REVIEW DATE: **5/28/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **E**
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**
MATERIAL LOCATION: **In Corridors - Above 2x4 Drop In Ceiling Panels and at Classroom Induction Units**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/28/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Pirie School** INSPECTION DATE: **3/22/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **F**
MATERIAL DESCRIPTION: **MJP E/F/V on Cardboard Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **In Corridors - Above 2x4 Drop In Ceiling Panels**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **EA**
DAMAGE QUANTITY: DAMAGE UNITS: **EA**

COMMENTS:

Inspector's Signature: _____



Date: 03/22/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Pirie School** REVIEW DATE: **5/28/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **F**
MATERIAL DESCRIPTION: **MJP E/F/V on Cardboard Pipe Insulation**
MATERIAL LOCATION: **In Corridors - Above 2x4 Drop In Ceiling Panels**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **EA**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/28/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Pirie School** INSPECTION DATE: **3/22/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **H**
MATERIAL DESCRIPTION: **Boiler Gaskets**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/22/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUILDING ID: **5440**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Pirie School** REVIEW DATE: **5/28/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **H**
MATERIAL DESCRIPTION: **Boiler Gaskets**
MATERIAL LOCATION: **Boiler Room**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/28/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Pirie School** INSPECTION DATE: **3/22/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **I**
MATERIAL DESCRIPTION: **Incinerator Insulation (Fire Brick) - REMOVED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Inaccessible- Door Welded Shut**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/22/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Pirie School** REVIEW DATE: **5/28/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **I**

MATERIAL DESCRIPTION: **Incinerator Insulation (Fire Brick) - REMOVED**

MATERIAL LOCATION: **Inaccessible- Door Welded Shut**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/28/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Pirie School** INSPECTION DATE: **3/22/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **J**
MATERIAL DESCRIPTION: **Roofing Panels**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Boiler Room and Gym**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/22/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Pirie School** REVIEW DATE: **5/28/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **J**
MATERIAL DESCRIPTION: **Roofing Panels**
MATERIAL LOCATION: **Boiler Room and Gym**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/28/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Pirie School** INSPECTION DATE: **3/22/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **K**
MATERIAL DESCRIPTION: **Various Styles 1 x 1 Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout Classrooms, Including: Pre-Kindergarten, Classroom in Core of Building**
MATERIAL QUANTITY: **26000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 03/22/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Pirie School** REVIEW DATE: **5/28/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **K**
MATERIAL DESCRIPTION: **Various Styles 1 x 1 Ceiling Tile**
MATERIAL LOCATION: **Throughout Classrooms, Including: Pre-Kindergarten, Classroom in Core of Building**
MATERIAL QUANTITY: **26000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/28/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Pirie School** INSPECTION DATE: **3/22/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **L**
MATERIAL DESCRIPTION: **2 x 4 Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout Corridors**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/22/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUILDING ID: **5440**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Pirie School** REVIEW DATE: **5/28/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **L**
MATERIAL DESCRIPTION: **2 x 4 Ceiling Tile**
MATERIAL LOCATION: **Throughout Corridors**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/28/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Pirie School** INSPECTION DATE: **3/22/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **M**
MATERIAL DESCRIPTION: **Plaster Ceiling**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 110, 111, 112, 113, 114, 115, 116, 107, 108 and 109**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/22/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Pirie School** REVIEW DATE: **5/28/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **M**
MATERIAL DESCRIPTION: **Plaster Ceiling**
MATERIAL LOCATION: **Rooms 110, 111, 112, 113, 114, 115, 116, 107, 108 and 109**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/28/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Pirie School** INSPECTION DATE: **3/22/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **N**
MATERIAL DESCRIPTION: **Fiberglass Pipe Insulation and Assumed Wrap**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Boiler Room, Slop Sink Room and Lunch Room**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____



Date: 03/22/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24971** BUIDLING ID: **5440**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Pirie School** REVIEW DATE: **5/28/2016**
ADDRESS: **650 E 85th Street** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **N**
MATERIAL DESCRIPTION: **Fiberglass Pipe Insulation and Assumed Wrap**
MATERIAL LOCATION: **Boiler Room, Slop Sink Room and Lunch Room**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/28/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

APPENDIX B

Inspector and Management Planner Licenses

CERTIFICATE OF ACHIEVEMENT ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that TOMMY R. THOMPSON
has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the
examination on 02/13/2016 with a minimum score of 70% or better. Training was in accordance
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:
Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.

02/13/2016

Course Dates: _____

02/13/2017

Expires: _____

1602BIR21

Certificate Number: _____



PUBLIC HEALTH & SAFETY inc.
Environmental and Occupational Services
1035 Ashland Ave., Chicago, IL 60607

Nicholas J. Peneff

Director of Training
Nicholas J. Peneff
Doctor of Public Health

Phone: 312-491-0081

FORM # A-010B



625-955 West Jefferson Street • Springfield, Illinois 62761-0001 • www.dph.illinois.gov

4/18/2016

TOMMY THOMPSON
855 W. Adams, Suite 200
Chicago, IL 60607

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 08023

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

		ASBESTOS PROFESSIONAL LICENSE		ENDORSEMENTS INSPECTOR	TC EXPIRES 2/13/2017
ID NUMBER 100 - 08023	ISSUED 4/18/2016	EXPIRES 05/15/2017		PROJECT MANAGER AIR SAMPLING PROFESSIONAL	2/6/2017
TOMMY THOMPSON 855 W. Adams, Suite 200 Chicago, IL 60607 Environmental Health		Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.			

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH, IMPROVING LIVES
Nationally Accredited by NABH



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • www.idph.illinois.gov

4/18/2016

ARTURO SAENZ
855 W ADAMS ST SUITE 200
CHICAGO, IL 60607

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 04019

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

 <p>ASBESTOS PROFESSIONAL LICENSE</p>			<p>ENDORSEMENTS</p> <p>INSPECTOR</p> <p>MANAGEMENT PLANNER</p> <p>AIR SAMPLING PROFESSIONAL</p> <p>Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.</p>	<p>TC EXPIRES</p> <p>1/19/2017</p> <p>1/27/2017</p>
<p>ID NUMBER 100 - 04019</p> <p>ARTURO SAENZ 855 W ADAMS ST SUITE 200 CHICAGO, IL 60607 Environmental Health</p>	<p>ISSUED 4/18/2016</p>	<p>EXPIRES 05/13/2017</p> 		

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH, IMPROVING LIVES
Nationally Accredited by PHAB

2016



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Arturo Saenz

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 1/27/2016

Exam Date: 1/27/2016

Expiration Date: 1/27/2017

Certificate Number: MPR1601270319

Kathy DeSalvo, Director

2016



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Jigar Shah

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 1/27/2016

Exam Date: 1/27/2016

Expiration Date: 1/27/2017

Certificate Number: MPR1601270320

Kathy DeSalvo, Director

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL		
	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE		
	Loc	Localized
	Dist	Distributed