

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM**

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-2410
SCHOOL NAME: Prescott School
ADDRESS OF SCHOOL: 1632 W. Wrightwood Avenue
CITY: Chicago, IL, 60614

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **4/6/2013**

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II (Please type or print)

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 5/25/2016 ENROLLMENT 377
IDPH INSPECTOR LICENSE NUMBER: 100-11255
IDPH LICENSED INSPECTOR NAME (Please Print): Esteban Nunez
IDPH MP LICENSE NUMBER: 100-01786
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Guillermo Garcia

DESIGNATED PERSON (Please Print): Robert Christlieb PHONE: (773) 553-3197



5/25/2016

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Prescott School

1632 W. Wrightwood Avenue
Chicago, IL, 60614

Unit: 25021
Building ID: 5500

IDPH ID Number: 14-016-2990-2410

REPORT DATE:

Wednesday, May 25, 2016

Prepared for:

Chicago Public Schools
125 S. Clark Street
Chicago, IL 60603

Prepared by:

GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone (312) 733-6262

Fax (312) 733-5612

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

May 10, 2016

Mr. R. Kent Cook
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2016 Three-Year Reinspections

Dear Mr. Cook:

GSG Consultants, Inc., Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 1,2,6 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 25021 Region: 02 IDPH ID: 14-016-2990-2410

School: Prescott School Building ID: 5500

Address: 1632 W. Wrightwood Avenue
Chicago, IL, 60614

Building Contact: Mcardle, James Contact Phone: 773-679-0649

Current Building Owners: Chicago Public Schools

Review Date: 05/24/2016

Inspector: Esteban Nunez Inspector IDPH License: 100-11255
Management Planner: Guillermo Garcia Management Planner IDPH License: 100-01786

If you have any questions or comments, please contact us at (312) 733-6262

Sincerely,
GSG Consultants, Inc.



Guillermo Garcia
100-01786

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: May 10, 2016

RE: Prescott School, Unit 25021
1632 W. Wrightwood Avenue
Chicago, IL, 60614

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2016 asbestos three year re-inspection has been completed at Prescott School , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at Prescott School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Robert Christlieb, the designated Local Education Authority's Designated Person at (773) 553-3197 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Prescott School Unit: 25021 Region: 02
Address: 1632 W. Wrightwood Avenue Chicago, IL, 60614
IDPH ID: 14-016-2990-2410 Building ID: 5500
Contact: Mcardle, James Phone: 773-679-0649

2. Description of Facility

Original Construction: 1900 Additional Construction: 1936
Total Square Footage: 33794 No of Floors: 3
Current Occupancy: 377

3. LEA Designated Person

Contact: Robert Christlieb Phone: (773) 553-3197
Address: 125 South Clark Street, 17th Floor
Chicago, IL 60603


4. Managing Environmental Consultant

MEC: GSG Consultants, Inc.
Contact: Arturo Saenz
Address 855 W. Adams St., Ste. 200
Phone: (312) 733-6262 Fax: (312) 733-5612

5. Inspector

Inspector Name: Esteban Nunez


Inspector IDPH license # 100-11255


Signature:
Date: 5/10/2016

6. Management Planner

Management Planner Name: Guillermo Garcia

Management Planner IDPH license # 100-01786


Signature:
Date: 05/24/2016

7. Review Date: 05/24/2016

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature:



Date: 5/25/2016

Name: Robert Christlieb

II. EXECUTIVE SUMMARY

GSG Consultants, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Prescott School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 5500:

10	9"x9" Brown w/ Yellow & White Streaks VFT
11	9"x9" Brown w/ Yellow & White Streaks VFT Mastic
22	2'x4' White w/ Small Grooves Ceiling Tile
25	12 x 12 Cream with Brown and White Streaks Floor Tile

B. The following new homogenous areas have been identified for Building 5500:

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

20	Brown Linoleum Not Observed
21	Brown Linoleum Mastic Not Observed
22	2'x4' White w/ Small Grooves Ceiling Tile
23	Hard Coat Plaster
24	Carpet Mastic
25	12 x 12 Cream with Brown and White Streaks Floor Tile
26	12 x 12 Cream with Brown and White Streaks Floor Tile Mastic
27	12 x 12 Brown with Brown and White Streaks Floor Tile
28	12 x 12 Brown with Brown and White Streaks Floor Tile Mastic
29	12 x 12 Grey with Grey Specks Floor Tile
30	12 x 12 Grey with Grey Specks Floor Tile Mastic
31	Blue/Peach Multicolored Carpet Mastic Not Observed

The following areas were deemed to be inaccessible:

24	Carpet Mastic
26	12 x 12 Cream with Brown and White Streaks Floor Tile Mastic
28	12 x 12 Brown with Brown and White Streaks Floor Tile Mastic
30	12 x 12 Grey with Grey Specks Floor Tile Mastic
31	Blue/Peach Multicolored Carpet Mastic Not Observed

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Esteban Nunez, IDPH License # 100-11255. The Management Plan was updated by Guillermo Garcia, IDPH License # 100-01786. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Prescott School Building 5500 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Prescott School Unit 25021 Building ID 5500

Address 1632 W. Wrightwood Avenue Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
02	9"x9" Light Gray w/ White & Orange Streaks VFT	1,500	SF	Art Room & Engineer's Office - 1890 Bldg	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
03	9"x9" Black w/ White & Orange Streaks Mastic	800	SF	Room 001 - 1890 Bldg	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
04	12"x12" Beige w/ Dark Brown & White Streaks VFT	10,060	SF	Room 301, 304, 201, 204, 104, 103, 1st, 2nd & 3rd Floor Corridors - 1890 Bldg	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
05	9"x9" Lt Gray w/ White & Orange Streaks VFT Mastic	1,500	SF	Art Room & Engineer's Office - 1890 Bldg	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
07	9"x9" Black w/ White Streaks VFT Mastic (Not Observed)	900	SF	Room 101 - 1890 Bldg	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
08	12"x12" Beige w/ Dark Brown & White Streaks VFT	5,750	SF	Room 305, 306, 307, 205, 206, 207, 105, 106, 107, 1st, 2nd & 3rd Floor Corridors - 1937 Bldg	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
09	12"x12" Beige w/ Dk Brn & White Streaks VFT Mastic	6,750	SF	Room 305, 306, 307, 205, 206, 207, 105, 106, 107, 1st, 2nd & 3rd Floor Corridors - 1937 Bldg	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
10	9"x9" Brown w/ Yellow & White Streaks VFT	1,150	SF	Room 007, Engineer's Office & Closet - 1937 Bldg	CHR	MISC	N	NONE	3		Yes	ACBM with the potential for damage	5	MODERATE
11	9"x9" Brown w/ Yellow & White Streaks VFT Mastic	1,150	SF	Room 007, Engineer's Office & Closet - 1937 Bldg	CHR	MISC	N	NONE	3		Yes	ACBM with the potential for damage	5	LOW
14	9"x9" Dark Brown w/ Orange & White VFT	250	SF	Room 001 Closet and Room 007C - 1890 Bldg	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
15	9"x9" Dark Brown w/ Orange & White VFT Mastic	250	SF	Room 001 Closet - 1890 Bldg	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
16	12"x12" Black w/ White Streaks VFT	250	SF	Room 001 Closet - 1890 Bldg	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
17	12"x12" Black w/ White Streaks VFT Mastic	50	SF	Room 001 Closet - 1890 Bldg	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
18	12"x12" Light Brown w/ White VFT	750	SF	Public Space (Under Carpet) - 1937 Bldg	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
19	12"x12" Light Brown w/ White VFT Mastic	750	SF	Public Space (Under Carpet) - 1937 Bldg	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Prescott School Unit 25021 Building ID 5500

Address 1632 W. Wrightwood Avenue Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
20	Brown Linoleum Not Observed			Principals Office (Under Carpet) - 1937 Bldg	ASSUMED	MISC					No			
21	Brown Linoleum Mastic Not Observed			Principals Office (Under Carpet) - 1937 Bldg	ASSUMED						No			
22	2'x4' White w/ Small Grooves Ceiling Tile	7,500	SF	Throughout 1890 Bldg	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
23	Hard Coat Plaster	15,000	SF	Throughout 1937 Bldg	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
24	Carpet Mastic	1,200	SF	Main Office Public Space, Principals Office - 1937 Bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
25	12 x 12 Cream with Brown and White Streaks Floor Tile	926	SF	3rd Floor Stairwell and 2nd Floor Landing, #102	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
26	12 x 12 Cream with Brown and White Streaks Floor Tile Mastic	926	SF	3rd Floor Stairwell and 2nd Floor Landing, #102	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
27	12 x 12 Brown with Brown and White Streaks Floor Tile	1,800	SF	Throughout	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
28	12 x 12 Brown with Brown and White Streaks Floor Tile Mastic	1,800	SF	Throughout	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
29	12 x 12 Grey with Grey Specks Floor Tile	280	SF	MDF Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
30	12 x 12 Grey with Grey Specks Floor Tile Mastic	280	SF	MDF Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
31	Blue/Peach Multicolored Carpet Mastic Not Observed	1,600	SF	Room 102 (Computer Room)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
B	Aircell Duct Insulation	1,400	LF	Lunchroom - 1890 Bldg	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
C	Aircell Pipe Insulation	80	LF	Room 001, Lunchroom (Basement) - 1890 Bldg	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
D	MJP E/F/V on Aircell Pipe Insulation	6	LF	Room 001 & Lunchroom - 1890 Bldg	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
G	MJP E/F/V on Fiberglass Pipe Insulation	5	LF	Rooms 102 and 103, Boiler Room, & Pump Room - 1937 Bldg	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
H	Cardboard Pipe Insulation	80	LF	Room 001, Lunchroom - 1890	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Prescott School Unit 25021 Building ID 5500

Address 1632 W. Wrightwood Avenue Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Bldg										
J	MJP E/F/V on Cardboard Pipe Insulation	750	LF	Boiler Room & Pump Room - 1937 Bldg	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
K	MJP E/F/V on Fiberglass Pipe Insulation	8	LF	Room 102, & 207 - 1890	CHR	TSI	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Prescott School Unit 25021 Building ID 5500

Address 1632 W. Wrightwood Avenue Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

Inspector's Comments are Summarized at the End of the Report

Reinspection Date 5/10/2016
Inspector Name Esteban Nunez
100-11255 2/13/2017
Inspector's IDPH License Number / Expiration Date

Inspector's Comments

HA Number:	Inspector Comments:
02	
03	
04	
05	
07	
08	
09	
10	
11	
14	
15	
16	
17	
18	
19	
20	
21	
22	
23	
24	
25	
26	
27	
28	

Chicago Public Schools

School Prescott School Unit 25021 Building ID 5500

Address 1632 W. Wrightwood Avenue Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
29	
30	
31	
B	
C	
D	
G	
H	
J	
K	

Table II

Management Planner's Review

Chicago Public Schools

School Prescott School
Address 1632 W. Wrightwood Avenue

Unit 25021
Chicago, IL, 60614

Building ID 5500
Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
02	9"x9" Light Gray w/ White & Orange Streaks VFT	1,500	SF	Art Room & Engineer's Office - 1890 Bldg	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
03	9"x9" Black w/ White & Orange Streaks Mastic	800	SF	Room 001 - 1890 Bldg	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
04	12"x12" Beige w/ Dark Brown & White Streaks VFT	10,060	SF	Room 301, 304, 201, 204, 104, 103, 1st, 2nd & 3rd Floor Corridors - 1890 Bldg	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
05	9"x9" Lt Gray w/ White & Orange Streaks VFT Mastic	1,500	SF	Art Room & Engineer's Office - 1890 Bldg	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
07	9"x9" Black w/ White Streaks VFT Mastic (Not Observed)	900	SF	Room 101 - 1890 Bldg	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	
08	12"x12" Beige w/ Dark Brown & White Streaks VFT	5,750	SF	Room 305, 306, 307, 205, 206, 207, 105, 106, 107, 1st, 2nd & 3rd Floor Corridors - 1937 Bldg	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
09	12"x12" Beige w/ Dk Brn & White Streaks VFT Mastic	6,750	SF	Room 305, 306, 307, 205, 206, 207, 105, 106, 107, 1st, 2nd & 3rd Floor Corridors - 1937 Bldg	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
10	9"x9" Brown w/ Yellow & White Streaks VFT	1,150	SF	Room 007, Engineer's Office & Closet - 1937 Bldg	Chrysotile	MISC	No	3	SF	6 ACBM with the potential for damage	Follow O&M Plan
11	9"x9" Brown w/ Yellow & White Streaks VFT Mastic	1,150	SF	Room 007, Engineer's Office & Closet - 1937 Bldg	Chrysotile	MISC	No	3	SF	6 ACBM with the potential for damage	Follow O&M Plan
14	9"x9" Dark Brown w/ Orange & White VFT	250	SF	Room 001 Closet and Room 007C - 1890 Bldg	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
15	9"x9" Dark Brown w/ Orange & White VFT Mastic	250	SF	Room 001 Closet - 1890 Bldg	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
16	12"x12" Black w/ White Streaks VFT	250	SF	Room 001 Closet - 1890 Bldg	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
17	12"x12" Black w/ White Streaks VFT Mastic	50	SF	Room 001 Closet - 1890 Bldg	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
18	12"x12" Light Brown w/ White VFT	750	SF	Public Space (Under Carpet) - 1937 Bldg	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
19	12"x12" Light Brown w/ White VFT Mastic	750	SF	Public Space (Under Carpet) - 1937 Bldg	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
20	Brown Linoleum Not Observed			Principals Office (Under Carpet) - 1937 Bldg	Assumed	MISC					
21	Brown Linoleum Mastic Not Observed			Principals Office (Under Carpet) - 1937 Bldg	Assumed						
22	2'x4' White w/ Small Grooves Ceiling Tile	7,500	SF	Throughout 1890 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
23	Hard Coat Plaster	15,000	SF	Throughout 1937 Bldg	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
24	Carpet Mastic	1,200	SF	Main Office Public Space, Principals	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Prescott School
Address 1632 W. Wrightwood Avenue

Unit 25021
 Chicago, IL, 60614

Building ID 5500
Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				Office - 1937 Bldg							
25	12 x 12 Cream with Brown and White Streaks Floor Tile	926	SF	3rd Floor Stairwell and 2nd Floor Landing, #102	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
26	12 x 12 Cream with Brown and White Streaks Floor Tile Mastic	926	SF	3rd Floor Stairwell and 2nd Floor Landing, #102	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
27	12 x 12 Brown with Brown and White Streaks Floor Tile	1,800	SF	Throughout	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
28	12 x 12 Brown with Brown and White Streaks Floor Tile Mastic	1,800	SF	Throughout	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
29	12 x 12 Grey with Grey Specks Floor Tile	280	SF	MDF Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
30	12 x 12 Grey with Grey Specks Floor Tile Mastic	280	SF	MDF Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
31	Blue/Peach Multicolored Carpet Mastic Not Observed	1,600	SF	Room 102 (Computer Room)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
B	Aircell Duct Insulation	1,400	LF	Lunchroom - 1890 Bldg	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
C	Aircell Pipe Insulation	80	LF	Room 001, Lunchroom (Basement) - 1890 Bldg	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
D	MJP E/F/V on Aircell Pipe Insulation	6	LF	Room 001 & Lunchroom - 1890 Bldg	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
G	MJP E/F/V on Fiberglass Pipe Insulation	5	LF	Rooms 102 and 103, Boiler Room, & Pump Room - 1937 Bldg	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
H	Cardboard Pipe Insulation	80	LF	Room 001, Lunchroom - 1890 Bldg	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
J	MJP E/F/V on Cardboard Pipe Insulation	750	LF	Boiler Room & Pump Room - 1937 Bldg	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
K	MJP E/F/V on Fiberglass Pipe Insulation	8	LF	Room 102, & 207 - 1890	Chrysotile	TSI	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Prescott School
Address 1632 W. Wrightwood Avenue

Unit 25021
 Chicago, IL, 60614

Building ID 5500
Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG Consultants, Inc.
 855 W. Adams St., Ste. 200
 Phone: (312) 733-6262

Fax: (312) 733-5612

Management Planner's Comments Summarized at the End of the Report

Review Date	5/24/2016
Manager Planner Name	Guillermo Garcia
100-01786	3/21/2017
Manager IDPH License No/Expiration	

HA Number	Management Comments
02	
03	
04	
05	
07	
08	
09	
10	
11	
14	
15	
16	
17	
18	
19	
20	

Chicago Public Schools

School Prescott School
Address 1632 W. Wrightwood Avenue

Unit 25021
 Chicago, IL, 60614

Building ID 5500
Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
21	
22	
23	
24	
25	
26	
27	
28	
29	
30	
31	
B	
C	
D	
G	
H	
J	
K	

Chicago Public Schools

GSG Consultants, Inc.

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25021** BUIDLING ID: **5500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Prescott School** INSPECTION DATE: **5/10/2016**
ADDRESS: **1632 W. Wrightwood Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **02**
MATERIAL DESCRIPTION: **9"x9" Light Gray w/ White & Orange Streaks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Art Room & Engineer's Office - 1890 Bldg**

MATERIAL QUANTITY: **1500**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/10/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25021** BUIDLING ID: **5500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Prescott School** REVIEW DATE: **5/24/2016**
ADDRESS: **1632 W. Wrightwood Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **02**
MATERIAL DESCRIPTION: **9"x9" Light Gray w/ White & Orange Streaks VFT**
MATERIAL LOCATION: **Art Room & Engineer's Office - 1890 Bldg**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/24/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25021** BUIDLING ID: **5500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Prescott School** INSPECTION DATE: **5/10/2016**
ADDRESS: **1632 W. Wrightwood Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **03**
MATERIAL DESCRIPTION: **9"x9" Black w/ White & Orange Streaks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Room 001 - 1890 Bldg**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/10/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25021** BUILDING ID: **5500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Prescott School** REVIEW DATE: **5/24/2016**
ADDRESS: **1632 W. Wrightwood Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **03**
MATERIAL DESCRIPTION: **9"x9" Black w/ White & Orange Streaks Mastic**
MATERIAL LOCATION: **Room 001 - 1890 Bldg**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/24/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25021** BUIDLING ID: **5500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Prescott School** INSPECTION DATE: **5/10/2016**
ADDRESS: **1632 W. Wrightwood Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **04**
MATERIAL DESCRIPTION: **12"x12" Beige w/ Dark Brown & White Streaks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Room 301, 304, 201, 204, 104, 103, 1st, 2nd & 3rd Floor Corridors - 1890 Bldg**
MATERIAL QUANTITY: **10060** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/10/2016**

Chicago Public Schools

GSG Consultants, Inc.

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25021** BUIDLING ID: **5500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Prescott School** REVIEW DATE: **5/24/2016**
ADDRESS: **1632 W. Wrightwood Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **04**
MATERIAL DESCRIPTION: **12"x12" Beige w/ Dark Brown & White Streaks VFT**
MATERIAL LOCATION: **Room 301, 304, 201, 204, 104, 103, 1st, 2nd & 3rd Floor Corridors - 1890 Bldg**
MATERIAL QUANTITY: **10060** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/24/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25021** BUIDLING ID: **5500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Prescott School** INSPECTION DATE: **5/10/2016**
ADDRESS: **1632 W. Wrightwood Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **05**
MATERIAL DESCRIPTION: **9"x9" Lt Gray w/ White & Orange Streaks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Art Room & Engineer's Office - 1890 Bldg**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/10/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25021** BUIDLING ID: **5500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Prescott School** REVIEW DATE: **5/24/2016**
ADDRESS: **1632 W. Wrightwood Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **05**
MATERIAL DESCRIPTION: **9"x9" Lt Gray w/ White & Orange Streaks VFT Mastic**
MATERIAL LOCATION: **Art Room & Engineer's Office - 1890 Bldg**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/24/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25021** BUIDLING ID: **5500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Prescott School** INSPECTION DATE: **5/10/2016**
ADDRESS: **1632 W. Wrightwood Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **07**
MATERIAL DESCRIPTION: **9"x9" Black w/ White Streaks VFT Mastic (Not Observed)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 101 - 1890 Bldg**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/10/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25021** BUIDLING ID: **5500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Prescott School** REVIEW DATE: **5/24/2016**
ADDRESS: **1632 W. Wrightwood Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **07**
MATERIAL DESCRIPTION: **9"x9" Black w/ White Streaks VFT Mastic (Not Observed)**
MATERIAL LOCATION: **Room 101 - 1890 Bldg**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/24/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25021** BUIDLING ID: **5500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Prescott School** INSPECTION DATE: **5/10/2016**
ADDRESS: **1632 W. Wrightwood Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **08**
MATERIAL DESCRIPTION: **12"x12" Beige w/ Dark Brown & White Streaks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Room 305, 306, 307, 205, 206, 207, 105, 106, 107, 1st, 2nd & 3rd Floor Corridors - 1937 Bldg**

MATERIAL QUANTITY: **5750** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/10/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25021** BUIDLING ID: **5500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Prescott School** REVIEW DATE: **5/24/2016**
ADDRESS: **1632 W. Wrightwood Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **08**
MATERIAL DESCRIPTION: **12"x12" Beige w/ Dark Brown & White Streaks VFT**
MATERIAL LOCATION: **Room 305, 306, 307, 205, 206, 207, 105, 106, 107, 1st, 2nd & 3rd Floor Corridors - 1937 Bldg**
MATERIAL QUANTITY: **5750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/24/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25021** BUIDLING ID: **5500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Prescott School** INSPECTION DATE: **5/10/2016**
ADDRESS: **1632 W. Wrightwood Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **09**
MATERIAL DESCRIPTION: **12"x12" Beige w/ Dk Brn & White Streaks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 305, 306, 307, 205, 206, 207, 105, 106, 107, 1st, 2nd & 3rd Floor Corridors - 1937 Bldg**

MATERIAL QUANTITY: **6750** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/10/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25021** BUIDLING ID: **5500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Prescott School** REVIEW DATE: **5/24/2016**
ADDRESS: **1632 W. Wrightwood Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **09**
MATERIAL DESCRIPTION: **12"x12" Beige w/ Dk Brn & White Streaks VFT Mastic**
MATERIAL LOCATION: **Room 305, 306, 307, 205, 206, 207, 105, 106, 107, 1st, 2nd & 3rd Floor Corridors - 1937 Bldg**
MATERIAL QUANTITY: **6750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/24/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25021** BUIDLING ID: **5500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Prescott School** INSPECTION DATE: **5/10/2016**
ADDRESS: **1632 W. Wrightwood Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10**
MATERIAL DESCRIPTION: **9"x9" Brown w/ Yellow & White Streaks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with potential for significant damage**
HISTORICAL DAMAGE REASON: **Physical Damage**
HISTORICAL RESPONSE ACTION: **Repair**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Physical Damage**
DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Room 007, Engineer's Office & Closet - 1937 Bldg**
MATERIAL QUANTITY: **1150** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **1150** DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: **05/10/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25021** BUIDLING ID: **5500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Prescott School** REVIEW DATE: **5/24/2016**
ADDRESS: **1632 W. Wrightwood Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **10**
MATERIAL DESCRIPTION: **9"x9" Brown w/ Yellow & White Streaks VFT**
MATERIAL LOCATION: **Room 007, Engineer's Office & Closet - 1937 Bldg**
MATERIAL QUANTITY: **1150** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **3** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Management Planner's Signature: _____



Date: **05/24/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25021** BUIDLING ID: **5500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Prescott School** INSPECTION DATE: **5/10/2016**
ADDRESS: **1632 W. Wrightwood Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11**
MATERIAL DESCRIPTION: **9"x9" Brown w/ Yellow & White Streaks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with potential for significant damage**
HISTORICAL DAMAGE REASON: **Physical Damage**
HISTORICAL RESPONSE ACTION: **Repair**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Physical Damage**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 007, Engineer's Office & Closet - 1937 Bldg**
MATERIAL QUANTITY: **1150** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **1150** DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: **05/10/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25021** BUIDLING ID: **5500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Prescott School** REVIEW DATE: **5/24/2016**
ADDRESS: **1632 W. Wrightwood Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **11**
MATERIAL DESCRIPTION: **9"x9" Brown w/ Yellow & White Streaks VFT Mastic**
MATERIAL LOCATION: **Room 007, Engineer's Office & Closet - 1937 Bldg**
MATERIAL QUANTITY: **1150** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **3** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Management Planner's Signature: _____



Date: **05/24/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25021** BUIDLING ID: **5500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Prescott School** INSPECTION DATE: **5/10/2016**
ADDRESS: **1632 W. Wrightwood Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14**
MATERIAL DESCRIPTION: **9"x9" Dark Brown w/ Orange & White VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Room 001 Closet and Room 007C - 1890 Bldg**
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:



Date: **05/10/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25021** BUIDLING ID: **5500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Prescott School** REVIEW DATE: **5/24/2016**
ADDRESS: **1632 W. Wrightwood Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **14**
MATERIAL DESCRIPTION: **9"x9" Dark Brown w/ Orange & White VFT**
MATERIAL LOCATION: **Room 001 Closet and Room 007C - 1890 Bldg**
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/24/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25021** BUIDLING ID: **5500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Prescott School** INSPECTION DATE: **5/10/2016**
ADDRESS: **1632 W. Wrightwood Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15**
MATERIAL DESCRIPTION: **9"x9" Dark Brown w/ Orange & White VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 001 Closet - 1890 Bldg**
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/10/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25021** BUIDLING ID: **5500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Prescott School** REVIEW DATE: **5/24/2016**
ADDRESS: **1632 W. Wrightwood Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **15**
MATERIAL DESCRIPTION: **9"x9" Dark Brown w/ Orange & White VFT Mastic**
MATERIAL LOCATION: **Room 001 Closet - 1890 Bldg**
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/24/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25021** BUIDLING ID: **5500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Prescott School** INSPECTION DATE: **5/10/2016**
ADDRESS: **1632 W. Wrightwood Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16**
MATERIAL DESCRIPTION: **12"x12" Black w/ White Streaks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Room 001 Closet - 1890 Bldg**
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 05/10/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25021** BUIDLING ID: **5500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Prescott School** REVIEW DATE: **5/24/2016**
ADDRESS: **1632 W. Wrightwood Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **16**
MATERIAL DESCRIPTION: **12"x12" Black w/ White Streaks VFT**
MATERIAL LOCATION: **Room 001 Closet - 1890 Bldg**
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/24/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25021** BUIDLING ID: **5500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Prescott School** INSPECTION DATE: **5/10/2016**
ADDRESS: **1632 W. Wrightwood Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17**
MATERIAL DESCRIPTION: **12"x12" Black w/ White Streaks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 001 Closet - 1890 Bldg**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 05/10/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25021** BUILDING ID: **5500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Prescott School** REVIEW DATE: **5/24/2016**
ADDRESS: **1632 W. Wrightwood Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **17**
MATERIAL DESCRIPTION: **12"x12" Black w/ White Streaks VFT Mastic**
MATERIAL LOCATION: **Room 001 Closet - 1890 Bldg**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/24/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25021** BUIDLING ID: **5500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Prescott School** INSPECTION DATE: **5/10/2016**
ADDRESS: **1632 W. Wrightwood Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18**
MATERIAL DESCRIPTION: **12"x12" Light Brown w/ White VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Public Space (Under Carpet) - 1937 Bldg**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:



Date: **05/10/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25021** BUIDLING ID: **5500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Prescott School** REVIEW DATE: **5/24/2016**
ADDRESS: **1632 W. Wrightwood Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **18**
MATERIAL DESCRIPTION: **12"x12" Light Brown w/ White VFT**
MATERIAL LOCATION: **Public Space (Under Carpet) - 1937 Bldg**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/24/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25021** BUIDLING ID: **5500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Prescott School** INSPECTION DATE: **5/10/2016**
ADDRESS: **1632 W. Wrightwood Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19**
MATERIAL DESCRIPTION: **12"x12" Light Brown w/ White VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Public Space (Under Carpet) - 1937 Bldg**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/10/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25021** BUIDLING ID: **5500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Prescott School** REVIEW DATE: **5/24/2016**
ADDRESS: **1632 W. Wrightwood Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **19**
MATERIAL DESCRIPTION: **12"x12" Light Brown w/ White VFT Mastic**
MATERIAL LOCATION: **Public Space (Under Carpet) - 1937 Bldg**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/24/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25021** BUIDLING ID: **5500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Prescott School** INSPECTION DATE: **5/10/2016**
ADDRESS: **1632 W. Wrightwood Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**
MATERIAL DESCRIPTION: **Brown Linloleum Not Observed**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Principals Office (Under Carpet) - 1937 Bldg**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/10/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25021** BUIDLING ID: **5500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Prescott School** REVIEW DATE: **5/24/2016**
ADDRESS: **1632 W. Wrightwood Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **20**
MATERIAL DESCRIPTION: **Brown Linloleum Not Observed**
MATERIAL LOCATION: **Principals Office (Under Carpet) - 1937 Bldg**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/24/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25021** BUIDLING ID: **5500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Prescott School** INSPECTION DATE: **5/10/2016**
ADDRESS: **1632 W. Wrightwood Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21**
MATERIAL DESCRIPTION: **Brown Linoleum Mastic Not Observed**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Principals Office (Under Carpet) - 1937 Bldg**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/10/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25021** BUIDLING ID: **5500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Prescott School** REVIEW DATE: **5/24/2016**
ADDRESS: **1632 W. Wrightwood Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **21**
MATERIAL DESCRIPTION: **Brown Linoleum Mastic Not Observed**
MATERIAL LOCATION: **Principals Office (Under Carpet) - 1937 Bldg**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/24/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25021** BUIDLING ID: **5500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Prescott School** INSPECTION DATE: **5/10/2016**
ADDRESS: **1632 W. Wrightwood Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22**
MATERIAL DESCRIPTION: **2'x4' White w/ Small Grooves Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout 1890 Bldg**
MATERIAL QUANTITY: **7500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/10/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25021** BUIDLING ID: **5500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Prescott School** REVIEW DATE: **5/24/2016**
ADDRESS: **1632 W. Wrightwood Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **22**
MATERIAL DESCRIPTION: **2'x4' White w/ Small Grooves Ceiling Tile**
MATERIAL LOCATION: **Throughout 1890 Bldg**
MATERIAL QUANTITY: **7500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/24/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25021** BUIDLING ID: **5500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Prescott School** INSPECTION DATE: **5/10/2016**
ADDRESS: **1632 W. Wrightwood Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23**
MATERIAL DESCRIPTION: **Hard Coat Plaster**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout 1937 Bldg**
MATERIAL QUANTITY: **15000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/10/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25021** BUIDLING ID: **5500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Prescott School** REVIEW DATE: **5/24/2016**
ADDRESS: **1632 W. Wrightwood Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **23**
MATERIAL DESCRIPTION: **Hard Coat Plaster**
MATERIAL LOCATION: **Throughout 1937 Bldg**
MATERIAL QUANTITY: **15000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/24/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25021** BUIDLING ID: **5500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Prescott School** INSPECTION DATE: **5/10/2016**
ADDRESS: **1632 W. Wrightwood Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **24**
MATERIAL DESCRIPTION: **Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Main Office Public Space, Principals Office - 1937 Bldg**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/10/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25021** BUILDING ID: **5500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Prescott School** REVIEW DATE: **5/24/2016**
ADDRESS: **1632 W. Wrightwood Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **24**
MATERIAL DESCRIPTION: **Carpet Mastic**
MATERIAL LOCATION: **Main Office Public Space, Principals Office - 1937 Bldg**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/24/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25021** BUIDLING ID: **5500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Prescott School** INSPECTION DATE: **5/10/2016**
ADDRESS: **1632 W. Wrightwood Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25**
MATERIAL DESCRIPTION: **12 x 12 Cream with Brown and White Streaks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **3rd Floor Stairwell and 2nd Floor Landing, #102**
MATERIAL QUANTITY: **926** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/10/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25021** BUIDLING ID: **5500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Prescott School** REVIEW DATE: **5/24/2016**
ADDRESS: **1632 W. Wrightwood Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **25**
MATERIAL DESCRIPTION: **12 x 12 Cream with Brown and White Streaks Floor Tile**
MATERIAL LOCATION: **3rd Floor Stairwell and 2nd Floor Landing, #102**
MATERIAL QUANTITY: **926** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/24/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25021** BUIDLING ID: **5500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Prescott School** INSPECTION DATE: **5/10/2016**
ADDRESS: **1632 W. Wrightwood Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26**
MATERIAL DESCRIPTION: **12 x 12 Cream with Brown and White Streaks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **3rd Floor Stairwell and 2nd Floor Landing, #102**
MATERIAL QUANTITY: **926** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/10/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25021** BUILDING ID: **5500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Prescott School** REVIEW DATE: **5/24/2016**
ADDRESS: **1632 W. Wrightwood Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **26**
MATERIAL DESCRIPTION: **12 x 12 Cream with Brown and White Streaks Floor Tile Mastic**
MATERIAL LOCATION: **3rd Floor Stairwell and 2nd Floor Landing, #102**
MATERIAL QUANTITY: **926** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/24/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25021** BUIDLING ID: **5500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Prescott School** INSPECTION DATE: **5/10/2016**
ADDRESS: **1632 W. Wrightwood Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27**
MATERIAL DESCRIPTION: **12 x 12 Brown with Brown and White Streaks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout**
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/10/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25021** BUIDLING ID: **5500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Prescott School** REVIEW DATE: **5/24/2016**
ADDRESS: **1632 W. Wrightwood Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **27**
MATERIAL DESCRIPTION: **12 x 12 Brown with Brown and White Streaks Floor Tile**
MATERIAL LOCATION: **Throughout**
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/24/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25021** BUIDLING ID: **5500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Prescott School** INSPECTION DATE: **5/10/2016**
ADDRESS: **1632 W. Wrightwood Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28**
MATERIAL DESCRIPTION: **12 x 12 Brown with Brown and White Streaks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout**
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/10/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25021** BUIDLING ID: **5500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Prescott School** REVIEW DATE: **5/24/2016**
ADDRESS: **1632 W. Wrightwood Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **28**
MATERIAL DESCRIPTION: **12 x 12 Brown with Brown and White Streaks Floor Tile Mastic**
MATERIAL LOCATION: **Throughout**
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/24/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25021** BUIDLING ID: **5500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Prescott School** INSPECTION DATE: **5/10/2016**
ADDRESS: **1632 W. Wrightwood Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **29**
MATERIAL DESCRIPTION: **12 x 12 Grey with Grey Specks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **MDF Room**
MATERIAL QUANTITY: **280** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/10/2016**

Chicago Public Schools

GSG Consultants, Inc.

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25021** BUIDLING ID: **5500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Prescott School** REVIEW DATE: **5/24/2016**
ADDRESS: **1632 W. Wrightwood Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **29**
MATERIAL DESCRIPTION: **12 x 12 Grey with Grey Specks Floor Tile**
MATERIAL LOCATION: **MDF Room**
MATERIAL QUANTITY: **280** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/24/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25021** BUIDLING ID: **5500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Prescott School** INSPECTION DATE: **5/10/2016**
ADDRESS: **1632 W. Wrightwood Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **30**
MATERIAL DESCRIPTION: **12 x 12 Grey with Grey Specks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **MDF Room**
MATERIAL QUANTITY: **280** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/10/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25021** BUIDLING ID: **5500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Prescott School** REVIEW DATE: **5/24/2016**
ADDRESS: **1632 W. Wrightwood Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **30**
MATERIAL DESCRIPTION: **12 x 12 Grey with Grey Specks Floor Tile Mastic**
MATERIAL LOCATION: **MDF Room**
MATERIAL QUANTITY: **280** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/24/2016**

Chicago Public Schools

GSG Consultants, Inc.

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25021** BUIDLING ID: **5500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Prescott School** INSPECTION DATE: **5/10/2016**
ADDRESS: **1632 W. Wrightwood Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **31**
MATERIAL DESCRIPTION: **Blue/Peach Multicolored Carpet Mastic Not Observed**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 102 (Computer Room)**
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 05/10/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25021** BUIDLING ID: **5500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Prescott School** REVIEW DATE: **5/24/2016**
ADDRESS: **1632 W. Wrightwood Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **31**
MATERIAL DESCRIPTION: **Blue/Peach Multicolored Carpet Mastic Not Observed**
MATERIAL LOCATION: **Room 102 (Computer Room)**
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/24/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25021** BUIDLING ID: **5500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Prescott School** INSPECTION DATE: **5/10/2016**
ADDRESS: **1632 W. Wrightwood Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **B**
MATERIAL DESCRIPTION: **Aircell Duct Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Lunchroom - 1890 Bldg**
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **05/10/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25021** BUIDLING ID: **5500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Prescott School** REVIEW DATE: **5/24/2016**
ADDRESS: **1632 W. Wrightwood Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **B**
MATERIAL DESCRIPTION: **Aircell Duct Insulation**
MATERIAL LOCATION: **Lunchroom - 1890 Bldg**
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/24/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25021** BUIDLING ID: **5500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Prescott School** INSPECTION DATE: **5/10/2016**
ADDRESS: **1632 W. Wrightwood Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **C**
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 001, Lunchroom (Basement) - 1890 Bldg**
MATERIAL QUANTITY: **80** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **05/10/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25021** BUIDLING ID: **5500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Prescott School** REVIEW DATE: **5/24/2016**
ADDRESS: **1632 W. Wrightwood Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **C**
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**
MATERIAL LOCATION: **Room 001, Lunchroom (Basement) - 1890 Bldg**
MATERIAL QUANTITY: **80** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/24/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25021** BUIDLING ID: **5500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Prescott School** INSPECTION DATE: **5/10/2016**
ADDRESS: **1632 W. Wrightwood Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **D**
MATERIAL DESCRIPTION: **MJP E/F/V on Aircell Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 001 & Lunchroom - 1890 Bldg**
MATERIAL QUANTITY: **6** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____



Date: 05/10/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25021** BUIDLING ID: **5500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Prescott School** REVIEW DATE: **5/24/2016**
ADDRESS: **1632 W. Wrightwood Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **D**
MATERIAL DESCRIPTION: **MJP E/F/V on Aircell Pipe Insulation**
MATERIAL LOCATION: **Room 001 & Lunchroom - 1890 Bldg**
MATERIAL QUANTITY: **6** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/24/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25021** BUIDLING ID: **5500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Prescott School** INSPECTION DATE: **5/10/2016**
ADDRESS: **1632 W. Wrightwood Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **G**
MATERIAL DESCRIPTION: **MJP E/F/V on Fiberglass Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 102 and 103, Boiler Room, & Pump Room - 1937 Bldg**
MATERIAL QUANTITY: **5** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **05/10/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25021** BUIDLING ID: **5500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Prescott School** REVIEW DATE: **5/24/2016**
ADDRESS: **1632 W. Wrightwood Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **G**
MATERIAL DESCRIPTION: **MJP E/F/V on Fiberglass Pipe Insulation**
MATERIAL LOCATION: **Rooms 102 and 103, Boiler Room, & Pump Room - 1937 Bldg**
MATERIAL QUANTITY: **5** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/24/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25021** BUIDLING ID: **5500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Prescott School** INSPECTION DATE: **5/10/2016**
ADDRESS: **1632 W. Wrightwood Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **H**
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 001, Lunchroom - 1890 Bldg**
MATERIAL QUANTITY: **80** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **05/10/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25021** BUIDLING ID: **5500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Prescott School** REVIEW DATE: **5/24/2016**
ADDRESS: **1632 W. Wrightwood Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **H**
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**
MATERIAL LOCATION: **Room 001, Lunchroom - 1890 Bldg**
MATERIAL QUANTITY: **80** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/24/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25021** BUIDLING ID: **5500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Prescott School** INSPECTION DATE: **5/10/2016**
ADDRESS: **1632 W. Wrightwood Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **J**
MATERIAL DESCRIPTION: **MJP E/F/V on Cardboard Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Boiler Room & Pump Room - 1937 Bldg**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **05/10/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25021** BUIDLING ID: **5500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Prescott School** REVIEW DATE: **5/24/2016**
ADDRESS: **1632 W. Wrightwood Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **J**
MATERIAL DESCRIPTION: **MJP E/F/V on Cardboard Pipe Insulation**
MATERIAL LOCATION: **Boiler Room & Pump Room - 1937 Bldg**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/24/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25021** BUIDLING ID: **5500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Prescott School** INSPECTION DATE: **5/10/2016**
ADDRESS: **1632 W. Wrightwood Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **K**
MATERIAL DESCRIPTION: **MJP E/F/V on Fiberglass Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 102, & 207 - 1890**
MATERIAL QUANTITY: **8** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **05/10/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25021** BUIDLING ID: **5500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Prescott School** REVIEW DATE: **5/24/2016**
ADDRESS: **1632 W. Wrightwood Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **K**
MATERIAL DESCRIPTION: **MJP E/F/V on Fiberglass Pipe Insulation**
MATERIAL LOCATION: **Room 102, & 207 - 1890**
MATERIAL QUANTITY: **8** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/24/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

APPENDIX B

Inspector and Management Planner Licenses

CERTIFICATE OF ACHIEVEMENT ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that ESTEBAN NUNEZ
has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the
examination on 02/13/2016 with a minimum score of 70% or better. Training was in accordance
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:
Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.

02/13/2016

Course Dates:

02/13/2017

Expires:

1602BIR19

Certificate Number:



N. Peneff

Director of Training

Nicholas J. Peneff

Doctor of Public Health

Phone: 312-491-0081

FORM # A-010B



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • www.idph.illinois.gov

4/18/2016

ESTEBAN NUNEZ
855 WEST ADAMS ST, #200
CHICAGO, IL 60607

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 11255

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

 <p>ASBESTOS PROFESSIONAL LICENSE</p>			<p>ENDORSEMENTS</p> <p>INSPECTOR</p> <p>PROJECT MANAGER AIR SAMPLING PROFESSIONAL</p>	<p>TC EXPIRES</p> <p>2/13/2017</p> <p>9/19/2016</p>
<p>ID NUMBER 100 - 11255</p> <p>ESTEBAN NUNEZ 855 WEST ADAMS ST, #200 CHICAGO, IL 60607 Environmental Health</p>	<p>ISSUED 4/18/2016</p>	<p>EXPIRES 05/15/2017</p> 	<p>Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.</p>	

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH, IMPROVING LIVES
Nationally Accredited by PHAB

CERTIFICATE OF ACHIEVEMENT ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that GUILLERMO GARCIA
has completed the Asbestos Management Planner Refresher course and passed the examination
on 03/21/2016 with a minimum score of 70% or better. Training was in accordance with U.S.
E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools: Model
Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.

03/21/2016

Course Dates:

03/21/2017

Expires:

1603MPR02

Certificate Number:



PUBLIC HEALTH & SAFETY inc.

Environmental and Occupational Services
105 S. Ashland Ave., Chicago, IL 60607

N. Penoff

Director of Training

Nicholas J. Penoff

Doctor of Public Health

Phone: 312-491-0081

FORM # A-011



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • www.dph.illinois.gov

4/20/2016

GUILLERMO GARCIA
 855 W ADAMS ST SUITE 100
 CHICAGO, IL 60607

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 01786

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

Front of License			Back of License	
 <p>ASBESTOS PROFESSIONAL LICENSE</p>			ENDORSEMENTS	TC EXPIRES
ID NUMBER 100 - 01733	ISSUED 4/20/2016	EXPIRES 05/15/2017	INSPECTOR	3/21/2017
GUILLERMO GARCIA 855 W ADAMS ST SUITE 100 CHICAGO, IL 60607 Environmental Health			MANAGEMENT PLANNER	3/21/2017
			PROJECT MANAGER	2/6/2017
			AIR SAMPLING PROFESSIONAL	
			Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
 EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH, IMPROVING LIVES
Nationally Accredited by PHAB

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL		
	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE		
	Loc	Localized
	Dist	Distributed