

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM**

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-3553
SCHOOL NAME: Seward School Branch
ADDRESS OF SCHOOL: 4541 South Wood Street
CITY: Chicago, IL, 60609

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED 2/27/2013

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II (Please type or print)

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 3/23/2016 ENROLLMENT 729
IDPH INSPECTOR LICENSE NUMBER: 100-08864
IDPH LICENSED INSPECTOR NAME (Please Print): Robert DeBord
IDPH MP LICENSE NUMBER: 100-09870
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Todd Huffer

DESIGNATED PERSON (Please Print): Robert Christlieb PHONE: (773) 553-3197



3/23/2016

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Seward School Branch

4541 South Wood Street
Chicago, IL, 60609

Unit: 25301
Building ID: 5821

IDPH ID Number: 14-016-2990-3553

REPORT DATE:

Wednesday, March 23, 2016

Prepared for:

Chicago Public Schools
125 S. Clark Street
Chicago, IL 60603

Prepared by:

Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone (312) 762-2900

Fax (312) 782-5145

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

March 9, 2016

Mr. R. Kent Cook
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2016 Three-Year Reinspections

Dear Mr. Cook:

Carnow, Conibear and Associates, Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 3,4,5 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 25302 Region: 04 IDPH ID: 14-016-2990-3553

School: Seward School Branch Building ID: 5821

Address: 4541 South Wood Street
Chicago, IL, 60609

Building Contact: Pluzycki, Robert Contact Phone: 773-991-3805

Current Building Owners: Chicago Public Schools

Review Date: 03/23/2016

Inspector: Robert DeBord Inspector IDPH License: 100-08864
Management Planner: Todd Huffer Management Planner IDPH License: 100-09870

If you have any questions or comments, please contact us at (312) 762-2900

Sincerely,
Carnow, Conibear and Associates



Todd Huffer
100-09870

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: March 09, 2016

RE: Seward School Branch, Unit 25301
4541 South Wood Street
Chicago, IL, 60609

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2016 asbestos three year re-inspection has been completed at Seward School Branch , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at Seward School Branch, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Robert Christlieb, the designated Local Education Authority's Designated Person at (773) 553-3197 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School:	Seward School Branch	Unit:	25302	Region:	04
Address:	4541 South Wood Street		Chicago, IL, 60609		
IDPH ID:	14-016-2990-3553		Building ID:	5821	
Contact:	Pluzycki, Robert		Phone:	773-991-3805	

2. Description of Facility

Original Construction:	1913	Additional Construction:	1894,1962
Total Square Footage:	29621	No of Floors:	3
Current Occupancy:	729		

3. LEA Designated Person

Contact:	Robert Christlieb	Phone:	(773) 553-3197
Address:	125 South Clark Street, 17th Floor		
	Chicago, IL 60603		

4. Managing Environmental Consultant

MEC:	Carnow, Conibear and Associates		
Contact:	Dan Juneau		
Address	600 West Van Buren St., Ste 500		
Phone:	(312) 762-2900	Fax:	(312) 782-5145

5. Inspector

Inspector Name: Robert DeBord


Inspector IDPH license # 100-08864

Signature:
Date: 3/9/2016

6. Management Planner

Management Planner Name: Todd Huffer

Management Planner IDPH license # 100-09870

Signature: 
Date: 03/23/2016

7. Review Date: 03/23/2016

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature: 

Date: 3/23/2016

Name: Robert Christlieb

II. EXECUTIVE SUMMARY

Carnow, Conibear and Associates was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Seward School Branch. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 5821:

1 L	9" x 9" Gold Floor Tile
A 2	Aircell Pipe Insulation

B. The following new homogenous areas have been identified for Building 5821:

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

01	Hard Coat Plaster
1 P	9" x 9" Brown Floor Tile w/Orange & White Streaks
1 Q	9" x 9" Medium Brown Floor Tile
1 R	9" x 9" Gray Floor Tile w/Pink Streaks
1 S	9"x9"Light Brown Floor Tile w/Brn & Orange Streaks
1 T	9" x 9" Brown Floor Tile w/Orange & Green Streaks
1 X	9" x 9" Brown Floor Tile w/Brown & White Streaks
10	Spray-on Material
14	Fire Door Insulation
17 A	4" Black Vinyl Baseboard Mastic
17 B	4" Brown Vinyl Baseboard Mastic
26	Cinderblock
27	Cinderblock Mortar
28	Mortar Between Glass Block Windows
29	Adhesive Behind Chalk Boards and Bulletin Boards
3 P	9" x 9" Brown Floor Tile w/ Orange & White Streaks
3 Q	9" x 9" Medium Brown Floor Tile Mastic
3 R	9" x 9" Gray Floor Tile w/Pink Streaks Mastic
3 S	9"x9" Lt Brown FT w/Brown & Orange Streaks Mastic
3 T	9" x 9" Brown FT w/Orange & Green Streaks Mastic
3 X	9" x 9" Brown FT w/ Brown & White Streaks Mastic
30	Yellow Laminate
31	Yellow Laminate Adhesive
32	12" x 12" Pale Green w/Olive Green Specks FT
33	12" x 12" Pale Grn w/Olive Green Specks FT Mastic
5	Air Vent Vibration Collar
C 1	Cardboard Pipe Insulation
C1	Cardboard Pipe Insulation
D 1	Hard Joint Compound on Cardboard Pipe Insulation

The following areas were deemed to be inaccessible:

14	Fire Door Insulation
17 A	4" Black Vinyl Baseboard Mastic

17 B	4" Brown Vinyl Baseboard Mastic
29	Adhesive Behind Chalk Boards and Bulletin Boards
3 A	9" x 9" Tan Floor Tile Mastic
3 B	9" x 9" Black Floor Tile Mastic
3 C	9" x 9" White Floor Tile Mastic
3 D	9" x 9" Beige Floor Tile Mastic
3 E	9" x 9" Grey Floor Tile w/Black Streaks Mastic
3 F	9" x 9" Pink Floor Tile Mastic
3 H	9" x 9" Red Floor Tile Mastic
3 I	9" x 9" Light Tan & Brown Floor Tile Mastic
3 K	9" x 9" Dark Green Floor Tile Mastic
3 L	9" x 9" Gold Floor Tile Mastic
3 N	9" x 9" Peach Floor Tile Mastic
3 Q	9" x 9" Medium Brown Floor Tile Mastic
3 R	9" x 9" Gray Floor Tile w/Pink Streaks Mastic
3 S	9"x9" Lt Brown FT w/Brown & Orange Streaks Mastic
3 T	9" x 9" Brown FT w/Orange & Green Streaks Mastic
3 X	9" x 9" Brown FT w/ Brown & White Streaks Mastic
31	Yellow Laminate Adhesive
33	12" x 12" Pale Grn w/Olive Green Specks FT Mastic
3G	9" x 9" Lime Green FT w/Dark Green Streaks Mastic
3J	9" x 9" Light Brown & Beige Floor Tile Mastic
C 1	Cardboard Pipe Insulation

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Robert DeBord, IDPH License # 100-08864. The Management Plan was updated by Todd Huffer, IDPH License # 100-09870. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Seward School Branch Building 5821 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Seward School Branch Unit 25302 Building ID 5821

Address 4541 South Wood Street Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
01	Hard Coat Plaster	3,000	SF	Throughout, 1925	ASSUMED	SURFACE	N	NONE	0		No	ACBM with the potential for damage		LOW
1 F	9" x 9" Pink Floor Tile	340	SF	Building #1 - Room 503	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
1 H	9" x 9" Red Floor Tile w/Brown & White Streaks	500	SF	Building #1 - East Foyer, West Stairwell	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
1 I	9" x 9" Light Tan & Brown Floor Tile	1,250	SF	Building #1 - Entrance and Corridors, Stairwell Areas, Washrooms, Stage Area, 514	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
1 J	9" x 9" Light Brown & Beige Swirl Floor Tile	800	SF	Building #1 - Stage Area and Room 514	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
1 L	9" x 9" Gold Floor Tile	1,240	SF	Building #1 Lunchroom & Kitchen, Rear Basement Hall	CHR	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
1 N	9" x 9" Peach Floor Tile	450	SF	Building #1 - Room 504	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
1 P	9" x 9" Brown Floor Tile w/Orange & White Streaks	600	SF	Office and Room 507, Teacher's Lounge	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
1 Q	9" x 9" Medium Brown Floor Tile	200	SF	Main Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
1 R	9" x 9" Gray Floor Tile w/Pink Streaks	300	SF	Building #1 - Room 503	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
1 S	9"x9"Light Brown Floor Tile w/Brn & Orange Streaks	300	SF	Building #1 - Room 506	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
1 T	9" x 9" Brown Floor Tile w/Orange & Green Streaks	300	SF	Building #1 Room 508	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
1 X	9" x 9" Brown Floor Tile w/Brown & White Streaks	100	SF	Building #1 East & West Stairways	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
10	Spray-on Material			All Columns in Building #1	ASSUMED	SURFACE								
13	Drywall			Material Not Present	UNDEFINE D			None						
14	Fire Door Insulation	100	SF	Throughout Building	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
16	9" x 9" Floor Tile			Separated by color. See HA's 1A - 1Q	UNDEFINE D									
17 A	4" Black Vinyl Baseboard Mastic	800	SF	Throughout Building #1	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Seward School Branch **Unit** 25302 **Building ID** 5821

Address 4541 South Wood Street **Region** 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
17 B	4" Brown Vinyl Baseboard Mastic	800	LF	Throughout Building #1	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
18	Exterior Brick - Not AHERA			Building #1 Exterior	NO_ACBM									
19	Exterior Brick - Not AHERA			Building #2 Exterior	NO_ACBM									
1A	9" x 9" Tan Floor Tile w/Black & Red Streaks	940	SF	Building # 1 Office, Teacher's Washroom, Room 504	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
1B	9" x 9" Black Floor Tile	1,750	SF	Throughout Building #1 Classrooms, Corridors, Etc.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
1C	9" x 9" White Floor Tile	1,050	SF	Building #1 Throughout Various Rooms 506, 504, 508 Office etc.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
1D	9" x 9" Beige Floor Tile	1,000	SF	Building #1 Corridors and Rooms 508 and 506	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
1E	9" x 9" Grey Floor Tile w/Black Streaks	1,000	SF	Building #1 Classrooms 505 & 507	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
1G	9" x 9" Lime Green FT w/Dark Green & White Streaks	224	SF	Building #1Basement Lunchroom/Gym , Kitchen & Room 505	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
1K	9" x 9" Dark Green Floor Tile	240	SF	Building #1 Lunchroom	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
20	Exterior Brick Mortar - Not AHERA			Building #1 Exterior	NO_ACBM									
26	Cinderblock	20,000	SF	Building #1	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
27	Cinderblock Mortar	20,000	SF	Building #1	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
28	Mortar Between Glass Block Windows	560	SF	Throughout Building #1	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
29	Adhesive Behind Chalk Boards and Bulletin Boards	2,000	SF	Building #1	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
3 A	9" x 9" Tan Floor Tile Mastic	800	SF	Building # 1 - Office, Teacher's Washroom, Room 504	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
3 B	9" x 9" Black Floor Tile Mastic	1,800	SF	Building #1 - Classrooms,	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Seward School Branch Unit 25302 Building ID 5821

Address 4541 South Wood Street Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Corridors, Etc.										
3 C	9" x 9" White Floor Tile Mastic	1,100	SF	Building #1 - Throughout Various Rooms 506, 504, 508 Office etc.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
3 D	9" x 9" Beige Floor Tile Mastic	970	SF	Building #1 - Corridors and Rooms 508 and 506	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
3 E	9" x 9" Grey Floor Tile w/Black Streaks Mastic	630	SF	Building #1 - Classrooms 505 & 507	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
3 F	9" x 9" Pink Floor Tile Mastic	340	SF	Building #1 Room 503	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
3 H	9" x 9" Red Floor Tile Mastic	800	SF	Building #1 - East Foyer, West Stairwell	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
3 I	9" x 9" Light Tan & Brown Floor Tile Mastic	1,250	SF	Building #1 - Entrance and Corridors, Stairwell Areas, Washrooms, Stage Area, 514	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
3 K	9" x 9" Dark Green Floor Tile Mastic	360	SF	Building #1 - Lunchroom	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
3 L	9" x 9" Gold Floor Tile Mastic	1,900	SF	Building #1 Lunchroom & Kitchen, Rear Basement Hall	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
3 N	9" x 9" Peach Floor Tile Mastic	450	SF	Building #1 Room 504	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
3 P	9" x 9" Brown Floor Tile w/ Orange & White Streaks	500	SF	Office and Room 507	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
3 Q	9" x 9" Medium Brown Floor Tile Mastic	200	SF	Main Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
3 R	9" x 9" Gray Floor Tile w/Pink Streaks Mastic	300	SF	Building #1 - Room 503	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
3 S	9"x9" Lt Brown FT w/Brown & Orange Streaks Mastic	500	SF	Building #1 - Room 506	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
3 T	9" x 9" Brown FT w/Orange & Green Streaks Mastic	500	SF	Building #1 - Room 508	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
3 X	9" x 9" Brown FT w/ Brown & White Streaks Mastic	100	SF	Building #1 - East & West Stairways	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
30	Yellow Laminate	15	SF	Countertop in Kitchen	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
31	Yellow Laminate Adhesive	15	SF	Countertop in	ASSUMED	MISC	N	NONE	0		No	ACBM with the		LOW

Chicago Public Schools

School Seward School Branch Unit 25302 Building ID 5821

Address 4541 South Wood Street Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Kitchen								potential for damage		
32	12" x 12" Pale Green w/Olive Green Specks FT	210	SF	Men's Basement Washroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
33	12" x 12" Pale Grn w/Olive Green Specks FT Mastic	210	SF	Men's Basement Washroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
3G	9" x 9" Lime Green FT w/Dark Green Streaks Mastic	22,000	SF	Building #1 - Basement Lunchroom/Gym , Kitchen & Room 505	CHR	MISC	N	UNKNO WN	0		No	ACBM with the potential for damage		LOW
3J	9" x 9" Light Brown & Beige Floor Tile Mastic	900	SF	Building #1 - Stage and Room 514	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
5	Air Vent Vibration Collar	10	LF	Building #1 - Closet	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
8	Hard Coat Plaster			Throughout Building #1	NO_ACBM	MISC		None						
9	Trowled-on Material			Throughout Building #1	NO_ACBM									
A 2	Aircell Pipe Insulation	700	LF	Throughout Building #1	CHR	TSI	Y	NONE	0		Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
B 2	Hard Joint Compound on Aircell Pipe Insulation	25	JOINTS	Throughout Building #1	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		MODERATE
C 1	Cardboard Pipe Insulation	100	LF	Throughout Building #1	ASSUMED	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
C1	Cardboard Pipe Insulation			1st Floor Down N/E Stairway	ASSUMED	TSI		None						
D 1	Hard Joint Compound on Cardboard Pipe Insulation			Building #1	ASSUMED	TSI		None						Low

Chicago Public Schools

School Seward School Branch **Unit** 25302 **Building ID** 5821

Address 4541 South Wood Street **Region** 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

Reinspection Date **3/9/2016**

Inspector Name **Robert DeBord**

100-08864

5/15/2016

Inspector's IDPH License Number / Expiration Date

Inspector's Comments

HA Number:	Inspector Comments:
01	
1 F	
1 H	
1 I	
1 J	
1 L	
1 N	
1 P	
1 Q	
1 R	
1 S	
1 T	
1 X	
10	Not observed 2016
13	
14	
16	
17 A	
17 B	
18	
19	
1A	
1B	
1C	

Chicago Public Schools

School Seward School Branch **Unit** 25302 **Building ID** 5821

Address 4541 South Wood Street **Region** 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
1D	
1E	
1G	
1K	
20	
26	
27	
28	
29	
3 A	
3 B	
3 C	
3 D	
3 E	
3 F	
3 H	
3 I	
3 K	
3 L	
3 N	
3 P	
3 Q	
3 R	
3 S	
3 T	
3 X	
30	
31	
32	

Chicago Public Schools

School Seward School Branch **Unit** 25302 **Building ID** 5821

Address 4541 South Wood Street **Region** 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
33	
3G	
3J	
5	
8	
9	
A 2	
B 2	
C 1	
C1	Not observed 2016
D 1	Not observed 2016

Table II

Management Planner's Review

Chicago Public Schools

School Seward School Branch

Unit 25302

Building ID 5821

Address 4541 South Wood Street

Chicago, IL, 60609

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
01	Hard Coat Plaster	3,000	SF	Throughout, 1925	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
1 F	9" x 9" Pink Floor Tile	340	SF	Building #1 - Room 503	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
1 H	9" x 9" Red Floor Tile w/Brown & White Streaks	500	SF	Building #1 - East Foyer, West Stairwell	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
1 I	9" x 9" Light Tan & Brown Floor Tile	1,250	SF	Building.#1 - Entrance and Corridors, Stairwell Areas, Washrooms, Stage Area, 514	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
1 J	9" x 9" Light Brown & Beige Swirl Floor Tile	800	SF	Building #1 - Stage Area and Room 514	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
1 L	9" x 9" Gold Floor Tile	1,240	SF	Building #1 Lunchroom & Kitchen, Rear Basement Hall	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
1 N	9" x 9" Peach Floor Tile	450	SF	Building #1 - Room 504	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
1 P	9" x 9" Brown Floor Tile w/Orange & White Streaks	600	SF	Office and Room 507, Teacher's Lounge	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
1 Q	9" x 9" Medium Brown Floor Tile	200	SF	Main Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
1 R	9" x 9" Gray Floor Tile w/Pink Streaks	300	SF	Building #1 - Room 503	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
1 S	9"x9"Light Brown Floor Tile w/Brn & Orange Streaks	300	SF	Building #1 - Room 506	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
1 T	9" x 9" Brown Floor Tile w/Orange & Green Streaks	300	SF	Building #1 Room 508	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
1 X	9" x 9" Brown Floor Tile w/Brown & White Streaks	100	SF	Building #1 East & West Stairways	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
10	Spray-on Material			All Columns in Building #1	Assumed	SURFACE					
13	Drywall			Material Not Present	Undefined						
14	Fire Door Insulation	100	SF	Throughout Building	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
16	9" x 9" Floor Tile			Separated by color. See HA's 1A - 1Q	Undefined						
17 A	4" Black Vinyl Baseboard Mastic	800	SF	Throughout Building #1	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
17 B	4" Brown Vinyl Baseboard Mastic	800	LF	Throughout Building #1	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
18	Exterior Brick - Not AHERA			Building #1 Exterior	No ACBM						
19	Exterior Brick - Not AHERA			Building #2 Exterior	No ACBM						
1A	9" x 9" Tan Floor Tile w/Black & Red Streaks	940	SF	Building # 1 Office, Teacher's Washroom, Room 504	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
1B	9" x 9" Black Floor Tile	1,750	SF	Throughout Building #1 Classrooms, Corridors, Etc.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
1C	9" x 9" White Floor Tile	1,050	SF	Building #1 Throughout Various Rooms 506, 504, 508 Office etc.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
1D	9" x 9" Beige Floor Tile	1,000	SF	Building #1 Corridors and Rooms 508 and 506	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Seward School Branch

Unit 25302

Building ID 5821

Address 4541 South Wood Street

Chicago, IL, 60609

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
1E	9" x 9" Grey Floor Tile w/Black Streaks	1,000	SF	Building #1 Classrooms 505 & 507	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
1G	9" x 9" Lime Green FT w/Dark Green & White Streaks	224	SF	Building #1Basement Lunchroom/Gym , Kitchen & Room 505	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
1K	9" x 9" Dark Green Floor Tile	240	SF	Building #1 Lunchroom	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
20	Exterior Brick Mortar - Not AHERA			Building #1 Exterior	No ACBM						
26	Cinderblock	20,000	SF	Building #1	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
27	Cinderblock Mortar	20,000	SF	Building #1	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
28	Mortar Between Glass Block Windows	560	SF	Throughout Building #1	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
29	Adhesive Behind Chalk Boards and Bulletin Boards	2,000	SF	Building #1	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
3 A	9" x 9" Tan Floor Tile Mastic	800	SF	Building # 1 - Office, Teacher's Washroom, Room 504	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
3 B	9" x 9" Black Floor Tile Mastic	1,800	SF	Building #1 - Classrooms, Corridors, Etc.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
3 C	9" x 9" White Floor Tile Mastic	1,100	SF	Building #1 - Throughout Various Rooms 506, 504, 508 Office etc.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
3 D	9" x 9" Beige Floor Tile Mastic	970	SF	Building #1 - Corridors and Rooms 508 and 506	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
3 E	9" x 9" Grey Floor Tile w/Black Streaks Mastic	630	SF	Building #1 - Classrooms 505 & 507	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
3 F	9" x 9" Pink Floor Tile Mastic	340	SF	Building #1 Room 503	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
3 H	9" x 9" Red Floor Tile Mastic	800	SF	Building #1 - East Foyer, West Stairwell	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
3 I	9" x 9" Light Tan & Brown Floor Tile Mastic	1,250	SF	Building #1 - Entrance and Corridors, Stairwell Areas, Washrooms, Stage Area, 514	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
3 K	9" x 9" Dark Green Floor Tile Mastic	360	SF	Building #1 - Lunchroom	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
3 L	9" x 9" Gold Floor Tile Mastic	1,900	SF	Building #1 Lunchroom & Kitchen, Rear Basement Hall	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
3 N	9" x 9" Peach Floor Tile Mastic	450	SF	Building #1 Room 504	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
3 P	9" x 9" Brown Floor Tile w/ Orange & White Streaks	500	SF	Office and Room 507	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
3 Q	9" x 9" Medium Brown Floor Tile Mastic	200	SF	Main Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
3 R	9" x 9" Gray Floor Tile w/Pink Streaks Mastic	300	SF	Building #1 - Room 503	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
3 S	9"x9" Lt Brown FT w/Brown & Orange Streaks Mastic	500	SF	Building #1 - Room 506	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
3 T	9" x 9" Brown FT w/Orange & Green Streaks Mastic	500	SF	Building #1 - Room 508	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
3 X	9" x 9" Brown FT w/ Brown & White Streaks Mastic	100	SF	Building #1 - East & West Stairways	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Seward School Branch

Unit 25302

Building ID 5821

Address 4541 South Wood Street

Chicago, IL, 60609

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
30	Yellow Laminate	15	SF	Countertop in Kitchen	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
31	Yellow Laminate Adhesive	15	SF	Countertop in Kitchen	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
32	12" x 12" Pale Green w/Olive Green Specks FT	210	SF	Men's Basement Washroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
33	12" x 12" Pale Grn w/Olive Green Specks FT Mastic	210	SF	Men's Basement Washroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
3G	9" x 9" Lime Green FT w/Dark Green Streaks Mastic	22,000	SF	Building #1 - Basement Lunchroom/Gym , Kitchen & Room 505	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
3J	9" x 9" Light Brown & Beige Floor Tile Mastic	900	SF	Building #1 - Stage and Room 514	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
5	Air Vent Vibration Collar	10	LF	Building #1 - Closet	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
8	Hard Coat Plaster			Throughout Building #1	No ACBM	MISC					
9	Trowled-on Material			Throughout Building #1	No ACBM						
A 2	Aircell Pipe Insulation	700	LF	Throughout Building #1	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
B 2	Hard Joint Compound on Aircell Pipe Insulation	25	JOINTS	Throughout Building #1	Chrysotile	TSI	Yes	0	JOINTS	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
C 1	Cardboard Pipe Insulation	100	LF	Throughout Building #1	Assumed	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
C1	Cardboard Pipe Insulation			1st Floor Down N/E Stairway	Assumed	TSI					
D 1	Hard Joint Compound on Cardboard Pipe Insulation			Building #1	Assumed	TSI					

Chicago Public Schools

School Seward School Branch

Unit 25302

Building ID 5821

Address 4541 South Wood Street

Chicago, IL, 60609

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

Review Date	3/23/2016
Manager Planner Name	Todd Huffer
100-09870	5/15/2016
Manager IDPH License No/Expiration	

HA Number	Management Comments
01	
1 F	
1 H	
1 I	
1 J	
1 L	
1 N	
1 P	
1 Q	
1 R	
1 S	
1 T	
1 X	
10	Material Not Observed in 2016
13	
14	
16	
17 A	

Chicago Public Schools

School Seward School Branch

Unit 25302

Building ID 5821

Address 4541 South Wood Street

Chicago, IL, 60609

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
17 B	
18	
19	
1A	
1B	
1C	
1D	
1E	
1G	
1K	
20	
26	
27	
28	
29	
3 A	
3 B	
3 C	
3 D	
3 E	
3 F	
3 H	
3 I	
3 K	
3 L	
3 N	
3 P	

Chicago Public Schools

School Seward School Branch

Unit 25302

Building ID 5821

Address 4541 South Wood Street

Chicago, IL, 60609

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
3 Q	
3 R	
3 S	
3 T	
3 X	
30	
31	
32	
33	
3G	
3J	
5	
8	
9	
A 2	
B 2	
C 1	
C1	Not observed in 2016
D 1	Material Not Observed in 2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25302	BUILDING ID:	5821
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Robert DeBord		
SCHOOL NAME:	Seward School Branch	INSPECTION DATE:	3/9/2016		
ADDRESS:	4541 South Wood Street	IDPH LICENSE NO:	100-08864		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	01		
MATERIAL DESCRIPTION:	Hard Coat Plaster		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Throughout, 1925**

MATERIAL QUANTITY: **3000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/09/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25302** BUILDING ID: **5821**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Seward School Branch** REVIEW DATE: **3/23/2016**
ADDRESS: **4541 South Wood Street** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **01**
MATERIAL DESCRIPTION: **Hard Coat Plaster**
MATERIAL LOCATION: **Throughout, 1925**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/23/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25302	BUILDING ID:	5821
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Robert DeBord		
SCHOOL NAME:	Seward School Branch	INSPECTION DATE:	3/9/2016		
ADDRESS:	4541 South Wood Street	IDPH LICENSE NO:	100-08864		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	1 F		
MATERIAL DESCRIPTION:	9" x 9" Pink Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Building #1 - Room 503**

MATERIAL QUANTITY: **340**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/09/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25302** BUILDING ID: **5821**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Seward School Branch** REVIEW DATE: **3/23/2016**
ADDRESS: **4541 South Wood Street** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **1 F**
MATERIAL DESCRIPTION: **9" x 9" Pink Floor Tile**
MATERIAL LOCATION: **Building #1 - Room 503**
MATERIAL QUANTITY: **340** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/23/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25302	BUILDING ID:	5821
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Robert DeBord		
SCHOOL NAME:	Seward School Branch	INSPECTION DATE:	3/9/2016		
ADDRESS:	4541 South Wood Street	IDPH LICENSE NO:	100-08864		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	1 H		
MATERIAL DESCRIPTION:	9" x 9" Red Floor Tile w/Brown & White Streaks		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Building #1 - East Foyer, West Stairwell**

MATERIAL QUANTITY: **500**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/09/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25302** BUILDING ID: **5821**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Seward School Branch** REVIEW DATE: **3/23/2016**
ADDRESS: **4541 South Wood Street** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **1 H**
MATERIAL DESCRIPTION: **9" x 9" Red Floor Tile w/Brown & White Streaks**
MATERIAL LOCATION: **Building #1 - East Foyer, West Stairwell**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/23/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25302	BUILDING ID:	5821
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Robert DeBord		
SCHOOL NAME:	Seward School Branch	INSPECTION DATE:	3/9/2016		
ADDRESS:	4541 South Wood Street	IDPH LICENSE NO:	100-08864		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	1 I		
MATERIAL DESCRIPTION:	9" x 9" Light Tan & Brown Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Building.#1 - Entrance and Corridors, Stairwell Areas, Washrooms, Stage Area, 514**

MATERIAL QUANTITY: **1250**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/09/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25302** BUILDING ID: **5821**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Seward School Branch** REVIEW DATE: **3/23/2016**
ADDRESS: **4541 South Wood Street** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **1 I**
MATERIAL DESCRIPTION: **9" x 9" Light Tan & Brown Floor Tile**
MATERIAL LOCATION: **Building.#1 - Entrance and Corridors, Stairwell Areas, Washrooms, Stage Area, 514**
MATERIAL QUANTITY: **1250** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/23/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25302	BUILDING ID:	5821
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Robert DeBord		
SCHOOL NAME:	Seward School Branch	INSPECTION DATE:	3/9/2016		
ADDRESS:	4541 South Wood Street	IDPH LICENSE NO:	100-08864		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	1 J		
MATERIAL DESCRIPTION:	9" x 9" Light Brown & Beige Swirl Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Building #1 - Stage Area and Room 514**

MATERIAL QUANTITY: **800**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/09/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25302** BUILDING ID: **5821**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Seward School Branch** REVIEW DATE: **3/23/2016**
ADDRESS: **4541 South Wood Street** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **1 J**
MATERIAL DESCRIPTION: **9" x 9" Light Brown & Beige Swirl Floor Tile**
MATERIAL LOCATION: **Building #1 - Stage Area and Room 514**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/23/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25302	BUILDING ID:	5821
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Robert DeBord		
SCHOOL NAME:	Seward School Branch	INSPECTION DATE:	3/9/2016		
ADDRESS:	4541 South Wood Street	IDPH LICENSE NO:	100-08864		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	1 L		
MATERIAL DESCRIPTION:	9" x 9" Gold Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with potential for significant damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Building #1 Lunchroom & Kitchen, Rear Basement Hall		
MATERIAL QUANTITY:	1240	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 03/09/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25302** BUILDING ID: **5821**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Seward School Branch** REVIEW DATE: **3/23/2016**
ADDRESS: **4541 South Wood Street** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **1 L**
MATERIAL DESCRIPTION: **9" x 9" Gold Floor Tile**
MATERIAL LOCATION: **Building #1 Lunchroom & Kitchen, Rear Basement Hall**
MATERIAL QUANTITY: **1240** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/23/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25302	BUILDING ID:	5821
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Robert DeBord		
SCHOOL NAME:	Seward School Branch	INSPECTION DATE:	3/9/2016		
ADDRESS:	4541 South Wood Street	IDPH LICENSE NO:	100-08864		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	1 N		
MATERIAL DESCRIPTION:	9" x 9" Peach Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Building #1 - Room 504**

MATERIAL QUANTITY: **450**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/09/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25302** BUILDING ID: **5821**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Seward School Branch** REVIEW DATE: **3/23/2016**
ADDRESS: **4541 South Wood Street** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **1 N**
MATERIAL DESCRIPTION: **9" x 9" Peach Floor Tile**
MATERIAL LOCATION: **Building #1 - Room 504**
MATERIAL QUANTITY: **450** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/23/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25302	BUILDING ID:	5821
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Robert DeBord		
SCHOOL NAME:	Seward School Branch	INSPECTION DATE:	3/9/2016		
ADDRESS:	4541 South Wood Street	IDPH LICENSE NO:	100-08864		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	1 P		
MATERIAL DESCRIPTION:	9" x 9" Brown Floor Tile w/Orange & White Streaks		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Office and Room 507, Teacher's Lounge**

MATERIAL QUANTITY: **600**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/09/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25302** BUIDLING ID: **5821**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Seward School Branch** REVIEW DATE: **3/23/2016**
ADDRESS: **4541 South Wood Street** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **1 P**
MATERIAL DESCRIPTION: **9" x 9" Brown Floor Tile w/Orange & White Streaks**
MATERIAL LOCATION: **Office and Room 507, Teacher's Lounge**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/23/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25302	BUILDING ID:	5821
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Robert DeBord		
SCHOOL NAME:	Seward School Branch	INSPECTION DATE:	3/9/2016		
ADDRESS:	4541 South Wood Street	IDPH LICENSE NO:	100-08864		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	1 Q		
MATERIAL DESCRIPTION:	9" x 9" Medium Brown Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Main Office**

MATERIAL QUANTITY: **200**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **03/09/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25302** BUILDING ID: **5821**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Seward School Branch** REVIEW DATE: **3/23/2016**
ADDRESS: **4541 South Wood Street** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **1 Q**
MATERIAL DESCRIPTION: **9" x 9" Medium Brown Floor Tile**
MATERIAL LOCATION: **Main Office**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/23/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25302	BUILDING ID:	5821
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Robert DeBord		
SCHOOL NAME:	Seward School Branch	INSPECTION DATE:	3/9/2016		
ADDRESS:	4541 South Wood Street	IDPH LICENSE NO:	100-08864		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	1 R		
MATERIAL DESCRIPTION:	9" x 9" Gray Floor Tile w/Pink Streaks		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Building #1 - Room 503**

MATERIAL QUANTITY: **300**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/09/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25302** BUILDING ID: **5821**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Seward School Branch** REVIEW DATE: **3/23/2016**
ADDRESS: **4541 South Wood Street** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **1 R**
MATERIAL DESCRIPTION: **9" x 9" Gray Floor Tile w/Pink Streaks**
MATERIAL LOCATION: **Building #1 - Room 503**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/23/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25302	BUILDING ID:	5821
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Robert DeBord		
SCHOOL NAME:	Seward School Branch	INSPECTION DATE:	3/9/2016		
ADDRESS:	4541 South Wood Street	IDPH LICENSE NO:	100-08864		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	1 S		
MATERIAL DESCRIPTION:	9"x9"Light Brown Floor Tile w/Brn & Orange Streaks		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Building #1 - Room 506**

MATERIAL QUANTITY: **300**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/09/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25302** BUILDING ID: **5821**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Seward School Branch** REVIEW DATE: **3/23/2016**
ADDRESS: **4541 South Wood Street** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **1 S**
MATERIAL DESCRIPTION: **9"x9"Light Brown Floor Tile w/Brn & Orange Streaks**
MATERIAL LOCATION: **Building #1 - Room 506**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/23/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25302	BUILDING ID:	5821
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Robert DeBord		
SCHOOL NAME:	Seward School Branch	INSPECTION DATE:	3/9/2016		
ADDRESS:	4541 South Wood Street	IDPH LICENSE NO:	100-08864		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	1 T		
MATERIAL DESCRIPTION:	9" x 9" Brown Floor Tile w/Orange & Green Streaks		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Building #1 Room 508**

MATERIAL QUANTITY: **300**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **03/09/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25302** BUILDING ID: **5821**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Seward School Branch** REVIEW DATE: **3/23/2016**
ADDRESS: **4541 South Wood Street** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **1 T**
MATERIAL DESCRIPTION: **9" x 9" Brown Floor Tile w/Orange & Green Streaks**
MATERIAL LOCATION: **Building #1 Room 508**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/23/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25302	BUILDING ID:	5821
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Robert DeBord		
SCHOOL NAME:	Seward School Branch	INSPECTION DATE:	3/9/2016		
ADDRESS:	4541 South Wood Street	IDPH LICENSE NO:	100-08864		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	1 X		
MATERIAL DESCRIPTION:	9" x 9" Brown Floor Tile w/Brown & White Streaks		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Building #1 East & West Stairways**

MATERIAL QUANTITY: **100**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/09/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25302** BUIDLING ID: **5821**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Seward School Branch** REVIEW DATE: **3/23/2016**
ADDRESS: **4541 South Wood Street** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **1 X**
MATERIAL DESCRIPTION: **9" x 9" Brown Floor Tile w/Brown & White Streaks**
MATERIAL LOCATION: **Building #1 East & West Stairways**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/23/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25302	BUILDING ID:	5821
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Robert DeBord		
SCHOOL NAME:	Seward School Branch	INSPECTION DATE:	3/9/2016		
ADDRESS:	4541 South Wood Street	IDPH LICENSE NO:	100-08864		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	10	
MATERIAL DESCRIPTION:	Spray-on Material	
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: All Columns in Building #1

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Not observed 2016

Inspector's Signature: _____ Date: 03/09/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25302** BUILDING ID: **5821**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Seward School Branch** REVIEW DATE: **3/23/2016**
ADDRESS: **4541 South Wood Street** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **10**
MATERIAL DESCRIPTION: **Spray-on Material**
MATERIAL LOCATION: **All Columns in Building #1**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Material Not Observed in 2016

Management Planner's Signature: _____



Date: **03/23/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25302	BUILDING ID:	5821
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Robert DeBord		
SCHOOL NAME:	Seward School Branch	INSPECTION DATE:	3/9/2016		
ADDRESS:	4541 South Wood Street	IDPH LICENSE NO:	100-08864		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	13	
MATERIAL DESCRIPTION:	Drywall	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Undefined	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 03/09/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25302** BUILDING ID: **5821**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Seward School Branch** REVIEW DATE: **3/23/2016**
ADDRESS: **4541 South Wood Street** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **13**
MATERIAL DESCRIPTION: **Drywall**
MATERIAL LOCATION: **Material Not Present**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **03/23/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25302	BUILDING ID:	5821
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Robert DeBord		
SCHOOL NAME:	Seward School Branch	INSPECTION DATE:	3/9/2016		
ADDRESS:	4541 South Wood Street	IDPH LICENSE NO:	100-08864		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	14		
MATERIAL DESCRIPTION:	Fire Door Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	7 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout Building		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 03/09/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25302** BUILDING ID: **5821**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Seward School Branch** REVIEW DATE: **3/23/2016**
ADDRESS: **4541 South Wood Street** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **14**
MATERIAL DESCRIPTION: **Fire Door Insulation**
MATERIAL LOCATION: **Throughout Building**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/23/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25302	BUILDING ID:	5821
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Robert DeBord		
SCHOOL NAME:	Seward School Branch	INSPECTION DATE:	3/9/2016		
ADDRESS:	4541 South Wood Street	IDPH LICENSE NO:	100-08864		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	16	
MATERIAL DESCRIPTION:	9" x 9" Floor Tile	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Undefined	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Separated by color. See HA's 1A - 1Q

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 03/09/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25302** BUIDLING ID: **5821**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Seward School Branch** REVIEW DATE: **3/23/2016**
ADDRESS: **4541 South Wood Street** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **16**
MATERIAL DESCRIPTION: **9" x 9" Floor Tile**
MATERIAL LOCATION: **Separated by color. See HA's 1A - 1Q**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **03/23/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25302	BUILDING ID:	5821
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Robert DeBord		
SCHOOL NAME:	Seward School Branch	INSPECTION DATE:	3/9/2016		
ADDRESS:	4541 South Wood Street	IDPH LICENSE NO:	100-08864		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	17 A		
MATERIAL DESCRIPTION:	4" Black Vinyl Baseboard Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Throughout Building #1**

MATERIAL QUANTITY: **800**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/09/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25302** BUILDING ID: **5821**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Seward School Branch** REVIEW DATE: **3/23/2016**
ADDRESS: **4541 South Wood Street** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **17 A**
MATERIAL DESCRIPTION: **4" Black Vinyl Baseboard Mastic**
MATERIAL LOCATION: **Throughout Building #1**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/23/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25302	BUILDING ID:	5821
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Robert DeBord		
SCHOOL NAME:	Seward School Branch	INSPECTION DATE:	3/9/2016		
ADDRESS:	4541 South Wood Street	IDPH LICENSE NO:	100-08864		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	17 B		
MATERIAL DESCRIPTION:	4" Brown Vinyl Baseboard Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Throughout Building #1**

MATERIAL QUANTITY: **800**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: **03/09/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25302** BUILDING ID: **5821**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Seward School Branch** REVIEW DATE: **3/23/2016**
ADDRESS: **4541 South Wood Street** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **17 B**
MATERIAL DESCRIPTION: **4" Brown Vinyl Baseboard Mastic**
MATERIAL LOCATION: **Throughout Building #1**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/23/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25302	BUILDING ID:	5821
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Robert DeBord		
SCHOOL NAME:	Seward School Branch	INSPECTION DATE:	3/9/2016		
ADDRESS:	4541 South Wood Street	IDPH LICENSE NO:	100-08864		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	18	
MATERIAL DESCRIPTION:	Exterior Brick - Not AHERA	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Building #1 Exterior

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 03/09/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25302** BUILDING ID: **5821**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Seward School Branch** REVIEW DATE: **3/23/2016**
ADDRESS: **4541 South Wood Street** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **18**
MATERIAL DESCRIPTION: **Exterior Brick - Not AHERA**
MATERIAL LOCATION: **Building #1 Exterior**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **03/23/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25302	BUILDING ID:	5821
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Robert DeBord		
SCHOOL NAME:	Seward School Branch	INSPECTION DATE:	3/9/2016		
ADDRESS:	4541 South Wood Street	IDPH LICENSE NO:	100-08864		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	19	
MATERIAL DESCRIPTION:	Exterior Brick - Not AHERA	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Building #2 Exterior

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 03/09/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25302** BUILDING ID: **5821**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Seward School Branch** REVIEW DATE: **3/23/2016**
ADDRESS: **4541 South Wood Street** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **19**
MATERIAL DESCRIPTION: **Exterior Brick - Not AHERA**
MATERIAL LOCATION: **Building #2 Exterior**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **03/23/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25302	BUILDING ID:	5821
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Robert DeBord		
SCHOOL NAME:	Seward School Branch	INSPECTION DATE:	3/9/2016		
ADDRESS:	4541 South Wood Street	IDPH LICENSE NO:	100-08864		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	1A		
MATERIAL DESCRIPTION:	9" x 9" Tan Floor Tile w/Black & Red Streaks		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Building # 1 Office, Teacher's Washroom, Room 504**

MATERIAL QUANTITY: **940**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/09/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25302** BUILDING ID: **5821**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Seward School Branch** REVIEW DATE: **3/23/2016**
ADDRESS: **4541 South Wood Street** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **1A**
MATERIAL DESCRIPTION: **9" x 9" Tan Floor Tile w/Black & Red Streaks**
MATERIAL LOCATION: **Building # 1 Office, Teacher's Washroom, Room 504**
MATERIAL QUANTITY: **940** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/23/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25302	BUILDING ID:	5821
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Robert DeBord		
SCHOOL NAME:	Seward School Branch	INSPECTION DATE:	3/9/2016		
ADDRESS:	4541 South Wood Street	IDPH LICENSE NO:	100-08864		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	1B		
MATERIAL DESCRIPTION:	9" x 9" Black Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout Building #1 Classrooms, Corridors, Etc.		
MATERIAL QUANTITY:	1750	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 03/09/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25302** BUILDING ID: **5821**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Seward School Branch** REVIEW DATE: **3/23/2016**
ADDRESS: **4541 South Wood Street** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **1B**
MATERIAL DESCRIPTION: **9" x 9" Black Floor Tile**
MATERIAL LOCATION: **Throughout Building #1 Classrooms, Corridors, Etc.**
MATERIAL QUANTITY: **1750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/23/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25302	BUILDING ID:	5821
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Robert DeBord		
SCHOOL NAME:	Seward School Branch	INSPECTION DATE:	3/9/2016		
ADDRESS:	4541 South Wood Street	IDPH LICENSE NO:	100-08864		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	1C		
MATERIAL DESCRIPTION:	9" x 9" White Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Building #1 Throughout Various Rooms 506, 504, 508 Office etc.		
MATERIAL QUANTITY:	1050	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 03/09/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25302** BUILDING ID: **5821**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Seward School Branch** REVIEW DATE: **3/23/2016**
ADDRESS: **4541 South Wood Street** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **1C**
MATERIAL DESCRIPTION: **9" x 9" White Floor Tile**
MATERIAL LOCATION: **Building #1 Throughout Various Rooms 506, 504, 508 Office etc.**
MATERIAL QUANTITY: **1050** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/23/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25302	BUILDING ID:	5821
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Robert DeBord		
SCHOOL NAME:	Seward School Branch	INSPECTION DATE:	3/9/2016		
ADDRESS:	4541 South Wood Street	IDPH LICENSE NO:	100-08864		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	1D		
MATERIAL DESCRIPTION:	9" x 9" Beige Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Building #1 Corridors and Rooms 508 and 506		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 03/09/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25302** BUILDING ID: **5821**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Seward School Branch** REVIEW DATE: **3/23/2016**
ADDRESS: **4541 South Wood Street** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **1D**
MATERIAL DESCRIPTION: **9" x 9" Beige Floor Tile**
MATERIAL LOCATION: **Building #1 Corridors and Rooms 508 and 506**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/23/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25302	BUILDING ID:	5821
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Robert DeBord		
SCHOOL NAME:	Seward School Branch	INSPECTION DATE:	3/9/2016		
ADDRESS:	4541 South Wood Street	IDPH LICENSE NO:	100-08864		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	1E		
MATERIAL DESCRIPTION:	9" x 9" Grey Floor Tile w/Black Streaks		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Building #1 Classrooms 505 & 507**

MATERIAL QUANTITY: **1000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/09/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25302** BUIDLING ID: **5821**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Seward School Branch** REVIEW DATE: **3/23/2016**
ADDRESS: **4541 South Wood Street** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **1E**
MATERIAL DESCRIPTION: **9" x 9" Grey Floor Tile w/Black Streaks**
MATERIAL LOCATION: **Building #1 Classrooms 505 & 507**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **03/23/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25302	BUILDING ID:	5821
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Robert DeBord		
SCHOOL NAME:	Seward School Branch	INSPECTION DATE:	3/9/2016		
ADDRESS:	4541 South Wood Street	IDPH LICENSE NO:	100-08864		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	1G		
MATERIAL DESCRIPTION:	9" x 9" Lime Green FT w/Dark Green & White Streaks		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with potential for significant damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Building #1Basement Lunchroom/Gym , Kitchen & Room 505**

MATERIAL QUANTITY: **224** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/09/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25302** BUIDLING ID: **5821**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Seward School Branch** REVIEW DATE: **3/23/2016**
ADDRESS: **4541 South Wood Street** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **1G**
MATERIAL DESCRIPTION: **9" x 9" Lime Green FT w/Dark Green & White Streaks**
MATERIAL LOCATION: **Building #1Basement Lunchroom/Gym , Kitchen & Room 505**
MATERIAL QUANTITY: **224** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/23/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25302	BUILDING ID:	5821
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Robert DeBord		
SCHOOL NAME:	Seward School Branch	INSPECTION DATE:	3/9/2016		
ADDRESS:	4541 South Wood Street	IDPH LICENSE NO:	100-08864		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	1K		
MATERIAL DESCRIPTION:	9" x 9" Dark Green Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Building #1 Lunchroom		
MATERIAL QUANTITY:	240	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 03/09/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25302** BUIDLING ID: **5821**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Seward School Branch** REVIEW DATE: **3/23/2016**
ADDRESS: **4541 South Wood Street** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **1K**
MATERIAL DESCRIPTION: **9" x 9" Dark Green Floor Tile**
MATERIAL LOCATION: **Building #1 Lunchroom**
MATERIAL QUANTITY: **240** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/23/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25302	BUILDING ID:	5821
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Robert DeBord		
SCHOOL NAME:	Seward School Branch	INSPECTION DATE:	3/9/2016		
ADDRESS:	4541 South Wood Street	IDPH LICENSE NO:	100-08864		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	20	
MATERIAL DESCRIPTION:	Exterior Brick Mortar - Not AHERA	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Building #1 Exterior

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 03/09/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25302** BUILDING ID: **5821**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Seward School Branch** REVIEW DATE: **3/23/2016**
ADDRESS: **4541 South Wood Street** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **20**

MATERIAL DESCRIPTION: **Exterior Brick Mortar - Not AHERA**

MATERIAL LOCATION: **Building #1 Exterior**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **03/23/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25302	BUILDING ID:	5821
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Robert DeBord		
SCHOOL NAME:	Seward School Branch	INSPECTION DATE:	3/9/2016		
ADDRESS:	4541 South Wood Street	IDPH LICENSE NO:	100-08864		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	26		
MATERIAL DESCRIPTION:	Cinderblock		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Building #1**

MATERIAL QUANTITY: **20000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **03/09/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25302** BUILDING ID: **5821**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Seward School Branch** REVIEW DATE: **3/23/2016**
ADDRESS: **4541 South Wood Street** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **26**
MATERIAL DESCRIPTION: **Cinderblock**
MATERIAL LOCATION: **Building #1**
MATERIAL QUANTITY: **20000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/23/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25302	BUILDING ID:	5821
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Robert DeBord		
SCHOOL NAME:	Seward School Branch	INSPECTION DATE:	3/9/2016		
ADDRESS:	4541 South Wood Street	IDPH LICENSE NO:	100-08864		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	27		
MATERIAL DESCRIPTION:	Cinderblock Mortar		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Building #1		
MATERIAL QUANTITY:	20000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 03/09/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25302** BUILDING ID: **5821**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Seward School Branch** REVIEW DATE: **3/23/2016**
ADDRESS: **4541 South Wood Street** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **27**
MATERIAL DESCRIPTION: **Cinderblock Mortar**
MATERIAL LOCATION: **Building #1**
MATERIAL QUANTITY: **20000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/23/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25302	BUILDING ID:	5821
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Robert DeBord		
SCHOOL NAME:	Seward School Branch	INSPECTION DATE:	3/9/2016		
ADDRESS:	4541 South Wood Street	IDPH LICENSE NO:	100-08864		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	28		
MATERIAL DESCRIPTION:	Mortar Between Glass Block Windows		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Throughout Building #1**

MATERIAL QUANTITY: **560**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **03/09/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25302** BUILDING ID: **5821**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Seward School Branch** REVIEW DATE: **3/23/2016**
ADDRESS: **4541 South Wood Street** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **28**
MATERIAL DESCRIPTION: **Mortar Between Glass Block Windows**
MATERIAL LOCATION: **Throughout Building #1**
MATERIAL QUANTITY: **560** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/23/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25302	BUILDING ID:	5821
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Robert DeBord		
SCHOOL NAME:	Seward School Branch	INSPECTION DATE:	3/9/2016		
ADDRESS:	4541 South Wood Street	IDPH LICENSE NO:	100-08864		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	29		
MATERIAL DESCRIPTION:	Adhesive Behind Chalk Boards and Bulletin Boards		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Building #1**

MATERIAL QUANTITY: **2000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/09/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25302** BUILDING ID: **5821**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Seward School Branch** REVIEW DATE: **3/23/2016**
ADDRESS: **4541 South Wood Street** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **29**
MATERIAL DESCRIPTION: **Adhesive Behind Chalk Boards and Bulletin Boards**
MATERIAL LOCATION: **Building #1**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/23/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25302	BUILDING ID:	5821
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Robert DeBord		
SCHOOL NAME:	Seward School Branch	INSPECTION DATE:	3/9/2016		
ADDRESS:	4541 South Wood Street	IDPH LICENSE NO:	100-08864		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	3 A		
MATERIAL DESCRIPTION:	9" x 9" Tan Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Building # 1 - Office, Teacher's Washroom, Room 504		
MATERIAL QUANTITY:	800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 03/09/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25302** BUIDLING ID: **5821**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Seward School Branch** REVIEW DATE: **3/23/2016**
ADDRESS: **4541 South Wood Street** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **3 A**
MATERIAL DESCRIPTION: **9" x 9" Tan Floor Tile Mastic**
MATERIAL LOCATION: **Building # 1 - Office, Teacher's Washroom, Room 504**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/23/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25302	BUILDING ID:	5821
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Robert DeBord		
SCHOOL NAME:	Seward School Branch	INSPECTION DATE:	3/9/2016		
ADDRESS:	4541 South Wood Street	IDPH LICENSE NO:	100-08864		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	3 B		
MATERIAL DESCRIPTION:	9" x 9" Black Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Building #1 - Classrooms, Corridors, Etc.**

MATERIAL QUANTITY: **1800**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/09/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25302** BUILDING ID: **5821**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Seward School Branch** REVIEW DATE: **3/23/2016**
ADDRESS: **4541 South Wood Street** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **3 B**
MATERIAL DESCRIPTION: **9" x 9" Black Floor Tile Mastic**
MATERIAL LOCATION: **Building #1 - Classrooms, Corridors, Etc.**
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/23/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25302	BUILDING ID:	5821
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Robert DeBord		
SCHOOL NAME:	Seward School Branch	INSPECTION DATE:	3/9/2016		
ADDRESS:	4541 South Wood Street	IDPH LICENSE NO:	100-08864		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	3 C		
MATERIAL DESCRIPTION:	9" x 9" White Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Building #1 - Throughout Various Rooms 506, 504, 508 Office etc.		
MATERIAL QUANTITY:	1100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 03/09/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25302** BUIDLING ID: **5821**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Seward School Branch** REVIEW DATE: **3/23/2016**
ADDRESS: **4541 South Wood Street** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **3 C**
MATERIAL DESCRIPTION: **9" x 9" White Floor Tile Mastic**
MATERIAL LOCATION: **Building #1 - Throughout Various Rooms 506, 504, 508 Office etc.**
MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/23/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25302	BUILDING ID:	5821
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Robert DeBord		
SCHOOL NAME:	Seward School Branch	INSPECTION DATE:	3/9/2016		
ADDRESS:	4541 South Wood Street	IDPH LICENSE NO:	100-08864		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	3 D		
MATERIAL DESCRIPTION:	9" x 9" Beige Floor Tile	Mastic	
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Building #1 - Corridors and Rooms 508 and 506**

MATERIAL QUANTITY: **970**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **03/09/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25302** BUIDLING ID: **5821**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Seward School Branch** REVIEW DATE: **3/23/2016**
ADDRESS: **4541 South Wood Street** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **3 D**
MATERIAL DESCRIPTION: **9" x 9" Beige Floor Tile Mastic**
MATERIAL LOCATION: **Building #1 - Corridors and Rooms 508 and 506**
MATERIAL QUANTITY: **970** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/23/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25302	BUILDING ID:	5821
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Robert DeBord		
SCHOOL NAME:	Seward School Branch	INSPECTION DATE:	3/9/2016		
ADDRESS:	4541 South Wood Street	IDPH LICENSE NO:	100-08864		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	3 E		
MATERIAL DESCRIPTION:	9" x 9" Grey Floor Tile w/Black Streaks Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Building #1 - Classrooms 505 & 507**

MATERIAL QUANTITY: **630**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/09/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25302** BUILDING ID: **5821**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Seward School Branch** REVIEW DATE: **3/23/2016**
ADDRESS: **4541 South Wood Street** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **3 E**
MATERIAL DESCRIPTION: **9" x 9" Grey Floor Tile w/Black Streaks Mastic**
MATERIAL LOCATION: **Building #1 - Classrooms 505 & 507**
MATERIAL QUANTITY: **630** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/23/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25302	BUILDING ID:	5821
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Robert DeBord		
SCHOOL NAME:	Seward School Branch	INSPECTION DATE:	3/9/2016		
ADDRESS:	4541 South Wood Street	IDPH LICENSE NO:	100-08864		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	3 F		
MATERIAL DESCRIPTION:	9" x 9" Pink Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Building #1 Room 503**

MATERIAL QUANTITY: **340**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/09/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25302** BUILDING ID: **5821**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Seward School Branch** REVIEW DATE: **3/23/2016**
ADDRESS: **4541 South Wood Street** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **3 F**
MATERIAL DESCRIPTION: **9" x 9" Pink Floor Tile Mastic**
MATERIAL LOCATION: **Building #1 Room 503**
MATERIAL QUANTITY: **340** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/23/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25302	BUILDING ID:	5821
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Robert DeBord		
SCHOOL NAME:	Seward School Branch	INSPECTION DATE:	3/9/2016		
ADDRESS:	4541 South Wood Street	IDPH LICENSE NO:	100-08864		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	3 H		
MATERIAL DESCRIPTION:	9" x 9" Red Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Building #1 - East Foyer, West Stairwell**

MATERIAL QUANTITY: **800**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/09/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25302** BUILDING ID: **5821**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Seward School Branch** REVIEW DATE: **3/23/2016**
ADDRESS: **4541 South Wood Street** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **3 H**
MATERIAL DESCRIPTION: **9" x 9" Red Floor Tile Mastic**
MATERIAL LOCATION: **Building #1 - East Foyer, West Stairwell**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/23/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25302	BUILDING ID:	5821
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Robert DeBord		
SCHOOL NAME:	Seward School Branch	INSPECTION DATE:	3/9/2016		
ADDRESS:	4541 South Wood Street	IDPH LICENSE NO:	100-08864		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	3 I		
MATERIAL DESCRIPTION:	9" x 9" Light Tan & Brown Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Building #1 - Entrance and Corridors, Stairwell Areas, Washrooms, Stage Area, 514**

MATERIAL QUANTITY: **1250**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/09/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25302** BUIDLING ID: **5821**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Seward School Branch** REVIEW DATE: **3/23/2016**
ADDRESS: **4541 South Wood Street** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **3 I**
MATERIAL DESCRIPTION: **9" x 9" Light Tan & Brown Floor Tile Mastic**
MATERIAL LOCATION: **Building #1 - Entrance and Corridors, Stairwell Areas, Washrooms, Stage Area, 514**
MATERIAL QUANTITY: **1250** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/23/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25302	BUILDING ID:	5821
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Robert DeBord		
SCHOOL NAME:	Seward School Branch	INSPECTION DATE:	3/9/2016		
ADDRESS:	4541 South Wood Street	IDPH LICENSE NO:	100-08864		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	3 K		
MATERIAL DESCRIPTION:	9" x 9" Dark Green Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Building #1 - Lunchroom		
MATERIAL QUANTITY:	360	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 03/09/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25302** BUIDLING ID: **5821**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Seward School Branch** REVIEW DATE: **3/23/2016**
ADDRESS: **4541 South Wood Street** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **3 K**
MATERIAL DESCRIPTION: **9" x 9" Dark Green Floor Tile Mastic**
MATERIAL LOCATION: **Building #1 - Lunchroom**
MATERIAL QUANTITY: **360** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/23/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25302	BUILDING ID:	5821
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Robert DeBord		
SCHOOL NAME:	Seward School Branch	INSPECTION DATE:	3/9/2016		
ADDRESS:	4541 South Wood Street	IDPH LICENSE NO:	100-08864		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	3 L		
MATERIAL DESCRIPTION:	9" x 9" Gold Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Building #1 Lunchroom & Kitchen, Rear Basement Hall**

MATERIAL QUANTITY: **1900** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/09/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25302** BUIDLING ID: **5821**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Seward School Branch** REVIEW DATE: **3/23/2016**
ADDRESS: **4541 South Wood Street** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **3 L**
MATERIAL DESCRIPTION: **9" x 9" Gold Floor Tile Mastic**
MATERIAL LOCATION: **Building #1 Lunchroom & Kitchen, Rear Basement Hall**
MATERIAL QUANTITY: **1900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/23/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25302	BUILDING ID:	5821
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Robert DeBord		
SCHOOL NAME:	Seward School Branch	INSPECTION DATE:	3/9/2016		
ADDRESS:	4541 South Wood Street	IDPH LICENSE NO:	100-08864		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	3 N		
MATERIAL DESCRIPTION:	9" x 9" Peach Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Building #1 Room 504**

MATERIAL QUANTITY: **450**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/09/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25302** BUILDING ID: **5821**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Seward School Branch** REVIEW DATE: **3/23/2016**
ADDRESS: **4541 South Wood Street** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **3 N**
MATERIAL DESCRIPTION: **9" x 9" Peach Floor Tile Mastic**
MATERIAL LOCATION: **Building #1 Room 504**
MATERIAL QUANTITY: **450** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/23/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25302	BUILDING ID:	5821
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Robert DeBord		
SCHOOL NAME:	Seward School Branch	INSPECTION DATE:	3/9/2016		
ADDRESS:	4541 South Wood Street	IDPH LICENSE NO:	100-08864		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	3 P		
MATERIAL DESCRIPTION:	9" x 9" Brown Floor Tile w/ Orange & White Streaks		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Office and Room 507**

MATERIAL QUANTITY: **500**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/09/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25302** BUIDLING ID: **5821**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Seward School Branch** REVIEW DATE: **3/23/2016**
ADDRESS: **4541 South Wood Street** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **3 P**
MATERIAL DESCRIPTION: **9" x 9" Brown Floor Tile w/ Orange & White Streaks**
MATERIAL LOCATION: **Office and Room 507**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/23/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25302	BUILDING ID:	5821
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Robert DeBord		
SCHOOL NAME:	Seward School Branch	INSPECTION DATE:	3/9/2016		
ADDRESS:	4541 South Wood Street	IDPH LICENSE NO:	100-08864		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	3 Q		
MATERIAL DESCRIPTION:	9" x 9" Medium Brown Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Main Office**

MATERIAL QUANTITY: **200**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/09/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25302** BUILDING ID: **5821**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Seward School Branch** REVIEW DATE: **3/23/2016**
ADDRESS: **4541 South Wood Street** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **3 Q**
MATERIAL DESCRIPTION: **9" x 9" Medium Brown Floor Tile Mastic**
MATERIAL LOCATION: **Main Office**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/23/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25302	BUILDING ID:	5821
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Robert DeBord		
SCHOOL NAME:	Seward School Branch	INSPECTION DATE:	3/9/2016		
ADDRESS:	4541 South Wood Street	IDPH LICENSE NO:	100-08864		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	3 R		
MATERIAL DESCRIPTION:	9" x 9" Gray Floor Tile w/Pink Streaks Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Building #1 - Room 503**

MATERIAL QUANTITY: **300**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/09/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25302** BUIDLING ID: **5821**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Seward School Branch** REVIEW DATE: **3/23/2016**
ADDRESS: **4541 South Wood Street** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **3 R**
MATERIAL DESCRIPTION: **9" x 9" Gray Floor Tile w/Pink Streaks Mastic**
MATERIAL LOCATION: **Building #1 - Room 503**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/23/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25302	BUILDING ID:	5821
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Robert DeBord		
SCHOOL NAME:	Seward School Branch	INSPECTION DATE:	3/9/2016		
ADDRESS:	4541 South Wood Street	IDPH LICENSE NO:	100-08864		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	3 S		
MATERIAL DESCRIPTION:	9"x9" Lt Brown FT w/Brown & Orange Streaks Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Building #1 - Room 506**

MATERIAL QUANTITY: **500**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/09/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25302** BUILDING ID: **5821**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Seward School Branch** REVIEW DATE: **3/23/2016**
ADDRESS: **4541 South Wood Street** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **3 S**
MATERIAL DESCRIPTION: **9"x9" Lt Brown FT w/Brown & Orange Streaks Mastic**
MATERIAL LOCATION: **Building #1 - Room 506**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/23/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25302	BUILDING ID:	5821
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Robert DeBord		
SCHOOL NAME:	Seward School Branch	INSPECTION DATE:	3/9/2016		
ADDRESS:	4541 South Wood Street	IDPH LICENSE NO:	100-08864		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	3 T		
MATERIAL DESCRIPTION:	9" x 9" Brown FT w/Orange & Green Streaks Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Building #1 - Room 508**

MATERIAL QUANTITY: **500**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/09/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25302** BUIDLING ID: **5821**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Seward School Branch** REVIEW DATE: **3/23/2016**
ADDRESS: **4541 South Wood Street** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **3 T**
MATERIAL DESCRIPTION: **9" x 9" Brown FT w/Orange & Green Streaks Mastic**
MATERIAL LOCATION: **Building #1 - Room 508**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/23/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25302	BUILDING ID:	5821
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Robert DeBord		
SCHOOL NAME:	Seward School Branch	INSPECTION DATE:	3/9/2016		
ADDRESS:	4541 South Wood Street	IDPH LICENSE NO:	100-08864		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	3 X		
MATERIAL DESCRIPTION:	9" x 9" Brown FT w/ Brown & White Streaks Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Building #1 - East & West Stairways**

MATERIAL QUANTITY: **100**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/09/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25302** BUILDING ID: **5821**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Seward School Branch** REVIEW DATE: **3/23/2016**
ADDRESS: **4541 South Wood Street** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **3 X**
MATERIAL DESCRIPTION: **9" x 9" Brown FT w/ Brown & White Streaks Mastic**
MATERIAL LOCATION: **Building #1 - East & West Stairways**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/23/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25302	BUILDING ID:	5821
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Robert DeBord		
SCHOOL NAME:	Seward School Branch	INSPECTION DATE:	3/9/2016		
ADDRESS:	4541 South Wood Street	IDPH LICENSE NO:	100-08864		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	30		
MATERIAL DESCRIPTION:	Yellow Laminate		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Countertop in Kitchen		
MATERIAL QUANTITY:	15	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 03/09/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25302** BUIDLING ID: **5821**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Seward School Branch** REVIEW DATE: **3/23/2016**
ADDRESS: **4541 South Wood Street** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **30**
MATERIAL DESCRIPTION: **Yellow Laminate**
MATERIAL LOCATION: **Countertop in Kitchen**
MATERIAL QUANTITY: **15** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/23/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25302	BUILDING ID:	5821
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Robert DeBord		
SCHOOL NAME:	Seward School Branch	INSPECTION DATE:	3/9/2016		
ADDRESS:	4541 South Wood Street	IDPH LICENSE NO:	100-08864		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	31		
MATERIAL DESCRIPTION:	Yellow Laminate Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Countertop in Kitchen		
MATERIAL QUANTITY:	15	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 03/09/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25302** BUIDLING ID: **5821**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Seward School Branch** REVIEW DATE: **3/23/2016**
ADDRESS: **4541 South Wood Street** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **31**
MATERIAL DESCRIPTION: **Yellow Laminate Adhesive**
MATERIAL LOCATION: **Countertop in Kitchen**
MATERIAL QUANTITY: **15** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/23/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25302	BUILDING ID:	5821
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Robert DeBord		
SCHOOL NAME:	Seward School Branch	INSPECTION DATE:	3/9/2016		
ADDRESS:	4541 South Wood Street	IDPH LICENSE NO:	100-08864		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	32		
MATERIAL DESCRIPTION:	12" x 12" Pale Green w/Olive Green Specks FT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Men's Basement Washroom**

MATERIAL QUANTITY: **210**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/09/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25302** BUIDLING ID: **5821**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Seward School Branch** REVIEW DATE: **3/23/2016**
ADDRESS: **4541 South Wood Street** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **32**
MATERIAL DESCRIPTION: **12" x 12" Pale Green w/Olive Green Specks FT**
MATERIAL LOCATION: **Men's Basement Washroom**
MATERIAL QUANTITY: **210** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/23/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25302	BUILDING ID:	5821
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Robert DeBord		
SCHOOL NAME:	Seward School Branch	INSPECTION DATE:	3/9/2016		
ADDRESS:	4541 South Wood Street	IDPH LICENSE NO:	100-08864		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	33		
MATERIAL DESCRIPTION:	12" x 12" Pale Grn w/Olive Green Specks FT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Men's Basement Washroom**

MATERIAL QUANTITY: **210**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/09/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25302** BUIDLING ID: **5821**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Seward School Branch** REVIEW DATE: **3/23/2016**
ADDRESS: **4541 South Wood Street** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **33**
MATERIAL DESCRIPTION: **12" x 12" Pale Grn w/Olive Green Specks FT Mastic**
MATERIAL LOCATION: **Men's Basement Washroom**
MATERIAL QUANTITY: **210** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/23/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25302	BUILDING ID:	5821
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Robert DeBord		
SCHOOL NAME:	Seward School Branch	INSPECTION DATE:	3/9/2016		
ADDRESS:	4541 South Wood Street	IDPH LICENSE NO:	100-08864		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	3G		
MATERIAL DESCRIPTION:	9" x 9" Lime Green FT w/Dark Green Streaks Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Building #1 - Basement Lunchroom/Gym , Kitchen & Room 505**

MATERIAL QUANTITY: **22000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/09/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25302** BUILDING ID: **5821**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Seward School Branch** REVIEW DATE: **3/23/2016**
ADDRESS: **4541 South Wood Street** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **3G**
MATERIAL DESCRIPTION: **9" x 9" Lime Green FT w/Dark Green Streaks Mastic**
MATERIAL LOCATION: **Building #1 - Basement Lunchroom/Gym , Kitchen & Room 505**
MATERIAL QUANTITY: **22000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/23/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25302	BUILDING ID:	5821
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Robert DeBord		
SCHOOL NAME:	Seward School Branch	INSPECTION DATE:	3/9/2016		
ADDRESS:	4541 South Wood Street	IDPH LICENSE NO:	100-08864		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	3J		
MATERIAL DESCRIPTION:	9" x 9" Light Brown & Beige Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Building #1 - Stage and Room 514**

MATERIAL QUANTITY: **900**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/09/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25302** BUIDLING ID: **5821**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Seward School Branch** REVIEW DATE: **3/23/2016**
ADDRESS: **4541 South Wood Street** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **3J**
MATERIAL DESCRIPTION: **9" x 9" Light Brown & Beige Floor Tile Mastic**
MATERIAL LOCATION: **Building #1 - Stage and Room 514**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/23/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25302	BUILDING ID:	5821
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Robert DeBord		
SCHOOL NAME:	Seward School Branch	INSPECTION DATE:	3/9/2016		
ADDRESS:	4541 South Wood Street	IDPH LICENSE NO:	100-08864		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	5		
MATERIAL DESCRIPTION:	Air Vent Vibration Collar		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Building #1 - Closet		
MATERIAL QUANTITY:	10	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature: _____ Date: 03/09/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25302** BUILDING ID: **5821**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Seward School Branch** REVIEW DATE: **3/23/2016**
ADDRESS: **4541 South Wood Street** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **5**
MATERIAL DESCRIPTION: **Air Vent Vibration Collar**
MATERIAL LOCATION: **Building #1 - Closet**
MATERIAL QUANTITY: **10** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/23/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25302	BUILDING ID:	5821
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Robert DeBord		
SCHOOL NAME:	Seward School Branch	INSPECTION DATE:	3/9/2016		
ADDRESS:	4541 South Wood Street	IDPH LICENSE NO:	100-08864		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	8	
MATERIAL DESCRIPTION:	Hard Coat Plaster	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throughout Building #1

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 03/09/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25302** BUILDING ID: **5821**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Seward School Branch** REVIEW DATE: **3/23/2016**
ADDRESS: **4541 South Wood Street** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **8**
MATERIAL DESCRIPTION: **Hard Coat Plaster**
MATERIAL LOCATION: **Throughout Building #1**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **03/23/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25302	BUILDING ID:	5821
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Robert DeBord		
SCHOOL NAME:	Seward School Branch	INSPECTION DATE:	3/9/2016		
ADDRESS:	4541 South Wood Street	IDPH LICENSE NO:	100-08864		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	9	
MATERIAL DESCRIPTION:	Trowled-on Material	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throughout Building #1

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 03/09/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25302** BUILDING ID: **5821**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Seward School Branch** REVIEW DATE: **3/23/2016**
ADDRESS: **4541 South Wood Street** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **9**
MATERIAL DESCRIPTION: **Trowled-on Material**
MATERIAL LOCATION: **Throughout Building #1**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **03/23/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25302	BUILDING ID:	5821
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Robert DeBord		
SCHOOL NAME:	Seward School Branch	INSPECTION DATE:	3/9/2016		
ADDRESS:	4541 South Wood Street	IDPH LICENSE NO:	100-08864		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	A 2		
MATERIAL DESCRIPTION:	Aircell Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	7 Damaged or significantly damaged friable thermal system insulating ACBM		
HISTORICAL DAMAGE REASON:	Physical Damage		
HISTORICAL RESPONSE ACTION:	Remove		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Throughout Building #1**

MATERIAL QUANTITY: **700**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: **03/09/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25302** BUILDING ID: **5821**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Seward School Branch** REVIEW DATE: **3/23/2016**
ADDRESS: **4541 South Wood Street** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **A 2**
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**
MATERIAL LOCATION: **Throughout Building #1**
MATERIAL QUANTITY: **700** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Remove

Comments:

Management Planner's Signature: _____



Date: **03/23/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25302	BUILDING ID:	5821
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Robert DeBord		
SCHOOL NAME:	Seward School Branch	INSPECTION DATE:	3/9/2016		
ADDRESS:	4541 South Wood Street	IDPH LICENSE NO:	100-08864		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	B 2		
MATERIAL DESCRIPTION:	Hard Joint Compound on Aircell Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	7 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Throughout Building #1		
MATERIAL QUANTITY:	25	MATERIAL UNITS:	JOINTS
DAMAGE QUANTITY:		DAMAGE UNITS:	JOINTS
COMMENTS:			

Inspector's Signature: _____ Date: 03/09/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25302** BUILDING ID: **5821**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Seward School Branch** REVIEW DATE: **3/23/2016**
ADDRESS: **4541 South Wood Street** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **B 2**
MATERIAL DESCRIPTION: **Hard Joint Compound on Aircell Pipe Insulation**
MATERIAL LOCATION: **Throughout Building #1**
MATERIAL QUANTITY: **25** MATERIAL UNITS: **JOINTS**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **JOINTS**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/23/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25302	BUILDING ID:	5821
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Robert DeBord		
SCHOOL NAME:	Seward School Branch	INSPECTION DATE:	3/9/2016		
ADDRESS:	4541 South Wood Street	IDPH LICENSE NO:	100-08864		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	C 1		
MATERIAL DESCRIPTION:	Cardboard Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	7 ACBM with potential for significant damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout Building #1		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature: _____ Date: 03/09/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25302** BUILDING ID: **5821**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Seward School Branch** REVIEW DATE: **3/23/2016**
ADDRESS: **4541 South Wood Street** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **C 1**
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**
MATERIAL LOCATION: **Throughout Building #1**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/23/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25302	BUILDING ID:	5821
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Robert DeBord		
SCHOOL NAME:	Seward School Branch	INSPECTION DATE:	3/9/2016		
ADDRESS:	4541 South Wood Street	IDPH LICENSE NO:	100-08864		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	C1	
MATERIAL DESCRIPTION:	Cardboard Pipe Insulation	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1st Floor Down N/E Stairway

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Not observed 2016

Inspector's Signature: _____ Date: 03/09/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25302** BUILDING ID: **5821**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Seward School Branch** REVIEW DATE: **3/23/2016**
ADDRESS: **4541 South Wood Street** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **C1**
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**
MATERIAL LOCATION: **1st Floor Down N/E Stairway**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Not observed in 2016

Management Planner's Signature: _____



Date: **03/23/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25302	BUILDING ID:	5821
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Robert DeBord		
SCHOOL NAME:	Seward School Branch	INSPECTION DATE:	3/9/2016		
ADDRESS:	4541 South Wood Street	IDPH LICENSE NO:	100-08864		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	D 1	
MATERIAL DESCRIPTION:	Hard Joint Compound on Cardboard Pipe Insulation	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: Low

MATERIAL LOCATION: Building #1

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Not observed 2016

Inspector's Signature: _____ Date: 03/09/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25302** BUILDING ID: **5821**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Seward School Branch** REVIEW DATE: **3/23/2016**
ADDRESS: **4541 South Wood Street** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **D 1**
MATERIAL DESCRIPTION: **Hard Joint Compound on Cardboard Pipe Insulation**
MATERIAL LOCATION: **Building #1**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Material Not Observed in 2016

Management Planner's Signature: _____



Date: **03/23/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

APPENDIX B

Inspector and Management Planner Licenses

2015



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Robert DeBord


has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 12/2/2015


Exam Date: 12/2/2015

Expiration Date: 12/2/2016

Certificate Number: BIR1512024160


Kathy DeSalvo, Director

Robert De Bord
Illinois Licensed Asbestos Inspector, Project Manager, and
Air Sampling Professional



ENDORSEMENTS	TC EXPIRES
INSPECTOR	2/13/2016
PROJECT MANAGER	2/12/2016
AIR SAMPLING PROFESSIONAL	

Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois
Department of Public Health
This license is valid only when accompanied by a valid
training course certificate.

**CARNOW
CONIBEAR**

2015



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Todd Huffer

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 12/2/2015

Exam Date: 12/2/2015


Expiration Date: 12/2/2016

Certificate Number: BIR1512024161

Kathy DeSalvo, Director

Todd Huffer

Illinois Licensed Asbestos Inspector, Management Planner,
Project Manager, and Air Sampling Professional



ENDORSEMENTS	TC EXPIRES
INSPECTOR	12/2/2015
MANAGEMENT PLANNER	2/20/2016
PROJECT MANAGER	12/11/2015
AIR SAMPLING PROFESSIONAL	

Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois
Department of Public Health
This license is valid only when accompanied by a valid
training course certificate.

**CARNOW
CONIBEAR**

2016



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Todd Huffer

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Course Date: 1/27/2016

Exam Date: 1/27/2016

Expiration Date: 1/27/2017

Certificate Number: MPR1601270318

Kathy DeSalvo, Director

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL		
	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE		
	Loc	Localized
	Dist	Distributed