

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM**

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-2477
SCHOOL NAME: Swift School
ADDRESS OF SCHOOL: 5900 N Winthrop Avenue
CITY: Chicago, IL, 60660

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **3/27/2013**

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II (Please type or print)

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 6/21/2016 ENROLLMENT 695

IDPH INSPECTOR LICENSE NUMBER: 100-08023

IDPH LICENSED INSPECTOR NAME (Please Print): Tommy Thompson

IDPH MP LICENSE NUMBER: 100-07342

IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Jigar Shah

DESIGNATED PERSON (Please Print): Robert Christlieb PHONE: (773) 553-3197



6/21/2016

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Swift School

5900 N Winthrop Avenue
Chicago, IL, 60660

Unit: 25571
Building ID: 6130

IDPH ID Number: 14-016-2990-2477

REPORT DATE:

Tuesday, June 21, 2016

Prepared for:

Chicago Public Schools
125 S. Clark Street
Chicago, IL 60603

Prepared by:

GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone (312) 733-6262

Fax (312) 733-5612

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: March 15, 2016

RE: Swift School, Unit 25571
5900 N Winthrop Avenue
Chicago, IL, 60660

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2016 asbestos three year re-inspection has been completed at Swift School , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at Swift School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Robert Christlieb, the designated Local Education Authority's Designated Person at (773) 553-3197 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Swift School Unit: 25571 Region: 01
Address: 5900 N Winthrop Avenue Chicago, IL, 60660
IDPH ID: 14-016-2990-2477 Building ID: 6130
Contact: Liberty, Steve Phone: 312-804-4304

2. Description of Facility

Original Construction: 1914 Additional Construction: 1998
Total Square Footage: 66708 No of Floors: 3
Current Occupancy: 695

3. LEA Designated Person

Contact: Robert Christlieb Phone: (773) 553-3197
Address: 125 South Clark Street, 17th Floor
Chicago, IL 60603

4. Managing Environmental Consultant

MEC: GSG Consultants, Inc.
Contact: Arturo Saenz
Address 855 W. Adams St., Ste. 200
Phone: (312) 733-6262 Fax: (312) 733-5612

5. Inspector

Inspector Name: Tommy Thompson




Inspector IDPH license # 100-08023

Signature:
Date: 3/15/2016

6. Management Planner

Management Planner Name: Jigar Shah



Management Planner IDPH license # 100-07342

Signature:
Date: 05/19/2016

7. Review Date: 05/19/2016

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature: 

Date: 6/21/2016

Name: Robert Christlieb

II. EXECUTIVE SUMMARY

GSG Consultants, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Swift School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 6130:

25	Rust Linoleum Mastic
32	Vinyl Baseboard
D	MJP E/F/V on Mag Block Pipe Insulation

B. The following new homogenous areas have been identified for Building 6130:

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

09	Red Linoleum
10	Red Linoleum Mastic
11	Hard Coat Plaster
13	12"x12" White w/ Light Brown Spots VFT
14	12"x12" White w/ Light Brown Spots VFT Mastic
15	Carpet Mastic OBSERVED ONLY IN ROOM 104
16	12"x12" White w/ Light Brown Spots VFT
17	12"x12" White w/ Light Brown Spots VFT Mastic
18	12"x12" Red VFT
19	12"x12" Red VFT Mastic
20	12"x12" Green VFT
21	12"x12" Green VFT Mastic
22	12"x12" Rust VFT
23	12"x12" Rust VFT Mastic
24	Rust Linoleum
25	Rust Linoleum Mastic
26	Green Linoleum
27	Green Linoleum Mastic
28	Beige Linoleum
29	Beige Linoleum Mastic
30	2'x4' Smooth Ceiling Tile
31	2'x4' Dot Ceiling Tile
32	Vinyl Baseboard
33	Vinyl Baseboard Mastic
34	Drywall
35	Drywall Compound
36	Carpet Mastic
37	Spray-on Insulation
38	Terrazo
39	12"x12" Light blue with light blue specks VFT
39 A	12"x12" Light blue with light blue specks VFT (MASTIC)
40	12"x12" White with Blue specks VFT
40 A	12"x12" White with Blue specks VFT (MASTIC)
41	12"x12" Beige with White specks VFT
41 A	12"x12" Beige with White specks VFT (MASTIC)
42	12" x 12" BLUE, VFT
42A	12" X 12" blue, mastic
43	12" X 12" yellow, VFT
43A	12" X 12" yellow, Mastic
44	Carpet mastic
45	12" X 12" white with blue specks, VFT

45A	12" X 12" white with blue specks, Mastic
46	Fire Door
47	12" X 12" white with gray specks, VFT
47A	12" X 12" white with gray specks, Mastic
48	Carpet mastic
49	Drywall System
50	2'x4' Ceiling Tile
D	MJP E/F/V on Mag Block Pipe Insulation
G	MJP E/F/V on Fiberglass Pipe Insulation

The following areas were deemed to be inaccessible:

10	Red Linoleum Mastic
15	Carpet Mastic OBSERVED ONLY IN ROOM 104
36	Carpet Mastic
44	Carpet mastic
48	Carpet mastic

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Tommy Thompson, IDPH License # 100-08023. The Management Plan was updated by Jigar Shah, IDPH License # 100-07342. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Swift School Building 6130 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Swift School Unit 25571 Building ID 6130

Address 5900 N Winthrop Avenue Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
01	12"x12" Off White w/ Speckles VFT NOT OBSERVED	80	SF	Main Office - 1914 NOT OBSERVED	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
02	12"x12" Off White w/ Speckles VFT Mastic NOT OBSERVED	80	SF	Main Office - 1914 NOT OBSERVED	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
03	9"x9" Beige VFT	740	SF	Room 106 (under the carpet) and Storage Rm. Next to Rm. 106 - 1914	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
04	9"x9" Beige VFT Mastic	740	SF	Room 106 (under the carpet) and Storage Rm. Next to Rm.106 -1914	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
05	12"x12" White w/ Tan VFT	900	SF	Room 205 - 1914	CHR	MISC	N	NONE	20		No	ACBM with the potential for damage		LOW
06	12"x12" White w/ Tan VFT Mastic	900	SF	Room 205 - 1914	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
07	12"x12" Off White VFT	1,400	SF	Stage & Stage Storage's - 1914	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
08	12"x12" Off White VFT Mastic	1,400	SF	Stage & Stage Storage's - 1914	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
09	Red Linoleum	400	SF	Rooms 108 (Under HA 39) & 109 (Under HA41) - 1914	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
10	Red Linoleum Mastic	400	SF	Rooms 108 (Under HA 39) & 109 (Under HA 41) - 1914	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
11	Hard Coat Plaster	30,000	SF	Throughout - 1914	ASSUMED	SURFACE	N	NONE	0		No	ACBM with the potential for damage		LOW
12	2'x2' Transite Ceiling Panel	3,100	SF	Natorium (Pool), men's and women's bath/shower room - 1914	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
13	12"x12" White w/ Light Brown Spots VFT	120	SF	Rooms 201,301,101 (speech), 2nd & 3rd Floor Teacher Toilets - 1914	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
14	12"x12" White w/ Light Brown Spots VFT Mastic	120	SF	Rooms 201,301,101 (speech), 2nd & 3rd Floor Teacher Toilets - 1914	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
15	Carpet Mastic OBSERVED ONLY IN	600	SF	Rooms 101, 102,	ASSUMED	MISC	N	NONE	0		No	ACBM with the		LOW

Chicago Public Schools

School Swift School Unit 25571 Building ID 6130

Address 5900 N Winthrop Avenue Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
	ROOM 104			103, 104, 108, & 109 - 1914 OBSERVED ONLY IN ROOM 104								potential for damage		
16	12"x12" White w/ Light Brown Spots VFT	16,200	SF	Throughout - 1999 Addition	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
17	12"x12" White w/ Light Brown Spots VFT Mastic	16,200	SF	Throughout - 1999 Addition	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
18	12"x12" Red VFT	540	SF	Rooms 112, 113, 213, 311, & 314 - 1999 Addition	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
19	12"x12" Red VFT Mastic	540	SF	Rooms 112, 113, 213, 311, & 314 - 1999 Addition	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
20	12"x12" Green VFT	540	SF	Rooms 114, 215, 312, & 313 - 1999 Addition	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
21	12"x12" Green VFT Mastic	540	SF	Rooms 114, 215, 312, & 313 - 1999 Addition	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
22	12"x12" Rust VFT	540	SF	Rooms 111, 112, 217, 310, & 315 - 1999 Addition	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
23	12"x12" Rust VFT Mastic	540	SF	Rooms 111, 112, 217, 310, & 315 - 1999 Addition	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
24	Rust Linoleum	264	SF	Lunchroom, & Elevator - 1999 Addition	ASSUMED	MISC	N	NONE	40		No	ACBM with the potential for damage		LOW
25	Rust Linoleum Mastic	354	SF	Lunchroom, & Elevator - 1999 Addition	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		MODERATE
26	Green Linoleum	780	SF	Lunchroom, Serving Area, & Elevator - 1999 Addition	ASSUMED	MISC	N	NONE	40		No	ACBM with the potential for damage		LOW
27	Green Linoleum Mastic	780	SF	Lunchroom, Serving Area, & Elevator - 1999 Addition	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
28	Beige Linoleum	2,405	SF	Lunchroom, Serving Area, & Elevator - 1999 Addition	ASSUMED	MISC	N	NONE	40		No	ACBM with the potential for damage		LOW
29	Beige Linoleum Mastic	2,405	SF	Lunchroom, Serving Area, & Elevator - 1999 Addition	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Swift School Unit 25571 Building ID 6130

Address 5900 N Winthrop Avenue Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
30	2'x4' Smooth Ceiling Tile	10,000	SF	Throughout - 1999 Addition	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
31	2'x4' Dot Ceiling Tile	12,000	SF	Kitchen: (Toilet, Corridor, & Office), Serving Area, Food Storage, & Dishwash - 1999 Addition	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
32	Vinyl Baseboard	8,000	LF	Throughout - 1999 Addition	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		MODERATE
33	Vinyl Baseboard Mastic	8,000	LF	Throughout - 1999 Addition	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
34	Drywall	3,000	SF	Throughout - 1999 Addition	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
35	Drywall Compound	150	SF	Throughout - 1999 Addition	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
36	Carpet Mastic	700	SF	Library - 1999 Addition	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
37	Spray-on Insulation	7,000	SF	Throughout Above Drop Ceilings - 1999 Addition	ASSUMED	SURFACE	Y	NONE	0		No	ACBM with the potential for damage		LOW
38	Terrazo	7,000	SF	Throughout 1999 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
39	12"x12" Light blue with light blue specks VFT	80	SF	Main Office - 1914 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
39 A	12"x12" Light blue with light blue specks VFT (MASTIC)	80	SF	Main Office - 1914 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
40	12"x12" White with Blue specks VFT	200	SF	Room 108 - 1914 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
40 A	12"x12" White with Blue specks VFT (MASTIC)	200	SF	Room 108 - 1914 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
41	12"x12" Beige with White specks VFT	200	SF	Room 109 - 1914 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
41 A	12"x12" Beige with White specks VFT (MASTIC)	200	SF	Room 109 - 1914 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
42	12" x 12" BLUE, VFT	80	SF	1st and 2nd floor corridors	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
42A	12" X 12" blue, mastic	80	SF	1st and 2nd floor corridors	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
43	12" X 12" yellow, VFT	70	SF	1st and 2nd floor corridors	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
43A	12" X 12" yellow, Mastic	70	SF	1st and 2nd floor corridors	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
44	Carpet mastic	600	SF	Rm 104	ASSUMED	MISC	N	NONE	0			ACBM with the		LOW

Chicago Public Schools

School Swift School Unit 25571 Building ID 6130

Address 5900 N Winthrop Avenue Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				(Removed from Rms 101, 102, 103, 108, and 109)								potential for damage		
45	12" X 12" white with blue specks, VFT	6,000	SF	1st and 2nd floor corridors; Rm 108	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
45A	12" X 12" white with blue specks, Mastic	6,000	SF	1st and 2nd floor corridors; Rm 108	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
46	Fire Door	10	EA	Balcony	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
47	12" X 12" white with gray specks, VFT	320	SF	Assembly Hall	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
47A	12" X 12" white with gray specks, Mastic	320	SF	Assembly Hall	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
48	Carpet mastic	400	SF	Auditorium, between isles	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
49	Drywall System			1919 Building	ASSUMED	MISC	Y	UNKNOWN			No	ACBM with the potential for damage		MODERATE
50	2'x4' Ceiling Tile			1919 Building	ASSUMED	MISC	Y	UNKNOWN			No	ACBM with the potential for damage		MODERATE
A	Aircell Pipe Insulation	16	LF	Room 202 & 2nd Floor Corridor - 1914	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
B	MJP E/F/V on Aircell Pipe Insulation	4	LF	Room 202 & 2nd Floor Corridor - 1914	CHR	TSI	Y		0		No	ACBM with the potential for damage		LOW
C	Mag Block Pipe Insulation	168	LF	North & South Engine Rooms, Boiler Room, Natatorium, Natatorium Entry Hall - 1914	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		MODERATE
D	MJP E/F/V on Mag Block Pipe Insulation	50	LF	North & South Engine Rooms, Boiler Room, Natatorium, Natatorium Entry Hall - 1914	ASSUMED	TSI	Y	NONE	0		Yes	ACBM with the potential for damage		MODERATE
E	Cardboard Pipe Insulation	100	LF	Room 202 & 208, Room 202 & 208 Closets, 2nd Floor Corridor - 1914	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		MODERATE
F	MJP E/F/V on Cardboard Pipe Insulation	8	LF	Room 202 (old 208), Room 202 (old 208) Closet, 2nd Floor	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		MODERATE

Chicago Public Schools

School Swift School Unit 25571 Building ID 6130

Address 5900 N Winthrop Avenue Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Corridor - 1914										
G	MJP E/F/V on Fiberglass Pipe Insulation	90	LF	Throughout - 1914	ASSUMED	TSI	Y	NONE	0		No	ACBM with the potential for damage		MODERATE
H	Boiler Rope	50	LF	Boiler Room - 1914	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		MODERATE

Chicago Public Schools

School Swift School Unit 25571 Building ID 6130

Address 5900 N Winthrop Avenue Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

Inspector's Comments are Summarized at the End of the Report

Reinspection Date 3/15/2016
Inspector Name Tommy Thompson
100-08023 2/13/2017
Inspector's IDPH License Number / Expiration Date

Inspector's Comments

HA Number:	Inspector Comments:
01	
02	
03	
04	
05	
06	
07	
08	
09	
10	
11	
12	
13	
14	
15	
16	
17	
18	
19	
20	
21	
22	
23	
24	

Chicago Public Schools

School Swift School Unit 25571 Building ID 6130

Address 5900 N Winthrop Avenue Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
25	
26	
27	
28	
29	
30	
31	
32	
33	
34	
35	
36	
37	
38	
39	
39 A	
40	
40 A	
41	
41 A	
42	
42A	
43	
43A	
44	
45	
45A	
46	
47	

Chicago Public Schools

School Swift School Unit 25571 Building ID 6130

Address 5900 N Winthrop Avenue Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
47A	
48	
49	
50	
A	
B	
C	
D	
E	
F	
G	
H	

Table II

Management Planner's Review

Chicago Public Schools

School Swift School
Address 5900 N Winthrop Avenue

Unit 25571
Chicago, IL, 60660

Building ID 6130
Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
01	12"x12" Off White w/ Speckles VFT NOT OBSERVED	80	SF	Main Office - 1914 NOT OBSERVED	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	
02	12"x12" Off White w/ Speckles VFT Mastic NOT OBSERVED	80	SF	Main Office - 1914 NOT OBSERVED	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	
03	9"x9" Beige VFT	740	SF	Room 106 (under the carpet) and Storage Rm. Next to Rm. 106 - 1914	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
04	9"x9" Beige VFT Mastic	740	SF	Room 106 (under the carpet) and Storage Rm. Next to Rm.106 -1914	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
05	12"x12" White w/ Tan VFT	900	SF	Room 205 - 1914	Chrysotile	MISC	No	20	SF	6 ACBM with the potential for damage	Repair
06	12"x12" White w/ Tan VFT Mastic	900	SF	Room 205 - 1914	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
07	12"x12" Off White VFT	1,400	SF	Stage & Stage Storage's - 1914	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
08	12"x12" Off White VFT Mastic	1,400	SF	Stage & Stage Storage's - 1914	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
09	Red Linoleum	400	SF	Rooms 108 (Under HA 39) & 109 (Under HA41) - 1914	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
10	Red Linoleum Mastic	400	SF	Rooms 108 (Under HA 39) & 109 (Under HA 41) - 1914	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
11	Hard Coat Plaster	30,000	SF	Throughout - 1914	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
12	2'x2' Transite Ceiling Panel	3,100	SF	Natatorium (Pool), men's and women's bath/shower room - 1914	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
13	12"x12" White w/ Light Brown Spots VFT	120	SF	Rooms 201,301,101 (speech), 2nd & 3rd Floor Teacher Toliets - 1914	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
14	12"x12" White w/ Light Brown Spots VFT Mastic	120	SF	Rooms 201,301,101 (speech), 2nd & 3rd Floor Teacher Toliets - 1914	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
15	Carpet Mastic OBSERVED ONLY IN ROOM 104	600	SF	Rooms 101, 102, 103, 104, 108, & 109 - 1914 OBSERVED ONLY IN ROOM 104	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
16	12"x12" White w/ Light Brown Spots VFT	16,200	SF	Throughout - 1999 Addition	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
17	12"x12" White w/ Light Brown Spots VFT Mastic	16,200	SF	Throughout - 1999 Addition	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
18	12"x12" Red VFT	540	SF	Rooms 112, 113, 213, 311, & 314 - 1999 Addition	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
19	12"x12" Red VFT Mastic	540	SF	Rooms 112, 113, 213, 311, & 314 - 1999 Addition	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
20	12"x12" Green VFT	540	SF	Rooms 114, 215, 312, & 313 - 1999 Addition	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
21	12"x12" Green VFT Mastic	540	SF	Rooms 114, 215, 312, & 313 - 1999	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Swift School
Address 5900 N Winthrop Avenue

Unit 25571
Chicago, IL, 60660

Building ID 6130
Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				Addition							
22	12"x12" Rust VFT	540	SF	Rooms 111, 112, 217, 310, & 315 - 1999 Addition	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
23	12"x12" Rust VFT Mastic	540	SF	Rooms 111, 112, 217, 310, & 315 - 1999 Addition	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
24	Rust Linoleum	264	SF	Lunchroom, & Elevator - 1999 Addition	Assumed	MISC	No	40	SF	6 ACBM with the potential for damage	Repair
25	Rust Linoleum Mastic	354	SF	Lunchroom, & Elevator - 1999 Addition	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
26	Green Linoleum	780	SF	Lunchroom, Serving Area, & Elevator - 1999 Addition	Assumed	MISC	No	40	SF	6 ACBM with the potential for damage	Repair
27	Green Linoleum Mastic	780	SF	Lunchroom, Serving Area, & Elevator - 1999 Addition	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
28	Beige Linoleum	2,405	SF	Lunchroom, Serving Area, & Elevator - 1999 Addition	Assumed	MISC	No	40	SF	6 ACBM with the potential for damage	Repair
29	Beige Linoleum Mastic	2,405	SF	Lunchroom, Serving Area, & Elevator - 1999 Addition	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
30	2'x4' Smooth Ceiling Tile	10,000	SF	Throughout - 1999 Addition	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
31	2'x4' Dot Ceiling Tile	12,000	SF	Kitchen: (Toliet, Corridor, & Office), Serving Area, Food Storage, & Dishwash - 1999 Addition	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
32	Vinyl Baseboard	8,000	LF	Throughout - 1999 Addition	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
33	Vinyl Baseboard Mastic	8,000	LF	Throughout - 1999 Addition	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
34	Drywall	3,000	SF	Throughout - 1999 Addition	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
35	Drywall Compound	150	SF	Throughout - 1999 Addition	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
36	Carpet Mastic	700	SF	Library - 1999 Addition	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
37	Spray-on Insulation	7,000	SF	Throughout Above Drop Ceilings - 1999 Addition	Assumed	SURFACE	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
38	Terrazo	7,000	SF	Throughout 1999 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
39	12"x12" Light blue with light blue specks VFT	80	SF	Main Office - 1914 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
39 A	12"x12" Light blue with light blue specks VFT (MASTIC)	80	SF	Main Office - 1914 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
40	12"x12" White with Blue specks VFT	200	SF	Room 108 - 1914 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
40 A	12"x12" White with Blue specks VFT (MASTIC)	200	SF	Room 108 - 1914 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
41	12"x12" Beige with White specks VFT	200	SF	Room 109 - 1914 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
41 A	12"x12" Beige with White specks VFT (MASTIC)	200	SF	Room 109 - 1914 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
42	12" x 12" BLUE, VFT	80	SF	1st and 2nd floor corridors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Swift School
Address 5900 N Winthrop Avenue

Unit 25571
Chicago, IL, 60660

Building ID 6130
Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
42A	12" X 12" blue, mastic	80	SF	1st and 2nd floor corridors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
43	12" X 12" yellow, VFT	70	SF	1st and 2nd floor corridors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
43A	12" X 12" yellow, Mastic	70	SF	1st and 2nd floor corridors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
44	Carpet mastic	600	SF	Rm 104 (Removed from Rms 101, 102, 103, 108, and 109)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
45	12" X 12" white with blue specks, VFT	6,000	SF	1st and 2nd floor corridors; Rm 108	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
45A	12" X 12" white with blue specks, Mastic	6,000	SF	1st and 2nd floor corridors; Rm 108	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
46	Fire Door	10	EA	Balcony	Assumed	MISC	No	0	EA	6 ACBM with the potential for damage	Follow O&M Plan
47	12" X 12" white with gray specks, VFT	320	SF	Assembly Hall	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
47A	12" X 12" white with gray specks, Mastic	320	SF	Assembly Hall	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
48	Carpet mastic	400	SF	Auditorium, between isles	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
49	Drywall System			1919 Building	Assumed	MISC	Yes			6 ACBM with the potential for damage	
50	2'x4' Ceiling Tile			1919 Building	Assumed	MISC	Yes			6 ACBM with the potential for damage	
A	Aircell Pipe Insulation	16	LF	Room 202 & 2nd Floor Corridor - 1914	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
B	MJP E/F/V on Aircell Pipe Insulation	4	LF	Room 202 & 2nd Floor Corridor - 1914	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
C	Mag Block Pipe Insulation	168	LF	North & South Engine Rooms, Boiler Room, Natatorium, Natatorium Entry Hall - 1914	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
D	MJP E/F/V on Mag Block Pipe Insulation	50	LF	North & South Engine Rooms, Boiler Room, Natatorium, Natatorium Entry Hall - 1914	Assumed	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
E	Cardboard Pipe Insulation	100	LF	Room 202 & 208, Room 202 & 208 Closets, 2nd Floor Corridor - 1914	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
F	MJP E/F/V on Cardboard Pipe Insulation	8	LF	Room 202 (old 208), Room 202 (old 208) Closet, 2nd Floor Corridor - 1914	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
G	MJP E/F/V on Fiberglass Pipe Insulation	90	LF	Throughout - 1914	Assumed	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
H	Boiler Rope	50	LF	Boiler Room - 1914	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Swift School
Address 5900 N Winthrop Avenue

Unit 25571
 Chicago, IL, 60660

Building ID 6130
Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG Consultants, Inc.
 855 W. Adams St., Ste. 200
 Phone: (312) 733-6262

Fax: (312) 733-5612

Management Planner's Comments Summarized at the End of the Report

Review Date	5/19/2016
Manager Planner Name	Jigar Shah
100-07342	1/19/2017
Manager IDPH License No/Expiration	

HA Number	Management Comments
01	
02	
03	
04	
05	Repair Damaged ACM, Follow O & M
06	
07	
08	
09	
10	
11	

Chicago Public Schools

School Swift School
Address 5900 N Winthrop Avenue

Unit 25571
 Chicago, IL, 60660

Building ID 6130
Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
12	
13	
14	
15	
16	
17	
18	
19	
20	
21	
22	
23	
24	Repair Damaged ACM, Follow o & M
25	
26	Repair Damaged ACM, Follow O & M
27	
28	Repair Damaged ACM and Follow O & M
29	
30	
31	
32	
33	
34	
35	
36	
37	
38	

Chicago Public Schools

School Swift School
Address 5900 N Winthrop Avenue

Unit 25571
Chicago, IL, 60660

Building ID 6130
Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
39	
39 A	
40	
40 A	
41	
41 A	
42	
42A	
43	
43A	
44	
45	
45A	
46	
47	
47A	
48	
49	
50	
A	
B	
C	
D	
E	
F	
G	
H	

Chicago Public Schools

School Swift School
Address 5900 N Winthrop Avenue

Unit 25571
Chicago, IL, 60660

Building ID 6130
Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

Management Planner's Comments Summarized at the End of the Report

Chicago Public Schools

GSG Consultants, Inc.

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUIDLING ID: **6130**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Swift School** INSPECTION DATE: **3/15/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **01**
MATERIAL DESCRIPTION: **12"x12" Off White w/ Speckles VFT NOT OBSERVED**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Main Office - 1914**

NOT OBSERVED

MATERIAL QUANTITY: **80**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/15/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUILDING ID: **6130**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Swift School** REVIEW DATE: **5/19/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **01**
MATERIAL DESCRIPTION: **12"x12" Off White w/ Speckles VFT NOT OBSERVED**
MATERIAL LOCATION: **Main Office - 1914**
NOT OBSERVED
MATERIAL QUANTITY: **80** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **05/19/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUILDING ID: **6130**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Swift School** INSPECTION DATE: **3/15/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **02**
MATERIAL DESCRIPTION: **12"x12" Off White w/ Speckles VFT Mastic NOT OBSERVED**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Main Office - 1914
NOT OBSERVED**

MATERIAL QUANTITY: **80**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/15/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUILDING ID: **6130**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Swift School** REVIEW DATE: **5/19/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **02**
MATERIAL DESCRIPTION: **12"x12" Off White w/ Speckles VFT Mastic NOT OBSERVED**
MATERIAL LOCATION: **Main Office - 1914 NOT OBSERVED**
MATERIAL QUANTITY: **80** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **05/19/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUIDLING ID: **6130**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Swift School** INSPECTION DATE: **3/15/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **03**
MATERIAL DESCRIPTION: **9"x9" Beige VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 106 (under the carpet) and Storage Rm. Next to Rm. 106 - 1914**
MATERIAL QUANTITY: **740** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/15/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUILDING ID: **6130**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Swift School** REVIEW DATE: **5/19/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **03**
MATERIAL DESCRIPTION: **9"x9" Beige VFT**
MATERIAL LOCATION: **Room 106 (under the carpet) and Storage Rm. Next to Rm. 106 - 1914**
MATERIAL QUANTITY: **740** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **05/19/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUIDLING ID: **6130**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Swift School** INSPECTION DATE: **3/15/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **04**
MATERIAL DESCRIPTION: **9"x9" Beige VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 106 (under the carpet) and Storage Rm. Next to Rm.106 -1914**
MATERIAL QUANTITY: **740** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/15/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUILDING ID: **6130**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Swift School** REVIEW DATE: **5/19/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **04**
MATERIAL DESCRIPTION: **9"x9" Beige VFT Mastic**
MATERIAL LOCATION: **Room 106 (under the carpet) and Storage Rm. Next to Rm.106 -1914**
MATERIAL QUANTITY: **740** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **05/19/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUIDLING ID: **6130**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Swift School** INSPECTION DATE: **3/15/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **05**
MATERIAL DESCRIPTION: **12"x12" White w/ Tan VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 205 - 1914**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/15/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUIDLING ID: **6130**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Swift School** REVIEW DATE: **5/19/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **05**
MATERIAL DESCRIPTION: **12"x12" White w/ Tan VFT**
MATERIAL LOCATION: **Room 205 - 1914**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **20** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Repair Damaged ACM, Follow O & M

Management Planner's Signature: _____



Date: **05/19/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUIDLING ID: **6130**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Swift School** INSPECTION DATE: **3/15/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **06**
MATERIAL DESCRIPTION: **12"x12" White w/ Tan VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 205 - 1914**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/15/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUIDLING ID: **6130**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Swift School** REVIEW DATE: **5/19/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **06**
MATERIAL DESCRIPTION: **12"x12" White w/ Tan VFT Mastic**
MATERIAL LOCATION: **Room 205 - 1914**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/19/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUIDLING ID: **6130**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Swift School** INSPECTION DATE: **3/15/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **07**
MATERIAL DESCRIPTION: **12"x12" Off White VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Stage & Stage Storage's - 1914**
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/15/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUILDING ID: **6130**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Swift School** REVIEW DATE: **5/19/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **07**
MATERIAL DESCRIPTION: **12"x12" Off White VFT**
MATERIAL LOCATION: **Stage & Stage Storage's - 1914**
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/19/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUIDLING ID: **6130**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Swift School** INSPECTION DATE: **3/15/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **08**
MATERIAL DESCRIPTION: **12"x12" Off White VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Stage & Stage Storage's - 1914**
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/15/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUIDLING ID: **6130**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Swift School** REVIEW DATE: **5/19/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **08**
MATERIAL DESCRIPTION: **12"x12" Off White VFT Mastic**
MATERIAL LOCATION: **Stage & Stage Storage's - 1914**
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/19/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUIDLING ID: **6130**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Swift School** INSPECTION DATE: **3/15/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **09**
MATERIAL DESCRIPTION: **Red Linoleum**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 108 (Under HA 39) & 109 (Under HA41) - 1914**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/15/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUILDING ID: **6130**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Swift School** REVIEW DATE: **5/19/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **09**
MATERIAL DESCRIPTION: **Red Linoleum**
MATERIAL LOCATION: **Rooms 108 (Under HA 39) & 109 (Under HA41) - 1914**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/19/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUIDLING ID: **6130**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Swift School** INSPECTION DATE: **3/15/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10**
MATERIAL DESCRIPTION: **Red Linoleum Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 108 (Under HA 39) & 109 (Under HA 41) - 1914**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/15/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUIDLING ID: **6130**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Swift School** REVIEW DATE: **5/19/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **10**
MATERIAL DESCRIPTION: **Red Linoleum Mastic**
MATERIAL LOCATION: **Rooms 108 (Under HA 39) & 109 (Under HA 41) - 1914**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/19/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUIDLING ID: **6130**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Swift School** INSPECTION DATE: **3/15/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11**
MATERIAL DESCRIPTION: **Hard Coat Plaster**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout - 1914**
MATERIAL QUANTITY: **30000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/15/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUIDLING ID: **6130**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Swift School** REVIEW DATE: **5/19/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **11**
MATERIAL DESCRIPTION: **Hard Coat Plaster**
MATERIAL LOCATION: **Throughout - 1914**
MATERIAL QUANTITY: **30000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **05/19/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUIDLING ID: **6130**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Swift School** INSPECTION DATE: **3/15/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12**
MATERIAL DESCRIPTION: **2'x2' Transite Ceiling Panel**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Natorium (Pool), men's and women's bath/shower room - 1914**
MATERIAL QUANTITY: **3100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/15/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUIDLING ID: **6130**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Swift School** REVIEW DATE: **5/19/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **12**
MATERIAL DESCRIPTION: **2'x2' Transite Ceiling Panel**
MATERIAL LOCATION: **Natatorium (Pool), men's and women's bath/shower room - 1914**
MATERIAL QUANTITY: **3100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/19/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUIDLING ID: **6130**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Swift School** INSPECTION DATE: **3/15/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13**
MATERIAL DESCRIPTION: **12"x12" White w/ Light Brown Spots VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 201,301,101 (speech), 2nd & 3rd Floor Teacher Toilets - 1914**
MATERIAL QUANTITY: **120** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/15/2016

Chicago Public Schools

GSG Consultants, Inc.

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUIDLING ID: **6130**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Swift School** REVIEW DATE: **5/19/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **13**
MATERIAL DESCRIPTION: **12"x12" White w/ Light Brown Spots VFT**
MATERIAL LOCATION: **Rooms 201,301,101 (speech), 2nd & 3rd Floor Teacher Toilets - 1914**
MATERIAL QUANTITY: **120** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/19/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUIDLING ID: **6130**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Swift School** INSPECTION DATE: **3/15/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14**
MATERIAL DESCRIPTION: **12"x12" White w/ Light Brown Spots VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 201,301,101 (speech), 2nd & 3rd Floor Teacher Toilets - 1914**
MATERIAL QUANTITY: **120** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/15/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUIDLING ID: **6130**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Swift School** REVIEW DATE: **5/19/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **14**
MATERIAL DESCRIPTION: **12"x12" White w/ Light Brown Spots VFT Mastic**
MATERIAL LOCATION: **Rooms 201,301,101 (speech), 2nd & 3rd Floor Teacher Toilets - 1914**
MATERIAL QUANTITY: **120** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/19/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUIDLING ID: **6130**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Swift School** INSPECTION DATE: **3/15/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15**
MATERIAL DESCRIPTION: **Carpet Mastic OBSERVED ONLY IN ROOM 104**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 101, 102, 103, 104, 108, & 109 - 1914
OBSERVED ONLY IN ROOM 104**

MATERIAL QUANTITY: **600**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/15/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUILDING ID: **6130**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Swift School** REVIEW DATE: **5/19/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **15**
MATERIAL DESCRIPTION: **Carpet Mastic OBSERVED ONLY IN ROOM 104**
MATERIAL LOCATION: **Rooms 101, 102, 103, 104, 108, & 109 - 1914
OBSERVED ONLY IN ROOM 104**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **05/19/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUIDLING ID: **6130**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Swift School** INSPECTION DATE: **3/15/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16**
MATERIAL DESCRIPTION: **12"x12" White w/ Light Brown Spots VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout - 1999 Addition**
MATERIAL QUANTITY: **16200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/15/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUILDING ID: **6130**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Swift School** REVIEW DATE: **5/19/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **16**
MATERIAL DESCRIPTION: **12"x12" White w/ Light Brown Spots VFT**
MATERIAL LOCATION: **Throughout - 1999 Addition**
MATERIAL QUANTITY: **16200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **05/19/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUIDLING ID: **6130**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Swift School** INSPECTION DATE: **3/15/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17**
MATERIAL DESCRIPTION: **12"x12" White w/ Light Brown Spots VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout - 1999 Addition**
MATERIAL QUANTITY: **16200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/15/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUILDING ID: **6130**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Swift School** REVIEW DATE: **5/19/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **17**
MATERIAL DESCRIPTION: **12"x12" White w/ Light Brown Spots VFT Mastic**
MATERIAL LOCATION: **Throughout - 1999 Addition**
MATERIAL QUANTITY: **16200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **05/19/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUIDLING ID: **6130**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Swift School** INSPECTION DATE: **3/15/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18**
MATERIAL DESCRIPTION: **12"x12" Red VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 112, 113, 213, 311, & 314 - 1999 Addition**
MATERIAL QUANTITY: **540** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/15/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUIDLING ID: **6130**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Swift School** REVIEW DATE: **5/19/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **18**
MATERIAL DESCRIPTION: **12"x12" Red VFT**
MATERIAL LOCATION: **Rooms 112, 113, 213, 311, & 314 - 1999 Addition**
MATERIAL QUANTITY: **540** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/19/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUIDLING ID: **6130**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Swift School** INSPECTION DATE: **3/15/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19**
MATERIAL DESCRIPTION: **12"x12" Red VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 112, 113, 213, 311, & 314 - 1999 Addition**
MATERIAL QUANTITY: **540** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/15/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUIDLING ID: **6130**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Swift School** REVIEW DATE: **5/19/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **19**
MATERIAL DESCRIPTION: **12"x12" Red VFT Mastic**
MATERIAL LOCATION: **Rooms 112, 113, 213, 311, & 314 - 1999 Addition**
MATERIAL QUANTITY: **540** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/19/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUIDLING ID: **6130**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Swift School** INSPECTION DATE: **3/15/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**
MATERIAL DESCRIPTION: **12"x12" Green VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 114, 215, 312, & 313 - 1999 Addition**
MATERIAL QUANTITY: **540** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/15/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUIDLING ID: **6130**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Swift School** REVIEW DATE: **5/19/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **20**
MATERIAL DESCRIPTION: **12"x12" Green VFT**
MATERIAL LOCATION: **Rooms 114, 215, 312, & 313 - 1999 Addition**
MATERIAL QUANTITY: **540** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/19/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUIDLING ID: **6130**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Swift School** INSPECTION DATE: **3/15/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21**
MATERIAL DESCRIPTION: **12"x12" Green VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 114, 215, 312, & 313 - 1999 Addition**
MATERIAL QUANTITY: **540** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/15/2016

Chicago Public Schools

GSG Consultants, Inc.

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUIDLING ID: **6130**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Swift School** REVIEW DATE: **5/19/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **21**
MATERIAL DESCRIPTION: **12"x12" Green VFT Mastic**
MATERIAL LOCATION: **Rooms 114, 215, 312, & 313 - 1999 Addition**
MATERIAL QUANTITY: **540** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **05/19/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUIDLING ID: **6130**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Swift School** INSPECTION DATE: **3/15/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22**
MATERIAL DESCRIPTION: **12"x12" Rust VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 111, 112, 217, 310, & 315 - 1999 Addition**
MATERIAL QUANTITY: **540** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/15/2016

Chicago Public Schools

GSG Consultants, Inc.

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUIDLING ID: **6130**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Swift School** REVIEW DATE: **5/19/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **22**
MATERIAL DESCRIPTION: **12"x12" Rust VFT**
MATERIAL LOCATION: **Rooms 111, 112, 217, 310, & 315 - 1999 Addition**
MATERIAL QUANTITY: **540** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/19/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUIDLING ID: **6130**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Swift School** INSPECTION DATE: **3/15/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23**
MATERIAL DESCRIPTION: **12"x12" Rust VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 111, 112, 217, 310, & 315 - 1999 Addition**
MATERIAL QUANTITY: **540** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/15/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUIDLING ID: **6130**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Swift School** REVIEW DATE: **5/19/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **23**
MATERIAL DESCRIPTION: **12"x12" Rust VFT Mastic**
MATERIAL LOCATION: **Rooms 111, 112, 217, 310, & 315 - 1999 Addition**
MATERIAL QUANTITY: **540** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **05/19/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUIDLING ID: **6130**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Swift School** INSPECTION DATE: **3/15/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **24**
MATERIAL DESCRIPTION: **Rust Linoleum**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Lunchroom, & Elevator - 1999 Addition**
MATERIAL QUANTITY: **264** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/15/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUILDING ID: **6130**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Swift School** REVIEW DATE: **5/19/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **24**
MATERIAL DESCRIPTION: **Rust Linoleum**
MATERIAL LOCATION: **Lunchroom, & Elevator - 1999 Addition**
MATERIAL QUANTITY: **264** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **40** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Repair Damaged ACM, Follow o & M

Management Planner's Signature: _____



Date: 05/19/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUIDLING ID: **6130**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Swift School** INSPECTION DATE: **3/15/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25**
MATERIAL DESCRIPTION: **Rust Linoleum Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Lunchroom, & Elevator - 1999 Addition**
MATERIAL QUANTITY: **354** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 03/15/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUIDLING ID: **6130**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Swift School** REVIEW DATE: **5/19/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **25**
MATERIAL DESCRIPTION: **Rust Linoleum Mastic**
MATERIAL LOCATION: **Lunchroom, & Elevator - 1999 Addition**
MATERIAL QUANTITY: **354** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/19/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUIDLING ID: **6130**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Swift School** INSPECTION DATE: **3/15/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26**
MATERIAL DESCRIPTION: **Green Linoleum**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Lunchroom, Serving Area, & Elevator - 1999 Addition**
MATERIAL QUANTITY: **780** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/15/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUILDING ID: **6130**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Swift School** REVIEW DATE: **5/19/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **26**
MATERIAL DESCRIPTION: **Green Linoleum**
MATERIAL LOCATION: **Lunchroom, Serving Area, & Elevator - 1999 Addition**
MATERIAL QUANTITY: **780** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **40** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Repair Damaged ACM, Follow O & M

Management Planner's Signature: _____



Date: 05/19/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUIDLING ID: **6130**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Swift School** INSPECTION DATE: **3/15/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27**
MATERIAL DESCRIPTION: **Green Linoleum Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Lunchroom, Serving Area, & Elevator - 1999 Addition**
MATERIAL QUANTITY: **780** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/15/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUILDING ID: **6130**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Swift School** REVIEW DATE: **5/19/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **27**
MATERIAL DESCRIPTION: **Green Linoleum Mastic**
MATERIAL LOCATION: **Lunchroom, Serving Area, & Elevator - 1999 Addition**
MATERIAL QUANTITY: **780** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/19/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUIDLING ID: **6130**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Swift School** INSPECTION DATE: **3/15/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28**
MATERIAL DESCRIPTION: **Beige Linoleum**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Lunchroom, Serving Area, & Elevator - 1999 Addition**
MATERIAL QUANTITY: **2405** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/15/2016

Chicago Public Schools

GSG Consultants, Inc.

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUIDLING ID: **6130**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Swift School** REVIEW DATE: **5/19/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **28**
MATERIAL DESCRIPTION: **Beige Linoleum**
MATERIAL LOCATION: **Lunchroom, Serving Area, & Elevator - 1999 Addition**
MATERIAL QUANTITY: **2405** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **40** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Repair Damaged ACM and Follow O & M

Management Planner's Signature: _____



Date: **05/19/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUIDLING ID: **6130**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Swift School** INSPECTION DATE: **3/15/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **29**
MATERIAL DESCRIPTION: **Beige Linoleum Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Lunchroom, Serving Area, & Elevator - 1999 Addition**
MATERIAL QUANTITY: **2405** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/15/2016

Chicago Public Schools

GSG Consultants, Inc.

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUILDING ID: **6130**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Swift School** REVIEW DATE: **5/19/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **29**
MATERIAL DESCRIPTION: **Beige Linoleum Mastic**
MATERIAL LOCATION: **Lunchroom, Serving Area, & Elevator - 1999 Addition**
MATERIAL QUANTITY: **2405** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/19/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUIDLING ID: **6130**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Swift School** INSPECTION DATE: **3/15/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **30**
MATERIAL DESCRIPTION: **2'x4' Smooth Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout - 1999 Addition**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/15/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUIDLING ID: **6130**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Swift School** REVIEW DATE: **5/19/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **30**
MATERIAL DESCRIPTION: **2'x4' Smooth Ceiling Tile**
MATERIAL LOCATION: **Throughout - 1999 Addtion**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/19/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUIDLING ID: **6130**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Swift School** INSPECTION DATE: **3/15/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **31**
MATERIAL DESCRIPTION: **2'x4' Dot Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Kitchen: (Toliet, Corridor, & Office), Serving Area, Food Storage, & Dishwash - 1999 Addition**

MATERIAL QUANTITY: **12000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/15/2016

Chicago Public Schools

GSG Consultants, Inc.

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUIDLING ID: **6130**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Swift School** REVIEW DATE: **5/19/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **31**
MATERIAL DESCRIPTION: **2'x4' Dot Ceiling Tile**
MATERIAL LOCATION: **Kitchen: (Toilet, Corridor, & Office), Serving Area, Food Storage, & Dishwash - 1999 Addition**
MATERIAL QUANTITY: **12000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/19/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUIDLING ID: **6130**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Swift School** INSPECTION DATE: **3/15/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **32**
MATERIAL DESCRIPTION: **Vinyl Baseboard**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Throughout - 1999 Addition**
MATERIAL QUANTITY: **8000** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**
COMMENTS:

Inspector's Signature: _____



Date: 03/15/2016

Chicago Public Schools

GSG Consultants, Inc.

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUIDLING ID: **6130**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Swift School** REVIEW DATE: **5/19/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **32**
MATERIAL DESCRIPTION: **Vinyl Baseboard**
MATERIAL LOCATION: **Throughout - 1999 Addition**
MATERIAL QUANTITY: **8000** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/19/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUIDLING ID: **6130**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Swift School** INSPECTION DATE: **3/15/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **33**
MATERIAL DESCRIPTION: **Vinyl Baseboard Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout - 1999 Addition**
MATERIAL QUANTITY: **8000** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____



Date: 03/15/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUIDLING ID: **6130**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Swift School** REVIEW DATE: **5/19/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **33**
MATERIAL DESCRIPTION: **Vinyl Baseboard Mastic**
MATERIAL LOCATION: **Throughout - 1999 Addition**
MATERIAL QUANTITY: **8000** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **05/19/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUIDLING ID: **6130**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Swift School** INSPECTION DATE: **3/15/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **34**
MATERIAL DESCRIPTION: **Drywall**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout - 1999 Addition**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/15/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUIDLING ID: **6130**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Swift School** REVIEW DATE: **5/19/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **34**
MATERIAL DESCRIPTION: **Drywall**
MATERIAL LOCATION: **Throughout - 1999 Addition**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **05/19/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUIDLING ID: **6130**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Swift School** INSPECTION DATE: **3/15/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **35**
MATERIAL DESCRIPTION: **Drywall Compound**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout - 1999 Addition**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/15/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUIDLING ID: **6130**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Swift School** REVIEW DATE: **5/19/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **35**
MATERIAL DESCRIPTION: **Drywall Compound**
MATERIAL LOCATION: **Throughout - 1999 Addition**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/19/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUIDLING ID: **6130**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Swift School** INSPECTION DATE: **3/15/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **36**
MATERIAL DESCRIPTION: **Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Library - 1999 Addition**
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/15/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUILDING ID: **6130**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Swift School** REVIEW DATE: **5/19/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **36**
MATERIAL DESCRIPTION: **Carpet Mastic**
MATERIAL LOCATION: **Library - 1999 Addition**
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/19/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUIDLING ID: **6130**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Swift School** INSPECTION DATE: **3/15/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37**
MATERIAL DESCRIPTION: **Spray-on Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout Above Drop Ceilings - 1999 Addition**
MATERIAL QUANTITY: **7000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/15/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUIDLING ID: **6130**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Swift School** REVIEW DATE: **5/19/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **37**
MATERIAL DESCRIPTION: **Spray-on Insulation**
MATERIAL LOCATION: **Throughout Above Drop Ceilings - 1999 Addition**
MATERIAL QUANTITY: **7000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **05/19/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUIDLING ID: **6130**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Swift School** INSPECTION DATE: **3/15/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **38**
MATERIAL DESCRIPTION: **Terrazo**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout 1999 Building**
MATERIAL QUANTITY: **7000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/15/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUILDING ID: **6130**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Swift School** REVIEW DATE: **5/19/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **38**
MATERIAL DESCRIPTION: **Terrazo**
MATERIAL LOCATION: **Throughout 1999 Building**
MATERIAL QUANTITY: **7000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/19/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUIDLING ID: **6130**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Swift School** INSPECTION DATE: **3/15/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **39**
MATERIAL DESCRIPTION: **12"x12" Light blue with light blue specks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Main Office - 1914 Bldg.**
MATERIAL QUANTITY: **80** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/15/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUILDING ID: **6130**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Swift School** REVIEW DATE: **5/19/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **39**
MATERIAL DESCRIPTION: **12"x12" Light blue with light blue specks VFT**
MATERIAL LOCATION: **Main Office - 1914 Bldg.**
MATERIAL QUANTITY: **80** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/19/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUIDLING ID: **6130**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Swift School** INSPECTION DATE: **3/15/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **39 A**
MATERIAL DESCRIPTION: **12"x12" Light blue with light blue specks VFT (MASTIC)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Main Office - 1914 Bldg.**
MATERIAL QUANTITY: **80** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/15/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUIDLING ID: **6130**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Swift School** REVIEW DATE: **5/19/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **39 A**
MATERIAL DESCRIPTION: **12"x12" Light blue with light blue specks VFT (MASTIC)**
MATERIAL LOCATION: **Main Office - 1914 Bldg.**
MATERIAL QUANTITY: **80** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **05/19/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUIDLING ID: **6130**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Swift School** INSPECTION DATE: **3/15/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **40**
MATERIAL DESCRIPTION: **12"x12" White with Blue specks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 108 - 1914 Bldg**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/15/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUILDING ID: **6130**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Swift School** REVIEW DATE: **5/19/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **40**
MATERIAL DESCRIPTION: **12"x12" White with Blue specks VFT**
MATERIAL LOCATION: **Room 108 - 1914 Bldg**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/19/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUIDLING ID: **6130**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Swift School** INSPECTION DATE: **3/15/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **40 A**
MATERIAL DESCRIPTION: **12"x12" White with Blue specks VFT (MASTIC)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Room 108 - 1914 Bldg.**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/15/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUIDLING ID: **6130**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Swift School** REVIEW DATE: **5/19/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **40 A**
MATERIAL DESCRIPTION: **12"x12" White with Blue specks VFT (MASTIC)**
MATERIAL LOCATION: **Room 108 - 1914 Bldg.**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/19/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUIDLING ID: **6130**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Swift School** INSPECTION DATE: **3/15/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **41**
MATERIAL DESCRIPTION: **12"x12" Beige with White specks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 109 - 1914 Bldg.**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/15/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUIDLING ID: **6130**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Swift School** REVIEW DATE: **5/19/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **41**
MATERIAL DESCRIPTION: **12"x12" Beige with White specks VFT**
MATERIAL LOCATION: **Room 109 - 1914 Bldg.**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/19/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUIDLING ID: **6130**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Swift School** INSPECTION DATE: **3/15/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **41 A**
MATERIAL DESCRIPTION: **12"x12" Beige with White specks VFT (MASTIC)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 109 - 1914 Bldg.**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/15/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUILDING ID: **6130**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Swift School** REVIEW DATE: **5/19/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **41 A**
MATERIAL DESCRIPTION: **12"x12" Beige with White specks VFT (MASTIC)**
MATERIAL LOCATION: **Room 109 - 1914 Bldg.**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/19/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUIDLING ID: **6130**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Swift School** INSPECTION DATE: **3/15/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **42**
MATERIAL DESCRIPTION: **12" x 12" BLUE, VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st and 2nd floor corridors**
MATERIAL QUANTITY: **80** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/15/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUIDLING ID: **6130**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Swift School** REVIEW DATE: **5/19/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **42**
MATERIAL DESCRIPTION: **12" x 12" BLUE, VFT**
MATERIAL LOCATION: **1st and 2nd floor corridors**
MATERIAL QUANTITY: **80** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/19/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUIDLING ID: **6130**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Swift School** INSPECTION DATE: **3/15/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **42A**
MATERIAL DESCRIPTION: **12" X 12" blue, mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st and 2nd floor corridors**
MATERIAL QUANTITY: **80** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/15/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUIDLING ID: **6130**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Swift School** REVIEW DATE: **5/19/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **42A**
MATERIAL DESCRIPTION: **12" X 12" blue, mastic**
MATERIAL LOCATION: **1st and 2nd floor corridors**
MATERIAL QUANTITY: **80** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/19/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUIDLING ID: **6130**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Swift School** INSPECTION DATE: **3/15/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **43**
MATERIAL DESCRIPTION: **12" X 12" yellow, VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st and 2nd floor corridors**
MATERIAL QUANTITY: **70** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/15/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUIDLING ID: **6130**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Swift School** REVIEW DATE: **5/19/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **43**
MATERIAL DESCRIPTION: **12" X 12" yellow, VFT**
MATERIAL LOCATION: **1st and 2nd floor corridors**
MATERIAL QUANTITY: **70** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/19/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUIDLING ID: **6130**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Swift School** INSPECTION DATE: **3/15/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **43A**
MATERIAL DESCRIPTION: **12" X 12" yellow, Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st and 2nd floor corridors**
MATERIAL QUANTITY: **70** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/15/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUILDING ID: **6130**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Swift School** REVIEW DATE: **5/19/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **43A**
MATERIAL DESCRIPTION: **12" X 12" yellow, Mastic**
MATERIAL LOCATION: **1st and 2nd floor corridors**
MATERIAL QUANTITY: **70** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/19/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUIDLING ID: **6130**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Swift School** INSPECTION DATE: **3/15/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **44**
MATERIAL DESCRIPTION: **Carpet mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rm 104
(Removed from Rms 101, 102, 103, 108, and 109)**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/15/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUILDING ID: **6130**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Swift School** REVIEW DATE: **5/19/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **44**
MATERIAL DESCRIPTION: **Carpet mastic**
MATERIAL LOCATION: **Rm 104
(Removed from Rms 101, 102, 103, 108, and 109)**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **05/19/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUIDLING ID: **6130**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Swift School** INSPECTION DATE: **3/15/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **45**
MATERIAL DESCRIPTION: **12" X 12" white with blue specks, VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st and 2nd floor corridors; Rm 108**
MATERIAL QUANTITY: **6000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/15/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUILDING ID: **6130**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Swift School** REVIEW DATE: **5/19/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **45**
MATERIAL DESCRIPTION: **12" X 12" white with blue specks, VFT**
MATERIAL LOCATION: **1st and 2nd floor corridors; Rm 108**
MATERIAL QUANTITY: **6000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/19/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUIDLING ID: **6130**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Swift School** INSPECTION DATE: **3/15/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **45A**
MATERIAL DESCRIPTION: **12" X 12" white with blue specks, Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st and 2nd floor corridors; Rm 108**
MATERIAL QUANTITY: **6000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/15/2016

Chicago Public Schools

GSG Consultants, Inc.

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUIDLING ID: **6130**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Swift School** REVIEW DATE: **5/19/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **45A**
MATERIAL DESCRIPTION: **12" X 12" white with blue specks, Mastic**
MATERIAL LOCATION: **1st and 2nd floor corridors; Rm 108**
MATERIAL QUANTITY: **6000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/19/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUIDLING ID: **6130**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Swift School** INSPECTION DATE: **3/15/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **46**
MATERIAL DESCRIPTION: **Fire Door**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Balcony**
MATERIAL QUANTITY: **10** MATERIAL UNITS: **EA**
DAMAGE QUANTITY: DAMAGE UNITS: **EA**

COMMENTS:

Inspector's Signature: _____



Date: 03/15/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUIDLING ID: **6130**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Swift School** REVIEW DATE: **5/19/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **46**
MATERIAL DESCRIPTION: **Fire Door**
MATERIAL LOCATION: **Balcony**
MATERIAL QUANTITY: **10** MATERIAL UNITS: **EA**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/19/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUIDLING ID: **6130**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Swift School** INSPECTION DATE: **3/15/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **47**
MATERIAL DESCRIPTION: **12" X 12" white with gray specks, VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Assembly Hall**
MATERIAL QUANTITY: **320** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/15/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUILDING ID: **6130**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Swift School** REVIEW DATE: **5/19/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **47**
MATERIAL DESCRIPTION: **12" X 12" white with gray specks, VFT**
MATERIAL LOCATION: **Assembly Hall**
MATERIAL QUANTITY: **320** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/19/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUIDLING ID: **6130**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Swift School** INSPECTION DATE: **3/15/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **47A**
MATERIAL DESCRIPTION: **12" X 12" white with gray specks, Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Assembly Hall**
MATERIAL QUANTITY: **320** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/15/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUILDING ID: **6130**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Swift School** REVIEW DATE: **5/19/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **47A**
MATERIAL DESCRIPTION: **12" X 12" white with gray specks, Mastic**
MATERIAL LOCATION: **Assembly Hall**
MATERIAL QUANTITY: **320** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **05/19/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUIDLING ID: **6130**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Swift School** INSPECTION DATE: **3/15/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **48**
MATERIAL DESCRIPTION: **Carpet mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Auditorium, between isles**

MATERIAL QUANTITY: **400**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/15/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUILDING ID: **6130**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Swift School** REVIEW DATE: **5/19/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **48**
MATERIAL DESCRIPTION: **Carpet mastic**
MATERIAL LOCATION: **Auditorium, between isles**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/19/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUILDING ID: **6130**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Swift School** INSPECTION DATE: **3/15/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **49**
MATERIAL DESCRIPTION: **Drywall System**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **1919 Building**

MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____



Date: 03/15/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUILDING ID: **6130**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Swift School** REVIEW DATE: **5/19/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **49**
MATERIAL DESCRIPTION: **Drywall System**
MATERIAL LOCATION: **1919 Building**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **05/19/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUIDLING ID: **6130**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Swift School** INSPECTION DATE: **3/15/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **50**
MATERIAL DESCRIPTION: **2'x4' Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **1919 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____



Date: 03/15/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUILDING ID: **6130**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Swift School** REVIEW DATE: **5/19/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **50**
MATERIAL DESCRIPTION: **2'x4' Ceiling Tile**
MATERIAL LOCATION: **1919 Building**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **05/19/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUIDLING ID: **6130**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Swift School** INSPECTION DATE: **3/15/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **A**
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 202 & 2nd Floor Corridor - 1914**
MATERIAL QUANTITY: **16** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**
COMMENTS:

Inspector's Signature: _____



Date: 03/15/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUIDLING ID: **6130**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Swift School** REVIEW DATE: **5/19/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **A**
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**
MATERIAL LOCATION: **Room 202 & 2nd Floor Corridor - 1914**
MATERIAL QUANTITY: **16** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/19/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUIDLING ID: **6130**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Swift School** INSPECTION DATE: **3/15/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **B**
MATERIAL DESCRIPTION: **MJP E/F/V on Aircell Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 202 & 2nd Floor Corridor - 1914**
MATERIAL QUANTITY: **4** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____



Date: 03/15/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUIDLING ID: **6130**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Swift School** REVIEW DATE: **5/19/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **B**
MATERIAL DESCRIPTION: **MJP E/F/V on Aircell Pipe Insulation**
MATERIAL LOCATION: **Room 202 & 2nd Floor Corridor - 1914**
MATERIAL QUANTITY: **4** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/19/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUIDLING ID: **6130**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Swift School** INSPECTION DATE: **3/15/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **C**
MATERIAL DESCRIPTION: **Mag Block Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **North & South Engine Rooms, Boiler Room, Natatorium, Natatorium Entry Hall - 1914**
MATERIAL QUANTITY: **168** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **03/15/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUIDLING ID: **6130**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Swift School** REVIEW DATE: **5/19/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **C**
MATERIAL DESCRIPTION: **Mag Block Pipe Insulation**
MATERIAL LOCATION: **North & South Engine Rooms, Boiler Room, Natatorium, Natatorium Entry Hall - 1914**
MATERIAL QUANTITY: **168** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/19/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUIDLING ID: **6130**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Swift School** INSPECTION DATE: **3/15/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **D**
MATERIAL DESCRIPTION: **MJP E/F/V on Mag Block Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **North & South Engine Rooms, Boiler Room, Natatorium, Natatorium Entry Hall - 1914**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**
COMMENTS:

Inspector's Signature: _____



Date: 03/15/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUIDLING ID: **6130**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Swift School** REVIEW DATE: **5/19/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **D**
MATERIAL DESCRIPTION: **MJP E/F/V on Mag Block Pipe Insulation**
MATERIAL LOCATION: **North & South Engine Rooms, Boiler Room, Natatorium, Natatorium Entry Hall - 1914**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/19/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUIDLING ID: **6130**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Swift School** INSPECTION DATE: **3/15/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **E**
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Room 202 & 208, Room 202 & 208 Closets, 2nd Floor Corridor - 1914**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**
COMMENTS:

Inspector's Signature: _____



Date: 03/15/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUIDLING ID: **6130**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Swift School** REVIEW DATE: **5/19/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **E**
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**
MATERIAL LOCATION: **Room 202 & 208, Room 202 & 208 Closets, 2nd Floor Corridor - 1914**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/19/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUIDLING ID: **6130**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Swift School** INSPECTION DATE: **3/15/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **F**
MATERIAL DESCRIPTION: **MJP E/F/V on Cardboard Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Room 202 (old 208), Room 202 (old 208) Closet, 2nd Floor Corridor - 1914**
MATERIAL QUANTITY: **8** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____



Date: 03/15/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUILDING ID: **6130**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Swift School** REVIEW DATE: **5/19/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **F**
MATERIAL DESCRIPTION: **MJP E/F/V on Cardboard Pipe Insulation**
MATERIAL LOCATION: **Room 202 (old 208), Room 202 (old 208) Closet, 2nd Floor Corridor - 1914**
MATERIAL QUANTITY: **8** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/19/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUIDLING ID: **6130**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Swift School** INSPECTION DATE: **3/15/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **G**
MATERIAL DESCRIPTION: **MJP E/F/V on Fiberglass Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Throughout - 1914**
MATERIAL QUANTITY: **90** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**
COMMENTS:

Inspector's Signature: _____



Date: 03/15/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUIDLING ID: **6130**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Swift School** REVIEW DATE: **5/19/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **G**
MATERIAL DESCRIPTION: **MJP E/F/V on Fiberglass Pipe Insulation**
MATERIAL LOCATION: **Throughout - 1914**
MATERIAL QUANTITY: **90** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **05/19/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUIDLING ID: **6130**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Tommy Thompson**
SCHOOL NAME: **Swift School** INSPECTION DATE: **3/15/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **H**
MATERIAL DESCRIPTION: **Boiler Rope**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Boiler Room - 1914**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____



Date: 03/15/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25571** BUIDLING ID: **6130**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Swift School** REVIEW DATE: **5/19/2016**
ADDRESS: **5900 N Winthrop Avenue** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **H**
MATERIAL DESCRIPTION: **Boiler Rope**
MATERIAL LOCATION: **Boiler Room - 1914**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/19/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

APPENDIX B

Inspector and Management Planner Licenses

CERTIFICATE OF ACHIEVEMENT ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that TOMMY R. THOMPSON
has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the
examination on 02/13/2016 with a minimum score of 70% or better. Training was in accordance
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:
Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.

02/13/2016

Course Dates:

02/13/2017

Expires:

1602BIR21

Certificate Number:



Nicholas J. Peneff

Director of Training
Nicholas J. Peneff
Doctor of Public Health

Phone: 312-491-0081

FORM # A-010B



625-955 West Jefferson Street • Springfield, Illinois 62761-0001 • www.dph.illinois.gov

4/18/2016

TOMMY THOMPSON
 855 W. Adams, Suite 200
 Chicago, IL 60607



ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 08023

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License


ASBESTOS PROFESSIONAL LICENSE			ENDORSEMENTS	TC EXPIRES
 ASBESTOS PROFESSIONAL LICENSE			INSPECTOR	2/13/2017
ID NUMBER	ISSUED	EXPIRES	PROJECT MANAGER	2/6/2017
100 - 08023	4/18/2016	05/15/2017	AIR SAMPLING PROFESSIONAL	
TOMMY THOMPSON 855 W. Adams, Suite 200 Chicago, IL 60607 Environmental Health			Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
 EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH, IMPROVING LIVES
Nationally Accredited by NABH

2016



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Jigar Shah

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 1/27/2016

Exam Date: 1/27/2016

Expiration Date: 1/27/2017

Certificate Number: MPR1601270320


Kathy DeSalvo, Director



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • www.dph.illinois.gov

4/20/2016

JIGAR M SHAH
855 W ADAMS ST, SUITE 200
CHICAGO, IL 60607

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 07342

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

		ASBESTOS PROFESSIONAL LICENSE		ENDORSEMENTS	TC EXPIRES
ID NUMBER 109 - 07342	ISSUED 4/20/2016	EXPIRES 05/15/2017		INSPECTOR PROJECT DESIGNER MANAGEMENT PLANNER PROJECT MANAGER AIR SAMPLING PROFESSIONAL	1/19/2017 2/2/2017 1/27/2017 2/26/2017
JIGAR M SHAH 855 W ADAMS ST, SUITE 200 CHICAGO, IL 60607 Environmental Health				Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH, IMPROVING LIVES
Nationally Accredited by PHAB

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL		
	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE		
	Loc	Localized
	Dist	Distributed