

ILLINOIS DEPARTMENT OF PUBLIC HEALTH  
AHERA THREE YEAR REINSPECTION  
ASBESTOS ABATEMENT PROGRAM  
SCHOOL INFORMATION FORM

**SECTION I**

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299  
SCHOOL ID NUMBER: 14-016-2990-2176  
SCHOOL NAME: Dumas School  
ADDRESS OF SCHOOL: 6650 S. Ellis  
CITY: Chicago, IL, 60637

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **3/12/2013**

**If the address on this form is different than the address of the building, submit a written explanation.**

**SECTION II** (Please type or print)

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 3/29/2016 ENROLLMENT 596  
IDPH INSPECTOR LICENSE NUMBER: 100-00249  
IDPH LICENSED INSPECTOR NAME (Please Print): John Feely  
IDPH MP LICENSE NUMBER: 100-09870  
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Todd Huffer

DESIGNATED PERSON (Please Print): Robert Christlieb PHONE: (773) 553-3197



3/29/2016

Signature of Designated Person

Date

**SECTION III**

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: \_\_\_\_\_

School has been closed. Date closed: \_\_\_\_\_

School building has been demolished. Date: \_\_\_\_\_

School building is asbestos free since last reinspection: \_\_\_\_\_

**Please explain in writing why the school building is now asbestos free and include the supporting documentation.**

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

**Explain in writing if the address of the building is different than the address on this form:**

**THREE-YEAR REINSPECTION**

**CHICAGO SCHOOL DIST 299**

**Dumas School**

6650 S. Ellis  
Chicago, IL, 60637

Unit: 25711  
Building ID: 6890

IDPH ID Number: 14-016-2990-2176

**REPORT DATE:**

Tuesday, March 29, 2016

**Prepared for:**

**Chicago Public Schools**  
**125 S. Clark Street**  
**Chicago, IL 60603**

**Prepared by:**

**Carnow, Conibear and Associates**

600 West Van Buren St., Ste 500

Phone (312) 762-2900

Fax (312) 782-5145

**DO NOT REMOVE FROM SCHOOL  
REQUIRED BY FEDERAL LAW**



## **Environmental Notification to Occupants**

To: Faculty, Staff and Parents  
From: Chicago Public Schools  
Date: March 10, 2016

RE: Dumas School, Unit 25711  
6650 S. Ellis  
Chicago, IL, 60637

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2016 asbestos three year re-inspection has been completed at Dumas School , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at Dumas School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Robert Christlieb, the designated Local Education Authority's Designated Person at (773) 553-3197 .

## **Table of Contents**

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

### **APPENDICES:**

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

## SCHOOL AND INSPECTION INFORMATION

### 1. School Information

School: Dumas School  
Address: 6650 S. Ellis  
IDPH ID: 14-016-2990-2176  
Contact:

Unit: 26171  
Chicago, IL, 60637  
Building ID: 6890  
Phone:

Region: 05

### 2. Description of Facility

Original Construction:  
Total Square Footage:  
Current Occupancy: 596

Additional Construction:  
No of Floors:

### 3. LEA Designated Person

Contact: Robert Christlieb  
Address: 125 South Clark Street, 17th Floor  
Chicago, IL 60603

Phone: (773) 553-3197

### 4. Managing Environmental Consultant

MEC: Carnow, Conibear and Associates  
Contact: Dan Juneau  
Address 600 West Van Buren St., Ste 500  
Phone: (312) 762-2900

Fax: (312) 782-5145

### 5. Inspector

Inspector Name: John Feely


Inspector IDPH license # 100-00249

Signature:  
Date: 3/10/2016

### 6. Management Planner

Management Planner Name: Todd Huffer

Management Planner IDPH license # 100-09870

Signature:   
Date: 03/29/2016

### 7. Review Date: 03/29/2016

### 8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature: 

Date: 3/29/2016

Name: Robert Christlieb

## II. EXECUTIVE SUMMARY

Carnow, Conibear and Associates was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Dumas School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 6890:

02	acoustic plaster
24	Black Coating on Sink

B. The following new homogenous areas have been identified for Building 6890:



C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

02	acoustic plaster
05	9x9 beige floor tile- Partially Removed
07	9x9 beige floor tile mastic - Partially Removed
08	12x12 off white w/pink floor tile mastic
09	12x12 white floor tile
09A	12x12 dark blue /light blue flr. Tile
10	12x12 white floor tile mastic
10A	mastic 12x12 dark blue/ light blue floor tile
11	9x9 dark beige floor tile - NOT OBSERVED
11A	12x12 darkpink/ light pink floor tile checker boar
12	9x9 dark beige floor tile mastic - NOT OBSERVED
12A	mastic 12x12 dk. Pink/light pink floor tile
13	9x9 dark brown floor tile - NOT OBSERVED
14	9x9 dark brown floor tile mastic -NOT OBSERVED
15	interior window caulk - REMOVED
16	blue carpet mastic
19	12x12 light pink/beige w/pink specks flr tile
20	mastic 12x12 light pink/ beige w/ pink specks
21	12x12 white w/ blue specks floor tile
22	mastic 12x12 white w/ blue specks floor tile
23	12x12 floor tile
24	Black Coating on Sink
25	12" x 12" Green w/ Speckles VFT
25A	12" x 12" Green w/ Speckles VFT Mastic
FT-1	ceramic tile Adhesive/grout

The following areas were deemed to be inaccessible:

08	12x12 off white w/pink floor tile mastic
10	12x12 white floor tile mastic
12A	mastic 12x12 dk. Pink/light pink floor tile
16	blue carpet mastic
18	mastic 12x12 beige (BROWN) w/ tan specks
20	mastic 12x12 light pink/ beige w/ pink specks
22	mastic 12x12 white w/ blue specks floor tile
25A	12" x 12" Green w/ Speckles VFT Mastic

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by John Feely, IDPH License # 100-00249. The Management Plan was updated by Todd Huffer, IDPH License # 100-09870. Inspector and Management Planner Licenses are included in Appendix B.

### **III. METHODOLOGY**

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

### **IV. ABATEMENT HISTORY**

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

### **V. REASSESSMENTS AND RECOMMENDATIONS**

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

### **VI. CONCLUSIONS**

The Dumas School Building 6890 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

**Table I**  
**Inspector's Reinspection Findings**

---

# Chicago Public Schools

School Dumas School Unit 26171 Building ID 6890

Address 6650 S. Ellis Region 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
02	acoustic plaster	5,200	SF	corridors and classrooms throughout	ASSUMED	SURFACE	N	NONE	0		Yes	ACBM with the potential for damage		LOW
05	9x9 beige floor tile- Partially Removed			114, 163, lunchroom, office	ASSUMED	MISC								
06	12x12 off white with brown floor tile	600	SF	1st floor corridor off lunchroom, room 304	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
07	9x9 beige floor tile mastic - Partially Removed			114, 163, lunchroom, office	ASSUMED	MISC								
08	12x12 off white w/pink floor tile mastic	600	SF	1st floor corridor off lunchroom, room 304	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
09	12x12 white floor tile	10,000	SF	gym, 3rd floor corridor, rms.301,303,201,207,208,211 & 3rd floor teachers lounge	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
09A	12x12 dark blue /light blue flr. Tile	14,600	SF	lunchrm.,214,212,210,209,205,206,202,201,302, 305, 306,308,314,307,309,310,311,312,313, main office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
10	12x12 white floor tile mastic	10,000	SF	gym, 3rd floor corridor, rms.301,303,201,207,208,211 & 3rd floor teachers lounge	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
10A	mastic 12x12 dark blue/ light blue floor tile	14,600	SF	lunchroom,214,212,210,209,205,206,202,201,306,308,314,307,309,310,311,312, 313,main office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
11	9x9 dark beige floor tile - NOT OBSERVED			2nd fl corridor	ASSUMED	MISC		None						Low
11A	12x12 darkpink/ light pink floor tile checker boar	3,052	SF	2nd floor corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
12	9x9 dark beige floor tile mastic - NOT OBSERVED			2nd fl corridor	ASSUMED	MISC		None						Low
12A	mastic 12x12 dk. Pink/light pink floor tile	3,052	SF	2nd floor corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
13	9x9 dark brown floor tile - NOT OBSERVED			2nd fl corridor, Rm 206	ASSUMED	MISC		None						Low

# Chicago Public Schools

School Dumas School Unit 26171 Building ID 6890

Address 6650 S. Ellis Region 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
14	9x9 dark brown floor tile mastic -NOT OBSERVED			2nd floor corridor, room 206	ASSUMED	MISC								
15	interior window caulk - REMOVED			throughout school	ASSUMED	MISC		None						
16	blue carpet mastic	1,176	SF	room 203, library	ASSUMED	MISC	N	NONE	0		No			LOW
17	12x12 beige (BROWN) w/ tan specks	42	SF	3rd floor mens washroom	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
18	mastic 12x12 beige (BROWN) w/ tan specks	42	SF	3rd floor mens washroom	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
19	12x12 light pink/beige w/pink specks flr tile	7,882	SF	1st. Floor corridor rm. 101,counseling,105, 108,110,106,104a,10 4b	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
20	mastic 12x12 light pink/ beige w/ pink specks	7,882	SF	1st. Floor corridor rooms 101,counseling rm. 105,108,110,106,10 4a,104b	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
21	12x12 white w/ blue specks floor tile	2,036	SF	rooms 107,109	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
22	mastic 12x12 white w/ blue specks floor tile	2,036	SF	rooms107,109	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
23	12x12 floor tile	20	SF	Lunchroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
24	Black Coating on Sink	400	SF	Rooms 103, 106, 107, 108, 109, 210	ASSUMED	SURFACE	N	NONE	0		Yes	ACBM with the potential for damage		LOW
25	12" x 12" Green w/ Speckles VFT	800	SF	Lunchroom, Office, Kitchen	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
25A	12" x 12" Green w/ Speckles VFT Mastic	800	SF	Lunchroom, Office, Kitchen	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
A	duct manifold			fan room, mechanical room	ABATED	MISC								
B	fiberglass joint compound			boiler room, fan room, pump room, toilet chases, unexcavated areas	ABATED	TSI								
C	header insulation - REMOVED			pump room	ABATED	MISC								
D	tank jacket - REMOVED			pump room	ABATED	MISC								
FT-1	ceramic tile Adhesive/grout	350	SF	Asst. Principal's office, 107, 109	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

# Chicago Public Schools

School Dumas School Unit 26171 Building ID 6890

Address 6650 S. Ellis Region 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

Reinspection Date <b>3/10/2016</b>
Inspector Name <b>John Feely</b>
<b>100-00249</b> <b>5/15/2016</b>
Inspector's IDPH License Number / Expiration Date

### Inspector's Comments

HA Number:	Inspector Comments:
02	
05	Not Observed 2016
06	
07	Not Observed 2016
08	
09	
09A	
10	
10A	
11	Not Observed 2016
11A	
12	Not Observed 2016
12A	
13	Not Observed 2016
14	Not Observed 2016
15	Not Observed 2016
16	
17	
18	
19	
20	
21	
22	
23	

# Chicago Public Schools

School Dumas School Unit 26171 Building ID 6890

Address 6650 S. Ellis Region 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
24	
25	
25A	
A	Not Observed 2016
B	Not Observed 2016
C	Not Observed 2016
D	Not Observed 2016
FT-1	



**Table II**

**Management Planner's Review**

---

# Chicago Public Schools

**School** Dumas School  
**Address** 6650 S. Ellis

**Unit** 26171  
 Chicago, IL, 60637

**Building ID** 6890  
**Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
02	acoustic plaster	5,200	SF	corridors and classrooms throughout	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
05	9x9 beige floor tile- Partially Removed			114, 163, lunchroom, office	Assumed	MISC					
06	12x12 off white with brown floor tile	600	SF	1st floor corridor off lunchroom, room 304	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
07	9x9 beige floor tile mastic - Partially Removed			114, 163, lunchroom, office	Assumed	MISC					
08	12x12 off white w/pink floor tile mastic	600	SF	1st floor corridor off lunchroom, room 304	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
09	12x12 white floor tile	10,000	SF	gym, 3rd floor corridor, rms.301,303,201,207,208,211 & 3rd floor teachers lounge	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
09A	12x12 dark blue /light blue flr. Tile	14,600	SF	lunchrm.,214,212,210,209,205,206,202,201,302, 305, 306,308,314,307,309,310,311,312,313, main office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
10	12x12 white floor tile mastic	10,000	SF	gym, 3rd floor corridor, rms.301,303,201,207,208,211 & 3rd floor teachers lounge	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
10A	mastic 12x12 dark blue/ light blue floor tile	14,600	SF	lunchroom,214,212,210,209,205,206,202,201,306,308,314,307,309,310,311,312,313,main office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
11	9x9 dark beige floor tile - NOT OBSERVED			2nd fl corridor	Assumed	MISC					
11A	12x12 darkpink/ light pink floor tile checker boar	3,052	SF	2nd floor corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
12	9x9 dark beige floor tile mastic - NOT OBSERVED			2nd fl corridor	Assumed	MISC					
12A	mastic 12x12 dk. Pink/light pink floor tile	3,052	SF	2nd floor corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
13	9x9 dark brown floor tile - NOT OBSERVED			2nd fl corridor, Rm 206	Assumed	MISC					
14	9x9 dark brown floor tile mastic -NOT OBSERVED			2nd floor corridor, room 206	Assumed	MISC					
15	interior window caulk - REMOVED			throughout school	Assumed	MISC					
16	blue carpet mastic	1,176	SF	room 203, library	Assumed	MISC	No	0	SF		Follow O&M Plan
17	12x12 beige (BROWN) w/ tan specks	42	SF	3rd floor mens washroom	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
18	mastic 12x12 beige (BROWN) w/ tan specks	42	SF	3rd floor mens washroom	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
19	12x12 light pink/beige w/pink specks flr tile	7,882	SF	1st. Floor corridor rm. 101,counseling,105,108,110,106,104a, 104b	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
20	mastic 12x12 light pink/ beige w/ pink specks	7,882	SF	1st. Floor corridor rooms 101,counseling rm. 105,108,110,106,104a,104b	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Dumas School  
**Address** 6650 S. Ellis

**Unit** 26171  
 Chicago, IL, 60637

**Building ID** 6890  
**Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
21	12x12 white w/ blue specks floor tile	2,036	SF	rooms 107,109	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
22	mastic 12x12 white w/ blue specks floor tile	2,036	SF	rooms107,109	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
23	12x12 floor tile	20	SF	Lunchroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
24	Black Coating on Sink	400	SF	Rooms 103, 106, 107, 108, 109, 210	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
25	12" x 12" Green w/ Speckles VFT	800	SF	Lunchroom, Office, Kitchen	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
25A	12" x 12" Green w/ Speckles VFT Mastic	800	SF	Lunchroom, Office, Kitchen	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
A	duct manifold			fan room, mechanical room	Abated	MISC					
B	fiberglass joint compound			boiler room, fan room, pump room, toilet chases, unexcavated areas	Abated	TSI					
C	header insulation - REMOVED			pump room	Abated	MISC					
D	tank jacket - REMOVED			pump room	Abated	MISC					
FT-1	ceramic tile Adhesive/grout	350	SF	Asst. Principal's office, 107, 109	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Dumas School  
**Address** 6650 S. Ellis

**Unit** 26171  
 Chicago, IL, 60637

**Building ID** 6890  
**Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

Review Date	3/29/2016
Manager Planner Name	Todd Huffer
100-09870	5/15/2016
Manager IDPH License No/Expiration	

HA Number	Management Comments
02	
05	Material Not Observed in 2016
06	
07	Material Not Observed in 2016
08	
09	
09A	
10	
10A	
11	Material Not Observed in 2016
11A	
12	Material Not Observed in 2016
12A	
13	Material Not Observed in 2016
14	Material Not Observed in 2016
15	Material Not Observed in 2016
16	
17	
18	
19	
20	
21	
22	
23	

# Chicago Public Schools

**School** Dumas School  
**Address** 6650 S. Ellis

**Unit** 26171  
Chicago, IL, 60637

**Building ID** 6890  
**Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
24	
25	
25A	
A	Material Not Observed in 2016
B	Material Not Observed in 2016
C	Material Not Observed in 2016
D	Material Not Observed in 2016
FT-1	

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26171** BUIDLING ID: **6890**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**  
SCHOOL NAME: **Dumas School** INSPECTION DATE: **3/10/2016**  
ADDRESS: **6650 S. Ellis** IDPH LICENSE NO: **100-00249**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **02**  
MATERIAL DESCRIPTION: **acoustic plaster**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with potential for significant damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **corridors and classrooms throughout**

MATERIAL QUANTITY: **5200**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 03/10/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26171** BUIDLING ID: **6890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Dumas School** REVIEW DATE: **3/29/2016**  
ADDRESS: **6650 S. Ellis** IDPH LICENSE NO: **100-00249**

---

HOMOGENEOUS AREA: **02**  
MATERIAL DESCRIPTION: **acoustic plaster**  
MATERIAL LOCATION: **corridors and classrooms throughout**  
MATERIAL QUANTITY: **5200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/29/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26171** BUIDLING ID: **6890**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**  
SCHOOL NAME: **Dumas School** INSPECTION DATE: **3/10/2016**  
ADDRESS: **6650 S. Ellis** IDPH LICENSE NO: **100-00249**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **05**  
MATERIAL DESCRIPTION: **9x9 beige floor tile- Partially Removed**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with potential for significant damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **114, 163, lunchroom, office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed 2016**

Inspector's Signature: \_\_\_\_\_

Date: 03/10/2016



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26171** BUIDLING ID: **6890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Dumas School** REVIEW DATE: **3/29/2016**  
ADDRESS: **6650 S. Ellis** IDPH LICENSE NO: **100-00249**

---

HOMOGENEOUS AREA: **05**

MATERIAL DESCRIPTION: **9x9 beige floor tile- Partially Removed**

MATERIAL LOCATION: **114, 163, lunchroom, office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Material Not Observed in 2016

Management Planner's Signature: \_\_\_\_\_



Date: **03/29/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26171** BUIDLING ID: **6890**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**  
SCHOOL NAME: **Dumas School** INSPECTION DATE: **3/10/2016**  
ADDRESS: **6650 S. Ellis** IDPH LICENSE NO: **100-00249**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **06**  
MATERIAL DESCRIPTION: **12x12 off white with brown floor tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st floor corridor off lunchroom, room 304**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 03/10/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26171** BUIDLING ID: **6890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Dumas School** REVIEW DATE: **3/29/2016**  
ADDRESS: **6650 S. Ellis** IDPH LICENSE NO: **100-00249**

---

HOMOGENEOUS AREA: **06**  
MATERIAL DESCRIPTION: **12x12 off white with brown floor tile**  
MATERIAL LOCATION: **1st floor corridor off lunchroom, room 304**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/29/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26171** BUIDLING ID: **6890**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**  
SCHOOL NAME: **Dumas School** INSPECTION DATE: **3/10/2016**  
ADDRESS: **6650 S. Ellis** IDPH LICENSE NO: **100-00249**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **07**  
MATERIAL DESCRIPTION: **9x9 beige floor tile mastic - Partially Removed**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **114, 163, lunchroom, office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed 2016**

Inspector's Signature: \_\_\_\_\_

Date: 03/10/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26171** BUIDLING ID: **6890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Dumas School** REVIEW DATE: **3/29/2016**  
ADDRESS: **6650 S. Ellis** IDPH LICENSE NO: **100-00249**

---

HOMOGENEOUS AREA: **07**

MATERIAL DESCRIPTION: **9x9 beige floor tile mastic - Partially Removed**

MATERIAL LOCATION: **114, 163, lunchroom, office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Material Not Observed in 2016

Management Planner's Signature: \_\_\_\_\_



Date: **03/29/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26171** BUIDLING ID: **6890**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**  
SCHOOL NAME: **Dumas School** INSPECTION DATE: **3/10/2016**  
ADDRESS: **6650 S. Ellis** IDPH LICENSE NO: **100-00249**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **08**  
MATERIAL DESCRIPTION: **12x12 off white w/pink floor tile mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st floor corridor off lunchroom, room 304**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 03/10/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26171** BUIDLING ID: **6890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Dumas School** REVIEW DATE: **3/29/2016**  
ADDRESS: **6650 S. Ellis** IDPH LICENSE NO: **100-00249**

---

HOMOGENEOUS AREA: **08**  
MATERIAL DESCRIPTION: **12x12 off white w/pink floor tile mastic**  
MATERIAL LOCATION: **1st floor corridor off lunchroom, room 304**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/29/2016**

# Chicago Public Schools

## Carnow, Conibear and Associates 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26171** BUIDLING ID: **6890**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**  
SCHOOL NAME: **Dumas School** INSPECTION DATE: **3/10/2016**  
ADDRESS: **6650 S. Ellis** IDPH LICENSE NO: **100-00249**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **09**  
MATERIAL DESCRIPTION: **12x12 white floor tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **gym, 3rd floor corridor, rms.301,303,201,207,208,211 & 3rd floor teachers lounge**  
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 03/10/2016



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26171** BUIDLING ID: **6890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Dumas School** REVIEW DATE: **3/29/2016**  
ADDRESS: **6650 S. Ellis** IDPH LICENSE NO: **100-00249**

---

HOMOGENEOUS AREA: **09**  
MATERIAL DESCRIPTION: **12x12 white floor tile**  
MATERIAL LOCATION: **gym, 3rd floor corridor, rms.301,303,201,207,208,211 & 3rd floor teachers lounge**  
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/29/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26171** BUIDLING ID: **6890**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**  
SCHOOL NAME: **Dumas School** INSPECTION DATE: **3/10/2016**  
ADDRESS: **6650 S. Ellis** IDPH LICENSE NO: **100-00249**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **09A**  
MATERIAL DESCRIPTION: **12x12 dark blue /light blue flr. Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **lunchrm.,214,212,210,209,205,206,202,201,302, 305,  
306,308,314,307,309,310,311,312,313,main office**

MATERIAL QUANTITY: **14600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **03/10/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26171** BUIDLING ID: **6890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Dumas School** REVIEW DATE: **3/29/2016**  
ADDRESS: **6650 S. Ellis** IDPH LICENSE NO: **100-00249**

---

HOMOGENEOUS AREA: **09A**  
MATERIAL DESCRIPTION: **12x12 dark blue /light blue flr. Tile**  
MATERIAL LOCATION: **lunchrm.,214,212,210,209,205,206,202,201,302, 305, 306,308,314,307,309,310,311,312,313,main office**  
MATERIAL QUANTITY: **14600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/29/2016**

# Chicago Public Schools

## Carnow, Conibear and Associates 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26171** BUIDLING ID: **6890**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**  
SCHOOL NAME: **Dumas School** INSPECTION DATE: **3/10/2016**  
ADDRESS: **6650 S. Ellis** IDPH LICENSE NO: **100-00249**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10**  
MATERIAL DESCRIPTION: **12x12 white floor tile mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **gym, 3rd floor corridor, rms.301,303,201,207,208,211 & 3rd floor teachers lounge**  
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 03/10/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26171** BUIDLING ID: **6890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Dumas School** REVIEW DATE: **3/29/2016**  
ADDRESS: **6650 S. Ellis** IDPH LICENSE NO: **100-00249**

---

HOMOGENEOUS AREA: **10**  
MATERIAL DESCRIPTION: **12x12 white floor tile mastic**  
MATERIAL LOCATION: **gym, 3rd floor corridor, rms.301,303,201,207,208,211 & 3rd floor teachers lounge**  
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/29/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26171** BUIDLING ID: **6890**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**  
SCHOOL NAME: **Dumas School** INSPECTION DATE: **3/10/2016**  
ADDRESS: **6650 S. Ellis** IDPH LICENSE NO: **100-00249**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10A**  
MATERIAL DESCRIPTION: **mastic 12x12 dark blue/ light blue floor tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **lunchroom,214,212,210,209,205,206,202,201,306,308,314,307,309,310,311,312,313,main office**

MATERIAL QUANTITY: **14600**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 03/10/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26171** BUIDLING ID: **6890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Dumas School** REVIEW DATE: **3/29/2016**  
ADDRESS: **6650 S. Ellis** IDPH LICENSE NO: **100-00249**

---

HOMOGENEOUS AREA: **10A**  
MATERIAL DESCRIPTION: **mastic 12x12 dark blue/ light blue floor tile**  
MATERIAL LOCATION: **lunchroom,214,212,210,209,205,206,202,201,306,308,314,307,309,310,311,312,313,main office**  
MATERIAL QUANTITY: **14600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/29/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26171** BUIDLING ID: **6890**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**  
SCHOOL NAME: **Dumas School** INSPECTION DATE: **3/10/2016**  
ADDRESS: **6650 S. Ellis** IDPH LICENSE NO: **100-00249**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11**  
MATERIAL DESCRIPTION: **9x9 dark beige floor tile - NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **2nd fl corridor**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not Observed 2016**

Inspector's Signature: \_\_\_\_\_ Date: **03/10/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26171** BUIDLING ID: **6890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Dumas School** REVIEW DATE: **3/29/2016**  
ADDRESS: **6650 S. Ellis** IDPH LICENSE NO: **100-00249**

---

HOMOGENEOUS AREA: **11**

MATERIAL DESCRIPTION: **9x9 dark beige floor tile - NOT OBSERVED**

MATERIAL LOCATION: **2nd fl corridor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Material Not Observed in 2016

Management Planner's Signature: \_\_\_\_\_



Date: **03/29/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26171** BUIDLING ID: **6890**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**  
SCHOOL NAME: **Dumas School** INSPECTION DATE: **3/10/2016**  
ADDRESS: **6650 S. Ellis** IDPH LICENSE NO: **100-00249**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11A**  
MATERIAL DESCRIPTION: **12x12 darkpink/ light pink floor tile checker boar**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **2nd floor corridor**  
MATERIAL QUANTITY: **3052** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 03/10/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26171** BUIDLING ID: **6890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Dumas School** REVIEW DATE: **3/29/2016**  
ADDRESS: **6650 S. Ellis** IDPH LICENSE NO: **100-00249**

---

HOMOGENEOUS AREA: **11A**  
MATERIAL DESCRIPTION: **12x12 darkpink/ light pink floor tile checker boar**  
MATERIAL LOCATION: **2nd floor corridor**  
MATERIAL QUANTITY: **3052** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/29/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26171** BUIDLING ID: **6890**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**  
SCHOOL NAME: **Dumas School** INSPECTION DATE: **3/10/2016**  
ADDRESS: **6650 S. Ellis** IDPH LICENSE NO: **100-00249**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12**  
MATERIAL DESCRIPTION: **9x9 dark beige floor tile mastic - NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **2nd fl corridor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed 2016**

Inspector's Signature: \_\_\_\_\_

Date: **03/10/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26171** BUIDLING ID: **6890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Dumas School** REVIEW DATE: **3/29/2016**  
ADDRESS: **6650 S. Ellis** IDPH LICENSE NO: **100-00249**

---

HOMOGENEOUS AREA: **12**

MATERIAL DESCRIPTION: **9x9 dark beige floor tile mastic - NOT OBSERVED**

MATERIAL LOCATION: **2nd fl corridor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Material Not Observed in 2016

Management Planner's Signature: \_\_\_\_\_



Date: **03/29/2016**

# Chicago Public Schools

## Carnow, Conibear and Associates 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **26171**    BUILDING ID: **6890**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **John Feely**  
SCHOOL NAME: **Dumas School**    INSPECTION DATE: **3/10/2016**  
ADDRESS: **6650 S. Ellis**    IDPH LICENSE NO: **100-00249**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12A**  
MATERIAL DESCRIPTION: **mastic 12x12 dk. Pink/light pink floor tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **2nd floor corridor**  
MATERIAL QUANTITY: **3052**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY:    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **03/10/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26171** BUIDLING ID: **6890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Dumas School** REVIEW DATE: **3/29/2016**  
ADDRESS: **6650 S. Ellis** IDPH LICENSE NO: **100-00249**

---

HOMOGENEOUS AREA: **12A**  
MATERIAL DESCRIPTION: **mastic 12x12 dk. Pink/light pink floor tile**  
MATERIAL LOCATION: **2nd floor corridor**  
MATERIAL QUANTITY: **3052** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/29/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **26171**    BUIDLING ID: **6890**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **John Feely**  
SCHOOL NAME: **Dumas School**    INSPECTION DATE: **3/10/2016**  
ADDRESS: **6650 S. Ellis**    IDPH LICENSE NO: **100-00249**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13**  
MATERIAL DESCRIPTION: **9x9 dark brown floor tile - NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed**    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **2nd fl corridor, Rm 206**

MATERIAL QUANTITY:    MATERIAL UNITS:

DAMAGE QUANTITY:    DAMAGE UNITS:

COMMENTS: **Not Observed 2016**

Inspector's Signature: \_\_\_\_\_ Date: **03/10/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26171** BUIDLING ID: **6890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Dumas School** REVIEW DATE: **3/29/2016**  
ADDRESS: **6650 S. Ellis** IDPH LICENSE NO: **100-00249**

---

HOMOGENEOUS AREA: **13**

MATERIAL DESCRIPTION: **9x9 dark brown floor tile - NOT OBSERVED**

MATERIAL LOCATION: **2nd fl corridor, Rm 206**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Material Not Observed in 2016

Management Planner's Signature: \_\_\_\_\_



Date: **03/29/2016** \_\_\_\_\_

# Chicago Public Schools

## Carnow, Conibear and Associates 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26171** BUIDLING ID: **6890**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**  
SCHOOL NAME: **Dumas School** INSPECTION DATE: **3/10/2016**  
ADDRESS: **6650 S. Ellis** IDPH LICENSE NO: **100-00249**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14**  
MATERIAL DESCRIPTION: **9x9 dark brown floor tile mastic -NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **2nd floor corridor, room 206**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed 2016**

Inspector's Signature: \_\_\_\_\_

Date: **03/10/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26171** BUIDLING ID: **6890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Dumas School** REVIEW DATE: **3/29/2016**  
ADDRESS: **6650 S. Ellis** IDPH LICENSE NO: **100-00249**

---

HOMOGENEOUS AREA: **14**

MATERIAL DESCRIPTION: **9x9 dark brown floor tile mastic -NOT OBSERVED**

MATERIAL LOCATION: **2nd floor corridor, room 206**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Material Not Observed in 2016

Management Planner's Signature: \_\_\_\_\_



Date: **03/29/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26171** BUIDLING ID: **6890**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**  
SCHOOL NAME: **Dumas School** INSPECTION DATE: **3/10/2016**  
ADDRESS: **6650 S. Ellis** IDPH LICENSE NO: **100-00249**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15**  
MATERIAL DESCRIPTION: **interior window caulk - REMOVED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **throughout school**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed 2016**

Inspector's Signature: \_\_\_\_\_ Date: **03/10/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26171** BUIDLING ID: **6890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Dumas School** REVIEW DATE: **3/29/2016**  
ADDRESS: **6650 S. Ellis** IDPH LICENSE NO: **100-00249**

---

HOMOGENEOUS AREA: **15**

MATERIAL DESCRIPTION: **interior window caulk - REMOVED**

MATERIAL LOCATION: **throughout school**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Material Not Observed in 2016

Management Planner's Signature: \_\_\_\_\_



Date: **03/29/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **26171**    BUIDLING ID: **6890**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **John Feely**  
SCHOOL NAME: **Dumas School**    INSPECTION DATE: **3/10/2016**  
ADDRESS: **6650 S. Ellis**    IDPH LICENSE NO: **100-00249**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16**  
MATERIAL DESCRIPTION: **blue carpet mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **room 203, library**

MATERIAL QUANTITY: **1176**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **03/10/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26171** BUIDLING ID: **6890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Dumas School** REVIEW DATE: **3/29/2016**  
ADDRESS: **6650 S. Ellis** IDPH LICENSE NO: **100-00249**

---

HOMOGENEOUS AREA: **16**  
MATERIAL DESCRIPTION: **blue carpet mastic**  
MATERIAL LOCATION: **room 203, library**  
MATERIAL QUANTITY: **1176** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/29/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26171** BUIDLING ID: **6890**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**  
SCHOOL NAME: **Dumas School** INSPECTION DATE: **3/10/2016**  
ADDRESS: **6650 S. Ellis** IDPH LICENSE NO: **100-00249**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17**  
MATERIAL DESCRIPTION: **12x12 beige (BROWN) w/ tan specks**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **3rd floor mens washroom**  
MATERIAL QUANTITY: **42** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 03/10/2016



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26171** BUIDLING ID: **6890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Dumas School** REVIEW DATE: **3/29/2016**  
ADDRESS: **6650 S. Ellis** IDPH LICENSE NO: **100-00249**

---

HOMOGENEOUS AREA: **17**  
MATERIAL DESCRIPTION: **12x12 beige (BROWN) w/ tan specks**  
MATERIAL LOCATION: **3rd floor mens washroom**  
MATERIAL QUANTITY: **42** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/29/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26171** BUIDLING ID: **6890**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**  
SCHOOL NAME: **Dumas School** INSPECTION DATE: **3/10/2016**  
ADDRESS: **6650 S. Ellis** IDPH LICENSE NO: **100-00249**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18**  
MATERIAL DESCRIPTION: **mastic 12x12 beige (BROWN) w/ tan specks**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **3rd floor mens washroom**  
MATERIAL QUANTITY: **42** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 03/10/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26171** BUIDLING ID: **6890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Dumas School** REVIEW DATE: **3/29/2016**  
ADDRESS: **6650 S. Ellis** IDPH LICENSE NO: **100-00249**

---

HOMOGENEOUS AREA: **18**  
MATERIAL DESCRIPTION: **mastic 12x12 beige (BROWN) w/ tan specks**  
MATERIAL LOCATION: **3rd floor mens washroom**  
MATERIAL QUANTITY: **42** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/29/2016**

# Chicago Public Schools

## Carnow, Conibear and Associates 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26171** BUIDLING ID: **6890**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**  
SCHOOL NAME: **Dumas School** INSPECTION DATE: **3/10/2016**  
ADDRESS: **6650 S. Ellis** IDPH LICENSE NO: **100-00249**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19**  
MATERIAL DESCRIPTION: **12x12 light pink/beige w/pink specks flr tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st. Floor corridor rm. 101,counseling,105,108,110,106,104a,104b**  
MATERIAL QUANTITY: **7882** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 03/10/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26171** BUIDLING ID: **6890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Dumas School** REVIEW DATE: **3/29/2016**  
ADDRESS: **6650 S. Ellis** IDPH LICENSE NO: **100-00249**

---

HOMOGENEOUS AREA: **19**  
MATERIAL DESCRIPTION: **12x12 light pink/beige w/pink specks flr tile**  
MATERIAL LOCATION: **1st. Floor corridor rm. 101,counseling,105,108,110,106,104a,104b**  
MATERIAL QUANTITY: **7882** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/29/2016**

# Chicago Public Schools

## Carnow, Conibear and Associates 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26171** BUIDLING ID: **6890**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**  
SCHOOL NAME: **Dumas School** INSPECTION DATE: **3/10/2016**  
ADDRESS: **6650 S. Ellis** IDPH LICENSE NO: **100-00249**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**  
MATERIAL DESCRIPTION: **mastic 12x12 light pink/ beige w/ pink specks**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st. Floor corridor rooms 101,counseling rm. 105,108,110,106,104a,104b**  
MATERIAL QUANTITY: **7882** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 03/10/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26171** BUIDLING ID: **6890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Dumas School** REVIEW DATE: **3/29/2016**  
ADDRESS: **6650 S. Ellis** IDPH LICENSE NO: **100-00249**

---

HOMOGENEOUS AREA: **20**  
MATERIAL DESCRIPTION: **mastic 12x12 light pink/ beige w/ pink specks**  
MATERIAL LOCATION: **1st. Floor corridor rooms 101,counseling rm. 105,108,110,106,104a,104b**  
MATERIAL QUANTITY: **7882** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/29/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26171** BUIDLING ID: **6890**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**  
SCHOOL NAME: **Dumas School** INSPECTION DATE: **3/10/2016**  
ADDRESS: **6650 S. Ellis** IDPH LICENSE NO: **100-00249**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21**  
MATERIAL DESCRIPTION: **12x12 white w/ blue specks floor tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **rooms 107,109**  
MATERIAL QUANTITY: **2036** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 03/10/2016



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26171** BUIDLING ID: **6890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Dumas School** REVIEW DATE: **3/29/2016**  
ADDRESS: **6650 S. Ellis** IDPH LICENSE NO: **100-00249**

---

HOMOGENEOUS AREA: **21**  
MATERIAL DESCRIPTION: **12x12 white w/ blue specks floor tile**  
MATERIAL LOCATION: **rooms 107,109**  
MATERIAL QUANTITY: **2036** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/29/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26171** BUIDLING ID: **6890**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**  
SCHOOL NAME: **Dumas School** INSPECTION DATE: **3/10/2016**  
ADDRESS: **6650 S. Ellis** IDPH LICENSE NO: **100-00249**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22**  
MATERIAL DESCRIPTION: **mastic 12x12 white w/ blue specks floor tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **rooms107,109**  
MATERIAL QUANTITY: **2036** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 03/10/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26171** BUIDLING ID: **6890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Dumas School** REVIEW DATE: **3/29/2016**  
ADDRESS: **6650 S. Ellis** IDPH LICENSE NO: **100-00249**

---

HOMOGENEOUS AREA: **22**  
MATERIAL DESCRIPTION: **mastic 12x12 white w/ blue specks floor tile**  
MATERIAL LOCATION: **rooms107,109**  
MATERIAL QUANTITY: **2036** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/29/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26171** BUIDLING ID: **6890**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**  
SCHOOL NAME: **Dumas School** INSPECTION DATE: **3/10/2016**  
ADDRESS: **6650 S. Ellis** IDPH LICENSE NO: **100-00249**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23**  
MATERIAL DESCRIPTION: **12x12 floor tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Lunchroom**

MATERIAL QUANTITY: **20**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 03/10/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26171** BUIDLING ID: **6890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Dumas School** REVIEW DATE: **3/29/2016**  
ADDRESS: **6650 S. Ellis** IDPH LICENSE NO: **100-00249**

---

HOMOGENEOUS AREA: **23**

MATERIAL DESCRIPTION: **12x12 floor tile**

MATERIAL LOCATION: **Lunchroom**

MATERIAL QUANTITY: **20**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/29/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26171** BUIDLING ID: **6890**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**  
SCHOOL NAME: **Dumas School** INSPECTION DATE: **3/10/2016**  
ADDRESS: **6650 S. Ellis** IDPH LICENSE NO: **100-00249**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **24**  
MATERIAL DESCRIPTION: **Black Coating on Sink**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with potential for significant damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 103, 106, 107, 108, 109, 210**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 03/10/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26171** BUIDLING ID: **6890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Dumas School** REVIEW DATE: **3/29/2016**  
ADDRESS: **6650 S. Ellis** IDPH LICENSE NO: **100-00249**

---

HOMOGENEOUS AREA: **24**  
MATERIAL DESCRIPTION: **Black Coating on Sink**  
MATERIAL LOCATION: **Rooms 103, 106, 107, 108, 109, 210**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/29/2016**

# Chicago Public Schools

## Carnow, Conibear and Associates 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26171** BUIDLING ID: **6890**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**  
SCHOOL NAME: **Dumas School** INSPECTION DATE: **3/10/2016**  
ADDRESS: **6650 S. Ellis** IDPH LICENSE NO: **100-00249**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25**  
MATERIAL DESCRIPTION: **12" x 12" Green w/ Speckles VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Lunchroom, Office, Kitchen**

MATERIAL QUANTITY: **800**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 03/10/2016



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26171** BUIDLING ID: **6890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Dumas School** REVIEW DATE: **3/29/2016**  
ADDRESS: **6650 S. Ellis** IDPH LICENSE NO: **100-00249**

---

HOMOGENEOUS AREA: **25**  
MATERIAL DESCRIPTION: **12" x 12" Green w/ Speckles VFT**  
MATERIAL LOCATION: **Lunchroom, Office, Kitchen**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/29/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26171** BUIDLING ID: **6890**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**  
SCHOOL NAME: **Dumas School** INSPECTION DATE: **3/10/2016**  
ADDRESS: **6650 S. Ellis** IDPH LICENSE NO: **100-00249**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25A**  
MATERIAL DESCRIPTION: **12" x 12" Green w/ Speckles VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Lunchroom, Office, Kitchen**

MATERIAL QUANTITY: **800**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 03/10/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26171** BUIDLING ID: **6890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Dumas School** REVIEW DATE: **3/29/2016**  
ADDRESS: **6650 S. Ellis** IDPH LICENSE NO: **100-00249**

---

HOMOGENEOUS AREA: **25A**  
MATERIAL DESCRIPTION: **12" x 12" Green w/ Speckles VFT Mastic**  
MATERIAL LOCATION: **Lunchroom, Office, Kitchen**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/29/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26171** BUIDLING ID: **6890**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**  
SCHOOL NAME: **Dumas School** INSPECTION DATE: **3/10/2016**  
ADDRESS: **6650 S. Ellis** IDPH LICENSE NO: **100-00249**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **A**  
MATERIAL DESCRIPTION: **duct manifold**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **fan room, mechanical room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed 2016**

Inspector's Signature: \_\_\_\_\_

Date: **03/10/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26171** BUIDLING ID: **6890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Dumas School** REVIEW DATE: **3/29/2016**  
ADDRESS: **6650 S. Ellis** IDPH LICENSE NO: **100-00249**

---

HOMOGENEOUS AREA: **A**  
MATERIAL DESCRIPTION: **duct manifold**  
MATERIAL LOCATION: **fan room, mechanical room**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Material Not Observed in 2016

Management Planner's Signature: \_\_\_\_\_



Date: **03/29/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **26171**    BUILDING ID: **6890**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **John Feely**  
SCHOOL NAME: **Dumas School**    INSPECTION DATE: **3/10/2016**  
ADDRESS: **6650 S. Ellis**    IDPH LICENSE NO: **100-00249**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **B**  
MATERIAL DESCRIPTION: **fiberglass joint compound**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated**    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **boiler room, fan room, pump room, toilet chases, unexcavated areas**

MATERIAL QUANTITY:    MATERIAL UNITS:

DAMAGE QUANTITY:    DAMAGE UNITS:

COMMENTS: **Not Observed 2016**

Inspector's Signature: \_\_\_\_\_ Date: **03/10/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26171** BUIDLING ID: **6890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Dumas School** REVIEW DATE: **3/29/2016**  
ADDRESS: **6650 S. Ellis** IDPH LICENSE NO: **100-00249**

---

HOMOGENEOUS AREA: **B**  
MATERIAL DESCRIPTION: **fiberglass joint compound**  
MATERIAL LOCATION: **boiler room, fan room, pump room, toilet chases, unexcavated areas**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Material Not Observed in 2016

Management Planner's Signature: \_\_\_\_\_



Date: **03/29/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26171** BUIDLING ID: **6890**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**  
SCHOOL NAME: **Dumas School** INSPECTION DATE: **3/10/2016**  
ADDRESS: **6650 S. Ellis** IDPH LICENSE NO: **100-00249**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **C**  
MATERIAL DESCRIPTION: **header insulation - REMOVED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **pump room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed 2016**

Inspector's Signature: \_\_\_\_\_ Date: **03/10/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26171** BUIDLING ID: **6890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Dumas School** REVIEW DATE: **3/29/2016**  
ADDRESS: **6650 S. Ellis** IDPH LICENSE NO: **100-00249**

---

HOMOGENEOUS AREA: **C**

MATERIAL DESCRIPTION: **header insulation - REMOVED**

MATERIAL LOCATION: **pump room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Material Not Observed in 2016

Management Planner's Signature: \_\_\_\_\_



Date: **03/29/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26171** BUIDLING ID: **6890**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**  
SCHOOL NAME: **Dumas School** INSPECTION DATE: **3/10/2016**  
ADDRESS: **6650 S. Ellis** IDPH LICENSE NO: **100-00249**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **D**  
MATERIAL DESCRIPTION: **tank jacket - REMOVED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **pump room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed 2016**

Inspector's Signature: \_\_\_\_\_

Date: **03/10/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26171** BUIDLING ID: **6890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Dumas School** REVIEW DATE: **3/29/2016**  
ADDRESS: **6650 S. Ellis** IDPH LICENSE NO: **100-00249**

---

HOMOGENEOUS AREA: **D**

MATERIAL DESCRIPTION: **tank jacket - REMOVED**

MATERIAL LOCATION: **pump room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Material Not Observed in 2016

Management Planner's Signature: \_\_\_\_\_



Date: **03/29/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26171** BUIDLING ID: **6890**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**  
SCHOOL NAME: **Dumas School** INSPECTION DATE: **3/10/2016**  
ADDRESS: **6650 S. Ellis** IDPH LICENSE NO: **100-00249**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FT-1**  
MATERIAL DESCRIPTION: **ceramic tile Adhesive/grout**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Asst. Principal's office, 107, 109**

MATERIAL QUANTITY: **350**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 03/10/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26171** BUIDLING ID: **6890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Dumas School** REVIEW DATE: **3/29/2016**  
ADDRESS: **6650 S. Ellis** IDPH LICENSE NO: **100-00249**

---

HOMOGENEOUS AREA: **FT-1**  
MATERIAL DESCRIPTION: **ceramic tile Adhesive/grout**  
MATERIAL LOCATION: **Asst. Principal's office, 107, 109**  
MATERIAL QUANTITY: **350** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/29/2016**

# **Chicago Public Schools**

**Carnow, Conibear and Associates**

***2016 AHERA REINSPECTION***

# APPENDIX B

## Inspector and Management Planner Licenses

---

**ASBESTOS INSPECTOR**  
 Issued by  
**STATE OF WISCONSIN**  
 Dept. of Health Services  
 John Charles Feely  
 9513 Lawton Ave  
 Oak Lawn, IL 60453-2999

ALI-369	Exp: 07/11/2016	250 lbs	5' 11"
		01/13/1963	Male

Training due by: 07/11/2016

LEAD DIVISION OF PUBLIC HEALTH  
**IDPH**  
 ASBESTOS PROFESSIONAL LICENSE

ID NUMBER 100 - 00249  
 ISSUED 3/2/2015  
 EXPIRES 05/15/2016

**JOHN C FEELY**  
 9513 SOUTH LAWTON AVENUE  
 OAK LAWN, IL 60453

Environmental Health



2016



**OCCUPATIONAL TRAINING & SUPPLY, INC.**

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900

# Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

**John Feely**


has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Course Date: 1/6/2016

Exam Date: 1/6/2016

Expiration Date: 1/6/2017

Certificate Number: BIR1601060019

  
Kathy DeSalvo, Director

2015



# OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900

## Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

**Todd Huffer**


has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 12/2/2015

Exam Date: 12/2/2015


Expiration Date: 12/2/2016

Certificate Number: BIR1512024161

  
Kathy DeSalvo, Director


# Todd Huffer

Illinois Licensed Asbestos Inspector, Management Planner,  
Project Manager, and Air Sampling Professional

 **ASBESTOS  
PROFESSIONAL  
LICENSE**

ID NUMBER	ISSUED	EXPIRES
<b>100 - 09870</b>	<b>3/16/2015</b>	<b>05/15/2016</b>

**TODD T HUFFER**  
315 HATLEN COURT  
MT. PROSPECT, IL 60056



Environmental Health

ENDORSEMENTS	TC EXPIRES
INSPECTOR	12/2/2015
MANAGEMENT PLANNER	2/20/2016
PROJECT MANAGER	12/11/2015
AIR SAMPLING PROFESSIONAL	

**Alteration of this license shall result in legal action**  
This license issued under authority of the State of Illinois  
Department of Public Health  
This license is valid only when accompanied by a valid  
training course certificate.

**CARNOW  
CONIBEAR**

2016



# OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900

## Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

**Todd Huffer**

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 1/27/2016

Exam Date: 1/27/2016

Expiration Date: 1/27/2017

Certificate Number: MPR1601270318

Kathy DeSalvo, Director

# APPENDIX C

## Laboratory Accreditations

---

# APPENDIX D

## Laboratory Results

---

# APPENDIX E

## Chain of Custody Forms

---

## Three-Year Reinspection Key to Terms

	<b>CODE</b>	<b>KEY</b>
<b>MATERIAL</b>		
	ACBM	Asbestos Containing Building Materials
<b>MATERIAL CATEGORY</b>		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
<b>MATERIAL UNITS</b>		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
<b>DAMAGE TYPE</b>		
	Loc	Localized
	Dist	Distributed