

ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-2510
SCHOOL NAME: Pritzker School
ADDRESS OF SCHOOL: 2009 W. Schiller Street
CITY: Chicago, IL, 60622

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **3/7/2013**

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II (Please type or print)

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 5/4/2016 ENROLLMENT 745
IDPH INSPECTOR LICENSE NUMBER: 100-07210
IDPH LICENSED INSPECTOR NAME (Please Print): Michael Holvay
IDPH MP LICENSE NUMBER: 100-04019
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Arturo Saenz

DESIGNATED PERSON (Please Print): Robert Christlieb PHONE: (773) 553-3197



5/4/2016

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Pritzker School

2009 W. Schiller Street
Chicago, IL, 60622

Unit: 25871
Building ID: 6460

IDPH ID Number: 14-016-2990-2510

REPORT DATE:

Wednesday, May 04, 2016

Prepared for:

Chicago Public Schools
125 S. Clark Street
Chicago, IL 60603

Prepared by:

GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone (312) 733-6262

Fax (312) 733-5612

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: March 09, 2016

RE: Pritzker School, Unit 25871
2009 W. Schiller Street
Chicago, IL, 60622

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2016 asbestos three year re-inspection has been completed at Pritzker School , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at Pritzker School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Robert Christlieb, the designated Local Education Authority's Designated Person at (773) 553-3197 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Pritzker School Unit: 25871 Region: 02
Address: 2009 W. Schiller Street Chicago, IL, 60622
IDPH ID: 14-016-2990-2510 Building ID: 6460
Contact: Marquez, Alexander Phone: 312-576-6449

2. Description of Facility

Original Construction: 1961 Additional Construction:
Total Square Footage: 66300 No of Floors: 3
Current Occupancy: 745

3. LEA Designated Person

Contact: Robert Christlieb Phone: (773) 553-3197
Address: 125 South Clark Street, 17th Floor
Chicago, IL 60603


4. Managing Environmental Consultant

MEC: GSG Consultants, Inc.
Contact: Arturo Saenz
Address 855 W. Adams St., Ste. 200
Phone: (312) 733-6262 Fax: (312) 733-5612

5. Inspector

Inspector Name: Michael Holvay


Inspector IDPH license # 100-07210


Michael Holvay
Project Manager
Signature:
Date: 3/9/2016

6. Management Planner

Management Planner Name: Arturo Saenz

Management Planner IDPH license # 100-04019


Signature:
Date: 04/01/2016

7. Review Date: 04/01/2016

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature: 

Date: 5/4/2016

Name: Robert Christlieb

II. EXECUTIVE SUMMARY

GSG Consultants, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Pritzker School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 6460:

B. The following new homogenous areas have been identified for Building 6460:

36	12x12 Pink Streaked VFT
37	12x12 Pink Streaked Mastic
38	Dry Wall Soffit
39	Black Painted Accoustic Ceiling
40	2x2 White Ceiling Tile
41	Unfinished Drywall Ceiling
42	Drywall above Ceiling tiles
43	Black tar-like Fireproofing

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

01	Plaster
03	1'x1' White Grooved Ceiling Tile
05	12"x12" Off-white floor tile
12	12"x12" Tan Floor Tile (Not Observed)
13	12"x12" Tan Floor Tile Mastic (Not Observed)
20	Exterior Window Caulk
21	12" x 12" Green with Dark Streaks Floor Tile
21 A	12" x 12" Green with Dark Streaks Floor Tile Mastic
22	12" x 12" Blue Gray Floor Tile
22 A	12" x 12" Blue Gray Floor Tile Mastic
23	Spray Applied Acoustical Plaster (Patch)
24	Carpet Adhesive
25	Green with Dark Green Streaks Floor Tile
25A	Green with Dark Green Streaks Floor Tile Mastic
26	Lab Table Tops
27	12 x 12 White and Blue Floor Tile
27A	12 x 12 White and Blue Floor Tile Mastic
28	12 x 12 Green Streaked Floor Tile
28A	12 x 12 Green Streaked Floor Tile Mastic
29	Terrazzo
30	12x12 Grey w/White and Dark Grey Floor Tile
30A	12x12 Grey w/White and Dark Grey Floor Tile Mastic
31	Fume Hood Lining
32	12x12 Light Blue w/ Blue specs VFT
33	12x12 Light Blue w/ blue specs VFT Mastic
34	12x12 Light Gray w/ Gray Specks VFT
35	12x12 Light Gray w/ Gray specks VFT Mastic
36	12x12 Pink Streaked VFT
37	12x12 Pink Streaked Mastic
38	Dry Wall Soffit
39	Black Painted Accoustic Ceiling
40	2x2 White Ceiling Tile
41	Unfinished Drywall Ceiling
42	Drywall above Ceiling tiles
43	Black tar-like Fireproofing
A	Boiler Lag (Not Observed)
G	Storage Tank Insulation (Not Observed)
H	12 x 12 inch Tan with Specks
I	12 x 12 inch Tan with Specks Mastic
J	12 x 12 inch Light Blue with Dark Blue Streaks

	Floor Tile
K	12 x 12 inch Lt Blue w/ Dk Blue Strks Floor Tile Mastic
L	Grey Speck Carpet Mastic

The following areas were deemed to be inaccessible:

21 A	12" x 12" Green with Dark Streaks Floor Tile Mastic
24	Carpet Adhesive
25A	Green with Dark Green Streaks Floor Tile Mastic
27A	12 x 12 White and Blue Floor Tile Mastic
28A	12 x 12 Green Streaked Floor Tile Mastic
30A	12x12 Grey w/White and Dark Grey Floor Tile Mastic

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Michael Holvay, IDPH License # 100-07210. The Management Plan was updated by Arturo Saenz, IDPH License # 100-04019. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Pritzker School Building 6460 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Pritzker School Unit 25871 Building ID 6460

Address 2009 W. Schiller Street Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
01	Plaster	80,000	SF	Throughout	ASSUMED	SURFACE	N	NONE	0		No	ACBM with the potential for damage		MODERATE
02	Acoustic Spray-on	15,065	SF	1st, 2nd & 3rd Floors, Breezeway Hallway	CHR	SURFACE	Y	NONE	0		No	ACBM with the potential for damage		LOW
03	1'x1' White Grooved Ceiling Tile	50,000	SF	Throughout	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
04	9"x9" Sand Floor Tile	150	SF	Engineers Office	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
05	12"x12" Off-white floor tile	8,530	SF	Lunch Room, Room 304, Room 117, Room 112	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
06	9"x9" Sand Floor Tile Mastic	150	SF	Engineer's Office	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
07	12"x12" Off-white Floor Tile Mastic	8,530	SF	Lunch Room, Rm 304, Room 117, Room 112	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
08	9"x9" Brown Floor Tile	3,820	SF	Room 301, 203, Library, Library Office, MDF Room	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
09	9"x9" Brown Floor Tile Mastic	3,820	SF	Room 301, 203, Library Office, MDF Room	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
10	9"x9" Orange Floor Tile (ABATED)			1st, 2nd, 3rd Fl Corridor	ABATED	MISC								
11	9"x9" Orange Floor Tile Mastic (ABATED)			1st, 2nd, 3rd Fl Corridor	ABATED	MISC								
12	12"x12" Tan Floor Tile (Not Observed)			1st Floor Corridor	ASSUMED						No			
13	12"x12" Tan Floor Tile Mastic (Not Observed)			1st Floor Corridor	ASSUMED						No			
14	9"x9" Grey Floor Tile	780	SF	Teachers Lounge, Office Hallway	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
15	9"x9" Grey Floor Tile Mastic	780	SF	Teachers Lounge, Office Hallway	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
16	9"x9" Dark Brown Floor Tile	11,550	SF	Rooms 101-109, 111, 201-204, 206, 207, 209, 301, 302, 306,308, 309, and 2nd Floor Storage Room	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
17	9"x9" Dark Brown Floor Tile Mastic	11,550	SF	Rooms 101-109, 111, 201-204, 206, 207, 209, 301, 302, 306,308, 309, and	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Pritzker School Unit 25871 Building ID 6460

Address 2009 W. Schiller Street Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				2nd Floor Storage Room										
18	9"x9" Beige Floor Tile (NOT OBSERVED)	50	SF	Corridor by Room 104, Breezeway	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
19	9"x9" Beige Floor Tile Mastic (NOT OBSERVED)	80	SF	Corridor by Room 104, Breezeway	CHR	MISC	N	None	0		No	ACBM with the potential for damage		LOW
20	Exterior Window Caulk	2,000	LF	Throughout	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
21	12" x 12" Green with Dark Streaks Floor Tile	800	SF	Room 307	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
21 A	12" x 12" Green with Dark Streaks Floor Tile Mastic	800	SF	Room 307	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
22	12" x 12" Blue Gray Floor Tile	150	SF	Libraray Office and Closet	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
22 A	12" x 12" Blue Gray Floor Tile Mastic	150	SF	Libraray Office and Closet	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
23	Spray Applied Acoustical Plaster (Patch)	15,000	SF	1st, 2nd & 3rd Floors, Breezeway Hallway	ASSUMED	SURFACE	Y	NONE	0		No	ACBM with the potential for damage		MODERATE
24	Carpet Adhesive	4,272	SF	Rooms 110, 113, 115, 205 (Library), Nurse's Office, and Office Hall	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
25	Green with Dark Green Streaks Floor Tile	99	SF	Vault, Store Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
25A	Green with Dark Green Streaks Floor Tile Mastic	99	SF	Vault, Store Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
26	Lab Table Tops	248	SF	Science Room (Room 302)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
27	12 x 12 White and Blue Floor Tile	2,340	SF	Rooms 208, 302 and 306	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
27A	12 x 12 White and Blue Floor Tile Mastic	2,340	SF	Rooms 208, 302 and 306	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
28	12 x 12 Green Streaked Floor Tile	165	SF	2nd Floor Store Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
28A	12 x 12 Green Streaked Floor Tile Mastic	165	SF	2nd Floor Store Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
29	Terrazzo	1,500	SF	All Entries	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
30	12x12 Grey w/White and Dark Grey Floor Tile	3,300	SF	Auditorium	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
30A	12x12 Grey w/White and Dark Grey Floor Tile Mastic	3,300	SF	Auditorium	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
31	Fume Hood Lining	60	SF	Science Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the		LOW

Chicago Public Schools

School Pritzker School Unit 25871 Building ID 6460

Address 2009 W. Schiller Street Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				(Room 302)								potential for damage		
32	12x12 Light Blue w/ Blue specs VFT	1,200	SF	auditorium	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		MODERATE
33	12x12 Light Blue w/ blue specs VFT Mastic	1,200	SF	auditorium	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
34	12x12 Light Gray w/ Gray Specks VFT	900	SF	Main office, principals office, conference room in office, Foyer outside auditorium	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
35	12x12 Light Gray w/ Gray specks VFT Mastic	900	SF	Main office, principals office, conference room in office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
36	12x12 Pink Streaked VFT	2,240	SF	1st, 2nd, 3rd Floor Classrooms under the Univents	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
37	12x12 Pink Streaked Mastic	2,240	SF	1st, 2nd, 3rd Floor Classrooms Under the Univents	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
38	Dry Wall Soffit	120	SF	Rooms 101 and 108	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
39	Black Painted Accoustic Ceiling	3,250	SF	Auditorium	ASSUMED	SURFACE	Y	DIST	50		No	Damaged friable surfacing ACBM	2	LOW
40	2x2 White Ceiling Tile	560	SF	1st Floor faculty Lounge	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		MODERATE
41	Unfinished Drywall Ceiling	2,000	SF	Mezzanine above First Floor Corridor	ASSUMED	MISC	N	DIST	20		No	ACBM with the potential for damage	5	MODERATE
42	Drywall above Ceiling tiles	20,000	SF	Above ceiling tiles in classrooms	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
43	Black tar-like Fireproofing	20,000	SF	Above ceiling tile in classrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
A	Boiler Lag (Not Observed)			Boiler Room	ASSUMED						No			
B	Water Tank Insulation (NOT OBSERVED)	120	SF	Boiler Room	CHR	TSI	Y	NONE			No			
E	MJP on Fiberglass Pipe Insulation (NOT OBSERVED)	192	LF	Boiler Room, Crawl Space, First Floor Storage Room Next To Office, Gym Storage Room on Second Level	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		MODERATE
G	Storage Tank Insulation (Not Observed)			Boiler Room	ASSUMED						No			
H	12 x 12 inch Tan with Specks	1,600	SF	303, 305, 112A	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
I	12 x 12 inch Tan with Specks Mastic	1,600	SF	room 303 & 305,	ASSUMED	MISC	N	NONE	0		No	ACBM with the		LOW

Chicago Public Schools

School Pritzker School Unit 25871 Building ID 6460

Address 2009 W. Schiller Street Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				112A								potential for damage		
J	12 x 12 inch Light Blue with Dark Blue Streaks Floor Tile	8,640	SF	1st, 2nd, and 3rd Floor Corridors and Stairwells	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
K	12 x 12 inch Lt Blue w/ Dk Blue Strks Floor Tile Mastic	8,640	SF	1st, 2nd & 3rd floor Corridors and Stairwells	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
L	Grey Speck Carpet Mastic	1,824	SF	Engineer's Office, 2nd Floor Faculty Lounge(rm 200), Library	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Pritzker School Unit 25871 Building ID 6460

Address 2009 W. Schiller Street Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

Inspector's Comments are Summarized at the End of the Report

Reinspection Date 3/9/2016
Inspector Name <u>Michael Holvay</u>
100-07210 1/18/2017
Inspector's IDPH License Number / Expiration Date

Inspector's Comments

HA Number:	Inspector Comments:
01	
02	
03	
04	
05	
06	
07	
08	
09	
10	
11	
12	
13	
14	
15	
16	
17	
18	
19	
20	
21	
21 A	
22	
22 A	

Chicago Public Schools

School Pritzker School Unit 25871 Building ID 6460

Address 2009 W. Schiller Street Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
23	
24	
25	
25A	
26	
27	
27A	
28	
28A	
29	
30	
30A	
31	
32	
33	
34	
35	
36	
37	
38	
39	
40	
41	
42	
43	
A	
B	Not Observed
E	Boiler Room & 2nd fl gym storage room not Observed
G	

Chicago Public Schools

School Pritzker School **Unit** 25871 **Building ID** 6460

Address 2009 W. Schiller Street **Region** 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
H	
I	
J	
K	
L	

Table II

Management Planner's Review

Chicago Public Schools

School Pritzker School
Address 2009 W. Schiller Street

Unit 25871
 Chicago, IL, 60622

Building ID 6460
Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
01	Plaster	80,000	SF	Throughout	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
02	Acoustic Spray-on	15,065	SF	1st, 2nd & 3rd Floors, Breezeway Hallway	Chrysotile	SURFACE	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
03	1'x1' White Grooved Ceiling Tile	50,000	SF	Throughout	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
04	9"x9" Sand Floor Tile	150	SF	Engineers Office	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
05	12"x12" Off-white floor tile	8,530	SF	Lunch Room, Room 304, Room 117, Room 112	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
06	9"x9" Sand Floor Tile Mastic	150	SF	Engineer's Office	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
07	12"x12" Off-white Floor Tile Mastic	8,530	SF	Lunch Room, Rm 304, Room 117, Room 112	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
08	9"x9" Brown Floor Tile	3,820	SF	Room 301, 203, Library, Library Office, MDF Room	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
09	9"x9" Brown Floor Tile Mastic	3,820	SF	Room 301, 203, Library Office, MDF Room	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
10	9"x9" Orange Floor Tile (ABATED)			1st, 2nd, 3rd Fl Corridor	Abated	MISC					
11	9"x9" Orange Floor Tile Mastic (ABATED)			1st, 2nd, 3rd Fl Corridor	Abated	MISC					
12	12"x12" Tan Floor Tile (Not Observed)			1st Floor Corridor	Assumed						
13	12"x12" Tan Floor Tile Mastic (Not Observed)			1st Floor Corridor	Assumed						
14	9"x9" Grey Floor Tile	780	SF	Teachers Lounge, Office Hallway	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
15	9"x9" Grey Floor Tile Mastic	780	SF	Teachers Lounge, Office Hallway	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
16	9"x9" Dark Brown Floor Tile	11,550	SF	Rooms 101-109, 111, 201-204, 206, 207, 209, 301, 302, 306,308, 309, and 2nd Floor Storage Room	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
17	9"x9" Dark Brown Floor Tile Mastic	11,550	SF	Rooms 101-109, 111, 201-204, 206, 207, 209, 301, 302, 306,308, 309, and 2nd Floor Storage Room	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
18	9"x9" Beige Floor Tile (NOT OBSERVED)	50	SF	Corridor by Room 104, Breezeway	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	
19	9"x9" Beige Floor Tile Mastic (NOT OBSERVED)	80	SF	Corridor by Room 104, Breezeway	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	
20	Exterior Window Caulk	2,000	LF	Throughout	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
21	12" x 12" Green with Dark Streaks Floor Tile	800	SF	Room 307	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
21 A	12" x 12" Green with Dark Streaks Floor Tile Mastic	800	SF	Room 307	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
22	12" x 12" Blue Gray Floor Tile	150	SF	Libraray Office and Closet	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
22 A	12" x 12" Blue Gray Floor Tile Mastic	150	SF	Libraray Office and Closet	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
23	Spray Applied Acoustical Plaster (Patch)	15,000	SF	1st, 2nd & 3rd Floors, Breezeway Hallway	Assumed	SURFACE	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Pritzker School
Address 2009 W. Schiller Street

Unit 25871
Chicago, IL, 60622

Building ID 6460
Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
24	Carpet Adhesive	4,272	SF	Rooms 110, 113, 115, 205 (Library), Nurse's Office, and Office Hall	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
25	Green with Dark Green Streaks Floor Tile	99	SF	Vault, Store Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
25A	Green with Dark Green Streaks Floor Tile Mastic	99	SF	Vault, Store Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
26	Lab Table Tops	248	SF	Science Room (Room 302)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
27	12 x 12 White and Blue Floor Tile	2,340	SF	Rooms 208, 302 and 306	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
27A	12 x 12 White and Blue Floor Tile Mastic	2,340	SF	Rooms 208, 302 and 306	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
28	12 x 12 Green Streaked Floor Tile	165	SF	2nd Floor Store Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
28A	12 x 12 Green Streaked Floor Tile Mastic	165	SF	2nd Floor Store Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
29	Terrazzo	1,500	SF	All Entries	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
30	12x12 Grey w/White and Dark Grey Floor Tile	3,300	SF	Auditorium	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
30A	12x12 Grey w/White and Dark Grey Floor Tile Mastic	3,300	SF	Auditorium	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
31	Fume Hood Lining	60	SF	Science Room (Room 302)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
32	12x12 Light Blue w/ Blue specs VFT	1,200	SF	auditorium	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
33	12x12 Light Blue w/ blue specs VFT Mastic	1,200	SF	auditorium	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
34	12x12 Light Gray w/ Gray Specks VFT	900	SF	Main office, principals office, conference room in office, Foyer outside auditorium	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
35	12x12 Light Gray w/ Gray specks VFT Mastic	900	SF	Main office, principals office, conference room in office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
36	12x12 Pink Streaked VFT	2,240	SF	1st, 2nd, 3rd Floor Classrooms under the Univents	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
37	12x12 Pink Streaked Mastic	2,240	SF	1st, 2nd, 3rd Floor Classrooms Under the Univents	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
38	Dry Wall Soffit	120	SF	Rooms 101 and 108	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
39	Black Painted Accoustic Ceiling	3,250	SF	Auditorium	Assumed	SURFACE	Yes	50	SF	2 Damaged friable surfacing ACBM	Repair
40	2x2 White Ceiling Tile	560	SF	1st Floor faculty Lounge	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
41	Unfinished Drywall Ceiling	2,000	SF	Mezzanine above First Floor Corridor	Assumed	MISC	No	20	SF	6 ACBM with the potential for damage	Repair
42	Drywall above Ceiling tiles	20,000	SF	Above ceiling tiles in classrooms	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
43	Black tar-like Fireproofing	20,000	SF	Above ceiling tile in classrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
A	Boiler Lag (Not Observed)			Boiler Room	Assumed						
B	Water Tank Insulation (NOT OBSERVED)	120	SF	Boiler Room	Chrysotile	TSI	Yes		SF		
E	MJP on Fiberglass Pipe Insulation (NOT OBSERVED)	192	LF	Boiler Room, Crawl Space, First Floor Storage Room Next To Office, Gym	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	

Chicago Public Schools

School Pritzker School
Address 2009 W. Schiller Street

Unit 25871
 Chicago, IL, 60622

Building ID 6460
Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				Storage Room on Second Level							
G	Storage Tank Insulation (Not Observed)			Boiler Room	Assumed						
H	12 x 12 inch Tan with Specks	1,600	SF	303, 305, 112A	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
I	12 x 12 inch Tan with Specks Mastic	1,600	SF	room 303 & 305, 112A	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
J	12 x 12 inch Light Blue with Dark Blue Streaks Floor Tile	8,640	SF	1st, 2nd, and 3rd Floor Corridors and Stairwells	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
K	12 x 12 inch Lt Blue w/ Dk Blue Strks Floor Tile Mastic	8,640	SF	1st, 2nd & 3rd floor Corridors and Stairwells	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
L	Grey Speck Carpet Mastic	1,824	SF	Engineer's Office, 2nd Floor Faculty Lounge(rm 200), Library	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Pritzker School
Address 2009 W. Schiller Street

Unit 25871
 Chicago, IL, 60622

Building ID 6460
Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

Management Planner's Comments Summarized at the End of the Report

Review Date	4/1/2016
Manager Planner Name	Arturo Saenz
100-04019	1/19/2017
Manager IDPH License No/Expiration	

HA Number	Management Comments
01	
02	
03	
04	
05	
06	
07	
08	
09	
10	
11	
12	
13	
14	
15	
16	
17	
18	
19	
20	
21	
21 A	
22	
22 A	
23	
24	

Chicago Public Schools

School Pritzker School
Address 2009 W. Schiller Street

Unit 25871
 Chicago, IL, 60622

Building ID 6460
Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
25	
25A	
26	
27	
27A	
28	
28A	
29	
30	
30A	
31	
32	
33	
34	
35	
36	
37	
38	
39	
40	
41	
42	
43	
A	
B	
E	
G	

Chicago Public Schools

School Pritzker School
Address 2009 W. Schiller Street

Unit 25871
Chicago, IL, 60622

Building ID 6460
Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
H	
I	
J	
K	
L	

Chicago Public Schools

GSG Consultants, Inc.

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25871** BUIDLING ID: **6460**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Pritzker School** INSPECTION DATE: **3/9/2016**
ADDRESS: **2009 W. Schiller Street** IDPH LICENSE NO: **100-07210**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **01**
MATERIAL DESCRIPTION: **Plaster**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Throughout**
MATERIAL QUANTITY: **80000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25871** BUIDLING ID: **6460**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Pritzker School** REVIEW DATE: **4/1/2016**
ADDRESS: **2009 W. Schiller Street** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **01**
MATERIAL DESCRIPTION: **Plaster**
MATERIAL LOCATION: **Throughout**
MATERIAL QUANTITY: **80000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/01/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25871** BUIDLING ID: **6460**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Pritzker School** INSPECTION DATE: **3/9/2016**
ADDRESS: **2009 W. Schiller Street** IDPH LICENSE NO: **100-07210**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **02**
MATERIAL DESCRIPTION: **Acoustic Spray-on**
HISTORICAL AHERA DAMAGE CATEGORY **6 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st, 2nd & 3rd Floors, Breezeway Hallway**
MATERIAL QUANTITY: **15065** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25871** BUIDLING ID: **6460**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Pritzker School** REVIEW DATE: **4/1/2016**
ADDRESS: **2009 W. Schiller Street** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **02**
MATERIAL DESCRIPTION: **Acoustic Spray-on**
MATERIAL LOCATION: **1st, 2nd & 3rd Floors, Breezeway Hallway**
MATERIAL QUANTITY: **15065** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/01/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25871** BUIDLING ID: **6460**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Pritzker School** INSPECTION DATE: **3/9/2016**
ADDRESS: **2009 W. Schiller Street** IDPH LICENSE NO: **100-07210**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **03**
MATERIAL DESCRIPTION: **1'x1' White Grooved Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout**
MATERIAL QUANTITY: **50000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25871** BUIDLING ID: **6460**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Pritzker School** REVIEW DATE: **4/1/2016**
ADDRESS: **2009 W. Schiller Street** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **03**
MATERIAL DESCRIPTION: **1'x1' White Grooved Ceiling Tile**
MATERIAL LOCATION: **Throughout**
MATERIAL QUANTITY: **50000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/01/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25871** BUIDLING ID: **6460**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Pritzker School** INSPECTION DATE: **3/9/2016**
ADDRESS: **2009 W. Schiller Street** IDPH LICENSE NO: **100-07210**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **04**
MATERIAL DESCRIPTION: **9"x9" Sand Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Engineers Office**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25871** BUILDING ID: **6460**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Pritzker School** REVIEW DATE: **4/1/2016**
ADDRESS: **2009 W. Schiller Street** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **04**
MATERIAL DESCRIPTION: **9"x9" Sand Floor Tile**
MATERIAL LOCATION: **Engineers Office**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/01/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25871** BUIDLING ID: **6460**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Pritzker School** INSPECTION DATE: **3/9/2016**
ADDRESS: **2009 W. Schiller Street** IDPH LICENSE NO: **100-07210**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **05**
MATERIAL DESCRIPTION: **12"x12" Off-white floor tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Lunch Room, Room 304, Room 117, Room 112**
MATERIAL QUANTITY: **8530** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25871** BUILDING ID: **6460**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Pritzker School** REVIEW DATE: **4/1/2016**
ADDRESS: **2009 W. Schiller Street** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **05**
MATERIAL DESCRIPTION: **12"x12" Off-white floor tile**
MATERIAL LOCATION: **Lunch Room, Room 304, Room 117, Room 112**
MATERIAL QUANTITY: **8530** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/01/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25871** BUIDLING ID: **6460**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Pritzker School** INSPECTION DATE: **3/9/2016**
ADDRESS: **2009 W. Schiller Street** IDPH LICENSE NO: **100-07210**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **06**
MATERIAL DESCRIPTION: **9"x9" Sand Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Engineer's Office**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25871** BUILDING ID: **6460**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Pritzker School** REVIEW DATE: **4/1/2016**
ADDRESS: **2009 W. Schiller Street** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **06**
MATERIAL DESCRIPTION: **9"x9" Sand Floor Tile Mastic**
MATERIAL LOCATION: **Engineer's Office**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/01/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25871** BUIDLING ID: **6460**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Pritzker School** INSPECTION DATE: **3/9/2016**
ADDRESS: **2009 W. Schiller Street** IDPH LICENSE NO: **100-07210**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **07**
MATERIAL DESCRIPTION: **12"x12" Off-white Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Lunch Room, Rm 304, Room 117, Room 112**
MATERIAL QUANTITY: **8530** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25871** BUILDING ID: **6460**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Pritzker School** REVIEW DATE: **4/1/2016**
ADDRESS: **2009 W. Schiller Street** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **07**
MATERIAL DESCRIPTION: **12"x12" Off-white Floor Tile Mastic**
MATERIAL LOCATION: **Lunch Room, Rm 304, Room 117, Room 112**
MATERIAL QUANTITY: **8530** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/01/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25871** BUIDLING ID: **6460**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Pritzker School** INSPECTION DATE: **3/9/2016**
ADDRESS: **2009 W. Schiller Street** IDPH LICENSE NO: **100-07210**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **08**
MATERIAL DESCRIPTION: **9"x9" Brown Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Room 301, 203, Library, Library Office, MDF Room**
MATERIAL QUANTITY: **3820** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25871** BUILDING ID: **6460**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Pritzker School** REVIEW DATE: **4/1/2016**
ADDRESS: **2009 W. Schiller Street** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **08**
MATERIAL DESCRIPTION: **9"x9" Brown Floor Tile**
MATERIAL LOCATION: **Room 301, 203, Library, Library Office, MDF Room**
MATERIAL QUANTITY: **3820** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/01/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25871** BUIDLING ID: **6460**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Pritzker School** INSPECTION DATE: **3/9/2016**
ADDRESS: **2009 W. Schiller Street** IDPH LICENSE NO: **100-07210**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **09**
MATERIAL DESCRIPTION: **9"x9" Brown Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 301, 203, Library Office, MDF Room**
MATERIAL QUANTITY: **3820** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25871** BUILDING ID: **6460**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Pritzker School** REVIEW DATE: **4/1/2016**
ADDRESS: **2009 W. Schiller Street** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **09**
MATERIAL DESCRIPTION: **9"x9" Brown Floor Tile Mastic**
MATERIAL LOCATION: **Room 301, 203, Library Office, MDF Room**
MATERIAL QUANTITY: **3820** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/01/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25871** BUIDLING ID: **6460**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Pritzker School** INSPECTION DATE: **3/9/2016**
ADDRESS: **2009 W. Schiller Street** IDPH LICENSE NO: **100-07210**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10**
MATERIAL DESCRIPTION: **9"x9" Orange Floor Tile (ABATED)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st, 2nd, 3rd FI Corridor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25871** BUILDING ID: **6460**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Pritzker School** REVIEW DATE: **4/1/2016**
ADDRESS: **2009 W. Schiller Street** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **10**

MATERIAL DESCRIPTION: **9"x9" Orange Floor Tile (ABATED)**

MATERIAL LOCATION: **1st, 2nd, 3rd FI Corridor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/01/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25871** BUIDLING ID: **6460**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Pritzker School** INSPECTION DATE: **3/9/2016**
ADDRESS: **2009 W. Schiller Street** IDPH LICENSE NO: **100-07210**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11**
MATERIAL DESCRIPTION: **9"x9" Orange Floor Tile Mastic (ABATED)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st, 2nd, 3rd FI Corridor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25871** BUILDING ID: **6460**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Pritzker School** REVIEW DATE: **4/1/2016**
ADDRESS: **2009 W. Schiller Street** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **11**
MATERIAL DESCRIPTION: **9"x9" Orange Floor Tile Mastic (ABATED)**
MATERIAL LOCATION: **1st, 2nd, 3rd FI Corridor**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/01/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25871** BUIDLING ID: **6460**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Pritzker School** INSPECTION DATE: **3/9/2016**
ADDRESS: **2009 W. Schiller Street** IDPH LICENSE NO: **100-07210**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12**
MATERIAL DESCRIPTION: **12"x12" Tan Floor Tile (Not Observed)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st Floor Corridor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25871** BUILDING ID: **6460**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Pritzker School** REVIEW DATE: **4/1/2016**
ADDRESS: **2009 W. Schiller Street** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **12**

MATERIAL DESCRIPTION: **12"x12" Tan Floor Tile (Not Observed)**

MATERIAL LOCATION: **1st Floor Corridor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/01/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25871** BUIDLING ID: **6460**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Pritzker School** INSPECTION DATE: **3/9/2016**
ADDRESS: **2009 W. Schiller Street** IDPH LICENSE NO: **100-07210**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13**
MATERIAL DESCRIPTION: **12"x12" Tan Floor Tile Mastic (Not Observed)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st Floor Corridor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25871** BUIDLING ID: **6460**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Pritzker School** REVIEW DATE: **4/1/2016**
ADDRESS: **2009 W. Schiller Street** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **13**
MATERIAL DESCRIPTION: **12"x12" Tan Floor Tile Mastic (Not Observed)**
MATERIAL LOCATION: **1st Floor Corridor**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/01/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25871** BUIDLING ID: **6460**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Pritzker School** INSPECTION DATE: **3/9/2016**
ADDRESS: **2009 W. Schiller Street** IDPH LICENSE NO: **100-07210**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14**
MATERIAL DESCRIPTION: **9"x9" Grey Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Teachers Lounge, Office Hallway**
MATERIAL QUANTITY: **780** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25871** BUIDLING ID: **6460**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Pritzker School** REVIEW DATE: **4/1/2016**
ADDRESS: **2009 W. Schiller Street** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **14**
MATERIAL DESCRIPTION: **9"x9" Grey Floor Tile**
MATERIAL LOCATION: **Teachers Lounge, Office Hallway**
MATERIAL QUANTITY: **780** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/01/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25871** BUIDLING ID: **6460**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Pritzker School** INSPECTION DATE: **3/9/2016**
ADDRESS: **2009 W. Schiller Street** IDPH LICENSE NO: **100-07210**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15**
MATERIAL DESCRIPTION: **9"x9" Grey Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Teachers Lounge, Office Hallway**
MATERIAL QUANTITY: **780** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25871** BUIDLING ID: **6460**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Pritzker School** REVIEW DATE: **4/1/2016**
ADDRESS: **2009 W. Schiller Street** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **15**
MATERIAL DESCRIPTION: **9"x9" Grey Floor Tile Mastic**
MATERIAL LOCATION: **Teachers Lounge, Office Hallway**
MATERIAL QUANTITY: **780** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/01/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25871** BUIDLING ID: **6460**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Pritzker School** INSPECTION DATE: **3/9/2016**
ADDRESS: **2009 W. Schiller Street** IDPH LICENSE NO: **100-07210**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16**
MATERIAL DESCRIPTION: **9"x9" Dark Brown Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Rooms 101-109, 111, 201-204, 206, 207, 209, 301, 302, 306,308, 309, and 2nd Floor Storage Room**

MATERIAL QUANTITY: **11550**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25871** BUIDLING ID: **6460**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Pritzker School** REVIEW DATE: **4/1/2016**
ADDRESS: **2009 W. Schiller Street** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **16**
MATERIAL DESCRIPTION: **9"x9" Dark Brown Floor Tile**
MATERIAL LOCATION: **Rooms 101-109, 111, 201-204, 206, 207, 209, 301, 302, 306,308, 309, and 2nd Floor Storage Room**
MATERIAL QUANTITY: **11550** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/01/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25871** BUIDLING ID: **6460**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Pritzker School** INSPECTION DATE: **3/9/2016**
ADDRESS: **2009 W. Schiller Street** IDPH LICENSE NO: **100-07210**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17**
MATERIAL DESCRIPTION: **9"x9" Dark Brown Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 101-109, 111, 201-204, 206, 207, 209, 301, 302, 306,308, 309, and 2nd Floor Storage Room**

MATERIAL QUANTITY: **11550**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25871** BUILDING ID: **6460**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Pritzker School** REVIEW DATE: **4/1/2016**
ADDRESS: **2009 W. Schiller Street** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **17**
MATERIAL DESCRIPTION: **9"x9" Dark Brown Floor Tile Mastic**
MATERIAL LOCATION: **Rooms 101-109, 111, 201-204, 206, 207, 209, 301, 302, 306,308, 309, and 2nd Floor Storage Room**
MATERIAL QUANTITY: **11550** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/01/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25871** BUIDLING ID: **6460**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Pritzker School** INSPECTION DATE: **3/9/2016**
ADDRESS: **2009 W. Schiller Street** IDPH LICENSE NO: **100-07210**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18**
MATERIAL DESCRIPTION: **9"x9" Beige Floor Tile (NOT OBSERVED)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Corridor by Room 104, Breezeway**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25871** BUILDING ID: **6460**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Pritzker School** REVIEW DATE: **4/1/2016**
ADDRESS: **2009 W. Schiller Street** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **18**
MATERIAL DESCRIPTION: **9"x9" Beige Floor Tile (NOT OBSERVED)**
MATERIAL LOCATION: **Corridor by Room 104, Breezeway**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/01/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25871** BUIDLING ID: **6460**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Pritzker School** INSPECTION DATE: **3/9/2016**
ADDRESS: **2009 W. Schiller Street** IDPH LICENSE NO: **100-07210**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19**
MATERIAL DESCRIPTION: **9"x9" Beige Floor Tile Mastic (NOT OBSERVED)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Corridor by Room 104, Breezeway**
MATERIAL QUANTITY: **80** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25871** BUILDING ID: **6460**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Pritzker School** REVIEW DATE: **4/1/2016**
ADDRESS: **2009 W. Schiller Street** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **19**
MATERIAL DESCRIPTION: **9"x9" Beige Floor Tile Mastic (NOT OBSERVED)**
MATERIAL LOCATION: **Corridor by Room 104, Breezeway**
MATERIAL QUANTITY: **80** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/01/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25871** BUIDLING ID: **6460**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Pritzker School** INSPECTION DATE: **3/9/2016**
ADDRESS: **2009 W. Schiller Street** IDPH LICENSE NO: **100-07210**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**
MATERIAL DESCRIPTION: **Exterior Window Caulk**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Throughout**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25871** BUIDLING ID: **6460**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Pritzker School** REVIEW DATE: **4/1/2016**
ADDRESS: **2009 W. Schiller Street** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **20**
MATERIAL DESCRIPTION: **Exterior Window Caulk**
MATERIAL LOCATION: **Throughout**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/01/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25871** BUIDLING ID: **6460**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Pritzker School** INSPECTION DATE: **3/9/2016**
ADDRESS: **2009 W. Schiller Street** IDPH LICENSE NO: **100-07210**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21**
MATERIAL DESCRIPTION: **12" x 12" Green with Dark Streaks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Room 307**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25871** BUIDLING ID: **6460**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Pritzker School** REVIEW DATE: **4/1/2016**
ADDRESS: **2009 W. Schiller Street** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **21**
MATERIAL DESCRIPTION: **12" x 12" Green with Dark Streaks Floor Tile**
MATERIAL LOCATION: **Room 307**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/01/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25871** BUIDLING ID: **6460**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Pritzker School** INSPECTION DATE: **3/9/2016**
ADDRESS: **2009 W. Schiller Street** IDPH LICENSE NO: **100-07210**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21 A**
MATERIAL DESCRIPTION: **12" x 12" Green with Dark Streaks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 307**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25871** BUILDING ID: **6460**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Pritzker School** REVIEW DATE: **4/1/2016**
ADDRESS: **2009 W. Schiller Street** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **21 A**
MATERIAL DESCRIPTION: **12" x 12" Green with Dark Streaks Floor Tile Mastic**
MATERIAL LOCATION: **Room 307**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/01/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25871** BUIDLING ID: **6460**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Pritzker School** INSPECTION DATE: **3/9/2016**
ADDRESS: **2009 W. Schiller Street** IDPH LICENSE NO: **100-07210**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22**
MATERIAL DESCRIPTION: **12" x 12" Blue Gray Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Libraray Office and Closet**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25871** BUIDLING ID: **6460**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Pritzker School** REVIEW DATE: **4/1/2016**
ADDRESS: **2009 W. Schiller Street** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **22**
MATERIAL DESCRIPTION: **12" x 12" Blue Gray Floor Tile**
MATERIAL LOCATION: **Libraray Office and Closet**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/01/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25871** BUIDLING ID: **6460**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Pritzker School** INSPECTION DATE: **3/9/2016**
ADDRESS: **2009 W. Schiller Street** IDPH LICENSE NO: **100-07210**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22 A**
MATERIAL DESCRIPTION: **12" x 12" Blue Gray Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Libraray Office and Closet**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25871** BUIDLING ID: **6460**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Pritzker School** REVIEW DATE: **4/1/2016**
ADDRESS: **2009 W. Schiller Street** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **22 A**
MATERIAL DESCRIPTION: **12" x 12" Blue Gray Floor Tile Mastic**
MATERIAL LOCATION: **Libraray Office and Closet**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/01/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25871** BUIDLING ID: **6460**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Pritzker School** INSPECTION DATE: **3/9/2016**
ADDRESS: **2009 W. Schiller Street** IDPH LICENSE NO: **100-07210**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23**
MATERIAL DESCRIPTION: **Spray Applied Acoustical Plaster (Patch)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with potential for significant damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **1st, 2nd & 3rd Floors, Breezeway Hallway**
MATERIAL QUANTITY: **15000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25871** BUILDING ID: **6460**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Pritzker School** REVIEW DATE: **4/1/2016**
ADDRESS: **2009 W. Schiller Street** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **23**
MATERIAL DESCRIPTION: **Spray Applied Acoustical Plaster (Patch)**
MATERIAL LOCATION: **1st, 2nd & 3rd Floors, Breezeway Hallway**
MATERIAL QUANTITY: **15000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/01/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25871** BUIDLING ID: **6460**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Pritzker School** INSPECTION DATE: **3/9/2016**
ADDRESS: **2009 W. Schiller Street** IDPH LICENSE NO: **100-07210**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **24**
MATERIAL DESCRIPTION: **Carpet Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 110, 113, 115, 205 (Library), Nurse's Office, and Office Hall**
MATERIAL QUANTITY: **4272** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25871** BUILDING ID: **6460**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Pritzker School** REVIEW DATE: **4/1/2016**
ADDRESS: **2009 W. Schiller Street** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **24**
MATERIAL DESCRIPTION: **Carpet Adhesive**
MATERIAL LOCATION: **Rooms 110, 113, 115, 205 (Library), Nurse's Office, and Office Hall**
MATERIAL QUANTITY: **4272** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/01/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25871** BUIDLING ID: **6460**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Pritzker School** INSPECTION DATE: **3/9/2016**
ADDRESS: **2009 W. Schiller Street** IDPH LICENSE NO: **100-07210**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25**
MATERIAL DESCRIPTION: **Green with Dark Green Streaks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Vault, Store Room**
MATERIAL QUANTITY: **99** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25871** BUIDLING ID: **6460**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Pritzker School** REVIEW DATE: **4/1/2016**
ADDRESS: **2009 W. Schiller Street** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **25**
MATERIAL DESCRIPTION: **Green with Dark Green Streaks Floor Tile**
MATERIAL LOCATION: **Vault, Store Room**
MATERIAL QUANTITY: **99** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/01/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25871** BUIDLING ID: **6460**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Pritzker School** INSPECTION DATE: **3/9/2016**
ADDRESS: **2009 W. Schiller Street** IDPH LICENSE NO: **100-07210**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25A**
MATERIAL DESCRIPTION: **Green with Dark Green Streaks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Vault, Store Room**
MATERIAL QUANTITY: **99** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25871** BUILDING ID: **6460**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Pritzker School** REVIEW DATE: **4/1/2016**
ADDRESS: **2009 W. Schiller Street** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **25A**
MATERIAL DESCRIPTION: **Green with Dark Green Streaks Floor Tile Mastic**
MATERIAL LOCATION: **Vault, Store Room**
MATERIAL QUANTITY: **99** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/01/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25871** BUIDLING ID: **6460**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Pritzker School** INSPECTION DATE: **3/9/2016**
ADDRESS: **2009 W. Schiller Street** IDPH LICENSE NO: **100-07210**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26**
MATERIAL DESCRIPTION: **Lab Table Tops**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Science Room (Room 302)**
MATERIAL QUANTITY: **248** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25871** BUIDLING ID: **6460**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Pritzker School** REVIEW DATE: **4/1/2016**
ADDRESS: **2009 W. Schiller Street** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **26**
MATERIAL DESCRIPTION: **Lab Table Tops**
MATERIAL LOCATION: **Science Room (Room 302)**
MATERIAL QUANTITY: **248** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/01/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25871** BUIDLING ID: **6460**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Pritzker School** INSPECTION DATE: **3/9/2016**
ADDRESS: **2009 W. Schiller Street** IDPH LICENSE NO: **100-07210**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27**
MATERIAL DESCRIPTION: **12 x 12 White and Blue Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 208, 302 and 306**
MATERIAL QUANTITY: **2340** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25871** BUIDLING ID: **6460**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Pritzker School** REVIEW DATE: **4/1/2016**
ADDRESS: **2009 W. Schiller Street** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **27**
MATERIAL DESCRIPTION: **12 x 12 White and Blue Floor Tile**
MATERIAL LOCATION: **Rooms 208, 302 and 306**
MATERIAL QUANTITY: **2340** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/01/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25871** BUIDLING ID: **6460**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Pritzker School** INSPECTION DATE: **3/9/2016**
ADDRESS: **2009 W. Schiller Street** IDPH LICENSE NO: **100-07210**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27A**
MATERIAL DESCRIPTION: **12 x 12 White and Blue Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 208, 302 and 306**
MATERIAL QUANTITY: **2340** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25871** BUIDLING ID: **6460**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Pritzker School** REVIEW DATE: **4/1/2016**
ADDRESS: **2009 W. Schiller Street** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **27A**
MATERIAL DESCRIPTION: **12 x 12 White and Blue Floor Tile Mastic**
MATERIAL LOCATION: **Rooms 208, 302 and 306**
MATERIAL QUANTITY: **2340** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/01/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25871** BUIDLING ID: **6460**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Pritzker School** INSPECTION DATE: **3/9/2016**
ADDRESS: **2009 W. Schiller Street** IDPH LICENSE NO: **100-07210**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28**
MATERIAL DESCRIPTION: **12 x 12 Green Streaked Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **2nd Floor Store Room**
MATERIAL QUANTITY: **165** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25871** BUILDING ID: **6460**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Pritzker School** REVIEW DATE: **4/1/2016**
ADDRESS: **2009 W. Schiller Street** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **28**
MATERIAL DESCRIPTION: **12 x 12 Green Streaked Floor Tile**
MATERIAL LOCATION: **2nd Floor Store Room**
MATERIAL QUANTITY: **165** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/01/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25871** BUIDLING ID: **6460**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Pritzker School** INSPECTION DATE: **3/9/2016**
ADDRESS: **2009 W. Schiller Street** IDPH LICENSE NO: **100-07210**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28A**
MATERIAL DESCRIPTION: **12 x 12 Green Streaked Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **2nd Floor Store Room**
MATERIAL QUANTITY: **165** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25871** BUILDING ID: **6460**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Pritzker School** REVIEW DATE: **4/1/2016**
ADDRESS: **2009 W. Schiller Street** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **28A**
MATERIAL DESCRIPTION: **12 x 12 Green Streaked Floor Tile Mastic**
MATERIAL LOCATION: **2nd Floor Store Room**
MATERIAL QUANTITY: **165** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/01/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25871** BUIDLING ID: **6460**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Pritzker School** INSPECTION DATE: **3/9/2016**
ADDRESS: **2009 W. Schiller Street** IDPH LICENSE NO: **100-07210**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **29**
MATERIAL DESCRIPTION: **Terrazzo**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **All Entries**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25871** BUIDLING ID: **6460**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Pritzker School** REVIEW DATE: **4/1/2016**
ADDRESS: **2009 W. Schiller Street** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **29**
MATERIAL DESCRIPTION: **Terrazzo**
MATERIAL LOCATION: **All Entries**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/01/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25871** BUIDLING ID: **6460**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Pritzker School** INSPECTION DATE: **3/9/2016**
ADDRESS: **2009 W. Schiller Street** IDPH LICENSE NO: **100-07210**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **30**
MATERIAL DESCRIPTION: **12x12 Grey w/White and Dark Grey Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Auditorium**
MATERIAL QUANTITY: **3300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25871** BUIDLING ID: **6460**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Pritzker School** REVIEW DATE: **4/1/2016**
ADDRESS: **2009 W. Schiller Street** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **30**
MATERIAL DESCRIPTION: **12x12 Grey w/White and Dark Grey Floor Tile**
MATERIAL LOCATION: **Auditorium**
MATERIAL QUANTITY: **3300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/01/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25871** BUIDLING ID: **6460**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Pritzker School** INSPECTION DATE: **3/9/2016**
ADDRESS: **2009 W. Schiller Street** IDPH LICENSE NO: **100-07210**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **30A**
MATERIAL DESCRIPTION: **12x12 Grey w/White and Dark Grey Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Auditorium**
MATERIAL QUANTITY: **3300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25871** BUIDLING ID: **6460**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Pritzker School** REVIEW DATE: **4/1/2016**
ADDRESS: **2009 W. Schiller Street** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **30A**
MATERIAL DESCRIPTION: **12x12 Grey w/White and Dark Grey Floor Tile Mastic**
MATERIAL LOCATION: **Auditorium**
MATERIAL QUANTITY: **3300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/01/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25871** BUIDLING ID: **6460**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Pritzker School** INSPECTION DATE: **3/9/2016**
ADDRESS: **2009 W. Schiller Street** IDPH LICENSE NO: **100-07210**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **31**
MATERIAL DESCRIPTION: **Fume Hood Lining**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Science Room (Room 302)**
MATERIAL QUANTITY: **60** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25871** BUIDLING ID: **6460**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Pritzker School** REVIEW DATE: **4/1/2016**
ADDRESS: **2009 W. Schiller Street** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **31**
MATERIAL DESCRIPTION: **Fume Hood Lining**
MATERIAL LOCATION: **Science Room (Room 302)**
MATERIAL QUANTITY: **60** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/01/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25871** BUIDLING ID: **6460**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Pritzker School** INSPECTION DATE: **3/9/2016**
ADDRESS: **2009 W. Schiller Street** IDPH LICENSE NO: **100-07210**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **32**
MATERIAL DESCRIPTION: **12x12 Light Blue w/ Blue specs VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **auditorium**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25871** BUIDLING ID: **6460**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Pritzker School** REVIEW DATE: **4/1/2016**
ADDRESS: **2009 W. Schiller Street** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **32**
MATERIAL DESCRIPTION: **12x12 Light Blue w/ Blue specs VFT**
MATERIAL LOCATION: **auditorium**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/01/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25871** BUIDLING ID: **6460**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Pritzker School** INSPECTION DATE: **3/9/2016**
ADDRESS: **2009 W. Schiller Street** IDPH LICENSE NO: **100-07210**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **33**
MATERIAL DESCRIPTION: **12x12 Light Blue w/ blue specs VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **auditorium**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25871** BUIDLING ID: **6460**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Pritzker School** REVIEW DATE: **4/1/2016**
ADDRESS: **2009 W. Schiller Street** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **33**
MATERIAL DESCRIPTION: **12x12 Light Blue w/ blue specs VFT Mastic**
MATERIAL LOCATION: **auditorium**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/01/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25871** BUIDLING ID: **6460**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Pritzker School** INSPECTION DATE: **3/9/2016**
ADDRESS: **2009 W. Schiller Street** IDPH LICENSE NO: **100-07210**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **34**
MATERIAL DESCRIPTION: **12x12 Light Gray w/ Gray Specks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Main office, principals office, conference room in office, Foyer outside auditorium**

MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25871** BUILDING ID: **6460**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Pritzker School** REVIEW DATE: **4/1/2016**
ADDRESS: **2009 W. Schiller Street** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **34**
MATERIAL DESCRIPTION: **12x12 Light Gray w/ Gray Specks VFT**
MATERIAL LOCATION: **Main office, principals office, conference room in office, Foyer outside auditorium**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/01/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25871** BUIDLING ID: **6460**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Pritzker School** INSPECTION DATE: **3/9/2016**
ADDRESS: **2009 W. Schiller Street** IDPH LICENSE NO: **100-07210**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **35**
MATERIAL DESCRIPTION: **12x12 Light Gray w/ Gray specks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Main office, principals office, conference room in office**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25871** BUIDLING ID: **6460**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Pritzker School** REVIEW DATE: **4/1/2016**
ADDRESS: **2009 W. Schiller Street** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **35**
MATERIAL DESCRIPTION: **12x12 Light Gray w/ Gray specks VFT Mastic**
MATERIAL LOCATION: **Main office, principals office, conference room in office**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/01/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25871** BUIDLING ID: **6460**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Pritzker School** INSPECTION DATE: **3/9/2016**
ADDRESS: **2009 W. Schiller Street** IDPH LICENSE NO: **100-07210**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **A**
MATERIAL DESCRIPTION: **Boiler Lag (Not Observed)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25871** BUILDING ID: **6460**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Pritzker School** REVIEW DATE: **4/1/2016**
ADDRESS: **2009 W. Schiller Street** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **A**

MATERIAL DESCRIPTION: **Boiler Lag (Not Observed)**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/01/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25871** BUIDLING ID: **6460**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Pritzker School** INSPECTION DATE: **3/9/2016**
ADDRESS: **2009 W. Schiller Street** IDPH LICENSE NO: **100-07210**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **B**
MATERIAL DESCRIPTION: **Water Tank Insulation (NOT OBSERVED)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: **120**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Not Observed**

Inspector's Signature:


Michael Holvay
Project Manager

Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25871** BUIDLING ID: **6460**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Pritzker School** REVIEW DATE: **4/1/2016**
ADDRESS: **2009 W. Schiller Street** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **B**
MATERIAL DESCRIPTION: **Water Tank Insulation (NOT OBSERVED)**
MATERIAL LOCATION: **Boiler Room**
MATERIAL QUANTITY: **120** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/01/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25871** BUIDLING ID: **6460**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Pritzker School** INSPECTION DATE: **3/9/2016**
ADDRESS: **2009 W. Schiller Street** IDPH LICENSE NO: **100-07210**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **E**
MATERIAL DESCRIPTION: **MJP on Fiberglass Pipe Insulation (NOT OBSERVED)**
HISTORICAL AHERA DAMAGE CATEGORY **6 Damaged or significantly damaged friable thermal system insulating ACBM**
HISTORICAL DAMAGE REASON: **Deterioration**
HISTORICAL RESPONSE ACTION: **Repair**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Boiler Room, Crawl Space, First Floor Storage Room Next To Office, Gym Storage Room on Second Level**

MATERIAL QUANTITY: **192** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS: **Boiler Room & 2nd fl gym storage room not Observed**

Inspector's Signature:


Michael Holvay
Project Manager

Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25871** BUIDLING ID: **6460**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Pritzker School** REVIEW DATE: **4/1/2016**
ADDRESS: **2009 W. Schiller Street** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **E**
MATERIAL DESCRIPTION: **MJP on Fiberglass Pipe Insulation (NOT OBSERVED)**
MATERIAL LOCATION: **Boiler Room, Crawl Space, First Floor Storage Room Next To Office, Gym Storage Room on Second Level**
MATERIAL QUANTITY: **192** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Management Planner's Signature: _____



Date: **04/01/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25871** BUIDLING ID: **6460**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Pritzker School** INSPECTION DATE: **3/9/2016**
ADDRESS: **2009 W. Schiller Street** IDPH LICENSE NO: **100-07210**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **G**
MATERIAL DESCRIPTION: **Storage Tank Insulation (Not Observed)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25871** BUIDLING ID: **6460**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Pritzker School** REVIEW DATE: **4/1/2016**
ADDRESS: **2009 W. Schiller Street** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **G**

MATERIAL DESCRIPTION: **Storage Tank Insulation (Not Observed)**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/01/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25871** BUIDLING ID: **6460**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Pritzker School** INSPECTION DATE: **3/9/2016**
ADDRESS: **2009 W. Schiller Street** IDPH LICENSE NO: **100-07210**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **H**
MATERIAL DESCRIPTION: **12 x 12 inch Tan with Specks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **303, 305, 112A**
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25871** BUIDLING ID: **6460**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Pritzker School** REVIEW DATE: **4/1/2016**
ADDRESS: **2009 W. Schiller Street** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **H**
MATERIAL DESCRIPTION: **12 x 12 inch Tan with Specks**
MATERIAL LOCATION: **303, 305, 112A**
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/01/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25871** BUIDLING ID: **6460**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Pritzker School** INSPECTION DATE: **3/9/2016**
ADDRESS: **2009 W. Schiller Street** IDPH LICENSE NO: **100-07210**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **I**
MATERIAL DESCRIPTION: **12 x 12 inch Tan with Specks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **room 303 & 305, 112A**
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25871** BUILDING ID: **6460**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Pritzker School** REVIEW DATE: **4/1/2016**
ADDRESS: **2009 W. Schiller Street** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **I**
MATERIAL DESCRIPTION: **12 x 12 inch Tan with Specks Mastic**
MATERIAL LOCATION: **room 303 & 305, 112A**
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/01/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25871** BUIDLING ID: **6460**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Pritzker School** INSPECTION DATE: **3/9/2016**
ADDRESS: **2009 W. Schiller Street** IDPH LICENSE NO: **100-07210**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **J**
MATERIAL DESCRIPTION: **12 x 12 inch Light Blue with Dark Blue Streaks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **1st, 2nd, and 3rd Floor Corridors and Stairwells**
MATERIAL QUANTITY: **8640** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25871** BUIDLING ID: **6460**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Pritzker School** REVIEW DATE: **4/1/2016**
ADDRESS: **2009 W. Schiller Street** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **J**
MATERIAL DESCRIPTION: **12 x 12 inch Light Blue with Dark Blue Streaks Floor Tile**
MATERIAL LOCATION: **1st, 2nd, and 3rd Floor Corridors and Stairwells**
MATERIAL QUANTITY: **8640** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/01/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25871** BUIDLING ID: **6460**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Pritzker School** INSPECTION DATE: **3/9/2016**
ADDRESS: **2009 W. Schiller Street** IDPH LICENSE NO: **100-07210**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **K**
MATERIAL DESCRIPTION: **12 x 12 inch Lt Blue w/ Dk Blue Strks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st, 2nd & 3rd floor Corridors and Stairwells**
MATERIAL QUANTITY: **8640** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25871** BUIDLING ID: **6460**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Pritzker School** REVIEW DATE: **4/1/2016**
ADDRESS: **2009 W. Schiller Street** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **K**
MATERIAL DESCRIPTION: **12 x 12 inch Lt Blue w/ Dk Blue Strks Floor Tile Mastic**
MATERIAL LOCATION: **1st, 2nd & 3rd floor Corridors and Stairwells**
MATERIAL QUANTITY: **8640** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/01/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25871** BUIDLING ID: **6460**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Pritzker School** INSPECTION DATE: **3/9/2016**
ADDRESS: **2009 W. Schiller Street** IDPH LICENSE NO: **100-07210**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **L**
MATERIAL DESCRIPTION: **Grey Speck Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Engineer's Office, 2nd Floor Faculty Lounge(rm 200), Library**
MATERIAL QUANTITY: **1824** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25871** BUIDLING ID: **6460**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Pritzker School** REVIEW DATE: **4/1/2016**
ADDRESS: **2009 W. Schiller Street** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **L**
MATERIAL DESCRIPTION: **Grey Speck Carpet Mastic**
MATERIAL LOCATION: **Engineer's Office, 2nd Floor Faculty Lounge(rm 200), Library**
MATERIAL QUANTITY: **1824** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/01/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25871** BUILDING ID: **6460**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Pritzker School** REVIEW DATE: **4/1/2016**
ADDRESS: **2009 W. Schiller Street** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **40**
MATERIAL DESCRIPTION: **2x2 White Ceiling Tile**
MATERIAL LOCATION: **1st Floor faculty Lounge**
MATERIAL QUANTITY: **560** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: 04/01/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25871** BUILDING ID: **6460**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Pritzker School** REVIEW DATE: **4/1/2016**
ADDRESS: **2009 W. Schiller Street** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **38**
MATERIAL DESCRIPTION: **Dry Wall Soffit**
MATERIAL LOCATION: **Rooms 101 and 108**
MATERIAL QUANTITY: **120** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: 04/01/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25871** BUILDING ID: **6460**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Pritzker School** INSPECTION DATE: **3/9/2016**
ADDRESS: **2009 W. Schiller Street** IDPH LICENSE NO: **100-07210**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **36**
MATERIAL DESCRIPTION: **12x12 Pink Streaked VFT**
MATERIAL LOCATION: **1st, 2nd, 3rd Floor Classrooms under the Univents**
MATERIAL QUANTITY: **2240** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **MODERATE** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____


Michael Holvay
Project Manager

Date: 03/09/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25871** BUILDING ID: **6460**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Pritzker School** REVIEW DATE: **4/1/2016**
ADDRESS: **2009 W. Schiller Street** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **36**
MATERIAL DESCRIPTION: **12x12 Pink Streaked VFT**
MATERIAL LOCATION: **1st, 2nd, 3rd Floor Classrooms under the Univents**
MATERIAL QUANTITY: **2240** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  _____ Date: **04/01/2016** _____

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25871** BUILDING ID: **6460**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Pritzker School** INSPECTION DATE: **3/9/2016**
ADDRESS: **2009 W. Schiller Street** IDPH LICENSE NO: **100-07210**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **42**
MATERIAL DESCRIPTION: **Drywall above Ceiling tiles**
MATERIAL LOCATION: **Above ceiling tiles in classrooms**
MATERIAL QUANTITY: **20000** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **Yes**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____


Michael Holvay
Project Manager

Date: 03/09/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25871** BUILDING ID: **6460**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Pritzker School** REVIEW DATE: **4/1/2016**
ADDRESS: **2009 W. Schiller Street** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **42**
MATERIAL DESCRIPTION: **Drywall above Ceiling tiles**
MATERIAL LOCATION: **Above ceiling tiles in classrooms**
MATERIAL QUANTITY: **20000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  _____ Date: **04/01/2016** _____

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25871** BUILDING ID: **6460**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Pritzker School** INSPECTION DATE: **3/9/2016**
ADDRESS: **2009 W. Schiller Street** IDPH LICENSE NO: **100-07210**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **43**
MATERIAL DESCRIPTION: **Black tar-like Fireproofing**
MATERIAL LOCATION: **Above ceiling tile in classrooms**
MATERIAL QUANTITY: **20000** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____


Michael Holvay
Project Manager

Date: 03/09/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25871** BUILDING ID: **6460**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Pritzker School** REVIEW DATE: **4/1/2016**
ADDRESS: **2009 W. Schiller Street** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **43**

MATERIAL DESCRIPTION: **Black tar-like Fireproofing**

MATERIAL LOCATION: **Above ceiling tile in classrooms**

MATERIAL QUANTITY: **20000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **04/01/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25871** BUILDING ID: **6460**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Pritzker School** INSPECTION DATE: **3/9/2016**
ADDRESS: **2009 W. Schiller Street** IDPH LICENSE NO: **100-07210**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **37**
MATERIAL DESCRIPTION: **12x12 Pink Streaked Mastic**
MATERIAL LOCATION: **1st, 2nd, 3rd Floor Classrooms Under the Univents**
MATERIAL QUANTITY: **2240** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **MODERATE** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Barely Reachable** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____


Michael Holvay
Project Manager

Date: 03/09/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25871** BUILDING ID: **6460**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Pritzker School** REVIEW DATE: **4/1/2016**
ADDRESS: **2009 W. Schiller Street** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **37**
MATERIAL DESCRIPTION: **12x12 Pink Streaked Mastic**
MATERIAL LOCATION: **1st, 2nd, 3rd Floor Classrooms Under the Univents**
MATERIAL QUANTITY: **2240** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **04/01/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25871** BUILDING ID: **6460**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Pritzker School** REVIEW DATE: **4/1/2016**
ADDRESS: **2009 W. Schiller Street** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **39**
MATERIAL DESCRIPTION: **Black Painted Accoustic Ceiling**
MATERIAL LOCATION: **Auditorium**
MATERIAL QUANTITY: **3250** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **50** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **04/01/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25871** BUILDING ID: **6460**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Pritzker School** INSPECTION DATE: **3/9/2016**
ADDRESS: **2009 W. Schiller Street** IDPH LICENSE NO: **100-07210**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **41**
MATERIAL DESCRIPTION: **Unfinished Drywall Ceiling**
MATERIAL LOCATION: **Mezzanine above First Floor Corridor**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **MODERATE** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **20** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____


Michael Holvay
Project Manager

Date: 03/09/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25871** BUILDING ID: **6460**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Pritzker School** REVIEW DATE: **4/1/2016**
ADDRESS: **2009 W. Schiller Street** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **41**
MATERIAL DESCRIPTION: **Unfinished Drywall Ceiling**
MATERIAL LOCATION: **Mezzanine above First Floor Corridor**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **20** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **04/01/2016**

APPENDIX B

Inspector and Management Planner Licenses



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • www.dph.illinois.gov

4/18/2016

MICHAEL HOLVAY
855 WEST ADAMS ST., Suite 200
CHICAGO, IL 60607

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 07210

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

 <p>ASBESTOS PROFESSIONAL LICENSE</p>			<p>ENDORSEMENTS</p> <p>INSPECTOR</p> <p>PROJECT MANAGER</p> <p>AIR SAMPLING PROFESSIONAL</p>	<p>TC EXPIRES</p> <p>9/18/2016</p> <p>1/20/2017</p>
<p>ID NUMBER 100 - 07210</p>	<p>ISSUED 4/18/2016</p>	<p>EXPIRES 05/13/2017</p>	<p>Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.</p>	
<p>MICHAEL HOLVAY 855 WEST ADAMS ST., Suite 200 CHICAGO, IL 60607</p> <p>Environmental Health</p>				

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH, IMPROVING LIVES
Nationally Accredited by PHAB

2015



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Michael Holvay

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Course Date: 9/18/2015

Exam Date: 9/18/2015

Expiration Date: 9/18/2016

Certificate Number: BIR1509183493



Kathy DeSalvo, Director



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • www.idph.illinois.gov

4/18/2016

ARTURO SAENZ
855 W ADAMS ST SUITE 200
CHICAGO, IL 60607

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 04019

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

 <p>ASBESTOS PROFESSIONAL LICENSE</p>			<p>ENDORSEMENTS</p>		<p>TC EXPIRES</p>
<p>ID NUMBER 100 - 04019</p>	<p>ISSUED 4/18/2016</p>	<p>EXPIRES 05/13/2017</p>	<p>INSPECTOR</p>	<p>1/19/2017</p>	
<p>ARTURO SAENZ 855 W ADAMS ST SUITE 200 CHICAGO, IL 60607 Environmental Health</p>			<p>MANAGEMENT PLANNER</p>	<p>1/27/2017</p>	
			<p>AIR SAMPLING PROFESSIONAL Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.</p>		

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH, IMPROVING LIVES
Nationally Accredited by PHAB

2016



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Arturo Saenz

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 1/27/2016

Exam Date: 1/27/2016

Expiration Date: 1/27/2017

Certificate Number: MPR1601270319

Kathy DeSalvo, Director

2016



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Jigar Shah

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 1/27/2016

Exam Date: 1/27/2016

Expiration Date: 1/27/2017

Certificate Number: MPR1601270320

Kathy DeSalvo, Director

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL		
	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE		
	Loc	Localized
	Dist	Distributed