

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM**

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-2437
SCHOOL NAME: Ashe School
ADDRESS OF SCHOOL: 8505 S Ingleside Avenue
CITY: Chicago, IL, 60619

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED 2/27/2013

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II (Please type or print)

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 6/9/2016 ENROLLMENT 295
IDPH INSPECTOR LICENSE NUMBER: 100-05183
IDPH LICENSED INSPECTOR NAME (Please Print): Delores Fitzpatrick
IDPH MP LICENSE NUMBER: 100-07342
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Jigar Shah

DESIGNATED PERSON (Please Print): Robert Christlieb PHONE: (773) 553-3197



6/9/2016

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Ashe School

8505 S Ingleside Avenue
Chicago, IL, 60619

Unit: 26191
Building ID: 6900

IDPH ID Number: 14-016-2990-2437

REPORT DATE:

Thursday, June 09, 2016

Prepared for:

Chicago Public Schools
125 S. Clark Street
Chicago, IL 60603

Prepared by:

GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone (312) 733-6262

Fax (312) 733-5612

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: February 25, 2016

RE: Ashe School, Unit 26191
8505 S Ingleside Avenue
Chicago, IL, 60619

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2016 asbestos three year re-inspection has been completed at Ashe School , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at Ashe School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Robert Christlieb, the designated Local Education Authority's Designated Person at (773) 553-3197 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Ashe School
Address: 8505 S Ingleside Avenue
IDPH ID: 14-016-2990-2437
Contact: Johnson, Lance

Unit: 26191
Chicago, IL, 60619
Building ID: 6900
Phone: 773-726-8797

Region: 06

2. Description of Facility

Original Construction: 1963
Total Square Footage: 55335
Current Occupancy: 295

Additional Construction:
No of Floors: 3

3. LEA Designated Person

Contact: Robert Christlieb
Address: 125 South Clark Street, 17th Floor
Chicago, IL 60603

Phone: (773) 553-3197

4. Managing Environmental Consultant


MEC: GSG Consultants, Inc.
Contact: Arturo Saenz
Address 855 W. Adams St., Ste. 200
Phone: (312) 733-6262

Fax: (312) 733-5612

5. Inspector

Inspector Name: Delores Fitzpatrick


Inspector IDPH license # 100-05183


Signature:
Date: 2/25/2016

6. Management Planner

Management Planner Name: Jigar Shah

Management Planner IDPH license # 100-07342


Signature:
Date: 06/07/2016

7. Review Date: 06/07/2016

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature:



Date: 6/9/2016

Name: Robert Christlieb

II. EXECUTIVE SUMMARY

GSG Consultants, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Ashe School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 6900:

B. The following new homogenous areas have been identified for Building 6900:

16B

TSI

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

04	1'x1' Ceiling Tiles
06	12"x12" Brown Floor Tile
08	Encapsulated Spray-On
09	12"x12" Aqua Floor Tile
10	12"x12" Aqua Floor Tile Mastic
11	Baseboard
12	Baseboard Mastic
15	Vibration Damper
16	12"x12" Gray VFT
16A	12"x12" Gray Mastic
16B	TSI
17	12"x12" White VFT
17A	12"x12" White Mastic
18	12"x12" Peach VFT
18A	12"X12" Peach Mastic
19	12"x12" Light Blue VFT
19A	12"x12" Light Blue Mastic
20	Textured Plaster Ceiling
21	MJP on Fiberglass Pipe Insulation
22	Blue Carpet Mastic
FT1	12"x12" Dark Blue Floor Tile
FT2	12"x12" Light Blue Floor Tile
FTM1	12"x12" Dark Blue Floor Tile Mastic
MF1	Beige & Green Terrazzo
SP1	Plaster

The following areas were deemed to be inaccessible:

07	12"x12" Brown Floor Tile Mastic
10	12"x12" Aqua Floor Tile Mastic
12	Baseboard Mastic
15	Vibration Damper
22	Blue Carpet Mastic
CM1	Carpet Mastic (NOT OBSERVED)
CM2	Carpet Mastic (MATERIAL NOT OBSERVED)
FTM2	12"x12" Light Blue Floor Tile Mastic

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Delores Fitzpatrick, IDPH License # 100-05183. The Management Plan was updated by Jigar Shah, IDPH License # 100-07342. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Ashe School Building 6900 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Ashe School Unit 26191 Building ID 6900

Address 8505 S Ingleside Avenue Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
04	1'x1' Ceiling Tiles	425	SF	Over Trophy Case on 1st Floor (next to stairs)	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
06	12"x12" Brown Floor Tile	3,000	SF	Rooms 300 and 309 (Aqua), 3rd Floor Corridor and 3rd Floor Teacher's Washroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
07	12"x12" Brown Floor Tile Mastic	3,000	SF	Rooms 300 and 309, South End of 3rd Floor Corridor	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
08	Encapsulated Spray-On	80,000	SF	Throughout Building	ASSUMED	SURFACE	Y	NONE	0		No	ACBM with the potential for damage		LOW
09	12"x12" Aqua Floor Tile	55,000	SF	Rooms 101-111, 201-211, 301-310, 2nd Floor Teacher's Lounge (next to boy's washroom) and 3rd Floor Janitor's Closet	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
10	12"x12" Aqua Floor Tile Mastic	55,000	SF	1st, 2nd and 3rd Corridors, Rooms 101-111, 201-211, 301-310, 2nd Floor Teacher's Lounge (next to boy's washroom), 3rd Floor Janitor's Closet	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
11	Baseboard	500	LF	Office Area and Lunchroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
12	Baseboard Mastic	500	LF	Office Area and Lunchroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
15	Vibration Damper	5	SF	Fan Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
16	12"x12" Gray VFT	350	SF	Engineer's Office/Washroom and Locker Room/Washroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
16A	12"x12" Gray Mastic	350	SF	Engineer's Office/Washroom and Locker Office/Washroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
16B	TSI	872	LF	Small boiler in boiler room near	ASSUMED	TSI	Y	LOC	250			Damaged or significantly damaged		MODERATE

Chicago Public Schools

School Ashe School Unit 26191 Building ID 6900

Address 8505 S Ingleside Avenue Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				engineer doorway								friable thermal system insulating ACBM		
17	12"x12" White VFT	80	SF	Engineer's Office/Washroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
17A	12"x12" White Mastic	80	SF	Engineer's Office/Washroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
18	12"x12" Peach VFT	120	SF	Patchwork in Kitchen	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
18A	12"x12" Peach Mastic	120	SF	Patchwork in Kitchen	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
19	12"x12" Light Blue VFT	100	SF	Patchwork in Kitchen	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		HIGH
19A	12"x12" Light Blue Mastic	100	SF	Patchwork in Kitchen	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
20	Textured Plaster Ceiling	700	SF	Fan Room	ASSUMED	SURFACE	Y	NONE	0		No	ACBM with the potential for damage		LOW
21	MJP on Fiberglass Pipe Insulation	250	EA	Fan Room and Crawlspace	ASSUMED	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
22	Blue Carpet Mastic	1,800	SF	Main Office and Library (Room 104)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
CM1	Carpet Mastic (NOT OBSERVED)			West/North/West Center Wall in Room 302 (NOT OBSERVED)		MISC								
CM2	Carpet Mastic (MATERIAL NOT OBSERVED)			West/South/West Center Walls in Library (MATERIAL NOT OBSERVED)		MISC								
FT1	12"x12" Dark Blue Floor Tile	3,500	SF	Teacher's Dining Area, Sink Room in Cafeteria Area	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FT2	12"x12" Light Blue Floor Tile	3,500	SF	Gym Area	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FTM1	12"x12" Dark Blue Floor Tile Mastic	3,500	SF	Teacher's Dining Room and Sink Room in Cafeteria Area	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FTM2	12"x12" Light Blue Floor Tile Mastic	3,500	SF	Gym Area	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
MF1	Beige & Green Terrazzo	5,000	SF	Stairs and Landings	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
SP1	Plaster	34,000	SF	Ceilings Throughout Facility	ASSUMED	SURFACE	Y	NONE	0			ACBM with the potential for damage		LOW

Chicago Public Schools

School Ashe School Unit 26191 Building ID 6900

Address 8505 S Ingleside Avenue Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

Inspector's Comments are Summarized at the End of the Report

Reinspection Date <u>2/25/2016</u>
Inspector Name <u>Delores Fitzpatrick</u>
<u>100-05183</u> <u>2/13/2017</u>
Inspector's IDPH License Number / Expiration Date

Inspector's Comments

HA Number:	Inspector Comments:
04	
06	
07	
08	
09	
10	
11	
12	
15	
16	
16A	
16B	
17	
17A	
18	
18A	
19	
19A	
20	
21	
22	
CM1	
CM2	
FT1	

Chicago Public Schools

School Ashe School **Unit** 26191 **Building ID** 6900

Address 8505 S Ingleside Avenue **Region** 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
FT2	
FTM1	
FTM2	
MF1	
SP1	

Table II

Management Planner's Review

Chicago Public Schools

School Ashe School
Address 8505 S Ingleside Avenue

Unit 26191
Chicago, IL, 60619

Building ID 6900
Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
04	1'x1' Ceiling Tiles	425	SF	Over Trophy Case on 1st Floor (next to stairs)	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
06	12"x12" Brown Floor Tile	3,000	SF	Rooms 300 and 309 (Aqua), 3rd Floor Corridor and 3rd Floor Teacher's Washroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
07	12"x12" Brown Floor Tile Mastic	3,000	SF	Rooms 300 and 309, South End of 3rd Floor Corridor	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
08	Encapsulated Spray-On	80,000	SF	Throughout Building	Assumed	SURFACE	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
09	12"x12" Aqua Floor Tile	55,000	SF	Rooms 101-111, 201-211, 301- 310, 2nd Floor Teacher's Lounge (next to boy's washroom) and 3rd Floor Janitor's Closet	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
10	12"x12" Aqua Floor Tile Mastic	55,000	SF	1st, 2nd and 3rd Corridors, Rooms 101-111, 201-211, 301-310, 2nd Floor Teacher's Lounge (next to boy's washroom), 3rd Floor Janitor's Closet	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
11	Baseboard	500	LF	Office Area and Lunchroom	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
12	Baseboard Mastic	500	LF	Office Area and Lunchroom	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
15	Vibration Damper	5	SF	Fan Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
16	12"x12" Gray VFT	350	SF	Engineer's Office/Washroom and Locker Room/Washroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
16A	12"x12" Gray Mastic	350	SF	Engineer's Office/Washroom and Locker Office/Washroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
16B	TSI	872	LF	Small boiler in boiler room near engineer doorway	Assumed	TSI	Yes	250	LF	1 Damaged or significantly damaged friable thermal system insulating ACBM	Repair
17	12"x12" White VFT	80	SF	Engineer's Office/Washroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
17A	12"x12" White Mastic	80	SF	Engineer's Office/Washroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
18	12"x12" Peach VFT	120	SF	Patchwork in Kitchen	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
18A	12"X12" Peach Mastic	120	SF	Patchwork in Kitchen	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
19	12"x12" Light Blue VFT	100	SF	Patchwork in Kitchen	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
19A	12"x12" Light Blue Mastic	100	SF	Patchwork in Kitchen	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
20	Textured Plaster Ceiling	700	SF	Fan Room	Assumed	SURFACE	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
21	MJP on Fiberglass Pipe Insulation	250	EA	Fan Room and Crawlspace	Assumed	TSI	Yes	0	EA	6 ACBM with the potential for damage	Follow O&M Plan
22	Blue Carpet Mastic	1,800	SF	Main Office and Library (Room 104)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
CM1	Carpet Mastic (NOT OBSERVED)			West/North/West Center Wall in Room 302 (NOT OBSERVED)		MISC					

Chicago Public Schools

School Ashe School
Address 8505 S Ingleside Avenue

Unit 26191
 Chicago, IL, 60619

Building ID 6900
Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
CM2	Carpet Mastic (MATERIAL NOT OBSERVED)			West/South/West Center Walls in Library (MATERIAL NOT OBSERVED)		MISC					
FT1	12"x12" Dark Blue Floor Tile	3,500	SF	Teacher's Dining Area, Sink Room in Cafeteria Area	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FT2	12"x12" Light Blue Floor Tile	3,500	SF	Gym Area	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FTM1	12"x12" Dark Blue Floor Tile Mastic	3,500	SF	Teacher's Dining Room and Sink Room in Cafeteria Area	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FTM2	12"x12" Light Blue Floor Tile Mastic	3,500	SF	Gym Area	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
MF1	Beige & Green Terrazzo	5,000	SF	Stairs and Landings	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
SP1	Plaster	34,000	SF	Ceilings Throughout Facility	Assumed	SURFACE	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Ashe School
Address 8505 S Ingleside Avenue

Unit 26191
 Chicago, IL, 60619

Building ID 6900
Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

Management Planner's Comments Summarized at the End of the Report

Review Date	6/7/2016
Manager Planner Name	Jigar Shah
100-07342	1/19/2017
Manager IDPH License No/Expiration	

HA Number	Management Comments
04	
06	
07	
08	
09	
10	
11	
12	
15	
16	
16A	
16B	Repair Damaged ACM ASAP
17	
17A	
18	
18A	
19	
19A	
20	
21	
22	
CM1	
CM2	
FT1	
FT2	
FTM1	

Chicago Public Schools

School Ashe School
Address 8505 S Ingleside Avenue

Unit 26191
Chicago, IL, 60619

Building ID 6900
Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
FTM2	
MF1	
SP1	

Chicago Public Schools

GSG Consultants, Inc.

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26191** BUIDLING ID: **6900**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Ashe School** INSPECTION DATE: **2/25/2016**
ADDRESS: **8505 S Ingleside Avenue** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **04**
MATERIAL DESCRIPTION: **1'x1' Ceiling Tiles**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Over Trophy Case on 1st Floor (next to stairs)**

MATERIAL QUANTITY: **425**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 02/25/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26191** BUIDLING ID: **6900**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Ashe School** REVIEW DATE: **6/7/2016**
ADDRESS: **8505 S Ingleside Avenue** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **04**
MATERIAL DESCRIPTION: **1'x1' Ceiling Tiles**
MATERIAL LOCATION: **Over Trophy Case on 1st Floor (next to stairs)**
MATERIAL QUANTITY: **425** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/07/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26191** BUIDLING ID: **6900**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Ashe School** INSPECTION DATE: **2/25/2016**
ADDRESS: **8505 S Ingleside Avenue** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **06**
MATERIAL DESCRIPTION: **12"x12" Brown Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 300 and 309 (Aqua), 3rd Floor Corridor and 3rd Floor Teacher's Washroom**

MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 02/25/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26191** BUILDING ID: **6900**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Ashe School** REVIEW DATE: **6/7/2016**
ADDRESS: **8505 S Ingleside Avenue** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **06**
MATERIAL DESCRIPTION: **12"x12" Brown Floor Tile**
MATERIAL LOCATION: **Rooms 300 and 309 (Aqua), 3rd Floor Corridor and 3rd Floor Teacher's Washroom**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/07/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26191** BUIDLING ID: **6900**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Ashe School** INSPECTION DATE: **2/25/2016**
ADDRESS: **8505 S Ingleside Avenue** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **07**
MATERIAL DESCRIPTION: **12"x12" Brown Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 300 and 309, South End of 3rd Floor Corridor**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 02/25/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26191** BUIDLING ID: **6900**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Ashe School** REVIEW DATE: **6/7/2016**
ADDRESS: **8505 S Ingleside Avenue** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **07**
MATERIAL DESCRIPTION: **12"x12" Brown Floor Tile Mastic**
MATERIAL LOCATION: **Rooms 300 and 309, South End of 3rd Floor Corridor**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/07/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26191** BUIDLING ID: **6900**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Ashe School** INSPECTION DATE: **2/25/2016**
ADDRESS: **8505 S Ingleside Avenue** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **08**
MATERIAL DESCRIPTION: **Encapsulated Spray-On**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout Building**
MATERIAL QUANTITY: **80000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 02/25/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26191** BUIDLING ID: **6900**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Ashe School** REVIEW DATE: **6/7/2016**
ADDRESS: **8505 S Ingleside Avenue** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **08**
MATERIAL DESCRIPTION: **Encapsulated Spray-On**
MATERIAL LOCATION: **Throughout Building**
MATERIAL QUANTITY: **80000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **06/07/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26191** BUIDLING ID: **6900**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Ashe School** INSPECTION DATE: **2/25/2016**
ADDRESS: **8505 S Ingleside Avenue** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **09**
MATERIAL DESCRIPTION: **12"x12" Aqua Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 101-111, 201-211, 301- 310, 2nd Floor Teacher's Lounge (next to boy's washroom) and 3rd Floor Janitor's Closet**

MATERIAL QUANTITY: **55000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **02/25/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26191** BUILDING ID: **6900**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Ashe School** REVIEW DATE: **6/7/2016**
ADDRESS: **8505 S Ingleside Avenue** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **09**
MATERIAL DESCRIPTION: **12"x12" Aqua Floor Tile**
MATERIAL LOCATION: **Rooms 101-111, 201-211, 301- 310, 2nd Floor Teacher's Lounge (next to boy's washroom) and 3rd Floor Janitor's Closet**
MATERIAL QUANTITY: **55000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/07/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26191** BUIDLING ID: **6900**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Ashe School** INSPECTION DATE: **2/25/2016**
ADDRESS: **8505 S Ingleside Avenue** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10**
MATERIAL DESCRIPTION: **12"x12" Aqua Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st, 2nd and 3rd Corridors, Rooms 101-111, 201-211, 301-310, 2nd Floor Teacher's Lounge (next to boy's washroom), 3rd Floor Janitor's Closet**

MATERIAL QUANTITY: **55000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 02/25/2016

Chicago Public Schools

GSG Consultants, Inc.

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26191** BUILDING ID: **6900**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Ashe School** REVIEW DATE: **6/7/2016**
ADDRESS: **8505 S Ingleside Avenue** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **10**
MATERIAL DESCRIPTION: **12"x12" Aqua Floor Tile Mastic**
MATERIAL LOCATION: **1st, 2nd and 3rd Corridors, Rooms 101-111, 201-211, 301-310, 2nd Floor Teacher's Lounge (next to boy's washroom), 3rd Floor Janitor's Closet**
MATERIAL QUANTITY: **55000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/07/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26191** BUIDLING ID: **6900**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Ashe School** INSPECTION DATE: **2/25/2016**
ADDRESS: **8505 S Ingleside Avenue** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11**
MATERIAL DESCRIPTION: **Baseboard**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Office Area and Lunchroom**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____



Date: 02/25/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26191** BUIDLING ID: **6900**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Ashe School** REVIEW DATE: **6/7/2016**
ADDRESS: **8505 S Ingleside Avenue** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **11**
MATERIAL DESCRIPTION: **Baseboard**
MATERIAL LOCATION: **Office Area and Lunchroom**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/07/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26191** BUIDLING ID: **6900**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Ashe School** INSPECTION DATE: **2/25/2016**
ADDRESS: **8505 S Ingleside Avenue** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12**
MATERIAL DESCRIPTION: **Baseboard Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Office Area and Lunchroom**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____



Date: 02/25/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26191** BUIDLING ID: **6900**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Ashe School** REVIEW DATE: **6/7/2016**
ADDRESS: **8505 S Ingleside Avenue** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **12**
MATERIAL DESCRIPTION: **Baseboard Mastic**
MATERIAL LOCATION: **Office Area and Lunchroom**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/07/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26191** BUIDLING ID: **6900**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Ashe School** INSPECTION DATE: **2/25/2016**
ADDRESS: **8505 S Ingleside Avenue** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15**
MATERIAL DESCRIPTION: **Vibration Damper**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Fan Room**
MATERIAL QUANTITY: **5** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 02/25/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26191** BUILDING ID: **6900**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Ashe School** REVIEW DATE: **6/7/2016**
ADDRESS: **8505 S Ingleside Avenue** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **15**
MATERIAL DESCRIPTION: **Vibration Damper**
MATERIAL LOCATION: **Fan Room**
MATERIAL QUANTITY: **5** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/07/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26191** BUIDLING ID: **6900**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Ashe School** INSPECTION DATE: **2/25/2016**
ADDRESS: **8505 S Ingleside Avenue** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16**
MATERIAL DESCRIPTION: **12"x12" Gray VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Engineer's Office/Washroom and Locker Room/Washroom**
MATERIAL QUANTITY: **350** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 02/25/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26191** BUIDLING ID: **6900**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Ashe School** REVIEW DATE: **6/7/2016**
ADDRESS: **8505 S Ingleside Avenue** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **16**
MATERIAL DESCRIPTION: **12"x12" Gray VFT**
MATERIAL LOCATION: **Engineer's Office/Washroom and Locker Room/Washroom**
MATERIAL QUANTITY: **350** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **06/07/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26191** BUIDLING ID: **6900**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Ashe School** INSPECTION DATE: **2/25/2016**
ADDRESS: **8505 S Ingleside Avenue** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16A**
MATERIAL DESCRIPTION: **12"x12" Gray Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Engineer's Office/Washroom and Locker Office/Washroom**
MATERIAL QUANTITY: **350** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 02/25/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26191** BUIDLING ID: **6900**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Ashe School** REVIEW DATE: **6/7/2016**
ADDRESS: **8505 S Ingleside Avenue** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **16A**
MATERIAL DESCRIPTION: **12"x12" Gray Mastic**
MATERIAL LOCATION: **Engineer's Office/Washroom and Locker Office/Washroom**
MATERIAL QUANTITY: **350** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/07/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26191** BUIDLING ID: **6900**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Ashe School** INSPECTION DATE: **2/25/2016**
ADDRESS: **8505 S Ingleside Avenue** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17**
MATERIAL DESCRIPTION: **12"x12" White VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Engineer's Office/Washroom**
MATERIAL QUANTITY: **80** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 02/25/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26191** BUILDING ID: **6900**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Ashe School** REVIEW DATE: **6/7/2016**
ADDRESS: **8505 S Ingleside Avenue** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **17**
MATERIAL DESCRIPTION: **12"x12" White VFT**
MATERIAL LOCATION: **Engineer's Office/Washroom**
MATERIAL QUANTITY: **80** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/07/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26191** BUIDLING ID: **6900**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Ashe School** INSPECTION DATE: **2/25/2016**
ADDRESS: **8505 S Ingleside Avenue** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17A**
MATERIAL DESCRIPTION: **12"x12" White Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Engineer's Office/Washroom**
MATERIAL QUANTITY: **80** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 02/25/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26191** BUIDLING ID: **6900**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Ashe School** REVIEW DATE: **6/7/2016**
ADDRESS: **8505 S Ingleside Avenue** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **17A**
MATERIAL DESCRIPTION: **12"x12" White Mastic**
MATERIAL LOCATION: **Engineer's Office/Washroom**
MATERIAL QUANTITY: **80** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/07/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26191** BUIDLING ID: **6900**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Ashe School** INSPECTION DATE: **2/25/2016**
ADDRESS: **8505 S Ingleside Avenue** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18**
MATERIAL DESCRIPTION: **12"x12" Peach VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Patchwork in Kitchen**
MATERIAL QUANTITY: **120** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 02/25/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26191** BUIDLING ID: **6900**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Ashe School** REVIEW DATE: **6/7/2016**
ADDRESS: **8505 S Ingleside Avenue** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **18**
MATERIAL DESCRIPTION: **12"x12" Peach VFT**
MATERIAL LOCATION: **Patchwork in Kitchen**
MATERIAL QUANTITY: **120** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/07/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26191** BUIDLING ID: **6900**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Ashe School** INSPECTION DATE: **2/25/2016**
ADDRESS: **8505 S Ingleside Avenue** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18A**
MATERIAL DESCRIPTION: **12"X12" Peach Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Patchwork in Kitchen**
MATERIAL QUANTITY: **120** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 02/25/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26191** BUIDLING ID: **6900**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Ashe School** REVIEW DATE: **6/7/2016**
ADDRESS: **8505 S Ingleside Avenue** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **18A**
MATERIAL DESCRIPTION: **12"X12" Peach Mastic**
MATERIAL LOCATION: **Patchwork in Kitchen**
MATERIAL QUANTITY: **120** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/07/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26191** BUIDLING ID: **6900**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Ashe School** INSPECTION DATE: **2/25/2016**
ADDRESS: **8505 S Ingleside Avenue** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19**
MATERIAL DESCRIPTION: **12"x12" Light Blue VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **HIGH**
MATERIAL LOCATION: **Patchwork in Kitchen**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 02/25/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26191** BUIDLING ID: **6900**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Ashe School** REVIEW DATE: **6/7/2016**
ADDRESS: **8505 S Ingleside Avenue** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **19**
MATERIAL DESCRIPTION: **12"x12" Light Blue VFT**
MATERIAL LOCATION: **Patchwork in Kitchen**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/07/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26191** BUIDLING ID: **6900**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Ashe School** INSPECTION DATE: **2/25/2016**
ADDRESS: **8505 S Ingleside Avenue** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19A**
MATERIAL DESCRIPTION: **12"x12" Light Blue Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Patchwork in Kitchen**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 02/25/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26191** BUIDLING ID: **6900**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Ashe School** REVIEW DATE: **6/7/2016**
ADDRESS: **8505 S Ingleside Avenue** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **19A**
MATERIAL DESCRIPTION: **12"x12" Light Blue Mastic**
MATERIAL LOCATION: **Patchwork in Kitchen**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/07/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26191** BUIDLING ID: **6900**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Ashe School** INSPECTION DATE: **2/25/2016**
ADDRESS: **8505 S Ingleside Avenue** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**
MATERIAL DESCRIPTION: **Textured Plaster Ceiling**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Fan Room**
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 02/25/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26191** BUILDING ID: **6900**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Ashe School** REVIEW DATE: **6/7/2016**
ADDRESS: **8505 S Ingleside Avenue** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **20**
MATERIAL DESCRIPTION: **Textured Plaster Ceiling**
MATERIAL LOCATION: **Fan Room**
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/07/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26191** BUIDLING ID: **6900**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Ashe School** INSPECTION DATE: **2/25/2016**
ADDRESS: **8505 S Ingleside Avenue** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21**
MATERIAL DESCRIPTION: **MJP on Fiberglass Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Fan Room and Crawlspace**
MATERIAL QUANTITY: **250** MATERIAL UNITS: **EA**
DAMAGE QUANTITY: DAMAGE UNITS: **EA**

COMMENTS:

Inspector's Signature: _____



Date: 02/25/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26191** BUIDLING ID: **6900**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Ashe School** REVIEW DATE: **6/7/2016**
ADDRESS: **8505 S Ingleside Avenue** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **21**
MATERIAL DESCRIPTION: **MJP on Fiberglass Pipe Insulation**
MATERIAL LOCATION: **Fan Room and Crawlspace**
MATERIAL QUANTITY: **250** MATERIAL UNITS: **EA**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/07/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26191** BUIDLING ID: **6900**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Ashe School** INSPECTION DATE: **2/25/2016**
ADDRESS: **8505 S Ingleside Avenue** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22**
MATERIAL DESCRIPTION: **Blue Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Main Office and Library (Room 104)**
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 02/25/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26191** BUIDLING ID: **6900**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Ashe School** REVIEW DATE: **6/7/2016**
ADDRESS: **8505 S Ingleside Avenue** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **22**
MATERIAL DESCRIPTION: **Blue Carpet Mastic**
MATERIAL LOCATION: **Main Office and Library (Room 104)**
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **06/07/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26191** BUIDLING ID: **6900**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Ashe School** INSPECTION DATE: **2/25/2016**
ADDRESS: **8505 S Ingleside Avenue** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **CM1**
MATERIAL DESCRIPTION: **Carpet Mastic (NOT OBSERVED)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **West/North/West Center Wall in Room 302 (NOT OBSERVED)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **02/25/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26191** BUILDING ID: **6900**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Ashe School** REVIEW DATE: **6/7/2016**
ADDRESS: **8505 S Ingleside Avenue** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **CM1**
MATERIAL DESCRIPTION: **Carpet Mastic (NOT OBSERVED)**
MATERIAL LOCATION: **West/North/West Center Wall in Room 302 (NOT OBSERVED)**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **06/07/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26191** BUIDLING ID: **6900**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Ashe School** INSPECTION DATE: **2/25/2016**
ADDRESS: **8505 S Ingleside Avenue** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **CM2**
MATERIAL DESCRIPTION: **Carpet Mastic (MATERIAL NOT OBSERVED)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **West/South/West Center Walls in Library (MATERIAL NOT OBSERVED)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____



Date: **02/25/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26191** BUILDING ID: **6900**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Ashe School** REVIEW DATE: **6/7/2016**
ADDRESS: **8505 S Ingleside Avenue** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **CM2**
MATERIAL DESCRIPTION: **Carpet Mastic (MATERIAL NOT OBSERVED)**
MATERIAL LOCATION: **West/South/West Center Walls in Library (MATERIAL NOT OBSERVED)**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **06/07/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26191** BUIDLING ID: **6900**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Ashe School** INSPECTION DATE: **2/25/2016**
ADDRESS: **8505 S Ingleside Avenue** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FT1**
MATERIAL DESCRIPTION: **12"x12" Dark Blue Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Teacher's Dining Area, Sink Room in Cafeteria Area**
MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 02/25/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26191** BUIDLING ID: **6900**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Ashe School** REVIEW DATE: **6/7/2016**
ADDRESS: **8505 S Ingleside Avenue** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **FT1**
MATERIAL DESCRIPTION: **12"x12" Dark Blue Floor Tile**
MATERIAL LOCATION: **Teacher's Dining Area, Sink Room in Cafeteria Area**
MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/07/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26191** BUIDLING ID: **6900**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Ashe School** INSPECTION DATE: **2/25/2016**
ADDRESS: **8505 S Ingleside Avenue** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FT2**
MATERIAL DESCRIPTION: **12"x12" Light Blue Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Gym Area**
MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 02/25/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26191** BUIDLING ID: **6900**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Ashe School** REVIEW DATE: **6/7/2016**
ADDRESS: **8505 S Ingleside Avenue** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **FT2**
MATERIAL DESCRIPTION: **12"x12" Light Blue Floor Tile**
MATERIAL LOCATION: **Gym Area**
MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/07/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26191** BUIDLING ID: **6900**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Ashe School** INSPECTION DATE: **2/25/2016**
ADDRESS: **8505 S Ingleside Avenue** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FTM1**
MATERIAL DESCRIPTION: **12"x12" Dark Blue Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Teacher's Dining Room and Sink Room in Cafeteria Area**
MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 02/25/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26191** BUILDING ID: **6900**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Ashe School** REVIEW DATE: **6/7/2016**
ADDRESS: **8505 S Ingleside Avenue** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **FTM1**
MATERIAL DESCRIPTION: **12"x12" Dark Blue Floor Tile Mastic**
MATERIAL LOCATION: **Teacher's Dining Room and Sink Room in Cafeteria Area**
MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/07/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26191** BUIDLING ID: **6900**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Ashe School** INSPECTION DATE: **2/25/2016**
ADDRESS: **8505 S Ingleside Avenue** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FTM2**
MATERIAL DESCRIPTION: **12"x12" Light Blue Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Gym Area**
MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 02/25/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26191** BUIDLING ID: **6900**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Ashe School** REVIEW DATE: **6/7/2016**
ADDRESS: **8505 S Ingleside Avenue** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **FTM2**
MATERIAL DESCRIPTION: **12"x12" Light Blue Floor Tile Mastic**
MATERIAL LOCATION: **Gym Area**
MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/07/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26191** BUIDLING ID: **6900**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Ashe School** INSPECTION DATE: **2/25/2016**
ADDRESS: **8505 S Ingleside Avenue** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **MF1**
MATERIAL DESCRIPTION: **Beige & Green Terrazzo**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Stairs and Landings**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 02/25/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26191** BUIDLING ID: **6900**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Ashe School** REVIEW DATE: **6/7/2016**
ADDRESS: **8505 S Ingleside Avenue** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **MF1**
MATERIAL DESCRIPTION: **Beige & Green Terrazzo**
MATERIAL LOCATION: **Stairs and Landings**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/07/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26191** BUIDLING ID: **6900**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Ashe School** INSPECTION DATE: **2/25/2016**
ADDRESS: **8505 S Ingleside Avenue** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **SP1**
MATERIAL DESCRIPTION: **Plaster**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Ceilings Throughout Facility**
MATERIAL QUANTITY: **34000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 02/25/2016

Chicago Public Schools

GSG Consultants, Inc.

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26191** BUIDLING ID: **6900**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Ashe School** REVIEW DATE: **6/7/2016**
ADDRESS: **8505 S Ingleside Avenue** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **SP1**
MATERIAL DESCRIPTION: **Plaster**
MATERIAL LOCATION: **Ceilings Throughout Facility**
MATERIAL QUANTITY: **34000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/07/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26191** BUILDING ID: **6900**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Ashe School** INSPECTION DATE: **2/25/2016**
ADDRESS: **8505 S Ingleside Avenue** IDPH LICENSE NO: **100-05183**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **16B**
MATERIAL DESCRIPTION: **TSI**
MATERIAL LOCATION: **Small boiler in boiler room near engineer doorway**
MATERIAL QUANTITY: **872** MATERIAL UNITS: **LF**
MATERIAL CATEGORY: **TSI** FRIABLE: **Yes**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **MODERATE** CONDITION:
AHERA DAMAGE CATEGORY: **1 Damaged or significantly damaged friable thermal system insulating ACBM**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **250** DAMAGE REASON:
DAMAGE UNITS: **LF**
COMMENTS:

Inspector's Signature: _____



Date: 02/25/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26191** BUILDING ID: **6900**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Ashe School** REVIEW DATE: **6/7/2016**
ADDRESS: **8505 S Ingleside Avenue** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **16B**
MATERIAL DESCRIPTION: **TSI**
MATERIAL LOCATION: **Small boiler in boiler room near engineer doorway**
MATERIAL QUANTITY: **872** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **250** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:
Repair Damaged ACM ASAP

Management Planner's Signature:  Date: **06/07/2016**

APPENDIX B

Inspector and Management Planner Licenses

CERTIFICATE OF ACHIEVEMENT ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that DELORES FITZPATRICK
has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the
examination on 02/16/2013 with a minimum score of 70% or better. Training was in accordance
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:
Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.



N. Kennedy

02/16/2013
Course Dates: _____
02/16/2014
Expires: _____
1302BIR20
Certificate Number: _____

Director of Training
Nicholas J. Penell
Doctor of Public Health
Phone Number: (312) 491-4081
FORM # A-010



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • www.dph.illinois.gov



4/20/2016

DELORES FITZPATRICK
855 WEST ADAMS, SUITE 200
CHICAGO, IL 60607

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 05183

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE


Front of License			Back of License	
 ASBESTOS PROFESSIONAL LICENSE			ENDORSEMENTS	TC EXPIRES
ID NUMBER TC0 - 05183	ISSUED 4/20/2016	EXPIRES 05/15/2017	INSPECTOR	2/13/2017
DELORES FITZPATRICK 855 WEST ADAMS, SUITE 200 CHICAGO, IL 60607 Environmental Health			PROJECT MANAGER AIR SAMPLING PROFESSIONAL	2/6/2017
			Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH, IMPROVING LIVES
Nationally Accredited by PHAB

2016



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Jigar Shah

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 1/27/2016

Exam Date: 1/27/2016

Expiration Date: 1/27/2017

Certificate Number: MPR1601270320


Kathy DeSalvo, Director



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • www.dph.illinois.gov

4/20/2016

JIGAR M SHAH
855 W ADAMS ST, SUITE 200
CHICAGO, IL 60607

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 07342

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

		ASBESTOS PROFESSIONAL LICENSE		ENDORSEMENTS	TC EXPIRES
ID NUMBER 109 - 07342	ISSUED 4/20/2016	EXPIRES 05/15/2017		INSPECTOR PROJECT DESIGNER MANAGEMENT PLANNER PROJECT MANAGER AIR SAMPLING PROFESSIONAL	1/19/2017 2/2/2017 1/27/2017 2/26/2017
JIGAR M SHAH 855 W ADAMS ST, SUITE 200 CHICAGO, IL 60607 Environmental Health				Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH, IMPROVING LIVES
Nationally Accredited by PHAB

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL		
	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE		
	Loc	Localized
	Dist	Distributed