

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH  
AHERA THREE YEAR REINSPECTION  
ASBESTOS ABATEMENT PROGRAM  
SCHOOL INFORMATION FORM**

**SECTION I**

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299  
SCHOOL ID NUMBER: 14-016-2990-2173  
SCHOOL NAME: DuBois School  
ADDRESS OF SCHOOL: 330 E. 133rd Street  
CITY: Chicago, IL, 60627

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **3/1/2013**

**If the address on this form is different than the address of the building, submit a written explanation.**

---

**SECTION II** *(Please type or print)*

**PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:**

DATE REINSPECTION COMPLETED: 5/23/2016 ENROLLMENT 261  
IDPH INSPECTOR LICENSE NUMBER: 100-18790  
IDPH LICENSED INSPECTOR NAME (Please Print): Allizon Brooks  
IDPH MP LICENSE NUMBER: 100-01786  
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Guillermo Garcia

DESIGNATED PERSON (Please Print): Robert Christlieb PHONE: (773) 553-3197



5/23/2016

*Signature of Designated Person*

*Date*

**SECTION III**

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: \_\_\_\_\_

School has been closed. Date closed: \_\_\_\_\_

School building has been demolished. Date: \_\_\_\_\_

School building is asbestos free since last reinspection: \_\_\_\_\_

**Please explain in writing why the school building is now asbestos free and include the supporting documentation.**

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

**Explain in writing if the address of the building is different than the address on this form:**

---

---

---

**THREE-YEAR REINSPECTION**

**CHICAGO SCHOOL DIST 299**

**DuBois School**

330 E. 133rd Street  
Chicago, IL, 60627

Unit: 26601  
Building ID: 8010

IDPH ID Number: 14-016-2990-2173

**REPORT DATE:**

Monday, May 23, 2016

**Prepared for:**

**Chicago Public Schools**  
**125 S. Clark Street**  
**Chicago, IL 60603**

**Prepared by:**

**GSG Consultants, Inc.**

855 W. Adams St., Ste. 200

Phone (312) 733-6262

Fax (312) 733-5612

**DO NOT REMOVE FROM SCHOOL  
REQUIRED BY FEDERAL LAW**

February 24, 2016

Mr. R. Kent Cook  
Asbestos Program  
Illinois Department of Public Health  
525 West Jefferson Street  
Springfield, Illinois 62761

Re: Chicago Public Schools - 2016 Three-Year Reinspections

Dear Mr. Cook:

GSG Consultants, Inc., Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 1,2,6 Elementary Schools. Please update your records with the following information.

School District: 299                      Unit: 26601                      Region: 06                      IDPH ID: 14-016-2990-2173

School: DuBois School                      Building ID: 8010

Address: 330 E. 133rd Street  
Chicago, IL, 60627

Building Contact: James, John                      Contact Phone: 773-535-1000

Current Building Owners: Chicago Public Schools

Review Date: 05/20/2016

Inspector: Allizon Brooks                      Inspector IDPH License: 100-18790  
Management Planner: Guillermo Garcia                      Management Planner IDPH License: 100-01786

If you have any questions or comments, please contact us at (312) 733-6262

Sincerely,  
GSG Consultants, Inc.



Guillermo Garcia  
100-01786

## **Environmental Notification to Occupants**

To: Faculty, Staff and Parents  
From: Chicago Public Schools  
Date: February 24, 2016

RE: DuBois School, Unit 26601  
330 E. 133rd Street  
Chicago, IL, 60627

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2016 asbestos three year re-inspection has been completed at DuBois School , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at DuBois School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Robert Christlieb, the designated Local Education Authority's Designated Person at (773) 553-3197 .

## **Table of Contents**

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

### **APPENDICES:**

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

## SCHOOL AND INSPECTION INFORMATION

### 1. School Information

School: DuBois School  
Address: 330 E. 133rd Street  
IDPH ID: 14-016-2990-2173  
Contact: James, John

Unit: 26601  
Chicago, IL, 60627  
Building ID: 8010  
Phone: 773-535-1000

Region: 06

### 2. Description of Facility

Original Construction: 1950  
Total Square Footage:  
Current Occupancy: 261

Additional Construction:  
No of Floors:

### 3. LEA Designated Person

Contact: Robert Christlieb  
Address: 125 South Clark Street, 17th Floor  
Chicago, IL 60603

Phone: (773) 553-3197

### 4. Managing Environmental Consultant

MEC: GSG Consultants, Inc.  
Contact: Arturo Saenz  
Address 855 W. Adams St., Ste. 200  
Phone: (312) 733-6262

Fax: (312) 733-5612

### 5. Inspector

Inspector Name: Allizon Brooks

Inspector IDPH license # 100-18790

Signature:  
Date: 2/24/2016

### 6. Management Planner

Management Planner Name: Guillermo Garcia

Management Planner IDPH license # 100-01786

Signature:  
Date: 05/20/2016



### 7. Review Date: 05/20/2016

### 8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature: 

Date: 5/23/2016

Name: Robert Christlieb

## II. EXECUTIVE SUMMARY

GSG Consultants, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the DuBois School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 8010:

- |   |   |
|---|---|
| A | Aircell Pipe Insulation - NO ACCESS; NOT OBSERVED   |
| F | Cardboard Pipe Insulation - NO ACCESS; NOT OBSERVED |

B. The following new homogenous areas have been identified for Building 8010:



C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

02	Stucco Ceiling
05	12"x12" Beige Floor Tile
06	12"x12" Beige Floor Tile Mastic
08	Hardcoat Plaster - NOT OBSERVED
09	2' x 4' Ceiling Tile - NOT OBSERVED
22	12"x12" Beige Floor Tile- DUPLICATE of HA 05
23	12"x12" Beige Floor Tile Mastic- DUPLICATE of HA 06
24	12"x12" Black Floor Tile
25	12"x12"Black Floor Tile Mastic
26	Black Vinyl Baseboard
27	Black Vinyl Baseboard Mastic
28	Blue Carpet Mastic
29	Brown Carpet Mastic
30	Insulation in Fire Rated Doors - NOT OBSERVED
31	12 x 12 White with Blue, Red and Yellow Specks Floor Tile
31M	12 x 12 White with Blue, Red and Yellow Specks Floor Tile Mastic
32	White with Black Terrazzo
33	Green Mosaic Ceramic Tile Grout
34	Green Mosaic Ceramic Tile Adhesive
35	Yellow Mosaic Ceramic Tile Grout
36	Yellow Mosaic Ceramic Tile Adhesive
37	Plaster Ceiling
38	Brown Mosaic Ceramic Tile Grout
39	Brown Mosaic Ceramic Tile Adhesive
40	12 x 12 Light Brown Floor Tile - NOT OBSERVED
40M	12 x 12 Light Brown Floor Tile Mastic - NOT OBSERVED
41	Brown Mosaic Ceramic Tile Grout - NOT OBSERVED
42	Brown Mosaic Ceramic Tile Adhesive - NOT OBSERVED
43	Mag Pipe Insulation - NOT OBSERVED
44	Hard Fittings on Fiberglass - NOT OBSERVED
45	2 x 4 White Fissured Ceiling Tile
46	9x9 Blue VFT
47	9x9 Blue floor tile mastic
48	2x4 white ceiling tile
49	12x12 beige w/ tan specs VFT
50	12x12 beige w/ tan specs mastic

F	Cardboard Pipe Insulation - NO ACCESS; NOT OBSERVED
J	Vibration Dampner
M	PIPEJOINTS - NOT OBSERVED
N	DUCT WRAP

The following areas were deemed to be inaccessible:

06	12"x12" Beige Floor Tile Mastic
08	Hardcoat Plaster - NOT OBSERVED
13	9"x9" Green Floor Tile Mastic
21	9"x9" Tan Floor Tile Mastic
23	12"x12" Beige Floor Tile Mastic- DUPLICATE of HA 06
25	12"x12"Black Floor Tile Mastic
27	Black Vinyl Baseboard Mastic
28	Blue Carpet Mastic
29	Brown Carpet Mastic
31M	12 x 12 White with Blue, Red and Yellow Specks Floor Tile Mastic
34	Green Mosaic Ceramic Tile Adhesive
39	Brown Mosaic Ceramic Tile Adhesive
40M	12 x 12 Light Brown Floor Tile Mastic - NOT OBSERVED
42	Brown Mosaic Ceramic Tile Adhesive - NOT OBSERVED
A	Aircell Pipe Insulation - NO ACCESS; NOT OBSERVED
B	MJP E/F/V on Aircell Pipe Insulation - NOT OBSERVED
J	Vibration Dampner

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Allizon Brooks, IDPH License # 100-18790. The Management Plan was updated by Guillermo Garcia, IDPH License # 100-01786. Inspector and Management Planner Licenses are included in Appendix B.

### **III. METHODOLOGY**

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

### **IV. ABATEMENT HISTORY**

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

### **V. REASSESSMENTS AND RECOMMENDATIONS**

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

### **VI. CONCLUSIONS**

The DuBois School Building 8010 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

**Table I**  
**Inspector's Reinspection Findings**

---

# Chicago Public Schools

School DuBois School Unit 26601 Building ID 8010

Address 330 E. 133rd Street Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
02	Stucco Ceiling	3,600	SF	Bldg 1968, All-Purpose Room	ASSUMED	SURFACE	Y	NONE	0		No	ACBM with the potential for damage		LOW
04	9"x9" Beige Floor Tile	10,500	SF	1st Floor Rooms and Rooms 210, 212, 214, MDF Room 2nd floor, Room 112, 111, 101, 109	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
05	12"x12" Beige Floor Tile	5,700	SF	1st and 2nd Floor Corridors and Lunchroom, Main office waiting area, Faculty lunchroom, and Room 103	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
06	12"x12" Beige Floor Tile Mastic	5,700	SF	1st and 2nd Floor Corridors and Lunchroom, Main office and waiting area, Faculty lunchroom, and Room 103	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
07	9"x9" Beige Floor Tile Mastic	10,500	SF	1st Floor Rooms and Rooms 210, 212, 214, 2nd Floor MDF Room 112, Room 111, Room 109, Room 101	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
08	Hardcoat Plaster - NOT OBSERVED	6,000	SF	Throughout Building 1937	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		MODERATE
09	2' x 4' Ceiling Tile - NOT OBSERVED	5,440	SF	Throughout Building 1937	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
10	9"x9" Brown Floor Tile (NOT OBSERVED)	150	SF	Room 101, 9x9 pink and 9x9 beige	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
11	9"x9" Floor Tile Mastic	150	SF	Bldg 1968 - Room 101--NOT OBSERVED	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
12	9"x9" Green Floor Tile	3,500	SF	1st Floor Classrooms, Rooms 103, 108, 113	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
13	9"x9" Green Floor Tile Mastic	3,500	SF	1st Floor Classrooms, Rooms 103, 108, 113	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
14	9"x9" Green Floor Tile- NOT OBSERVED	80	SF	Basement Engineer's Office (1937)	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
15	9"x9" Green Floor Tile Mastic - NOT OBSERVED	80	SF	Basement Engineer's Office (1937)	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

# Chicago Public Schools

School DuBois School Unit 26601 Building ID 8010

Address 330 E. 133rd Street Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
16	9"x9" Gray Floor Tile	1,450	SF	Bldg 1968 - Counsellor's Room, 1st Floor Offices, 1st and 2nd floor storage rooms, Vault and Lunchroom storage room	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
17	9"x9" Gray Floor Tile Mastic	1,450	SF	Bldg 1968 - Counsellor's Room, 1st Floor Offices, 1st and 2nd Floor storage rooms, vault and Lunchroom storage room	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
18	9"x9" Pink Floor Tile (NOT OBSERVED); peach floor tile in room	1,050	SF	1st Floor stage storage room, Room 101	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
19	9"x9" Pink Floor Tile Mastic (NOT OBSERVED);peach floor tile in room	1,050	SF	1st floor storage room, Room 101	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
20	9"x9" Tan Floor Tile	600	SF	Rooms 208, 213, Engineers office 1968 building	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
21	9"x9" Tan Floor Tile Mastic	600	SF	Rooms 208, 213, Engineers office, 1968 Building	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
22	12"x12" Beige Floor Tile- DUPLICATE of HA 05	5,670	SF	1st and 2nd Floor Corridors and Lunchroom	ASSUMED	MISC		NONE	0		No	ACBM with the potential for damage		MODERATE
23	12"x12" Beige Floor Tile Mastic- DUPLICATE of HA 06	5,670	SF	1st and 2nd Floor Corridors and Lunchroom	ASSUMED	MISC		NONE	0		No	ACBM with the potential for damage		LOW
24	12"x12" Black Floor Tile	3,515	SF	1st and 2nd Floor Corridors	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
25	12"x12"Black Floor Tile Mastic	3,515	SF	1st and 2nd Floor Corridors	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
26	Black Vinyl Baseboard	320	LF	School Offices	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
27	Black Vinyl Baseboard Mastic	320	LF	School Offices	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
28	Blue Carpet Mastic	1,000	SF	School Offices and LIBRARY, Carpet removed in room 209 and 211	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
29	Brown Carpet Mastic	700	SF	Main Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the		LOW

# Chicago Public Schools

School DuBois School Unit 26601 Building ID 8010

Address 330 E. 133rd Street Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
												potential for damage		
30	Insulation in Fire Rated Doors - NOT OBSERVED	2	EA	Boiler Room (1937)	ASSUMED	TSI	N	NONE	0		No	ACBM with the potential for damage		LOW
31	12 x 12 White with Blue, Red and Yellow Specks Floor Tile	1,700	SF	Bldg 1968 - Room 209, 211	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
31M	12 x 12 White with Blue, Red and Yellow Specks Floor Tile Mastic	1,700	SF	Bldg 1968 - Room 209, 211	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
32	White with Black Terrazzo	900	SF	1968 Bldg - NE and SE Stairwells, Lobby	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
33	Green Mosaic Ceramic Tile Grout	640	SF	1968 Bldg - 1st and 2nd Floor Boys and Girls Washrooms	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
34	Green Mosaic Ceramic Tile Adhesive	640	SF	1968 Bldg - 1st and 2nd Floor Boys and Girls Washrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
35	Yellow Mosaic Ceramic Tile Grout	170	SF	1968 Bldg - 1st and 2nd Floor Teachers Washrooms, Office Restroom, 101 and 103 Restrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
36	Yellow Mosaic Ceramic Tile Adhesive	170	SF	1968 Bldg - 1st and 2nd Floor Teachers Washrooms, Office Restroom, 101 and 103 Restrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
37	Plaster Ceiling	1,800	SF	Boiler Room, All Washrooms, 1st and 2nd Floor Storage Rooms	ASSUMED	SURFACE	Y	NONE	0		No	ACBM with the potential for damage		LOW
38	Brown Mosaic Ceramic Tile Grout	230	SF	1968 Bldg - North, South and East Vestibules	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
39	Brown Mosaic Ceramic Tile Adhesive	230	SF	1968 Bldg - North, South and East Vestibules	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
40	12 x 12 Light Brown Floor Tile - NOT OBSERVED	6,800	SF	1937 Bldg - Throughout 1st Floor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
40M	12 x 12 Light Brown Floor Tile Mastic - NOT OBSERVED	6,800	SF	1937 Bldg - Throughout 1st Floor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
41	Brown Mosaic Ceramic Tile Grout - NOT OBSERVED	800	SF	1937 Bldg - 1st Floor Vestibules,	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW

# Chicago Public Schools

School DuBois School Unit 26601 Building ID 8010

Address 330 E. 133rd Street Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Boys and Girls Washrooms										
42	Brown Mosaic Ceramic Tile Adhesive - NOT OBSERVED	800	SF	1937 Bldg - 1st Floor Vestibules, Boys and Girls Washrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
43	Mag Pipe Insulation - NOT OBSERVED	30	LF	1937 Bldg - Boiler Room	ASSUMED	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
44	Hard Fittings on Fiberglass - NOT OBSERVED	30	LF	1937 Bldg - Boiler Room	ASSUMED	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
45	2 x 4 White Fissured Ceiling Tile	45,000	SF	1968 Bldg - Throughout	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		MODERATE
46	9x9 Blue VFT	25	SF	2nd fl. janitors closet 1968 bldg	ASSUMED	MISC	N	LOC	1		No	ACBM with the potential for damage	5	MODERATE
47	9x9 Blue floor tile mastic	25	SF	2nd fl janitors- 1968 bldg	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
48	2x4 white ceiling tile	3,500	SF	lunch room bldg 1968 faculty lunchroom bldg 1968 rm 103 bldg 1968 rm 101 bldg 1968	ASSUMED	MISC	Y	NONE	0			ACBM with the potential for damage		LOW
49	12x12 beige w/ tan specs VFT	400	SF	rm 134 bldg 1968	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		MODERATE
50	12x12 beige w/ tan specs mastic	400	SF	rm 134- 1968 bldg	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
A	Aircell Pipe Insulation - NO ACCESS; NOT OBSERVED	200	LF	Basement Building 1937	CHR	TSI	Y	DIST	10		Yes	Damaged or significantly damaged friable thermal system insulating ACBM	5	MODERATE
B	MJP E/F/V on Aircell Pipe Insulation - NOT OBSERVED	25	LF	Basement, Building 1937	AMO	TSI	Y	NONE	0		No	ACBM with the potential for damage		MODERATE
D	MJP E/F/V on Fiberglass Pipe Insulation-- Abated			2nd Floor Boiler Room, 1st fl. fan Rm	ABATED	TSI								
E	MJP E/F/V on Fiberglass Pipe Insulation - Duplicate	45	LF	1st Floor Storage Room	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		MODERATE
F	Cardboard Pipe Insulation - NO ACCESS; NOT OBSERVED	200	LF	Tunnel Area, Building 1937	ASSUMED	TSI	Y	LOC	5		Yes	Damaged or significantly damaged friable thermal system insulating ACBM	5	MODERATE
I	Cementitious Duct Insulation - NOT OBSERVED	150	SF	Basement Building 1937	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
J	Vibration Dampner	10	LF	Fan Room, Pipe Chase, 2nd Floor	ASSUMED	TSI		NONE	0		No	ACBM with the potential for damage		LOW



# Chicago Public Schools

School DuBois School Unit 26601 Building ID 8010

Address 330 E. 133rd Street Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Boiler Room										
K	Furnace Gasket Insulation - NOT OBSERVED	5	LF	Basement Building 1937	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
L	MJP E/F/V on Paperwrap Pipe Insulation - NOT OBSERVED	15	LF	Basement Building 1937	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		MODERATE
M	PIPEJOINTS - NOT OBSERVED	20	LF	2ND Floor Boiler Room and Fan Room (PRIMARY BLDG.)	ASSUMED	TSI	N	NONE	0		No	ACBM with the potential for damage		LOW
N	DUCT WRAP	150	SF	2ND FLR BOILER ROOM (PRIMARY BLDG.) AND FAN UNIT	ASSUMED	TSI	N	NONE	0		No	ACBM with the potential for damage		LOW

# Chicago Public Schools

School DuBois School Unit 26601 Building ID 8010

Address 330 E. 133rd Street Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

*Inspector's Comments are Summarized at the End of the Report*

Reinspection Date <b>2/24/2016</b>
Inspector Name <b>Allizon Brooks</b>
<b>100-18790</b> <b>10/28/2016</b>
Inspector's IDPH License Number / Expiration Date

### Inspector's Comments

HA Number:	Inspector Comments:
02	
04	
05	
06	
07	
08	- NOT OBSERVED
09	- NOT OBSERVED
10	
11	
12	
13	
14	- NOT OBSERVED
15	
16	
17	
18	Pink not observed- peach floor tile in room
19	Pink not observed- peach floor tile in storage, gym storage
20	
21	
22	
23	
24	
25	
26	

# Chicago Public Schools

School DuBois School Unit 26601 Building ID 8010

Address 330 E. 133rd Street Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
27	
28	
29	
30	
31	
31M	
32	
33	
34	
35	
36	
37	
38	
39	
40	
40M	
41	
42	
43	
44	
45	
46	
47	
48	
49	
50	
A	Material within locked, inaccessible 1937 bldg.
B	
D	

# Chicago Public Schools

School DuBois School Unit 26601 Building ID 8010

Address 330 E. 133rd Street Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
E	
F	NO ACCESS; NOT OBSERVED
I	
J	
K	
L	
M	
N	

**Table II**

**Management Planner's Review**

---

# Chicago Public Schools

**School** DuBois School  
**Address** 330 E. 133rd Street

**Unit** 26601  
Chicago, IL, 60627

**Building ID** 8010  
**Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

### *Management Planner's Comments Summarized at the End of the Report*

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
02	Stucco Ceiling	3,600	SF	Bldg 1968, All-Purpose Room	Assumed	SURFACE	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
04	9"x9" Beige Floor Tile	10,500	SF	1st Floor Rooms and Rooms 210, 212, 214, MDF Room 2nd floor, Room 112, 111, 101, 109	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
05	12"x12" Beige Floor Tile	5,700	SF	1st and 2nd Floor Corridors and Lunchroom, Main office waiting area, Faculty lunchroom, and Room 103	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
06	12"x12" Beige Floor Tile Mastic	5,700	SF	1st and 2nd Floor Corridors and Lunchroom, Main office and waiting area, Faculty lunchroom, and Room 103	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
07	9"x9" Beige Floor Tile Mastic	10,500	SF	1st Floor Rooms and Rooms 210, 212, 214, 2nd Floor MDF Room 112, Room 111, Room 109, Room 101	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
08	Hardcoat Plaster - NOT OBSERVED	6,000	SF	Throughout Building 1937	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	
09	2' x 4' Ceiling Tile - NOT OBSERVED	5,440	SF	Throughout Building 1937	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
10	9"x9" Brown Floor Tile (NOT OBSERVED)	150	SF	Room 101, 9x9 pink and 9x9 beige	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	
11	9"x9" Floor Tile Mastic	150	SF	Bldg 1968 - Room 101--NOT OBSERVED	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
12	9"x9" Green Floor Tile	3,500	SF	1st Floor Classrooms, Rooms 103, 108, 113	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
13	9"x9" Green Floor Tile Mastic	3,500	SF	1st Floor Classrooms, Rooms 103, 108, 113	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
14	9"x9" Green Floor Tile- NOT OBSERVED	80	SF	Basement Engineer's Office (1937)	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	
15	9"x9" Green Floor Tile Mastic - NOT OBSERVED	80	SF	Basement Engineer's Office (1937)	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	
16	9"x9" Gray Floor Tile	1,450	SF	Bldg 1968 - Counsellor's Room, 1st Floor Offices, 1st and 2nd floor storage rooms, Vault and Lunchroom storage room	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
17	9"x9" Gray Floor Tile Mastic	1,450	SF	Bldg 1968 - Counsellor's Room, 1st Floor Offices, 1st and 2nd Floor storage rooms, vault and Lunchroom storage room	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
18	9"x9" Pink Floor Tile (NOT OBSERVED); peach floor tile in room	1,050	SF	1st Floor stage storage room, Room 101	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	
19	9"x9" Pink Floor Tile Mastic (NOT	1,050	SF	1st floor storage room, Room 101	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	

# Chicago Public Schools

**School** DuBois School  
**Address** 330 E. 133rd Street

**Unit** 26601  
Chicago, IL, 60627

**Building ID** 8010  
**Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
	OBSERVED);peach floor tile in room										
20	9"x9" Tan Floor Tile	600	SF	Rooms 208, 213, Engineers office 1968 building	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
21	9"x9" Tan Floor Tile Mastic	600	SF	Rooms 208, 213, Engineers office, 1968 Building	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
22	12"x12" Beige Floor Tile- DUPLICATE of HA 05	5,670	SF	1st and 2nd Floor Corridors and Lunchroom	Assumed	MISC		0	SF	6 ACBM with the potential for damage	Follow O&M Plan
23	12"x12" Beige Floor Tile Mastic- DUPLICATE of HA 06	5,670	SF	1st and 2nd Floor Corridors and Lunchroom	Assumed	MISC		0	SF	6 ACBM with the potential for damage	Follow O&M Plan
24	12"x12" Black Floor Tile	3,515	SF	1st and 2nd Floor Corridors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
25	12"x12"Black Floor Tile Mastic	3,515	SF	1st and 2nd Floor Corridors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
26	Black Vinyl Baseboard	320	LF	School Offices	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
27	Black Vinyl Baseboard Mastic	320	LF	School Offices	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
28	Blue Carpet Mastic	1,000	SF	School Offices and LIBRARY, Carpet removed in room 209 and 211	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
29	Brown Carpet Mastic	700	SF	Main Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
30	Insulation in Fire Rated Doors - NOT OBSERVED	2	EA	Boiler Room (1937)	Assumed	TSI	No	0	EA	6 ACBM with the potential for damage	
31	12 x 12 White with Blue, Red and Yellow Specks Floor Tile	1,700	SF	Bldg 1968 - Room 209, 211	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
31M	12 x 12 White with Blue, Red and Yellow Specks Floor Tile Mastic	1,700	SF	Bldg 1968 - Room 209, 211	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
32	White with Black Terrazzo	900	SF	1968 Bldg - NE and SE Stairwells, Lobby	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
33	Green Mosaic Ceramic Tile Grout	640	SF	1968 Bldg - 1st and 2nd Floor Boys and Girls Washrooms	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
34	Green Mosaic Ceramic Tile Adhesive	640	SF	1968 Bldg - 1st and 2nd Floor Boys and Girls Washrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
35	Yellow Mosaic Ceramic Tile Grout	170	SF	1968 Bldg - 1st and 2nd Floor Teachers Washrooms, Office Restroom, 101 and 103 Restrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
36	Yellow Mosaic Ceramic Tile Adhesive	170	SF	1968 Bldg - 1st and 2nd Floor Teachers Washrooms, Office Restroom, 101 and 103 Restrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
37	Plaster Ceiling	1,800	SF	Boiler Room, All Washrooms, 1st and 2nd Floor Storage Rooms	Assumed	SURFACE	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
38	Brown Mosaic Ceramic Tile Grout	230	SF	1968 Bldg - North, South and East	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** DuBois School  
**Address** 330 E. 133rd Street

**Unit** 26601  
Chicago, IL, 60627

**Building ID** 8010  
**Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				Vestibules							
39	Brown Mosaic Ceramic Tile Adhesive	230	SF	1968 Bldg - North, South and East Vestibules	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
40	12 x 12 Light Brown Floor Tile - NOT OBSERVED	6,800	SF	1937 Bldg - Throughout 1st Floor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
40M	12 x 12 Light Brown Floor Tile Mastic - NOT OBSERVED	6,800	SF	1937 Bldg - Throughout 1st Floor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
41	Brown Mosaic Ceramic Tile Grout - NOT OBSERVED	800	SF	1937 Bldg - 1st Floor Vestibules, Boys and Girls Washrooms	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	
42	Brown Mosaic Ceramic Tile Adhesive - NOT OBSERVED	800	SF	1937 Bldg - 1st Floor Vestibules, Boys and Girls Washrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
43	Mag Pipe Insulation - NOT OBSERVED	30	LF	1937 Bldg - Boiler Room	Assumed	TSI	Yes	0	LF	6 ACBM with the potential for damage	
44	Hard Fittings on Fiberglass - NOT OBSERVED	30	LF	1937 Bldg - Boiler Room	Assumed	TSI	Yes	0	LF	6 ACBM with the potential for damage	
45	2 x 4 White Fissured Ceiling Tile	45,000	SF	1968 Bldg - Throughout	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
46	9x9 Blue VFT	25	SF	2nd fl. janitors closet 1968 bldg	Assumed	MISC	No	1	SF	6 ACBM with the potential for damage	Repair
47	9x9 Blue floor tile mastic	25	SF	2nd fl janitors- 1968 bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
48	2x4 white ceiling tile	3,500	SF	lunch room bldg 1968 faculty lunchroom bldg 1968 rm 103 bldg 1968 rm 101 bldg 1968	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
49	12x12 beige w/ tan specs VFT	400	SF	rm 134 bldg 1968	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
50	12x12 beige w/ tan specs mastic	400	SF	rm 134- 1968 bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
A	Aircell Pipe Insulation - NO ACCESS; NOT OBSERVED	200	LF	Basement Building 1937	Chrysotile	TSI	Yes	10	LF	1 Damaged or significantly damaged friable thermal system insulating ACBM	Repair
B	MJP E/F/V on Aircell Pipe Insulation - NOT OBSERVED	25	LF	Basement, Building 1937	Amosite	TSI	Yes	0	LF	6 ACBM with the potential for damage	
D	MJP E/F/V on Fiberglass Pipe Insulation-- Abated			2nd Floor Boiler Room, 1st fl. fan Rm	Abated	TSI					
E	MJP E/F/V on Fiberglass Pipe Insulation - Duplicate	45	LF	1st Floor Storage Room	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	
F	Cardboard Pipe Insulation - NO ACCESS; NOT OBSERVED	200	LF	Tunnel Area, Building 1937	Assumed	TSI	Yes	5	LF	1 Damaged or significantly damaged friable thermal system insulating ACBM	Repair
I	Cementitious Duct Insulation - NOT OBSERVED	150	SF	Basement Building 1937	Chrysotile	TSI	Yes	0	SF	6 ACBM with the potential for damage	
J	Vibration Dampner	10	LF	Fan Room, Pipe Chase, 2nd Floor Boiler Room	Assumed	TSI		0	LF	6 ACBM with the potential for damage	Follow O&M Plan
K	Furnace Gasket Insulation - NOT OBSERVED	5	LF	Basement Building 1937	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	
L	MJP E/F/V on Paperwrap Pipe Insulation - NOT OBSERVED	15	LF	Basement Building 1937	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	



# Chicago Public Schools

**School** DuBois School  
**Address** 330 E. 133rd Street

**Unit** 26601  
 Chicago, IL, 60627

**Building ID** 8010  
**Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

### *Management Planner's Comments Summarized at the End of the Report*

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
M	PIPEJOINTS - NOT OBSERVED	20	LF	2ND Floor Boiler Room and Fan Room (PRIMARY BLDG.)	Assumed	TSI	No	0	LF	6 ACBM with the potential for damage	
N	DUCT WRAP	150	SF	2ND FLR BOILER ROOM (PRIMARY BLDG.) AND FAN UNIT	Assumed	TSI	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Review Date 5/20/2016

HA Number	Management Comments
-----------	---------------------

# Chicago Public Schools

**School** DuBois School  
**Address** 330 E. 133rd Street

**Unit** 26601  
 Chicago, IL, 60627

**Building ID** 8010  
**Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

### *Management Planner's Comments Summarized at the End of the Report*

Manager Planner Name	Guillermo Garcia
100-01786	3/21/2017
Manager IDPH License No/Expiration	

HA Number	Management Comments
02	
04	
05	
06	
07	
08	
09	
10	
11	
12	
13	
14	
15	
16	
17	
18	
19	
20	
21	
22	
23	
24	
25	
26	
27	
28	
29	

# Chicago Public Schools

**School** DuBois School  
**Address** 330 E. 133rd Street

**Unit** 26601  
 Chicago, IL, 60627

**Building ID** 8010  
**Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

***Management Planner's Comments Summarized at the End of the Report***

HA Number	Management Comments
30	
31	
31M	
32	
33	
34	
35	
36	
37	
38	
39	
40	
40M	
41	
42	
43	
44	
45	
46	
47	
48	
49	
50	
A	
B	
D	
E	

# Chicago Public Schools

**School** DuBois School  
**Address** 330 E. 133rd Street

**Unit** 26601  
Chicago, IL, 60627

**Building ID** 8010  
**Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
F	
I	
J	
K	
L	
M	
N	

# Chicago Public Schools

GSG Consultants, Inc.

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26601** BUIDLING ID: **8010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**  
SCHOOL NAME: **DuBois School** INSPECTION DATE: **2/24/2016**  
ADDRESS: **330 E. 133rd Street** IDPH LICENSE NO: **100-18790**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **02**  
MATERIAL DESCRIPTION: **Stucco Ceiling**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON: **Deterioration**  
HISTORICAL RESPONSE ACTION: **Repair**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Bldg 1968, All-Purpose Room**

MATERIAL QUANTITY: **3600**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 02/24/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26601** BUIDLING ID: **8010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **DuBois School** REVIEW DATE: **5/20/2016**  
ADDRESS: **330 E. 133rd Street** IDPH LICENSE NO: **100-18790**

---

HOMOGENEOUS AREA: **02**  
MATERIAL DESCRIPTION: **Stucco Ceiling**  
MATERIAL LOCATION: **Bldg 1968, All-Purpose Room**  
MATERIAL QUANTITY: **3600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/20/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26601** BUIDLING ID: **8010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**  
SCHOOL NAME: **DuBois School** INSPECTION DATE: **2/24/2016**  
ADDRESS: **330 E. 133rd Street** IDPH LICENSE NO: **100-18790**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **04**  
MATERIAL DESCRIPTION: **9"x9" Beige Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **1st Floor Rooms and Rooms 210, 212, 214, MDF Room 2nd floor, Room 112, 111, 101, 109**

MATERIAL QUANTITY: **10500**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 02/24/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26601** BUIDLING ID: **8010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **DuBois School** REVIEW DATE: **5/20/2016**  
ADDRESS: **330 E. 133rd Street** IDPH LICENSE NO: **100-18790**

---

HOMOGENEOUS AREA: **04**  
MATERIAL DESCRIPTION: **9"x9" Beige Floor Tile**  
MATERIAL LOCATION: **1st Floor Rooms and Rooms 210, 212, 214, MDF Room 2nd floor, Room 112, 111, 101, 109**  
MATERIAL QUANTITY: **10500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/20/2016**



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26601** BUIDLING ID: **8010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**  
SCHOOL NAME: **DuBois School** INSPECTION DATE: **2/24/2016**  
ADDRESS: **330 E. 133rd Street** IDPH LICENSE NO: **100-18790**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **05**  
MATERIAL DESCRIPTION: **12"x12" Beige Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **1st and 2nd Floor Corridors and Lunchroom, Main office waiting area, Faculty lunchroom, and Room 103**

MATERIAL QUANTITY: **5700** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 02/24/2016

# Chicago Public Schools

GSG Consultants, Inc.

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26601** BUIDLING ID: **8010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **DuBois School** REVIEW DATE: **5/20/2016**  
ADDRESS: **330 E. 133rd Street** IDPH LICENSE NO: **100-18790**

---

HOMOGENEOUS AREA: **05**  
MATERIAL DESCRIPTION: **12"x12" Beige Floor Tile**  
MATERIAL LOCATION: **1st and 2nd Floor Corridors and Lunchroom, Main office waiting area, Faculty lunchroom, and Room 103**  
MATERIAL QUANTITY: **5700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/20/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26601** BUIDLING ID: **8010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**  
SCHOOL NAME: **DuBois School** INSPECTION DATE: **2/24/2016**  
ADDRESS: **330 E. 133rd Street** IDPH LICENSE NO: **100-18790**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **06**  
MATERIAL DESCRIPTION: **12"x12" Beige Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st and 2nd Floor Corridors and Lunchroom, Main office and waiting area, Faculty lunchroom, and Room 103**

MATERIAL QUANTITY: **5700** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 02/24/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26601** BUIDLING ID: **8010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **DuBois School** REVIEW DATE: **5/20/2016**  
ADDRESS: **330 E. 133rd Street** IDPH LICENSE NO: **100-18790**

---

HOMOGENEOUS AREA: **06**  
MATERIAL DESCRIPTION: **12"x12" Beige Floor Tile Mastic**  
MATERIAL LOCATION: **1st and 2nd Floor Corridors and Lunchroom, Main office and waiting area, Faculty lunchroom, and Room 103**  
MATERIAL QUANTITY: **5700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/20/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26601** BUIDLING ID: **8010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**  
SCHOOL NAME: **DuBois School** INSPECTION DATE: **2/24/2016**  
ADDRESS: **330 E. 133rd Street** IDPH LICENSE NO: **100-18790**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **07**  
MATERIAL DESCRIPTION: **9"x9" Beige Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st Floor Rooms and Rooms 210, 212, 214, 2nd Floor MDF Room 112, Room 111, Room 109, Room 101**

MATERIAL QUANTITY: **10500**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 02/24/2016

# Chicago Public Schools

GSG Consultants, Inc.

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26601** BUIDLING ID: **8010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **DuBois School** REVIEW DATE: **5/20/2016**  
ADDRESS: **330 E. 133rd Street** IDPH LICENSE NO: **100-18790**

---

HOMOGENEOUS AREA: **07**  
MATERIAL DESCRIPTION: **9"x9" Beige Floor Tile Mastic**  
MATERIAL LOCATION: **1st Floor Rooms and Rooms 210, 212, 214, 2nd Floor MDF Room 112, Room 111, Room 109, Room 101**  
MATERIAL QUANTITY: **10500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/20/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26601** BUIDLING ID: **8010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**  
SCHOOL NAME: **DuBois School** INSPECTION DATE: **2/24/2016**  
ADDRESS: **330 E. 133rd Street** IDPH LICENSE NO: **100-18790**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **08**  
MATERIAL DESCRIPTION: **Hardcoat Plaster - NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Throughout Building 1937**  
MATERIAL QUANTITY: **6000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **- NOT OBSERVED**

Inspector's Signature: \_\_\_\_\_ Date: 02/24/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26601** BUILDING ID: **8010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **DuBois School** REVIEW DATE: **5/20/2016**  
ADDRESS: **330 E. 133rd Street** IDPH LICENSE NO: **100-18790**

---

HOMOGENEOUS AREA: **08**  
MATERIAL DESCRIPTION: **Hardcoat Plaster - NOT OBSERVED**  
MATERIAL LOCATION: **Throughout Building 1937**  
MATERIAL QUANTITY: **6000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/20/2016**



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26601** BUIDLING ID: **8010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**  
SCHOOL NAME: **DuBois School** INSPECTION DATE: **2/24/2016**  
ADDRESS: **330 E. 133rd Street** IDPH LICENSE NO: **100-18790**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **09**  
MATERIAL DESCRIPTION: **2' x 4' Ceiling Tile - NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout Building 1937**  
MATERIAL QUANTITY: **5440** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **- NOT OBSERVED**

Inspector's Signature: \_\_\_\_\_ Date: 02/24/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26601** BUIDLING ID: **8010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **DuBois School** REVIEW DATE: **5/20/2016**  
ADDRESS: **330 E. 133rd Street** IDPH LICENSE NO: **100-18790**

---

HOMOGENEOUS AREA: **09**  
MATERIAL DESCRIPTION: **2' x 4' Ceiling Tile - NOT OBSERVED**  
MATERIAL LOCATION: **Throughout Building 1937**  
MATERIAL QUANTITY: **5440** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/20/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26601** BUIDLING ID: **8010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**  
SCHOOL NAME: **DuBois School** INSPECTION DATE: **2/24/2016**  
ADDRESS: **330 E. 133rd Street** IDPH LICENSE NO: **100-18790**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10**  
MATERIAL DESCRIPTION: **9"x9" Brown Floor Tile (NOT OBSERVED)**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 101, 9x9 pink and 9x9 beige**

MATERIAL QUANTITY: **150**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 02/24/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26601** BUILDING ID: **8010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **DuBois School** REVIEW DATE: **5/20/2016**  
ADDRESS: **330 E. 133rd Street** IDPH LICENSE NO: **100-18790**

---

HOMOGENEOUS AREA: **10**  
MATERIAL DESCRIPTION: **9"x9" Brown Floor Tile (NOT OBSERVED)**  
MATERIAL LOCATION: **Room 101, 9x9 pink and 9x9 beige**  
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/20/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26601** BUIDLING ID: **8010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**  
SCHOOL NAME: **DuBois School** INSPECTION DATE: **2/24/2016**  
ADDRESS: **330 E. 133rd Street** IDPH LICENSE NO: **100-18790**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11**  
MATERIAL DESCRIPTION: **9"x9" Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Bldg 1968 - Room 101--NOT OBSERVED**  
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 02/24/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26601** BUIDLING ID: **8010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **DuBois School** REVIEW DATE: **5/20/2016**  
ADDRESS: **330 E. 133rd Street** IDPH LICENSE NO: **100-18790**

---

HOMOGENEOUS AREA: **11**  
MATERIAL DESCRIPTION: **9"x9" Floor Tile Mastic**  
MATERIAL LOCATION: **Bldg 1968 - Room 101--NOT OBSERVED**  
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/20/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26601** BUIDLING ID: **8010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**  
SCHOOL NAME: **DuBois School** INSPECTION DATE: **2/24/2016**  
ADDRESS: **330 E. 133rd Street** IDPH LICENSE NO: **100-18790**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12**  
MATERIAL DESCRIPTION: **9"x9" Green Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **1st Floor Classrooms, Rooms 103, 108, 113**  
MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 02/24/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26601** BUIDLING ID: **8010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **DuBois School** REVIEW DATE: **5/20/2016**  
ADDRESS: **330 E. 133rd Street** IDPH LICENSE NO: **100-18790**

---

HOMOGENEOUS AREA: **12**  
MATERIAL DESCRIPTION: **9"x9" Green Floor Tile**  
MATERIAL LOCATION: **1st Floor Classrooms, Rooms 103, 108, 113**  
MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/20/2016**



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26601** BUIDLING ID: **8010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**  
SCHOOL NAME: **DuBois School** INSPECTION DATE: **2/24/2016**  
ADDRESS: **330 E. 133rd Street** IDPH LICENSE NO: **100-18790**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13**  
MATERIAL DESCRIPTION: **9"x9" Green Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st Floor Classrooms, Rooms 103, 108, 113**

MATERIAL QUANTITY: **3500**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 02/24/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26601** BUIDLING ID: **8010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **DuBois School** REVIEW DATE: **5/20/2016**  
ADDRESS: **330 E. 133rd Street** IDPH LICENSE NO: **100-18790**

---

HOMOGENEOUS AREA: **13**  
MATERIAL DESCRIPTION: **9"x9" Green Floor Tile Mastic**  
MATERIAL LOCATION: **1st Floor Classrooms, Rooms 103, 108, 113**  
MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/20/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26601** BUIDLING ID: **8010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**  
SCHOOL NAME: **DuBois School** INSPECTION DATE: **2/24/2016**  
ADDRESS: **330 E. 133rd Street** IDPH LICENSE NO: **100-18790**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14**  
MATERIAL DESCRIPTION: **9"x9" Green Floor Tile- NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Basement Engineer's Office (1937)**

MATERIAL QUANTITY: **80**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **- NOT OBSERVED**

Inspector's Signature: \_\_\_\_\_

Date: 02/24/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26601** BUILDING ID: **8010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **DuBois School** REVIEW DATE: **5/20/2016**  
ADDRESS: **330 E. 133rd Street** IDPH LICENSE NO: **100-18790**

---

HOMOGENEOUS AREA: **14**  
MATERIAL DESCRIPTION: **9"x9" Green Floor Tile- NOT OBSERVED**  
MATERIAL LOCATION: **Basement Engineer's Office (1937)**  
MATERIAL QUANTITY: **80** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/20/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26601** BUIDLING ID: **8010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**  
SCHOOL NAME: **DuBois School** INSPECTION DATE: **2/24/2016**  
ADDRESS: **330 E. 133rd Street** IDPH LICENSE NO: **100-18790**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15**  
MATERIAL DESCRIPTION: **9"x9" Green Floor Tile Mastic - NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Basement Engineer's Office (1937)**

MATERIAL QUANTITY: **80** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 02/24/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26601** BUIDLING ID: **8010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **DuBois School** REVIEW DATE: **5/20/2016**  
ADDRESS: **330 E. 133rd Street** IDPH LICENSE NO: **100-18790**

---

HOMOGENEOUS AREA: **15**  
MATERIAL DESCRIPTION: **9"x9" Green Floor Tile Mastic - NOT OBSERVED**  
MATERIAL LOCATION: **Basement Engineer's Office (1937)**  
MATERIAL QUANTITY: **80** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/20/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26601** BUIDLING ID: **8010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**  
SCHOOL NAME: **DuBois School** INSPECTION DATE: **2/24/2016**  
ADDRESS: **330 E. 133rd Street** IDPH LICENSE NO: **100-18790**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16**  
MATERIAL DESCRIPTION: **9"x9" Gray Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Bldg 1968 - Counsellor's Room, 1st Floor Offices, 1st and 2nd floor storage rooms, Vault and Lunchroom storage room**

MATERIAL QUANTITY: **1450** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 02/24/2016

# Chicago Public Schools

GSG Consultants, Inc.

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26601** BUIDLING ID: **8010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **DuBois School** REVIEW DATE: **5/20/2016**  
ADDRESS: **330 E. 133rd Street** IDPH LICENSE NO: **100-18790**

---

HOMOGENEOUS AREA: **16**  
MATERIAL DESCRIPTION: **9"x9" Gray Floor Tile**  
MATERIAL LOCATION: **Bldg 1968 - Counsellor's Room, 1st Floor Offices, 1st and 2nd floor storage rooms, Vault and Lunchroom storage room**  
MATERIAL QUANTITY: **1450** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/20/2016**



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26601** BUIDLING ID: **8010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**  
SCHOOL NAME: **DuBois School** INSPECTION DATE: **2/24/2016**  
ADDRESS: **330 E. 133rd Street** IDPH LICENSE NO: **100-18790**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17**  
MATERIAL DESCRIPTION: **9"x9" Gray Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Bldg 1968 - Counsellor's Room, 1st Floor Offices, 1st and 2nd Floor storage rooms, vault and Lunchroom storage room**

MATERIAL QUANTITY: **1450** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 02/24/2016

# Chicago Public Schools

GSG Consultants, Inc.

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26601** BUIDLING ID: **8010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **DuBois School** REVIEW DATE: **5/20/2016**  
ADDRESS: **330 E. 133rd Street** IDPH LICENSE NO: **100-18790**

---

HOMOGENEOUS AREA: **17**  
MATERIAL DESCRIPTION: **9"x9" Gray Floor Tile Mastic**  
MATERIAL LOCATION: **Bldg 1968 - Counsellor's Room, 1st Floor Offices, 1st and 2nd Floor storage rooms, vault and Lunchroom storage room**  
MATERIAL QUANTITY: **1450** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/20/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26601** BUIDLING ID: **8010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**  
SCHOOL NAME: **DuBois School** INSPECTION DATE: **2/24/2016**  
ADDRESS: **330 E. 133rd Street** IDPH LICENSE NO: **100-18790**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18**  
MATERIAL DESCRIPTION: **9"x9" Pink Floor Tile (NOT OBSERVED); peach floor tile in room**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **1st Floor stage storage room, Room 101**  
MATERIAL QUANTITY: **1050** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **Pink not observed- peach floor tile in room**

Inspector's Signature: \_\_\_\_\_ Date: 02/24/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26601** BUIDLING ID: **8010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **DuBois School** REVIEW DATE: **5/20/2016**  
ADDRESS: **330 E. 133rd Street** IDPH LICENSE NO: **100-18790**

---

HOMOGENEOUS AREA: **18**  
MATERIAL DESCRIPTION: **9"x9" Pink Floor Tile (NOT OBSERVED); peach floor tile in room**  
MATERIAL LOCATION: **1st Floor stage storage room, Room 101**  
MATERIAL QUANTITY: **1050** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/20/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26601** BUIDLING ID: **8010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**  
SCHOOL NAME: **DuBois School** INSPECTION DATE: **2/24/2016**  
ADDRESS: **330 E. 133rd Street** IDPH LICENSE NO: **100-18790**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19**  
MATERIAL DESCRIPTION: **9"x9" Pink Floor Tile Mastic (NOT OBSERVED);peach floor tile in room**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **1st floor storage room, Room 101**  
MATERIAL QUANTITY: **1050** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **Pink not observed- peach floor tile in storage, gym storage**

Inspector's Signature: \_\_\_\_\_ Date: 02/24/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26601** BUILDING ID: **8010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **DuBois School** REVIEW DATE: **5/20/2016**  
ADDRESS: **330 E. 133rd Street** IDPH LICENSE NO: **100-18790**

---

HOMOGENEOUS AREA: **19**  
MATERIAL DESCRIPTION: **9"x9" Pink Floor Tile Mastic (NOT OBSERVED);peach floor tile in room**  
MATERIAL LOCATION: **1st floor storage room, Room 101**  
MATERIAL QUANTITY: **1050** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/20/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26601** BUIDLING ID: **8010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**  
SCHOOL NAME: **DuBois School** INSPECTION DATE: **2/24/2016**  
ADDRESS: **330 E. 133rd Street** IDPH LICENSE NO: **100-18790**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**  
MATERIAL DESCRIPTION: **9"x9" Tan Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Rooms 208, 213, Engineers office 1968 building**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 02/24/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26601** BUIDLING ID: **8010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **DuBois School** REVIEW DATE: **5/20/2016**  
ADDRESS: **330 E. 133rd Street** IDPH LICENSE NO: **100-18790**

---

HOMOGENEOUS AREA: **20**  
MATERIAL DESCRIPTION: **9"x9" Tan Floor Tile**  
MATERIAL LOCATION: **Rooms 208, 213, Engineers office 1968 building**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/20/2016**



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26601** BUIDLING ID: **8010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**  
SCHOOL NAME: **DuBois School** INSPECTION DATE: **2/24/2016**  
ADDRESS: **330 E. 133rd Street** IDPH LICENSE NO: **100-18790**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21**  
MATERIAL DESCRIPTION: **9"x9" Tan Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 208, 213, Engineers office, 1968 Building**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 02/24/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26601** BUIDLING ID: **8010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **DuBois School** REVIEW DATE: **5/20/2016**  
ADDRESS: **330 E. 133rd Street** IDPH LICENSE NO: **100-18790**

---

HOMOGENEOUS AREA: **21**  
MATERIAL DESCRIPTION: **9"x9" Tan Floor Tile Mastic**  
MATERIAL LOCATION: **Rooms 208, 213, Engineers office, 1968 Building**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/20/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26601** BUIDLING ID: **8010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**  
SCHOOL NAME: **DuBois School** INSPECTION DATE: **2/24/2016**  
ADDRESS: **330 E. 133rd Street** IDPH LICENSE NO: **100-18790**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22**  
MATERIAL DESCRIPTION: **12"x12" Beige Floor Tile- DUPLICATE of HA 05**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **1st and 2nd Floor Corridors and Lunchroom**  
MATERIAL QUANTITY: **5670** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 02/24/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26601** BUILDING ID: **8010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **DuBois School** REVIEW DATE: **5/20/2016**  
ADDRESS: **330 E. 133rd Street** IDPH LICENSE NO: **100-18790**

---

HOMOGENEOUS AREA: **22**  
MATERIAL DESCRIPTION: **12"x12" Beige Floor Tile- DUPLICATE of HA 05**  
MATERIAL LOCATION: **1st and 2nd Floor Corridors and Lunchroom**  
MATERIAL QUANTITY: **5670** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/20/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **26601**    BUIDLING ID: **8010**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Allizon Brooks**  
SCHOOL NAME: **DuBois School**    INSPECTION DATE: **2/24/2016**  
ADDRESS: **330 E. 133rd Street**    IDPH LICENSE NO: **100-18790**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23**  
MATERIAL DESCRIPTION: **12"x12" Beige Floor Tile Mastic- DUPLICATE of HA 06**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st and 2nd Floor Corridors and Lunchroom**  
MATERIAL QUANTITY: **5670**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY:    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **02/24/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26601** BUIDLING ID: **8010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **DuBois School** REVIEW DATE: **5/20/2016**  
ADDRESS: **330 E. 133rd Street** IDPH LICENSE NO: **100-18790**

---

HOMOGENEOUS AREA: **23**  
MATERIAL DESCRIPTION: **12"x12" Beige Floor Tile Mastic- DUPLICATE of HA 06**  
MATERIAL LOCATION: **1st and 2nd Floor Corridors and Lunchroom**  
MATERIAL QUANTITY: **5670** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/20/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26601** BUIDLING ID: **8010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**  
SCHOOL NAME: **DuBois School** INSPECTION DATE: **2/24/2016**  
ADDRESS: **330 E. 133rd Street** IDPH LICENSE NO: **100-18790**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **24**  
MATERIAL DESCRIPTION: **12"x12" Black Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **1st and 2nd Floor Corridors**  
MATERIAL QUANTITY: **3515** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 02/24/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26601** BUIDLING ID: **8010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **DuBois School** REVIEW DATE: **5/20/2016**  
ADDRESS: **330 E. 133rd Street** IDPH LICENSE NO: **100-18790**

---

HOMOGENEOUS AREA: **24**  
MATERIAL DESCRIPTION: **12"x12" Black Floor Tile**  
MATERIAL LOCATION: **1st and 2nd Floor Corridors**  
MATERIAL QUANTITY: **3515** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/20/2016**



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26601** BUIDLING ID: **8010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**  
SCHOOL NAME: **DuBois School** INSPECTION DATE: **2/24/2016**  
ADDRESS: **330 E. 133rd Street** IDPH LICENSE NO: **100-18790**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25**  
MATERIAL DESCRIPTION: **12"x12"Black Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st and 2nd Floor Corridors**  
MATERIAL QUANTITY: **3515** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 02/24/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26601** BUIDLING ID: **8010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **DuBois School** REVIEW DATE: **5/20/2016**  
ADDRESS: **330 E. 133rd Street** IDPH LICENSE NO: **100-18790**

---

HOMOGENEOUS AREA: **25**  
MATERIAL DESCRIPTION: **12"x12"Black Floor Tile Mastic**  
MATERIAL LOCATION: **1st and 2nd Floor Corridors**  
MATERIAL QUANTITY: **3515** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/20/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26601** BUIDLING ID: **8010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**  
SCHOOL NAME: **DuBois School** INSPECTION DATE: **2/24/2016**  
ADDRESS: **330 E. 133rd Street** IDPH LICENSE NO: **100-18790**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26**  
MATERIAL DESCRIPTION: **Black Vinyl Baseboard**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **School Offices**  
MATERIAL QUANTITY: **320** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 02/24/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26601** BUIDLING ID: **8010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **DuBois School** REVIEW DATE: **5/20/2016**  
ADDRESS: **330 E. 133rd Street** IDPH LICENSE NO: **100-18790**

---

HOMOGENEOUS AREA: **26**  
MATERIAL DESCRIPTION: **Black Vinyl Baseboard**  
MATERIAL LOCATION: **School Offices**  
MATERIAL QUANTITY: **320** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/20/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26601** BUIDLING ID: **8010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**  
SCHOOL NAME: **DuBois School** INSPECTION DATE: **2/24/2016**  
ADDRESS: **330 E. 133rd Street** IDPH LICENSE NO: **100-18790**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27**  
MATERIAL DESCRIPTION: **Black Vinyl Baseboard Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **School Offices**

MATERIAL QUANTITY: **320**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 02/24/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26601** BUIDLING ID: **8010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **DuBois School** REVIEW DATE: **5/20/2016**  
ADDRESS: **330 E. 133rd Street** IDPH LICENSE NO: **100-18790**

---

HOMOGENEOUS AREA: **27**  
MATERIAL DESCRIPTION: **Black Vinyl Baseboard Mastic**  
MATERIAL LOCATION: **School Offices**  
MATERIAL QUANTITY: **320** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/20/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26601** BUIDLING ID: **8010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**  
SCHOOL NAME: **DuBois School** INSPECTION DATE: **2/24/2016**  
ADDRESS: **330 E. 133rd Street** IDPH LICENSE NO: **100-18790**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28**  
MATERIAL DESCRIPTION: **Blue Carpet Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **School Offices and LIBRARY, Carpet removed in room 209 and 211**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 02/24/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26601** BUIDLING ID: **8010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **DuBois School** REVIEW DATE: **5/20/2016**  
ADDRESS: **330 E. 133rd Street** IDPH LICENSE NO: **100-18790**

---

HOMOGENEOUS AREA: **28**  
MATERIAL DESCRIPTION: **Blue Carpet Mastic**  
MATERIAL LOCATION: **School Offices and LIBRARY, Carpet removed in room 209 and 211**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/20/2016**



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26601** BUIDLING ID: **8010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**  
SCHOOL NAME: **DuBois School** INSPECTION DATE: **2/24/2016**  
ADDRESS: **330 E. 133rd Street** IDPH LICENSE NO: **100-18790**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **29**  
MATERIAL DESCRIPTION: **Brown Carpet Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Main Office**  
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 02/24/2016

# Chicago Public Schools

GSG Consultants, Inc.

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26601** BUIDLING ID: **8010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **DuBois School** REVIEW DATE: **5/20/2016**  
ADDRESS: **330 E. 133rd Street** IDPH LICENSE NO: **100-18790**

---

HOMOGENEOUS AREA: **29**

MATERIAL DESCRIPTION: **Brown Carpet Mastic**

MATERIAL LOCATION: **Main Office**

MATERIAL QUANTITY: **700**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/20/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26601** BUIDLING ID: **8010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**  
SCHOOL NAME: **DuBois School** INSPECTION DATE: **2/24/2016**  
ADDRESS: **330 E. 133rd Street** IDPH LICENSE NO: **100-18790**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **30**  
MATERIAL DESCRIPTION: **Insulation in Fire Rated Doors - NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Boiler Room (1937)**  
MATERIAL QUANTITY: **2** MATERIAL UNITS: **EA**  
DAMAGE QUANTITY: DAMAGE UNITS: **EA**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 02/24/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26601** BUIDLING ID: **8010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **DuBois School** REVIEW DATE: **5/20/2016**  
ADDRESS: **330 E. 133rd Street** IDPH LICENSE NO: **100-18790**

---

HOMOGENEOUS AREA: **30**  
MATERIAL DESCRIPTION: **Insulation in Fire Rated Doors - NOT OBSERVED**  
MATERIAL LOCATION: **Boiler Room (1937)**  
MATERIAL QUANTITY: **2** MATERIAL UNITS: **EA**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 05/20/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26601** BUIDLING ID: **8010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**  
SCHOOL NAME: **DuBois School** INSPECTION DATE: **2/24/2016**  
ADDRESS: **330 E. 133rd Street** IDPH LICENSE NO: **100-18790**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **31**  
MATERIAL DESCRIPTION: **12 x 12 White with Blue, Red and Yellow Specks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Bldg 1968 - Room 209, 211**  
MATERIAL QUANTITY: **1700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 02/24/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26601** BUILDING ID: **8010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **DuBois School** REVIEW DATE: **5/20/2016**  
ADDRESS: **330 E. 133rd Street** IDPH LICENSE NO: **100-18790**

---

HOMOGENEOUS AREA: **31**  
MATERIAL DESCRIPTION: **12 x 12 White with Blue, Red and Yellow Specks Floor Tile**  
MATERIAL LOCATION: **Bldg 1968 - Room 209, 211**  
MATERIAL QUANTITY: **1700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/20/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26601** BUIDLING ID: **8010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**  
SCHOOL NAME: **DuBois School** INSPECTION DATE: **2/24/2016**  
ADDRESS: **330 E. 133rd Street** IDPH LICENSE NO: **100-18790**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **31M**  
MATERIAL DESCRIPTION: **12 x 12 White with Blue, Red and Yellow Specks Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Bldg 1968 - Room 209, 211**

MATERIAL QUANTITY: **1700**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 02/24/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26601** BUIDLING ID: **8010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **DuBois School** REVIEW DATE: **5/20/2016**  
ADDRESS: **330 E. 133rd Street** IDPH LICENSE NO: **100-18790**

---

HOMOGENEOUS AREA: **31M**  
MATERIAL DESCRIPTION: **12 x 12 White with Blue, Red and Yellow Specks Floor Tile Mastic**  
MATERIAL LOCATION: **Bldg 1968 - Room 209, 211**  
MATERIAL QUANTITY: **1700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/20/2016**



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26601** BUIDLING ID: **8010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**  
SCHOOL NAME: **DuBois School** INSPECTION DATE: **2/24/2016**  
ADDRESS: **330 E. 133rd Street** IDPH LICENSE NO: **100-18790**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **32**  
MATERIAL DESCRIPTION: **White with Black Terrazzo**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1968 Bldg - NE and SE Stairwells, Lobby**  
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 02/24/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26601** BUILDING ID: **8010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **DuBois School** REVIEW DATE: **5/20/2016**  
ADDRESS: **330 E. 133rd Street** IDPH LICENSE NO: **100-18790**

---

HOMOGENEOUS AREA: **32**  
MATERIAL DESCRIPTION: **White with Black Terrazzo**  
MATERIAL LOCATION: **1968 Bldg - NE and SE Stairwells, Lobby**  
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/20/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26601** BUIDLING ID: **8010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**  
SCHOOL NAME: **DuBois School** INSPECTION DATE: **2/24/2016**  
ADDRESS: **330 E. 133rd Street** IDPH LICENSE NO: **100-18790**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **33**  
MATERIAL DESCRIPTION: **Green Mosaic Ceramic Tile Grout**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1968 Bldg - 1st and 2nd Floor Boys and Girls Washrooms**  
MATERIAL QUANTITY: **640** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 02/24/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26601** BUIDLING ID: **8010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **DuBois School** REVIEW DATE: **5/20/2016**  
ADDRESS: **330 E. 133rd Street** IDPH LICENSE NO: **100-18790**

---

HOMOGENEOUS AREA: **33**  
MATERIAL DESCRIPTION: **Green Mosaic Ceramic Tile Grout**  
MATERIAL LOCATION: **1968 Bldg - 1st and 2nd Floor Boys and Girls Washrooms**  
MATERIAL QUANTITY: **640** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/20/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26601** BUIDLING ID: **8010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**  
SCHOOL NAME: **DuBois School** INSPECTION DATE: **2/24/2016**  
ADDRESS: **330 E. 133rd Street** IDPH LICENSE NO: **100-18790**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **34**  
MATERIAL DESCRIPTION: **Green Mosaic Ceramic Tile Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1968 Bldg - 1st and 2nd Floor Boys and Girls Washrooms**  
MATERIAL QUANTITY: **640** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 02/24/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26601** BUIDLING ID: **8010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **DuBois School** REVIEW DATE: **5/20/2016**  
ADDRESS: **330 E. 133rd Street** IDPH LICENSE NO: **100-18790**

---

HOMOGENEOUS AREA: **34**  
MATERIAL DESCRIPTION: **Green Mosaic Ceramic Tile Adhesive**  
MATERIAL LOCATION: **1968 Bldg - 1st and 2nd Floor Boys and Girls Washrooms**  
MATERIAL QUANTITY: **640** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/20/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26601** BUIDLING ID: **8010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**  
SCHOOL NAME: **DuBois School** INSPECTION DATE: **2/24/2016**  
ADDRESS: **330 E. 133rd Street** IDPH LICENSE NO: **100-18790**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **35**  
MATERIAL DESCRIPTION: **Yellow Mosaic Ceramic Tile Grout**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1968 Bldg - 1st and 2nd Floor Teachers Washrooms, Office Restroom, 101 and 103 Restrooms**

MATERIAL QUANTITY: **170** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 02/24/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26601** BUIDLING ID: **8010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **DuBois School** REVIEW DATE: **5/20/2016**  
ADDRESS: **330 E. 133rd Street** IDPH LICENSE NO: **100-18790**

---

HOMOGENEOUS AREA: **35**  
MATERIAL DESCRIPTION: **Yellow Mosaic Ceramic Tile Grout**  
MATERIAL LOCATION: **1968 Bldg - 1st and 2nd Floor Teachers Washrooms, Office Restroom, 101 and 103 Restrooms**  
MATERIAL QUANTITY: **170** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/20/2016**



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26601** BUIDLING ID: **8010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**  
SCHOOL NAME: **DuBois School** INSPECTION DATE: **2/24/2016**  
ADDRESS: **330 E. 133rd Street** IDPH LICENSE NO: **100-18790**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **36**  
MATERIAL DESCRIPTION: **Yellow Mosaic Ceramic Tile Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1968 Bldg - 1st and 2nd Floor Teachers Washrooms, Office Restroom, 101 and 103 Restrooms**

MATERIAL QUANTITY: **170** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 02/24/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26601** BUIDLING ID: **8010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **DuBois School** REVIEW DATE: **5/20/2016**  
ADDRESS: **330 E. 133rd Street** IDPH LICENSE NO: **100-18790**

---

HOMOGENEOUS AREA: **36**  
MATERIAL DESCRIPTION: **Yellow Mosaic Ceramic Tile Adhesive**  
MATERIAL LOCATION: **1968 Bldg - 1st and 2nd Floor Teachers Washrooms, Office Restroom, 101 and 103 Restrooms**  
MATERIAL QUANTITY: **170** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/20/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26601** BUIDLING ID: **8010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**  
SCHOOL NAME: **DuBois School** INSPECTION DATE: **2/24/2016**  
ADDRESS: **330 E. 133rd Street** IDPH LICENSE NO: **100-18790**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37**  
MATERIAL DESCRIPTION: **Plaster Ceiling**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Boiler Room, All Washrooms, 1st and 2nd Floor Storage Rooms**  
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 02/24/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26601** BUIDLING ID: **8010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **DuBois School** REVIEW DATE: **5/20/2016**  
ADDRESS: **330 E. 133rd Street** IDPH LICENSE NO: **100-18790**

---

HOMOGENEOUS AREA: **37**  
MATERIAL DESCRIPTION: **Plaster Ceiling**  
MATERIAL LOCATION: **Boiler Room, All Washrooms, 1st and 2nd Floor Storage Rooms**  
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/20/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26601** BUIDLING ID: **8010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**  
SCHOOL NAME: **DuBois School** INSPECTION DATE: **2/24/2016**  
ADDRESS: **330 E. 133rd Street** IDPH LICENSE NO: **100-18790**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **38**  
MATERIAL DESCRIPTION: **Brown Mosaic Ceramic Tile Grout**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1968 Bldg - North, South and East Vestibules**  
MATERIAL QUANTITY: **230** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 02/24/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26601** BUIDLING ID: **8010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **DuBois School** REVIEW DATE: **5/20/2016**  
ADDRESS: **330 E. 133rd Street** IDPH LICENSE NO: **100-18790**

---

HOMOGENEOUS AREA: **38**  
MATERIAL DESCRIPTION: **Brown Mosaic Ceramic Tile Grout**  
MATERIAL LOCATION: **1968 Bldg - North, South and East Vestibules**  
MATERIAL QUANTITY: **230** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/20/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26601** BUIDLING ID: **8010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**  
SCHOOL NAME: **DuBois School** INSPECTION DATE: **2/24/2016**  
ADDRESS: **330 E. 133rd Street** IDPH LICENSE NO: **100-18790**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **39**  
MATERIAL DESCRIPTION: **Brown Mosaic Ceramic Tile Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1968 Bldg - North, South and East Vestibules**  
MATERIAL QUANTITY: **230** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 02/24/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26601** BUIDLING ID: **8010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **DuBois School** REVIEW DATE: **5/20/2016**  
ADDRESS: **330 E. 133rd Street** IDPH LICENSE NO: **100-18790**

---

HOMOGENEOUS AREA: **39**  
MATERIAL DESCRIPTION: **Brown Mosaic Ceramic Tile Adhesive**  
MATERIAL LOCATION: **1968 Bldg - North, South and East Vestibules**  
MATERIAL QUANTITY: **230** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/20/2016**



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26601** BUIDLING ID: **8010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**  
SCHOOL NAME: **DuBois School** INSPECTION DATE: **2/24/2016**  
ADDRESS: **330 E. 133rd Street** IDPH LICENSE NO: **100-18790**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **40**  
MATERIAL DESCRIPTION: **12 x 12 Light Brown Floor Tile - NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1937 Bldg - Throughout 1st Floor**  
MATERIAL QUANTITY: **6800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 02/24/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26601** BUIDLING ID: **8010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **DuBois School** REVIEW DATE: **5/20/2016**  
ADDRESS: **330 E. 133rd Street** IDPH LICENSE NO: **100-18790**

---

HOMOGENEOUS AREA: **40**  
MATERIAL DESCRIPTION: **12 x 12 Light Brown Floor Tile - NOT OBSERVED**  
MATERIAL LOCATION: **1937 Bldg - Throughout 1st Floor**  
MATERIAL QUANTITY: **6800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/20/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26601** BUIDLING ID: **8010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**  
SCHOOL NAME: **DuBois School** INSPECTION DATE: **2/24/2016**  
ADDRESS: **330 E. 133rd Street** IDPH LICENSE NO: **100-18790**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **40M**  
MATERIAL DESCRIPTION: **12 x 12 Light Brown Floor Tile Mastic - NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1937 Bldg - Throughout 1st Floor**  
MATERIAL QUANTITY: **6800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 02/24/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26601** BUIDLING ID: **8010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **DuBois School** REVIEW DATE: **5/20/2016**  
ADDRESS: **330 E. 133rd Street** IDPH LICENSE NO: **100-18790**

---

HOMOGENEOUS AREA: **40M**  
MATERIAL DESCRIPTION: **12 x 12 Light Brown Floor Tile Mastic - NOT OBSERVED**  
MATERIAL LOCATION: **1937 Bldg - Throughout 1st Floor**  
MATERIAL QUANTITY: **6800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/20/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26601** BUIDLING ID: **8010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**  
SCHOOL NAME: **DuBois School** INSPECTION DATE: **2/24/2016**  
ADDRESS: **330 E. 133rd Street** IDPH LICENSE NO: **100-18790**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **41**  
MATERIAL DESCRIPTION: **Brown Mosaic Ceramic Tile Grout - NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1937 Bldg - 1st Floor Vestibules, Boys and Girls Washrooms**

MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 02/24/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26601** BUIDLING ID: **8010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **DuBois School** REVIEW DATE: **5/20/2016**  
ADDRESS: **330 E. 133rd Street** IDPH LICENSE NO: **100-18790**

---

HOMOGENEOUS AREA: **41**  
MATERIAL DESCRIPTION: **Brown Mosaic Ceramic Tile Grout - NOT OBSERVED**  
MATERIAL LOCATION: **1937 Bldg - 1st Floor Vestibules, Boys and Girls Washrooms**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/20/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26601** BUIDLING ID: **8010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**  
SCHOOL NAME: **DuBois School** INSPECTION DATE: **2/24/2016**  
ADDRESS: **330 E. 133rd Street** IDPH LICENSE NO: **100-18790**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **42**  
MATERIAL DESCRIPTION: **Brown Mosaic Ceramic Tile Adhesive - NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1937 Bldg - 1st Floor Vestibules, Boys and Girls Washrooms**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 02/24/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26601** BUIDLING ID: **8010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **DuBois School** REVIEW DATE: **5/20/2016**  
ADDRESS: **330 E. 133rd Street** IDPH LICENSE NO: **100-18790**

---

HOMOGENEOUS AREA: **42**  
MATERIAL DESCRIPTION: **Brown Mosaic Ceramic Tile Adhesive - NOT OBSERVED**  
MATERIAL LOCATION: **1937 Bldg - 1st Floor Vestibules, Boys and Girls Washrooms**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/20/2016**



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26601** BUIDLING ID: **8010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**  
SCHOOL NAME: **DuBois School** INSPECTION DATE: **2/24/2016**  
ADDRESS: **330 E. 133rd Street** IDPH LICENSE NO: **100-18790**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **43**  
MATERIAL DESCRIPTION: **Mag Pipe Insulation - NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1937 Bldg - Boiler Room**  
MATERIAL QUANTITY: **30** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 02/24/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26601** BUIDLING ID: **8010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **DuBois School** REVIEW DATE: **5/20/2016**  
ADDRESS: **330 E. 133rd Street** IDPH LICENSE NO: **100-18790**

---

HOMOGENEOUS AREA: **43**  
MATERIAL DESCRIPTION: **Mag Pipe Insulation - NOT OBSERVED**  
MATERIAL LOCATION: **1937 Bldg - Boiler Room**  
MATERIAL QUANTITY: **30** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/20/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26601** BUIDLING ID: **8010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**  
SCHOOL NAME: **DuBois School** INSPECTION DATE: **2/24/2016**  
ADDRESS: **330 E. 133rd Street** IDPH LICENSE NO: **100-18790**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **44**  
MATERIAL DESCRIPTION: **Hard Fittings on Fiberglass - NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1937 Bldg - Boiler Room**  
MATERIAL QUANTITY: **30** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 02/24/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26601** BUIDLING ID: **8010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **DuBois School** REVIEW DATE: **5/20/2016**  
ADDRESS: **330 E. 133rd Street** IDPH LICENSE NO: **100-18790**

---

HOMOGENEOUS AREA: **44**  
MATERIAL DESCRIPTION: **Hard Fittings on Fiberglass - NOT OBSERVED**  
MATERIAL LOCATION: **1937 Bldg - Boiler Room**  
MATERIAL QUANTITY: **30** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/20/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26601** BUIDLING ID: **8010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**  
SCHOOL NAME: **DuBois School** INSPECTION DATE: **2/24/2016**  
ADDRESS: **330 E. 133rd Street** IDPH LICENSE NO: **100-18790**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **45**  
MATERIAL DESCRIPTION: **2 x 4 White Fissured Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **1968 Bldg - Throughout**  
MATERIAL QUANTITY: **45000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 02/24/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26601** BUIDLING ID: **8010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **DuBois School** REVIEW DATE: **5/20/2016**  
ADDRESS: **330 E. 133rd Street** IDPH LICENSE NO: **100-18790**

---

HOMOGENEOUS AREA: **45**  
MATERIAL DESCRIPTION: **2 x 4 White Fissured Ceiling Tile**  
MATERIAL LOCATION: **1968 Bldg - Throughout**  
MATERIAL QUANTITY: **45000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/20/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26601** BUIDLING ID: **8010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**  
SCHOOL NAME: **DuBois School** INSPECTION DATE: **2/24/2016**  
ADDRESS: **330 E. 133rd Street** IDPH LICENSE NO: **100-18790**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **46**  
MATERIAL DESCRIPTION: **9x9 Blue VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON: **Physical Damage**  
HISTORICAL RESPONSE ACTION: **Repair**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Physical Damage**  
DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **2nd fl. janitors closet 1968 bldg**  
MATERIAL QUANTITY: **25** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY:  DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **02/24/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26601** BUIDLING ID: **8010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **DuBois School** REVIEW DATE: **5/20/2016**  
ADDRESS: **330 E. 133rd Street** IDPH LICENSE NO: **100-18790**

---

HOMOGENEOUS AREA: **46**  
MATERIAL DESCRIPTION: **9x9 Blue VFT**  
MATERIAL LOCATION: **2nd fl. janitors closet 1968 bldg**  
MATERIAL QUANTITY: **25** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **1** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/20/2016**



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26601** BUIDLING ID: **8010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**  
SCHOOL NAME: **DuBois School** INSPECTION DATE: **2/24/2016**  
ADDRESS: **330 E. 133rd Street** IDPH LICENSE NO: **100-18790**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **47**  
MATERIAL DESCRIPTION: **9x9 Blue floor tile mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **2nd fl janitors- 1968 bldg**  
MATERIAL QUANTITY: **25** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 02/24/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26601** BUIDLING ID: **8010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **DuBois School** REVIEW DATE: **5/20/2016**  
ADDRESS: **330 E. 133rd Street** IDPH LICENSE NO: **100-18790**

---

HOMOGENEOUS AREA: **47**  
MATERIAL DESCRIPTION: **9x9 Blue floor tile mastic**  
MATERIAL LOCATION: **2nd fl janitors- 1968 bldg**  
MATERIAL QUANTITY: **25** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/20/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26601** BUIDLING ID: **8010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**  
SCHOOL NAME: **DuBois School** INSPECTION DATE: **2/24/2016**  
ADDRESS: **330 E. 133rd Street** IDPH LICENSE NO: **100-18790**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **48**  
MATERIAL DESCRIPTION: **2x4 white ceiling tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **lunch room bldg 1968  
faculty lunchroom bldg 1968  
rm 103 bldg 1968  
rm 101 bldg 1968**

MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 02/24/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26601** BUILDING ID: **8010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **DuBois School** REVIEW DATE: **5/20/2016**  
ADDRESS: **330 E. 133rd Street** IDPH LICENSE NO: **100-18790**

---

HOMOGENEOUS AREA: **48**  
MATERIAL DESCRIPTION: **2x4 white ceiling tile**  
MATERIAL LOCATION: **lunch room bldg 1968  
faculty lunchroom bldg 1968  
rm 103 bldg 1968  
rm 101 bldg 1968**  
MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/20/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26601** BUIDLING ID: **8010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**  
SCHOOL NAME: **DuBois School** INSPECTION DATE: **2/24/2016**  
ADDRESS: **330 E. 133rd Street** IDPH LICENSE NO: **100-18790**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **49**  
MATERIAL DESCRIPTION: **12x12 beige w/ tan specs VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **rm 134 bldg 1968**

MATERIAL QUANTITY: **400**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 02/24/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26601** BUIDLING ID: **8010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **DuBois School** REVIEW DATE: **5/20/2016**  
ADDRESS: **330 E. 133rd Street** IDPH LICENSE NO: **100-18790**

---

HOMOGENEOUS AREA: **49**  
MATERIAL DESCRIPTION: **12x12 beige w/ tan specs VFT**  
MATERIAL LOCATION: **rm 134 bldg 1968**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/20/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26601** BUIDLING ID: **8010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**  
SCHOOL NAME: **DuBois School** INSPECTION DATE: **2/24/2016**  
ADDRESS: **330 E. 133rd Street** IDPH LICENSE NO: **100-18790**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **50**  
MATERIAL DESCRIPTION: **12x12 beige w/ tan specs mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **rm 134- 1968 bldg**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 02/24/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26601** BUIDLING ID: **8010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **DuBois School** REVIEW DATE: **5/20/2016**  
ADDRESS: **330 E. 133rd Street** IDPH LICENSE NO: **100-18790**

---

HOMOGENEOUS AREA: **50**  
MATERIAL DESCRIPTION: **12x12 beige w/ tan specs mastic**  
MATERIAL LOCATION: **rm 134- 1968 bldg**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/20/2016**



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26601** BUIDLING ID: **8010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**  
SCHOOL NAME: **DuBois School** INSPECTION DATE: **2/24/2016**  
ADDRESS: **330 E. 133rd Street** IDPH LICENSE NO: **100-18790**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **A**  
MATERIAL DESCRIPTION: **Aircell Pipe Insulation - NO ACCESS; NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY **1 Damaged or significantly damaged friable thermal system insulating ACBM**  
HISTORICAL DAMAGE REASON: **Physical Damage Deterioration**  
HISTORICAL RESPONSE ACTION: **Repair**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON: **Physical Damage Deterioration**  
DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Basement Building 1937**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY:  DAMAGE UNITS: **LF**  
COMMENTS: **Material within locked, inaccessible 1937 bldg.**

Inspector's Signature: \_\_\_\_\_ Date: 02/24/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26601** BUILDING ID: **8010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **DuBois School** REVIEW DATE: **5/20/2016**  
ADDRESS: **330 E. 133rd Street** IDPH LICENSE NO: **100-18790**

---

HOMOGENEOUS AREA: **A**  
MATERIAL DESCRIPTION: **Aircell Pipe Insulation - NO ACCESS; NOT OBSERVED**  
MATERIAL LOCATION: **Basement Building 1937**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **10** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/20/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26601** BUIDLING ID: **8010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**  
SCHOOL NAME: **DuBois School** INSPECTION DATE: **2/24/2016**  
ADDRESS: **330 E. 133rd Street** IDPH LICENSE NO: **100-18790**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **B**  
MATERIAL DESCRIPTION: **MJP E/F/V on Aircell Pipe Insulation - NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Amosite** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Basement, Building 1937**

MATERIAL QUANTITY: **25**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 02/24/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26601** BUILDING ID: **8010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **DuBois School** REVIEW DATE: **5/20/2016**  
ADDRESS: **330 E. 133rd Street** IDPH LICENSE NO: **100-18790**

---

HOMOGENEOUS AREA: **B**  
MATERIAL DESCRIPTION: **MJP E/F/V on Aircell Pipe Insulation - NOT OBSERVED**  
MATERIAL LOCATION: **Basement, Building 1937**  
MATERIAL QUANTITY: **25** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/20/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26601** BUIDLING ID: **8010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**  
SCHOOL NAME: **DuBois School** INSPECTION DATE: **2/24/2016**  
ADDRESS: **330 E. 133rd Street** IDPH LICENSE NO: **100-18790**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **D**  
MATERIAL DESCRIPTION: **MJP E/F/V on Fiberglass Pipe Insulation-- Abated**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **2nd Floor Boiler Room, 1st fl. fan Rm**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **02/24/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26601** BUIDLING ID: **8010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **DuBois School** REVIEW DATE: **5/20/2016**  
ADDRESS: **330 E. 133rd Street** IDPH LICENSE NO: **100-18790**

---

HOMOGENEOUS AREA: **D**  
MATERIAL DESCRIPTION: **MJP E/F/V on Fiberglass Pipe Insulation-- Abated**  
MATERIAL LOCATION: **2nd Floor Boiler Room, 1st fl. fan Rm**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/20/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26601** BUIDLING ID: **8010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**  
SCHOOL NAME: **DuBois School** INSPECTION DATE: **2/24/2016**  
ADDRESS: **330 E. 133rd Street** IDPH LICENSE NO: **100-18790**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **E**  
MATERIAL DESCRIPTION: **MJP E/F/V on Fiberglass Pipe Insulation - Duplicate**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **1st Floor Storage Room**  
MATERIAL QUANTITY: **45** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 02/24/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26601** BUIDLING ID: **8010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **DuBois School** REVIEW DATE: **5/20/2016**  
ADDRESS: **330 E. 133rd Street** IDPH LICENSE NO: **100-18790**

---

HOMOGENEOUS AREA: **E**  
MATERIAL DESCRIPTION: **MJP E/F/V on Fiberglass Pipe Insulation - Duplicate**  
MATERIAL LOCATION: **1st Floor Storage Room**  
MATERIAL QUANTITY: **45** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/20/2016**



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26601** BUILDING ID: **8010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**  
SCHOOL NAME: **DuBois School** INSPECTION DATE: **2/24/2016**  
ADDRESS: **330 E. 133rd Street** IDPH LICENSE NO: **100-18790**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **F**  
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation - NO ACCESS; NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY **1 Damaged or significantly damaged friable thermal system insulating ACBM**  
HISTORICAL DAMAGE REASON: **Physical Damage Deterioration**  
HISTORICAL RESPONSE ACTION: **Repair**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON: **Physical Damage Deterioration**  
DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Tunnel Area, Building 1937**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **200** DAMAGE UNITS: **LF**  
COMMENTS: **NO ACCESS; NOT OBSERVED**

Inspector's Signature: \_\_\_\_\_ Date: 02/24/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26601** BUILDING ID: **8010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **DuBois School** REVIEW DATE: **5/20/2016**  
ADDRESS: **330 E. 133rd Street** IDPH LICENSE NO: **100-18790**

---

HOMOGENEOUS AREA: **F**  
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation - NO ACCESS; NOT OBSERVED**  
MATERIAL LOCATION: **Tunnel Area, Building 1937**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **5** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/20/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26601** BUIDLING ID: **8010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**  
SCHOOL NAME: **DuBois School** INSPECTION DATE: **2/24/2016**  
ADDRESS: **330 E. 133rd Street** IDPH LICENSE NO: **100-18790**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **I**  
MATERIAL DESCRIPTION: **Cementitious Duct Insulation - NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Basement Building 1937**  
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 02/24/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26601** BUIDLING ID: **8010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **DuBois School** REVIEW DATE: **5/20/2016**  
ADDRESS: **330 E. 133rd Street** IDPH LICENSE NO: **100-18790**

---

HOMOGENEOUS AREA: **I**  
MATERIAL DESCRIPTION: **Cementitious Duct Insulation - NOT OBSERVED**  
MATERIAL LOCATION: **Basement Building 1937**  
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/20/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26601** BUIDLING ID: **8010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**  
SCHOOL NAME: **DuBois School** INSPECTION DATE: **2/24/2016**  
ADDRESS: **330 E. 133rd Street** IDPH LICENSE NO: **100-18790**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **J**  
MATERIAL DESCRIPTION: **Vibration Dampner**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Fan Room, Pipe Chase, 2nd Floor Boiler Room**

MATERIAL QUANTITY: **10** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 02/24/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26601** BUIDLING ID: **8010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **DuBois School** REVIEW DATE: **5/20/2016**  
ADDRESS: **330 E. 133rd Street** IDPH LICENSE NO: **100-18790**

---

HOMOGENEOUS AREA: **J**  
MATERIAL DESCRIPTION: **Vibration Dampner**  
MATERIAL LOCATION: **Fan Room, Pipe Chase, 2nd Floor Boiler Room**  
MATERIAL QUANTITY: **10** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/20/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26601** BUIDLING ID: **8010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**  
SCHOOL NAME: **DuBois School** INSPECTION DATE: **2/24/2016**  
ADDRESS: **330 E. 133rd Street** IDPH LICENSE NO: **100-18790**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **K**  
MATERIAL DESCRIPTION: **Furnace Gasket Insulation - NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Basement Building 1937**

MATERIAL QUANTITY: **5**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 02/24/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26601** BUIDLING ID: **8010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **DuBois School** REVIEW DATE: **5/20/2016**  
ADDRESS: **330 E. 133rd Street** IDPH LICENSE NO: **100-18790**

---

HOMOGENEOUS AREA: **K**  
MATERIAL DESCRIPTION: **Furnace Gasket Insulation - NOT OBSERVED**  
MATERIAL LOCATION: **Basement Building 1937**  
MATERIAL QUANTITY: **5** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/20/2016**



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26601** BUIDLING ID: **8010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**  
SCHOOL NAME: **DuBois School** INSPECTION DATE: **2/24/2016**  
ADDRESS: **330 E. 133rd Street** IDPH LICENSE NO: **100-18790**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **L**  
MATERIAL DESCRIPTION: **MJP E/F/V on Paperwrap Pipe Insulation - NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Basement Building 1937**

MATERIAL QUANTITY: **15**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 02/24/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26601** BUIDLING ID: **8010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **DuBois School** REVIEW DATE: **5/20/2016**  
ADDRESS: **330 E. 133rd Street** IDPH LICENSE NO: **100-18790**

---

HOMOGENEOUS AREA: **L**  
MATERIAL DESCRIPTION: **MJP E/F/V on Paperwrap Pipe Insulation - NOT OBSERVED**  
MATERIAL LOCATION: **Basement Building 1937**  
MATERIAL QUANTITY: **15** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/20/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26601** BUIDLING ID: **8010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**  
SCHOOL NAME: **DuBois School** INSPECTION DATE: **2/24/2016**  
ADDRESS: **330 E. 133rd Street** IDPH LICENSE NO: **100-18790**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **M**  
MATERIAL DESCRIPTION: **PIPEJOINTS - NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **2ND Floor Boiler Room and Fan Room (PRIMARY BLDG.)**  
MATERIAL QUANTITY: **20** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 02/24/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26601** BUIDLING ID: **8010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **DuBois School** REVIEW DATE: **5/20/2016**  
ADDRESS: **330 E. 133rd Street** IDPH LICENSE NO: **100-18790**

---

HOMOGENEOUS AREA: **M**  
MATERIAL DESCRIPTION: **PIPEJOINTS - NOT OBSERVED**  
MATERIAL LOCATION: **2ND Floor Boiler Room and Fan Room (PRIMARY BLDG.)**  
MATERIAL QUANTITY: **20** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/20/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26601** BUIDLING ID: **8010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Allizon Brooks**  
SCHOOL NAME: **DuBois School** INSPECTION DATE: **2/24/2016**  
ADDRESS: **330 E. 133rd Street** IDPH LICENSE NO: **100-18790**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **N**  
MATERIAL DESCRIPTION: **DUCT WRAP**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **2ND FLR BOILER ROOM (PRIMARY BLDG.) AND FAN UNIT**  
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 02/24/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26601** BUIDLING ID: **8010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **DuBois School** REVIEW DATE: **5/20/2016**  
ADDRESS: **330 E. 133rd Street** IDPH LICENSE NO: **100-18790**

---

HOMOGENEOUS AREA: **N**  
MATERIAL DESCRIPTION: **DUCT WRAP**  
MATERIAL LOCATION: **2ND FLR BOILER ROOM (PRIMARY BLDG.) AND FAN UNIT**  
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/20/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
*2016 AHERA REINSPECTION*

# APPENDIX B

## Inspector and Management Planner Licenses

---



**TC EXPIRES**

10/28/2016

**ENDORSEMENTS**

INSPECTOR

2/27/2016

PROJECT MANAGER  
AIR SAMPLING PROFESSIONAL

**Alteration of this license shall result in legal action**  
This license issued under authority of the State of Illinois  
Department of Public Health

This license is valid only when accompanied by a valid



**ASBESTOS  
PROFESSIONAL  
LICENSE**

**ID NUMBER**      **ISSUED**      **EXPIRES**  
100 - 18790      5/7/2015      05/15/2016

ALLIZON L BROOKS  
9344 S RACINE  
CHICAGO, IL 60620  
Environmental Health



PROJECT MANAGER  
AIR SAMPLING PROFESSIONAL  
2/27/2016  
Alteration of this license shall result in legal action  
This license issued under authority of the State of Illinois  
Department of Public Health  
This license is valid only when accompanied by a valid  
training course certificate.

TC EXPIRES

ENDORSEMENTS



**ASBESTOS  
PROFESSIONAL  
LICENSE**

**ID NUMBER**      **ISSUED**      **EXPIRES**  
100 - 18790      5/7/2015      05/15/2016

ALLIZON L BROOKS  
9344 S RACINE  
CHICAGO, IL 60620  
Environmental Health



PROJECT MANAGER  
AIR SAMPLING PROFESSIONAL  
2/27/2016  
Alliteration of this license shall result in legal action  
Department of Public Health  
This license issued under authority of the State of Illinois  
This license is valid only when accompanied by a valid  
training course certificate.

TC EXPIRES

ENDORSEMENTS

**ENDORSEMENTS**

INSPECTOR

10/28/2016

PROJECT MANAGER

AIR SAMPLING PROFESSIONAL

2/27/2016

**Alteration of this license shall result in legal action**  
This license issued under authority of the State of Illinois  
Department of Public Health

This license is valid only when accompanied by a valid

# CERTIFICATE OF ACHIEVEMENT ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that GUILLERMO GARCIA  
has completed the Asbestos Management Planner Refresher course and passed the examination  
on 03/21/2016 with a minimum score of 70% or better. Training was in accordance with U.S.  
E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools: Model  
Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.

03/21/2016

Course Dates:

03/21/2017

Expires:

1603MPR02

Certificate Number:



**PUBLIC HEALTH & SAFETY** inc.

Environmental and Occupational Services  
105 S. Ashland Ave., Chicago, IL 60607

*Nicholas J. Penoff*

Director of Training

Nicholas J. Penoff

Doctor of Public Health

Phone: 312-491-0081

FORM # A-011



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • www.dph.illinois.gov

4/20/2016

**GUILLERMO GARCIA**  
855 W ADAMS ST SUITE 100  
CHICAGO, IL 60607

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 01786

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

**COPY OF THE ASBESTOS PROFESSIONAL LICENSE**

Front of License

Back of License

Front of License			Back of License	
 <p><b>ASBESTOS PROFESSIONAL LICENSE</b></p>			<b>ENDORSEMENTS</b>	<b>TC EXPIRES</b>
<b>ID NUMBER</b> 100 - 01733	<b>ISSUED</b> 4/20/2016	<b>EXPIRES</b> 05/15/2017	INSPECTOR	3/21/2017
<b>GUILLERMO GARCIA</b> 855 W ADAMS ST SUITE 100 CHICAGO, IL 60607 Environmental Health			MANAGEMENT PLANNER PROJECT MANAGER AIR SAMPLING PROFESSIONAL	3/21/2017 2/6/2017
			<b>Alteration of this license shall result in legal action</b> This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: [dph.illinois.gov/topics-services/environmental-health-protection/asbestos](http://dph.illinois.gov/topics-services/environmental-health-protection/asbestos)  
EMAIL Address: [dph.asbestos@illinois.gov](mailto:dph.asbestos@illinois.gov)

**PROTECTING HEALTH, IMPROVING LIVES**  
*Nationally Accredited by PHAB*

# APPENDIX C

## Laboratory Accreditations

---

# APPENDIX D

## Laboratory Results

---



# APPENDIX E

## Chain of Custody Forms

---

## Three-Year Reinspection Key to Terms

	<b>CODE</b>	<b>KEY</b>
<b>MATERIAL</b>		
	ACBM	Asbestos Containing Building Materials
<b>MATERIAL CATEGORY</b>		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
<b>MATERIAL UNITS</b>		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
<b>DAMAGE TYPE</b>		
	Loc	Localized
	Dist	Distributed