

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM**

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-2249
SCHOOL NAME: Hawthorne Academy
ADDRESS OF SCHOOL: 3319 N Clifton Avenue
CITY: Chicago, IL, 60657

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **3/26/2013**

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II *(Please type or print)*

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 6/24/2016 ENROLLMENT 569
IDPH INSPECTOR LICENSE NUMBER: 100-07210
IDPH LICENSED INSPECTOR NAME (Please Print): Michael Holvay
IDPH MP LICENSE NUMBER: 100-07342
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Jigar Shah

DESIGNATED PERSON (Please Print): Robert Christlieb PHONE: (773) 553-3197



6/24/2016

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Hawthorne Academy

3319 N Clifton Avenue
Chicago, IL, 60657

Unit: 29131
Building ID: 3830

IDPH ID Number: 14-016-2990-2249

REPORT DATE:

Friday, June 24, 2016

Prepared for:

Chicago Public Schools
125 S. Clark Street
Chicago, IL 60603

Prepared by:

GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone (312) 733-6262

Fax (312) 733-5612

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

March 9, 2016

Mr. R. Kent Cook
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2016 Three-Year Reinspections

Dear Mr. Cook:

GSG Consultants, Inc., Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 1,2,6 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 29131 Region: 01 IDPH ID: 14-016-2990-2249

School: Hawthorne Academy Building ID: 3830

Address: 3319 N Clifton Avenue
Chicago, IL, 60657

Building Contact: Strzykaski, Michael Contact Phone: 773-636-6684

Current Building Owners: Chicago Public Schools

Review Date: 05/20/2016

Inspector: Michael Holvay Inspector IDPH License: 100-07210
Management Planner: Jigar Shah Management Planner IDPH License: 100-07342

If you have any questions or comments, please contact us at (312) 733-6262

Sincerely,
GSG Consultants, Inc.



Jigar Shah
100-07342

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: March 09, 2016

RE: Hawthorne Academy, Unit 29131
3319 N Clifton Avenue
Chicago, IL, 60657

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2016 asbestos three year re-inspection has been completed at Hawthorne Academy, following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at Hawthorne Academy, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Robert Christlieb, the designated Local Education Authority's Designated Person at (773) 553-3197 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Hawthorne Academy Unit: 29131 Region: 01
Address: 3319 N Clifton Avenue Chicago, IL, 60657
IDPH ID: 14-016-2990-2249 Building ID: 3830
Contact: Strzykaski, Michael Phone: 773-636-6684

2. Description of Facility

Original Construction: 1961 Additional Construction: 1930,1954
Total Square Footage: 14988 No of Floors: 3
Current Occupancy: 569

3. LEA Designated Person

Contact: Robert Christlieb Phone: (773) 553-3197
Address: 125 South Clark Street, 17th Floor
Chicago, IL 60603


4. Managing Environmental Consultant

MEC: GSG Consultants, Inc.
Contact: Arturo Saenz
Address 855 W. Adams St., Ste. 200
Phone: (312) 733-6262 Fax: (312) 733-5612

5. Inspector

Inspector Name: Michael Holvay


Inspector IDPH license # 100-07210


Michael Holvay
Project Manager
Signature: _____
Date: 3/9/2016

6. Management Planner

Management Planner Name: Jigar Shah

Management Planner IDPH license # 100-07342


Signature: _____
Date: 05/20/2016

7. Review Date: 05/20/2016

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature: 

Date: 6/24/2016

Name: Robert Christlieb

II. EXECUTIVE SUMMARY

GSG Consultants, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Hawthorne Academy. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 3830:

B. The following new homogenous areas have been identified for Building 3830:

| | |
|-----|------------------------------------|
| 114 | 12" x 12" Gray Streaked VFT |
| 115 | 12" x 12" Gray Streaked VFT Mastic |
| 116 | 12" x 12" Gray Streaked VFT |
| 117 | 12" X 12" Gray Streaked VFT Mastic |
| 118 | Carpet Mastic |
| 119 | Black Rubber Floor-Adhesive |
| 120 | Troweled on plaster |

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

| | |
|-------|--|
| 07 | 12"x12" Light Tan VFT |
| 100 | 12" x 12" White w/Brown Spots VFT |
| 101 | 12" x 12" White w/Brown Spots VFT Mastic |
| 102 | 12 x 12 inch Green w/White Streaks VFT |
| 102 A | 12 x 12 inch Green w/White Streaks VFT Mastic |
| 103 | Carpet mastic |
| 104 | Carpet mastic |
| 105 | 1' X 1' Ceiling Tiles |
| 105A | 1' X 1' Ceiling Tiles Mastic |
| 106 | Damper Cloth |
| 107 | Black sink-coating |
| 108 | 12"X12" Gray VFT |
| 108A | 12"X12" Gray VFT Mastic |
| 109 | 12"X12" White w/black streaks NOT OBSERVED |
| 109A | 12"X12" White w/black streaks Mastic- NOT OBSERVED |
| 10A | 1 ft X 1 ft ceiling tile mastic (1952) |
| 110 | 12"X12" Taupe VFT |
| 110A | 12"x12" Taupe VFT Mastic |
| 111 | 12"X12" White w/Beige VFT |
| 111A | 12"X12" White w/Beige VFT Mastic |
| 112 | Vinyl Baseboard Mastic |
| 113 | 1'x1' white w/grooves & holes ceiling tile |
| 114 | 12" x 12" Gray Streaked VFT |
| 115 | 12" x 12" Gray Streaked VFT Mastic |
| 116 | 12" x 12" Gray Streaked VFT |
| 117 | 12" X 12" Gray Streaked VFT Mastic |
| 118 | Carpet Mastic |
| 119 | Black Rubber Floor-Adhesive |
| 120 | Troweled on plaster |
| 16 | 12"x12" Peach VFT |
| 17 | 12"x12" Peach VFT Mastic |
| 20 | 12"x12" Tan w/ Scaly Brown Spots VFT |
| G | Acoustic Plaster Ceiling |
| H | Terrazzo |
| I | Terrazzo |
| J | Terrazzo |

The following areas were deemed to be inaccessible:

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Michael Holvay, IDPH License # 100-07210. The Management Plan was updated by Jigar Shah, IDPH License # 100-07342. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Hawthorne Academy Building 3830 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Hawthorne Academy Unit 29131 Building ID 3830

Address 3319 N Clifton Avenue Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

Inspector's Comments are Summarized at the End of the Report

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category | Damage Category | Damage Reason | Disturbance Potential |
|-------|--|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|------------------------------------|---------------|-----------------------|
| 04 | 9"x9" Tan VFT | 2,900 | SF | Room 113, 114, 115, 213, 214, 215, 216, storage room between rms 215 & 216 - 1960 | CHR | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | MODERATE |
| 05 | 12"x12" Tan VFT | 15,300 | SF | Rooms 101, 102-105, 107-112, 202-212, Toilet & Storage (teacher's rm 2nd fl. & 1st fl.), Eng.off, Main Office, Prin. office, toilet & storage, 1st & 2nd fl. corridors, bsmt teacher's break rm. - 1952- | CHR | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | MODERATE |
| 06 | 9"x9" Dark Brown VFT | | | Assembly Hall, 1928 | ABATED | MISC | | | | | | | | Low |
| 07 | 12"x12" Light Tan VFT | 1,400 | SF | Basement Room 004 - 1952 | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | MODERATE |
| 08 | 9"x9" Tan VFT Mastic | 2,900 | SF | Room 113, 114, 115, 213, 214, 215, 216, storage room between rms 215 & 216 - 1960 | CHR | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 09 | 12"x12" Tan VFT Mastic | 15,305 | SF | Rooms 101, 102-105, 107-112, 202-212, Toilet & Storage (teacher's rm 2nd fl. & 1st fl.), Eng.off, Main Office, Prin. office, toilet & storage, 1st & 2nd fl. corridors, bsmt teacher's break rm. - 1952- | CHR | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 10 | 1'x1' Ceiling Tile | | | Lunchroom, Kitchen- 1952 | NO_ACBM | | | | | | | | | |
| 100 | 12" x 12" White w/Brown Spots VFT | 500 | SF | 1st Floor MDF Room and teacher's toilet- 1960 | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 101 | 12" x 12" White w/Brown Spots VFT Mastic | 500 | SF | 1st Floor MDF Room & Teacher's Toilet- 1960 | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 102 | 12 x 12 inch Green w/White Streaks VFT | 1,200 | SF | Basement Lunch | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the | | MODERATE |

Chicago Public Schools

School Hawthorne Academy Unit 29131 Building ID 3830

Address 3319 N Clifton Avenue Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

Inspector's Comments are Summarized at the End of the Report

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category | Damage Category | Damage Reason | Disturbance Potential |
|-------|--|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|------------------------------------|---------------|-----------------------|
| | | | | Room, 1952 Bldg | | | | | | | | potential for damage | | |
| 102 A | 12 x 12 inch Green w/White Streaks VFT Mastic | 1,200 | SF | Basement Lunch Room, Bldg 1952 | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 103 | Carpet mastic | 800 | SF | Room 226 (1928) | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 104 | Carpet mastic | 1,200 | SF | Room 201, Main Office, Principal's Office (1952) | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 105 | 1' X 1' Ceiling Tiles | 40,000 | SF | Gymnasium and Assembly Hall (1928) | ASSUMED | MISC | Y | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 105A | 1' X 1' Ceiling Tiles Mastic | 4,000 | SF | Gymnasium and Assembly Hall (1928) | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 106 | Damper Cloth | 80 | LF | Fan Room, North and South Attic - (1952) | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 107 | Black sink-coating | 36 | SF | Rooms 113, 115, 116, 213, 215, 216 (1960) | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 108 | 12"X12" Gray VFT | 2,000 | SF | Assembly Hall - (1928) | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | MODERATE |
| 108A | 12"X12" Gray VFT Mastic | 2,000 | SF | Assembly Hall - (1928) | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 109 | 12"X12" White w/black streaks NOT OBSERVED | 1,500 | SF | Lunch Room - (1952) | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | MODERATE |
| 109A | 12"X12" White w/black streaks Mastic- NOT OBSERVED | 1,500 | SF | Lunch Room - (1952) | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 10A | 1 ft X 1 ft ceiling tile mastic (1952) | 1,600 | SF | Lunch Room, Kitchen | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 11 | 9"x9" Dark Brown VFT Mastic | | | Assembly Hall, 1928 | ABATED | MISC | | None | | | | | | Low |
| 110 | 12"X12" Taupe VFT | 70 | SF | Room 216 (1960) | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | MODERATE |
| 110A | 12"x12" Taupe VFT Mastic | 70 | SF | Room 216 (1960) | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 111 | 12"X12" White w/Beige VFT | 800 | SF | Room 116 (1960) | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | MODERATE |
| 111A | 12"X12" White w/Beige VFT Mastic | 800 | SF | Room 116T (1960) | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 112 | Vinyl Baseboard Mastic | 140 | SF | Room 114 (1960) | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 113 | 1'x1' white w/grooves & holes ceiling tile | 650 | SF | Bsmt play area by pump room - 1960 | ASSUMED | MISC | Y | NONE | 0 | | No | ACBM with the potential for damage | | LOW |

Chicago Public Schools

School Hawthorne Academy Unit 29131 Building ID 3830

Address 3319 N Clifton Avenue Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

Inspector's Comments are Summarized at the End of the Report

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category | Damage Category | Damage Reason | Disturbance Potential |
|-------|--|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|---|---------------|-----------------------|
| | | | | Office, Teachers' Room - 1952 bldg. | | | | | | | | | | |
| 23 | 12"x12" Tan w/ Maroon Streaks VFT Mastic | | | Room 101, 1st Floor Corridor, Main Office, Teachers' Room - 1952 bldg. | ABATED | MISC | | | | | | | | |
| 24 | Sprayed Applied Acoustical Plaster | | | Basement Play Area West of Pump Room- 1960 | NO_ACBM | | | | | | No | | | |
| 25 | 9"x9" Green w/ White & Black Streaks VFT - ABATED | | | Lunchroom- 1952 | ABATED | MISC | | None | | | | | | Low |
| 26 | 9"x9" Green w/ White & Black Streaks VFT Mastic - ABATED | | | Lunchroom- 1952 | ABATED | MISC | | None | | | | | | Low |
| 27 | 9"x9" Tan w/ Brown & White Streaks VFT - ABATED | | | Lunchroom- 1952 | ABATED | MISC | | None | | | | | | Low |
| 28 | 9"x9" Tan w/ Brown & White Streaks VFT Mastic - ABATED | | | Lunchroom- 1952 | ABATED | MISC | | Dist | | | | | | Low |
| 29 | MJP E/F/V on Aircell Pipe Insulation | 390 | LF | Throughout (See Hatching Maps)- 1952 | CHR | TSI | Y | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 30 | MJP E/F/V on Fiberglass Pipe Insulation | 45 | LF | Playroom Closet, Pipe Chase in SE Corner of Playroom Area - 1960 | CHR | TSI | Y | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 31 | Aircell Pipe Insulation | 31 | LF | Playroom Closet, Pump Room Storage, Pipe Chase in SE Corner of Playroom Area - 1960 | CHR | TSI | Y | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 32 | MJP E/F/V on Aircell Pipe Insulation | 15 | LF | Playroom Closet, Pump Room Storage, Pipe Chase in SE Corner of Playroom Area - 1960 | CHR | TSI | Y | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 33 | Aircell Pipe Insulation | 350 | LF | Fan Room, Unexcavated Area, Stage Area, Janitors Storage, Corridor outside basement- 1928 | CHR | TSI | Y | DIST | 40 | | No | Damaged or significantly damaged friable thermal system insulating ACBM | 3 | LOW |
| 34 | MJP E/F/V on Aircell Pipe Insulation | 30 | LF | Fan Room, Unexcavated Area, Stage Area, Janitors | CHR | TSI | Y | NONE | 0 | | No | ACBM with the potential for damage | | LOW |

Chicago Public Schools

School Hawthorne Academy Unit 29131 Building ID 3830

Address 3319 N Clifton Avenue Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

Inspector's Comments are Summarized at the End of the Report

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category | Damage Category | Damage Reason | Disturbance Potential |
|-------|---|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|---|---------------|-----------------------|
| | | | | Storage, Corridor outside basement-1928 | | | | | | | | | | |
| 35 | Cardboard Pipe Insulation | 350 | LF | Unexcavated Area Under Auditorium-, Foyer and Stairs outside Auditorium-1928 | CHR | TSI | Y | DIST | 20 | | No | Damaged or significantly damaged friable thermal system insulating ACBM | 3 | LOW |
| 36 | MJP E/F/V on Cardboard Pipe Insulation | 35 | LF | Unexcavated Area Under Auditorium-1928 | CHR | TSI | Y | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 37 | 6"x18" Black VFT - ABATED | | | Assembly Hall - 1928 | ABATED | MISC | | | | | | | | Low |
| 38 | 6"x18" Black VFT Mastic - ABATED | | | Assembly Hall - 1928 | ABATED | MISC | | Dist | | | | | | Low |
| 39 | 12"x12" Red VFT - ABATED | | | Assembly Hall - 1928 | ABATED | MISC | | None | | | | | | Low |
| 40 | 12"x12" Red VFT Mastic - ABATED | | | Assembly Hall - 1928 | ABATED | MISC | | None | | | | | | Low |
| 41 | 9"x9" Green VFT Mastic | 3,050 | SF | Room 113, 114, 115, 213, 214, 215, 216, storage rm between rms 215 & 216 - 1960 | CHR | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 42 | 12"x12" Green VFT Mastic | 11,385 | SF | Room 100, 103-105, 107-112, 202-212, bsmt teacher's break room - 1952 | CHR | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| A | Aircell Pipe Insulation - Same as HA 33 | 1,600 | LF | Throughout (See Hatching Maps), 101, Toilet Rooms-1952 | CHR | TSI | Y | | | | No | | 3 | LOW |
| B | Cardboard Pipe Insulation - Same as HA 35 | 1,200 | LF | Throughout (See Hatching Maps)-1952 | CHR | TSI | Y | | | | No | | 3 | LOW |
| C | MJP E/F/V on Cardboard Pipe Insulation | 400 | LF | Throughout (See Hatching Maps)-1952 | CHR | TSI | Y | DIST | 20 | | No | Damaged or significantly damaged friable thermal system insulating ACBM | 3 | LOW |
| D | Mag Block Pipe Insulation | 1,800 | LF | 2nd Floor Boys Toilet, Pump Room, Boiler Room, Fan Room - 1952 | CHR | TSI | Y | DIST | 15 | | No | Damaged or significantly damaged friable thermal system insulating ACBM | 3 | LOW |
| E | MJP E/F/V on Mag Block Pipe Insulation | 450 | LF | 2nd Floor Boys | CHR | TSI | Y | NONE | 0 | | No | ACBM with the | | LOW |

Chicago Public Schools

School Hawthorne Academy **Unit** 29131 **Building ID** 3830

Address 3319 N Clifton Avenue **Region** 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

Inspector's Comments are Summarized at the End of the Report

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category | Damage Category | Damage Reason | Disturbance Potential |
|-------|------------------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|------------------------------------|---------------|-----------------------|
| | | | | Toilet, Pump Room, Boiler Room, Fan Room - 1952 | | | | | | | | potential for damage | | |
| F | Tank Insulation *abated on 8/28/10 | | | Tank Room | ABATED | TSI | | None | | | | | | Low |
| G | Acoustic Plaster Ceiling | 3,000 | SF | 1st and 2nd Floor Hallways - 1960 Bldg. | ASSUMED | SURFACE | Y | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| H | Terrazzo | 1,000 | SF | Stair treads and landings and assembly-stair treads and landing. - (1928) | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | MODERATE |
| I | Terrazzo | 1,000 | SF | Stairwell treads and landings - (1952) | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | MODERATE |
| J | Terrazzo | 1,000 | SF | Stairwell treads and landings - (1960) | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | MODERATE |

Chicago Public Schools

School Hawthorne Academy Unit 29131 Building ID 3830

Address 3319 N Clifton Avenue Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

Inspector's Comments are Summarized at the End of the Report

| |
|---|
| Reinspection Date 3/9/2016 |
| Inspector Name <u>Michael Holvay</u> |
| 100-07210 1/18/2017 |
| Inspector's IDPH License Number / Expiration Date |

Inspector's Comments

| HA Number: | Inspector Comments: |
|------------|---------------------|
| 04 | |
| 05 | |
| 06 | |
| 07 | |
| 08 | |
| 09 | |
| 10 | |
| 100 | |
| 101 | |
| 102 | |
| 102 A | |
| 103 | |
| 104 | |
| 105 | |
| 105A | |
| 106 | |
| 107 | |
| 108 | |
| 108A | |
| 109 | |
| 109A | |
| 10A | |
| 11 | |
| 110 | |

Chicago Public Schools

School Hawthorne Academy Unit 29131 Building ID 3830

Address 3319 N Clifton Avenue Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

Inspector's Comments are Summarized at the End of the Report

| HA Number: | Inspector Comments: |
|------------|---------------------|
| 110A | |
| 111 | |
| 111A | |
| 112 | |
| 113 | |
| 114 | |
| 115 | |
| 116 | |
| 117 | |
| 118 | |
| 119 | |
| 12 | |
| 120 | |
| 13 | |
| 14 | |
| 15 | |
| 16 | |
| 17 | |
| 18 | |
| 19 | |
| 20 | |
| 21 | |
| 22 | |
| 23 | |
| 24 | |
| 25 | |
| 26 | |
| 27 | |
| 28 | |

Chicago Public Schools

School Hawthorne Academy Unit 29131 Building ID 3830

Address 3319 N Clifton Avenue Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

Inspector's Comments are Summarized at the End of the Report

| HA Number: | Inspector Comments: |
|------------|---------------------|
| 29 | |
| 30 | |
| 31 | |
| 32 | |
| 33 | |
| 34 | |
| 35 | |
| 36 | |
| 37 | |
| 38 | |
| 39 | |
| 40 | |
| 41 | |
| 42 | |
| A | Same as HA 33 |
| B | Same as HA 35 |
| C | |
| D | |
| E | |
| F | |
| G | |
| H | |
| I | |
| J | |

Chicago Public Schools

School Hawthorne Academy **Unit** 29131 **Building ID** 3830

Address 3319 N Clifton Avenue **Region** 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

Inspector's Comments are Summarized at the End of the Report

Table II

Management Planner's Review

Chicago Public Schools

School Hawthorne Academy

Unit 29131

Building ID 3830

Address 3319 N Clifton Avenue

Chicago, IL, 60657

Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

Management Planner's Comments Summarized at the End of the Report

| HA Num | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Quantity | Damage Units | Damage Category | Response |
|--------|---|-------------------|----------------|--|---------------|-------------------|---------|-----------------|--------------|--------------------------------------|-----------------|
| 04 | 9"x9" Tan VFT | 2,900 | SF | Room 113, 114, 115, 213, 214, 215, 216, storage room between rms 215 & 216 - 1960 | Chrysotile | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 05 | 12"x12" Tan VFT | 15,300 | SF | Rooms 101, 102-105, 107-112, 202-212, Toilet & Storage (teacher's rm 2nd fl. & 1st fl.), Eng.off, Main Office, Prin. office, toilet & storage, 1st & 2nd fl. corridors, bsmt teacher's break rm. - 1952- | Chrysotile | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 06 | 9"x9" Dark Brown VFT | | | Assembly Hall, 1928 | Abated | MISC | | | | | |
| 07 | 12"x12" Light Tan VFT | 1,400 | SF | Basement Room 004 - 1952 | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 08 | 9"x9" Tan VFT Mastic | 2,900 | SF | Room 113, 114, 115, 213, 214, 215, 216, storage room between rms 215 & 216 - 1960 | Chrysotile | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 09 | 12"x12" Tan VFT Mastic | 15,305 | SF | Rooms 101, 102-105, 107-112, 202-212, Toilet & Storage (teacher's rm 2nd fl. & 1st fl.), Eng.off, Main Office, Prin. office, toilet & storage, 1st & 2nd fl. corridors, bsmt teacher's break rm. - 1952- | Chrysotile | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 10 | 1'x1' Ceiling Tile | | | Lunchroom, Kitchen- 1952 | No ACBM | | | | | | |
| 100 | 12" x 12" White w/Brown Spots VFT | 500 | SF | 1st Floor MDF Room and teacher's toilet- 1960 | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 101 | 12" x 12" White w/Brown Spots VFT Mastic | 500 | SF | 1st Floor MDF Room & Teacher's Toilet- 1960 | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 102 | 12 x 12 inch Green w/White Streaks VFT | 1,200 | SF | Basement Lunch Room, 1952 Bldg | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 102 A | 12 x 12 inch Green w/White Streaks VFT Mastic | 1,200 | SF | Basement Lunch Room, Bldg 1952 | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 103 | Carpet mastic | 800 | SF | Room 226 (1928) | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 104 | Carpet mastic | 1,200 | SF | Room 201, Main Office, Principal's Office (1952) | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 105 | 1' X 1' Ceiling Tiles | 40,000 | SF | Gymnasium and Assembly Hall (1928) | Assumed | MISC | Yes | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 105A | 1' X 1' Ceiling Tiles Mastic | 4,000 | SF | Gymnasium and Assembly Hall (1928) | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 106 | Damper Cloth | 80 | LF | Fan Room, North and South Attic - (1952) | Assumed | MISC | No | 0 | LF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 107 | Black sink-coating | 36 | SF | Rooms 113, 115, 116, 213, 215, 216 (1960) | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |

Chicago Public Schools

School Hawthorne Academy
Address 3319 N Clifton Avenue

Unit 29131
Chicago, IL, 60657

Building ID 3830
Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

Management Planner's Comments Summarized at the End of the Report

| HA Num | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Quantity | Damage Units | Damage Category | Response |
|--------|--|-------------------|----------------|--|---------------|-------------------|---------|-----------------|--------------|--------------------------------------|-----------------|
| 108 | 12"x12" Gray VFT | 2,000 | SF | Assembly Hall - (1928) | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 108A | 12"x12" Gray VFT Mastic | 2,000 | SF | Assembly Hall - (1928) | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 109 | 12"x12" White w/black streaks NOT OBSERVED | 1,500 | SF | Lunch Room - (1952)- | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | |
| 109A | 12"x12" White w/black streaks Mastic- NOT OBSERVED | 1,500 | SF | Lunch Room - (1952) | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | |
| 10A | 1 ft X 1 ft ceiling tile mastic (1952) | 1,600 | SF | Lunch Room, Kitchen | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 11 | 9"x9" Dark Brown VFT Mastic | | | Assembly Hall, 1928 | Abated | MISC | | | | | |
| 110 | 12"x12" Taupe VFT | 70 | SF | Room 216 (1960) | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 110A | 12"x12" Taupe VFT Mastic | 70 | SF | Room 216 (1960) | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 111 | 12"x12" White w/Beige VFT | 800 | SF | Room 116 (1960) | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 111A | 12"x12" White w/Beige VFT Mastic | 800 | SF | Room 116T (1960) | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 112 | Vinyl Baseboard Mastic | 140 | SF | Room 114 (1960) | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 113 | 1'x1' white w/grooves & holes ceiling tile | 650 | SF | Bsmt play area by pump room - 1960 bldg. | Assumed | MISC | Yes | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 114 | 12" x 12" Gray Streaked VFT | 3,200 | SF | 1st Floor Corridor, Main Office (1952 Addition) | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 115 | 12" x 12" Gray Streaked VFT Mastic | 3,200 | SF | 1st Floor Corridor, Main Office (1952 Addition) | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 116 | 12" x 12" Gray Streaked VFT | 500 | SF | 1st Floor Corridor (1960 Addition) | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 117 | 12" X 12" Gray Streaked VFT Mastic | 500 | SF | 1st Floor Corridor (1960 Addition) | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 118 | Carpet Mastic | 600 | SF | Room 113 (1960 Addition) | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 119 | Black Rubber Floor-Adhesive | 1,200 | SF | Room 004 (1952 Addition) | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 12 | 1'x1' Ceiling Tile | | | Assembly Hall- 1928 | No ACBM | | | | | | |
| 120 | Troweled on plaster | 80 | SF | Auditorium Foyer (1928 Bldg) | Assumed | SURFACE | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 13 | 9"x9" Green VFT | 3,050 | SF | Room 113 through 115, 213 through 215, storage rm. between rms. 215 & 216 - 1960 | Chrysotile | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 14 | 12"x12" Green VFT | 11,385 | SF | Room 100, 103-105, 107-112, 202-212, bsmt teacher's break rm. - 1952 | Chrysotile | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 15 | 12"x12" Light Tan VFT Mastic | | | Basement Room 004 - (1952) | No ACBM | | | | | | |
| 16 | 12"x12" Peach VFT | 500 | SF | 1st and 2nd Floor Corridor- 1960 | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 17 | 12"x12" Peach VFT Mastic | 1,000 | SF | 1st and 2nd Floor Corridor- 1960 | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 18 | 9"x9" Tan w/ Black & White VFT | | | 1st Floor Corridor- 1952 | Abated | MISC | | | | | |
| 19 | 9"x9" Tan w/ Black & White VFT Mastic | | | 1st Floor Corridor- 1952 | Abated | MISC | | | | | |
| 20 | 12"x12" Tan w/ Scaly Brown Spots VFT | 400 | SF | 3rd Floor Penthouse - 1928 | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |

Chicago Public Schools

School Hawthorne Academy
Address 3319 N Clifton Avenue

Unit 29131
Chicago, IL, 60657

Building ID 3830
Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

Management Planner's Comments Summarized at the End of the Report

| HA Num | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Quantity | Damage Units | Damage Category | Response |
|--------|--|-------------------|----------------|---|---------------|-------------------|---------|-----------------|--------------|---|-----------------|
| 21 | 12"x12" Tan w/ Scaly Brown Spots VFT Mastic | 400 | SF | 3rd Floor Penthouse - 1928 | Chrysotile | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 22 | 12"x12" Tan w/ Maroon Streaks VFT | | | Room 101, 1st Floor Corridor, Main Office, Teachers' Room - 1952 bldg. | Abated | MISC | | | | | |
| 23 | 12"x12" Tan w/ Maroon Streaks VFT Mastic | | | Room 101, 1st Floor Corridor, Main Office, Teachers' Room - 1952 bldg. | Abated | MISC | | | | | |
| 24 | Sprayed Applied Acoustical Plaster | | | Basement Play Area West of Pump Room- 1960 | No ACBM | | | | | | |
| 25 | 9"x9" Green w/ White & Black Streaks VFT - ABATED | | | Lunchroom- 1952 | Abated | MISC | | | | | |
| 26 | 9"x9" Green w/ White & Black Streaks VFT Mastic - ABATED | | | Lunchroom- 1952 | Abated | MISC | | | | | |
| 27 | 9"x9" Tan w/ Brown & White Streaks VFT - ABATED | | | Lunchroom- 1952 | Abated | MISC | | | | | |
| 28 | 9"x9" Tan w/ Brown & White Streaks VFT Mastic - ABATED | | | Lunchroom- 1952 | Abated | MISC | | | | | |
| 29 | MJP E/F/V on Aircell Pipe Insulation | 390 | LF | Throughout (See Hatching Maps)- 1952 | Chrysotile | TSI | Yes | 0 | LF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 30 | MJP E/F/V on Fiberglass Pipe Insulation | 45 | LF | Playroom Closet, Pipe Chase in SE Corner of Playroom Area - 1960 | Chrysotile | TSI | Yes | 0 | LF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 31 | Aircell Pipe Insulation | 31 | LF | Playroom Closet, Pump Room Storage, Pipe Chase in SE Corner of Playroom Area - 1960 | Chrysotile | TSI | Yes | 0 | LF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 32 | MJP E/F/V on Aircell Pipe Insulation | 15 | LF | Playroom Closet, Pump Room Storage, Pipe Chase in SE Corner of Playroom Area - 1960 | Chrysotile | TSI | Yes | 0 | LF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 33 | Aircell Pipe Insulation | 350 | LF | Fan Room, Unexcavated Area, Stage Area, Janitors Storage, Corridor outside basement- 1928 | Chrysotile | TSI | Yes | 40 | LF | 1 Damaged or significantly damaged friable thermal system insulating ACBM | Repair |
| 34 | MJP E/F/V on Aircell Pipe Insulation | 30 | LF | Fan Room, Unexcavated Area, Stage Area, Janitors Storage, Corridor outside basement- 1928 | Chrysotile | TSI | Yes | 0 | LF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 35 | Cardboard Pipe Insulation | 350 | LF | Unexcavated Area Under Auditorium-, Foyer and Stairs outside Auditorium- 1928 | Chrysotile | TSI | Yes | 20 | LF | 1 Damaged or significantly damaged friable thermal system insulating ACBM | Repair |
| 36 | MJP E/F/V on Cardboard Pipe Insulation | 35 | LF | Unexcavated Area Under Auditorium- 1928 | Chrysotile | TSI | Yes | 0 | LF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 37 | 6"x18" Black VFT - ABATED | | | Assembly Hall - 1928 | Abated | MISC | | | | | |

Chicago Public Schools

School Hawthorne Academy
Address 3319 N Clifton Avenue

Unit 29131
Chicago, IL, 60657

Building ID 3830
Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

Management Planner's Comments Summarized at the End of the Report

| HA Num | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Quantity | Damage Units | Damage Category | Response |
|--------|---|-------------------|----------------|---|---------------|-------------------|---------|-----------------|--------------|---|-----------------|
| 38 | 6"x18" Black VFT Mastic - ABATED | | | Assembly Hall - 1928 | Abated | MISC | | | | | |
| 39 | 12"x12" Red VFT - ABATED | | | Assembly Hall - 1928 | Abated | MISC | | | | | |
| 40 | 12"x12" Red VFT Mastic - ABATED | | | Assembly Hall - 1928 | Abated | MISC | | | | | |
| 41 | 9"x9" Green VFT Mastic | 3,050 | SF | Room 113, 114, 115, 213, 214, 215, 216, storage rm between rms 215 & 216 - 1960 | Chrysotile | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 42 | 12"x12" Green VFT Mastic | 11,385 | SF | Room 100, 103-105, 107-112, 202-212, bsmt teacher's break room - 1952 | Chrysotile | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| A | Aircell Pipe Insulation - Same as HA 33 | 1,600 | LF | Throughout (See Hatching Maps), 101, Toilet Rooms- 1952 | Chrysotile | TSI | Yes | | LF | | Follow O&M Plan |
| B | Cardboard Pipe Insulation - Same as HA 35 | 1,200 | LF | Throughout (See Hatching Maps)- 1952 | Chrysotile | TSI | Yes | | LF | | Follow O&M Plan |
| C | MJP E/F/V on Cardboard Pipe Insulation | 400 | LF | Throughout (See Hatching Maps)- 1952 | Chrysotile | TSI | Yes | 20 | LF | 1 Damaged or significantly damaged friable thermal system insulating ACBM | Repair |
| D | Mag Block Pipe Insulation | 1,800 | LF | 2nd Floor Boys Toilet, Pump Room, Boiler Room, Fan Room - 1952 | Chrysotile | TSI | Yes | 15 | LF | 1 Damaged or significantly damaged friable thermal system insulating ACBM | Repair |
| E | MJP E/F/V on Mag Block Pipe Insulation | 450 | LF | 2nd Floor Boys Toilet, Pump Room, Boiler Room, Fan Room - 1952 | Chrysotile | TSI | Yes | 0 | LF | 6 ACBM with the potential for damage | Follow O&M Plan |
| F | Tank Insulation *abated on 8/28/10 | | | Tank Room | Abated | TSI | | | | | |
| G | Acoustic Plaster Ceiling | 3,000 | SF | 1st and 2nd Floor Hallways - 1960 Bldg. | Assumed | SURFACE | Yes | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| H | Terrazzo | 1,000 | SF | Stair treads and landings and assembly-stair treads and landing. - (1928) | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| I | Terrazzo | 1,000 | SF | Stairwell treads and landings - (1952) | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| J | Terrazzo | 1,000 | SF | Stairwell treads and landings - (1960) | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |

Chicago Public Schools

School Hawthorne Academy
Address 3319 N Clifton Avenue

Unit 29131
 Chicago, IL, 60657

Building ID 3830
Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG Consultants, Inc.
 855 W. Adams St., Ste. 200
 Phone: (312) 733-6262

Fax: (312) 733-5612

Management Planner's Comments Summarized at the End of the Report

| | |
|------------------------------------|------------|
| Review Date | 5/20/2016 |
| Manager Planner Name | Jigar Shah |
| 100-07342 | 1/19/2017 |
| Manager IDPH License No/Expiration | |

| HA Number | Management Comments |
|-----------|---------------------|
| 04 | |
| 05 | |
| 06 | |
| 07 | |
| 08 | |
| 09 | |
| 10 | |
| 100 | |
| 101 | |
| 102 | |
| 102 A | |
| 103 | |
| 104 | |

Chicago Public Schools

School Hawthorne Academy

Unit 29131

Building ID 3830

Address 3319 N Clifton Avenue

Chicago, IL, 60657

Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

Management Planner's Comments Summarized at the End of the Report

| HA Number | Management Comments |
|-----------|---------------------|
| 105 | |
| 105A | |
| 106 | |
| 107 | |
| 108 | |
| 108A | |
| 109 | |
| 109A | |
| 10A | |
| 11 | |
| 110 | |
| 110A | |
| 111 | |
| 111A | |
| 112 | |
| 113 | |
| 114 | |
| 115 | |
| 116 | |
| 117 | |
| 118 | |
| 119 | |
| 12 | |
| 120 | |
| 13 | |
| 14 | |
| 15 | |

Chicago Public Schools

School Hawthorne Academy
Address 3319 N Clifton Avenue

Unit 29131
 Chicago, IL, 60657

Building ID 3830
Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

Management Planner's Comments Summarized at the End of the Report

| HA Number | Management Comments |
|-----------|-------------------------|
| 16 | |
| 17 | |
| 18 | |
| 19 | |
| 20 | |
| 21 | |
| 22 | |
| 23 | |
| 24 | |
| 25 | |
| 26 | |
| 27 | |
| 28 | |
| 29 | |
| 30 | |
| 31 | |
| 32 | |
| 33 | Repair Damaged ACM ASAP |
| 34 | |
| 35 | Repair Damaged ACM ASAP |
| 36 | |
| 37 | |
| 38 | |
| 39 | |
| 40 | |
| 41 | |
| 42 | |

Chicago Public Schools

School Hawthorne Academy

Unit 29131

Building ID 3830

Address 3319 N Clifton Avenue

Chicago, IL, 60657

Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

Management Planner's Comments Summarized at the End of the Report

| HA Number | Management Comments |
|-----------|--|
| A | |
| B | |
| C | Repair Damaged ACM, Restrict Access until Repaired |
| D | Repair Damaged ACM ASAP |
| E | |
| F | |
| G | |
| H | |
| I | |
| J | |

Chicago Public Schools

GSG Consultants, Inc.

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Hawthorne Academy** INSPECTION DATE: **3/9/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **04**
MATERIAL DESCRIPTION: **9"x9" Tan VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Room 113, 114, 115, 213, 214, 215, 216, storage room between rms 215 & 216 - 1960**

MATERIAL QUANTITY: **2900** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Hawthorne Academy** REVIEW DATE: **5/20/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **04**
MATERIAL DESCRIPTION: **9"x9" Tan VFT**
MATERIAL LOCATION: **Room 113, 114, 115, 213, 214, 215, 216, storage room between rms 215 & 216 - 1960**
MATERIAL QUANTITY: **2900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/20/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Hawthorne Academy** INSPECTION DATE: **3/9/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **05**
MATERIAL DESCRIPTION: **12"x12" Tan VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Rooms 101, 102-105, 107-112, 202-212, Toilet & Storage (teacher's rm 2nd fl. & 1st fl.), Eng.off, Main Office, Prin. office, toilet & storage, 1st & 2nd fl. corridors, bsmt teacher's break rm. - 1952-**

MATERIAL QUANTITY: **15300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc.

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Hawthorne Academy** REVIEW DATE: **5/20/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **05**

MATERIAL DESCRIPTION: **12"x12" Tan VFT**

MATERIAL LOCATION: **Rooms 101, 102-105, 107-112, 202-212, Toilet & Storage (teacher's rm 2nd fl. & 1st fl.), Eng.off, Main Office, Prin. office, toilet & storage, 1st & 2nd fl. corridors, bsmt teacher's break rm. - 1952-**

MATERIAL QUANTITY: **15300**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/20/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Hawthorne Academy** INSPECTION DATE: **3/9/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **06**
MATERIAL DESCRIPTION: **9"x9" Dark Brown VFT**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **Assembly Hall, 1928**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUILDING ID: **3830**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Hawthorne Academy** REVIEW DATE: **5/20/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **06**

MATERIAL DESCRIPTION: **9"x9" Dark Brown VFT**

MATERIAL LOCATION: **Assembly Hall, 1928**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:


DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/20/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Hawthorne Academy** INSPECTION DATE: **3/9/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **07**
MATERIAL DESCRIPTION: **12"x12" Light Tan VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Basement Room 004 - 1952**
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc.

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Hawthorne Academy** REVIEW DATE: **5/20/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **07**
MATERIAL DESCRIPTION: **12"x12" Light Tan VFT**
MATERIAL LOCATION: **Basement Room 004 - 1952**
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **05/20/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Hawthorne Academy** INSPECTION DATE: **3/9/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **08**
MATERIAL DESCRIPTION: **9"x9" Tan VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 113, 114, 115, 213, 214, 215, 216, storage room between rms 215 & 216 - 1960**
MATERIAL QUANTITY: **2900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Hawthorne Academy** REVIEW DATE: **5/20/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **08**
MATERIAL DESCRIPTION: **9"x9" Tan VFT Mastic**
MATERIAL LOCATION: **Room 113, 114, 115, 213, 214, 215, 216, storage room between rms 215 & 216 - 1960**
MATERIAL QUANTITY: **2900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/20/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Hawthorne Academy** INSPECTION DATE: **3/9/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **09**
MATERIAL DESCRIPTION: **12"x12" Tan VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 101, 102-105, 107-112, 202-212, Toilet & Storage (teacher's rm 2nd fl. & 1st fl.), Eng.off, Main Office, Prin. office, toilet & storage, 1st & 2nd fl. corridors, bsmt teacher's break rm. - 1952-**

MATERIAL QUANTITY: **15305** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Hawthorne Academy** REVIEW DATE: **5/20/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **09**
MATERIAL DESCRIPTION: **12"x12" Tan VFT Mastic**
MATERIAL LOCATION: **Rooms 101, 102-105, 107-112, 202-212, Toilet & Storage (teacher's rm 2nd fl. & 1st fl.), Eng.off, Main Office, Prin. office, toilet & storage, 1st & 2nd fl. corridors, bsmt teacher's break rm. - 1952-**
MATERIAL QUANTITY: **15305** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/20/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Hawthorne Academy** INSPECTION DATE: **3/9/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10**
MATERIAL DESCRIPTION: **1'x1' Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Lunchroom, Kitchen- 1952**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Hawthorne Academy** REVIEW DATE: **5/20/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **10**
MATERIAL DESCRIPTION: **1'x1' Ceiling Tile**
MATERIAL LOCATION: **Lunchroom, Kitchen- 1952**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **05/20/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Hawthorne Academy** INSPECTION DATE: **3/9/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **100**
MATERIAL DESCRIPTION: **12" x 12" White w/Brown Spots VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st Floor MDF Room and teacher's toilet- 1960**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Hawthorne Academy** REVIEW DATE: **5/20/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **100**
MATERIAL DESCRIPTION: **12" x 12" White w/Brown Spots VFT**
MATERIAL LOCATION: **1st Floor MDF Room and teacher's toilet- 1960**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/20/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Hawthorne Academy** INSPECTION DATE: **3/9/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **101**
MATERIAL DESCRIPTION: **12" x 12" White w/Brown Spots VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st Floor MDF Room & Teacher's Toilet- 1960**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Hawthorne Academy** REVIEW DATE: **5/20/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **101**
MATERIAL DESCRIPTION: **12" x 12" White w/Brown Spots VFT Mastic**
MATERIAL LOCATION: **1st Floor MDF Room & Teacher's Toilet- 1960**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: **05/20/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Hawthorne Academy** INSPECTION DATE: **3/9/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **102**
MATERIAL DESCRIPTION: **12 x 12 inch Green w/White Streaks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Basement Lunch Room, 1952 Bldg**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Hawthorne Academy** REVIEW DATE: **5/20/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **102**
MATERIAL DESCRIPTION: **12 x 12 inch Green w/White Streaks VFT**
MATERIAL LOCATION: **Basement Lunch Room, 1952 Bldg**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **05/20/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Hawthorne Academy** INSPECTION DATE: **3/9/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **102 A**
MATERIAL DESCRIPTION: **12 x 12 inch Green w/White Streaks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Basement Lunch Room, Bldg 1952**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Hawthorne Academy** REVIEW DATE: **5/20/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **102 A**
MATERIAL DESCRIPTION: **12 x 12 inch Green w/White Streaks VFT Mastic**
MATERIAL LOCATION: **Basement Lunch Room, Bldg 1952**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/20/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Hawthorne Academy** INSPECTION DATE: **3/9/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **103**
MATERIAL DESCRIPTION: **Carpet mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 226 (1928)**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Hawthorne Academy** REVIEW DATE: **5/20/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **103**
MATERIAL DESCRIPTION: **Carpet mastic**
MATERIAL LOCATION: **Room 226 (1928)**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/20/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Hawthorne Academy** INSPECTION DATE: **3/9/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **104**
MATERIAL DESCRIPTION: **Carpet mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 201, Main Office, Principal's Office (1952)**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Hawthorne Academy** REVIEW DATE: **5/20/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **104**
MATERIAL DESCRIPTION: **Carpet mastic**
MATERIAL LOCATION: **Room 201, Main Office, Principal's Office (1952)**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **05/20/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Hawthorne Academy** INSPECTION DATE: **3/9/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **105**
MATERIAL DESCRIPTION: **1' X 1' Ceiling Tiles**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Gymnasium and Assembly Hall (1928)**
MATERIAL QUANTITY: **40000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____


Michael Holvay
Project Manager

Date: 03/09/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Hawthorne Academy** REVIEW DATE: **5/20/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **105**
MATERIAL DESCRIPTION: **1' X 1' Ceiling Tiles**
MATERIAL LOCATION: **Gymnasium and Assembly Hall (1928)**
MATERIAL QUANTITY: **40000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/20/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Hawthorne Academy** INSPECTION DATE: **3/9/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **105A**
MATERIAL DESCRIPTION: **1' X 1' Ceiling Tiles Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Gymnasium and Assembly Hall (1928)**
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____


Michael Holvay
Project Manager

Date: 03/09/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUILDING ID: **3830**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Hawthorne Academy** REVIEW DATE: **5/20/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **105A**
MATERIAL DESCRIPTION: **1' X 1' Ceiling Tiles Mastic**
MATERIAL LOCATION: **Gymnasium and Assembly Hall (1928)**
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/20/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Hawthorne Academy** INSPECTION DATE: **3/9/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **106**
MATERIAL DESCRIPTION: **Damper Cloth**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Fan Room, North and South Attic - (1952)**
MATERIAL QUANTITY: **80** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Hawthorne Academy** REVIEW DATE: **5/20/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **106**
MATERIAL DESCRIPTION: **Damper Cloth**
MATERIAL LOCATION: **Fan Room, North and South Attic - (1952)**
MATERIAL QUANTITY: **80** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **05/20/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Hawthorne Academy** INSPECTION DATE: **3/9/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **107**
MATERIAL DESCRIPTION: **Black sink-coating**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 113, 115, 116, 213, 215, 216 (1960)**
MATERIAL QUANTITY: **36** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Hawthorne Academy** REVIEW DATE: **5/20/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **107**
MATERIAL DESCRIPTION: **Black sink-coating**
MATERIAL LOCATION: **Rooms 113, 115, 116, 213, 215, 216 (1960)**
MATERIAL QUANTITY: **36** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **05/20/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Hawthorne Academy** INSPECTION DATE: **3/9/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **108**
MATERIAL DESCRIPTION: **12"X12" Gray VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Assembly Hall - (1928)**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Hawthorne Academy** REVIEW DATE: **5/20/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **108**
MATERIAL DESCRIPTION: **12"X12" Gray VFT**
MATERIAL LOCATION: **Assembly Hall - (1928)**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: **05/20/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Hawthorne Academy** INSPECTION DATE: **3/9/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **108A**
MATERIAL DESCRIPTION: **12"X12" Gray VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Assembly Hall - (1928)**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Hawthorne Academy** REVIEW DATE: **5/20/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **108A**
MATERIAL DESCRIPTION: **12"X12" Gray VFT Mastic**
MATERIAL LOCATION: **Assembly Hall - (1928)**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/20/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Hawthorne Academy** INSPECTION DATE: **3/9/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **109**
MATERIAL DESCRIPTION: **12"X12" White w/black streaks NOT OBSERVED**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Lunch Room - (1952)-**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUILDING ID: **3830**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Hawthorne Academy** REVIEW DATE: **5/20/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **109**
MATERIAL DESCRIPTION: **12"X12" White w/black streaks NOT OBSERVED**
MATERIAL LOCATION: **Lunch Room - (1952)-**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **05/20/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Hawthorne Academy** INSPECTION DATE: **3/9/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **109A**
MATERIAL DESCRIPTION: **12"X12" White w/black streaks Mastic- NOT OBSERVED**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Lunch Room - (1952)**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Hawthorne Academy** REVIEW DATE: **5/20/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **109A**
MATERIAL DESCRIPTION: **12"X12" White w/black streaks Mastic- NOT OBSERVED**
MATERIAL LOCATION: **Lunch Room - (1952)**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: **05/20/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Hawthorne Academy** INSPECTION DATE: **3/9/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10A**
MATERIAL DESCRIPTION: **1 ft X 1 ft ceiling tile mastic (1952)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Lunch Room, Kitchen**
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Hawthorne Academy** REVIEW DATE: **5/20/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **10A**
MATERIAL DESCRIPTION: **1 ft X 1 ft ceiling tile mastic (1952)**
MATERIAL LOCATION: **Lunch Room, Kitchen**
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **05/20/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Hawthorne Academy** INSPECTION DATE: **3/9/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11**
MATERIAL DESCRIPTION: **9"x9" Dark Brown VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **Assembly Hall, 1928**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Hawthorne Academy** REVIEW DATE: **5/20/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **11**

MATERIAL DESCRIPTION: **9"x9" Dark Brown VFT Mastic**

MATERIAL LOCATION: **Assembly Hall, 1928**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/20/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Hawthorne Academy** INSPECTION DATE: **3/9/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **110**
MATERIAL DESCRIPTION: **12"X12" Taupe VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Room 216 (1960)**
MATERIAL QUANTITY: **70** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Hawthorne Academy** REVIEW DATE: **5/20/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **110**
MATERIAL DESCRIPTION: **12"X12" Taupe VFT**
MATERIAL LOCATION: **Room 216 (1960)**
MATERIAL QUANTITY: **70** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/20/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Hawthorne Academy** INSPECTION DATE: **3/9/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **110A**
MATERIAL DESCRIPTION: **12"x12" Taupe VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 216 (1960)**
MATERIAL QUANTITY: **70** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Hawthorne Academy** REVIEW DATE: **5/20/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **110A**
MATERIAL DESCRIPTION: **12"x12" Taupe VFT Mastic**
MATERIAL LOCATION: **Room 216 (1960)**
MATERIAL QUANTITY: **70** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/20/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Hawthorne Academy** INSPECTION DATE: **3/9/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **111**
MATERIAL DESCRIPTION: **12"X12" White w/Beige VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Room 116 (1960)**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Hawthorne Academy** REVIEW DATE: **5/20/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **111**
MATERIAL DESCRIPTION: **12"X12" White w/Beige VFT**
MATERIAL LOCATION: **Room 116 (1960)**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: **05/20/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Hawthorne Academy** INSPECTION DATE: **3/9/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **111A**
MATERIAL DESCRIPTION: **12"X12" White w/Beige VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 116T (1960)**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Hawthorne Academy** REVIEW DATE: **5/20/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **111A**
MATERIAL DESCRIPTION: **12"X12" White w/Beige VFT Mastic**
MATERIAL LOCATION: **Room 116T (1960)**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: **05/20/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Hawthorne Academy** INSPECTION DATE: **3/9/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **112**
MATERIAL DESCRIPTION: **Vinyl Baseboard Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 114 (1960)**
MATERIAL QUANTITY: **140** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Hawthorne Academy** REVIEW DATE: **5/20/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **112**
MATERIAL DESCRIPTION: **Vinyl Baseboard Mastic**
MATERIAL LOCATION: **Room 114 (1960)**
MATERIAL QUANTITY: **140** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **05/20/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Hawthorne Academy** INSPECTION DATE: **3/9/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **113**
MATERIAL DESCRIPTION: **1'x1' white w/grooves & holes ceiling tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Bsmt play area by pump room - 1960 bldg.**
MATERIAL QUANTITY: **650** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Hawthorne Academy** REVIEW DATE: **5/20/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **113**
MATERIAL DESCRIPTION: **1'x1' white w/grooves & holes ceiling tile**
MATERIAL LOCATION: **Bsmt play area by pump room - 1960 bldg.**
MATERIAL QUANTITY: **650** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **05/20/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Hawthorne Academy** INSPECTION DATE: **3/9/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12**
MATERIAL DESCRIPTION: **1'x1' Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Assembly Hall- 1928**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUILDING ID: **3830**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Hawthorne Academy** REVIEW DATE: **5/20/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **12**
MATERIAL DESCRIPTION: **1'x1' Ceiling Tile**
MATERIAL LOCATION: **Assembly Hall- 1928**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **05/20/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Hawthorne Academy** INSPECTION DATE: **3/9/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13**
MATERIAL DESCRIPTION: **9"x9" Green VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 113 through 115, 213 through 215, storage rm. between rms. 215 & 216 - 1960**
MATERIAL QUANTITY: **3050** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Hawthorne Academy** REVIEW DATE: **5/20/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **13**
MATERIAL DESCRIPTION: **9"x9" Green VFT**
MATERIAL LOCATION: **Room 113 through 115, 213 through 215, storage rm. between rms. 215 & 216 - 1960**
MATERIAL QUANTITY: **3050** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: **05/20/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Hawthorne Academy** INSPECTION DATE: **3/9/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14**
MATERIAL DESCRIPTION: **12"x12" Green VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 100, 103-105, 107-112, 202-212, bsmt teacher's break rm. - 1952**
MATERIAL QUANTITY: **11385** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Hawthorne Academy** REVIEW DATE: **5/20/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **14**
MATERIAL DESCRIPTION: **12"x12" Green VFT**
MATERIAL LOCATION: **Room 100, 103-105, 107-112, 202-212, bsmt teacher's break rm. - 1952**
MATERIAL QUANTITY: **11385** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: **05/20/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Hawthorne Academy** INSPECTION DATE: **3/9/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15**
MATERIAL DESCRIPTION: **12"x12" Light Tan VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Basement Room 004 - (1952)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUILDING ID: **3830**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Hawthorne Academy** REVIEW DATE: **5/20/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **15**
MATERIAL DESCRIPTION: **12"x12" Light Tan VFT Mastic**
MATERIAL LOCATION: **Basement Room 004 - (1952)**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **05/20/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Hawthorne Academy** INSPECTION DATE: **3/9/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16**
MATERIAL DESCRIPTION: **12"x12" Peach VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **1st and 2nd Floor Corridor- 1960**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Hawthorne Academy** REVIEW DATE: **5/20/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **16**
MATERIAL DESCRIPTION: **12"x12" Peach VFT**
MATERIAL LOCATION: **1st and 2nd Floor Corridor- 1960**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/20/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Hawthorne Academy** INSPECTION DATE: **3/9/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17**
MATERIAL DESCRIPTION: **12"x12" Peach VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st and 2nd Floor Corridor- 1960**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Hawthorne Academy** REVIEW DATE: **5/20/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **17**
MATERIAL DESCRIPTION: **12"x12" Peach VFT Mastic**
MATERIAL LOCATION: **1st and 2nd Floor Corridor- 1960**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: **05/20/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Hawthorne Academy** INSPECTION DATE: **3/9/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18**
MATERIAL DESCRIPTION: **9"x9" Tan w/ Black & White VFT**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st Floor Corridor- 1952**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Hawthorne Academy** REVIEW DATE: **5/20/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **18**

MATERIAL DESCRIPTION: **9"x9" Tan w/ Black & White VFT**

MATERIAL LOCATION: **1st Floor Corridor- 1952**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/20/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Hawthorne Academy** INSPECTION DATE: **3/9/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19**
MATERIAL DESCRIPTION: **9"x9" Tan w/ Black & White VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st Floor Corridor- 1952**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Hawthorne Academy** REVIEW DATE: **5/20/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **19**
MATERIAL DESCRIPTION: **9"x9" Tan w/ Black & White VFT Mastic**
MATERIAL LOCATION: **1st Floor Corridor- 1952**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: **05/20/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Hawthorne Academy** INSPECTION DATE: **3/9/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**
MATERIAL DESCRIPTION: **12"x12" Tan w/ Scaly Brown Spots VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **3rd Floor Penthouse - 1928**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Hawthorne Academy** REVIEW DATE: **5/20/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **20**
MATERIAL DESCRIPTION: **12"x12" Tan w/ Scaly Brown Spots VFT**
MATERIAL LOCATION: **3rd Floor Penthouse - 1928**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: **05/20/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Hawthorne Academy** INSPECTION DATE: **3/9/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21**
MATERIAL DESCRIPTION: **12"x12" Tan w/ Scaly Brown Spots VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **3rd Floor Penthouse - 1928**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Hawthorne Academy** REVIEW DATE: **5/20/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **21**
MATERIAL DESCRIPTION: **12"x12" Tan w/ Scaly Brown Spots VFT Mastic**
MATERIAL LOCATION: **3rd Floor Penthouse - 1928**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: **05/20/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Hawthorne Academy** INSPECTION DATE: **3/9/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22**
MATERIAL DESCRIPTION: **12"x12" Tan w/ Maroon Streaks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 101, 1st Floor Corridor, Main Office, Teachers' Room - 1952 bldg.**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Hawthorne Academy** REVIEW DATE: **5/20/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **22**
MATERIAL DESCRIPTION: **12"x12" Tan w/ Maroon Streaks VFT**
MATERIAL LOCATION: **Room 101, 1st Floor Corridor, Main Office, Teachers' Room - 1952 bldg.**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/20/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Hawthorne Academy** INSPECTION DATE: **3/9/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23**
MATERIAL DESCRIPTION: **12"x12" Tan w/ Maroon Streaks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 101, 1st Floor Corridor, Main Office, Teachers' Room - 1952 bldg.**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Hawthorne Academy** REVIEW DATE: **5/20/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **23**
MATERIAL DESCRIPTION: **12"x12" Tan w/ Maroon Streaks VFT Mastic**
MATERIAL LOCATION: **Room 101, 1st Floor Corridor, Main Office, Teachers' Room - 1952 bldg.**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/20/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Hawthorne Academy** INSPECTION DATE: **3/9/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **24**
MATERIAL DESCRIPTION: **Sprayed Applied Acoustical Plaster**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Basement Play Area West of Pump Room- 1960**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Hawthorne Academy** REVIEW DATE: **5/20/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**


HOMOGENEOUS AREA: **24**
MATERIAL DESCRIPTION: **Sprayed Applied Acoustical Plaster**
MATERIAL LOCATION: **Basement Play Area West of Pump Room- 1960**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/20/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Hawthorne Academy** INSPECTION DATE: **3/9/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25**
MATERIAL DESCRIPTION: **9"x9" Green w/ White & Black Streaks VFT - ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **Lunchroom- 1952**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Hawthorne Academy** REVIEW DATE: **5/20/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **25**
MATERIAL DESCRIPTION: **9"x9" Green w/ White & Black Streaks VFT - ABATED**
MATERIAL LOCATION: **Lunchroom- 1952**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **05/20/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUILDING ID: **3830**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Hawthorne Academy** INSPECTION DATE: **3/9/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26**
MATERIAL DESCRIPTION: **9"x9" Green w/ White & Black Streaks VFT Mastic - ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **Lunchroom- 1952**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUILDING ID: **3830**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Hawthorne Academy** REVIEW DATE: **5/20/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **26**

MATERIAL DESCRIPTION: **9"x9" Green w/ White & Black Streaks VFT Mastic - ABATED**

MATERIAL LOCATION: **Lunchroom- 1952**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:


DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/20/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Hawthorne Academy** INSPECTION DATE: **3/9/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27**
MATERIAL DESCRIPTION: **9"x9" Tan w/ Brown & White Streaks VFT - ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **Lunchroom- 1952**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUILDING ID: **3830**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Hawthorne Academy** REVIEW DATE: **5/20/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **27**

MATERIAL DESCRIPTION: **9"x9" Tan w/ Brown & White Streaks VFT - ABATED**

MATERIAL LOCATION: **Lunchroom- 1952**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:


DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/20/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Hawthorne Academy** INSPECTION DATE: **3/9/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28**
MATERIAL DESCRIPTION: **9"x9" Tan w/ Brown & White Streaks VFT Mastic - ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **Lunchroom- 1952**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Hawthorne Academy** REVIEW DATE: **5/20/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**


HOMOGENEOUS AREA: **28**
MATERIAL DESCRIPTION: **9"x9" Tan w/ Brown & White Streaks VFT Mastic - ABATED**
MATERIAL LOCATION: **Lunchroom- 1952**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/20/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Hawthorne Academy** INSPECTION DATE: **3/9/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **29**
MATERIAL DESCRIPTION: **MJP E/F/V on Aircell Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout (See Hatching Maps)- 1952**
MATERIAL QUANTITY: **390** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**
COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Hawthorne Academy** REVIEW DATE: **5/20/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **29**
MATERIAL DESCRIPTION: **MJP E/F/V on Aircell Pipe Insulation**
MATERIAL LOCATION: **Throughout (See Hatching Maps)- 1952**
MATERIAL QUANTITY: **390** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: **05/20/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Hawthorne Academy** INSPECTION DATE: **3/9/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **30**
MATERIAL DESCRIPTION: **MJP E/F/V on Fiberglass Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with potential for significant damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Playroom Closet, Pipe Chase in SE Corner of Playroom Area - 1960**
MATERIAL QUANTITY: **45** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Hawthorne Academy** REVIEW DATE: **5/20/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **30**
MATERIAL DESCRIPTION: **MJP E/F/V on Fiberglass Pipe Insulation**
MATERIAL LOCATION: **Playroom Closet, Pipe Chase in SE Corner of Playroom Area - 1960**
MATERIAL QUANTITY: **45** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: **05/20/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Hawthorne Academy** INSPECTION DATE: **3/9/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **31**
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Playroom Closet, Pump Room Storage, Pipe Chase in SE Corner of Playroom Area - 1960**

MATERIAL QUANTITY: **31** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Hawthorne Academy** REVIEW DATE: **5/20/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **31**
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**
MATERIAL LOCATION: **Playroom Closet, Pump Room Storage, Pipe Chase in SE Corner of Playroom Area - 1960**
MATERIAL QUANTITY: **31** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: **05/20/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Hawthorne Academy** INSPECTION DATE: **3/9/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **32**
MATERIAL DESCRIPTION: **MJP E/F/V on Aircell Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Playroom Closet, Pump Room Storage, Pipe Chase in SE Corner of Playroom Area - 1960**

MATERIAL QUANTITY: **15** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Hawthorne Academy** REVIEW DATE: **5/20/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **32**
MATERIAL DESCRIPTION: **MJP E/F/V on Aircell Pipe Insulation**
MATERIAL LOCATION: **Playroom Closet, Pump Room Storage, Pipe Chase in SE Corner of Playroom Area - 1960**
MATERIAL QUANTITY: **15** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **05/20/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Hawthorne Academy** INSPECTION DATE: **3/9/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **33**
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **1 ACBM with potential for significant damage**
HISTORICAL DAMAGE REASON: **Deterioration**
HISTORICAL RESPONSE ACTION: **Repair**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**


RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON: **Deterioration**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Fan Room, Unexcavated Area, Stage Area, Janitors Storage, Corridor outside basement- 1928**
MATERIAL QUANTITY: **350** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**
COMMENTS:

Inspector's Signature: _____


Michael Holvay
Project Manager

Date: 03/09/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Hawthorne Academy** REVIEW DATE: **5/20/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **33**
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**
MATERIAL LOCATION: **Fan Room, Unexcavated Area, Stage Area, Janitors Storage, Corridor outside basement- 1928**
MATERIAL QUANTITY: **350** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **40** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Repair Damaged ACM ASAP

Management Planner's Signature:  Date: **05/20/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Hawthorne Academy** INSPECTION DATE: **3/9/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **34**
MATERIAL DESCRIPTION: **MJP E/F/V on Aircell Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Fan Room, Unexcavated Area, Stage Area, Janitors Storage, Corridor outside basement- 1928**

MATERIAL QUANTITY: **30** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Hawthorne Academy** REVIEW DATE: **5/20/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **34**
MATERIAL DESCRIPTION: **MJP E/F/V on Aircell Pipe Insulation**
MATERIAL LOCATION: **Fan Room, Unexcavated Area, Stage Area, Janitors Storage, Corridor outside basement- 1928**
MATERIAL QUANTITY: **30** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **05/20/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Hawthorne Academy** INSPECTION DATE: **3/9/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **35**
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **1 ACBM with potential for significant damage**
HISTORICAL DAMAGE REASON: **Deterioration**
HISTORICAL RESPONSE ACTION: **Repair**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON: **Deterioration**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Unexcavated Area Under Auditorium-, Foyer and Stairs outside Auditorium- 1928**
MATERIAL QUANTITY: **350** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **350** DAMAGE UNITS: **LF**
COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Hawthorne Academy** REVIEW DATE: **5/20/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **35**
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**
MATERIAL LOCATION: **Unexcavated Area Under Auditorium-, Foyer and Stairs outside Auditorium- 1928**
MATERIAL QUANTITY: **350** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **20** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Repair Damaged ACM ASAP

Management Planner's Signature: _____

Jigar Shah

Date: **05/20/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Hawthorne Academy** INSPECTION DATE: **3/9/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **36**
MATERIAL DESCRIPTION: **MJP E/F/V on Cardboard Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Unexcavated Area Under Auditorium- 1928**
MATERIAL QUANTITY: **35** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**
COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Hawthorne Academy** REVIEW DATE: **5/20/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **36**
MATERIAL DESCRIPTION: **MJP E/F/V on Cardboard Pipe Insulation**
MATERIAL LOCATION: **Unexcavated Area Under Auditorium- 1928**
MATERIAL QUANTITY: **35** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: **05/20/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Hawthorne Academy** INSPECTION DATE: **3/9/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37**
MATERIAL DESCRIPTION: **6"x18" Black VFT - ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **Assembly Hall - 1928**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUILDING ID: **3830**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Hawthorne Academy** REVIEW DATE: **5/20/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **37**

MATERIAL DESCRIPTION: **6"x18" Black VFT - ABATED**

MATERIAL LOCATION: **Assembly Hall - 1928**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:


DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/20/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Hawthorne Academy** INSPECTION DATE: **3/9/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **38**
MATERIAL DESCRIPTION: **6"x18" Black VFT Mastic - ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **Assembly Hall - 1928**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Hawthorne Academy** REVIEW DATE: **5/20/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **38**
MATERIAL DESCRIPTION: **6"x18" Black VFT Mastic - ABATED**
MATERIAL LOCATION: **Assembly Hall - 1928**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/20/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Hawthorne Academy** INSPECTION DATE: **3/9/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **39**
MATERIAL DESCRIPTION: **12"x12" Red VFT - ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **Assembly Hall - 1928**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUILDING ID: **3830**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Hawthorne Academy** REVIEW DATE: **5/20/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **39**

MATERIAL DESCRIPTION: **12"x12" Red VFT - ABATED**

MATERIAL LOCATION: **Assembly Hall - 1928**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:


DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/20/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Hawthorne Academy** INSPECTION DATE: **3/9/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **40**
MATERIAL DESCRIPTION: **12"x12" Red VFT Mastic - ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **Assembly Hall - 1928**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUILDING ID: **3830**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Hawthorne Academy** REVIEW DATE: **5/20/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **40**

MATERIAL DESCRIPTION: **12"x12" Red VFT Mastic - ABATED**

MATERIAL LOCATION: **Assembly Hall - 1928**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:


DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/20/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Hawthorne Academy** INSPECTION DATE: **3/9/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **41**
MATERIAL DESCRIPTION: **9"x9" Green VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 113, 114, 115, 213, 214, 215, 216, storage rm between rms 215 & 216 - 1960**
MATERIAL QUANTITY: **3050** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Hawthorne Academy** REVIEW DATE: **5/20/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **41**
MATERIAL DESCRIPTION: **9"x9" Green VFT Mastic**
MATERIAL LOCATION: **Room 113, 114, 115, 213, 214, 215, 216, storage rm between rms 215 & 216 - 1960**
MATERIAL QUANTITY: **3050** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: **05/20/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Hawthorne Academy** INSPECTION DATE: **3/9/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **42**
MATERIAL DESCRIPTION: **12"x12" Green VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 100, 103-105, 107-112, 202-212, bsmt teacher's break room - 1952**
MATERIAL QUANTITY: **11385** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Hawthorne Academy** REVIEW DATE: **5/20/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **42**
MATERIAL DESCRIPTION: **12"x12" Green VFT Mastic**
MATERIAL LOCATION: **Room 100, 103-105, 107-112, 202-212, bsmt teacher's break room - 1952**
MATERIAL QUANTITY: **11385** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **05/20/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Hawthorne Academy** INSPECTION DATE: **3/9/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **A**
MATERIAL DESCRIPTION: **Aircell Pipe Insulation - Same as HA 33**
HISTORICAL AHERA DAMAGE CATEGORY: **ACBM with potential for significant damage**
HISTORICAL DAMAGE REASON: **Deterioration**
HISTORICAL RESPONSE ACTION: **Repair**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON: **Deterioration**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout (See Hatching Maps), 101, Toilet Rooms- 1952**
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **1600** DAMAGE UNITS: **LF**
COMMENTS: **Same as HA 33**

Inspector's Signature: _____


Michael Holvay
Project Manager

Date: 03/09/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Hawthorne Academy** REVIEW DATE: **5/20/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **A**
MATERIAL DESCRIPTION: **Aircell Pipe Insulation - Same as HA 33**
MATERIAL LOCATION: **Throughout (See Hatching Maps), 101, Toilet Rooms- 1952**
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Management Planner's Signature: _____



Date: **05/20/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Hawthorne Academy** INSPECTION DATE: **3/9/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **B**
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation - Same as HA 35**
HISTORICAL AHERA DAMAGE CATEGORY: **ACBM with potential for significant damage**
HISTORICAL DAMAGE REASON: **Deterioration**
HISTORICAL RESPONSE ACTION: **Repair**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON: **Deterioration**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout (See Hatching Maps)- 1952**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**
COMMENTS: **Same as HA 35**

Inspector's Signature:


Michael Holvay
Project Manager

Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Hawthorne Academy** REVIEW DATE: **5/20/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **B**
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation - Same as HA 35**
MATERIAL LOCATION: **Throughout (See Hatching Maps)- 1952**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Management Planner's Signature:  Date: **05/20/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Hawthorne Academy** INSPECTION DATE: **3/9/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **C**
MATERIAL DESCRIPTION: **MJP E/F/V on Cardboard Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **1 ACBM with potential for significant damage**
HISTORICAL DAMAGE REASON: **Deterioration**
HISTORICAL RESPONSE ACTION: **Repair**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON: **Deterioration**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout (See Hatching Maps)- 1952**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**
COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUILDING ID: **3830**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Hawthorne Academy** REVIEW DATE: **5/20/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **C**
MATERIAL DESCRIPTION: **MJP E/F/V on Cardboard Pipe Insulation**
MATERIAL LOCATION: **Throughout (See Hatching Maps)- 1952**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **20** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Repair Damaged ACM, Restrict Access until Repaired

Management Planner's Signature: _____

Jigar Shah

Date: **05/20/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Hawthorne Academy** INSPECTION DATE: **3/9/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **D**
MATERIAL DESCRIPTION: **Mag Block Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **1 ACBM with potential for significant damage**
HISTORICAL DAMAGE REASON: **Deterioration**
HISTORICAL RESPONSE ACTION: **Repair**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON: **Deterioration**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **2nd Floor Boys Toilet, Pump Room, Boiler Room, Fan Room - 1952**
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **1800** DAMAGE UNITS: **LF**
COMMENTS:

Inspector's Signature: _____


Michael Holvay
Project Manager

Date: 03/09/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Hawthorne Academy** REVIEW DATE: **5/20/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **D**
MATERIAL DESCRIPTION: **Mag Block Pipe Insulation**
MATERIAL LOCATION: **2nd Floor Boys Toilet, Pump Room, Boiler Room, Fan Room - 1952**
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **15** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Repair Damaged ACM ASAP

Management Planner's Signature: _____

Jigar Shah

Date: **05/20/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Hawthorne Academy** INSPECTION DATE: **3/9/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **E**
MATERIAL DESCRIPTION: **MJP E/F/V on Mag Block Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **2nd Floor Boys Toilet, Pump Room, Boiler Room, Fan Room - 1952**
MATERIAL QUANTITY: **450** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**
COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Hawthorne Academy** REVIEW DATE: **5/20/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **E**
MATERIAL DESCRIPTION: **MJP E/F/V on Mag Block Pipe Insulation**
MATERIAL LOCATION: **2nd Floor Boys Toilet, Pump Room, Boiler Room, Fan Room - 1952**
MATERIAL QUANTITY: **450** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **05/20/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Hawthorne Academy** INSPECTION DATE: **3/9/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **F**
MATERIAL DESCRIPTION: **Tank Insulation *abated on 8/28/10**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **Tank Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Hawthorne Academy** REVIEW DATE: **5/20/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **F**

MATERIAL DESCRIPTION: **Tank Insulation *abated on 8/28/10**

MATERIAL LOCATION: **Tank Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:


DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/20/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Hawthorne Academy** INSPECTION DATE: **3/9/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **G**
MATERIAL DESCRIPTION: **Acoustic Plaster Ceiling**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st and 2nd Floor Hallways - 1960 Bldg.**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Hawthorne Academy** REVIEW DATE: **5/20/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **G**
MATERIAL DESCRIPTION: **Acoustic Plaster Ceiling**
MATERIAL LOCATION: **1st and 2nd Floor Hallways - 1960 Bldg.**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **05/20/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Hawthorne Academy** INSPECTION DATE: **3/9/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **H**
MATERIAL DESCRIPTION: **Terrazzo**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Stair treads and landings and assembly-stair treads and landing. - (1928)**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____


Michael Holvay
Project Manager

Date: 03/09/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUILDING ID: **3830**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Hawthorne Academy** REVIEW DATE: **5/20/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **H**
MATERIAL DESCRIPTION: **Terrazzo**
MATERIAL LOCATION: **Stair treads and landings and assembly-stair treads and landing. - (1928)**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **05/20/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Hawthorne Academy** INSPECTION DATE: **3/9/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **I**
MATERIAL DESCRIPTION: **Terrazzo**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Stairwell treads and landings - (1952)**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____


Michael Holvay
Project Manager

Date: 03/09/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Hawthorne Academy** REVIEW DATE: **5/20/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **I**
MATERIAL DESCRIPTION: **Terrazzo**
MATERIAL LOCATION: **Stairwell treads and landings - (1952)**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **05/20/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Hawthorne Academy** INSPECTION DATE: **3/9/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **J**
MATERIAL DESCRIPTION: **Terrazzo**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Stairwell treads and landings - (1960)**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUIDLING ID: **3830**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Hawthorne Academy** REVIEW DATE: **5/20/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **J**
MATERIAL DESCRIPTION: **Terrazzo**
MATERIAL LOCATION: **Stairwell treads and landings - (1960)**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **05/20/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUILDING ID: **3830**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Hawthorne Academy** INSPECTION DATE: **3/9/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **115**
MATERIAL DESCRIPTION: **12" x 12" Gray Streaked VFT Mastic**
MATERIAL LOCATION: **1st Floor Corridor, Main Office (1952 Addition)**
MATERIAL QUANTITY: **3200** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Barely Reachable** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____


Michael Holvay
Project Manager

Date: 03/09/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUILDING ID: **3830**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Hawthorne Academy** REVIEW DATE: **5/20/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **115**
MATERIAL DESCRIPTION: **12" x 12" Gray Streaked VFT Mastic**
MATERIAL LOCATION: **1st Floor Corridor, Main Office (1952 Addition)**
MATERIAL QUANTITY: **3200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____

Jigar Shah

Date: 05/20/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUILDING ID: **3830**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Hawthorne Academy** REVIEW DATE: **5/20/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **117**
MATERIAL DESCRIPTION: **12" X 12" Gray Streaked VFT Mastic**
MATERIAL LOCATION: **1st Floor Corridor (1960 Addition)**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: **05/20/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUILDING ID: **3830**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Hawthorne Academy** REVIEW DATE: **5/20/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **116**
MATERIAL DESCRIPTION: **12" x 12" Gray Streaked VFT**
MATERIAL LOCATION: **1st Floor Corridor (1960 Addition)**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____

Jigar Shah

Date: **05/20/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUILDING ID: **3830**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Hawthorne Academy** REVIEW DATE: **5/20/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **119**
MATERIAL DESCRIPTION: **Black Rubber Floor-Adhesive**
MATERIAL LOCATION: **Room 004 (1952 Addition)**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **05/20/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUILDING ID: **3830**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**
SCHOOL NAME: **Hawthorne Academy** INSPECTION DATE: **3/9/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **114**
MATERIAL DESCRIPTION: **12" x 12" Gray Streaked VFT**
MATERIAL LOCATION: **1st Floor Corridor, Main Office (1952 Addition)**
MATERIAL QUANTITY: **3200** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **MODERATE** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form


LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUILDING ID: **3830**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Hawthorne Academy** REVIEW DATE: **5/20/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **114**
MATERIAL DESCRIPTION: **12" x 12" Gray Streaked VFT**
MATERIAL LOCATION: **1st Floor Corridor, Main Office (1952 Addition)**
MATERIAL QUANTITY: **3200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: **05/20/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUILDING ID: **3830**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Hawthorne Academy** REVIEW DATE: **5/20/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **120**
MATERIAL DESCRIPTION: **Troweled on plaster**
MATERIAL LOCATION: **Auditorium Foyer (1928 Bldg)**
MATERIAL QUANTITY: **80** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **05/20/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29131** BUILDING ID: **3830**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Hawthorne Academy** REVIEW DATE: **5/20/2016**
ADDRESS: **3319 N Clifton Avenue** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **118**
MATERIAL DESCRIPTION: **Carpet Mastic**
MATERIAL LOCATION: **Room 113 (1960 Addition)**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: 05/20/2016

APPENDIX B

Inspector and Management Planner Licenses



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • www.dph.illinois.gov

4/18/2016

MICHAEL HOLVAY
855 WEST ADAMS ST., Suite 200
CHICAGO, IL 60607

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 07210

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

| | | | | |
|---|------------------------------------|--|--|--|
|  <p>ASBESTOS PROFESSIONAL LICENSE</p> | | | <p>ENDORSEMENTS</p> <p>INSPECTOR</p> <p>PROJECT MANAGER</p> <p>AIR SAMPLING PROFESSIONAL</p> | <p>TC EXPIRES</p> <p>9/18/2016</p> <p>1/20/2017</p> |
| <p>ID NUMBER 100 - 07210</p> | <p>ISSUED 4/18/2016</p> | <p>EXPIRES 05/13/2017</p> | <p>Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.</p> | |
| <p>MICHAEL HOLVAY 855 WEST ADAMS ST., Suite 20 CHICAGO, IL 60607</p> <p>Environmental Health</p> | |  | | |

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH, IMPROVING LIVES
Nationally Accredited by PHAB

2015



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Michael Holway

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Course Date: 9/18/2015

Exam Date: 9/18/2015


Expiration Date: 9/18/2016

Certificate Number: BIR1509183493



Kathy DeSalvo, Director

2016



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Jigar Shah

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 1/27/2016

Exam Date: 1/27/2016

Expiration Date: 1/27/2017

Certificate Number: MPR1601270320


Kathy DeSalvo, Director



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • www.dph.illinois.gov

4/20/2016

JIGAR M SHAH
 855 W ADAMS ST, SUITE 200
 CHICAGO, IL 60607

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 07342

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

| | | | | | |
|---|----------------------------|---|--|---|---|
|  | | ASBESTOS PROFESSIONAL LICENSE | | ENDORSEMENTS | TC EXPIRES |
| ID NUMBER 109 - 07342 | ISSUED 4/20/2016 | EXPIRES 05/15/2017 |  | INSPECTOR PROJECT DESIGNER MANAGEMENT PLANNER PROJECT MANAGER AIR SAMPLING PROFESSIONAL | 1/19/2017 2/2/2017 1/27/2017 2/26/2017 |
| JIGAR M SHAH 855 W ADAMS ST, SUITE 200 CHICAGO, IL 60607 Environmental Health | | Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate. | | | |

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
 EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH, IMPROVING LIVES
Nationally Accredited by PHAB

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

| | CODE | KEY |
|--------------------------|-------------|--|
| MATERIAL | | |
| | ACBM | Asbestos Containing Building Materials |
| MATERIAL CATEGORY | | |
| | MISC | Miscellaneous |
| | SURF | Surfacing |
| | TSI | Thermal System Insulation |
| MATERIAL UNITS | | |
| | LF | Linear Feet |
| | SF | Square Feet |
| | CF | Cubic Feet |
| DAMAGE TYPE | | |
| | Loc | Localized |
| | Dist | Distributed |