

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH  
AHERA THREE YEAR REINSPECTION  
ASBESTOS ABATEMENT PROGRAM  
SCHOOL INFORMATION FORM**

**SECTION I**

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299  
SCHOOL ID NUMBER: 14-016-2990-2306  
SCHOOL NAME: LaSalle Academy  
ADDRESS OF SCHOOL: 1734 N. Orleans Street  
CITY: Chicago, IL, 60614

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **4/2/2013**

**If the address on this form is different than the address of the building, submit a written explanation.**

---

**SECTION II** *(Please type or print)*

**PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:**

DATE REINSPECTION COMPLETED: 8/11/2016 ENROLLMENT 560  
IDPH INSPECTOR LICENSE NUMBER: 100-11372  
IDPH LICENSED INSPECTOR NAME (Please Print): Eric Moore  
IDPH MP LICENSE NUMBER: 100-07342  
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Jigar Shah

DESIGNATED PERSON (Please Print): Robert Christlieb PHONE: (773) 553-3197



8/11/2016

*Signature of Designated Person*

*Date*

**SECTION III**

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: \_\_\_\_\_

School has been closed. Date closed: \_\_\_\_\_

School building has been demolished. Date: \_\_\_\_\_

School building is asbestos free since last reinspection: \_\_\_\_\_

**Please explain in writing why the school building is now asbestos free and include the supporting documentation.**

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

**Explain in writing if the address of the building is different than the address on this form:**

---

---

---

**THREE-YEAR REINSPECTION**

**CHICAGO SCHOOL DIST 299**

**LaSalle Academy**

1734 N. Orleans Street  
Chicago, IL, 60614

Unit: 29161  
Building ID: 4420

IDPH ID Number: 14-016-2990-2306

**REPORT DATE:**

Thursday, August 11, 2016

**Prepared for:**

**Chicago Public Schools**  
**125 S. Clark Street**  
**Chicago, IL 60603**

**Prepared by:**

**GSG Consultants, Inc.**

855 W. Adams St., Ste. 200

Phone (312) 733-6262

Fax (312) 733-5612

**DO NOT REMOVE FROM SCHOOL  
REQUIRED BY FEDERAL LAW**

July 29, 2016

Mr. R. Kent Cook  
Asbestos Program  
Illinois Department of Public Health  
525 West Jefferson Street  
Springfield, Illinois 62761

Re: Chicago Public Schools - 2016 Three-Year Reinspections

Dear Mr. Cook:

GSG Consultants, Inc., Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 1,2,6 Elementary Schools. Please update your records with the following information.

School District: 299            Unit: 29161            Region: 02            IDPH ID: 14-016-2990-2306

School: LaSalle Academy            Building ID: 4420

Address: 1734 N. Orleans Street  
Chicago, IL, 60614

Building Contact: Rosas, Manuel            Contact Phone: 773-852-7654

Current Building Owners: Chicago Public Schools

Review Date: 08/05/2016

Inspector: Eric Moore            Inspector IDPH License: 100-11372  
Management Planner: Jigar Shah            Management Planner IDPH License: 100-07342

If you have any questions or comments, please contact us at (312) 733-6262

Sincerely,  
GSG Consultants, Inc.



Jigar Shah  
100-07342

## **Environmental Notification to Occupants**

To: Faculty, Staff and Parents  
From: Chicago Public Schools  
Date: July 29, 2016

RE: LaSalle Academy, Unit 29161  
1734 N. Orleans Street  
Chicago, IL, 60614

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2016 asbestos three year re-inspection has been completed at LaSalle Academy, following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at LaSalle Academy, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Robert Christlieb, the designated Local Education Authority's Designated Person at (773) 553-3197 .

## **Table of Contents**

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

### **APPENDICES:**

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

## SCHOOL AND INSPECTION INFORMATION

### 1. School Information

School: LaSalle Academy Unit: 29161 Region: 02  
Address: 1734 N. Orleans Street Chicago, IL, 60614  
IDPH ID: 14-016-2990-2306 Building ID: 4420  
Contact: Rosas, Manuel Phone: 773-852-7654

### 2. Description of Facility

Original Construction: 1961 Additional Construction:  
Total Square Footage: 47156 No of Floors: 2  
Current Occupancy: 560

### 3. LEA Designated Person

Contact: Robert Christlieb Phone: (773) 553-3197  
Address: 125 South Clark Street, 17th Floor  
Chicago, IL 60603

### 4. Managing Environmental Consultant

MEC: GSG Consultants, Inc.  
Contact: Arturo Saenz  
Address 855 W. Adams St., Ste. 200  
Phone: (312) 733-6262 Fax: (312) 733-5612

### 5. Inspector

Inspector Name: Eric Moore


Inspector IDPH license # 100-11372

Signature:  
Date: 7/29/2016

### 6. Management Planner

Management Planner Name: Jigar Shah

Management Planner IDPH license # 100-07342

  
Signature:  
Date: 08/05/2016

### 7. Review Date: 08/05/2016

### 8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature: 

Date: 8/11/2016

Name: Robert Christlieb

## II. EXECUTIVE SUMMARY

GSG Consultants, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the LaSalle Academy. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 4420:

B                                      Tank Insulation

B. The following new homogenous areas have been identified for Building 4420:

- 38                    1x1 Ceiling Tile
- 39                    Vinyl Baseboard Brown



C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

04	12"x12" Brown w/ white and gray streaks VFT
06	Brown Hard Coat Plaster
12	12"x12" White w/ Beige Floor Tile
14	12" x 12" Ceiling Tiles w/Grooves
15	12" x 12" Light Brown Streaked Floor Tile
15A	12" x 12" Light Brown Streaked Floor Tile Mastic
16	12" x 12" Gray Streaked Floor Tile
16A	12" x 12" Gray Streaked Floor Tile Mastic
17	9" x 9" Green Streaked Floor Tile
17A	9" x 9" Green Streaked Floor Tile Mastic
18	12 x 12 VFT Lt. Blue Mixed Speckled
19	12 x 12 Mastic Lt. Blue Mixed Speckled
20	12 x 12 VFT Yellow Mixed Speckled
21	12 x 12 Mastic Yellow Mixed Speckled
22	12 X 12 VFT Dark Blue with Lt. Blue Specs
23	12 x 12 Mastic Dark Blue with Lt. Blue Specs
24	12 x 12 VFT Pink with Specs
25	12 x 12 Mastic Pink with Specs
26	12 x 12 VFT Dark Green Mixed Speckled
27	12 x 12 Mastic Dark Green Mixed Speckled
28	12 x 12 VFT Lt. Green Mixed Speckled
29	12 X 12 Mastic Lt. Green Mixed Speckled
30	12 x 12 VFT Dark Brown Mixed Speckled
31	12 x 12 Mastic Dark Brown Mixed Speckled
32	Drywall
33	Carpet Mastic
34	12 x 12 VFT Gray Mixed Speckled
35	12 x 12 Mastic Gray Mixec Speckled
36	12 x 12 VFT Cream with Brown Specs
37	12 X 12 Mastic Cream with Brown Specs
38	1x1 Ceiling Tile
39	Vinyl Baseboard Brown
G	Boiler Caulk
H	Boiler Gasket
I	Duct Dampening Cloth
J	12 x 12 Beige with Brown Specs Floor Tile
K	12 x 12 Beige with Brown Specs Floor Tile Mastic

The following areas were deemed to be inaccessible:

15A	12" x 12" Light Brown Streaked Floor Tile Mastic
16A	12" x 12" Gray Streaked Floor Tile Mastic
17A	9" x 9" Green Streaked Floor Tile Mastic

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Eric Moore, IDPH License # 100-11372. The Management Plan was updated by Jigar Shah, IDPH License # 100-07342. Inspector and Management Planner Licenses are included in Appendix B.

### **III. METHODOLOGY**

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

### **IV. ABATEMENT HISTORY**

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

### **V. REASSESSMENTS AND RECOMMENDATIONS**

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

### **VI. CONCLUSIONS**

The LaSalle Academy Building 4420 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

**Table I**  
**Inspector's Reinspection Findings**

---

# Chicago Public Schools

School LaSalle Academy Unit 29161 Building ID 4420

Address 1734 N. Orleans Street Region 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
02	9"x9" Brown Floor Tile	2,400	SF	Lunchroom, Rms 101,107,207 & 1st Fl Boy's Toilet. Landing by Boiler Room toilet, Maintenance Room	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
03	9"x9" Gray Floor Tile	1,500	SF	Office and Equipment Room, Engineer's office, Boiler room Stairway	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		HIGH
04	12"x12" Brown w/ white and gray streaks VFT	2,000	SF	Room 109, 110, & 1st Floor Northeast Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage	5	HIGH
06	Brown Hard Coat Plaster	28,000	SF	Throughout	ASSUMED	SURFACE	N	NONE	0		No	ACBM with the potential for damage	5	HIGH
09	9"x9" Brown Floor Tile Mastic	2,400	SF	Lunchroom, Rms 101,107,207,1st Fl Boy's Toilet, Landing by Boiler Room Toilet	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
10	9"x9" Gray Floor Tile Mastic	1,500	SF	Office and Equipment Room, Engineer's office, Boiler room Stairway	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		
11	12"x12" White Floor Tile Mastic W/ Gray specks	1,500	SF	Room 109, 110, & 1st Floor Northeast Corridor	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
12	12"x12" White w/ Beige Floor Tile	2,000	SF	Principal's Office, Main Office, Health Suite, Faculty Room, and Stage	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage	5	HIGH
13	12"x12" White w/ Beige Floor Tile Mastic	2,000	SF	Principal's Office, Main Office	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage	5	HIGH
14	12" x 12" Ceiling Tiles w/Grooves	21,000	SF	Throughout	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage	10	MODERATE
15	12" x 12" Light Brown Streaked Floor Tile	900	SF	Entrance to gym, hall by room 111 and 111A	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
15A	12" x 12" Light Brown Streaked Floor Tile Mastic	900	SF	Entrance to gym, hall by room 111 and 111A	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
16	12" x 12" Gray Streaked Floor Tile	2,700	SF	Room 111, 111A, Room doorway	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage	5	MODERATE

# Chicago Public Schools

School LaSalle Academy Unit 29161 Building ID 4420

Address 1734 N. Orleans Street Region 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				206A, elevator, rooms 215 and 112,200, 201, and 2nd fl. corridor										
16A	12" x 12" Gray Streaked Floor Tile Mastic	2,700	SF	Room 111, 111A, doorway 206A, elevator, 2nd fl. corridor and rooms 215, 112, and 200, 201	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
17	9" x 9" Green Streaked Floor Tile	4,000	SF	Rooms 206, 206A, 205, 204, 203, 209, 209A replacements	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
17A	9" x 9" Green Streaked Floor Tile Mastic	3,200	SF	Rooms 206, 206A, 205, 204, 203, 209, 209A replacements	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
18	12 x 12 VFT Lt. Blue Mixed Speckled	1,200	SF	2nd Floor Corridor and Lunch Room	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
19	12 x 12 Mastic Lt. Blue Mixed Speckled	1,200	SF	2nd Flr Corridor and LunchRoom	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
20	12 x 12 VFT Yellow Mixed Speckled	450	SF	LunchRoom	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
21	12 x 12 Mastic Yellow Mixed Speckled	450	SF	LunchRoom	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
22	12 X 12 VFT Dark Blue with Lt. Blue Specs	600	SF	Rm 200 & LunchRoom	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
23	12 x 12 Mastic Dark Blue with Lt. Blue Specs	600	SF	Rm 200 & Lunch Room	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
24	12 x 12 VFT Pink with Specs	200	SF	Rm. 201	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
25	12 x 12 Mastic Pink with Specs	200	SF	Rm. 201	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
26	12 x 12 VFT Dark Green Mixed Speckled	200	SF	LunchRoom	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
27	12 x 12 Mastic Dark Green Mixed Speckled	200	SF	LunchRoom	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
28	12 x 12 VFT Lt. Green Mixed Speckled	200	SF	LunchRoom	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
29	12 X 12 Mastic Lt. Green Mixed Speckled	200	SF	LunchRoom	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
30	12 x 12 VFT Dark Brown Mixed Speckled	700	SF	Rm 202 and 1st Floor Men & Womens Teacher's toilet	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW

# Chicago Public Schools

School LaSalle Academy Unit 29161 Building ID 4420

Address 1734 N. Orleans Street Region 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
31	12 x 12 Mastic Dark Brown Mixed Speckled	700	SF	Rm 202 and 1st Floor Men & Womens Teachers Toilet	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
32	Drywall	2,000	SF	1st and 2nd Floor Boys and Girls Bathroom	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
33	Carpet Mastic	700	SF	Room 208	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
34	12 x 12 VFT Gray Mixed Speckled	2,400	SF	Rm 107, 105, 103, 101, 210, 212, 213	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
35	12 x 12 Mastic Gray Mixec Speckled	2,400	SF	Rm 107, 105, 103, 101, 210, 212, 213	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
36	12 x 12 VFT Cream with Brown Specs	1,200	SF	Rm 102 and 100	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
37	12 X 12 Mastic Cream with Brown Specs	1,200	SF	Rm 102 and 100	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
38	1x1 Ceiling Tile	1,000	SF	Gymnasium Stage	ASSUMED	MISC	Y	LOC	20			Damaged or significantly damaged friable misc. ACBM		
39	Vinyl Baseboard Brown	3,500	SF	1st and 2nd Corridors, Rooms 206, 209, 210, 213	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
A	Breeching Insulation	3,250	SF	Boiler Room	CHR	TSI	Y	LOC	10		No	Damaged or significantly damaged friable thermal system insulating ACBM		LOW
B	Tank Insulation	250	SF	Boiler Room	CHR	TSI	Y	LOC	4		Yes	Damaged or significantly damaged friable thermal system insulating ACBM		LOW
C	Aircell Pipe Insulation	2,494	LF	Above Corridor Ceilings	CHR	TSI	Y	LOC	2		No	Damaged or significantly damaged friable thermal system insulating ACBM		LOW
D	MJP E/F/V on Aircell Pipe Insulation	856	LF	Above Corridor Ceilings	CHR	TSI	Y	LOC	5		No	Damaged or significantly damaged friable thermal system insulating ACBM		Low
E	Cardboard Pipe Insulation	1,800	LF	Throughout Building (See Hatching Maps)	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
F	MJP E/F/V on Cardboard Pipe Insulation	725	LF	Throughout Building (See	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW

# Chicago Public Schools

School LaSalle Academy Unit 29161 Building ID 4420

Address 1734 N. Orleans Street Region 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Hatching Maps)										
G	Boiler Caulk	40	LF	Boiler Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
H	Boiler Gasket	30	LF	Boiler Room	ASSUMED	TSI	Y	NONE	0		No	ACBM with the potential for damage	3	LOW
I	Duct Dampening Cloth	20	SF	Room 208	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage	3	MODERATE
J	12 x 12 Beige with Brown Specs Floor Tile	6,000	SF	1st Floor Hallway;2nd Floor Corridor	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
K	12 x 12 Beige with Brown Specs Floor Tile Mastic	6,000	SF	1st Floor Hallway, 2nd floor corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW



# Chicago Public Schools

School LaSalle Academy Unit 29161 Building ID 4420

Address 1734 N. Orleans Street Region 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

*Inspector's Comments are Summarized at the End of the Report*

Reinspection Date **7/29/2016**  
Inspector Name **Eric Moore**  
**100-11372** **12/8/2016**  
Inspector's IDPH License Number / Expiration Date

### Inspector's Comments

HA Number:	Inspector Comments:
02	
03	
04	
06	
09	
10	
11	
12	
13	
14	
15	
15A	
16	
16A	
17	
17A	
18	
19	
20	
21	
22	
23	
24	
25	

# Chicago Public Schools

School LaSalle Academy Unit 29161 Building ID 4420

Address 1734 N. Orleans Street Region 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
26	
27	
28	
29	
30	
31	
32	
33	
34	
35	
36	
37	
38	Missing tiles
39	
A	
B	
C	
D	
E	
F	
G	
H	
I	
J	
K	

# Chicago Public Schools

**School** LaSalle Academy **Unit** 29161 **Building ID** 4420

**Address** 1734 N. Orleans Street **Region** 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

*Inspector's Comments are Summarized at the End of the Report*

---

**Table II**

**Management Planner's Review**

---

# Chicago Public Schools

**School** LaSalle Academy  
**Address** 1734 N. Orleans Street

**Unit** 29161  
 Chicago, IL, 60614

**Building ID** 4420  
**Region** 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

### *Management Planner's Comments Summarized at the End of the Report*

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
02	9"x9" Brown Floor Tile	2,400	SF	Lunchroom, Rms 101,107,207 & 1st Fl Boy's Toilet. Landing by Boiler Room toilet, Maintenance Room	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
03	9"x9" Gray Floor Tile	1,500	SF	Office and Equipment Room, Engineer's office, Boiler room Stairway	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
04	12"x12" Brown w/ white and gray streaks VFT	2,000	SF	Room 109, 110, & 1st Floor Northeast Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
06	Brown Hard Coat Plaster	28,000	SF	Throughout	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
09	9"x9" Brown Floor Tile Mastic	2,400	SF	Lunchroom, Rms 101,107,207,1st Fl Boy's Toilet, Landing by Boiler Room Toilet	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
10	9"x9" Gray Floor Tile Mastic	1,500	SF	Office and Equipment Room, Engineer's office, Boiler room Stairway	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
11	12"x12" White Floor Tile Mastic W/ Gray specks	1,500	SF	Room 109, 110, & 1st Floor Northeast Corridor	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
12	12"x12" White w/ Beige Floor Tile	2,000	SF	Principal's Office, Main Office, Health Suite, Faculty Room, and Stage	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
13	12"x12" White w/ Beige Floor Tile Mastic	2,000	SF	Principal's Office, Main Office	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
14	12" x 12" Ceiling Tiles w/Grooves	21,000	SF	Throughout	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
15	12" x 12" Light Brown Streaked Floor Tile	900	SF	Entrance to gym, hall by room 111 and 111A	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
15A	12" x 12" Light Brown Streaked Floor Tile Mastic	900	SF	Entrance to gym, hall by room 111 and 111A	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
16	12" x 12" Gray Streaked Floor Tile	2,700	SF	Room 111, 111A, Room doorway 206A, elevator, rooms 215 and 112,200, 201, and 2nd fl. corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
16A	12" x 12" Gray Streaked Floor Tile Mastic	2,700	SF	Room 111, 111A, doorway 206A, elevator, 2nd fl. corridor and rooms 215, 112, and 200, 201	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
17	9" x 9" Green Streaked Floor Tile	4,000	SF	Rooms 206, 206A, 205, 204, 203, 209, 209A replacements	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
17A	9" x 9" Green Streaked Floor Tile Mastic	3,200	SF	Rooms 206, 206A, 205, 204, 203, 209, 209A replacements	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
18	12 x 12 VFT Lt. Blue Mixed Speckled	1,200	SF	2nd Floor Corridor and Lunch Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
19	12 x 12 Mastic Lt. Blue Mixed Speckled	1,200	SF	2nd Flr Corridor and LunchRoom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
20	12 x 12 VFT Yellow Mixed Speckled	450	SF	LunchRoom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** LaSalle Academy  
**Address** 1734 N. Orleans Street

**Unit** 29161  
Chicago, IL, 60614

**Building ID** 4420  
**Region** 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
21	12 x 12 Mastic Yellow Mixed Speckled	450	SF	LunchRoom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
22	12 X 12 VFT Dark Blue with Lt. Blue Specs	600	SF	Rm 200 & LunchRoom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
23	12 x 12 Mastic Dark Blue with Lt. Blue Specs	600	SF	Rm 200 & Lunch Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
24	12 x 12 VFT Pink with Specs	200	SF	Rm. 201	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
25	12 x 12 Mastic Pink with Specs	200	SF	Rm. 201	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
26	12 x 12 VFT Dark Green Mixed Speckled	200	SF	LunchRoom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
27	12 x 12 Mastic Dark Green Mixed Speckled	200	SF	LunchRoom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
28	12 x 12 VFT Lt. Green Mixed Speckled	200	SF	LunchRoom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
29	12 X 12 Mastic Lt. Green Mixed Speckled	200	SF	LunchRoom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
30	12 x 12 VFT Dark Brown Mixed Speckled	700	SF	Rm 202 and 1st Floor Men & Womens Teacher's toilet	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
31	12 x 12 Mastic Dark Brown Mixed Speckled	700	SF	Rm 202 and 1st Floor Men & Womens Teachers Toilet	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
32	Drywall	2,000	SF	1st and 2nd Floor Boys and Girls Bathroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
33	Carpet Mastic	700	SF	Room 208	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
34	12 x 12 VFT Gray Mixed Speckled	2,400	SF	Rm 107, 105, 103, 101, 210, 212, 213	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
35	12 x 12 Mastic Gray Mixec Speckled	2,400	SF	Rm 107, 105, 103, 101, 210, 212, 213	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
36	12 x 12 VFT Cream with Brown Specs	1,200	SF	Rm 102 and 100	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
37	12 X 12 Mastic Cream with Brown Specs	1,200	SF	Rm 102 and 100	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
38	1x1 Ceiling Tile	1,000	SF	Gymnasium Stage	Assumed	MISC	Yes	20	SF	4 Damaged or significantly damaged friable misc. ACBM	Remove
39	Vinyl Baseboard Brown	3,500	SF	1st and 2nd Corridors, Rooms 206, 209, 210, 213	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
A	Breeching Insulation	3,250	SF	Boiler Room	Chrysotile	TSI	Yes	10	SF	1 Damaged or significantly damaged friable thermal system insulating ACBM	Repair
B	Tank Insulation	250	SF	Boiler Room	Chrysotile	TSI	Yes	4	SF	1 Damaged or significantly damaged friable thermal system insulating ACBM	Repair
C	Aircell Pipe Insulation	2,494	LF	Above Corridor Ceilings	Chrysotile	TSI	Yes	2	LF	1 Damaged or significantly damaged friable thermal system insulating ACBM	Repair
D	MJP E/F/V on Aircell Pipe Insulation	856	LF	Above Corridor Ceilings	Chrysotile	TSI	Yes	5	LF	1 Damaged or significantly damaged friable thermal system insulating ACBM	Repair
E	Cardboard Pipe Insulation	1,800	LF	Throughout Building (See Hatching Maps)	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
F	MJP E/F/V on Cardboard Pipe Insulation	725	LF	Throughout Building (See Hatching Maps)	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** LaSalle Academy  
**Address** 1734 N. Orleans Street

**Unit** 29161  
 Chicago, IL, 60614

**Building ID** 4420  
**Region** 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

### *Management Planner's Comments Summarized at the End of the Report*

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
G	Boiler Caulk	40	LF	Boiler Room	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
H	Boiler Gasket	30	LF	Boiler Room	Assumed	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
I	Duct Dampening Cloth	20	SF	Room 208	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
J	12 x 12 Beige with Brown Specs Floor Tile	6,000	SF	1st Floor Hallway;2nd Floor Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
K	12 x 12 Beige with Brown Specs Floor Tile Mastic	6,000	SF	1st Floor Hallway, 2nd floor corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

HA Number	Management Comments
-----------	---------------------

# Chicago Public Schools

**School** LaSalle Academy  
**Address** 1734 N. Orleans Street

**Unit** 29161  
 Chicago, IL, 60614

**Building ID** 4420  
**Region** 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG Consultants, Inc.  
 855 W. Adams St., Ste. 200  
 Phone: (312) 733-6262

Fax: (312) 733-5612

### *Management Planner's Comments Summarized at the End of the Report*

Review Date	8/5/2016
Manager Planner Name	Jigar Shah
100-07342	1/19/2017
Manager IDPH License No/Expiration	

HA Number	Management Comments
02	
03	
04	
06	
09	
10	
11	
12	
13	
14	
15	
15A	
16	
16A	
17	
17A	
18	
19	
20	
21	
22	
23	
24	
25	
26	
27	
28	



# Chicago Public Schools

**School** LaSalle Academy  
**Address** 1734 N. Orleans Street

**Unit** 29161  
 Chicago, IL, 60614

**Building ID** 4420  
**Region** 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
29	
30	
31	
32	
33	
34	
35	
36	
37	
38	Remove Damaged ACM ASAP
39	
A	Repair Damaged ACM
B	Repair Damaged ACM
C	Repair Damaged ACM ASAP
D	Repair Damaged ACM ASAP
E	
F	
G	
H	
I	
J	
K	

# Chicago Public Schools

GSG Consultants, Inc.

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29161** BUIDLING ID: **4420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **LaSalle Academy** INSPECTION DATE: **7/29/2016**  
ADDRESS: **1734 N. Orleans Street** IDPH LICENSE NO: **100-11372**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **02**  
MATERIAL DESCRIPTION: **9"x9" Brown Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Lunchroom, Rms 101,107,207 & 1st FI Boy's Toilet. Landing by Boiler Room toilet, Maintenance Room**

MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 07/29/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29161** BUIDLING ID: **4420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **LaSalle Academy** REVIEW DATE: **8/5/2016**  
ADDRESS: **1734 N. Orleans Street** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **02**  
MATERIAL DESCRIPTION: **9"x9" Brown Floor Tile**  
MATERIAL LOCATION: **Lunchroom, Rms 101,107,207 & 1st FI Boy's Toilet. Landing by Boiler Room toilet, Mainteanance Room**  
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/05/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29161** BUIDLING ID: **4420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **LaSalle Academy** INSPECTION DATE: **7/29/2016**  
ADDRESS: **1734 N. Orleans Street** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **03**  
MATERIAL DESCRIPTION: **9"x9" Gray Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **HIGH**  
MATERIAL LOCATION: **Office and Equipment Room, Engineer's office, Boiler room Stairway**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 07/29/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29161** BUIDLING ID: **4420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **LaSalle Academy** REVIEW DATE: **8/5/2016**  
ADDRESS: **1734 N. Orleans Street** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **03**  
MATERIAL DESCRIPTION: **9"x9" Gray Floor Tile**  
MATERIAL LOCATION: **Office and Equipment Room, Engineer's office, Boiler room Stairway**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jigar Shah*

Date: **08/05/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29161** BUIDLING ID: **4420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **LaSalle Academy** INSPECTION DATE: **7/29/2016**  
ADDRESS: **1734 N. Orleans Street** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **04**  
MATERIAL DESCRIPTION: **12"x12" Brown w/ white and gray streaks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON: **Physical Damage**  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Physical Damage**  
DISTURBANCE POTENTIAL: **HIGH**  
MATERIAL LOCATION: **Room 109, 110, & 1st Floor Northeast Corridor**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY:  DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 07/29/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29161** BUIDLING ID: **4420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **LaSalle Academy** REVIEW DATE: **8/5/2016**  
ADDRESS: **1734 N. Orleans Street** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **04**  
MATERIAL DESCRIPTION: **12"x12" Brown w/ white and gray streaks VFT**  
MATERIAL LOCATION: **Room 109, 110, & 1st Floor Northeast Corridor**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/05/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29161** BUIDLING ID: **4420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **LaSalle Academy** INSPECTION DATE: **7/29/2016**  
ADDRESS: **1734 N. Orleans Street** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **06**  
MATERIAL DESCRIPTION: **Brown Hard Coat Plaster**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON: **Physical Damage**  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Physical Damage**  
DISTURBANCE POTENTIAL: **HIGH**  
MATERIAL LOCATION: **Throughout**  
MATERIAL QUANTITY: **28000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 07/29/2016



# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29161** BUIDLING ID: **4420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **LaSalle Academy** REVIEW DATE: **8/5/2016**  
ADDRESS: **1734 N. Orleans Street** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **06**  
MATERIAL DESCRIPTION: **Brown Hard Coat Plaster**  
MATERIAL LOCATION: **Throughout**  
MATERIAL QUANTITY: **28000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/05/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29161** BUIDLING ID: **4420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **LaSalle Academy** INSPECTION DATE: **7/29/2016**  
ADDRESS: **1734 N. Orleans Street** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **09**  
MATERIAL DESCRIPTION: **9"x9" Brown Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Lunchroom, Rms 101,107,207,1st FI Boy's Toilet, Landing by Boiler Room Toilet**  
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 07/29/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29161** BUIDLING ID: **4420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **LaSalle Academy** REVIEW DATE: **8/5/2016**  
ADDRESS: **1734 N. Orleans Street** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **09**  
MATERIAL DESCRIPTION: **9"x9" Brown Floor Tile Mastic**  
MATERIAL LOCATION: **Lunchroom, Rms 101,107,207,1st Fl Boy's Toilet, Landing by Boiler Room Toilet**  
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jigar Shah*

Date: **08/05/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29161** BUIDLING ID: **4420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **LaSalle Academy** INSPECTION DATE: **7/29/2016**  
ADDRESS: **1734 N. Orleans Street** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10**  
MATERIAL DESCRIPTION: **9"x9" Gray Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Office and Equipment Room, Engineer's office, Boiler room Stairway**

MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 07/29/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29161** BUIDLING ID: **4420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **LaSalle Academy** REVIEW DATE: **8/5/2016**  
ADDRESS: **1734 N. Orleans Street** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **10**  
MATERIAL DESCRIPTION: **9"x9" Gray Floor Tile Mastic**  
MATERIAL LOCATION: **Office and Equipment Room, Engineer's office, Boiler room Stairway**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/05/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29161** BUIDLING ID: **4420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **LaSalle Academy** INSPECTION DATE: **7/29/2016**  
ADDRESS: **1734 N. Orleans Street** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11**  
MATERIAL DESCRIPTION: **12"x12" White Floor Tile Mastic W/ Gray specks**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 109, 110, & 1st Floor Northeast Corridor**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 07/29/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29161** BUIDLING ID: **4420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **LaSalle Academy** REVIEW DATE: **8/5/2016**  
ADDRESS: **1734 N. Orleans Street** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **11**  
MATERIAL DESCRIPTION: **12"x12" White Floor Tile Mastic W/ Gray specks**  
MATERIAL LOCATION: **Room 109, 110, & 1st Floor Northeast Corridor**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jigar Shah*

Date: **08/05/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29161** BUIDLING ID: **4420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **LaSalle Academy** INSPECTION DATE: **7/29/2016**  
ADDRESS: **1734 N. Orleans Street** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12**  
MATERIAL DESCRIPTION: **12"x12" White w/ Beige Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON: **Physical Damage**  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Physical Damage**  
DISTURBANCE POTENTIAL: **HIGH**  
MATERIAL LOCATION: **Principal's Office, Main Office, Health Suite, Faculty Room, and Stage**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **2000** DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 07/29/2016



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29161** BUIDLING ID: **4420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **LaSalle Academy** REVIEW DATE: **8/5/2016**  
ADDRESS: **1734 N. Orleans Street** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **12**  
MATERIAL DESCRIPTION: **12"x12" White w/ Beige Floor Tile**  
MATERIAL LOCATION: **Principal's Office, Main Office, Health Suite, Faculty Room, and Stage**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **08/05/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29161** BUIDLING ID: **4420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **LaSalle Academy** INSPECTION DATE: **7/29/2016**  
ADDRESS: **1734 N. Orleans Street** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13**  
MATERIAL DESCRIPTION: **12"x12" White w/ Beige Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON: **Physical Damage**  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Physical Damage**  
DISTURBANCE POTENTIAL: **HIGH**  
MATERIAL LOCATION: **Principal's Office, Main Office**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **2000** DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **07/29/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29161** BUIDLING ID: **4420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **LaSalle Academy** REVIEW DATE: **8/5/2016**  
ADDRESS: **1734 N. Orleans Street** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **13**  
MATERIAL DESCRIPTION: **12"x12" White w/ Beige Floor Tile Mastic**  
MATERIAL LOCATION: **Principal's Office, Main Office**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jigar Shah*

Date: **08/05/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29161** BUIDLING ID: **4420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **LaSalle Academy** INSPECTION DATE: **7/29/2016**  
ADDRESS: **1734 N. Orleans Street** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14**  
MATERIAL DESCRIPTION: **12" x 12" Ceiling Tiles w/Grooves**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON: **Water  
Physical Damage**  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Water  
Physical Damage**  
DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Throughout**  
MATERIAL QUANTITY: **21000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 07/29/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29161** BUIDLING ID: **4420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **LaSalle Academy** REVIEW DATE: **8/5/2016**  
ADDRESS: **1734 N. Orleans Street** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **14**  
MATERIAL DESCRIPTION: **12" x 12" Ceiling Tiles w/Grooves**  
MATERIAL LOCATION: **Throughout**  
MATERIAL QUANTITY: **21000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jigar Shah*

Date: **08/05/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29161** BUIDLING ID: **4420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **LaSalle Academy** INSPECTION DATE: **7/29/2016**  
ADDRESS: **1734 N. Orleans Street** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15**  
MATERIAL DESCRIPTION: **12" x 12" Light Brown Streaked Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Enance to gym, hall by room 111 and 111A**  
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 07/29/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29161** BUIDLING ID: **4420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **LaSalle Academy** REVIEW DATE: **8/5/2016**  
ADDRESS: **1734 N. Orleans Street** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **15**  
MATERIAL DESCRIPTION: **12" x 12" Light Brown Streaked Floor Tile**  
MATERIAL LOCATION: **Enance to gym, hall by room 111 and 111A**  
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jigar Shah*

Date: **08/05/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29161** BUIDLING ID: **4420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **LaSalle Academy** INSPECTION DATE: **7/29/2016**  
ADDRESS: **1734 N. Orleans Street** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15A**  
MATERIAL DESCRIPTION: **12" x 12" Light Brown Streaked Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Entrance to gym, hall by room 111 and 111A**

MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 07/29/2016



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29161** BUIDLING ID: **4420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **LaSalle Academy** REVIEW DATE: **8/5/2016**  
ADDRESS: **1734 N. Orleans Street** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **15A**  
MATERIAL DESCRIPTION: **12" x 12" Light Brown Streaked Floor Tile Mastic**  
MATERIAL LOCATION: **Entrance to gym, hall by room 111 and 111A**  
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **08/05/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29161** BUIDLING ID: **4420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **LaSalle Academy** INSPECTION DATE: **7/29/2016**  
ADDRESS: **1734 N. Orleans Street** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16**  
MATERIAL DESCRIPTION: **12" x 12" Gray Streaked Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON: **Physical Damage**  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Physical Damage**  
DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Room 111, 111A, Room doorway 206A, elevator, rooms 215 and 112,200, 201, and 2nd fl. corridor**  
MATERIAL QUANTITY: **2700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 07/29/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29161** BUIDLING ID: **4420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **LaSalle Academy** REVIEW DATE: **8/5/2016**  
ADDRESS: **1734 N. Orleans Street** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **16**  
MATERIAL DESCRIPTION: **12" x 12" Gray Streaked Floor Tile**  
MATERIAL LOCATION: **Room 111, 111A, Room doorway 206A, elevator, rooms 215 and 112,200, 201, and 2nd fl. corridor**  
MATERIAL QUANTITY: **2700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **08/05/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29161** BUIDLING ID: **4420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **LaSalle Academy** INSPECTION DATE: **7/29/2016**  
ADDRESS: **1734 N. Orleans Street** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16A**  
MATERIAL DESCRIPTION: **12" x 12" Gray Streaked Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 111, 111A, doorway 206A, elevator, 2nd fl. corridor and rooms 215, 112, and 200, 201**

MATERIAL QUANTITY: **2700** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 07/29/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29161** BUIDLING ID: **4420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **LaSalle Academy** REVIEW DATE: **8/5/2016**  
ADDRESS: **1734 N. Orleans Street** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **16A**  
MATERIAL DESCRIPTION: **12" x 12" Gray Streaked Floor Tile Mastic**  
MATERIAL LOCATION: **Room 111, 111A, doorway 206A, elevator, 2nd fl. corridor and rooms 215, 112, and 200, 201**  
MATERIAL QUANTITY: **2700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/05/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29161** BUIDLING ID: **4420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **LaSalle Academy** INSPECTION DATE: **7/29/2016**  
ADDRESS: **1734 N. Orleans Street** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17**  
MATERIAL DESCRIPTION: **9" x 9" Green Streaked Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 206, 206A, 205, 204, 203, 209, 209A replacements**  
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 07/29/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29161** BUIDLING ID: **4420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **LaSalle Academy** REVIEW DATE: **8/5/2016**  
ADDRESS: **1734 N. Orleans Street** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **17**  
MATERIAL DESCRIPTION: **9" x 9" Green Streaked Floor Tile**  
MATERIAL LOCATION: **Rooms 206, 206A, 205, 204, 203, 209, 209A replacements**  
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jigar Shah*

Date: **08/05/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29161** BUIDLING ID: **4420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **LaSalle Academy** INSPECTION DATE: **7/29/2016**  
ADDRESS: **1734 N. Orleans Street** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17A**  
MATERIAL DESCRIPTION: **9" x 9" Green Streaked Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 206, 206A, 205, 204, 203, 209, 209A replacements**  
MATERIAL QUANTITY: **3200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 07/29/2016



# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29161** BUIDLING ID: **4420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **LaSalle Academy** REVIEW DATE: **8/5/2016**  
ADDRESS: **1734 N. Orleans Street** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **17A**  
MATERIAL DESCRIPTION: **9" x 9" Green Streaked Floor Tile Mastic**  
MATERIAL LOCATION: **Rooms 206, 206A, 205, 204, 203, 209, 209A replacements**  
MATERIAL QUANTITY: **3200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/05/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29161** BUIDLING ID: **4420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **LaSalle Academy** INSPECTION DATE: **7/29/2016**  
ADDRESS: **1734 N. Orleans Street** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18**  
MATERIAL DESCRIPTION: **12 x 12 VFT Lt. Blue Mixed Speckled**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **2nd Floor Corridor and Lunch Room**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 07/29/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29161** BUILDING ID: **4420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **LaSalle Academy** REVIEW DATE: **8/5/2016**  
ADDRESS: **1734 N. Orleans Street** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **18**  
MATERIAL DESCRIPTION: **12 x 12 VFT Lt. Blue Mixed Speckled**  
MATERIAL LOCATION: **2nd Floor Corridor and Lunch Room**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/05/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29161** BUIDLING ID: **4420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **LaSalle Academy** INSPECTION DATE: **7/29/2016**  
ADDRESS: **1734 N. Orleans Street** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19**  
MATERIAL DESCRIPTION: **12 x 12 Mastic Lt. Blue Mixed Speckled**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **2nd Flr Corridor and LunchRoom**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 07/29/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29161** BUIDLING ID: **4420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **LaSalle Academy** REVIEW DATE: **8/5/2016**  
ADDRESS: **1734 N. Orleans Street** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **19**  
MATERIAL DESCRIPTION: **12 x 12 Mastic Lt. Blue Mixed Speckled**  
MATERIAL LOCATION: **2nd Flr Corridor and LunchRoom**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jigar Shah*

Date: **08/05/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29161** BUIDLING ID: **4420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **LaSalle Academy** INSPECTION DATE: **7/29/2016**  
ADDRESS: **1734 N. Orleans Street** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**  
MATERIAL DESCRIPTION: **12 x 12 VFT Yellow Mixed Speckled**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **LunchRoom**  
MATERIAL QUANTITY: **450** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 07/29/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29161** BUIDLING ID: **4420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **LaSalle Academy** REVIEW DATE: **8/5/2016**  
ADDRESS: **1734 N. Orleans Street** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **20**  
MATERIAL DESCRIPTION: **12 x 12 VFT Yellow Mixed Speckled**  
MATERIAL LOCATION: **LunchRoom**  
MATERIAL QUANTITY: **450** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **08/05/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29161** BUIDLING ID: **4420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **LaSalle Academy** INSPECTION DATE: **7/29/2016**  
ADDRESS: **1734 N. Orleans Street** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21**  
MATERIAL DESCRIPTION: **12 x 12 Mastic Yellow Mixed Speckled**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **LunchRoom**  
MATERIAL QUANTITY: **450** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 07/29/2016



# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29161** BUIDLING ID: **4420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **LaSalle Academy** REVIEW DATE: **8/5/2016**  
ADDRESS: **1734 N. Orleans Street** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **21**  
MATERIAL DESCRIPTION: **12 x 12 Mastic Yellow Mixed Speckled**  
MATERIAL LOCATION: **LunchRoom**  
MATERIAL QUANTITY: **450** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **08/05/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29161** BUIDLING ID: **4420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **LaSalle Academy** INSPECTION DATE: **7/29/2016**  
ADDRESS: **1734 N. Orleans Street** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22**  
MATERIAL DESCRIPTION: **12 X 12 VFT Dark Blue with Lt. Blue Specs**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rm 200 & LunchRoom**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 07/29/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29161** BUIDLING ID: **4420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **LaSalle Academy** REVIEW DATE: **8/5/2016**  
ADDRESS: **1734 N. Orleans Street** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **22**  
MATERIAL DESCRIPTION: **12 X 12 VFT Dark Blue with Lt. Blue Specs**  
MATERIAL LOCATION: **Rm 200 & LunchRoom**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/05/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29161** BUIDLING ID: **4420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **LaSalle Academy** INSPECTION DATE: **7/29/2016**  
ADDRESS: **1734 N. Orleans Street** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23**  
MATERIAL DESCRIPTION: **12 x 12 Mastic Dark Blue with Lt. Blue Specs**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rm 200 & Lunch Room**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 07/29/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29161** BUIDLING ID: **4420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **LaSalle Academy** REVIEW DATE: **8/5/2016**  
ADDRESS: **1734 N. Orleans Street** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **23**  
MATERIAL DESCRIPTION: **12 x 12 Mastic Dark Blue with Lt. Blue Specs**  
MATERIAL LOCATION: **Rm 200 & Lunch Room**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/05/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29161** BUIDLING ID: **4420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **LaSalle Academy** INSPECTION DATE: **7/29/2016**  
ADDRESS: **1734 N. Orleans Street** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **24**  
MATERIAL DESCRIPTION: **12 x 12 VFT Pink with Specs**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rm. 201**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 07/29/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29161** BUIDLING ID: **4420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **LaSalle Academy** REVIEW DATE: **8/5/2016**  
ADDRESS: **1734 N. Orleans Street** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **24**  
MATERIAL DESCRIPTION: **12 x 12 VFT Pink with Specs**  
MATERIAL LOCATION: **Rm. 201**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jigar Shah*

Date: **08/05/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29161** BUIDLING ID: **4420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **LaSalle Academy** INSPECTION DATE: **7/29/2016**  
ADDRESS: **1734 N. Orleans Street** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25**  
MATERIAL DESCRIPTION: **12 x 12 Mastic Pink with Specs**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rm. 201**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 07/29/2016



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29161** BUIDLING ID: **4420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **LaSalle Academy** REVIEW DATE: **8/5/2016**  
ADDRESS: **1734 N. Orleans Street** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **25**  
MATERIAL DESCRIPTION: **12 x 12 Mastic Pink with Specs**  
MATERIAL LOCATION: **Rm. 201**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **08/05/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29161** BUIDLING ID: **4420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **LaSalle Academy** INSPECTION DATE: **7/29/2016**  
ADDRESS: **1734 N. Orleans Street** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26**  
MATERIAL DESCRIPTION: **12 x 12 VFT Dark Green Mixed Speckled**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **LunchRoom**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 07/29/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29161** BUIDLING ID: **4420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **LaSalle Academy** REVIEW DATE: **8/5/2016**  
ADDRESS: **1734 N. Orleans Street** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **26**  
MATERIAL DESCRIPTION: **12 x 12 VFT Dark Green Mixed Speckled**  
MATERIAL LOCATION: **LunchRoom**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/05/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29161** BUIDLING ID: **4420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **LaSalle Academy** INSPECTION DATE: **7/29/2016**  
ADDRESS: **1734 N. Orleans Street** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27**  
MATERIAL DESCRIPTION: **12 x 12 Mastic Dark Green Mixed Speckled**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **LunchRoom**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 07/29/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29161** BUIDLING ID: **4420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **LaSalle Academy** REVIEW DATE: **8/5/2016**  
ADDRESS: **1734 N. Orleans Street** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **27**  
MATERIAL DESCRIPTION: **12 x 12 Mastic Dark Green Mixed Speckled**  
MATERIAL LOCATION: **LunchRoom**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jigar Shah*

Date: **08/05/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29161** BUIDLING ID: **4420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **LaSalle Academy** INSPECTION DATE: **7/29/2016**  
ADDRESS: **1734 N. Orleans Street** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28**  
MATERIAL DESCRIPTION: **12 x 12 VFT Lt. Green Mixed Speckled**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **LunchRoom**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 07/29/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29161** BUIDLING ID: **4420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **LaSalle Academy** REVIEW DATE: **8/5/2016**  
ADDRESS: **1734 N. Orleans Street** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **28**  
MATERIAL DESCRIPTION: **12 x 12 VFT Lt. Green Mixed Speckled**  
MATERIAL LOCATION: **LunchRoom**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jigar Shah*

Date: **08/05/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29161** BUIDLING ID: **4420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **LaSalle Academy** INSPECTION DATE: **7/29/2016**  
ADDRESS: **1734 N. Orleans Street** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **29**  
MATERIAL DESCRIPTION: **12 X 12 Mastic Lt. Green Mixed Speckled**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **LunchRoom**

MATERIAL QUANTITY: **200**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 07/29/2016



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29161** BUIDLING ID: **4420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **LaSalle Academy** REVIEW DATE: **8/5/2016**  
ADDRESS: **1734 N. Orleans Street** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **29**  
MATERIAL DESCRIPTION: **12 X 12 Mastic Lt. Green Mixed Speckled**  
MATERIAL LOCATION: **LunchRoom**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jigar Shah*

Date: **08/05/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29161** BUIDLING ID: **4420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **LaSalle Academy** INSPECTION DATE: **7/29/2016**  
ADDRESS: **1734 N. Orleans Street** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **30**  
MATERIAL DESCRIPTION: **12 x 12 VFT Dark Brown Mixed Speckled**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rm 202 and 1st Floor Men & Womens Teacher's toilet**  
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 07/29/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29161** BUIDLING ID: **4420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **LaSalle Academy** REVIEW DATE: **8/5/2016**  
ADDRESS: **1734 N. Orleans Street** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **30**  
MATERIAL DESCRIPTION: **12 x 12 VFT Dark Brown Mixed Speckled**  
MATERIAL LOCATION: **Rm 202 and 1st Floor Men & Womens Teacher's toilet**  
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/05/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29161** BUIDLING ID: **4420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **LaSalle Academy** INSPECTION DATE: **7/29/2016**  
ADDRESS: **1734 N. Orleans Street** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **31**  
MATERIAL DESCRIPTION: **12 x 12 Mastic Dark Brown Mixed Speckled**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rm 202 and 1st Floor Men & Womens Teachers Toilet**  
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 07/29/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29161** BUIDLING ID: **4420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **LaSalle Academy** REVIEW DATE: **8/5/2016**  
ADDRESS: **1734 N. Orleans Street** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **31**  
MATERIAL DESCRIPTION: **12 x 12 Mastic Dark Brown Mixed Speckled**  
MATERIAL LOCATION: **Rm 202 and 1st Floor Men & Womens Teachers Toilet**  
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/05/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29161** BUIDLING ID: **4420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **LaSalle Academy** INSPECTION DATE: **7/29/2016**  
ADDRESS: **1734 N. Orleans Street** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **32**  
MATERIAL DESCRIPTION: **Drywall**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st and 2nd Floor Boys and Girls Bathroom**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 07/29/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29161** BUIDLING ID: **4420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **LaSalle Academy** REVIEW DATE: **8/5/2016**  
ADDRESS: **1734 N. Orleans Street** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **32**  
MATERIAL DESCRIPTION: **Drywall**  
MATERIAL LOCATION: **1st and 2nd Floor Boys and Girls Bathroom**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jigar Shah*

Date: **08/05/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29161** BUIDLING ID: **4420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **LaSalle Academy** INSPECTION DATE: **7/29/2016**  
ADDRESS: **1734 N. Orleans Street** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **33**  
MATERIAL DESCRIPTION: **Carpet Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 208**  
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 07/29/2016



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29161** BUIDLING ID: **4420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **LaSalle Academy** REVIEW DATE: **8/5/2016**  
ADDRESS: **1734 N. Orleans Street** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **33**  
MATERIAL DESCRIPTION: **Carpet Mastic**  
MATERIAL LOCATION: **Room 208**  
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **08/05/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29161** BUIDLING ID: **4420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **LaSalle Academy** INSPECTION DATE: **7/29/2016**  
ADDRESS: **1734 N. Orleans Street** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **34**  
MATERIAL DESCRIPTION: **12 x 12 VFT Gray Mixed Speckled**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rm 107, 105, 103, 101, 210, 212, 213**  
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 07/29/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29161** BUIDLING ID: **4420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **LaSalle Academy** REVIEW DATE: **8/5/2016**  
ADDRESS: **1734 N. Orleans Street** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **34**  
MATERIAL DESCRIPTION: **12 x 12 VFT Gray Mixed Speckled**  
MATERIAL LOCATION: **Rm 107, 105, 103, 101, 210, 212, 213**  
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **08/05/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29161** BUIDLING ID: **4420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **LaSalle Academy** INSPECTION DATE: **7/29/2016**  
ADDRESS: **1734 N. Orleans Street** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **35**  
MATERIAL DESCRIPTION: **12 x 12 Mastic Gray Mixec Speckled**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rm 107, 105, 103, 101, 210, 212, 213**  
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 07/29/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29161** BUIDLING ID: **4420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **LaSalle Academy** REVIEW DATE: **8/5/2016**  
ADDRESS: **1734 N. Orleans Street** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **35**  
MATERIAL DESCRIPTION: **12 x 12 Mastic Gray Mixec Speckled**  
MATERIAL LOCATION: **Rm 107, 105, 103, 101, 210, 212, 213**  
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jigar Shah*

Date: **08/05/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29161** BUIDLING ID: **4420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **LaSalle Academy** INSPECTION DATE: **7/29/2016**  
ADDRESS: **1734 N. Orleans Street** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **36**  
MATERIAL DESCRIPTION: **12 x 12 VFT Cream with Brown Specs**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rm 102 and 100**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 07/29/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29161** BUIDLING ID: **4420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **LaSalle Academy** REVIEW DATE: **8/5/2016**  
ADDRESS: **1734 N. Orleans Street** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **36**  
MATERIAL DESCRIPTION: **12 x 12 VFT Cream with Brown Specs**  
MATERIAL LOCATION: **Rm 102 and 100**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jigar Shah*

Date: **08/05/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29161** BUIDLING ID: **4420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **LaSalle Academy** INSPECTION DATE: **7/29/2016**  
ADDRESS: **1734 N. Orleans Street** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37**  
MATERIAL DESCRIPTION: **12 X 12 Mastic Cream with Brown Specs**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rm 102 and 100**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 07/29/2016



# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29161** BUILDING ID: **4420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **LaSalle Academy** REVIEW DATE: **8/5/2016**  
ADDRESS: **1734 N. Orleans Street** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **37**  
MATERIAL DESCRIPTION: **12 X 12 Mastic Cream with Brown Specs**  
MATERIAL LOCATION: **Rm 102 and 100**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jigar Shah*

Date: **08/05/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29161** BUIDLING ID: **4420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **LaSalle Academy** INSPECTION DATE: **7/29/2016**  
ADDRESS: **1734 N. Orleans Street** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **A**  
MATERIAL DESCRIPTION: **Breeching Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **1 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: **3250**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 07/29/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29161** BUIDLING ID: **4420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **LaSalle Academy** REVIEW DATE: **8/5/2016**  
ADDRESS: **1734 N. Orleans Street** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **A**  
MATERIAL DESCRIPTION: **Breeching Insulation**  
MATERIAL LOCATION: **Boiler Room**  
MATERIAL QUANTITY: **3250** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **10** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.


The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Repair Damaged ACM

Management Planner's Signature: \_\_\_\_\_



Date: **08/05/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29161** BUIDLING ID: **4420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **LaSalle Academy** INSPECTION DATE: **7/29/2016**  
ADDRESS: **1734 N. Orleans Street** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **B**  
MATERIAL DESCRIPTION: **Tank Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **1 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: **250**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 07/29/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29161** BUIDLING ID: **4420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **LaSalle Academy** REVIEW DATE: **8/5/2016**  
ADDRESS: **1734 N. Orleans Street** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **B**  
MATERIAL DESCRIPTION: **Tank Insulation**  
MATERIAL LOCATION: **Boiler Room**  
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **4** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Repair Damaged ACM

Management Planner's Signature:  Date: **08/05/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29161** BUIDLING ID: **4420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **LaSalle Academy** INSPECTION DATE: **7/29/2016**  
ADDRESS: **1734 N. Orleans Street** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **C**  
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **1 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Above Corridor Ceilings**

MATERIAL QUANTITY: **2494**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 07/29/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29161** BUIDLING ID: **4420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **LaSalle Academy** REVIEW DATE: **8/5/2016**  
ADDRESS: **1734 N. Orleans Street** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **C**  
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**  
MATERIAL LOCATION: **Above Corridor Ceilings**  
MATERIAL QUANTITY: **2494** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **2** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Repair Damaged ACM ASAP

Management Planner's Signature:  Date: **08/05/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29161** BUIDLING ID: **4420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **LaSalle Academy** INSPECTION DATE: **7/29/2016**  
ADDRESS: **1734 N. Orleans Street** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **D**  
MATERIAL DESCRIPTION: **MJP E/F/V on Aircell Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **1 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **Above Corridor Ceilings**

MATERIAL QUANTITY: **856**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 07/29/2016



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29161** BUIDLING ID: **4420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **LaSalle Academy** REVIEW DATE: **8/5/2016**  
ADDRESS: **1734 N. Orleans Street** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **D**  
MATERIAL DESCRIPTION: **MJP E/F/V on Aircell Pipe Insulation**  
MATERIAL LOCATION: **Above Corridor Ceilings**  
MATERIAL QUANTITY: **856** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **5** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Repair Damaged ACM ASAP

Management Planner's Signature: \_\_\_\_\_



Date: **08/05/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29161** BUIDLING ID: **4420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **LaSalle Academy** INSPECTION DATE: **7/29/2016**  
ADDRESS: **1734 N. Orleans Street** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **E**  
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout Building (See Hatching Maps)**  
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 07/29/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29161** BUILDING ID: **4420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **LaSalle Academy** REVIEW DATE: **8/5/2016**  
ADDRESS: **1734 N. Orleans Street** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **E**  
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**  
MATERIAL LOCATION: **Throughout Building (See Hatching Maps)**  
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jigar Shah*

Date: **08/05/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29161** BUIDLING ID: **4420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **LaSalle Academy** INSPECTION DATE: **7/29/2016**  
ADDRESS: **1734 N. Orleans Street** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **F**  
MATERIAL DESCRIPTION: **MJP E/F/V on Cardboard Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout Building (See Hatching Maps)**  
MATERIAL QUANTITY: **725** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 07/29/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29161** BUIDLING ID: **4420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **LaSalle Academy** REVIEW DATE: **8/5/2016**  
ADDRESS: **1734 N. Orleans Street** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **F**  
MATERIAL DESCRIPTION: **MJP E/F/V on Cardboard Pipe Insulation**  
MATERIAL LOCATION: **Throughout Building (See Hatching Maps)**  
MATERIAL QUANTITY: **725** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jigar Shah*

Date: **08/05/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29161** BUIDLING ID: **4420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **LaSalle Academy** INSPECTION DATE: **7/29/2016**  
ADDRESS: **1734 N. Orleans Street** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **G**  
MATERIAL DESCRIPTION: **Boiler Caulk**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Boiler Room**  
MATERIAL QUANTITY: **40** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 07/29/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29161** BUIDLING ID: **4420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **LaSalle Academy** REVIEW DATE: **8/5/2016**  
ADDRESS: **1734 N. Orleans Street** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **G**  
MATERIAL DESCRIPTION: **Boiler Caulk**  
MATERIAL LOCATION: **Boiler Room**  
MATERIAL QUANTITY: **40** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jigar Shah*

Date: **08/05/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29161** BUIDLING ID: **4420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **LaSalle Academy** INSPECTION DATE: **7/29/2016**  
ADDRESS: **1734 N. Orleans Street** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **H**  
MATERIAL DESCRIPTION: **Boiler Gasket**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON: **Deterioration**  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Deterioration**  
DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Boiler Room**  
MATERIAL QUANTITY: **30** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **30** DAMAGE UNITS: **LF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **07/29/2016**



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29161** BUIDLING ID: **4420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **LaSalle Academy** REVIEW DATE: **8/5/2016**  
ADDRESS: **1734 N. Orleans Street** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **H**  
MATERIAL DESCRIPTION: **Boiler Gasket**  
MATERIAL LOCATION: **Boiler Room**  
MATERIAL QUANTITY: **30** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **08/05/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29161** BUIDLING ID: **4420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **LaSalle Academy** INSPECTION DATE: **7/29/2016**  
ADDRESS: **1734 N. Orleans Street** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **I**  
MATERIAL DESCRIPTION: **Duct Dampening Cloth**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON: **Deterioration**  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Deterioration**  
DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Room 208**  
MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY:  DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **07/29/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29161** BUIDLING ID: **4420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **LaSalle Academy** REVIEW DATE: **8/5/2016**  
ADDRESS: **1734 N. Orleans Street** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **I**  
MATERIAL DESCRIPTION: **Duct Dampening Cloth**  
MATERIAL LOCATION: **Room 208**  
MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **08/05/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29161** BUIDLING ID: **4420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **LaSalle Academy** INSPECTION DATE: **7/29/2016**  
ADDRESS: **1734 N. Orleans Street** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **J**  
MATERIAL DESCRIPTION: **12 x 12 Beige with Brown Specs Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st Floor Hallway;2nd Floor Corridor**  
MATERIAL QUANTITY: **6000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 07/29/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29161** BUIDLING ID: **4420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **LaSalle Academy** REVIEW DATE: **8/5/2016**  
ADDRESS: **1734 N. Orleans Street** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **J**  
MATERIAL DESCRIPTION: **12 x 12 Beige with Brown Specs Floor Tile**  
MATERIAL LOCATION: **1st Floor Hallway;2nd Floor Corridor**  
MATERIAL QUANTITY: **6000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jigar Shah*

Date: **08/05/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29161** BUIDLING ID: **4420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **LaSalle Academy** INSPECTION DATE: **7/29/2016**  
ADDRESS: **1734 N. Orleans Street** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **K**  
MATERIAL DESCRIPTION: **12 x 12 Beige with Brown Specs Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st Floor Hallway, 2nd floor corridor**  
MATERIAL QUANTITY: **6000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 07/29/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29161** BUIDLING ID: **4420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **LaSalle Academy** REVIEW DATE: **8/5/2016**  
ADDRESS: **1734 N. Orleans Street** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **K**  
MATERIAL DESCRIPTION: **12 x 12 Beige with Brown Specs Floor Tile Mastic**  
MATERIAL LOCATION: **1st Floor Hallway, 2nd floor corridor**  
MATERIAL QUANTITY: **6000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **08/05/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **29161**    BUILDING ID: **4420**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **LaSalle Academy**    INSPECTION DATE: **7/29/2016**  
ADDRESS: **1734 N. Orleans Street**    IDPH LICENSE NO: **100-11372**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **39**  
MATERIAL DESCRIPTION: **Vinyl Baseboard Brown**  
MATERIAL LOCATION: **1st and 2nd Corridors, Rooms 206, 209, 210, 213**  
MATERIAL QUANTITY: **3500**    MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**    FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**    CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**    DAMAGE REASON:  
DAMAGE QUANTITY: **0**    DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **07/29/2016**



# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **29161**      BUILDING ID: **4420**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **LaSalle Academy**      REVIEW DATE: **8/5/2016**  
ADDRESS: **1734 N. Orleans Street**      IDPH LICENSE NO: **100-11372**

HOMOGENEOUS AREA: **39**  
MATERIAL DESCRIPTION: **Vinyl Baseboard Brown**  
MATERIAL LOCATION: **1st and 2nd Corridors, Rooms 206, 209, 210, 213**  
MATERIAL QUANTITY: **3500**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:       Date: **08/05/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **29161**    BUILDING ID: **4420**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **LaSalle Academy**    INSPECTION DATE: **7/29/2016**  
ADDRESS: **1734 N. Orleans Street**    IDPH LICENSE NO: **100-11372**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **38**  
MATERIAL DESCRIPTION: **1x1 Ceiling Tile**  
MATERIAL LOCATION: **Gymnasium Stage**  
MATERIAL QUANTITY: **1000**    MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**    FRIABLE: **Yes**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL:    CONDITION:  
AHERA DAMAGE CATEGORY: **4 Damaged or significantly damaged friable misc. ACBM**  
ACCESSIBILITY: **Within Reach**    DAMAGE REASON:  
DAMAGE QUANTITY: **20**    DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:  
Missing tiles

Inspector's Signature: \_\_\_\_\_ Date: 07/29/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29161** BUILDING ID: **4420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **LaSalle Academy** REVIEW DATE: **8/5/2016**  
ADDRESS: **1734 N. Orleans Street** IDPH LICENSE NO: **100-11372**

HOMOGENEOUS AREA: **38**  
MATERIAL DESCRIPTION: **1x1 Ceiling Tile**  
MATERIAL LOCATION: **Gymnasium Stage**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **20** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:  
Remove Damaged ACM ASAP

Management Planner's Signature: \_\_\_\_\_

*Jigar Shah*

Date: **08/05/2016**

# APPENDIX B

## Inspector and Management Planner Licenses

---

2015



**OCCUPATIONAL TRAINING & SUPPLY, INC.**

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900

# Asbestos Abatement Supervisor Refresher

Occupational Training & Supply, Inc. certifies that

**Eric Moore**

has successfully completed the Asbestos Abatement Supervisor Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Course Date: 11/30/2015

Exam Date: 11/30/2015

Expiration Date: 11/30/2016

Certificate Number: ASR1511304117

  
Kathy DeSalvo, Director



525-525 West Jefferson Street • Springfield, Illinois 62761-0001 • www.idph.illinois.gov

4/18/2016

**ERIC D MOORE**  
 855 W Adams Street, Suite 200  
 Chicago, IL 60607



ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 11372

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

**COPY OF THE ASBESTOS PROFESSIONAL LICENSE**

Front of License

Back of License


Front of License			Back of License	
 <p><b>ASBESTOS PROFESSIONAL LICENSE</b></p>			<p><b>ENDORSEMENTS</b></p>	
<p><b>ID NUMBER</b> 100 - 11372</p>	<p><b>ISSUED</b> 4/18/2016</p>	<p><b>EXPIRES</b> 05/15/2017</p>	<p>INSPECTOR</p>	<p><b>TC EXPIRES</b> 12/8/2016</p>
<p><b>ERIC D MOORE</b> 855 W Adams Street, Suite 200 Chicago, IL 60607 Environmental Health</p>			<p>PROJECT MANAGER AIR SAMPLING PROFESSIONAL</p>	<p>11/30/2016</p>
			<p><b>Alteration of this license shall result in legal action</b>            This license issued under authority of the State of Illinois            Department of Public Health            This license is valid only when accompanied by a valid            training course certificate.</p>	

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: [dph.illinois.gov/topics-services/environmental-health-protection/asbestos](http://dph.illinois.gov/topics-services/environmental-health-protection/asbestos)  
 EMAIL Address: [dph.asbestos@illinois.gov](mailto:dph.asbestos@illinois.gov)

**PROTECTING HEALTH, IMPROVING LIVES**  
*Nationally Accredited by PHAB*

2016



**OCCUPATIONAL TRAINING & SUPPLY, INC.**

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900

# Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

**Jigar Shah**

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 1/27/2016

Exam Date: 1/27/2016

Expiration Date: 1/27/2017

Certificate Number: MPR1601270320

  
Kathy DeSalvo, Director



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • www.dph.illinois.gov

4/20/2016

**JIGAR M SHAH**  
855 W ADAMS ST, SUITE 200  
CHICAGO, IL 60607

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 07342

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

**COPY OF THE ASBESTOS PROFESSIONAL LICENSE**

Front of License

Back of License

		<b>ASBESTOS PROFESSIONAL LICENSE</b>		<b>ENDORSEMENTS</b>	<b>TC EXPIRES</b>
<b>ID NUMBER</b> 109 - 07342	<b>ISSUED</b> 4/20/2016	<b>EXPIRES</b> 05/15/2017		INSPECTOR PROJECT DESIGNER MANAGEMENT PLANNER PROJECT MANAGER AIR SAMPLING PROFESSIONAL	1/19/2017 2/2/2017 1/27/2017 2/26/2017
<b>JIGAR M SHAH</b> 855 W ADAMS ST, SUITE 200 CHICAGO, IL 60607 Environmental Health				<b>Alteration of this license shall result in legal action</b> This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: [dph.illinois.gov/topics-services/environmental-health-protection/asbestos](http://dph.illinois.gov/topics-services/environmental-health-protection/asbestos)  
EMAIL Address: [dph.asbestos@illinois.gov](mailto:dph.asbestos@illinois.gov)

**PROTECTING HEALTH, IMPROVING LIVES**  
*Nationally Accredited by PHAB*



# APPENDIX C

## Laboratory Accreditations

---

# APPENDIX D

## Laboratory Results

---

# APPENDIX E

## Chain of Custody Forms

---

## Three-Year Reinspection Key to Terms

	<b>CODE</b>	<b>KEY</b>
<b>MATERIAL</b>		
	ACBM	Asbestos Containing Building Materials
<b>MATERIAL CATEGORY</b>		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
<b>MATERIAL UNITS</b>		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
<b>DAMAGE TYPE</b>		
	Loc	Localized
	Dist	Distributed