

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM**

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-3522
SCHOOL NAME: Sumner Academy
ADDRESS OF SCHOOL: 4320 W. Fifth
CITY: Chicago, IL, 60624

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **3/27/2013**

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II (Please type or print)

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 5/2/2016 ENROLLMENT 262
IDPH INSPECTOR LICENSE NUMBER: 100-08864
IDPH LICENSED INSPECTOR NAME (Please Print): Robert DeBord
IDPH MP LICENSE NUMBER: 100-09870
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Todd Huffer

DESIGNATED PERSON (Please Print): Robert Christlieb PHONE: (773) 553-3197



5/2/2016

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Sumner Academy

4320 W. Fifth
Chicago, IL, 60624

Unit: 31221
Building ID: 6110

IDPH ID Number: 14-016-2990-3522

REPORT DATE:

Monday, May 02, 2016

Prepared for:

Chicago Public Schools
125 S. Clark Street
Chicago, IL 60603

Prepared by:

Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone (312) 762-2900

Fax (312) 782-5145

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

February 24, 2016

Mr. R. Kent Cook
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2016 Three-Year Reinspections

Dear Mr. Cook:

Carnow, Conibear and Associates, Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 3,4,5 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 31221 Region: 03 IDPH ID: 14-016-2990-3522

School: Sumner Academy Building ID: 6110

Address: 4320 W. Fifth

Chicago, IL, 60624

Building Contact: Cintron, Raymond

Contact Phone: 773-787-3425

Current Building Owners: Chicago Public Schools

Review Date: 05/02/2016

Inspector: Robert DeBord

Inspector IDPH License: 100-08864

Management Planner: Todd Huffer

Management Planner IDPH License: 100-09870

If you have any questions or comments, please contact us at (312) 762-2900

Sincerely,
Carnow, Conibear and Associates



Todd Huffer
100-09870

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: February 24, 2016

RE: Sumner Academy, Unit 31221
4320 W. Fifth
Chicago, IL, 60624

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2016 asbestos three year re-inspection has been completed at Sumner Academy , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at Sumner Academy, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Robert Christlieb, the designated Local Education Authority's Designated Person at (773) 553-3197 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Sumner Academy
Address: 4320 W. Fifth
IDPH ID: 14-016-2990-3522
Contact: Cintron, Raymond

Unit: 31221
Chicago, IL, 60624
Building ID: 6110
Phone: 773-787-3425

Region: 03

2. Description of Facility

Original Construction: 1968
Total Square Footage:
Current Occupancy: 262

Additional Construction: 1948,1948
No of Floors:

3. LEA Designated Person

Contact: Robert Christlieb
Address: 125 South Clark Street, 17th Floor
Chicago, IL 60603

Phone: (773) 553-3197

4. Managing Environmental Consultant

MEC: Carnow, Conibear and Associates
Contact: Dan Juneau
Address 600 West Van Buren St., Ste 500
Phone: (312) 762-2900

Fax: (312) 782-5145

5. Inspector

Inspector Name: Robert DeBord

Inspector IDPH license # 100-08864

Signature:
Date: 2/24/2016

6. Management Planner

Management Planner Name: Todd Huffer

Management Planner IDPH license # 100-09870

Signature:
Date: 05/02/2016

7. Review Date: 05/02/2016

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature: 

Date: 5/2/2016

Name: Robert Christlieb

II. EXECUTIVE SUMMARY

Carnow, Conibear and Associates was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Sumner Academy. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 6110:

013.2	2'x4' Acoustical Ceiling Tile
73	12' x 12' Beige w/ White specs Floor Tiles
74	12' x 12' Red w/ white specs Floor Tiles
75	12' x 12' Floor Tile Mastic

B. The following new homogenous areas have been identified for Building 6110:

- | | |
|----|--|
| 73 | 12' x 12' Beige w/ White specs Floor Tiles |
| 74 | 12' x 12' Red w/ white specs Floor Tiles |
| 75 | 12' x 12' Floor Tile Mastic |

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

013.2	2'x4' Acoustical Ceiling Tile
023.1	12x12 Lt. Gray w/Brn and White Streaks Floor Tile
023.3	12"x12" Brown Floor Tile w/Dk Brwn & White Streaks
023.5	12" x 12" Cream Flecks w/ Tan Specks Floor Tile
024.2	Mastic Assoc. w/ 12"x12" Tan Flecks Floor Tile
026.2	Light Brown Vinyl Baseboard Adhesive
027.1	12x12 VFT, Tan Flecks w/Brown and White Specks
028.1	12x12 VFT, Beige Flecks w/Brown and White Specks
030.1	12x12 VFT, Brown w/Dk. Brown and White Streaks
031.1	12x12 VFT, Beige w/Brown and White Streaks
031.1M	Mastic Assoc. w/ 12"x12" Beige w/ Brn & Wh VFT
032.1	12x12 VFT, Lt. Beige w/Brown and White Streaks
032.1M	Mastic Assoc. w/ 12"x12" Lt Beige w/Brn & Wh VFT
033.1	12x12 VFT, Beige Flecks w/Brown and White Specks
033.2	12x12 VFT, Beige w/Brown and White Streaks
034.1	Black Vinyl Molding
036.1	12x12 VFT, Beige w/Blue, Gray, and Rust Streaks
037.1	12x12 VFT, Cream Flecks w/Tan Specks
044.2	12x12 VFT, Beige w/Blue, Pink, Gray, & Brown
044.2M	Mastic Assoc. w/12"x12" VFT, Beige, Blue, Pink...
045.2	12x12 VFT, Tan w/Blue, Gray, Brown, Orange & Beige
045.2M	12"x12" Tan, Bl, Gray,Brn, Or & Gray VFT Mastic
047.1	Boiler Brick
048.1	Boiler Brick Mortar
049.2	Fire Doors
050.1	Roof (NOT AHERA)
050.2	Roof (NOT AHERA)
051.1	Roof Flashing (NOT AHERA)
051.2	Roof Flashing (NOT AHERA)
053.2	Door Caulk (NOT AHERA)
054.1	Window Caulk (NOT AHERA)
054.2	Window Caulk (NOT AHERA)
58	12" x 12" Tan with black and white floor tile
59	Mastic for 12" x 12" Tan with black and white floor tile
60	12" x 12" Tan with blue and red floor tile
61	Mastic for 12" x 12" tan with blue and red floor tile

62	12" x 12" Lt gray with white and black floor tile
63	Mastic for 12" x 12" Light gray with white and black floor tile
64	Black Chalk board Adhesive
65	Green Chalk Board Adhesive
66	12" x 12" Tan floor tile
67	Mastic for 12" x 12" Tan floor tile
68	12" x 12" Blue/Green /Purple floor tile
69	Mastic for 12" x 12" Blue/Gree/Purple floor tile
70	12" x 12" Red floor tile
71	Mastic for 12" x 12" Red flor tile
72	Green Terrazzo
73	12' x 12' Beige w/ White specs Floor Tiles
74	12' x 12' Red w/ white specs Floor Tiles
75	12' x 12' Floor Tile Mastic
K.2	Joint Insulation on Fiberglass Insulated Piping

The following areas were deemed to be inaccessible:

024.3	12"x12: Brown w/Dark Brown Floor Tile Mastic
024.4	Mastic Assoc. w/12"x12" Cream Flks w/Tan Spks VFT
024.5	12"x12" Beige w/White & Brown Floor Tile Mastic
049.2	Fire Doors
59	Mastic for 12" x 12" Tan with black and white floor tile
61	Mastic for 12" x 12" tan with blue and red floor tile
63	Mastic for 12" x 12" Light gray with white and black floor tile
64	Black Chalk board Adhesive
65	Green Chalk Board Adhesive
67	Mastic for 12" x 12" Tan floor tile
69	Mastic for 12" x 12" Blue/Gree/Purple floor tile
71	Mastic for 12" x 12" Red flor tile
75	12' x 12' Floor Tile Mastic

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Robert DeBord, IDPH License # 100-08864. The Management Plan was updated by Todd Huffer, IDPH License # 100-09870. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Sumner Academy Building 6110 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Sumner Academy Unit 31221 Building ID 6110

Address 4320 W. Fifth Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
054.1	Window Caulk (NOT AHERA)			Exterior, 1890 Building	ASSUMED									
054.2	Window Caulk (NOT AHERA)			Exterior, 1912 Building	ASSUMED									
055.1	Blue Mixed Carpet Mastic			Room 235, 1890 Building	NO_ACBM									
055.2	Blue Mixed Carpet Mastic			Room 024	NO_ACBM									
056.1	Pink Mixed Carpet Mastic			Room 235 Closet, 1890 Building	NO_ACBM									
056.2	Pink Mixed Carpet Mastic			Rooms 020, 125, Teacher's Lounge 1912 Building	NO_ACBM									
057.1	Brown Mixed Carpet Mastic			Main Office, 1890 Building	NO_ACBM									
58	12" x 12" Tan with black and white floor tile	325	SF	Rooms 122, Teacher's Lounge - 1912 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
59	Mastic for 12" x 12" Tan with black and white floor tile	325	SF	Rooms 122, Teachers Lounge	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
60	12" x 12" Tan with blue and red floor tile	250	SF	1912 Building Rooms 124, 221 and 1890 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
61	Mastic for 12" x 12" tan with blue and red floor tile	250	SF	1912 Building Rooms Room 124, and 221 and 1890 Building room 332	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
62	12" x 12" Lt gray with white and black floor tile	1,750	SF	1890 Building Rooms 231, 335	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
63	Mastic for 12" x 12" Light gray with white and black floor tile	1,750	SF	1890 Building Rooms 231, 335	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
64	Black Chalk board Adhesive	4,000	SF	1890 and 1912 Building classrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
65	Green Chalk Board Adhesive	4,000	SF	1966 Building Classrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
66	12" x 12" Tan floor tile	10,000	SF	1966 Building Lunch Room 101 (offices), 102, faculty washroom, 103-107, 109-111, 114-116, PC Lab, 1st floor hallway	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
67	Mastic for 12" x 12" Tan floor tile	10,000	SF	1966 Building Lunch Room 101 (offices), 102,	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Sumner Academy Unit 31221 Building ID 6110

Address 4320 W. Fifth Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

Reinspection Date 2/24/2016
Inspector Name Robert DeBord
100-08864 5/15/2016
Inspector's IDPH License Number / Expiration Date

Inspector's Comments

HA Number:	Inspector Comments:
001.1	
001.2	
002.1	
002A.1	
013.1	
013.2	
016.1	
016.2	
017.1	
017.2	
018.1	
018.2	
019.1	
019.2	
020.1	
020.2	
021.1	
021.2	
022.1	
022.2	
023.1	Not Observed 2016
023.3	
023.4	
023.5	

Chicago Public Schools

School Sumner Academy Unit 31221 Building ID 6110

Address 4320 W. Fifth Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
024.1	Not Observed 2016
024.2	
024.3	
024.4	
024.5	
025.1	
025.2	
026.1	
026.2	
027.1	
027.1M	
027.2	
027.2M	
028.1	
028.1M	
028.2	Not Observed 2016
028.2M	Not Observed 2016
029.1	
029.2	
030.1	Room 137 Is listed as separate
031.1	Not Observed 2016
031.1M	Not Observed 2016
032.1	
032.1M	Not Observed 2016-may be under wooden floor
033.1	Not Observed 2016
033.1M	Not Observed 2016
033.2	Not Observed 2016
034.1	
034.2	

Chicago Public Schools

School Sumner Academy Unit 31221 Building ID 6110

Address 4320 W. Fifth Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
035.1	
035.2	
036.1	
036.1M	
037.1	
038.1	
038A.1	
039.1	
039.2	
040.1	
040.2	
042.2	
043.2	
044.2	Not Observed 2016
044.2M	Not Observed 2016
045.2	Not Observed 2016 - Room 321 Not Found
045.2M	Not Observed 2016 - Room 321 not found
046.2	
047.1	
048.1	
049.2	
050.1	
050.2	
051.1	
051.2	
053.1	
053.2	
054.1	
054.2	

Chicago Public Schools

School Sumner Academy Unit 31221 Building ID 6110

Address 4320 W. Fifth Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
055.1	
055.2	
056.1	
056.2	
057.1	
58	Not Observed in Room 122
59	Not Observed in Room 122
60	Not Observed in Room 124
61	Not Observed in Room 124 or Room 332
62	
63	
64	
65	
66	In Annex Report
67	In Annex Report
68	In Annex Report
69	In Annex Report
70	In Annex Report
71	In Annex Report
72	In Annex Report
73	
74	
75	
A.1	
B.1	
C.1	
C.2	
D.1	
I.1	

Chicago Public Schools

School Sumner Academy Unit 31221 Building ID 6110

Address 4320 W. Fifth Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
J.2	
K.1	
K.2	Not Observed 2016

Table II

Management Planner's Review

Chicago Public Schools

School Sumner Academy
Address 4320 W. Fifth

Unit 31221
 Chicago, IL, 60624

Building ID 6110
Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
001.1	Wall/Ceiling Plaster			Throughout the 1890 building	No ACBM						
001.2	Wall/Ceiling Plaster			Throughout the 1912 building	No ACBM						
002.1	1x1 Ceiling Tile			Lunch Room, 1890 Building	No ACBM						
002A.1	1x1 Acoustic Ceiling Tile			Lunch Room, 1890 Building	No ACBM						
013.1	2x4 Acoustic Ceiling Tiles			Room 334, 1890 Building	No ACBM						
013.2	2'x4' Acoustical Ceiling Tile	750	SF	Room 335, 1912 Building	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
016.1	Window Caulk, Green			Teacher's Lounge, Room 131, 1890 Building	No ACBM						
016.2	Window Caulk			Throughout Interior, 1912 Building	No ACBM						
017.1	Masonry Brick			Tank Room, Boiler Room, 1912 Building	No ACBM						
017.2	Masonry Brick Mortar			Engine Room, 1912 Building	No ACBM						
018.1	Masonry Mortar			Tank Room, Boiler Room, 1890 Building	No ACBM						
018.2	Masonry Brick Wall			Engine Room, 1912 Building	No ACBM						
019.1	Wood Wall Board			Basement Stairwell, 1890 Building	No ACBM						
019.2	Wood Wall Board			Room 124, 1912 Building	No ACBM						
020.1	Cinder Block			Tank Room, Boiler Room, 1890 Building	No ACBM						
020.2	Cinder Block			Store Room Across From Assembly Hall, 1912 Building	No ACBM						
021.1	Cinder Block Mortar			Tank Room, Boiler Room, 1890 Building	No ACBM						
021.2	Cinder Block Mortar			Storeroom Across From Assembly Hall, 1912 Building	No ACBM						
022.1	Drywall			Teacher's Lounge, 1st Floor Slop Sink, 1890 Building	No ACBM						
022.2	Drywall			Room 120 and 223, 1912 Building	No ACBM						
023.1	12x12 Lt. Gray w/Brn and White Streaks Floor Tile			Lunch Room, 1890 Building	Assumed	MISC					
023.3	12"x12" Brown Floor Tile w/Dk Brwn & White Streaks	800	SF	Room 137, 1890 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
023.4	12"x12" Beige w/White & Brown Floor Tile	15,000	SF	1st, 2nd & 3rd Floor Corridors, 1912 Building	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
023.5	12"x 12" Cream Flecks w/ Tan Specks Floor Tile	200	SF	Engineers Office, 1890 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
024.1	12"x12" Lt. Gray w/Brown & Wh Floor Tile Mastic			Lunch Room, 1890 Building	No ACBM						

Chicago Public Schools

School Sumner Academy

Unit 31221

Building ID 6110

Address 4320 W. Fifth

Chicago, IL, 60624

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
024.2	Mastic Assoc. w/ 12"x12" Tan Flecks Floor Tile	700	SF	Room 221, 1912 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
024.3	12"x12: Brown w/Dark Brown Floor Tile Mastic	800	SF	Room 137, 1890 Building	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
024.4	Mastic Assoc. w/12"x12" Cream Flks w/Tan Spks VFT	200	SF	Engineer's Office, 1890 Building	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
024.5	12"x12" Beige w/White & Brown Floor Tile Mastic	15,000	SF	1st, 2nd & 3rd Floor Corridors, 1912 Building, 024	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
025.1	Brown Vinyl Baseboard			Lunch Room, 1890 Building	No ACBM	MISC					
025.2	Light Brown Vinyl Baseboard			Teacher's Lounge	No ACBM						
026.1	Brown Vinyl Baseboard Adhesive			Lunch Room, 1890 Building	No ACBM						
026.2	Light Brown Vinyl Baseboard Adhesive	80	LF	Teacher's Lounge	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
027.1	12x12 VFT, Tan Flecks w/Brown and White Specks	1,576	SF	Lunchroom kitchen, 1890 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
027.1M	Mastic Assoc. w/ 12"x12" Tan Flks w/Brn & Wh VFT			Lunchroom, Kitchen, 1890 Building	No ACBM						
027.2	Mastic Assoc. w/12"x12" Tan Flecks w/Brn & Wh VFT			Assembly Hall, Gym, 1912 Building	No ACBM						
027.2M	Mastic Assoc. w/ 12"x12" Tan Flks w/Brn & Wh VFT			Assembly Hall, Gym, 1912 Building	No ACBM						
028.1	12x12 VFT, Beige Flecks w/Brown and White Specks	332	SF	Room 133, 1890 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
028.1M	Mastic Assoc. w/12"x12"Beige Flecks w/Brn & Wh VFT			Room 133, 1890 Building	No ACBM						
028.2	12x12 VFTMastic, Beige Flecks w/Brn & Wh Specks			2nd Floor Corridor, 1912 Building	No ACBM						
028.2M	Mastic Assoc. w/12"x12"Beige Flecks w/Brn & Wh VFT			2nd Floor Corridor, 1912 Building	No ACBM						
029.1	VFT Molding, Brown			Room 133, 1890 Building	No ACBM						
029.2	VFT Molding, Brown			Assembly Hall, 1912 Building	No ACBM						
030.1	12x12 VFT, Brown w/Dk. Brown and White Streaks	2,240	SF	Room 137, 1890 Building, 234	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
031.1	12x12 VFT, Beige w/Brown and White Streaks			1st Floor Corridor	Assumed	MISC					
031.1M	Mastic Assoc. w/ 12"x12" Beige w/ Brn & Wh VFT			1st Floor Corridor	Assumed	MISC					
032.1	12x12 VFT, Lt. Beige w/Brown and White Streaks	936	SF	Room 233, 1890 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
032.1M	Mastic Assoc. w/ 12"x12" Lt Beige w/Brn & Wh VFT			Room 223, 1890 Building	Assumed	MISC					
033.1	12x12 VFT, Beige Flecks w/Brown and White Specks			2nd Floor Corridor, 1890 Building	Assumed	MISC					
033.1M	Mastic Assoc. w/12"x12" Beige Flks w/Brn & Wh VFT			2nd Floor Corridor, 1890 Building	No ACBM						

Chicago Public Schools

School Sumner Academy
Address 4320 W. Fifth

Unit 31221
Chicago, IL, 60624

Building ID 6110
Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
033.2	12x12 VFT, Beige w/Brown and White Streaks			1st, 2nd & 3rd Floor Corridors, 1912 Building	Assumed	MISC					Follow O&M Plan
034.1	Black Vinyl Molding			1st and 2nd Floor Corridors, 1890 Building	Assumed	MISC					
034.2	VFT Molding, Black			Room 220, 1912 Building	No ACBM						
035.1	Light Brown Mastic for Black Vinyl Molding			1st and 2nd Floor Corridors, 1890 Building	No ACBM						
035.2	VFT Molding Mastic (Light Brown)			Assembly Hall, 1912 Building	No ACBM						
036.1	12x12 VFT, Beige w/Blue, Gray, and Rust Streaks	1,156	SF	Room 332, 1890 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
036.1M	Mastic Assoc.w/12"x12" Beige, Blue, Gry & Rust VFT			Room 332, 1890 Building	No ACBM						
037.1	12x12 VFT, Cream Flecks w/Tan Specks	200	SF	Engineer's Office, 1890 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
038.1	Incinerator Brick			Tank Room, 1890 Building	No ACBM						
038A.1	Incinerator Brick Mortar			Tank Room, 1890 Building	No ACBM						
039.1	Brick			Exterior, 1890 Building	No ACBM						
039.2	Brick			Exterior, 1912 Building	No ACBM						
040.1	Brick Mortar			Exterior, 1890 Building	No ACBM						
040.2	Brick Mortar			Exterior, 1912 Building	No ACBM						
042.2	Glazed Brick			Assembly Hall, 1912 Building	No ACBM						
043.2	Glazed Brick Mortar			Assembly Hall, 1912 Building	No ACBM						
044.2	12x12 VFT, Beige w/Blue, Pink, Gray, & Brown			Room 120 121, and 220, 1912 Building	Assumed	MISC					
044.2M	Mastic Assoc. w/12"x12" VFT, Beige, Blue, Pink...			Rooms 120, 121, and 220, 1912 Building	Assumed	MISC					
045.2	12x12 VFT, Tan w/Blue, Gray, Brown, Orange & Beige			Room 321, 1912 Building	Assumed	MISC					
045.2M	12"x12" Tan, Bl, Gray,Brn, Or & Gray VFT Mastic			Room 321, 1912 Building	Assumed	MISC					
046.2	Gray Vinyl Baseboard			Assembly Hall, 1912 Building	No ACBM						
047.1	Boiler Brick	1,200	SF	Boiler Room, 1890 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
048.1	Boiler Brick Mortar	750	SF	Boiler Room, 1890 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
049.2	Fire Doors	300	SF	Throughout Stairwell Areas, 1912 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
050.1	Roof (NOT AHERA)			Exterior, 1890 Building	Assumed						
050.2	Roof (NOT AHERA)			Exterior, 1912 Building	Assumed						
051.1	Roof Flashing (NOT AHERA)			Exterior, 1890 Building	Assumed						
051.2	Roof Flashing (NOT AHERA)			Exterior, 1912 Building	Assumed						

Chicago Public Schools

School Sumner Academy
Address 4320 W. Fifth

Unit 31221
Chicago, IL, 60624

Building ID 6110
Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
053.1	Door Caulk (NOT AHERA)			Exterior, 1890 Building	Chrysotile						
053.2	Door Caulk (NOT AHERA)			Exterior, 1912 Building	Assumed						
054.1	Window Caulk (NOT AHERA)			Exterior, 1890 Building	Assumed						
054.2	Window Caulk (NOT AHERA)			Exterior, 1912 Building	Assumed						
055.1	Blue Mixed Carpet Mastic			Room 235, 1890 Building	No ACBM						
055.2	Blue Mixed Carpet Mastic			Room 024	No ACBM						
056.1	Pink Mixed Carpet Mastic			Room 235 Closet, 1890 Building	No ACBM						
056.2	Pink Mixed Carpet Mastic			Rooms 020, 125, Teacher's Lounge 1912 Building	No ACBM						
057.1	Brown Mixed Carpet Mastic			Main Office, 1890 Building	No ACBM						
58	12" x 12" Tan with black and white floor tile	325	SF	Rooms 122, Teacher's Lounge - 1912 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
59	Mastic for 12" x 12" Tan with black and white floor tile	325	SF	Rooms 122, Teachers Lounge	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
60	12" x 12" Tan with blue and red floor tile	250	SF	1912 Building Rooms 124, 221 and 1890 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
61	Mastic for 12" x 12" tan with blue and red floor tile	250	SF	1912 Building Rooms Room 124, and 221 and 1890 Building room 332	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
62	12" x 12" Lt gray with white and black floor tile	1,750	SF	1890 Building Rooms 231, 335	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
63	Mastic for 12" x 12" Light gray with white and black floor tile	1,750	SF	1890 Building Rooms 231, 335	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
64	Black Chalk board Adhesive	4,000	SF	1890 and 1912 Building classrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
65	Green Chalk Board Adhesive	4,000	SF	1966 Building Classrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
66	12" x 12" Tan floor tile	10,000	SF	1966 Building Lunch Room 101 (offices), 102, faculty washroom, 103-107, 109-111, 114-116, PC Lab, 1st floor hallway	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
67	Mastic for 12" x 12" Tan floor tile	10,000	SF	1966 Building Lunch Room 101 (offices), 102, faculty washroom, 103-107, 109-111, 114-116, PC Lab, 1st floor hallway	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
68	12" x 12" Blue/Green /Purple floor tile	800	SF	1966 Building Room 112	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
69	Mastic for 12" x 12" Blue/Gree/Purple floor tile	800	SF	1966 Building Room 112	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
70	12" x 12" Red floor tile	400	SF	1966 Building lunch room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
71	Mastic for 12" x 12" Red flor tile	400	SF	1966 Building Lunch Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
72	Green Terrazzo	3,000	SF	1966 Building Entrance and stairwells	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Sumner Academy
Address 4320 W. Fifth

Unit 31221
 Chicago, IL, 60624

Building ID 6110
Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
73	12' x 12' Beige w/ White specs Floor Tiles	2,110	SF	Lunchroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
74	12' x 12' Red w/ white specs Floor Tiles	1,710	SF	Lunchroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
75	12' x 12' Floor Tile Mastic	3,820	SF	Lunchroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
A.1	Cardboard Pipe Insulation			Main Entrance, 1890 Building	No ACBM						
B.1	Joint Insulation on Cardboard Insulated Piping			Main Entrance, 1890 Building	No ACBM						
C.1	Mag Block Pipe Insulation			Main Entrance, 1890 Building	Abated	TSI					
C.2	Mag-Block Pipe Insulation			Engine Room, 1912 Building	Abated	TSI					
D.1	Joint Insulation on Mag Block Insulated Piping			Main Entrance, 1890 Building	Abated	TSI					
I.1	Cardboard Duct Wrap			Filter Room, 1890 Building	No ACBM						
J.2	Joint Insulation on Mag Block Insulated Piping			Engine Room, 1912 Building	Abated	TSI					
K.1	Joint Insulation on Fiberglass Insulated Piping			2nd and 3rd Floor Janitor Closets, 1890 Building	No ACBM						
K.2	Joint Insulation on Fiberglass Insulated Piping			1st and 2nd Floor Girl's Washrooms and 1st Floor Boy's Washroom, 1912 building	Assumed	MISC					

Chicago Public Schools

School Sumner Academy
Address 4320 W. Fifth

Unit 31221
 Chicago, IL, 60624

Building ID 6110
Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

Review Date	5/2/2016
Manager Planner Name	Todd Huffer
100-09870	5/15/2016
Manager IDPH License No/Expiration	

HA Number	Management Comments
001.1	
001.2	
002.1	
002A.1	
013.1	
013.2	
016.1	
016.2	
017.1	
017.2	
018.1	
018.2	
019.1	
019.2	
020.1	
020.2	
021.1	
021.2	
022.1	
022.2	
023.1	material not observed in 2016
023.3	

Chicago Public Schools

School Sumner Academy
Address 4320 W. Fifth

Unit 31221
 Chicago, IL, 60624

Building ID 6110
Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
023.4	
023.5	
024.1	
024.2	
024.3	
024.4	
024.5	
025.1	
025.2	
026.1	
026.2	
027.1	
027.1M	
027.2	
027.2M	
028.1	
028.1M	
028.2	
028.2M	
029.1	
029.2	
030.1	
031.1	material not observed in 2016
031.1M	material not observed in 2016
032.1	
032.1M	material not observed in 2016
033.1	material not observed in 2016

Chicago Public Schools

School Sumner Academy
Address 4320 W. Fifth

Unit 31221
 Chicago, IL, 60624

Building ID 6110
Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
033.1M	
033.2	
034.1	material not observed in 2016
034.2	
035.1	
035.2	
036.1	
036.1M	
037.1	
038.1	
038A.1	
039.1	
039.2	
040.1	
040.2	
042.2	
043.2	
044.2	material not observed in 2016
044.2M	material not observed in 2016
045.2	material not observed in 2016
045.2M	material not observed in 2016
046.2	
047.1	
048.1	
049.2	
050.1	
050.2	

Chicago Public Schools

School Sumner Academy
Address 4320 W. Fifth

Unit 31221
 Chicago, IL, 60624

Building ID 6110
Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
051.1	
051.2	
053.1	
053.2	
054.1	
054.2	
055.1	
055.2	
056.1	
056.2	
057.1	
58	material not observed in room 122
59	material not observed in room 122
60	Not Observed in Room 124
61	Not Observed in Room 124 or Room 332
62	
63	
64	
65	
66	
67	
68	
69	
70	
71	
72	
73	

Chicago Public Schools

School Sumner Academy
Address 4320 W. Fifth

Unit 31221
Chicago, IL, 60624

Building ID 6110
Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
74	
75	
A.1	
B.1	
C.1	
C.2	
D.1	
I.1	
J.2	
K.1	
K.2	Not Observed 2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Sumner Academy** INSPECTION DATE: **2/24/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **001.1**
MATERIAL DESCRIPTION: **Wall/Ceiling Plaster**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout the 1890 building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **02/24/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Sumner Academy** REVIEW DATE: **5/2/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **001.1**

MATERIAL DESCRIPTION: **Wall/Ceiling Plaster**

MATERIAL LOCATION: **Throughout the 1890 building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/02/2016** _____

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUILDING ID: **6110**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Sumner Academy** INSPECTION DATE: **2/24/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **001.2**
MATERIAL DESCRIPTION: **Wall/Ceiling Plaster**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout the 1912 building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **02/24/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Sumner Academy** REVIEW DATE: **5/2/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **001.2**

MATERIAL DESCRIPTION: **Wall/Ceiling Plaster**

MATERIAL LOCATION: **Throughout the 1912 building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/02/2016** _____

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Sumner Academy** INSPECTION DATE: **2/24/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **002.1**
MATERIAL DESCRIPTION: **1x1 Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Lunch Room,1890 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____

Date: 02/24/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Sumner Academy** REVIEW DATE: **5/2/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **002.1**

MATERIAL DESCRIPTION: **1x1 Ceiling Tile**

MATERIAL LOCATION: **Lunch Room,1890 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/02/2016** _____

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Sumner Academy** INSPECTION DATE: **2/24/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **002A.1**
MATERIAL DESCRIPTION: **1x1 Acoustic Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Lunch Room, 1890 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **02/24/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Sumner Academy** REVIEW DATE: **5/2/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **002A.1**

MATERIAL DESCRIPTION: **1x1 Acoustic Ceiling Tile**

MATERIAL LOCATION: **Lunch Room, 1890 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/02/2016** _____

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Sumner Academy** INSPECTION DATE: **2/24/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **013.1**
MATERIAL DESCRIPTION: **2x4 Acoustic Ceiling Tiles**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 334, 1890 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **02/24/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Sumner Academy** REVIEW DATE: **5/2/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **013.1**

MATERIAL DESCRIPTION: **2x4 Acoustic Ceiling Tiles**

MATERIAL LOCATION: **Room 334, 1890 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/02/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Sumner Academy** INSPECTION DATE: **2/24/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **013.2**
MATERIAL DESCRIPTION: **2'x4' Acoustical Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 335, 1912 Building**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 02/24/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Sumner Academy** REVIEW DATE: **5/2/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **013.2**
MATERIAL DESCRIPTION: **2'x4' Acoustical Ceiling Tile**
MATERIAL LOCATION: **Room 335, 1912 Building**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/02/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Sumner Academy** INSPECTION DATE: **2/24/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **016.1**
MATERIAL DESCRIPTION: **Window Caulk, Green**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Teacher's Lounge, Room 131, 1890 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **02/24/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Sumner Academy** REVIEW DATE: **5/2/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **016.1**

MATERIAL DESCRIPTION: **Window Caulk, Green**

MATERIAL LOCATION: **Teacher's Lounge, Room 131, 1890 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/02/2016** _____

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Sumner Academy** INSPECTION DATE: **2/24/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **016.2**
MATERIAL DESCRIPTION: **Window Caulk**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Interior, 1912 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **02/24/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Sumner Academy** REVIEW DATE: **5/2/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **016.2**

MATERIAL DESCRIPTION: **Window Caulk**

MATERIAL LOCATION: **Throughout Interior, 1912 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/02/2016**

Chicago Public Schools

Carnow, Conibear and Associates 2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUILDING ID: **6110**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Sumner Academy** INSPECTION DATE: **2/24/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **017.1**
MATERIAL DESCRIPTION: **Masonry Brick**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Tank Room, Boiler Room, 1912 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **02/24/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Sumner Academy** REVIEW DATE: **5/2/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **017.1**

MATERIAL DESCRIPTION: **Masonry Brick**

MATERIAL LOCATION: **Tank Room, Boiler Room, 1912 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/02/2016** _____

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Sumner Academy** INSPECTION DATE: **2/24/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **017.2**
MATERIAL DESCRIPTION: **Masonry Brick Mortar**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Engine Room, 1912 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____

Date: **02/24/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Sumner Academy** REVIEW DATE: **5/2/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **017.2**

MATERIAL DESCRIPTION: **Masonry Brick Mortar**

MATERIAL LOCATION: **Engine Room, 1912 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/02/2016** _____

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Sumner Academy** INSPECTION DATE: **2/24/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **018.1**
MATERIAL DESCRIPTION: **Masonry Mortar**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Tank Room, Boiler Room, 1890 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 02/24/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Sumner Academy** REVIEW DATE: **5/2/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **018.1**

MATERIAL DESCRIPTION: **Masonry Mortar**

MATERIAL LOCATION: **Tank Room, Boiler Room, 1890 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/02/2016** _____

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Sumner Academy** INSPECTION DATE: **2/24/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **018.2**
MATERIAL DESCRIPTION: **Masonry Brick Wall**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Engine Room, 1912 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **02/24/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Sumner Academy** REVIEW DATE: **5/2/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **018.2**

MATERIAL DESCRIPTION: **Masonry Brick Wall**

MATERIAL LOCATION: **Engine Room, 1912 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/02/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUILDING ID: **6110**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Sumner Academy** INSPECTION DATE: **2/24/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **019.1**
MATERIAL DESCRIPTION: **Wood Wall Board**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Basement Stairwell, 1890 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **02/24/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Sumner Academy** REVIEW DATE: **5/2/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **019.1**

MATERIAL DESCRIPTION: **Wood Wall Board**

MATERIAL LOCATION: **Basement Stairwell, 1890 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/02/2016** _____

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Sumner Academy** INSPECTION DATE: **2/24/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **019.2**
MATERIAL DESCRIPTION: **Wood Wall Board**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 124, 1912 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **02/24/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Sumner Academy** REVIEW DATE: **5/2/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **019.2**

MATERIAL DESCRIPTION: **Wood Wall Board**

MATERIAL LOCATION: **Room 124, 1912 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/02/2016** _____

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Sumner Academy** INSPECTION DATE: **2/24/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **020.1**
MATERIAL DESCRIPTION: **Cinder Block**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Tank Room, Boiler Room, 1890 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **02/24/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Sumner Academy** REVIEW DATE: **5/2/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **020.1**

MATERIAL DESCRIPTION: **Cinder Block**

MATERIAL LOCATION: **Tank Room, Boiler Room, 1890 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/02/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Sumner Academy** INSPECTION DATE: **2/24/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **020.2**
MATERIAL DESCRIPTION: **Cinder Block**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Store Room Across From Assembly Hall, 1912 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **02/24/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Sumner Academy** REVIEW DATE: **5/2/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **020.2**

MATERIAL DESCRIPTION: **Cinder Block**

MATERIAL LOCATION: **Store Room Across From Assembly Hall, 1912 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/02/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Sumner Academy** INSPECTION DATE: **2/24/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **021.1**
MATERIAL DESCRIPTION: **Cinder Block Mortar**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Tank Room, Boiler Room, 1890 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 02/24/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Sumner Academy** REVIEW DATE: **5/2/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **021.1**

MATERIAL DESCRIPTION: **Cinder Block Mortar**

MATERIAL LOCATION: **Tank Room, Boiler Room, 1890 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/02/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Sumner Academy** INSPECTION DATE: **2/24/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **021.2**
MATERIAL DESCRIPTION: **Cinder Block Mortar**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Storeroom Across From Assembly Hall, 1912 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **02/24/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Sumner Academy** REVIEW DATE: **5/2/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **021.2**

MATERIAL DESCRIPTION: **Cinder Block Mortar**

MATERIAL LOCATION: **Storeroom Across From Assembly Hall, 1912 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/02/2016** _____

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Sumner Academy** INSPECTION DATE: **2/24/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **022.1**
MATERIAL DESCRIPTION: **Drywall**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Teacher's Lounge, 1st Floor Stop Sink, 1890 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **02/24/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Sumner Academy** REVIEW DATE: **5/2/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **022.1**

MATERIAL DESCRIPTION: **Drywall**

MATERIAL LOCATION: **Teacher's Lounge, 1st Floor Slop Sink, 1890 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/02/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Sumner Academy** INSPECTION DATE: **2/24/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **022.2**
MATERIAL DESCRIPTION: **Drywall**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 120 and 223, 1912 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **02/24/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Sumner Academy** REVIEW DATE: **5/2/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **022.2**

MATERIAL DESCRIPTION: **Drywall**

MATERIAL LOCATION: **Room 120 and 223, 1912 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/02/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Sumner Academy** INSPECTION DATE: **2/24/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **023.1**
MATERIAL DESCRIPTION: **12x12 Lt. Gray w/Brn and White Streaks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Lunch Room, 1890 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed 2016**

Inspector's Signature: _____

Date: 02/24/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUILDING ID: **6110**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Sumner Academy** REVIEW DATE: **5/2/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **023.1**

MATERIAL DESCRIPTION: **12x12 Lt. Gray w/Brn and White Streaks Floor Tile**

MATERIAL LOCATION: **Lunch Room, 1890 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

material not observed in 2016

Management Planner's Signature: _____



Date: **05/02/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Sumner Academy** INSPECTION DATE: **2/24/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **023.3**
MATERIAL DESCRIPTION: **12"x12" Brown Floor Tile w/Dk Brwn & White Streaks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 137, 1890 Building**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 02/24/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Sumner Academy** REVIEW DATE: **5/2/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **023.3**
MATERIAL DESCRIPTION: **12"x12" Brown Floor Tile w/Dk Brwn & White Streaks**
MATERIAL LOCATION: **Room 137, 1890 Building**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/02/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Sumner Academy** INSPECTION DATE: **2/24/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **023.4**
MATERIAL DESCRIPTION: **12"x12" Beige w/White & Brown Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st, 2nd & 3rd Floor Corridors, 1912 Building**
MATERIAL QUANTITY: **15000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 02/24/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUILDING ID: **6110**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Sumner Academy** REVIEW DATE: **5/2/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **023.4**
MATERIAL DESCRIPTION: **12"x12" Beige w/White & Brown Floor Tile**
MATERIAL LOCATION: **1st, 2nd & 3rd Floor Corridors, 1912 Building**
MATERIAL QUANTITY: **15000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/02/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Sumner Academy** INSPECTION DATE: **2/24/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **023.5**
MATERIAL DESCRIPTION: **12"x 12" Cream Flecks w/ Tan Specks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Engineers Office, 1890 Building**

MATERIAL QUANTITY: **200**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 02/24/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Sumner Academy** REVIEW DATE: **5/2/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **023.5**
MATERIAL DESCRIPTION: **12"x 12" Cream Flecks w/ Tan Specks Floor Tile**
MATERIAL LOCATION: **Engineers Office, 1890 Building**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/02/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Sumner Academy** INSPECTION DATE: **2/24/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **024.1**
MATERIAL DESCRIPTION: **12"x12" Lt. Gray w/Brown & Wh Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Lunch Room, 1890 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed 2016**

Inspector's Signature: _____

Date: 02/24/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Sumner Academy** REVIEW DATE: **5/2/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **024.1**

MATERIAL DESCRIPTION: **12"x12" Lt. Gray w/Brown & Wh Floor Tile Mastic**

MATERIAL LOCATION: **Lunch Room, 1890 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/02/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Sumner Academy** INSPECTION DATE: **2/24/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **024.2**
MATERIAL DESCRIPTION: **Mastic Assoc. w/ 12"x12" Tan Flecks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 221, 1912 Building**

MATERIAL QUANTITY: **700**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 02/24/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Sumner Academy** REVIEW DATE: **5/2/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **024.2**

MATERIAL DESCRIPTION: **Mastic Assoc. w/ 12"x12" Tan Flecks Floor Tile**

MATERIAL LOCATION: **Room 221, 1912 Building**

MATERIAL QUANTITY: **700**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/02/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Sumner Academy** INSPECTION DATE: **2/24/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **024.3**
MATERIAL DESCRIPTION: **12"x12: Brown w/Dark Brown Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 137, 1890 Building**

MATERIAL QUANTITY: **800**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 02/24/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Sumner Academy** REVIEW DATE: **5/2/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **024.3**
MATERIAL DESCRIPTION: **12"x12: Brown w/Dark Brown Floor Tile Mastic**
MATERIAL LOCATION: **Room 137, 1890 Building**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/02/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Sumner Academy** INSPECTION DATE: **2/24/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **024.4**
MATERIAL DESCRIPTION: **Mastic Assoc. w/12"x12" Cream Flks w/Tan Spks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Engineer's Office, 1890 Building**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 02/24/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Sumner Academy** REVIEW DATE: **5/2/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **024.4**
MATERIAL DESCRIPTION: **Mastic Assoc. w/12"x12" Cream Flks w/Tan Spks VFT**
MATERIAL LOCATION: **Engineer's Office, 1890 Building**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/02/2016**

Chicago Public Schools

Carnow, Conibear and Associates 2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Sumner Academy** INSPECTION DATE: **2/24/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **024.5**
MATERIAL DESCRIPTION: **12"x12" Beige w/White & Brown Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st, 2nd & 3rd Floor Corridors, 1912 Building, 024**
MATERIAL QUANTITY: **15000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 02/24/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Sumner Academy** REVIEW DATE: **5/2/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **024.5**
MATERIAL DESCRIPTION: **12"x12" Beige w/White & Brown Floor Tile Mastic**
MATERIAL LOCATION: **1st, 2nd & 3rd Floor Corridors, 1912 Building, 024**
MATERIAL QUANTITY: **15000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/02/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Sumner Academy** INSPECTION DATE: **2/24/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **025.1**
MATERIAL DESCRIPTION: **Brown Vinyl Baseboard**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Lunch Room,1890 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **02/24/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Sumner Academy** REVIEW DATE: **5/2/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **025.1**

MATERIAL DESCRIPTION: **Brown Vinyl Baseboard**

MATERIAL LOCATION: **Lunch Room,1890 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/02/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Sumner Academy** INSPECTION DATE: **2/24/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **025.2**
MATERIAL DESCRIPTION: **Light Brown Vinyl Baseboard**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Teacher's Lounge**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____

Date: **02/24/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Sumner Academy** REVIEW DATE: **5/2/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **025.2**

MATERIAL DESCRIPTION: **Light Brown Vinyl Baseboard**

MATERIAL LOCATION: **Teacher's Lounge**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/02/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUILDING ID: **6110**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Sumner Academy** INSPECTION DATE: **2/24/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **026.1**
MATERIAL DESCRIPTION: **Brown Vinyl Baseboard Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Lunch Room, 1890 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **02/24/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Sumner Academy** REVIEW DATE: **5/2/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **026.1**

MATERIAL DESCRIPTION: **Brown Vinyl Baseboard Adhesive**

MATERIAL LOCATION: **Lunch Room, 1890 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/02/2016** _____

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Sumner Academy** INSPECTION DATE: **2/24/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **026.2**
MATERIAL DESCRIPTION: **Light Brown Vinyl Baseboard Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Teacher's Lounge**

MATERIAL QUANTITY: **80**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____

Date: 02/24/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Sumner Academy** REVIEW DATE: **5/2/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **026.2**

MATERIAL DESCRIPTION: **Light Brown Vinyl Baseboard Adhesive**

MATERIAL LOCATION: **Teacher's Lounge**

MATERIAL QUANTITY: **80**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/02/2016**

Chicago Public Schools

Carnow, Conibear and Associates 2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Sumner Academy** INSPECTION DATE: **2/24/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **027.1**
MATERIAL DESCRIPTION: **12x12 VFT, Tan Flecks w/Brown and White Specks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Lunchroom kitchen, 1890 Building**

MATERIAL QUANTITY: **1576**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 02/24/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Sumner Academy** REVIEW DATE: **5/2/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **027.1**
MATERIAL DESCRIPTION: **12x12 VFT, Tan Flecks w/Brown and White Specks**
MATERIAL LOCATION: **Lunchroom kitchen, 1890 Building**
MATERIAL QUANTITY: **1576** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/02/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Sumner Academy** INSPECTION DATE: **2/24/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **027.1M**
MATERIAL DESCRIPTION: **Mastic Assoc. w/ 12"x12" Tan Flks w/Brn & Wh VFT**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Lunchroom, Kitchen, 1890 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 02/24/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Sumner Academy** REVIEW DATE: **5/2/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **027.1M**

MATERIAL DESCRIPTION: **Mastic Assoc. w/ 12"x12" Tan Flks w/Brn & Wh VFT**

MATERIAL LOCATION: **Lunchroom, Kitchen, 1890 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/02/2016** _____

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Sumner Academy** INSPECTION DATE: **2/24/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **027.2**
MATERIAL DESCRIPTION: **Mastic Assoc. w/12"x12" Tan Flecks w/Brn & Wh VFT**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Assembly Hall, Gym, 1912 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 02/24/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Sumner Academy** REVIEW DATE: **5/2/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **027.2**

MATERIAL DESCRIPTION: **Mastic Assoc. w/12"x12" Tan Flecks w/Brn & Wh VFT**

MATERIAL LOCATION: **Assembly Hall, Gym, 1912 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/02/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Sumner Academy** INSPECTION DATE: **2/24/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **027.2M**
MATERIAL DESCRIPTION: **Mastic Assoc. w/ 12"x12" Tan Flks w/Brn & Wh VFT**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Assembly Hall, Gym, 1912 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **02/24/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Sumner Academy** REVIEW DATE: **5/2/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **027.2M**

MATERIAL DESCRIPTION: **Mastic Assoc. w/ 12"x12" Tan Flks w/Brn & Wh VFT**

MATERIAL LOCATION: **Assembly Hall, Gym, 1912 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/02/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Sumner Academy** INSPECTION DATE: **2/24/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **028.1**
MATERIAL DESCRIPTION: **12x12 VFT, Beige Flecks w/Brown and White Specks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 133, 1890 Building**

MATERIAL QUANTITY: **332**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 02/24/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Sumner Academy** REVIEW DATE: **5/2/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **028.1**
MATERIAL DESCRIPTION: **12x12 VFT, Beige Flecks w/Brown and White Specks**
MATERIAL LOCATION: **Room 133, 1890 Building**
MATERIAL QUANTITY: **332** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/02/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Sumner Academy** INSPECTION DATE: **2/24/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **028.1M**
MATERIAL DESCRIPTION: **Mastic Assoc. w/12"x12"Beige Flecks w/Brn & Wh VFT**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 133, 1890 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____

Date: 02/24/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Sumner Academy** REVIEW DATE: **5/2/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **028.1M**

MATERIAL DESCRIPTION: **Mastic Assoc. w/12"x12"Beige Flecks w/Brn & Wh VFT**

MATERIAL LOCATION: **Room 133, 1890 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/02/2016** _____

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Sumner Academy** INSPECTION DATE: **2/24/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **028.2**
MATERIAL DESCRIPTION: **12x12 VFTMastic, Beige Flecks w/Brn & Wh Specks**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **2nd Floor Corridor, 1912 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed 2016**

Inspector's Signature: _____

Date: 02/24/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Sumner Academy** REVIEW DATE: **5/2/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **028.2**

MATERIAL DESCRIPTION: **12x12 VFTMastic, Beige Flecks w/Brn & Wh Specks**

MATERIAL LOCATION: **2nd Floor Corridor, 1912 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/02/2016** _____

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Sumner Academy** INSPECTION DATE: **2/24/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **028.2M**
MATERIAL DESCRIPTION: **Mastic Assoc. w/12"x12"Beige Flecks w/Brn & Wh VFT**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **2nd Floor Corridor, 1912 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not Observed 2016**

Inspector's Signature: _____ Date: **02/24/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Sumner Academy** REVIEW DATE: **5/2/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **028.2M**

MATERIAL DESCRIPTION: **Mastic Assoc. w/12"x12"Beige Flecks w/Brn & Wh VFT**

MATERIAL LOCATION: **2nd Floor Corridor, 1912 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/02/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Sumner Academy** INSPECTION DATE: **2/24/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **029.1**
MATERIAL DESCRIPTION: **VFT Molding, Brown**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 133, 1890 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **02/24/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Sumner Academy** REVIEW DATE: **5/2/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **029.1**

MATERIAL DESCRIPTION: **VFT Molding, Brown**

MATERIAL LOCATION: **Room 133, 1890 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/02/2016** _____

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Sumner Academy** INSPECTION DATE: **2/24/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **029.2**
MATERIAL DESCRIPTION: **VFT Molding, Brown**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Assembly Hall, 1912 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____

Date: 02/24/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUILDING ID: **6110**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Sumner Academy** REVIEW DATE: **5/2/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **029.2**

MATERIAL DESCRIPTION: **VFT Molding, Brown**

MATERIAL LOCATION: **Assembly Hall, 1912 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/02/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Sumner Academy** INSPECTION DATE: **2/24/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **030.1**
MATERIAL DESCRIPTION: **12x12 VFT, Brown w/Dk. Brown and White Streaks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 137, 1890 Building, 234**

MATERIAL QUANTITY: **2240**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Room 137 Is listed as separate**

Inspector's Signature: _____

Date: 02/24/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Sumner Academy** REVIEW DATE: **5/2/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **030.1**
MATERIAL DESCRIPTION: **12x12 VFT, Brown w/Dk. Brown and White Streaks**
MATERIAL LOCATION: **Room 137, 1890 Building, 234**
MATERIAL QUANTITY: **2240** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/02/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Sumner Academy** INSPECTION DATE: **2/24/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **031.1**
MATERIAL DESCRIPTION: **12x12 VFT, Beige w/Brown and White Streaks**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st Floor Corridor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed 2016**

Inspector's Signature: _____

Date: 02/24/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Sumner Academy** REVIEW DATE: **5/2/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **031.1**

MATERIAL DESCRIPTION: **12x12 VFT, Beige w/Brown and White Streaks**

MATERIAL LOCATION: **1st Floor Corridor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

material not observed in 2016

Management Planner's Signature: _____



Date: **05/02/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Sumner Academy** INSPECTION DATE: **2/24/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **031.1M**
MATERIAL DESCRIPTION: **Mastic Assoc. w/ 12"x12" Beige w/ Brn & Wh VFT**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st Floor Corridor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed 2016**

Inspector's Signature: _____

Date: 02/24/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUILDING ID: **6110**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Sumner Academy** REVIEW DATE: **5/2/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **031.1M**

MATERIAL DESCRIPTION: **Mastic Assoc. w/ 12"x12" Beige w/ Brn & Wh VFT**

MATERIAL LOCATION: **1st Floor Corridor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

material not observed in 2016

Management Planner's Signature: _____



Date: **05/02/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Sumner Academy** INSPECTION DATE: **2/24/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **032.1**
MATERIAL DESCRIPTION: **12x12 VFT, Lt. Beige w/Brown and White Streaks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 233, 1890 Building**
MATERIAL QUANTITY: **936** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 02/24/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Sumner Academy** REVIEW DATE: **5/2/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **032.1**

MATERIAL DESCRIPTION: **12x12 VFT, Lt. Beige w/Brown and White Streaks**

MATERIAL LOCATION: **Room 233, 1890 Building**

MATERIAL QUANTITY: **936**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/02/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Sumner Academy** INSPECTION DATE: **2/24/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **032.1M**
MATERIAL DESCRIPTION: **Mastic Assoc. w/ 12"x12" Lt Beige w/Brn & Wh VFT**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 223, 1890 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed 2016-may be under wooden floor**

Inspector's Signature: _____

Date: 02/24/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUILDING ID: **6110**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Sumner Academy** REVIEW DATE: **5/2/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **032.1M**

MATERIAL DESCRIPTION: **Mastic Assoc. w/ 12"x12" Lt Beige w/Brn & Wh VFT**

MATERIAL LOCATION: **Room 223, 1890 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

material not observed in 2016

Management Planner's Signature: _____



Date: **05/02/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Sumner Academy** INSPECTION DATE: **2/24/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **033.1**
MATERIAL DESCRIPTION: **12x12 VFT, Beige Flecks w/Brown and White Specks**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with potential for significant damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **2nd Floor Corridor, 1890 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed 2016**

Inspector's Signature: _____

Date: 02/24/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Sumner Academy** REVIEW DATE: **5/2/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **033.1**

MATERIAL DESCRIPTION: **12x12 VFT, Beige Flecks w/Brown and White Specks**

MATERIAL LOCATION: **2nd Floor Corridor, 1890 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

material not observed in 2016

Management Planner's Signature: _____



Date: **05/02/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Sumner Academy** INSPECTION DATE: **2/24/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **033.1M**
MATERIAL DESCRIPTION: **Mastic Assoc. w/12"x12" Beige Flks w/Brn & Wh VFT**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **2nd Floor Corridor, 1890 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed 2016**

Inspector's Signature: _____

Date: 02/24/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Sumner Academy** REVIEW DATE: **5/2/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **033.1M**

MATERIAL DESCRIPTION: **Mastic Assoc. w/12"x12" Beige Flks w/Brn & Wh VFT**

MATERIAL LOCATION: **2nd Floor Corridor, 1890 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/02/2016** _____

Chicago Public Schools

Carnow, Conibear and Associates 2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Sumner Academy** INSPECTION DATE: **2/24/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **033.2**
MATERIAL DESCRIPTION: **12x12 VFT, Beige w/Brown and White Streaks**
HISTORICAL AHERA DAMAGE CATEGORY: **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st, 2nd & 3rd Floor Corridors, 1912 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not Observed 2016**

Inspector's Signature: _____ Date: 02/24/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Sumner Academy** REVIEW DATE: **5/2/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **033.2**

MATERIAL DESCRIPTION: **12x12 VFT, Beige w/Brown and White Streaks**

MATERIAL LOCATION: **1st, 2nd & 3rd Floor Corridors, 1912 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/02/2016**

Chicago Public Schools

Carnow, Conibear and Associates 2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Sumner Academy** INSPECTION DATE: **2/24/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **034.1**
MATERIAL DESCRIPTION: **Black Vinyl Molding**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st and 2nd Floor Corridors, 1890 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 02/24/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Sumner Academy** REVIEW DATE: **5/2/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **034.1**

MATERIAL DESCRIPTION: **Black Vinyl Molding**

MATERIAL LOCATION: **1st and 2nd Floor Corridors, 1890 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

material not observed in 2016

Management Planner's Signature: _____



Date: **05/02/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Sumner Academy** INSPECTION DATE: **2/24/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **034.2**
MATERIAL DESCRIPTION: **VFT Molding, Black**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 220, 1912 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____

Date: 02/24/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUILDING ID: **6110**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Sumner Academy** REVIEW DATE: **5/2/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **034.2**

MATERIAL DESCRIPTION: **VFT Molding, Black**

MATERIAL LOCATION: **Room 220, 1912 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/02/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Sumner Academy** INSPECTION DATE: **2/24/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **035.1**
MATERIAL DESCRIPTION: **Light Brown Mastic for Black Vinyl Molding**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st and 2nd Floor Corridors, 1890 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **02/24/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Sumner Academy** REVIEW DATE: **5/2/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **035.1**

MATERIAL DESCRIPTION: **Light Brown Mastic for Black Vinyl Molding**

MATERIAL LOCATION: **1st and 2nd Floor Corridors, 1890 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/02/2016** _____

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Sumner Academy** INSPECTION DATE: **2/24/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **035.2**
MATERIAL DESCRIPTION: **VFT Molding Mastic (Light Brown)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Assembly Hall, 1912 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **02/24/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Sumner Academy** REVIEW DATE: **5/2/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **035.2**

MATERIAL DESCRIPTION: **VFT Molding Mastic (Light Brown)**

MATERIAL LOCATION: **Assembly Hall, 1912 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/02/2016** _____

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Sumner Academy** INSPECTION DATE: **2/24/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **036.1**
MATERIAL DESCRIPTION: **12x12 VFT, Beige w/Blue, Gray, and Rust Streaks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 332, 1890 Building**

MATERIAL QUANTITY: **1156**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 02/24/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Sumner Academy** REVIEW DATE: **5/2/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **036.1**
MATERIAL DESCRIPTION: **12x12 VFT, Beige w/Blue, Gray, and Rust Streaks**
MATERIAL LOCATION: **Room 332, 1890 Building**
MATERIAL QUANTITY: **1156** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/02/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUILDING ID: **6110**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Sumner Academy** INSPECTION DATE: **2/24/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **036.1M**
MATERIAL DESCRIPTION: **Mastic Assoc.w/12"x12" Beige ,Blue, Gry & Rust VFT**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 332, 1890 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **02/24/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Sumner Academy** REVIEW DATE: **5/2/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **036.1M**

MATERIAL DESCRIPTION: **Mastic Assoc.w/12"x12" Beige ,Blue, Gry & Rust VFT**

MATERIAL LOCATION: **Room 332, 1890 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/02/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Sumner Academy** INSPECTION DATE: **2/24/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **037.1**
MATERIAL DESCRIPTION: **12x12 VFT, Cream Flecks w/Tan Specks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Engineer's Office, 1890 Building**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 02/24/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Sumner Academy** REVIEW DATE: **5/2/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **037.1**
MATERIAL DESCRIPTION: **12x12 VFT, Cream Flecks w/Tan Specks**
MATERIAL LOCATION: **Engineer's Office, 1890 Building**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/02/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUILDING ID: **6110**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Sumner Academy** INSPECTION DATE: **2/24/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **038.1**
MATERIAL DESCRIPTION: **Incinerator Brick**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Tank Room, 1890 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **02/24/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Sumner Academy** REVIEW DATE: **5/2/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **038.1**

MATERIAL DESCRIPTION: **Incinerator Brick**

MATERIAL LOCATION: **Tank Room, 1890 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/02/2016** _____

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Sumner Academy** INSPECTION DATE: **2/24/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **038A.1**
MATERIAL DESCRIPTION: **Incinerator Brick Mortar**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Tank Room, 1890 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 02/24/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Sumner Academy** REVIEW DATE: **5/2/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **038A.1**

MATERIAL DESCRIPTION: **Incinerator Brick Mortar**

MATERIAL LOCATION: **Tank Room, 1890 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/02/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Sumner Academy** INSPECTION DATE: **2/24/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **039.1**
MATERIAL DESCRIPTION: **Brick**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior, 1890 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **02/24/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUILDING ID: **6110**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Sumner Academy** REVIEW DATE: **5/2/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **039.1**

MATERIAL DESCRIPTION: **Brick**

MATERIAL LOCATION: **Exterior, 1890 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/02/2016** _____

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Sumner Academy** INSPECTION DATE: **2/24/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **039.2**
MATERIAL DESCRIPTION: **Brick**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior, 1912 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **02/24/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Sumner Academy** REVIEW DATE: **5/2/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **039.2**

MATERIAL DESCRIPTION: **Brick**

MATERIAL LOCATION: **Exterior, 1912 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/02/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Sumner Academy** INSPECTION DATE: **2/24/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **040.1**
MATERIAL DESCRIPTION: **Brick Mortar**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior, 1890 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **02/24/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Sumner Academy** REVIEW DATE: **5/2/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **040.1**

MATERIAL DESCRIPTION: **Brick Mortar**

MATERIAL LOCATION: **Exterior, 1890 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/02/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUILDING ID: **6110**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Sumner Academy** INSPECTION DATE: **2/24/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **040.2**
MATERIAL DESCRIPTION: **Brick Mortar**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior, 1912 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **02/24/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Sumner Academy** REVIEW DATE: **5/2/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **040.2**

MATERIAL DESCRIPTION: **Brick Mortar**

MATERIAL LOCATION: **Exterior, 1912 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/02/2016** _____

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Sumner Academy** INSPECTION DATE: **2/24/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **042.2**
MATERIAL DESCRIPTION: **Glazed Brick**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Assembly Hall, 1912 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **02/24/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Sumner Academy** REVIEW DATE: **5/2/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **042.2**

MATERIAL DESCRIPTION: **Glazed Brick**

MATERIAL LOCATION: **Assembly Hall, 1912 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/02/2016** _____

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Sumner Academy** INSPECTION DATE: **2/24/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **043.2**
MATERIAL DESCRIPTION: **Glazed Brick Mortar**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Assembly Hall, 1912 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____

Date: **02/24/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Sumner Academy** REVIEW DATE: **5/2/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **043.2**

MATERIAL DESCRIPTION: **Glazed Brick Mortar**

MATERIAL LOCATION: **Assembly Hall, 1912 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/02/2016** _____

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Sumner Academy** INSPECTION DATE: **2/24/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **044.2**
MATERIAL DESCRIPTION: **12x12 VFT, Beige w/Blue, Pink, Gray, & Brown**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 120 121, and 220, 1912 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed 2016**

Inspector's Signature: _____

Date: 02/24/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Sumner Academy** REVIEW DATE: **5/2/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **044.2**

MATERIAL DESCRIPTION: **12x12 VFT, Beige w/Blue, Pink, Gray, & Brown**

MATERIAL LOCATION: **Room 120 121, and 220, 1912 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

material not observed in 2016

Management Planner's Signature: _____



Date: **05/02/2016**

Chicago Public Schools

Carnow, Conibear and Associates 2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Sumner Academy** INSPECTION DATE: **2/24/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **044.2M**
MATERIAL DESCRIPTION: **Mastic Assoc. w/12"x12" VFT, Beige, Blue, Pink...**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 120, 121, and 220, 1912 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not Observed 2016**

Inspector's Signature: _____ Date: **02/24/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Sumner Academy** REVIEW DATE: **5/2/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **044.2M**

MATERIAL DESCRIPTION: **Mastic Assoc. w/12"x12" VFT, Beige, Blue, Pink...**

MATERIAL LOCATION: **Rooms 120, 121, and 220, 1912 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

material not observed in 2016

Management Planner's Signature: _____



Date: **05/02/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Sumner Academy** INSPECTION DATE: **2/24/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **045.2**
MATERIAL DESCRIPTION: **12x12 VFT, Tan w/Blue, Gray, Brown, Orange & Beige**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 321, 1912 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed 2016 - Room 321 Not Found**

Inspector's Signature: _____

Date: 02/24/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Sumner Academy** REVIEW DATE: **5/2/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **045.2**

MATERIAL DESCRIPTION: **12x12 VFT, Tan w/Blue, Gray, Brown, Orange & Beige**

MATERIAL LOCATION: **Room 321, 1912 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

material not observed in 2016

Management Planner's Signature: _____



Date: **05/02/2016** _____

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Sumner Academy** INSPECTION DATE: **2/24/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **045.2M**
MATERIAL DESCRIPTION: **12"x12" Tan, Bl, Gray,Brn, Or & Gray VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 321, 1912 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed 2016 - Room 321 not found**

Inspector's Signature: _____

Date: 02/24/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Sumner Academy** REVIEW DATE: **5/2/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **045.2M**

MATERIAL DESCRIPTION: **12"x12" Tan, Bl, Gray, Brn, Or & Gray VFT Mastic**

MATERIAL LOCATION: **Room 321, 1912 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

material not observed in 2016

Management Planner's Signature: _____



Date: **05/02/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Sumner Academy** INSPECTION DATE: **2/24/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **046.2**
MATERIAL DESCRIPTION: **Gray Vinyl Baseboard**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Assembly Hall, 1912 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **02/24/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Sumner Academy** REVIEW DATE: **5/2/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **046.2**

MATERIAL DESCRIPTION: **Gray Vinyl Baseboard**

MATERIAL LOCATION: **Assembly Hall, 1912 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/02/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Sumner Academy** INSPECTION DATE: **2/24/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **047.1**
MATERIAL DESCRIPTION: **Boiler Brick**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Boiler Room, 1890 Building**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 02/24/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Sumner Academy** REVIEW DATE: **5/2/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **047.1**
MATERIAL DESCRIPTION: **Boiler Brick**
MATERIAL LOCATION: **Boiler Room, 1890 Building**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/02/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Sumner Academy** INSPECTION DATE: **2/24/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **048.1**
MATERIAL DESCRIPTION: **Boiler Brick Mortar**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Boiler Room, 1890 Building**

MATERIAL QUANTITY: **750**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 02/24/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Sumner Academy** REVIEW DATE: **5/2/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **048.1**
MATERIAL DESCRIPTION: **Boiler Brick Mortar**
MATERIAL LOCATION: **Boiler Room, 1890 Building**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/02/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUILDING ID: **6110**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Sumner Academy** INSPECTION DATE: **2/24/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **049.2**
MATERIAL DESCRIPTION: **Fire Doors**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout Stairwell Areas, 1912 Building**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 02/24/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Sumner Academy** REVIEW DATE: **5/2/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **049.2**
MATERIAL DESCRIPTION: **Fire Doors**
MATERIAL LOCATION: **Throughout Stairwell Areas, 1912 Building**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/02/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUILDING ID: **6110**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Sumner Academy** INSPECTION DATE: **2/24/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **050.1**
MATERIAL DESCRIPTION: **Roof (NOT AHERA)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior, 1890 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **02/24/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Sumner Academy** REVIEW DATE: **5/2/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **050.1**

MATERIAL DESCRIPTION: **Roof (NOT AHERA)**

MATERIAL LOCATION: **Exterior, 1890 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/02/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUILDING ID: **6110**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Sumner Academy** INSPECTION DATE: **2/24/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **050.2**
MATERIAL DESCRIPTION: **Roof (NOT AHERA)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior, 1912 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **02/24/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Sumner Academy** REVIEW DATE: **5/2/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **050.2**

MATERIAL DESCRIPTION: **Roof (NOT AHERA)**

MATERIAL LOCATION: **Exterior, 1912 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/02/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Sumner Academy** INSPECTION DATE: **2/24/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **051.1**
MATERIAL DESCRIPTION: **Roof Flashing (NOT AHERA)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior, 1890 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **02/24/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Sumner Academy** REVIEW DATE: **5/2/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **051.1**

MATERIAL DESCRIPTION: **Roof Flashing (NOT AHERA)**

MATERIAL LOCATION: **Exterior, 1890 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/02/2016** _____

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Sumner Academy** INSPECTION DATE: **2/24/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **051.2**
MATERIAL DESCRIPTION: **Roof Flashing (NOT AHERA)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior, 1912 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____

Date: **02/24/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Sumner Academy** REVIEW DATE: **5/2/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **051.2**

MATERIAL DESCRIPTION: **Roof Flashing (NOT AHERA)**

MATERIAL LOCATION: **Exterior, 1912 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/02/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Sumner Academy** INSPECTION DATE: **2/24/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **053.1**
MATERIAL DESCRIPTION: **Door Caulk (NOT AHERA)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior, 1890 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **02/24/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Sumner Academy** REVIEW DATE: **5/2/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **053.1**

MATERIAL DESCRIPTION: **Door Caulk (NOT AHERA)**

MATERIAL LOCATION: **Exterior, 1890 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/02/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Sumner Academy** INSPECTION DATE: **2/24/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **053.2**
MATERIAL DESCRIPTION: **Door Caulk (NOT AHERA)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior, 1912 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **02/24/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUILDING ID: **6110**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Sumner Academy** REVIEW DATE: **5/2/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **053.2**

MATERIAL DESCRIPTION: **Door Caulk (NOT AHERA)**

MATERIAL LOCATION: **Exterior, 1912 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/02/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Sumner Academy** INSPECTION DATE: **2/24/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **054.1**
MATERIAL DESCRIPTION: **Window Caulk (NOT AHERA)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior, 1890 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **02/24/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Sumner Academy** REVIEW DATE: **5/2/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **054.1**

MATERIAL DESCRIPTION: **Window Caulk (NOT AHERA)**

MATERIAL LOCATION: **Exterior, 1890 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/02/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Sumner Academy** INSPECTION DATE: **2/24/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **054.2**
MATERIAL DESCRIPTION: **Window Caulk (NOT AHERA)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior, 1912 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **02/24/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Sumner Academy** REVIEW DATE: **5/2/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **054.2**

MATERIAL DESCRIPTION: **Window Caulk (NOT AHERA)**

MATERIAL LOCATION: **Exterior, 1912 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/02/2016** _____

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUILDING ID: **6110**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Sumner Academy** INSPECTION DATE: **2/24/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **055.1**
MATERIAL DESCRIPTION: **Blue Mixed Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 235, 1890 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **02/24/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Sumner Academy** REVIEW DATE: **5/2/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **055.1**

MATERIAL DESCRIPTION: **Blue Mixed Carpet Mastic**

MATERIAL LOCATION: **Room 235, 1890 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/02/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Sumner Academy** INSPECTION DATE: **2/24/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **055.2**
MATERIAL DESCRIPTION: **Blue Mixed Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 024**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **02/24/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Sumner Academy** REVIEW DATE: **5/2/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **055.2**

MATERIAL DESCRIPTION: **Blue Mixed Carpet Mastic**

MATERIAL LOCATION: **Room 024**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/02/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Sumner Academy** INSPECTION DATE: **2/24/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **056.1**
MATERIAL DESCRIPTION: **Pink Mixed Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 235 Closet, 1890 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **02/24/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Sumner Academy** REVIEW DATE: **5/2/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **056.1**

MATERIAL DESCRIPTION: **Pink Mixed Carpet Mastic**

MATERIAL LOCATION: **Room 235 Closet, 1890 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/02/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Sumner Academy** INSPECTION DATE: **2/24/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **056.2**
MATERIAL DESCRIPTION: **Pink Mixed Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 020, 125, Teacher's Lounge 1912 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **02/24/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Sumner Academy** REVIEW DATE: **5/2/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **056.2**

MATERIAL DESCRIPTION: **Pink Mixed Carpet Mastic**

MATERIAL LOCATION: **Rooms 020, 125, Teacher's Lounge 1912 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/02/2016** _____

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Sumner Academy** INSPECTION DATE: **2/24/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **057.1**
MATERIAL DESCRIPTION: **Brown Mixed Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Main Office, 1890 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 02/24/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Sumner Academy** REVIEW DATE: **5/2/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **057.1**

MATERIAL DESCRIPTION: **Brown Mixed Carpet Mastic**

MATERIAL LOCATION: **Main Office, 1890 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/02/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Sumner Academy** INSPECTION DATE: **2/24/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **58**
MATERIAL DESCRIPTION: **12" x 12" Tan with black and white floor tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 122, Teacher's Lounge - 1912 Building**

MATERIAL QUANTITY: **325** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not Observed in Room 122**

Inspector's Signature: _____ Date: 02/24/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Sumner Academy** REVIEW DATE: **5/2/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **58**
MATERIAL DESCRIPTION: **12" x 12" Tan with black and white floor tile**
MATERIAL LOCATION: **Rooms 122, Teacher's Lounge - 1912 Building**
MATERIAL QUANTITY: **325** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

material not observed in room 122

Management Planner's Signature: _____



Date: **05/02/2016**

Chicago Public Schools

Carnow, Conibear and Associates 2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Sumner Academy** INSPECTION DATE: **2/24/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **59**
MATERIAL DESCRIPTION: **Mastic for 12" x 12" Tan with black and white floor tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 122, Teachers Lounge**

MATERIAL QUANTITY: **325**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Not Observed in Room 122**

Inspector's Signature: _____

Date: 02/24/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Sumner Academy** REVIEW DATE: **5/2/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **59**
MATERIAL DESCRIPTION: **Mastic for 12" x 12" Tan with black and white floor tile**
MATERIAL LOCATION: **Rooms 122, Teachers Lounge**
MATERIAL QUANTITY: **325** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

material not observed in room 122

Management Planner's Signature: _____



Date: **05/02/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Sumner Academy** INSPECTION DATE: **2/24/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **60**
MATERIAL DESCRIPTION: **12" x 12" Tan with blue and red floor tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1912 Building Rooms 124, 221 and 1890 Building**

MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not Observed in Room 124**

Inspector's Signature: _____ Date: 02/24/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUILDING ID: **6110**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Sumner Academy** REVIEW DATE: **5/2/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **60**
MATERIAL DESCRIPTION: **12" x 12" Tan with blue and red floor tile**
MATERIAL LOCATION: **1912 Building Rooms 124, 221 and 1890 Building**
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Not Observed in Room 124

Management Planner's Signature: _____



Date: **05/02/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Sumner Academy** INSPECTION DATE: **2/24/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **61**
MATERIAL DESCRIPTION: **Mastic for 12" x 12" tan with blue and red floor tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1912 Building Rooms Room 124, and 221 and 1890 Building room 332**
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS: **Not Observed in Room 124 or Room 332**

Inspector's Signature: _____ Date: 02/24/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUILDING ID: **6110**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Sumner Academy** REVIEW DATE: **5/2/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **61**
MATERIAL DESCRIPTION: **Mastic for 12" x 12" tan with blue and red floor tile**
MATERIAL LOCATION: **1912 Building Rooms Room 124, and 221 and 1890 Building room 332**
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Not Observed in Room 124 or Room 332

Management Planner's Signature: _____



Date: **05/02/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Sumner Academy** INSPECTION DATE: **2/24/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **62**
MATERIAL DESCRIPTION: **12" x 12" Lt gray with white and black floor tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1890 Building Rooms 231, 335**
MATERIAL QUANTITY: **1750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 02/24/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Sumner Academy** REVIEW DATE: **5/2/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **62**
MATERIAL DESCRIPTION: **12" x 12" Lt gray with white and black floor tile**
MATERIAL LOCATION: **1890 Building Rooms 231, 335**
MATERIAL QUANTITY: **1750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/02/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Sumner Academy** INSPECTION DATE: **2/24/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **63**
MATERIAL DESCRIPTION: **Mastic for 12" x 12" Light gray with white and black floor tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1890 Building Rooms 231, 335**

MATERIAL QUANTITY: **1750**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 02/24/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Sumner Academy** REVIEW DATE: **5/2/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **63**
MATERIAL DESCRIPTION: **Mastic for 12" x 12" Light gray with white and black floor tile**
MATERIAL LOCATION: **1890 Building Rooms 231, 335**
MATERIAL QUANTITY: **1750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/02/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Sumner Academy** INSPECTION DATE: **2/24/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **64**
MATERIAL DESCRIPTION: **Black Chalk board Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1890 and 1912 Building classrooms**
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 02/24/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Sumner Academy** REVIEW DATE: **5/2/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **64**
MATERIAL DESCRIPTION: **Black Chalk board Adhesive**
MATERIAL LOCATION: **1890 and 1912 Building classrooms**
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/02/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Sumner Academy** INSPECTION DATE: **2/24/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **65**
MATERIAL DESCRIPTION: **Green Chalk Board Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1966 Building Classrooms**

MATERIAL QUANTITY: **4000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 02/24/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Sumner Academy** REVIEW DATE: **5/2/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **65**
MATERIAL DESCRIPTION: **Green Chalk Board Adhesive**
MATERIAL LOCATION: **1966 Building Classrooms**
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/02/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Sumner Academy** INSPECTION DATE: **2/24/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **66**
MATERIAL DESCRIPTION: **12" x 12" Tan floor tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1966 Building Lunch Room 101 (offices), 102, faculty washroom, 103-107, 109-111, 114-116, PC Lab, 1st floor hallway**

MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **In Annex Report**

Inspector's Signature: _____ Date: 02/24/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Sumner Academy** REVIEW DATE: **5/2/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **66**
MATERIAL DESCRIPTION: **12" x 12" Tan floor tile**
MATERIAL LOCATION: **1966 Building Lunch Room 101 (offices), 102, faculty washroom, 103-107, 109-111, 114-116, PC Lab, 1st floor hallway**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/02/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Sumner Academy** INSPECTION DATE: **2/24/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **67**
MATERIAL DESCRIPTION: **Mastic for 12" x 12" Tan floor tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1966 Building Lunch Room 101 (offices), 102, faculty washroom, 103-107, 109-111, 114-116, PC Lab, 1st floor hallway**

MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **In Annex Report**

Inspector's Signature: _____ Date: 02/24/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Sumner Academy** REVIEW DATE: **5/2/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **67**
MATERIAL DESCRIPTION: **Mastic for 12" x 12" Tan floor tile**
MATERIAL LOCATION: **1966 Building Lunch Room 101 (offices), 102, faculty washroom, 103-107, 109-111, 114-116, PC Lab, 1st floor hallway**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/02/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Sumner Academy** INSPECTION DATE: **2/24/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **68**
MATERIAL DESCRIPTION: **12" x 12" Blue/Green /Purple floor tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1966 Building Room 112**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS: **In Annex Report**

Inspector's Signature: _____ Date: 02/24/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Sumner Academy** REVIEW DATE: **5/2/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **68**
MATERIAL DESCRIPTION: **12" x 12" Blue/Green /Purple floor tile**
MATERIAL LOCATION: **1966 Building Room 112**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/02/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Sumner Academy** INSPECTION DATE: **2/24/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **69**
MATERIAL DESCRIPTION: **Mastic for 12" x 12" Blue/Gree/Purple floor tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1966 Building Room 112**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS: **In Annex Report**

Inspector's Signature: _____ Date: 02/24/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUILDING ID: **6110**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Sumner Academy** REVIEW DATE: **5/2/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **69**

MATERIAL DESCRIPTION: **Mastic for 12" x 12" Blue/Gree/Purple floor tile**

MATERIAL LOCATION: **1966 Building Room 112**

MATERIAL QUANTITY: **800**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/02/2016**

Chicago Public Schools

Carnow, Conibear and Associates 2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Sumner Academy** INSPECTION DATE: **2/24/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **70**
MATERIAL DESCRIPTION: **12" x 12" Red floor tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1966 Building lunch room**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS: **In Annex Report**

Inspector's Signature: _____ Date: 02/24/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Sumner Academy** REVIEW DATE: **5/2/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **70**
MATERIAL DESCRIPTION: **12" x 12" Red floor tile**
MATERIAL LOCATION: **1966 Building lunch room**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/02/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Sumner Academy** INSPECTION DATE: **2/24/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **71**
MATERIAL DESCRIPTION: **Mastic for 12" x 12" Red flor tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1966 Building Lunch Room**

MATERIAL QUANTITY: **400**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **In Annex Report**

Inspector's Signature: _____

Date: 02/24/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Sumner Academy** REVIEW DATE: **5/2/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **71**
MATERIAL DESCRIPTION: **Mastic for 12" x 12" Red flor tile**
MATERIAL LOCATION: **1966 Building Lunch Room**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/02/2016**

Chicago Public Schools

Carnow, Conibear and Associates 2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Sumner Academy** INSPECTION DATE: **2/24/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **72**
MATERIAL DESCRIPTION: **Green Terrazzo**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Enclose**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1966 Building Entrance and stairwells**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS: **In Annex Report**

Inspector's Signature: _____ Date: 02/24/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Sumner Academy** REVIEW DATE: **5/2/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **72**
MATERIAL DESCRIPTION: **Green Terrazzo**
MATERIAL LOCATION: **1966 Building Entrance and stairwells**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Enclose

Comments:

Management Planner's Signature: _____



Date: **05/02/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Sumner Academy** INSPECTION DATE: **2/24/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **A.1**
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Main Entrance, 1890 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____

Date: **02/24/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Sumner Academy** REVIEW DATE: **5/2/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **A.1**
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**
MATERIAL LOCATION: **Main Entrance, 1890 Building**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/02/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUILDING ID: **6110**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Sumner Academy** INSPECTION DATE: **2/24/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **B.1**
MATERIAL DESCRIPTION: **Joint Insulation on Cardboard Insulated Piping**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Main Entrance, 1890 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **02/24/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Sumner Academy** REVIEW DATE: **5/2/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **B.1**

MATERIAL DESCRIPTION: **Joint Insulation on Cardboard Insulated Piping**

MATERIAL LOCATION: **Main Entrance, 1890 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/02/2016** _____

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUILDING ID: **6110**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Sumner Academy** INSPECTION DATE: **2/24/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **C.1**
MATERIAL DESCRIPTION: **Mag Block Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Main Entrance, 1890 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **02/24/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUILDING ID: **6110**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Sumner Academy** REVIEW DATE: **5/2/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **C.1**
MATERIAL DESCRIPTION: **Mag Block Pipe Insulation**
MATERIAL LOCATION: **Main Entrance, 1890 Building**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/02/2016** _____

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Sumner Academy** INSPECTION DATE: **2/24/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **C.2**
MATERIAL DESCRIPTION: **Mag-Block Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Engine Room, 1912 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **02/24/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Sumner Academy** REVIEW DATE: **5/2/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **C.2**
MATERIAL DESCRIPTION: **Mag-Block Pipe Insulation**
MATERIAL LOCATION: **Engine Room, 1912 Building**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/02/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUILDING ID: **6110**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Sumner Academy** INSPECTION DATE: **2/24/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **D.1**
MATERIAL DESCRIPTION: **Joint Insulation on Mag Block Insulated Piping**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Main Entrance, 1890 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **02/24/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUILDING ID: **6110**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Sumner Academy** REVIEW DATE: **5/2/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **D.1**

MATERIAL DESCRIPTION: **Joint Insulation on Mag Block Insulated Piping**

MATERIAL LOCATION: **Main Entrance, 1890 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/02/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Sumner Academy** INSPECTION DATE: **2/24/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **I.1**
MATERIAL DESCRIPTION: **Cardboard Duct Wrap**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Filter Room, 1890 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **02/24/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Sumner Academy** REVIEW DATE: **5/2/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **I.1**

MATERIAL DESCRIPTION: **Cardboard Duct Wrap**

MATERIAL LOCATION: **Filter Room, 1890 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/02/2016** _____

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Sumner Academy** INSPECTION DATE: **2/24/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **J.2**
MATERIAL DESCRIPTION: **Joint Insulation on Mag Block Insulated Piping**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Engine Room, 1912 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____

Date: 02/24/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Sumner Academy** REVIEW DATE: **5/2/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **J.2**

MATERIAL DESCRIPTION: **Joint Insulation on Mag Block Insulated Piping**

MATERIAL LOCATION: **Engine Room, 1912 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/02/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Sumner Academy** INSPECTION DATE: **2/24/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **K.1**
MATERIAL DESCRIPTION: **Joint Insulation on Fiberglass Insulated Piping**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **2nd and 3rd Floor Janitor Closets, 1890 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **02/24/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Sumner Academy** REVIEW DATE: **5/2/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **K.1**
MATERIAL DESCRIPTION: **Joint Insulation on Fiberglass Insulated Piping**
MATERIAL LOCATION: **2nd and 3rd Floor Janitor Closets, 1890 Building**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/02/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUIDLING ID: **6110**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Sumner Academy** INSPECTION DATE: **2/24/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **K.2**
MATERIAL DESCRIPTION: **Joint Insulation on Fiberglass Insulated Piping**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st and 2nd Floor Girl's Washrooms and 1st Floor Boy's Washroom, 1912 building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not Observed 2016**

Inspector's Signature: _____ Date: 02/24/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUILDING ID: **6110**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Sumner Academy** REVIEW DATE: **5/2/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **K.2**
MATERIAL DESCRIPTION: **Joint Insulation on Fiberglass Insulated Piping**
MATERIAL LOCATION: **1st and 2nd Floor Girl's Washrooms and 1st Floor Boy's Washroom, 1912 building**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Not Observed 2016

Management Planner's Signature: _____



Date: **05/02/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUILDING ID: **6110**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Sumner Academy** INSPECTION DATE: **2/24/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **75**
MATERIAL DESCRIPTION: **12' x 12' Floor Tile Mastic**
MATERIAL LOCATION: **Lunchroom**
MATERIAL QUANTITY: **3820** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Not Reachable** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: **02/24/2016**

Chicago Public Schools

Carnow, Conibear and Associates 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUILDING ID: **6110**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Sumner Academy** REVIEW DATE: **5/2/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **75**
MATERIAL DESCRIPTION: **12' x 12' Floor Tile Mastic**
MATERIAL LOCATION: **Lunchroom**
MATERIAL QUANTITY: **3820** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: 05/02/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUILDING ID: **6110**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Sumner Academy** INSPECTION DATE: **2/24/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **73**
MATERIAL DESCRIPTION: **12' x 12' Beige w/ White specs Floor Tiles**
MATERIAL LOCATION: **Lunchroom**
MATERIAL QUANTITY: **2110** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: **02/24/2016**

Chicago Public Schools

Carnow, Conibear and Associates 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUILDING ID: **6110**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Sumner Academy** REVIEW DATE: **5/2/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **73**
MATERIAL DESCRIPTION: **12' x 12' Beige w/ White specs Floor Tiles**
MATERIAL LOCATION: **Lunchroom**
MATERIAL QUANTITY: **2110** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **05/02/2016**

Chicago Public Schools

Carnow, Conibear and Associates 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31221** BUILDING ID: **6110**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Sumner Academy** REVIEW DATE: **5/2/2016**
ADDRESS: **4320 W. Fifth** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **74**
MATERIAL DESCRIPTION: **12' x 12' Red w/ white specs Floor Tiles**
MATERIAL LOCATION: **Lunchroom**
MATERIAL QUANTITY: **1710** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **05/02/2016**

APPENDIX B

Inspector and Management Planner Licenses

2015



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Robert DeBord


has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 12/2/2015


Exam Date: 12/2/2015

Expiration Date: 12/2/2016

Certificate Number: BIR1512024160



Kathy DeSalvo, Director

Robert De Bord
Illinois Licensed Asbestos Inspector, Project Manager, and
Air Sampling Professional

 **ASBESTOS
PROFESSIONAL
LICENSE**

ID NUMBER: **100 - 08864** ISSUED: **5/27/2015** EXPIRES: **05/15/2016**

ROBERT W DE BORD
301 MIAMI ST
PARK FOREST, IL 60466


Environmental Health

ENDORSEMENTS	TC EXPIRES
INSPECTOR	2/13/2016
PROJECT MANAGER AIR SAMPLING PROFESSIONAL	2/12/2016

Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois
Department of Public Health
This license is valid only when accompanied by a valid
training course certificate.

**CARNOW
CONIBEAR**

2015



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Todd Huffer


has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 12/2/2015

Exam Date: 12/2/2015

Expiration Date: 12/2/2016


Certificate Number: BIR1512024161



Kathy DeSalvo, Director


Todd Huffer

Illinois Licensed Asbestos Inspector, Management Planner,
Project Manager, and Air Sampling Professional

 **ASBESTOS
PROFESSIONAL
LICENSE**

ID NUMBER	ISSUED	EXPIRES
100 - 09870	3/16/2015	05/15/2016

TODD T HUFFER
315 HATLEN COURT
MT. PROSPECT, IL 60056



Environmental Health

ENDORSEMENTS	TC EXPIRES
INSPECTOR	12/2/2015
MANAGEMENT PLANNER	2/20/2016
PROJECT MANAGER	12/11/2015
AIR SAMPLING PROFESSIONAL	

Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois
Department of Public Health
This license is valid only when accompanied by a valid
training course certificate.

**CARNOW
CONIBEAR**

2016



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Todd Huffer

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 1/27/2016

Exam Date: 1/27/2016

Expiration Date: 1/27/2017

Certificate Number: MPR1601270318

Kathy DeSalvo, Director

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL		
	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE		
	Loc	Localized
	Dist	Distributed