

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH  
AHERA THREE YEAR REINSPECTION  
ASBESTOS ABATEMENT PROGRAM  
SCHOOL INFORMATION FORM**

**SECTION I**

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299  
SCHOOL ID NUMBER: 14-016-2990-0013  
SCHOOL NAME: Foreman High School  
ADDRESS OF SCHOOL: 3235 N. LeClaire Ave.  
CITY: Chicago, IL, 60641

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **3/25/2013**

**If the address on this form is different than the address of the building, submit a written explanation.**

---

**SECTION II** *(Please type or print)*

**PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:**

DATE REINSPECTION COMPLETED: 5/4/2016 ENROLLMENT 829  
IDPH INSPECTOR LICENSE NUMBER: 100-06327  
IDPH LICENSED INSPECTOR NAME (Please Print): Roberto Rivera  
IDPH MP LICENSE NUMBER: 100-07342  
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Jigar Shah

DESIGNATED PERSON (Please Print): Robert Christlieb PHONE: (773) 553-3197



5/4/2016

*Signature of Designated Person*

*Date*

**SECTION III**

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: \_\_\_\_\_

School has been closed. Date closed: \_\_\_\_\_

School building has been demolished. Date: \_\_\_\_\_

School building is asbestos free since last reinspection: \_\_\_\_\_

**Please explain in writing why the school building is now asbestos free and include the supporting documentation.**

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

**Explain in writing if the address of the building is different than the address on this form:**

---

---

---

**THREE-YEAR REINSPECTION**

**CHICAGO SCHOOL DIST 299**

**Foreman High School**

3235 N. LeClaire Ave.  
Chicago, IL, 60641

Unit: 46131  
Building ID: 1330

IDPH ID Number: 14-016-2990-0013

**REPORT DATE:**

Wednesday, May 04, 2016

**Prepared for:**

**Chicago Public Schools**  
**125 S. Clark Street**  
**Chicago, IL 60603**

**Prepared by:**

**GSG Consultants, Inc.**

855 W. Adams St., Ste. 200

Phone (312) 733-6262

Fax (312) 733-5612

**DO NOT REMOVE FROM SCHOOL  
REQUIRED BY FEDERAL LAW**

March 11, 2016

Mr. R. Kent Cook  
Asbestos Program  
Illinois Department of Public Health  
525 West Jefferson Street  
Springfield, Illinois 62761

Re: Chicago Public Schools - 2016 Three-Year Reinspections

Dear Mr. Cook:

GSG Consultants, Inc., Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 1,2,6 Elementary Schools. Please update your records with the following information.

School District: 299      Unit: 46131      Region: 01      IDPH ID: 14-016-2990-0013

School: Foreman High School      Building ID: 1330

Address: 3235 N. LeClaire Ave.  
Chicago, IL, 60641

Building Contact: Hancock, Ronald      Contact Phone: 773-534-3406

Current Building Owners: Chicago Public Schools

Review Date: 05/04/2016

Inspector: Roberto Rivera      Inspector IDPH License: 100-06327  
Management Planner: Jigar Shah      Management Planner IDPH License: 100-07342

If you have any questions or comments, please contact us at (312) 733-6262

Sincerely,  
GSG Consultants, Inc.



Jigar Shah  
100-07342

## **Environmental Notification to Occupants**

To: Faculty, Staff and Parents  
From: Chicago Public Schools  
Date: March 11, 2016

RE: Foreman High School, Unit 46131  
3235 N. LeClaire Ave.  
Chicago, IL, 60641

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2016 asbestos three year re-inspection has been completed at Foreman High School , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at Foreman High School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Robert Christlieb, the designated Local Education Authority's Designated Person at (773) 553-3197 .

## **Table of Contents**

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

### **APPENDICES:**

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

## SCHOOL AND INSPECTION INFORMATION

### 1. School Information

School: Foreman High School Unit: 46131 Region: 01  
Address: 3235 N. LeClaire Ave. Chicago, IL, 60641  
IDPH ID: 14-016-2990-0013 Building ID: 1330  
Contact: Hancock, Ronald Phone: 773-534-3406

### 2. Description of Facility

Original Construction: Additional Construction:  
Total Square Footage: 13157 No of Floors:  
Current Occupancy: 829

### 3. LEA Designated Person

Contact: Robert Christlieb Phone: (773) 553-3197  
Address: 125 South Clark Street, 17th Floor  
Chicago, IL 60603

### 4. Managing Environmental Consultant

MEC: GSG Consultants, Inc.  
Contact: Arturo Saenz  
Address 855 W. Adams St., Ste. 200  
Phone: (312) 733-6262 Fax: (312) 733-5612

### 5. Inspector

Inspector Name: Roberto Rivera

Inspector IDPH license # 100-06327




Signature:  
Date: 3/11/2016

### 6. Management Planner

Management Planner Name: Jigar Shah

Management Planner IDPH license # 100-07342



Signature:  
Date: 05/04/2016

### 7. Review Date: 05/04/2016

### 8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature: 

Date: 5/4/2016

Name: Robert Christlieb

## II. EXECUTIVE SUMMARY

GSG Consultants, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Foreman High School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 1330:

B. The following new homogenous areas have been identified for Building 1330:



C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

100	12" x 12" Peach w/ Gray Specks VFT
101	12" x 12" Peach w/ Gray Specks VFT Mastic
102	2' x 2' Ceiling Tile
103	2' x 4' White Dot Ceiling Tile
104	1' x 1' White Dot Ceiling Tile
105	Drywall
106	Drywall Joint Compound
107	Beige Linoleum
108	Beige Linoleum Mastic
109	12" x 12" Beige w/Dark Streaks VFT
110	Terrazo
111	Carpet Mastic
112	Textured Ceiling Plaster
113	12"x12" Beige w/Dark Streaks VFT Mastic
114	2'X4' White Grooved Ceiling Tiles
115	12"X12" Gray-Streaked Floor Tiles
115A	12"X12" Gray-Streaked Floor Tiles Mastic
116	12"X12" White w/Gray Streaks VFT
116A	12"X12" White w/Gray Streaks VFT Mastic
117	12"X12" Off-White w/Gray Streaks VFT
117A	12"X12" Off-White w/Gray Streaks VFT Mastic
118	Trowled on Plaster
119	12'X12" White w/Gray Streaks VFT
119A	12'X12" White w/Gray Streaks VFT Mastic
120	2'X2' White Ceiling Tiles
121	Vinyl Baseboard Mastic
122	Fire Doors (2 Each)
123	Blue Linoleum
123A	Blue Linoleum Mastic
124	Pink Linoleum
124A	Pink Linoleum Mastic
125	12"x12" yellow w/ blue and tan streaks VFT
125A	12"x"12 yellow w/ blue and tan streaks VFT mastic
126	Transite fume hood
127	Brown linoleum
127A	Brown linoleum mastic
128	4"x12" ceiling tile w/holes
128A	4"x12" ceiling tile w/ holes mastic
129	heat shields (inside radiator cabinet)
45	12"x12" Blue w/ Gray Streaks VFT
47	9"x9" Green w/ White Streaks VFT Mastic
48	12"x12" Blue w/ Gray Streaks VFT Mastic

53	12"x12" Pink w/ White Streaks VFT
54	12"x12" Pink w/ White Streaks VFT Mastic
65	12"x12" Marble Color VFT
66	12"x12" Marble Color VFT Mastic
67	12"x12" Gray w/ White Specks VFT
68	12"x12" Gray w/ White Specks VFT Mastic
69	12"x12" Brown w/ White & Gray Streaks VFT
70	12"x12" Brown w/ White & Gray Streaks VFT Mastic
74	12"x12" Sand w/ White Streaks VFT Mastic
77	Table Tops
CM-001	Brown Capet Adhesive
FT-001	9" x 9" Green Floor Tile
FTM-001	9" x 9" Green Floor Tile Mastic
TSI-001	MJP E/F/V

The following areas were deemed to be inaccessible:

102	2' x 2' Ceiling Tile
112	Textured Ceiling Plaster
128	4"x12" ceiling tile w/holes
128A	4"x12" ceiling tile w/ holes mastic
129	heat shields (inside radiator cabinet)
13	MJP E/F/V on Fiberglass Pipe Insulation
43	Vibration Joint Material

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Roberto Rivera, IDPH License # 100-06327. The Management Plan was updated by Jigar Shah, IDPH License # 100-07342. Inspector and Management Planner Licenses are included in Appendix B.

### **III. METHODOLOGY**

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

### **IV. ABATEMENT HISTORY**

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

### **V. REASSESSMENTS AND RECOMMENDATIONS**

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

### **VI. CONCLUSIONS**

The Foreman High School Building 1330 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

**Table I**  
**Inspector's Reinspection Findings**

---

# Chicago Public Schools

School Foreman High School Unit 46131 Building ID 1330

Address 3235 N. LeClaire Ave. Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
01	Boiler Gasket #1	4	LF	Boiler Room	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
02	Boiler Gasket #2	4	SF	Boiler Room	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
03	Boiler Gasket #3	4	SF	Boiler Room	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
04	Boiler Gasket #4	4	SF	Boiler Room	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
100	12" x 12" Peach w/ Gray Specks VFT	1,600	SF	Room 322, 318	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
101	12" x 12" Peach w/ Gray Specks VFT Mastic	1,600	SF	Room 322, 318	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
102	2' x 2' Ceiling Tile	800	SF	Room 225	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
103	2' x 4' White Dot Ceiling Tile	5,500	SF	Boys Lockerroom, Room 122, 124, 125, 126, 127, 130, 216, 222B, 326, 328	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
104	1' x 1' White Dot Ceiling Tile	5,800	SF	Lunchroom, Serving Area	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
105	Drywall	4,500	SF	Room 124, 126, 228, 306	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
106	Drywall Joint Compound	1,200	SF	Room 124, 126, 228, 306	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
107	Beige Linoleum	1,200	SF	Room 225 & office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
108	Beige Linoleum Mastic	1,200	SF	Room 225 & office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
109	12" x 12" Beige w/Dark Streaks VFT	1,500	SF	Rooms 100, 102, 104	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
110	Terrazo	9,500	SF	All Stairwells and Corridors, kitchen, lunchroom, dish washer room, bakery storage rm, aud. vestibule, aud. stage stairs	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
111	Carpet Mastic	7,000	SF	Rooms: 110, 112, 123, 129, 3rd fl. women's washroom, 208, 206, 222 A, 229, 234, 304	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
112	Textured Ceiling Plaster	1,500	SF	Library	ASSUMED	SURFACE	Y	NONE	0		No	ACBM with the potential for damage		LOW

# Chicago Public Schools

School Foreman High School Unit 46131 Building ID 1330

Address 3235 N. LeClaire Ave. Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
113	12"x12" Beige w/Dark Streaks VFT Mastic	1,500	SF	Rooms 100, 102, 104	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
114	2'X4' White Grooved Ceiling Tiles	800	SF	Main Office Area, Principal's Office	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
115	12"X12" Gray-Streaked Floor Tiles	3,000	SF	Rms 111, 113, 115/117	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
115A	12"X12" Gray-Streaked Floor Tiles Mastic	3,000	SF	Rms 111, 113, 115/117	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
116	12"X12" White w/Gray Streaks VFT	4,000	SF	Auditorium	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
116A	12"X12" White w/Gray Streaks VFT Mastic	4,000	SF	Auditorium	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
117	12"X12" Off-White w/Gray Streaks VFT	2,250	SF	Rms 125, 127, 224	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
117A	12"X12" Off-White w/Gray Streaks VFT Mastic	2,250	SF	Rms 125, 127, 224	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
118	Trowled on Plaster	5,000	SF	Auditorium	ASSUMED	SURFACE	N	NONE	0		No	ACBM with the potential for damage		LOW
119	12"X12" White w/Gray Streaks VFT	6,000	SF	Throughout All Classrooms and Hallways in Both 2003 Mobile Units	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
119A	12"X12" White w/Gray Streaks VFT Mastic	6,000	SF	Throughout All Classrooms and Hallways in Both 2003 Mobile Units	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
120	2'X2' White Ceiling Tiles	6,000	SF	Throughout All Classrooms and Hallways in Both 2003 Mobile Units	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
121	Vinyl Baseboard Mastic	1,200	SF	Throughout Both 2003 Mobile Units	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
122	Fire Doors (2 Each)	4	EA	Mechanical Rooms in Both 2003 Mobile Units	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
123	Blue Linoleum	200	SF	Boys Restrooms in Both 2003 Mobile Units	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
123A	Blue Linoleum Mastic	200	SF	Boys Restrooms in Both 2003 Mobile Units	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
124	Pink Linoleum	200	SF	Girls Toilets in Both 2003 Mobile Units	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
124A	Pink Linoleum Mastic	200	SF	Girls Toilets in Both	ASSUMED	MISC	N	NONE	0		No	ACBM with the		LOW



# Chicago Public Schools

School Foreman High School Unit 46131 Building ID 1330

Address 3235 N. LeClaire Ave. Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				vault & teacher's office, 319, vault & teacher's office, 321 and Vault, 322										
52	Gray w/ Blue Streaks Linoleum Mastic	0		Room 209, 317, vault & teacher's office, 319, vault & teacher's office, 321 and Vault, 322	NO_ACBM									
53	12"x12" Pink w/ White Streaks VFT	1,500	SF	Third Floor Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
54	12"x12" Pink w/ White Streaks VFT Mastic	1,500	SF	Third Floor Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
55	9"x9" Green w/ Gray Streaks VFT	1,440	SF	Rooms 312 & 314	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
56	9"x9" Green w/ Gray Streaks VFT Mastic	1,440	SF	Rooms 312 & 314	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
57	12"x12" Off White w/ Gray Streaks VFT	3,700	SF	Rooms 122, 124, 126, 123 A (under carpet), 123 B (under carpet)	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
58	12"x12" Off White w/ Gray Streaks VFT Mastic	3,700	SF	Rooms 122, 124, 126, 123 A (Under Carpet), 123 B (Under Carpet)	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
59	9"x9" Gray w/ White & Black Streaks VFT	9,999	SF	1st and 2nd Floor Hall, Engineer's Office & Closet, Vault, Rm 128/130, Rm 112 (under carpet), 112 offices	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
60	9"x9" Gray w/ White & Black Streaks VFT Mastic	9,999	SF	1st and 2nd Floor Hall, Engineer's Office & Closet, Vault, Rm 128/130, Rm 112 (under carpet), 112 offices	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
61	9" x 9" Gray w/ Pink, White, & Black Streaks VFT	1,550	SF	Room 211, 213/215	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
62	9" x 9" Gray w/ Pink, White, & Black Streaks VFT	1,550	SF	Room 211, 213/215	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
63	12"x12" Brown w/ White & Black Streaks VFT	1,200	SF	Rooms 218/ 220	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
64	12"x12" Brown w/ White & Black Streaks	1,200	SF	Rooms 218/ 220	CHR	MISC	N	NONE	0		No	ACBM with the		LOW



# Chicago Public Schools

School Foreman High School Unit 46131 Building ID 1330

Address 3235 N. LeClaire Ave. Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
	VFT Mastic											potential for damage		
65	12"x12" Marble Color VFT	1,200	SF	Rooms 217/219	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
66	12"x12" Marble Color VFT Mastic	1,200	SF	Rooms 217/ 219	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
67	12"x12" Gray w/ White Specks VFT	40	SF	Room 221 vault	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
68	12"x12" Gray w/ White Specks VFT Mastic	40	SF	Room 221 vault	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
69	12"x12" Brown w/ White & Gray Streaks VFT	700	SF	Room 225 (Under HA 107)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
70	12"x12" Brown w/ White & Gray Streaks VFT Mastic	700	SF	Room 225 (Under HA 107)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
71	1'x2' Black VFT	120	SF	Room 128, 129 (Under Carpet)	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
72	1'x2' Black VFT Mastic	120	SF	Room 128, 129 (Under Carpet)	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
73	12"x12" Sand w/ White Streaks VFT	880	SF	Main Office & Principal's Office	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
74	12"x12" Sand w/ White Streaks VFT Mastic	880	SF	Main Office & Principal's Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
75	1'x1' White Wormy Ceiling Tile	0		Lunchroom, Room 329 & Vestibule, 330 & vestibule, 125	NO_ACBM									
76	1'x1' White Wormy Ceiling Tile Mastic	0		Lunchroom, Room 329 & Vestibule, 330 & vestibule, 125	NO_ACBM									
77	Table Tops	2,500	SF	Room 317, 318, 321, 322, 319 vault and teacher's office, 209, 217/219, 221/223 and office and vault	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
98	Interior Window Caulk	0		Interior Windows	NO_ACBM									
99	Exterior Window Caulk	1,000	LF	Exterior Windows	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
CM-001	Brown Capet Adhesive	350	SF	Room 129	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FT-001	9" x 9" Green Floor Tile	350	SF	Room 128	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
FTM-001	9" x 9" Green Floor Tile Mastic	350	SF	Room 128	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
TSI-001	MJP E/F/V	100	LF	Boiler Room	ASSUMED	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW

# Chicago Public Schools

School Foreman High School Unit 46131 Building ID 1330

Address 3235 N. LeClaire Ave. Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

*Inspector's Comments are Summarized at the End of the Report*

Reinspection Date <b>3/11/2016</b>
Inspector Name <b>Roberto Rivera</b>
<b>100-06327</b> <b>1/6/2017</b>
Inspector's IDPH License Number / Expiration Date

### Inspector's Comments

HA Number:	Inspector Comments:
01	
02	
03	
04	
100	
101	
102	
103	
104	
105	
106	
107	
108	
109	
110	
111	
112	
113	
114	
115	
115A	
116	
116A	
117	

# Chicago Public Schools

School Foreman High School Unit 46131 Building ID 1330

Address 3235 N. LeClaire Ave. Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
117A	
118	
119	
119A	
120	
121	
122	
123	
123A	
124	
124A	
125	
125A	
126	
127	
127A	
128	
128A	
129	
13	
43	
44	
45	
46	
47	
48	
50	
51	
52	

# Chicago Public Schools

School Foreman High School Unit 46131 Building ID 1330

Address 3235 N. LeClaire Ave. Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
53	
54	
55	
56	
57	
58	
59	
60	
61	
62	
63	
64	
65	
66	
67	
68	
69	
70	
71	
72	
73	
74	
75	
76	
77	
98	
99	
CM-001	
FT-001	

# Chicago Public Schools

**School** Foreman High School **Unit** 46131 **Building ID** 1330

**Address** 3235 N. LeClaire Ave. **Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
FTM-001	
TSI-001	

**Table II**

**Management Planner's Review**

---

# Chicago Public Schools

School Foreman High School

Unit 46131

Building ID 1330

Address 3235 N. LeClaire Ave.

Chicago, IL, 60641

Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
01	Boiler Gasket #1	4	LF	Boiler Room	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
02	Boiler Gasket #2	4	SF	Boiler Room	Chrysotile	TSI	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
03	Boiler Gasket #3	4	SF	Boiler Room	Chrysotile	TSI	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
04	Boiler Gasket #4	4	SF	Boiler Room	Chrysotile	TSI	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
100	12" x 12" Peach w/ Gray Specks VFT	1,600	SF	Room 322, 318	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
101	12" x 12" Peach w/ Gray Specks VFT Mastic	1,600	SF	Room 322, 318	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
102	2' x 2' Ceiling Tile	800	SF	Room 225	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
103	2' x 4' White Dot Ceiling Tile	5,500	SF	Boys Lockerroom, Room 122, 124, 125, 126, 127, 130, 216, 222B, 326, 328	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
104	1' x 1' White Dot Ceiling Tile	5,800	SF	Lunchroom, Serving Area	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
105	Drywall	4,500	SF	Room 124, 126, 228, 306	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
106	Drywall Joint Compound	1,200	SF	Room 124, 126, 228, 306	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
107	Beige Linoleum	1,200	SF	Room 225 & office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
108	Beige Linoleum Mastic	1,200	SF	Room 225 & office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
109	12" x 12" Beige w/Dark Streaks VFT	1,500	SF	Rooms 100, 102, 104	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
110	Terrazo	9,500	SF	All Stairwells and Corridors, kitchen, lunchroom, dish washer room, bakery storage rm, aud. vestibule, aud. stage stairs	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
111	Carpet Mastic	7,000	SF	Rooms:110, 112, 123, 129, 3rd fl. women's washroom, 208, 206, 222 A, 229, 234, 304	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
112	Textured Ceiling Plaster	1,500	SF	Library	Assumed	SURFACE	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
113	12"x12" Beige w/Dark Streaks VFT Mastic	1,500	SF	Rooms 100, 102, 104	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
114	2'X4' White Grooved Ceiling Tiles	800	SF	Main Office Area, Principal's Office	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
115	12"X12" Gray-Streaked Floor Tiles	3,000	SF	Rms 111, 113, 115/117	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
115A	12"X12" Gray-Streaked Floor Tiles Mastic	3,000	SF	Rms 111, 113, 115/117	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
116	12"X12" White w/Gray Streaks VFT	4,000	SF	Auditorium	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
116A	12"X12" White w/Gray Streaks VFT Mastic	4,000	SF	Auditorium	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
117	12"X12" Off-White w/Gray Streaks VFT	2,250	SF	Rms 125, 127, 224	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
117A	12"X12" Off-White w/Gray Streaks VFT Mastic	2,250	SF	Rms 125, 127, 224	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
118	Trowled on Plaster	5,000	SF	Auditorium	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
119	12"X12" White w/Gray Streaks VFT	6,000	SF	Throughout All Classrooms and Hallways in Both 2003 Mobile Units	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
119A	12"X12" White w/Gray Streaks VFT Mastic	6,000	SF	Throughout All Classrooms and	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Foreman High School  
**Address** 3235 N. LeClaire Ave.

**Unit** 46131  
Chicago, IL, 60641

**Building ID** 1330  
**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				Hallways in Both 2003 Mobile Units							
120	2'X2' White Ceiling Tiles	6,000	SF	Throughout All Classrooms and Hallways in Both 2003 Mobile Units	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
121	Vinyl Baseboard Mastic	1,200	SF	Throughout Both 2003 Mobile Units	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
122	Fire Doors (2 Each)	4	EA	Mechanical Rooms in Both 2003 Mobile Units	Assumed	MISC	No	0	EA	6 ACBM with the potential for damage	Follow O&M Plan
123	Blue Linoleum	200	SF	Boys Restrooms in Both 2003 Mobile Units	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
123A	Blue Linoleum Mastic	200	SF	Boys Restrooms in Both 2003 Mobile Units	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
124	Pink Linoleum	200	SF	Girls Toilets in Both 2003 Mobile Units	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
124A	Pink Linoleum Mastic	200	SF	Girls Toilets in Both 2003 Mobile Units	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
125	12"x12" yellow w/ blue and tan streaks VFT	1,600	SF	Rm 221/223 & teacher's office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
125A	12"x12" yellow w/ blue and tan streaks VFT mastic	1,600	SF	room 221/223 & teacher's office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
126	Transite fume hood	80	SF	Rm 221/223	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
127	Brown linoleum	200	SF	2nd fl. storage room by police dept. office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
127A	Brown linoleum mastic	200	SF	2nd fl. storage room by police dept. office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
128	4"x12" ceiling tile w/holes	4,500	SF	Auditorium, storage and balcony, library	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
128A	4"x12" ceiling tile w/ holes mastic	4,500	SF	auditorium & storage & balcony, library	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
129	heat shields (inside radiator cabinet)	50	SF	Rm 112	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
13	MJP E/F/V on Fiberglass Pipe Insulation	500	LF	All Toilet Pipe Chases & Room 217, 121	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
43	Vibration Joint Material	20	SF	Basement & NW Fan Room	Chrysotile	TSI	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
44	9"x9" Green w/ White Streaks VFT	9,095	SF	1st and 2nd Floor Corridor, Library, & Engineer's Office and Closet, rm 112 (under carpet), 112 offices	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
45	12"x12" Blue w/ Gray Streaks VFT	7,500	SF	3rd Floor Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
46	Brown w/ White Streaks Linoleum	0		Room 101A	No ACBM						
47	9"x9" Green w/ White Streaks VFT Mastic	9,095	SF	1st and 2nd Floor Corridor, Library, & Engineer's Office and Closet, Rm 112 (under carpet), 112 offices	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
48	12"x12" Blue w/ Gray Streaks VFT Mastic	7,500	SF	3rd Floor Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
50	Brown w/ White Streaks Linoleum Mastic	0		Room 101A	No ACBM						
51	Gray w/ Blue Streaks Linoleum	0		Room 209, 317, vault & teacher's	No ACBM						



# Chicago Public Schools

School Foreman High School

Unit 46131

Building ID 1330

Address 3235 N. LeClaire Ave.

Chicago, IL, 60641

Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				office, 319, vault & teacher's office, 321 and Vault, 322							
52	Gray w/ Blue Streaks Linoleum Mastic	0		Room 209, 317, vault & teacher's office, 319, vault & teacher's office, 321 and Vault, 322	No ACBM						
53	12"x12" Pink w/ White Streaks VFT	1,500	SF	Third Floor Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
54	12"x12" Pink w/ White Streaks VFT Mastic	1,500	SF	Third Floor Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
55	9"x9" Green w/ Gray Streaks VFT	1,440	SF	Rooms 312 & 314	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
56	9"x9" Green w/ Gray Streaks VFT Mastic	1,440	SF	Rooms 312 & 314	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
57	12"x12" Off White w/ Gray Streaks VFT	3,700	SF	Rooms 122, 124, 126, 123 A (under carpet), 123 B (under carpet)	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
58	12"x12" Off White w/ Gray Streaks VFT Mastic	3,700	SF	Rooms 122, 124, 126, 123 A (Under Carpet), 123 B (Under Carpet)	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
59	9"x9" Gray w/ White & Black Streaks VFT	9,999	SF	1st and 2nd Floor Hall, Engineer's Office & Closet, Vault, Rm 128/130, Rm 112 (under carpet), 112 offices	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
60	9"x9" Gray w/ White & Black Streaks VFT Mastic	9,999	SF	1st and 2nd Floor Hall, Engineer's Office & Closet, Vault, Rm 128/130, Rm 112 (under carpet), 112 offices	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
61	9" x 9" Gray w/ Pink, White, & Black Streaks VFT	1,550	SF	Room 211, 213/215	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
62	9" x 9" Gray w/ Pink, White, & Black Streaks VFT	1,550	SF	Room 211, 213/215	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
63	12"x12" Brown w/ White & Black Streaks VFT	1,200	SF	Rooms 218/ 220	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
64	12"x12" Brown w/ White & Black Streaks VFT Mastic	1,200	SF	Rooms 218/ 220	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
65	12"x12" Marble Color VFT	1,200	SF	Rooms 217/219	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
66	12"x12" Marble Color VFT Mastic	1,200	SF	Rooms 217/ 219	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
67	12"x12" Gray w/ White Specks VFT	40	SF	Room 221 vault	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
68	12"x12" Gray w/ White Specks VFT Mastic	40	SF	Room 221 vault	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
69	12"x12" Brown w/ White & Gray Streaks VFT	700	SF	Room 225 (Under HA 107)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
70	12"x12" Brown w/ White & Gray Streaks VFT Mastic	700	SF	Room 225 (Under HA 107)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
71	1'x2' Black VFT	120	SF	Room 128, 129 (Under Carpet)	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
72	1'x2' Black VFT Mastic	120	SF	Room 128, 129 (Under Carpet)	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
73	12"x12" Sand w/ White Streaks VFT	880	SF	Main Office & Principal's Office	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
74	12"x12" Sand w/ White Streaks VFT Mastic	880	SF	Main Office & Principal's Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
75	1'x1' White Wormy Ceiling Tile	0		Lunchroom, Room 329 & Vestibule,	No ACBM						

# Chicago Public Schools

**School** Foreman High School  
**Address** 3235 N. LeClaire Ave.

**Unit** 46131  
 Chicago, IL, 60641

**Building ID** 1330  
**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

### *Management Planner's Comments Summarized at the End of the Report*

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
76	1'x1' White Wormy Ceiling Tile Mastic	0		330 & vestibule, 125 Lunchroom, Room 329 & Vestibule, 330 & vestibule, 125	No ACBM						
77	Table Tops	2,500	SF	Room 317, 318, 321, 322, 319 vault and teacher's office, 209, 217/219, 221/223 and office and vault	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
98	Interior Window Caulk	0		Interior Windows	No ACBM						
99	Exterior Window Caulk	1,000	LF	Exterior Windows	Chrysotile	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
CM-001	Brown Capet Adhesive	350	SF	Room 129	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FT-001	9" x 9" Green Floor Tile	350	SF	Room 128	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FTM-001	9" x 9" Green Floor Tile Mastic	350	SF	Room 128	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
TSI-001	MJP E/F/V	100	LF	Boiler Room	Assumed	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Foreman High School  
**Address** 3235 N. LeClaire Ave.

**Unit** 46131  
 Chicago, IL, 60641

**Building ID** 1330  
**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

### *Management Planner's Comments Summarized at the End of the Report*

Review Date	5/4/2016
Manager Planner Name	Jigar Shah
100-07342	1/19/2017
Manager IDPH License No/Expiration	

HA Number	Management Comments
01	
02	
03	
04	
100	
101	
102	
103	
104	
105	
106	
107	
108	
109	
110	
111	
112	
113	
114	
115	
115A	
116	
116A	
117	

# Chicago Public Schools

**School** Foreman High School  
**Address** 3235 N. LeClaire Ave.

**Unit** 46131  
 Chicago, IL, 60641

**Building ID** 1330  
**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
117A	
118	
119	
119A	
120	
121	
122	
123	
123A	
124	
124A	
125	
125A	
126	
127	
127A	
128	
128A	
129	
13	
43	
44	
45	
46	
47	
48	
50	

# Chicago Public Schools

**School** Foreman High School  
**Address** 3235 N. LeClaire Ave.

**Unit** 46131  
Chicago, IL, 60641

**Building ID** 1330  
**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
51	
52	
53	
54	
55	
56	
57	
58	
59	
60	
61	
62	
63	
64	
65	
66	
67	
68	
69	
70	
71	
72	
73	
74	
75	
76	
77	

# Chicago Public Schools

**School** Foreman High School

**Unit** 46131

**Building ID** 1330

**Address** 3235 N. LeClaire Ave.

Chicago, IL, 60641

**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
98	
99	
CM-001	
FT-001	
FTM-001	
TSI-001	

# Chicago Public Schools

GSG Consultants, Inc.

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Foreman High School** INSPECTION DATE: **3/11/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **01**  
MATERIAL DESCRIPTION: **Boiler Gasket #1**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: **4**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **03/11/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUILDING ID: **1330**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Foreman High School** REVIEW DATE: **5/4/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **01**  
MATERIAL DESCRIPTION: **Boiler Gasket #1**  
MATERIAL LOCATION: **Boiler Room**  
MATERIAL QUANTITY: **4** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jigar Shah*

Date: **05/04/2016**



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Foreman High School** INSPECTION DATE: **3/11/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **02**  
MATERIAL DESCRIPTION: **Boiler Gasket #2**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Boiler Room**  
MATERIAL QUANTITY: **4** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Roberto Rivera*

Date: 03/11/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Foreman High School** REVIEW DATE: **5/4/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **02**  
MATERIAL DESCRIPTION: **Boiler Gasket #2**  
MATERIAL LOCATION: **Boiler Room**  
MATERIAL QUANTITY: **4** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jigar Shah*

Date: **05/04/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Foreman High School** INSPECTION DATE: **3/11/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **03**  
MATERIAL DESCRIPTION: **Boiler Gasket #3**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Boiler Room**  
MATERIAL QUANTITY: **4** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: *Roberto Rivera*

Date: 03/11/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUILDING ID: **1330**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Foreman High School** REVIEW DATE: **5/4/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **03**  
MATERIAL DESCRIPTION: **Boiler Gasket #3**  
MATERIAL LOCATION: **Boiler Room**  
MATERIAL QUANTITY: **4** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jigar Shah*

Date: **05/04/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Foreman High School** INSPECTION DATE: **3/11/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **04**  
MATERIAL DESCRIPTION: **Boiler Gasket #4**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Boiler Room**  
MATERIAL QUANTITY: **4** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Roberto Rivera*

Date: 03/11/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUILDING ID: **1330**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Foreman High School** REVIEW DATE: **5/4/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **04**  
MATERIAL DESCRIPTION: **Boiler Gasket #4**  
MATERIAL LOCATION: **Boiler Room**  
MATERIAL QUANTITY: **4** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jigar Shah*

Date: **05/04/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 46131    BUILDING ID: 1330  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Roberto Rivera  
SCHOOL NAME: Foreman High School    INSPECTION DATE: 3/11/2016  
ADDRESS: 3235 N. LeClaire Ave.    IDPH LICENSE NO: 100-06327

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 100  
MATERIAL DESCRIPTION: 12" x 12" Peach w/ Gray Specks VFT  
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed    FRIABLE: No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: MODERATE  
MATERIAL LOCATION: Room 322, 318  
MATERIAL QUANTITY: 1600    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF  
COMMENTS:

Inspector's Signature: Roberto Rivera

Date: 03/11/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUILDING ID: **1330**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Foreman High School** REVIEW DATE: **5/4/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **100**  
MATERIAL DESCRIPTION: **12" x 12" Peach w/ Gray Specks VFT**  
MATERIAL LOCATION: **Room 322, 318**  
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jigar Shah*

Date: **05/04/2016**



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Foreman High School** INSPECTION DATE: **3/11/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **101**  
MATERIAL DESCRIPTION: **12" x 12" Peach w/ Gray Specks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 322, 318**  
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Roberto Rivera*

Date: 03/11/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Foreman High School** REVIEW DATE: **5/4/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **101**  
MATERIAL DESCRIPTION: **12" x 12" Peach w/ Gray Specks VFT Mastic**  
MATERIAL LOCATION: **Room 322, 318**  
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/04/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Foreman High School** INSPECTION DATE: **3/11/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **102**  
MATERIAL DESCRIPTION: **2' x 2' Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 225**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: *Roberto Rivera*

Date: 03/11/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUILDING ID: **1330**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Foreman High School** REVIEW DATE: **5/4/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **102**  
MATERIAL DESCRIPTION: **2' x 2' Ceiling Tile**  
MATERIAL LOCATION: **Room 225**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jigar Shah*

Date: **05/04/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Foreman High School** INSPECTION DATE: **3/11/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **103**  
MATERIAL DESCRIPTION: **2' x 4' White Dot Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Boys Lockerroom, Room 122, 124, 125, 126, 127, 130, 216, 222B, 326, 328**  
MATERIAL QUANTITY: **5500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/11/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUILDING ID: **1330**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Foreman High School** REVIEW DATE: **5/4/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **103**  
MATERIAL DESCRIPTION: **2' x 4' White Dot Ceiling Tile**  
MATERIAL LOCATION: **Boys Lockerroom, Room 122, 124, 125, 126, 127, 130, 216, 222B, 326, 328**  
MATERIAL QUANTITY: **5500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jigar Shah*

Date: **05/04/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Foreman High School** INSPECTION DATE: **3/11/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **104**  
MATERIAL DESCRIPTION: **1' x 1' White Dot Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Lunchroom, Serving Area**  
MATERIAL QUANTITY: **5800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/11/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Foreman High School** REVIEW DATE: **5/4/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **104**  
MATERIAL DESCRIPTION: **1' x 1' White Dot Ceiling Tile**  
MATERIAL LOCATION: **Lunchroom, Serving Area**  
MATERIAL QUANTITY: **5800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jigar Shah*

Date: **05/04/2016**



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Foreman High School** INSPECTION DATE: **3/11/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **105**  
MATERIAL DESCRIPTION: **Drywall**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 124, 126, 228, 306**  
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Roberto Rivera*

Date: 03/11/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUILDING ID: **1330**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Foreman High School** REVIEW DATE: **5/4/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **105**  
MATERIAL DESCRIPTION: **Drywall**  
MATERIAL LOCATION: **Room 124, 126, 228, 306**  
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/04/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Foreman High School** INSPECTION DATE: **3/11/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **106**  
MATERIAL DESCRIPTION: **Drywall Joint Compound**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 124, 126, 228, 306**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/11/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Foreman High School** REVIEW DATE: **5/4/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **106**  
MATERIAL DESCRIPTION: **Drywall Joint Compound**  
MATERIAL LOCATION: **Room 124, 126, 228, 306**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **05/04/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Foreman High School** INSPECTION DATE: **3/11/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **107**  
MATERIAL DESCRIPTION: **Beige Linoleum**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Room 225 & office**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Roberto Rivera*

Date: 03/11/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Foreman High School** REVIEW DATE: **5/4/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **107**  
MATERIAL DESCRIPTION: **Beige Linoleum**  
MATERIAL LOCATION: **Room 225 & office**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jigar Shah*

Date: **05/04/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Foreman High School** INSPECTION DATE: **3/11/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **108**  
MATERIAL DESCRIPTION: **Beige Linoleum Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 225 & office**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/11/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUILDING ID: **1330**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Foreman High School** REVIEW DATE: **5/4/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **108**  
MATERIAL DESCRIPTION: **Beige Linoleum Mastic**  
MATERIAL LOCATION: **Room 225 & office**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/04/2016**



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Foreman High School** INSPECTION DATE: **3/11/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **109**  
MATERIAL DESCRIPTION: **12" x 12" Beige w/Dark Streaks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Rooms 100, 102, 104**

MATERIAL QUANTITY: **1500**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Roberto Rivera*

Date: 03/11/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUILDING ID: **1330**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Foreman High School** REVIEW DATE: **5/4/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **109**  
MATERIAL DESCRIPTION: **12" x 12" Beige w/Dark Streaks VFT**  
MATERIAL LOCATION: **Rooms 100, 102, 104**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jigar Shah*

Date: **05/04/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Foreman High School** INSPECTION DATE: **3/11/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **110**  
MATERIAL DESCRIPTION: **Terrazo**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **All Stairwells and Corridors, kitchen, lunchroom, dish washer room, bakery storage rm, aud. vestibule, aud. stage stairs**

MATERIAL QUANTITY: **9500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: 

Date: 03/11/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUILDING ID: **1330**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Foreman High School** REVIEW DATE: **5/4/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **110**  
MATERIAL DESCRIPTION: **Terrazo**  
MATERIAL LOCATION: **All Stairwells and Corridors, kitchen, lunchroom, dish washer room, bakery storage rm, aud. vestibule, aud. stage stairs**  
MATERIAL QUANTITY: **9500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/04/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Foreman High School** INSPECTION DATE: **3/11/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **111**  
MATERIAL DESCRIPTION: **Carpet Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms:110, 112, 123, 129, 3rd fl. women's washroom, 208, 206, 222 A, 229, 234, 304**

MATERIAL QUANTITY: **7000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Roberto Rivera*

Date: 03/11/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUILDING ID: **1330**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Foreman High School** REVIEW DATE: **5/4/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **111**  
MATERIAL DESCRIPTION: **Carpet Mastic**  
MATERIAL LOCATION: **Rooms:110, 112, 123, 129, 3rd fl. women's washroom, 208, 206, 222 A, 229, 234, 304**  
MATERIAL QUANTITY: **7000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jigar Shah*

Date: **05/04/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Foreman High School** INSPECTION DATE: **3/11/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **112**  
MATERIAL DESCRIPTION: **Textured Ceiling Plaster**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Library**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: *Roberto Rivera*

Date: 03/11/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUILDING ID: **1330**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Foreman High School** REVIEW DATE: **5/4/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **112**  
MATERIAL DESCRIPTION: **Textured Ceiling Plaster**  
MATERIAL LOCATION: **Library**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jigar Shah*

Date: **05/04/2016**



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Foreman High School** INSPECTION DATE: **3/11/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **113**  
MATERIAL DESCRIPTION: **12"x12" Beige w/Dark Streaks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 100, 102, 104**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: *Roberto Rivera*

Date: 03/11/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Foreman High School** REVIEW DATE: **5/4/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **113**  
MATERIAL DESCRIPTION: **12"x12" Beige w/Dark Streaks VFT Mastic**  
MATERIAL LOCATION: **Rooms 100, 102, 104**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jigar Shah*

Date: **05/04/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Foreman High School** INSPECTION DATE: **3/11/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **114**  
MATERIAL DESCRIPTION: **2'X4' White Grooved Ceiling Tiles**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Main Office Area, Principal's Office**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/11/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Foreman High School** REVIEW DATE: **5/4/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **114**  
MATERIAL DESCRIPTION: **2'X4' White Grooved Ceiling Tiles**  
MATERIAL LOCATION: **Main Office Area, Principal's Office**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jigar Shah*

Date: **05/04/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Foreman High School** INSPECTION DATE: **3/11/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **115**  
MATERIAL DESCRIPTION: **12"X12" Gray-Streaked Floor Tiles**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Rms 111, 113, 115/117**  
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Roberto Rivera*

Date: 03/11/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Foreman High School** REVIEW DATE: **5/4/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **115**  
MATERIAL DESCRIPTION: **12"X12" Gray-Streaked Floor Tiles**  
MATERIAL LOCATION: **Rms 111, 113, 115/117**  
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jigar Shah*

Date: **05/04/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Foreman High School** INSPECTION DATE: **3/11/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **115A**  
MATERIAL DESCRIPTION: **12"X12" Gray-Streaked Floor Tiles Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rms 111, 113, 115/117**  
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/11/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Foreman High School** REVIEW DATE: **5/4/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **115A**  
MATERIAL DESCRIPTION: **12"X12" Gray-Streaked Floor Tiles Mastic**  
MATERIAL LOCATION: **Rms 111, 113, 115/117**  
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/04/2016**



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Foreman High School** INSPECTION DATE: **3/11/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **116**  
MATERIAL DESCRIPTION: **12"X12" White w/Gray Streaks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Auditorium**

MATERIAL QUANTITY: **4000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/11/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Foreman High School** REVIEW DATE: **5/4/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **116**  
MATERIAL DESCRIPTION: **12"X12" White w/Gray Streaks VFT**  
MATERIAL LOCATION: **Auditorium**  
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jigar Shah*

Date: **05/04/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Foreman High School** INSPECTION DATE: **3/11/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **116A**  
MATERIAL DESCRIPTION: **12"X12" White w/Gray Streaks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Auditorium**  
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: *Roberto Rivera*

Date: 03/11/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Foreman High School** REVIEW DATE: **5/4/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **116A**  
MATERIAL DESCRIPTION: **12"X12" White w/Gray Streaks VFT Mastic**  
MATERIAL LOCATION: **Auditorium**  
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **05/04/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Foreman High School** INSPECTION DATE: **3/11/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **117**  
MATERIAL DESCRIPTION: **12"X12" Off-White w/Gray Streaks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Rms 125, 127, 224**  
MATERIAL QUANTITY: **2250** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Roberto Rivera*

Date: 03/11/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Foreman High School** REVIEW DATE: **5/4/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **117**  
MATERIAL DESCRIPTION: **12"X12" Off-White w/Gray Streaks VFT**  
MATERIAL LOCATION: **Rms 125, 127, 224**  
MATERIAL QUANTITY: **2250** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **05/04/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Foreman High School** INSPECTION DATE: **3/11/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **117A**  
MATERIAL DESCRIPTION: **12"X12" Off-White w/Gray Streaks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rms 125, 127, 224**  
MATERIAL QUANTITY: **2250** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/11/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Foreman High School** REVIEW DATE: **5/4/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **117A**  
MATERIAL DESCRIPTION: **12"X12" Off-White w/Gray Streaks VFT Mastic**  
MATERIAL LOCATION: **Rms 125, 127, 224**  
MATERIAL QUANTITY: **2250** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/04/2016**



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Foreman High School** INSPECTION DATE: **3/11/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **118**  
MATERIAL DESCRIPTION: **Trowled on Plaster**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Auditorium**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/11/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Foreman High School** REVIEW DATE: **5/4/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **118**  
MATERIAL DESCRIPTION: **Trowled on Plaster**  
MATERIAL LOCATION: **Auditorium**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jigar Shah*

Date: **05/04/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Foreman High School** INSPECTION DATE: **3/11/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **119**  
MATERIAL DESCRIPTION: **12'X12" White w/Gray Streaks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Throughout All Classrooms and Hallways in Both 2003 Mobile Units**  
MATERIAL QUANTITY: **6000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/11/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Foreman High School** REVIEW DATE: **5/4/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **119**  
MATERIAL DESCRIPTION: **12'X12" White w/Gray Streaks VFT**  
MATERIAL LOCATION: **Throughout All Classrooms and Hallways in Both 2003 Mobile Units**  
MATERIAL QUANTITY: **6000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jigar Shah*

Date: **05/04/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Foreman High School** INSPECTION DATE: **3/11/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **119A**  
MATERIAL DESCRIPTION: **12'X12" White w/Gray Streaks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout All Classrooms and Hallways in Both 2003 Mobile Units**  
MATERIAL QUANTITY: **6000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/11/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Foreman High School** REVIEW DATE: **5/4/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **119A**  
MATERIAL DESCRIPTION: **12'X12" White w/Gray Streaks VFT Mastic**  
MATERIAL LOCATION: **Throughout All Classrooms and Hallways in Both 2003 Mobile Units**  
MATERIAL QUANTITY: **6000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/04/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Foreman High School** INSPECTION DATE: **3/11/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **120**  
MATERIAL DESCRIPTION: **2'X2' White Ceiling Tiles**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout All Classrooms and Hallways in Both 2003 Mobile Units**  
MATERIAL QUANTITY: **6000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/11/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUILDING ID: **1330**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Foreman High School** REVIEW DATE: **5/4/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **120**  
MATERIAL DESCRIPTION: **2'X2' White Ceiling Tiles**  
MATERIAL LOCATION: **Throughout All Classrooms and Hallways in Both 2003 Mobile Units**  
MATERIAL QUANTITY: **6000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jigar Shah*

Date: **05/04/2016**



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Foreman High School** INSPECTION DATE: **3/11/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **121**  
MATERIAL DESCRIPTION: **Vinyl Baseboard Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout Both 2003 Mobile Units**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/11/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Foreman High School** REVIEW DATE: **5/4/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **121**  
MATERIAL DESCRIPTION: **Vinyl Baseboard Mastic**  
MATERIAL LOCATION: **Throughout Both 2003 Mobile Units**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/04/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Foreman High School** INSPECTION DATE: **3/11/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **122**  
MATERIAL DESCRIPTION: **Fire Doors (2 Each)**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Mechanical Rooms in Both 2003 Mobile Units**  
MATERIAL QUANTITY: **4** MATERIAL UNITS: **EA**  
DAMAGE QUANTITY: DAMAGE UNITS: **EA**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Roberto Rivera*

Date: 03/11/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Foreman High School** REVIEW DATE: **5/4/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **122**  
MATERIAL DESCRIPTION: **Fire Doors (2 Each)**  
MATERIAL LOCATION: **Mechanical Rooms in Both 2003 Mobile Units**  
MATERIAL QUANTITY: **4** MATERIAL UNITS: **EA**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **05/04/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Foreman High School** INSPECTION DATE: **3/11/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **123**  
MATERIAL DESCRIPTION: **Blue Linoleum**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Boys Restrooms in Both 2003 Mobile Units**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Roberto Rivera*

Date: 03/11/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Foreman High School** REVIEW DATE: **5/4/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **123**  
MATERIAL DESCRIPTION: **Blue Linoleum**  
MATERIAL LOCATION: **Boys Restrooms in Both 2003 Mobile Units**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jigar Shah*

Date: **05/04/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Foreman High School** INSPECTION DATE: **3/11/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **123A**  
MATERIAL DESCRIPTION: **Blue Linoleum Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Boys Restrooms in Both 2003 Mobile Units**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/11/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Foreman High School** REVIEW DATE: **5/4/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **123A**  
MATERIAL DESCRIPTION: **Blue Linoleum Mastic**  
MATERIAL LOCATION: **Boys Restrooms in Both 2003 Mobile Units**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jigar Shah*

Date: **05/04/2016**



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Foreman High School** INSPECTION DATE: **3/11/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **124**  
MATERIAL DESCRIPTION: **Pink Linoleum**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Girls Toilets in Both 2003 Mobile Units**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Roberto Rivera*

Date: 03/11/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Foreman High School** REVIEW DATE: **5/4/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **124**  
MATERIAL DESCRIPTION: **Pink Linoleum**  
MATERIAL LOCATION: **Girls Toilets in Both 2003 Mobile Units**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/04/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Foreman High School** INSPECTION DATE: **3/11/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **124A**  
MATERIAL DESCRIPTION: **Pink Linoleum Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Girls Toilets in Both 2003 Mobile Units**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: *Roberto Rivera*

Date: 03/11/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Foreman High School** REVIEW DATE: **5/4/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **124A**  
MATERIAL DESCRIPTION: **Pink Linoleum Mastic**  
MATERIAL LOCATION: **Girls Toilets in Both 2003 Mobile Units**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/04/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Foreman High School** INSPECTION DATE: **3/11/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **125**  
MATERIAL DESCRIPTION: **12"x12" yellow w/ blue and tan streaks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Rm 221/223 & teacher's office**  
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Roberto Rivera*

Date: 03/11/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Foreman High School** REVIEW DATE: **5/4/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **125**  
MATERIAL DESCRIPTION: **12"x12" yellow w/ blue and tan streaks VFT**  
MATERIAL LOCATION: **Rm 221/223 & teacher's office**  
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jigar Shah*

Date: **05/04/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Foreman High School** INSPECTION DATE: **3/11/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **125A**  
MATERIAL DESCRIPTION: **12"x"12 yellow w/ blue and tan streaks VFT mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **room 221/223 & teacher's office**  
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

*Roberto Rivera*

Date: **03/11/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUILDING ID: **1330**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Foreman High School** REVIEW DATE: **5/4/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **125A**  
MATERIAL DESCRIPTION: **12"x"12 yellow w/ blue and tan streaks VFT mastic**  
MATERIAL LOCATION: **room 221/223 & teacher's office**  
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jigar Shah*

Date: **05/04/2016**



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Foreman High School** INSPECTION DATE: **3/11/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **126**  
MATERIAL DESCRIPTION: **Transite fume hood**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rm 221/223**  
MATERIAL QUANTITY: **80** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Roberto Rivera*

Date: 03/11/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Foreman High School** REVIEW DATE: **5/4/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **126**  
MATERIAL DESCRIPTION: **Transite fume hood**  
MATERIAL LOCATION: **Rm 221/223**  
MATERIAL QUANTITY: **80** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/04/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Foreman High School** INSPECTION DATE: **3/11/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **127**  
MATERIAL DESCRIPTION: **Brown linoleum**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **2nd fl. storage room by police dept. office**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Roberto Rivera*

Date: 03/11/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUILDING ID: **1330**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Foreman High School** REVIEW DATE: **5/4/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **127**  
MATERIAL DESCRIPTION: **Brown linoleum**  
MATERIAL LOCATION: **2nd fl. storage room by police dept. office**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jigar Shah*

Date: **05/04/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Foreman High School** INSPECTION DATE: **3/11/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **127A**  
MATERIAL DESCRIPTION: **Brown linoleum mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **2nd fl. storage room by police dept. office**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: *Roberto Rivera*

Date: 03/11/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUILDING ID: **1330**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Foreman High School** REVIEW DATE: **5/4/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **127A**  
MATERIAL DESCRIPTION: **Brown linoleum mastic**  
MATERIAL LOCATION: **2nd fl. storage room by police dept. office**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/04/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Foreman High School** INSPECTION DATE: **3/11/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **128**  
MATERIAL DESCRIPTION: **4"x12" ceiling tile w/holes**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Auditorium, storage and balcony, library**  
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Roberto Rivera*

Date: 03/11/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Foreman High School** REVIEW DATE: **5/4/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **128**  
MATERIAL DESCRIPTION: **4"x12" ceiling tile w/holes**  
MATERIAL LOCATION: **Auditorium, storage and balcony, library**  
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **05/04/2016**



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Foreman High School** INSPECTION DATE: **3/11/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **128A**  
MATERIAL DESCRIPTION: **4"x12" ceiling tile w/ holes mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **auditorium & storage & balcony, library**  
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/11/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Foreman High School** REVIEW DATE: **5/4/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **128A**  
MATERIAL DESCRIPTION: **4"x12" ceiling tile w/ holes mastic**  
MATERIAL LOCATION: **auditorium & storage & balcony, library**  
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **05/04/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Foreman High School** INSPECTION DATE: **3/11/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **129**  
MATERIAL DESCRIPTION: **heat shields (inside radiator cabinet)**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rm 112**  
MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: *Roberto Rivera*

Date: 03/11/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Foreman High School** REVIEW DATE: **5/4/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **129**  
MATERIAL DESCRIPTION: **heat shields (inside radiator cabinet)**  
MATERIAL LOCATION: **Rm 112**  
MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jigar Shah*

Date: **05/04/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Foreman High School** INSPECTION DATE: **3/11/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13**  
MATERIAL DESCRIPTION: **MJP E/F/V on Fiberglass Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **All Toilet Pipe Chases & Room 217, 121**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Roberto Rivera*

Date: 03/11/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Foreman High School** REVIEW DATE: **5/4/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **13**  
MATERIAL DESCRIPTION: **MJP E/F/V on Fiberglass Pipe Insulation**  
MATERIAL LOCATION: **All Toilet Pipe Chases & Room 217, 121**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/04/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Foreman High School** INSPECTION DATE: **3/11/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **43**  
MATERIAL DESCRIPTION: **Vibration Joint Material**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Basement & NW Fan Room**  
MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Roberto Rivera*

Date: 03/11/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Foreman High School** REVIEW DATE: **5/4/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **43**  
MATERIAL DESCRIPTION: **Vibration Joint Material**  
MATERIAL LOCATION: **Basement & NW Fan Room**  
MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/04/2016**



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Foreman High School** INSPECTION DATE: **3/11/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **44**  
MATERIAL DESCRIPTION: **9"x9" Green w/ White Streaks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **1st and 2nd Floor Corridor, Library, & Engineer's Office and Closet, rm 112 (under carpet), 112 offices**

MATERIAL QUANTITY: **9095** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: *Roberto Rivera*

Date: 03/11/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Foreman High School** REVIEW DATE: **5/4/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **44**  
MATERIAL DESCRIPTION: **9"x9" Green w/ White Streaks VFT**  
MATERIAL LOCATION: **1st and 2nd Floor Corridor, Library, & Engineer's Office and Closet, rm 112 (under carpet), 112 offices**  
MATERIAL QUANTITY: **9095** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/04/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Foreman High School** INSPECTION DATE: **3/11/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **45**  
MATERIAL DESCRIPTION: **12"x12" Blue w/ Gray Streaks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **3rd Floor Corridor**  
MATERIAL QUANTITY: **7500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Roberto Rivera*

Date: 03/11/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Foreman High School** REVIEW DATE: **5/4/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **45**  
MATERIAL DESCRIPTION: **12"x12" Blue w/ Gray Streaks VFT**  
MATERIAL LOCATION: **3rd Floor Corridor**  
MATERIAL QUANTITY: **7500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **05/04/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Foreman High School** INSPECTION DATE: **3/11/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **46**  
MATERIAL DESCRIPTION: **Brown w/ White Streaks Linoleum**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 101A**

MATERIAL QUANTITY: **0** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/11/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Foreman High School** REVIEW DATE: **5/4/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **46**  
MATERIAL DESCRIPTION: **Brown w/ White Streaks Linoleum**  
MATERIAL LOCATION: **Room 101A**  
MATERIAL QUANTITY: **0** MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/04/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Foreman High School** INSPECTION DATE: **3/11/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **47**  
MATERIAL DESCRIPTION: **9"x9" Green w/ White Streaks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st and 2nd Floor Corridor, Library, & Engineer's Office and Closet, Rm 112 (under carpet), 112 offices**

MATERIAL QUANTITY: **9095** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: 

Date: 03/11/2016

# Chicago Public Schools

GSG Consultants, Inc.

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Foreman High School** REVIEW DATE: **5/4/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **47**  
MATERIAL DESCRIPTION: **9"x9" Green w/ White Streaks VFT Mastic**  
MATERIAL LOCATION: **1st and 2nd Floor Corridor, Library, & Engineer's Office and Closet, Rm 112 (under carpet), 112 offices**  
MATERIAL QUANTITY: **9095** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/04/2016**



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Foreman High School** INSPECTION DATE: **3/11/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **48**  
MATERIAL DESCRIPTION: **12"x12" Blue w/ Gray Streaks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **3rd Floor Corridor**  
MATERIAL QUANTITY: **7500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/11/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUILDING ID: **1330**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Foreman High School** REVIEW DATE: **5/4/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **48**  
MATERIAL DESCRIPTION: **12"x12" Blue w/ Gray Streaks VFT Mastic**  
MATERIAL LOCATION: **3rd Floor Corridor**  
MATERIAL QUANTITY: **7500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/04/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Foreman High School** INSPECTION DATE: **3/11/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **50**  
MATERIAL DESCRIPTION: **Brown w/ White Streaks Linoleum Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 101A**

MATERIAL QUANTITY: **0** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/11/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Foreman High School** REVIEW DATE: **5/4/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **50**  
MATERIAL DESCRIPTION: **Brown w/ White Streaks Linoleum Mastic**  
MATERIAL LOCATION: **Room 101A**  
MATERIAL QUANTITY: **0** MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 05/04/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Foreman High School** INSPECTION DATE: **3/11/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **51**  
MATERIAL DESCRIPTION: **Gray w/ Blue Streaks Linoleum**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 209, 317, vault & teacher's office, 319, vault & teacher's office, 321 and Vault, 322**

MATERIAL QUANTITY: **0** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: *Roberto Rivera*

Date: 03/11/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Foreman High School** REVIEW DATE: **5/4/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **51**  
MATERIAL DESCRIPTION: **Gray w/ Blue Streaks Linoleum**  
MATERIAL LOCATION: **Room 209, 317, vault & teacher's office, 319, vault & teacher's office, 321 and Vault, 322**  
MATERIAL QUANTITY: **0** MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 05/04/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Foreman High School** INSPECTION DATE: **3/11/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **52**  
MATERIAL DESCRIPTION: **Gray w/ Blue Streaks Linoleum Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 209, 317, vault & teacher's office, 319, vault & teacher's office, 321 and Vault, 322**

MATERIAL QUANTITY: **0** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: *Roberto Rivera*

Date: 03/11/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Foreman High School** REVIEW DATE: **5/4/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **52**  
MATERIAL DESCRIPTION: **Gray w/ Blue Streaks Linoleum Mastic**  
MATERIAL LOCATION: **Room 209, 317, vault & teacher's office, 319, vault & teacher's office, 321 and Vault, 322**  
MATERIAL QUANTITY: **0** MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/04/2016**



# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Foreman High School** INSPECTION DATE: **3/11/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **53**  
MATERIAL DESCRIPTION: **12"x12" Pink w/ White Streaks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Third Floor Corridor**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Roberto Rivera*

Date: 03/11/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Foreman High School** REVIEW DATE: **5/4/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **53**  
MATERIAL DESCRIPTION: **12"x12" Pink w/ White Streaks VFT**  
MATERIAL LOCATION: **Third Floor Corridor**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/04/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Foreman High School** INSPECTION DATE: **3/11/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **54**  
MATERIAL DESCRIPTION: **12"x12" Pink w/ White Streaks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Third Floor Corridor**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Roberto Rivera*

Date: 03/11/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUILDING ID: **1330**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Foreman High School** REVIEW DATE: **5/4/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **54**  
MATERIAL DESCRIPTION: **12"x12" Pink w/ White Streaks VFT Mastic**  
MATERIAL LOCATION: **Third Floor Corridor**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/04/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Foreman High School** INSPECTION DATE: **3/11/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **55**  
MATERIAL DESCRIPTION: **9"x9" Green w/ Gray Streaks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Rooms 312 & 314**  
MATERIAL QUANTITY: **1440** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/11/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Foreman High School** REVIEW DATE: **5/4/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **55**  
MATERIAL DESCRIPTION: **9"x9" Green w/ Gray Streaks VFT**  
MATERIAL LOCATION: **Rooms 312 & 314**  
MATERIAL QUANTITY: **1440** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jigar Shah*

Date: **05/04/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Foreman High School** INSPECTION DATE: **3/11/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **56**  
MATERIAL DESCRIPTION: **9"x9" Green w/ Gray Streaks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 312 & 314**  
MATERIAL QUANTITY: **1440** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Roberto Rivera*

Date: 03/11/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUILDING ID: **1330**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Foreman High School** REVIEW DATE: **5/4/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **56**  
MATERIAL DESCRIPTION: **9"x9" Green w/ Gray Streaks VFT Mastic**  
MATERIAL LOCATION: **Rooms 312 & 314**  
MATERIAL QUANTITY: **1440** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **05/04/2016**



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Foreman High School** INSPECTION DATE: **3/11/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **57**  
MATERIAL DESCRIPTION: **12"x12" Off White w/ Gray Streaks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 122, 124, 126, 123 A (under carpet), 123 B (under carpet)**  
MATERIAL QUANTITY: **3700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: *Roberto Rivera*

Date: 03/11/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Foreman High School** REVIEW DATE: **5/4/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **57**  
MATERIAL DESCRIPTION: **12"x12" Off White w/ Gray Streaks VFT**  
MATERIAL LOCATION: **Rooms 122, 124, 126, 123 A (under carpet), 123 B (under carpet)**  
MATERIAL QUANTITY: **3700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jigar Shah*

Date: **05/04/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Foreman High School** INSPECTION DATE: **3/11/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **58**  
MATERIAL DESCRIPTION: **12"x12" Off White w/ Gray Streaks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 122, 124, 126, 123 A (Under Carpet), 123 B (Under Carpet)**  
MATERIAL QUANTITY: **3700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Roberto Rivera*

Date: 03/11/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUILDING ID: **1330**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Foreman High School** REVIEW DATE: **5/4/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **58**  
MATERIAL DESCRIPTION: **12"x12" Off White w/ Gray Streaks VFT Mastic**  
MATERIAL LOCATION: **Rooms 122, 124, 126, 123 A (Under Carpet), 123 B (Under Carpet)**  
MATERIAL QUANTITY: **3700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/04/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Foreman High School** INSPECTION DATE: **3/11/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **59**  
MATERIAL DESCRIPTION: **9"x9" Gray w/ White & Black Streaks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **1st and 2nd Floor Hall, Engineer's Office & Closet, Vault, Rm 128/130, Rm 112 (under carpet), 112 offices**

MATERIAL QUANTITY: **9999** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: 03/11/2016

# Chicago Public Schools

GSG Consultants, Inc.

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUILDING ID: **1330**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Foreman High School** REVIEW DATE: **5/4/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **59**  
MATERIAL DESCRIPTION: **9"x9" Gray w/ White & Black Streaks VFT**  
MATERIAL LOCATION: **1st and 2nd Floor Hall, Engineer's Office & Closet, Vault, Rm 128/130, Rm 112 (under carpet), 112 offices**  
MATERIAL QUANTITY: **9999** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/04/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Foreman High School** INSPECTION DATE: **3/11/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **60**  
MATERIAL DESCRIPTION: **9"x9" Gray w/ White & Black Streaks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st and 2nd Floor Hall, Engineer's Office & Closet, Vault, Rm 128/130, Rm 112 (under carpet), 112 offices**

MATERIAL QUANTITY: **9999** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: 

Date: 03/11/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUILDING ID: **1330**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Foreman High School** REVIEW DATE: **5/4/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **60**  
MATERIAL DESCRIPTION: **9"x9" Gray w/ White & Black Streaks VFT Mastic**  
MATERIAL LOCATION: **1st and 2nd Floor Hall, Engineer's Office & Closet, Vault, Rm 128/130, Rm 112 (under carpet), 112 offices**  
MATERIAL QUANTITY: **9999** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/04/2016**



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Foreman High School** INSPECTION DATE: **3/11/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **61**  
MATERIAL DESCRIPTION: **9" x 9" Gray w/ Pink, White, & Black Streaks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Room 211, 213/215**

MATERIAL QUANTITY: **1550**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/11/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Foreman High School** REVIEW DATE: **5/4/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **61**  
MATERIAL DESCRIPTION: **9" x 9" Gray w/ Pink, White, & Black Streaks VFT**  
MATERIAL LOCATION: **Room 211, 213/215**  
MATERIAL QUANTITY: **1550** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/04/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Foreman High School** INSPECTION DATE: **3/11/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **62**  
MATERIAL DESCRIPTION: **9" x 9" Gray w/ Pink, White, & Black Streaks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 211, 213/215**  
MATERIAL QUANTITY: **1550** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: 

Date: 03/11/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Foreman High School** REVIEW DATE: **5/4/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **62**  
MATERIAL DESCRIPTION: **9" x 9" Gray w/ Pink, White, & Black Streaks VFT**  
MATERIAL LOCATION: **Room 211, 213/215**  
MATERIAL QUANTITY: **1550** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jigar Shah*

Date: **05/04/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Foreman High School** INSPECTION DATE: **3/11/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **63**  
MATERIAL DESCRIPTION: **12"x12" Brown w/ White & Black Streaks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Rooms 218/ 220**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/11/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Foreman High School** REVIEW DATE: **5/4/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **63**  
MATERIAL DESCRIPTION: **12"x12" Brown w/ White & Black Streaks VFT**  
MATERIAL LOCATION: **Rooms 218/ 220**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jigar Shah*

Date: **05/04/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Foreman High School** INSPECTION DATE: **3/11/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **64**  
MATERIAL DESCRIPTION: **12"x12" Brown w/ White & Black Streaks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 218/ 220**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/11/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Foreman High School** REVIEW DATE: **5/4/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **64**  
MATERIAL DESCRIPTION: **12"x12" Brown w/ White & Black Streaks VFT Mastic**  
MATERIAL LOCATION: **Rooms 218/ 220**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/04/2016**



# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Foreman High School** INSPECTION DATE: **3/11/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **65**  
MATERIAL DESCRIPTION: **12"x12" Marble Color VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Rooms 217/219**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Roberto Rivera*

Date: 03/11/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUILDING ID: **1330**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Foreman High School** REVIEW DATE: **5/4/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **65**  
MATERIAL DESCRIPTION: **12"x12" Marble Color VFT**  
MATERIAL LOCATION: **Rooms 217/219**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/04/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Foreman High School** INSPECTION DATE: **3/11/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **66**  
MATERIAL DESCRIPTION: **12"x12" Marble Color VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 217/ 219**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Roberto Rivera*

Date: 03/11/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUILDING ID: **1330**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Foreman High School** REVIEW DATE: **5/4/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **66**  
MATERIAL DESCRIPTION: **12"x12" Marble Color VFT Mastic**  
MATERIAL LOCATION: **Rooms 217/ 219**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jigar Shah*

Date: **05/04/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Foreman High School** INSPECTION DATE: **3/11/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **67**  
MATERIAL DESCRIPTION: **12"x12" Gray w/ White Specks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 221 vault**  
MATERIAL QUANTITY: **40** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Roberto Rivera*

Date: 03/11/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Foreman High School** REVIEW DATE: **5/4/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **67**  
MATERIAL DESCRIPTION: **12"x12" Gray w/ White Specks VFT**  
MATERIAL LOCATION: **Room 221 vault**  
MATERIAL QUANTITY: **40** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jigar Shah*

Date: **05/04/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Foreman High School** INSPECTION DATE: **3/11/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **68**  
MATERIAL DESCRIPTION: **12"x12" Gray w/ White Specks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 221 vault**  
MATERIAL QUANTITY: **40** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Roberto Rivera*

Date: 03/11/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Foreman High School** REVIEW DATE: **5/4/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **68**  
MATERIAL DESCRIPTION: **12"x12" Gray w/ White Specks VFT Mastic**  
MATERIAL LOCATION: **Room 221 vault**  
MATERIAL QUANTITY: **40** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **05/04/2016**



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Foreman High School** INSPECTION DATE: **3/11/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **69**  
MATERIAL DESCRIPTION: **12"x12" Brown w/ White & Gray Streaks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 225 (Under HA 107)**  
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: *Roberto Rivera*

Date: 03/11/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Foreman High School** REVIEW DATE: **5/4/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **69**  
MATERIAL DESCRIPTION: **12"x12" Brown w/ White & Gray Streaks VFT**  
MATERIAL LOCATION: **Room 225 (Under HA 107)**  
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/04/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Foreman High School** INSPECTION DATE: **3/11/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **70**  
MATERIAL DESCRIPTION: **12"x12" Brown w/ White & Gray Streaks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 225 (Under HA 107)**  
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Roberto Rivera*

Date: 03/11/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Foreman High School** REVIEW DATE: **5/4/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **70**  
MATERIAL DESCRIPTION: **12"x12" Brown w/ White & Gray Streaks VFT Mastic**  
MATERIAL LOCATION: **Room 225 (Under HA 107)**  
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jigar Shah*

Date: **05/04/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Foreman High School** INSPECTION DATE: **3/11/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **71**  
MATERIAL DESCRIPTION: **1'x2' Black VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 128, 129 (Under Carpet)**  
MATERIAL QUANTITY: **120** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: *Roberto Rivera*

Date: 03/11/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Foreman High School** REVIEW DATE: **5/4/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **71**  
MATERIAL DESCRIPTION: **1'x2' Black VFT**  
MATERIAL LOCATION: **Room 128, 129 (Under Carpet)**  
MATERIAL QUANTITY: **120** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jigar Shah*

Date: **05/04/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Foreman High School** INSPECTION DATE: **3/11/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **72**  
MATERIAL DESCRIPTION: **1'x2' Black VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 128, 129 (Under Carpet)**  
MATERIAL QUANTITY: **120** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: *Roberto Rivera*

Date: 03/11/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Foreman High School** REVIEW DATE: **5/4/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **72**  
MATERIAL DESCRIPTION: **1'x2' Black VFT Mastic**  
MATERIAL LOCATION: **Room 128, 129 (Under Carpet)**  
MATERIAL QUANTITY: **120** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jigar Shah*

Date: **05/04/2016**



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Foreman High School** INSPECTION DATE: **3/11/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **73**  
MATERIAL DESCRIPTION: **12"x12" Sand w/ White Streaks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Main Office & Principal's Office**

MATERIAL QUANTITY: **880**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

*Roberto Rivera*

Date: **03/11/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Foreman High School** REVIEW DATE: **5/4/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **73**  
MATERIAL DESCRIPTION: **12"x12" Sand w/ White Streaks VFT**  
MATERIAL LOCATION: **Main Office & Principal's Office**  
MATERIAL QUANTITY: **880** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jigar Shah*

Date: **05/04/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Foreman High School** INSPECTION DATE: **3/11/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **74**  
MATERIAL DESCRIPTION: **12"x12" Sand w/ White Streaks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Main Office & Principal's Office**  
MATERIAL QUANTITY: **880** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: *Roberto Rivera*

Date: 03/11/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Foreman High School** REVIEW DATE: **5/4/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **74**  
MATERIAL DESCRIPTION: **12"x12" Sand w/ White Streaks VFT Mastic**  
MATERIAL LOCATION: **Main Office & Principal's Office**  
MATERIAL QUANTITY: **880** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **05/04/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Foreman High School** INSPECTION DATE: **3/11/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **75**  
MATERIAL DESCRIPTION: **1'x1' White Wormy Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Lunchroom, Room 329 & Vestibule, 330 & vestibule, 125**

MATERIAL QUANTITY: **0** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/11/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Foreman High School** REVIEW DATE: **5/4/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **75**  
MATERIAL DESCRIPTION: **1'x1' White Wormy Ceiling Tile**  
MATERIAL LOCATION: **Lunchroom, Room 329 & Vestibule, 330 & vestibule, 125**  
MATERIAL QUANTITY: **0** MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/04/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Foreman High School** INSPECTION DATE: **3/11/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **76**  
MATERIAL DESCRIPTION: **1'x1' White Wormy Ceiling Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Lunchroom, Room 329 & Vestibule, 330 & vestibule, 125**

MATERIAL QUANTITY: **0** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/11/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Foreman High School** REVIEW DATE: **5/4/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **76**  
MATERIAL DESCRIPTION: **1'x1' White Wormy Ceiling Tile Mastic**  
MATERIAL LOCATION: **Lunchroom, Room 329 & Vestibule, 330 & vestibule, 125**  
MATERIAL QUANTITY: **0** MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 05/04/2016



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Foreman High School** INSPECTION DATE: **3/11/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **77**  
MATERIAL DESCRIPTION: **Table Tops**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Room 317, 318, 321, 322, 319 vault and teacher's office, 209, 217/219, 221/223 and office and vault**

MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/11/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Foreman High School** REVIEW DATE: **5/4/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **77**  
MATERIAL DESCRIPTION: **Table Tops**  
MATERIAL LOCATION: **Room 317, 318, 321, 322, 319 vault and teacher's office, 209, 217/219, 221/223 and office and vault**  
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jigar Shah*

Date: **05/04/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Foreman High School** INSPECTION DATE: **3/11/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **98**  
MATERIAL DESCRIPTION: **Interior Window Caulk**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Interior Windows**

MATERIAL QUANTITY: **0** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/11/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUILDING ID: **1330**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Foreman High School** REVIEW DATE: **5/4/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **98**

MATERIAL DESCRIPTION: **Interior Window Caulk**

MATERIAL LOCATION: **Interior Windows**

MATERIAL QUANTITY: **0**

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/04/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Foreman High School** INSPECTION DATE: **3/11/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **99**  
MATERIAL DESCRIPTION: **Exterior Window Caulk**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Exterior Windows**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **03/11/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUILDING ID: **1330**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Foreman High School** REVIEW DATE: **5/4/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **99**  
MATERIAL DESCRIPTION: **Exterior Window Caulk**  
MATERIAL LOCATION: **Exterior Windows**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jigar Shah*

Date: **05/04/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Foreman High School** INSPECTION DATE: **3/11/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **CM-001**  
MATERIAL DESCRIPTION: **Brown Capet Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 129**  
MATERIAL QUANTITY: **350** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/11/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Foreman High School** REVIEW DATE: **5/4/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **CM-001**  
MATERIAL DESCRIPTION: **Brown Capet Adhesive**  
MATERIAL LOCATION: **Room 129**  
MATERIAL QUANTITY: **350** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **05/04/2016**



# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Foreman High School** INSPECTION DATE: **3/11/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FT-001**  
MATERIAL DESCRIPTION: **9" x 9" Green Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Room 128**  
MATERIAL QUANTITY: **350** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Roberto Rivera*

Date: 03/11/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Foreman High School** REVIEW DATE: **5/4/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **FT-001**  
MATERIAL DESCRIPTION: **9" x 9" Green Floor Tile**  
MATERIAL LOCATION: **Room 128**  
MATERIAL QUANTITY: **350** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/04/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Foreman High School** INSPECTION DATE: **3/11/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FTM-001**  
MATERIAL DESCRIPTION: **9" x 9" Green Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 128**  
MATERIAL QUANTITY: **350** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: *Roberto Rivera*

Date: 03/11/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Foreman High School** REVIEW DATE: **5/4/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **FTM-001**  
MATERIAL DESCRIPTION: **9" x 9" Green Floor Tile Mastic**  
MATERIAL LOCATION: **Room 128**  
MATERIAL QUANTITY: **350** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_

*Jigar Shah*

Date: **05/04/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Foreman High School** INSPECTION DATE: **3/11/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **TSI-001**  
MATERIAL DESCRIPTION: **MJP E/F/V**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Boiler Room**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Roberto Rivera*

Date: 03/11/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46131** BUIDLING ID: **1330**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Foreman High School** REVIEW DATE: **5/4/2016**  
ADDRESS: **3235 N. LeClaire Ave.** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **TSI-001**  
MATERIAL DESCRIPTION: **MJP E/FV**  
MATERIAL LOCATION: **Boiler Room**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **05/04/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
*2016 AHERA REINSPECTION*

# APPENDIX B

## **Inspector and Management Planner Licenses**

---



2016



**OCCUPATIONAL TRAINING & SUPPLY, INC.**

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900

# Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

**Roberto Rivera**

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Course Date: 1/6/2016

Exam Date: 1/6/2016

Expiration Date: 1/6/2017

Certificate Number: BIR1601060030

  
\_\_\_\_\_  
Kathy DeSalvo, Director



525-535 West Jefferson Street • Springfield, Illinois 62761-6001 • www.dph.illinois.gov

4/20/2016

**ROBERTO RIVERA**  
855 WEST ADAMS STREET, STE 200  
CHICAGO, IL 60607

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 06327

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

**COPY OF THE ASBESTOS PROFESSIONAL LICENSE**

Front of License

Back of License


 <p><b>ASBESTOS PROFESSIONAL LICENSE</b></p>			<p><b>ENDORSEMENTS</b></p> <p>SUPERVISOR/WORKER INSPECTOR</p>	<p><b>TC EXPIRES</b></p> <p>1/20/2017 1/6/2017</p>
<p>ID NUMBER 000 - 06327</p>	<p>ISSUED 4/20/2016</p>	<p>EXPIRES 05/15/2017</p>	<p>PROJECT MANAGER AIR SAMPLING PROFESSIONAL</p>	<p>1/20/2017</p>
<p><b>ROBERTO RIVERA</b> 855 WEST ADAMS STREET, ST CHICAGO, IL 60607 Environmental Health</p>			<p><b>Alteration of this license shall result in legal action</b> This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.</p>	

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: [dph.illinois.gov/topics-services/environmental-health-protection/asbestos](http://dph.illinois.gov/topics-services/environmental-health-protection/asbestos)  
EMAIL Address: [dph.asbestos@illinois.gov](mailto:dph.asbestos@illinois.gov)

**PROTECTING HEALTH, IMPROVING LIVES**  
*Nationally Accredited by PHAB*

2016



**OCCUPATIONAL TRAINING & SUPPLY, INC.**

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900

# Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

**Jigar Shah**

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 1/27/2016

Exam Date: 1/27/2016

Expiration Date: 1/27/2017

Certificate Number: MPR1601270320

  
Kathy DeSalvo, Director



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • [www.dph.illinois.gov](http://www.dph.illinois.gov)

4/20/2016

**JIGAR M SHAH**  
 855 W ADAMS ST, SUITE 200  
 CHICAGO, IL 60607

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 07342

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

**COPY OF THE ASBESTOS PROFESSIONAL LICENSE**

Front of License

Back of License

		<b>ASBESTOS          PROFESSIONAL          LICENSE</b>		<b>ENDORSEMENTS</b>	<b>TC EXPIRES</b>
<b>ID NUMBER</b> 109 - 07342	<b>ISSUED</b> 4/20/2016	<b>EXPIRES</b> 05/15/2017		INSPECTOR PROJECT DESIGNER MANAGEMENT PLANNER PROJECT MANAGER AIR SAMPLING PROFESSIONAL	1/19/2017 2/2/2017 1/27/2017 2/26/2017
<b>JIGAR M SHAH</b> 855 W ADAMS ST, SUITE 200 CHICAGO, IL 60607 Environmental Health		<b>Alteration of this license shall result in legal action</b> This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.			

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: [dph.illinois.gov/topics-services/environmental-health-protection/asbestos](http://dph.illinois.gov/topics-services/environmental-health-protection/asbestos)  
 EMAIL Address: [dph.asbestos@illinois.gov](mailto:dph.asbestos@illinois.gov)

**PROTECTING HEALTH, IMPROVING LIVES**  
*Nationally Accredited by PHAB*

# APPENDIX C

## Laboratory Accreditations

---

# APPENDIX D

## Laboratory Results

---

# APPENDIX E

## Chain of Custody Forms

---

## Three-Year Reinspection Key to Terms

	<b>CODE</b>	<b>KEY</b>
<b>MATERIAL</b>		
	ACBM	Asbestos Containing Building Materials
<b>MATERIAL CATEGORY</b>		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
<b>MATERIAL UNITS</b>		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
<b>DAMAGE TYPE</b>		
	Loc	Localized
	Dist	Distributed