

ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-0023
SCHOOL NAME: Kelvyn Park High School
ADDRESS OF SCHOOL: 4343 W. Wrightwood Ave.
CITY: Chicago, IL, 60639

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **3/27/2013**

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II (Please type or print)

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 6/21/2016 ENROLLMENT 522
IDPH INSPECTOR LICENSE NUMBER: 100-05183
IDPH LICENSED INSPECTOR NAME (Please Print): Delores Fitzpatrick
IDPH MP LICENSE NUMBER: 100-07342
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Jigar Shah

DESIGNATED PERSON (Please Print): Robert Christlieb PHONE: (773) 553-3197



6/21/2016

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Kelvyn Park High School

4343 W. Wrightwood Ave.
Chicago, IL, 60639

Unit: 46191
Building ID: 1410

IDPH ID Number: 14-016-2990-0023

REPORT DATE:

Tuesday, June 21, 2016

Prepared for:

Chicago Public Schools
125 S. Clark Street
Chicago, IL 60603

Prepared by:

GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone (312) 733-6262

Fax (312) 733-5612

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

March 9, 2016

Mr. R. Kent Cook
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2016 Three-Year Reinspections

Dear Mr. Cook:

GSG Consultants, Inc., Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 1,2,6 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 46191 Region: 02 IDPH ID: 14-016-2990-0023

School: Kelvyn Park High School Building ID: 1410

Address: 4343 W. Wrightwood Ave.

Chicago, IL, 60639

Building Contact: Diaz, Joseph

Contact Phone: 773-551-8974

Current Building Owners: Chicago Public Schools

Review Date: 06/21/2016

Inspector: Delores Fitzpatrick

Inspector IDPH License: 100-05183

Management Planner: Jigar Shah

Management Planner IDPH License: 100-07342

If you have any questions or comments, please contact us at (312) 733-6262

Sincerely,
GSG Consultants, Inc.



Jigar Shah
100-07342

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: March 09, 2016

RE: Kelvyn Park High School, Unit 46191
4343 W. Wrightwood Ave.
Chicago, IL, 60639

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2016 asbestos three year re-inspection has been completed at Kelvyn Park High School , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at Kelvyn Park High School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Robert Christlieb, the designated Local Education Authority's Designated Person at (773) 553-3197 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Kelvyn Park High School Unit: 46191 Region: 02
Address: 4343 W. Wrightwood Ave. Chicago, IL, 60639
IDPH ID: 14-016-2990-0023 Building ID: 1410
Contact: Diaz, Joseph Phone: 773-551-8974

2. Description of Facility

Original Construction: 1918 Additional Construction: 1928
Total Square Footage: 98284 No of Floors: 3
Current Occupancy: 522

3. LEA Designated Person

Contact: Robert Christlieb Phone: (773) 553-3197
Address: 125 South Clark Street, 17th Floor
Chicago, IL 60603

4. Managing Environmental Consultant

MEC: GSG Consultants, Inc.
Contact: Arturo Saenz
Address 855 W. Adams St., Ste. 200
Phone: (312) 733-6262 Fax: (312) 733-5612

5. Inspector

Inspector Name: Delores Fitzpatrick

Inspector IDPH license # 100-05183

Signature:
Date: 3/9/2016



6. Management Planner

Management Planner Name: Jigar Shah

Management Planner IDPH license # 100-07342

Signature:
Date: 06/21/2016



7. Review Date: 06/21/2016

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature:



Date: 6/21/2016

Name: Robert Christlieb

II. EXECUTIVE SUMMARY

GSG Consultants, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Kelvyn Park High School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 1410:

138

12x12 White VFT

B. The following new homogenous areas have been identified for Building 1410:

132	12x12 Gray, Black and beige VFT
133	12x12 Gray, Black and beige VFT Mastic
134	12x12 Gray, Black and White VFT
135	12x12 Gray, Black and White VFT Mastic
136	12x12 Gray and Black VFT
137	12x12 Gray and Black VFT Mastic
138	12x12 White VFT
139	12x12 White VFT Mastic

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

008A	12x12 Black w/ Brown Streaks Floor Tile Mastic
080	MJP E/F/V on Fiberglass Pipe Insulation
092	9"x9" Gray w/ Speckles Floor Tile - (NOT OBSERVED)
092A	9"x9" Gray w/Speckles VFT Mastic - (NOT OBSERVED)
098	12x12 Light Brown w/ White & Dark Streaks Floor Tile
099	12x12 Gray Floor Tile
099A	12x12 Gray Floor Tile Mastic
101	12x12 Light Pink Floor Tile - (NOT OBSERVED)
101A	12x12 Light Pink Floor Tile Mastic - (NOT OBSERVED)
102	12x12 Light Brown w/ Speckles Floor Tile - (NOT OBSERVED)
102A	12x12 Light Brown w/ Speckles Floor Tile Mastic - (NOT OBSERVED)
103	12x12 Light Beige w/ White Streaks Floor Tile
103A	12x12 Beige w/ White Streaks VFT Mastic
104	12"x12" Light Blue Floor Tile
106	12"x12" Tan w/ Brown & White Spots VFT
107	12"x12" Tan w/ Brown & White Spots VFT Mastic
108	12"x12" Grey W/ Specks VFT
109	12"x12" Grey W/ Specks VFT Mastic
110	Blue Linoleum
110 A	Blue Linoleum Mastic
111	12"x12" Black w/White Specks Floor Tile
111A	12"x12" Black w/White Specks Floor Tile Mastic
112	12"x12" Blue w/White Specks Floor Tile
112A	12"x12" Blue w/White Specks Floor Tile Mastic
113	12"x12" White w/Specks Floor Tile
113A	12"x12" White w/Specks Floor Tile Mastic
114	12"x12" Light Blue w/Specks Floor Tile
114A	12"x12" Light Blue w/Specks Floor Tile Mastic
115	Blue Carpet Adhesive
116	12"x12" Ceramic Tile Grout
117	12"x12" Ceramic Tile Adhesive
118	2' X 4' white with swirls, ceiling tile
119	12" X 12" yellow speckle, VFT
120	12" X 12" yellow speckle, mastic
121	12" X 12" black with white specks, VFT (DUPLICATE OF 001A NOT OBSERVED)

122	12" X 12" black with white specks, Mastic (DUPLICATE OF 004A, NOT OBSERVED)
123	12" X 12" yellow speckled VFT
124	12" X 12" yellow speckled, Mastic
125	12" X 12" black with dark brown specks, VFT
126	12" X 12" black with dark brown specks, Mastic
127	12" X 12" blue speckled, VFT
128	12" X 12" blue speckled, mastic
129	12" X 12" gray speckled VFT
130	12" X 12" gray speckled, Mastic
131	Fume Hood
132	12x12 Gray, Black and beige VFT
133	12x12 Gray, Black and beige VFT Mastic
134	12x12 Gray, Black and White VFT
135	12x12 Gray, Black and White VFT Mastic
136	12x12 Gray and Black VFT
137	12x12 Gray and Black VFT Mastic
138	12x12 White VFT
139	12x12 White VFT Mastic
B	2'x4' White Wormy Ceiling Tile
C	2'x4' Multiple Color 1/4" Wormy Ceiling Tile (NOT OBSERVED)
D	2'x4' Dk Wht w/Multi Color 1/2" Wormy Ceiling Tile (NOT OBSERVED)
E	2'x4' Off White Large Wormy Ceiling Tile
F	1'x1' Off White Wormy Ceiling Tile
G	1'x1' Off White Large Wormy Ceiling Tile
H	Spray - On Walls & Beams (NOT OBSERVED)
I	18"x18" Dirty White Ceiling Tile
J	1'x1' Dirty White Ceiling Tile
K	2'x4' Multiple Color 1/2" Wormy Ceiling Tile (NOT OBSERVED)
L	1'x1' White Wormy Ceiling Tile
N	Sheeted Walls

The following areas were deemed to be inaccessible:

008A	12x12 Black w/ Brown Streaks Floor Tile Mastic
087A	1'x1' Brown w/ White Streaks Floor Tile Mastic
088A	12x12 Off White w/ Speckles Floor Tile Mastic
090A	12x12 Green w/White Speckles Floor Tile Mastic
092A	9"x9" Gray w/Speckles VFT Mastic - (NOT OBSERVED)
093A	9"x9" Light Brown Floor Tile Mastic - (NOT OBSERVED)
094A	9"x9" Beige w/ Green Streaks VFT Mastic - (NOT

	OBSERVED)
098A	12x12 Light Brown w/ White & Dark Strks Floor Tile Mastic
099A	12x12 Gray Floor Tile Mastic
101A	12x12 Light Pink Floor Tile Mastic - (NOT OBSERVED)
102A	12x12 Light Brown w/ Speckles Floor Tile Mastic - (NOT OBSERVED)
103A	12x12 Beige w/ White Streaks VFT Mastic
107	12"x12" Tan w/ Brown & White Spots VFT Mastic
109	12"x12" Grey W/ Specks VFT Mastic
111A	12"x12" Black w/White Specks Floor Tile Mastic
112A	12"x12" Blue w/White Specks Floor Tile Mastic
113A	12"x12" White w/Specks Floor Tile Mastic
114A	12"x12" Light Blue w/Specks Floor Tile Mastic
115	Blue Carpet Adhesive
117	12"x12" Ceramic Tile Adhesive
120	12" X 12" yellow speckle, mastic
122	12" X 12" black with white specks, Mastic (DUPLICATE OF 004A, NOT OBSERVED)
124	12" X 12" yellow speckled, Mastic
126	12" X 12" black with dark brown specks, Mastic
128	12" X 12" blue speckled, mastic
130	12" X 12" gray speckled, Mastic

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Delores Fitzpatrick, IDPH License # 100-05183. The Management Plan was updated by Jigar Shah, IDPH License # 100-07342. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Kelvyn Park High School Building 1410 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Kelvyn Park High School Unit 46191 Building ID 1410

Address 4343 W. Wrightwood Ave. Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
001A	1'x1' Black w/ White Streaks Floor Tile (NOT OBSERVED)	13,500	SF	1st & 3rd Floor Corridors, 2nd Floor East Corridor, Room 303, 206 - 1918 Bldg. NOT OBSERVED in 1st Floor Corridor; 2nd Floor East Corridor; Rm 206	CHR	MISC	N	None	0		No	ACBM with the potential for damage		MODERATE
004A	1'x1' Black w/ White Streaks Floor Tile Mastic (NOT OBSERVED)	13,500	SF	1st & 3rd Floor Corridors, 2nd Floor East Corridor, Room 303, 206 - 1918 Bldg. NOT OBSERVED in 1st Floor Corridor; 2nd Floor East Corridor; Rm 206	CHR	MISC	N	None	0		No	ACBM with the potential for damage		LOW
006A	1'x1' Black w/ Brown Streaks Floor Tile (NOT OBSERVED)	900	SF	3rd Floor: Music Room & Vestibule, Rooms 319, 323, & 327 - 1928 Bldg. NOT OBSERVED in 3rd Floor: Music Room & Vestibule, Rm 323	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
007A	9"x9" Dark Red Floor Tile - (NOT OBSERVED)	4,000	SF	1st 2nd & 3rd Floor Corridors - 1928 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
008A	12x12 Black w/ Brown Streaks Floor Tile Mastic	2,400	SF	3rd Floor: Music Room & Vestibule, Rooms 319, 323, & 327 - 1928 Bldg. NOT OBSERVED in 3rd Floor: Music Room & Vestibule, Rm 323	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
009A	9"x9" Dark Red Floor Tile Mastic - (NOT OBSERVED)	4,000	SF	1st 2nd & 3rd Floor Corridors - 1928 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
017	Boiler Gasket (Removed)			Boiler Room - 1918 Bldg	ABATED	TSI	Y				No			

Chicago Public Schools

School Kelvyn Park High School Unit 46191 Building ID 1410

Address 4343 W. Wrightwood Ave. Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
018	Boiler Insulation (Removed)			Boiler Room - 1918 Bldg	ABATED	TSI	Y				No			
019	Boiler Lagging (Removed)			Boiler Room - 1918 Bldg	ABATED	TSI	Y				No			
020	Boiler Brick - REMOVED			Boiler Room - 1918 Bldg	ABATED	TSI					No			
040	Vent Debris (Removed)			Inside Ducts - Throughout 1918 Bldg	ABATED	MISC	Y				No			
057	Cardboard Pipe Insulation (Removed)			1st Floor Janitor Closet (West) - 1918 Bldg.	ABATED	TSI	Y				No			
058	Aircell Pipe Insulation (Removed)			1st Floor Janitor Close (West) - 1918 Bldg.	ABATED	TSI					No			
080	MJP E/F/V on Fiberglass Pipe Insulation	300	SF	1st Floor: Men's Toilet Pipe Chases, Rooms 119 & 123, Throughout Basement - 1928 Bldg.	ASSUMED	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
087	1'x1' Brown w/ White Streaks Floor Tile (NOT OBSERVED)	4,200	SF	Room 398, 300, 302, 304, 311 - 1918 Bldg	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
087A	1'x1' Brown w/ White Streaks Floor Tile Mastic	4,200	SF	Room 398, 300, 302, 304, 311 - 1918 Bldg	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
088	12x12 Off White w/ Speckles Floor Tile	6,400	SF	Room 398, 300, 302, 304, 311 - 1918 Bldg	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
088A	12x12 Off White w/ Speckles Floor Tile Mastic	6,400	SF	Room 398, 300, 302, 304, 311 - 1918 Bldg	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
090	12x12 Green W/White Speckles Floor Tile	2,500	SF	2nd Floor Kitchen - 1928	CHR	MISC	N	None	0		No	ACBM with the potential for damage		MODERATE
090A	12x12 Green w/White Speckles Floor Tile Mastic	2,500	SF	2nd Floor Kitchen - 1928 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
092	9"x9" Gray w/ Speckles Floor Tile - (NOT OBSERVED)	5,000	SF	Main Offices (211), Auditorium, 201 - 1918 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
092A	9"x9" Gray w/Speckles VFT Mastic - (NOT OBSERVED)	5,000	SF	Main Offices (211), Auditorium, 201 - 1918 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
093	9"x9" Light Brown Floor Tile - (NOT	2,700	SF	Room 205, 107	CHR	MISC	N	None	0		No	ACBM with the		LOW

Chicago Public Schools

School Kelvyn Park High School Unit 46191 Building ID 1410

Address 4343 W. Wrightwood Ave. Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
	OBSERVED)			Closet, 2nd Floor West Hall and Connecting Corridor - 1918 Bldg.								potential for damage		
093A	9"x9" Light Brown Floor Tile Mastic - (NOT OBSERVED)	3,000	SF	Room 205, 107 Vloset, 2nd Floor West Hall and Connecting Corridor - 1918 Bldg.	CHR	MISC	N	None	0		No	ACBM with the potential for damage		LOW
094	9"x9" Beige w/ Green Streaks Floor Tile - (NOT OBSERVED)	750	SF	Room 211 - 1918 Bldg.	CHR	MISC	N	None	0		No	ACBM with the potential for damage		LOW
094A	9"x9" Beige w/ Green Streaks VFT Mastic - (NOT OBSERVED)	1,200	SF	Room 211 - 1918 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
097	9"x9" Black Floor Tile - (NOT OBSERVED)	6,000	SF	1st, 2nd & 3rd Floor Corridors - 1928 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
097A	9"x9" Black Floor Tile Mastic - (NOT OBSERVED)	6,000	SF	1st, 2nd & 3rd Floor Corridors - 1928 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		Low
098	12x12 Light Brown w/ White & Dark Streaks Floor Tile	4,800	SF	Room 213, 215, 1st Floor East Corridor, 119, 123, 127, 129, 323, 217 - 1928 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
098A	12x12 Light Brown w/ White & Dark Strks Floor Tile Mastic	4,800	SF	Room 213, 215, 1st Floor East Corridor, 119, 123, 127, 129, 323, 217 - 1928 Bldg.	ANT	MISC	N	NONE	2		No	ACBM with the potential for damage		LOW
099	12x12 Gray Floor Tile	5,500	SF	3rd Fl: Computer Rm & Off; Rms: 113, 117, 123, 221 & 227 - 1928 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
099A	12x12 Gray Floor Tile Mastic	5,500	SF	3rd Fl: Computer Rm & Off; Rms: 113, 117, 123, 221 & 227 - 1928 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
100	12x12' Light Brown VFT - (NOT OBSERVED)	1,800	SF	3rd Floor Corridor to Room 314; Rooms: 121, 223 & 227 - 1928 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
100A	12x12 Light Brown Floor Tile Mastic - (NOT OBSERVED)	3,300	SF	3rd Floor Corridor to Room 314; Rooms: 121, & 227 - 1928 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Kelvyn Park High School Unit 46191 Building ID 1410

Address 4343 W. Wrightwood Ave. Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
101	12x12 Light Pink Floor Tile - (NOT OBSERVED)	1,600	SF	Rooms: 113, 125, 221 & 223 - 1928 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
101A	12x12 Light Pink Floor Tile Mastic - (NOT OBSERVED)	1,600	SF	Rooms: 113, 125, 221 & 223 - 1928 Bldg.	ASSUMED	MISC	N	None	0		No	ACBM with the potential for damage		LOW
102	12x12 Light Brown w/ Speckles Floor Tile - (NOT OBSERVED)	1,600	SF	Rooms: 113, 221, 223, 225 Storage & 227 inner room - 1928 Bldg. NOT OBSERVED in any of these locations during the 2013 Re-inspection.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
102A	12x12 Light Brown w/ Speckles Floor Tile Mastic - (NOT OBSERVED)	1,600	SF	Rooms: 113, 221, 223, 225 Storage & 227 inner room - 1928 Bldg. NOT OBSERVED in any of these locations during the 2013 Re-inspection.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
103	12x12 Light Beige w/ White Streaks Floor Tile	1,600	SF	Rooms 121, 123 & 125 - 1928 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
103A	12x12 Beige w/ White Streaks VFT Mastic	1,600	SF	Rooms 121, 123 & 125 - 1928 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
104	12"x12" Light Blue Floor Tile	2,150	SF	Room 312(not observed), Gym, ROTC, Library (100) - 1918	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
105	12"x12" Light Blue Floor Tile Mastic	2,150	SF	Room 312(not observed), Gym, ROTC, Library (100) - 1918	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
106	12"x12" Tan w/ Brown & White Spots VFT	4,000	SF	099, 101, 103, 105, 107, 109, 111, 309, 2nd Floor Hall Lockers - 1918 Room 312, Gym, ROTC, Library (100) - 1918 Rooms 121, 123 & 125 - 1928 Bldg. NOT OBSERVED in 2nd Floor Hall	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE

Chicago Public Schools

School Kelvyn Park High School Unit 46191 Building ID 1410

Address 4343 W. Wrightwood Ave. Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Lockers during the 2013 Re-inspection.										
107	12"x12" Tan w/ Brown & White Spots VFT Mastic	4,000	SF	099, 101, 103, 105, 107, 109, 111, 309, 2nd Floor Hall Lockers - 1918 Room 312, Gym, ROTC, Library (100) - 1918 Rooms 121, 123 & 125 - 1928 Bldg. NOT OBSERVED in 2nd Floor Hall Lockers during the 2013 Re-inspection.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
108	12"x12" Grey W/ Specks VFT	6,000	SF	1st Floor Corridor, Old Engineers Former Office - 1928	ASSUMED	MISC	N	None	0		No	ACBM with the potential for damage		MODERATE
109	12"x12" Grey W/ Specks VFT Mastic	6,000	SF	1st Floor Corridor, Old Engineers Former Office - 1928	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
110	Blue Linoleum	4,800	SF	Rooms: 115, 125, 221, 223, 225, 227 1928 Bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
110 A	Blue Linoleum Mastic	4,800	SF	Rooms: 115, 125, 221, 223, 225, 227 1928 Bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
111	12"x12" Black w/White Specks Floor Tile	800	SF	Music Room (313), 319, 323, 327 -1928 Bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
111A	12"x12" Black w/White Specks Floor Tile Mastic	800	SF	Music Room (313), 319, 323, 327 -1928 Bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
112	12"x12" Blue w/White Specks Floor Tile	700	SF	Music Room (313) - 1928 Bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
112A	12"x12" Blue w/White Specks Floor Tile Mastic	700	SF	Music Room (313) - 1928 Bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
113	12"x12" White w/Specks Floor Tile	1,400	SF	Room 316, 318, 216, 220 - 1999 Addition	ASSUMED	MISC	N	None	0		No	ACBM with the potential for damage		MODERATE
113A	12"x12" White w/Specks Floor Tile Mastic	1,400	SF	Room 316, 318, 216, 220 - 1999 Addition	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
114	12"x12" Light Blue w/Specks Floor Tile	1,400	SF	2nd Floor Lunchroom, room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE

Chicago Public Schools

School Kelvyn Park High School Unit 46191 Building ID 1410

Address 4343 W. Wrightwood Ave. Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				400 - 1918 Bldg.										
114A	12"x12" Light Blue w/Specks Floor Tile Mastic	1,400	SF	2nd Floor Lunchroom, Room 400 - 1918 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
115	Blue Carpet Adhesive	3,800	SF	Library, Main Office, Principal's Office and Rooms 104 and 211; 205, 207, 209A, 209B - 1918 Bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
116	12"x12" Ceramic Tile Grout	1,300	SF	Main Office, Library (100) - 1918 Bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
117	12"x12" Ceramic Tile Adhesive	1,300	SF	Main Office, Library (100) - 1918 Bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
118	2' X 4' white with swirls, ceiling tile	2,400	SF	Rms 216, 220, 316, 318 - 1999 Bldg.	ASSUMED	MISC	Y	NONE	0			ACBM with the potential for damage		LOW
119	12" X 12" yellow speckle, VFT	7,800	SF	1st and 2nd floor corridors, Auditorium - 1918 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
120	12" X 12" yellow speckle, mastic	7,800	SF	1st and 2nd floor corridors, Auditorium - 1918 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
121	12" X 12" black with white specks, VFT (DUPLICATE OF 001A NOT OBSERVED)	14,200	SF	2nd and 3rd floor corridors - 1928 bldg.	ASSUMED	MISC	N	NONE			No			MODERATE
122	12" X 12" black with white specks, Mastic (DUPLICATE OF 004A, NOT OBSERVED)	14,200	SF	2nd and 3rd floor corridors - 1928 bldg.	ASSUMED	MISC	N	NONE			No			LOW
123	12" X 12" yellow speckled VFT	3,600	SF	2nd and 3rd floor corridors - 1928 bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
124	12" X 12" yellow speckled, Mastic	3,600	SF	2nd and 3rd floor corridors - 1928 bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
125	12" X 12" black with dark brown specks, VFT	600	SF	Rm 206 - 1918 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
126	12" X 12" black with dark brown specks, Mastic	600	SF	Rm 206 - 1918 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
127	12" X 12" blue speckled, VFT	500	SF	Rm 211 - 1918 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
128	12" X 12" blue speckled, mastic	500	SF	Rm 211 - 1918 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Kelvyn Park High School Unit 46191 Building ID 1410

Address 4343 W. Wrightwood Ave. Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
129	12" X 12" gray speckled VFT	600	SF	Rm 211 - 1918 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
130	12" X 12" gray speckled, Mastic	600	SF	Rm 211 - 1918 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
131	Fume Hood	40	SF	Rm 223 - 1928 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
132	12x12 Gray, Black and beige VFT	2,400	SF	Rooms, 327, 323, 319	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
133	12x12 Gray, Black and beige VFT Mastic	2,400	SF	Rooms 327, 323, 319	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
134	12x12 Gray, Black and White VFT	3,350	SF	2nd floor main office, Rooms 105, 312	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
135	12x12 Gray, Black and White VFT Mastic	3,350	SF	2nd floor main office, Rooms 105, 312	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
136	12x12 Gray and Black VFT	5,600	SF	Rooms 107G, 205, 206, 211, 303, 304, 308	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
137	12x12 Gray and Black VFT Mastic	5,600	SF	Rooms 107G, 205, 206, 211, 303, 304, 308	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
138	12x12 White VFT	17,500	SF	1st and 3rd floor corridors	ASSUMED	MISC	Y	NONE	0		Yes	ACBM with the potential for damage		MODERATE
139	12x12 White VFT Mastic	17,500	SF	1st and 3rd floor corridors	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
56	Aircell Pipe Insulation (Removed)			SW Unexcavated Area - 1928	ABATED	TSI	Y				No			
B	2'x4' White Wormy Ceiling Tile	1,500	SF	Rooms: 206 Closet, 208 & 398, 302, 304 - 1918 Bldg.	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		MODERATE
C	2'x4' Multiple Color 1/4" Wormy Ceiling Tile (NOT OBSERVED)			Rooms 200 & 300 - 1918 Bldg.	ASSUMED	MISC	Y	None	0		No	ACBM with the potential for damage		MODERATE
D	2'x4' Dk Wht w/Multi Color 1/2" Wormy Ceiling Tile (NOT OBSERVED)	900	SF	Rooms 104 & 300 - 1918 Bldg.	ASSUMED	MISC	Y	None	0		No	ACBM with the potential for damage		MODERATE
E	2'x4' Off White Large Wormy Ceiling Tile	300	SF	Room 208 - 1918 Bldg.	ASSUMED	MISC	Y	None	0		No	ACBM with the potential for damage		MODERATE
F	1'x1' Off White Wormy Ceiling Tile	2,400	SF	ROTC, ROTC Office, Rooms 110 & 212, Engineer's Former Office - 1918 Bldg.	ASSUMED	MISC	Y	None	0		No	ACBM with the potential for damage		MODERATE
G	1'x1' Off White Large Wormy Ceiling Tile	1,500	SF	ROTC, Room 212, Cafeteria by	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		MODERATE

Chicago Public Schools

School Kelvyn Park High School Unit 46191 Building ID 1410

Address 4343 W. Wrightwood Ave. Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Lunchroom & Auditorium - 1918 Bldg.										
H	Spray - On Walls & Beams (NOT OBSERVED)	800	SF	3rd Floor Computer Room - 1928 Bldg.	ASSUMED	SURFACE	Y	None	0		No	ACBM with the potential for damage		MODERATE
I	18"x18" Dirty White Ceiling Tile	1,000	SF	3rd Floor Music Room - 1928 Bldg.	ASSUMED	MISC	Y	None	0		No	ACBM with the potential for damage		MODERATE
J	1'x1' Dirty White Ceiling Tile	200	SF	Room 314 East & West Vestibule - 1928 Bldg.	ASSUMED	MISC	Y	None	0		No	ACBM with the potential for damage		MODERATE
K	2'x4' Multiple Color 1/2" Wormy Ceiling Tile (NOT OBSERVED)	1,200	SF	Rms 127 & 220 - 1928 Bldg.	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		MODERATE
L	1'x1' White Wormy Ceiling Tile	1,400	SF	Rooms 123 and 213 - 1928 Bldg.	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		MODERATE
M	Transite Table Tops	1,200	SF	Rooms: 123, 125, 221, 223, 225, 227 - 1928 Bldg. (129 Abated in 2003)	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
N	Sheeted Walls	800	SF	1st Floor Supply Storage near Exit - 1928 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Kelvyn Park High School Unit 46191 Building ID 1410

Address 4343 W. Wrightwood Ave. Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

Inspector's Comments are Summarized at the End of the Report

Reinspection Date 3/9/2016
Inspector Name <u>Delores Fitzpatrick</u>
100-05183 2/13/2017
Inspector's IDPH License Number / Expiration Date

Inspector's Comments

HA Number:	Inspector Comments:
001A	
004A	
006A	
007A	
008A	
009A	
017	
018	
019	
020	
040	
057	
058	
080	
087	
087A	
088	
088A	
090	
090A	
092	
092A	
093	
093A	

Chicago Public Schools

School Kelvyn Park High School Unit 46191 Building ID 1410

Address 4343 W. Wrightwood Ave. Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
094	
094A	
097	
097A	
098	
098A	
099	
099A	
100	
100A	
101	
101A	
102	
102A	
103	
103A	
104	
105	
106	
107	
108	
109	
110	
110 A	
111	
111A	
112	
112A	
113	

Chicago Public Schools

School Kelvyn Park High School Unit 46191 Building ID 1410

Address 4343 W. Wrightwood Ave. Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
113A	
114	
114A	
115	
116	
117	
118	
119	
120	
121	
122	
123	
124	
125	
126	
127	
128	
129	
130	
131	
132	
133	
134	
135	
136	
137	
138	
139	
56	

Chicago Public Schools

School Kelvyn Park High School **Unit** 46191 **Building ID** 1410

Address 4343 W. Wrightwood Ave. **Region** 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
B	
C	
D	
E	
F	
G	
H	
I	
J	
K	
L	
M	
N	

Table II

Management Planner's Review

Chicago Public Schools

School Kelvyn Park High School
Address 4343 W. Wrightwood Ave.

Unit 46191
 Chicago, IL, 60639

Building ID 1410
Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
001A	1'x1' Black w/ White Streaks Floor Tile (NOT OBSERVED)	13,500	SF	1st & 3rd Floor Corridors, 2nd Floor East Corridor, Room 303, 206 - 1918 Bldg. NOT OBSERVED in 1st Floor Corridor; 2nd Floor East Corridor; Rm 206	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	
004A	1'x1' Black w/ White Streaks Floor Tile Mastic (NOT OBSERVED)	13,500	SF	1st & 3rd Floor Corridors, 2nd Floor East Corridor, Room 303, 206 - 1918 Bldg. NOT OBSERVED in 1st Floor Corridor; 2nd Floor East Corridor; Rm 206	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	
006A	1'x1' Black w/ Brown Streaks Floor Tile (NOT OBSERVED)	900	SF	3rd Floor: Music Room & Vestibule, Rooms 319, 323, & 327 - 1928 Bldg. NOT OBSERVED in 3rd Floor: Music Room & Vestibule, Rm 323	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	
007A	9"x9" Dark Red Floor Tile - (NOT OBSERVED)	4,000	SF	1st 2nd & 3rd Floor Corridors - 1928 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	
008A	12x12 Black w/ Brown Streaks Floor Tile Mastic	2,400	SF	3rd Floor: Music Room & Vestibule, Rooms 319, 323, & 327 - 1928 Bldg. NOT OBSERVED in 3rd Floor: Music Room & Vestibule, Rm 323	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
009A	9"x9" Dark Red Floor Tile Mastic - (NOT OBSERVED)	4,000	SF	1st 2nd & 3rd Floor Corridors - 1928 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	
017	Boiler Gasket (Removed)			Boiler Room - 1918 Bldg	Abated	TSI	Yes				
018	Boiler Insulation (Removed)			Boiler Room - 1918 Bldg	Abated	TSI	Yes				
019	Boiler Lagging (Removed)			Boiler Room - 1918 Bldg	Abated	TSI	Yes				
020	Boiler Brick - REMOVED			Boiler Room - 1918 Bldg	Abated	TSI					
040	Vent Debris (Removed)			Inside Ducts - Throughout 1918 Bldg	Abated	MISC	Yes				
057	Cardboard Pipe Insulation (Removed)			1st Floor Janitor Closet (West) - 1918 Bldg.	Abated	TSI	Yes				
058	Aircell Pipe Insulation (Removed)			1st Floor Janitor Close tWest) - 1918 Bldg.	Abated	TSI					
080	MJP E/F/V on Fiberglass Pipe Insulation	300	SF	1st Floor: Men's Toilet Pipe Chases, Rooms 119 & 123, Throughout Basement - 1928 Bldg.	Assumed	TSI	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
087	1'x1' Brown w/ White Streaks Floor Tile (NOT OBSERVED)	4,200	SF	Room 398, 300, 302, 304, 311 - 1918	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	

Chicago Public Schools

School Kelvyn Park High School
Address 4343 W. Wrightwood Ave.

Unit 46191
 Chicago, IL, 60639

Building ID 1410
Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
	OBSERVED)			Bldg							
087A	1'x1' Brown w/ White Streaks Floor Tile Mastic	4,200	SF	Room 398, 300, 302, 304, 311 - 1918 Bldg	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
088	12x12 Off White w/ Speckles Floor Tile	6,400	SF	Room 398, 300, 302, 304, 311 - 1918 Bldg	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
088A	12x12 Off White w/ Speckles Floor Tile Mastic	6,400	SF	Room 398, 300, 302, 304, 311 - 1918 Bldg	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
090	12x12 Green W/White Speckles Floor Tile	2,500	SF	2nd Floor Kitchen - 1928	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
090A	12x12 Green w/White Speckles Floor Tile Mastic	2,500	SF	2nd Floor Kitchen - 1928 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
092	9"x9" Gray w/ Speckles Floor Tile - (NOT OBSERVED)	5,000	SF	Main Offices (211), Auditorium, 201 - 1918 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
092A	9"x9" Gray w/Speckles VFT Mastic - (NOT OBSERVED)	5,000	SF	Main Offices (211), Auditorium, 201 - 1918 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
093	9"x9" Light Brown Floor Tile - (NOT OBSERVED)	2,700	SF	Room 205, 107 Closet, 2nd Floor West Hall and Connecting Corridor - 1918 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	
093A	9"x9" Light Brown Floor Tile Mastic - (NOT OBSERVED)	3,000	SF	Room 205, 107 Vloset, 2nd Floor West Hall and Connecting Corridor - 1918 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	
094	9"x9" Beige w/ Green Streaks Floor Tile - (NOT OBSERVED)	750	SF	Room 211 - 1918 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	
094A	9"x9" Beige w/ Green Streaks VFT Mastic - (NOT OBSERVED)	1,200	SF	Room 211 - 1918 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	
097	9"x9" Black Floor Tile - (NOT OBSERVED)	6,000	SF	1st, 2nd & 3rd Floor Corridors - 1928 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	
097A	9"x9" Black Floor Tile Mastic - (NOT OBSERVED)	6,000	SF	1st, 2nd & 3rd Floor Corridors - 1928 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	
098	12x12 Light Brown w/ White & Dark Streaks Floor Tile	4,800	SF	Room 213, 215, 1st Floor East Corridor, 119, 123, 127, 129, 323, 217 - 1928 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
098A	12x12 Light Brown w/ White & Dark Strks Floor Tile Mastic	4,800	SF	Room 213, 215, 1st Floor East Corridor, 119, 123, 127, 129, 323, 217 - 1928 Bldg.	Anthophyllite	MISC	No	2	SF	6 ACBM with the potential for damage	Follow O&M Plan
099	12x12 Gray Floor Tile	5,500	SF	3rd Fl: Computer Rm & Off; Rms: 113, 117, 123,, 221 & 227 - 1928 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
099A	12x12 Gray Floor Tile Mastic	5,500	SF	3rd Fl: Computer Rm & Off; Rms: 113,	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Kelvyn Park High School
Address 4343 W. Wrightwood Ave.

Unit 46191
 Chicago, IL, 60639

Building ID 1410
Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
100	12x12' Light Brown VFT - (NOT OBSERVED)	1,800	SF	117, 123, 221 & 227 - 1928 Bldg. 3rd Floor Corridor to Room 314; Rooms: 121, 223 & 227 - 1928 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	
100A	12x12 Light Brown Floor Tile Mastic - (NOT OBSERVED)	3,300	SF	3rd Floor Corridor to Room 314; Rooms: 121, & 227 - 1928 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	
101	12x12 Light Pink Floor Tile - (NOT OBSERVED)	1,600	SF	Rooms: 113, 125, 221 & 223 - 1928 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
101A	12x12 Light Pink Floor Tile Mastic - (NOT OBSERVED)	1,600	SF	Rooms: 113, 125, 221 & 223 - 1928 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
102	12x12 Light Brown w/ Speckles Floor Tile - (NOT OBSERVED)	1,600	SF	Rooms: 113, 221, 223, 225 Storage & 227 inner room - 1928 Bldg. NOT OBSERVED in any of these locations during the 2013 Re-inspection.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
102A	12x12 Light Brown w/ Speckles Floor Tile Mastic - (NOT OBSERVED)	1,600	SF	Rooms: 113, 221, 223, 225 Storage & 227 inner room - 1928 Bldg. NOT OBSERVED in any of these locations during the 2013 Re-inspection.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
103	12x12 Light Beige w/ White Streaks Floor Tile	1,600	SF	Rooms 121, 123 & 125 - 1928 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
103A	12x12 Beige w/ White Streaks VFT Mastic	1,600	SF	Rooms 121, 123 & 125 - 1928 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
104	12"x12" Light Blue Floor Tile	2,150	SF	Room 312(not observed), Gym, ROTC, Library (100) - 1918	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
105	12"x12" Light Blue Floor Tile Mastic	2,150	SF	Room 312(not observed), Gym, ROTC, Library (100) - 1918	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
106	12"x12" Tan w/ Brown & White Spots VFT	4,000	SF	099, 101, 103, 105, 107, 109, 111, 309, 2nd Floor Hall Lockers - 1918 Room 312, Gym, ROTC, Library (100) - 1918 Rooms 121, 123 & 125 - 1928 Bldg. NOT OBSERVED in 2nd Floor Hall Lockers during the 2013 Re-inspection.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
107	12"x12" Tan w/ Brown & White Spots VFT Mastic	4,000	SF	099, 101, 103, 105, 107, 109, 111, 309, 2nd Floor Hall Lockers - 1918 Room 312, Gym, ROTC, Library (100) -	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Kelvyn Park High School

Unit 46191

Building ID 1410

Address 4343 W. Wrightwood Ave.

Chicago, IL, 60639

Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				1918 Rooms 121, 123 & 125 - 1928 Bldg. NOT OBSERVED in 2nd Floor Hall Lockers during the 2013 Re- inspection.							
108	12"x12" Grey W/ Specks VFT	6,000	SF	1st Floor Corridor, Old Engineers Former Office - 1928	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
109	12"x12" Grey W/ Specks VFT Mastic	6,000	SF	1st Floor Corridor, Old Engineers Former Office - 1928	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
110	Blue Linoleum	4,800	SF	Rooms: 115, 125, 221, 223, 225, 227 1928 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
110 A	Blue Linoleum Mastic	4,800	SF	Rooms: 115, 125, 221, 223, 225, 227 1928 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
111	12"x12" Black w/White Specks Floor Tile	800	SF	Music Room (313), 319, 323, 327 - 1928 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
111A	12"x12" Black w/White Specks Floor Tile Mastic	800	SF	Music Room (313), 319, 323, 327 - 1928 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
112	12"x12" Blue w/White Specks Floor Tile	700	SF	Music Room (313) - 1928 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
112A	12"x12" Blue w/White Specks Floor Tile Mastic	700	SF	Music Room (313) - 1928 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
113	12"x12" White w/Specks Floor Tile	1,400	SF	Room 316, 318, 216, 220 - 1999 Addition	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
113A	12"x12" White w/Specks Floor Tile Mastic	1,400	SF	Room 316, 318, 216, 220 - 1999 Addition	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
114	12"x12" Light Blue w/Specks Floor Tile	1,400	SF	2nd Floor Lunchroom, room 400 - 1918 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
114A	12"x12" Light Blue w/Specks Floor Tile Mastic	1,400	SF	2nd Floor Lunchroom, Room 400 - 1918 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
115	Blue Carpet Adhesive	3,800	SF	Library, Main Office, Principal's Office and Rooms 104 and 211; 205, 207, 209A, 209B - 1918 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
116	12"x12" Ceramic Tile Grout	1,300	SF	Main Office, Library (100) - 1918 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
117	12"x12" Ceramic Tile Adhesive	1,300	SF	Main Office, Library (100) - 1918 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
118	2' X 4' white with swirls, ceiling tile	2,400	SF	Rms 216, 220, 316, 318 - 1999 Bldg.	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
119	12" X 12" yellow speckle, VFT	7,800	SF	1st and 2nd floor corridors, Auditorium - 1918 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
120	12" X 12" yellow speckle, mastic	7,800	SF	1st and 2nd floor corridors, Auditorium -	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Kelvyn Park High School

Unit 46191

Building ID 1410

Address 4343 W. Wrightwood Ave.

Chicago, IL, 60639

Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				1918 Bldg.							
121	12" X 12" black with white specks, VFT (DUPLICATE OF 001A NOT OBSERVED)	14,200	SF	2nd and 3rd floor corridors - 1928 bldg.	Assumed	MISC	No		SF		
122	12" X 12" black with white specks, Mastic (DUPLICATE OF 004A, NOT OBSERVED)	14,200	SF	2nd and 3rd floor corridors - 1928 bldg.	Assumed	MISC	No		SF		
123	12" X 12" yellow speckled VFT	3,600	SF	2nd and 3rd floor corridors - 1928 bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
124	12" X 12" yellow speckled, Mastic	3,600	SF	2nd and 3rd floor corridors - 1928 bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
125	12" X 12" black with dark brown specks, VFT	600	SF	Rm 206 - 1918 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
126	12" X 12" black with dark brown specks, Mastic	600	SF	Rm 206 - 1918 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
127	12" X 12" blue speckled, VFT	500	SF	Rm 211 - 1918 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
128	12" X 12" blue speckled, mastic	500	SF	Rm 211 - 1918 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
129	12" X 12" gray speckled VFT	600	SF	Rm 211 - 1918 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
130	12" X 12" gray speckled, Mastic	600	SF	Rm 211 - 1918 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
131	Fume Hood	40	SF	Rm 223 - 1928 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
132	12x12 Gray, Black and beige VFT	2,400	SF	Rooms, 327, 323, 319	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
133	12x12 Gray, Black and beige VFT Mastic	2,400	SF	Rooms 327, 323, 319	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
134	12x12 Gray, Black and White VFT	3,350	SF	2nd floor main office, Rooms 105, 312	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
135	12x12 Gray, Black and White VFT Mastic	3,350	SF	2nd floor main office, Rooms 105, 312	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
136	12x12 Gray and Black VFT	5,600	SF	Rooms 107G, 205, 206, 211, 303, 304, 308	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
137	12x12 Gray and Black VFT Mastic	5,600	SF	Rooms 107G, 205, 206, 211, 303, 304, 308	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
138	12x12 White VFT	17,500	SF	1st and 3rd floor corridors	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
139	12x12 White VFT Mastic	17,500	SF	1st and 3rd floor corridors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
56	Aircell Pipe Insulation (Removed)			SW Unexcavated Area - 1928	Abated	TSI	Yes				
B	2'x4' White Wormy Ceiling Tile	1,500	SF	Rooms: 206 Closet, 208 & 398, 302, 304 - 1918 Bldg.	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
C	2'x4' Multiple Color 1/4" Wormy Ceiling Tile (NOT OBSERVED)			Rooms 200 & 300 - 1918 Bldg.	Assumed	MISC	Yes	0		6 ACBM with the potential for damage	
D	2'x4' Dk Wht w/Multi Color 1/2" Wormy Ceiling Tile (NOT OBSERVED)	900	SF	Rooms 104 & 300 - 1918 Bldg.	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	
E	2'x4' Off White Large Wormy Ceiling Tile	300	SF	Room 208 - 1918 Bldg.	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
F	1'x1' Off White Wormy Ceiling Tile	2,400	SF	ROTC, ROTC Office, Rooms 110 & 212, Engineer's Former Office - 1918 Bldg.	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Kelvyn Park High School
Address 4343 W. Wrightwood Ave.

Unit 46191
 Chicago, IL, 60639

Building ID 1410
Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
G	1'x1' Off White Large Wormy Ceiling Tile	1,500	SF	ROTC, Room 212, Cafeteria by Lunchroom & Auditorium - 1918 Bldg.	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
H	Spray - On Walls & Beams (NOT OBSERVED)	800	SF	3rd Floor Computer Room - 1928 Bldg.	Assumed	SURFACE	Yes	0	SF	6 ACBM with the potential for damage	
I	18"x18" Dirty White Ceiling Tile	1,000	SF	3rd Floor Music Room - 1928 Bldg.	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
J	1'x1' Dirty White Ceiling Tile	200	SF	Room 314 East & West Vestibule - 1928 Bldg.	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
K	2'x4' Multiple Color 1/2" Wormy Ceiling Tile (NOT OBSERVED)	1,200	SF	Rms 127 & 220 - 1928 Bldg.	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	
L	1'x1' White Wormy Ceiling Tile	1,400	SF	Rooms 123 and 213 - 1928 Bldg.	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
M	Transite Table Tops	1,200	SF	Rooms: 123, 125, 221, 223, 225, 227 - 1928 Bldg. (129 Abated in 2003)	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
N	Sheeted Walls	800	SF	1st Floor Supply Storage near Exit - 1928 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Kelvyn Park High School
Address 4343 W. Wrightwood Ave.

Unit 46191
 Chicago, IL, 60639

Building ID 1410
Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG Consultants, Inc.
 855 W. Adams St., Ste. 200
 Phone: (312) 733-6262

Fax: (312) 733-5612

Management Planner's Comments Summarized at the End of the Report

Review Date	6/21/2016
Manager Planner Name	Jigar Shah
100-07342	1/19/2017
Manager IDPH License No/Expiration	

HA Number	Management Comments
001A	
004A	
006A	
007A	
008A	
009A	
017	
018	
019	
020	
040	
057	
058	
080	
087	
087A	
088	
088A	
090	
090A	
092	
092A	
093	
093A	

Chicago Public Schools

School Kelvyn Park High School

Unit 46191

Building ID 1410

Address 4343 W. Wrightwood Ave.

Chicago, IL, 60639

Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
094	
094A	
097	
097A	
098	
098A	Repair Damaged ACM and Follow O&M
099	
099A	
100	
100A	
101	
101A	
102	
102A	
103	
103A	
104	
105	
106	
107	
108	
109	
110	
110 A	
111	
111A	
112	

Chicago Public Schools

School Kelvyn Park High School

Unit 46191

Building ID 1410

Address 4343 W. Wrightwood Ave.

Chicago, IL, 60639

Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
112A	
113	
113A	
114	
114A	
115	
116	
117	
118	
119	
120	
121	
122	
123	
124	
125	
126	
127	
128	
129	
130	
131	
132	
133	
134	
135	
136	

Chicago Public Schools

School Kelvyn Park High School

Unit 46191

Building ID 1410

Address 4343 W. Wrightwood Ave.

Chicago, IL, 60639

Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
137	
138	
139	
56	
B	
C	
D	
E	
F	
G	
H	
I	
J	
K	
L	
M	
N	

Chicago Public Schools

GSG Consultants, Inc.

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUIDLING ID: **1410**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Kelvyn Park High School** INSPECTION DATE: **3/9/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **001A**
MATERIAL DESCRIPTION: **1'x1' Black w/ White Streaks Floor Tile (NOT OBSERVED)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **1st & 3rd Floor Corridors, 2nd Floor East Corridor, Room 303, 206 - 1918 Bldg.
NOT OBSERVED in 1st Floor Corridor; 2nd Floor East Corridor; Rm 206**

MATERIAL QUANTITY: **13500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/09/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUIDLING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **6/21/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **001A**
MATERIAL DESCRIPTION: **1'x1' Black w/ White Streaks Floor Tile (NOT OBSERVED)**
MATERIAL LOCATION: **1st & 3rd Floor Corridors, 2nd Floor East Corridor, Room 303, 206 - 1918 Bldg. NOT OBSERVED in 1st Floor Corridor; 2nd Floor East Corridor; Rm 206**
MATERIAL QUANTITY: **13500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **06/21/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUIDLING ID: **1410**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Kelvyn Park High School** INSPECTION DATE: **3/9/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **004A**
MATERIAL DESCRIPTION: **1'x1' Black w/ White Streaks Floor Tile Mastic (NOT OBSERVED)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st & 3rd Floor Corridors, 2nd Floor East Corridor, Room 303, 206 - 1918 Bldg.**

NOT OBSERVED in 1st Floor Corridor; 2nd Floor East Corridor; Rm 206

MATERIAL QUANTITY: **13500**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/09/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUIDLING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **6/21/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **004A**
MATERIAL DESCRIPTION: **1'x1' Black w/ White Streaks Floor Tile Mastic (NOT OBSERVED)**
MATERIAL LOCATION: **1st & 3rd Floor Corridors, 2nd Floor East Corridor, Room 303, 206 - 1918 Bldg.**
NOT OBSERVED in 1st Floor Corridor; 2nd Floor East Corridor; Rm 206
MATERIAL QUANTITY: **13500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/21/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUIDLING ID: **1410**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Kelvyn Park High School** INSPECTION DATE: **3/9/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **006A**
MATERIAL DESCRIPTION: **1'x1' Black w/ Brown Streaks Floor Tile (NOT OBSERVED)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **3rd Floor: Music Room & Vestibule, Rooms 319, 323, & 327 - 1928 Bldg.
NOT OBSERVED in 3rd Floor: Music Room & Vestibule, Rm 323**

MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUILDING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **6/21/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **006A**
MATERIAL DESCRIPTION: **1'x1' Black w/ Brown Streaks Floor Tile (NOT OBSERVED)**
MATERIAL LOCATION: **3rd Floor: Music Room & Vestibule, Rooms 319, 323, & 327 - 1928 Bldg.
NOT OBSERVED in 3rd Floor: Music Room & Vestibule, Rm 323**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **06/21/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUIDLING ID: **1410**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Kelvyn Park High School** INSPECTION DATE: **3/9/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **007A**
MATERIAL DESCRIPTION: **9"x9" Dark Red Floor Tile - (NOT OBSERVED)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **1st 2nd & 3rd Floor Corridors - 1928 Bldg.**
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 03/09/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUILDING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **6/21/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **007A**
MATERIAL DESCRIPTION: **9"x9" Dark Red Floor Tile - (NOT OBSERVED)**
MATERIAL LOCATION: **1st 2nd & 3rd Floor Corridors - 1928 Bldg.**
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **06/21/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUIDLING ID: **1410**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Kelvyn Park High School** INSPECTION DATE: **3/9/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **008A**
MATERIAL DESCRIPTION: **12x12 Black w/ Brown Streaks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **3rd Floor: Music Room & Vestibule, Rooms 319, 323, & 327 - 1928 Bldg.
NOT OBSERVED in 3rd Floor: Music Room & Vestibule, Rm 323**

MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUIDLING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **6/21/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **008A**
MATERIAL DESCRIPTION: **12x12 Black w/ Brown Streaks Floor Tile Mastic**
MATERIAL LOCATION: **3rd Floor: Music Room & Vestibule, Rooms 319, 323, & 327 - 1928 Bldg.
NOT OBSERVED in 3rd Floor: Music Room & Vestibule, Rm 323**
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **06/21/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUIDLING ID: **1410**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Kelvyn Park High School** INSPECTION DATE: **3/9/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **009A**
MATERIAL DESCRIPTION: **9"x9" Dark Red Floor Tile Mastic - (NOT OBSERVED)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st 2nd & 3rd Floor Corridors - 1928 Bldg.**
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/09/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUILDING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **6/21/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **009A**
MATERIAL DESCRIPTION: **9"x9" Dark Red Floor Tile Mastic - (NOT OBSERVED)**
MATERIAL LOCATION: **1st 2nd & 3rd Floor Corridors - 1928 Bldg.**
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **06/21/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUIDLING ID: **1410**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Kelvyn Park High School** INSPECTION DATE: **3/9/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **017**
MATERIAL DESCRIPTION: **Boiler Gasket (Removed)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room - 1918 Bldg**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUILDING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **6/21/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **017**
MATERIAL DESCRIPTION: **Boiler Gasket (Removed)**
MATERIAL LOCATION: **Boiler Room - 1918 Bldg**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: **06/21/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUIDLING ID: **1410**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Kelvyn Park High School** INSPECTION DATE: **3/9/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **018**
MATERIAL DESCRIPTION: **Boiler Insulation (Removed)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room - 1918 Bldg**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUILDING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **6/21/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **018**
MATERIAL DESCRIPTION: **Boiler Insulation (Removed)**
MATERIAL LOCATION: **Boiler Room - 1918 Bldg**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **06/21/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUIDLING ID: **1410**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Kelvyn Park High School** INSPECTION DATE: **3/9/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **019**
MATERIAL DESCRIPTION: **Boiler Lagging (Removed)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room - 1918 Bldg**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUILDING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **6/21/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **019**
MATERIAL DESCRIPTION: **Boiler Lagging (Removed)**
MATERIAL LOCATION: **Boiler Room - 1918 Bldg**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **06/21/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUIDLING ID: **1410**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Kelvyn Park High School** INSPECTION DATE: **3/9/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **020**
MATERIAL DESCRIPTION: **Boiler Brick - REMOVED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room - 1918 Bldg**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUILDING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **6/21/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **020**
MATERIAL DESCRIPTION: **Boiler Brick - REMOVED**
MATERIAL LOCATION: **Boiler Room - 1918 Bldg**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **06/21/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUIDLING ID: **1410**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Kelvyn Park High School** INSPECTION DATE: **3/9/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **040**
MATERIAL DESCRIPTION: **Vent Debris (Removed)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Inside Ducts - Throughout 1918 Bldg**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUILDING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **6/21/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **040**
MATERIAL DESCRIPTION: **Vent Debris (Removed)**
MATERIAL LOCATION: **Inside Ducts - Throughout 1918 Bldg**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **06/21/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 46191 BUILDING ID: 1410
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Delores Fitzpatrick
SCHOOL NAME: Kelvyn Park High School INSPECTION DATE: 3/9/2016
ADDRESS: 4343 W. Wrightwood Ave. IDPH LICENSE NO: 100-05183

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 057
MATERIAL DESCRIPTION: Cardboard Pipe Insulation (Removed)
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: Abated FRIABLE: Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1st Floor Janitor Closet (West) - 1918 Bldg.

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____



Date: 03/09/2016 _____

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUILDING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **6/21/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **057**
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation (Removed)**
MATERIAL LOCATION: **1st Floor Janitor Closet (West) - 1918 Bldg.**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **06/21/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 46191 BUIDLING ID: 1410
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Delores Fitzpatrick
SCHOOL NAME: Kelvyn Park High School INSPECTION DATE: 3/9/2016
ADDRESS: 4343 W. Wrightwood Ave. IDPH LICENSE NO: 100-05183

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 058
MATERIAL DESCRIPTION: Aircell Pipe Insulation (Removed)
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: Abated FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1st Floor Janitor Close tWest) - 1918 Bldg.

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 03/09/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUILDING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **6/21/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **058**
MATERIAL DESCRIPTION: **Aircell Pipe Insulation (Removed)**
MATERIAL LOCATION: **1st Floor Janitor Close tWest) - 1918 Bldg.**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **06/21/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUIDLING ID: **1410**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Kelvyn Park High School** INSPECTION DATE: **3/9/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **080**
MATERIAL DESCRIPTION: **MJP E/F/V on Fiberglass Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st Floor: Men's Toilet Pipe Chases, Rooms 119 & 123, Throughout Basement - 1928 Bldg.**

MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUIDLING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **6/21/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **080**
MATERIAL DESCRIPTION: **MJP E/F/V on Fiberglass Pipe Insulation**
MATERIAL LOCATION: **1st Floor: Men's Toilet Pipe Chases, Rooms 119 & 123, Throughout Basement - 1928 Bldg.**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **06/21/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUIDLING ID: **1410**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Kelvyn Park High School** INSPECTION DATE: **3/9/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **087**
MATERIAL DESCRIPTION: **1'x1' Brown w/ White Streaks Floor Tile (NOT OBSERVED)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Room 398, 300, 302, 304, 311 - 1918 Bldg**
MATERIAL QUANTITY: **4200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 03/09/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUILDING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **6/21/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **087**
MATERIAL DESCRIPTION: **1'x1' Brown w/ White Streaks Floor Tile (NOT OBSERVED)**
MATERIAL LOCATION: **Room 398, 300, 302, 304, 311 - 1918 Bldg**
MATERIAL QUANTITY: **4200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **06/21/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUIDLING ID: **1410**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Kelvyn Park High School** INSPECTION DATE: **3/9/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **087A**
MATERIAL DESCRIPTION: **1'x1' Brown w/ White Streaks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 398, 300, 302, 304, 311 - 1918 Bldg**
MATERIAL QUANTITY: **4200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUILDING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **6/21/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **087A**
MATERIAL DESCRIPTION: **1'x1' Brown w/ White Streaks Floor Tile Mastic**
MATERIAL LOCATION: **Room 398, 300, 302, 304, 311 - 1918 Bldg**
MATERIAL QUANTITY: **4200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **06/21/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUIDLING ID: **1410**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Kelvyn Park High School** INSPECTION DATE: **3/9/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **088**
MATERIAL DESCRIPTION: **12x12 Off White w/ Speckles Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Room 398, 300, 302, 304, 311 - 1918 Bldg**
MATERIAL QUANTITY: **6400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 03/09/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUILDING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **6/21/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **088**
MATERIAL DESCRIPTION: **12x12 Off White w/ Speckles Floor Tile**
MATERIAL LOCATION: **Room 398, 300, 302, 304, 311 - 1918 Bldg**
MATERIAL QUANTITY: **6400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **06/21/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUIDLING ID: **1410**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Kelvyn Park High School** INSPECTION DATE: **3/9/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **088A**
MATERIAL DESCRIPTION: **12x12 Off White w/ Speckles Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 398, 300, 302, 304, 311 - 1918 Bldg**
MATERIAL QUANTITY: **6400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUILDING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **6/21/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **088A**
MATERIAL DESCRIPTION: **12x12 Off White w/ Speckles Floor Tile Mastic**
MATERIAL LOCATION: **Room 398, 300, 302, 304, 311 - 1918 Bldg**
MATERIAL QUANTITY: **6400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **06/21/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUIDLING ID: **1410**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Kelvyn Park High School** INSPECTION DATE: **3/9/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **090**
MATERIAL DESCRIPTION: **12x12 Green W/White Speckles Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **2nd Floor Kitchen - 1928**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 03/09/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUILDING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **6/21/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **090**
MATERIAL DESCRIPTION: **12x12 Green W/White Speckles Floor Tile**
MATERIAL LOCATION: **2nd Floor Kitchen - 1928**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **06/21/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUIDLING ID: **1410**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Kelvyn Park High School** INSPECTION DATE: **3/9/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **090A**
MATERIAL DESCRIPTION: **12x12 Green w/White Speckles Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **2nd Floor Kitchen - 1928 Bldg.**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUILDING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **6/21/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **090A**
MATERIAL DESCRIPTION: **12x12 Green w/White Speckles Floor Tile Mastic**
MATERIAL LOCATION: **2nd Floor Kitchen - 1928 Bldg.**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **06/21/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUIDLING ID: **1410**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Kelvyn Park High School** INSPECTION DATE: **3/9/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **092**
MATERIAL DESCRIPTION: **9"x9" Gray w/ Speckles Floor Tile - (NOT OBSERVED)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Main Offices (211), Auditorium, 201 - 1918 Bldg.**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/09/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUILDING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **6/21/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **092**
MATERIAL DESCRIPTION: **9"x9" Gray w/ Speckles Floor Tile - (NOT OBSERVED)**
MATERIAL LOCATION: **Main Offices (211), Auditorium, 201 - 1918 Bldg.**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **06/21/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUIDLING ID: **1410**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Kelvyn Park High School** INSPECTION DATE: **3/9/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **092A**
MATERIAL DESCRIPTION: **9"x9" Gray w/Speckles VFT Mastic - (NOT OBSERVED)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Main Offices (211), Auditorium, 201 - 1918 Bldg.**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc.

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUIDLING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **6/21/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **092A**
MATERIAL DESCRIPTION: **9"x9" Gray w/Speckles VFT Mastic - (NOT OBSERVED)**
MATERIAL LOCATION: **Main Offices (211), Auditorium, 201 - 1918 Bldg.**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **06/21/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUIDLING ID: **1410**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Kelvyn Park High School** INSPECTION DATE: **3/9/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **093**
MATERIAL DESCRIPTION: **9"x9" Light Brown Floor Tile - (NOT OBSERVED)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 205, 107 Closet, 2nd Floor West Hall and Connecting Corridor - 1918 Bldg.**
MATERIAL QUANTITY: **2700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/09/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUIDLING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **6/21/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **093**
MATERIAL DESCRIPTION: **9"x9" Light Brown Floor Tile - (NOT OBSERVED)**
MATERIAL LOCATION: **Room 205, 107 Closet, 2nd Floor West Hall and Connecting Corridor - 1918 Bldg.**
MATERIAL QUANTITY: **2700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **06/21/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUIDLING ID: **1410**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Kelvyn Park High School** INSPECTION DATE: **3/9/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **093A**
MATERIAL DESCRIPTION: **9"x9" Light Brown Floor Tile Mastic - (NOT OBSERVED)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 205, 107 Vloset, 2nd Floor West Hall and Connecting Corridor - 1918 Bldg.**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/09/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUIDLING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **6/21/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **093A**
MATERIAL DESCRIPTION: **9"x9" Light Brown Floor Tile Mastic - (NOT OBSERVED)**
MATERIAL LOCATION: **Room 205, 107 Vloset, 2nd Floor West Hall and Connecting Corridor - 1918 Bldg.**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **06/21/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUIDLING ID: **1410**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Kelvyn Park High School** INSPECTION DATE: **3/9/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **094**
MATERIAL DESCRIPTION: **9"x9" Beige w/ Green Streaks Floor Tile - (NOT OBSERVED)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 211 - 1918 Bldg.**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/09/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUILDING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **6/21/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **094**
MATERIAL DESCRIPTION: **9"x9" Beige w/ Green Streaks Floor Tile - (NOT OBSERVED)**
MATERIAL LOCATION: **Room 211 - 1918 Bldg.**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **06/21/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUIDLING ID: **1410**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Kelvyn Park High School** INSPECTION DATE: **3/9/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **094A**
MATERIAL DESCRIPTION: **9"x9" Beige w/ Green Streaks VFT Mastic - (NOT OBSERVED)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 211 - 1918 Bldg.**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/09/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUILDING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **6/21/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **094A**
MATERIAL DESCRIPTION: **9"x9" Beige w/ Green Streaks VFT Mastic - (NOT OBSERVED)**
MATERIAL LOCATION: **Room 211 - 1918 Bldg.**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **06/21/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUIDLING ID: **1410**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Kelvyn Park High School** INSPECTION DATE: **3/9/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **097**
MATERIAL DESCRIPTION: **9"x9" Black Floor Tile - (NOT OBSERVED)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st, 2nd & 3rd Floor Corridors - 1928 Bldg.**
MATERIAL QUANTITY: **6000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUILDING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **6/21/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **097**
MATERIAL DESCRIPTION: **9"x9" Black Floor Tile - (NOT OBSERVED)**
MATERIAL LOCATION: **1st, 2nd & 3rd Floor Corridors - 1928 Bldg.**
MATERIAL QUANTITY: **6000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **06/21/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUIDLING ID: **1410**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Kelvyn Park High School** INSPECTION DATE: **3/9/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **097A**
MATERIAL DESCRIPTION: **9"x9" Black Floor Tile Mastic - (NOT OBSERVED)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**
MATERIAL LOCATION: **1st, 2nd & 3rd Floor Corridors - 1928 Bldg.**
MATERIAL QUANTITY: **6000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/09/2016

Chicago Public Schools

GSG Consultants, Inc.

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUIDLING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **6/21/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **097A**
MATERIAL DESCRIPTION: **9"x9" Black Floor Tile Mastic - (NOT OBSERVED)**
MATERIAL LOCATION: **1st, 2nd & 3rd Floor Corridors - 1928 Bldg.**
MATERIAL QUANTITY: **6000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **06/21/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUIDLING ID: **1410**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Kelvyn Park High School** INSPECTION DATE: **3/9/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **098**
MATERIAL DESCRIPTION: **12x12 Light Brown w/ White & Dark Streaks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Room 213, 215, 1st Floor East Corridor, 119, 123, 127, 129, 323, 217 - 1928 Bldg.**
MATERIAL QUANTITY: **4800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/09/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUILDING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **6/21/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **098**
MATERIAL DESCRIPTION: **12x12 Light Brown w/ White & Dark Streaks Floor Tile**
MATERIAL LOCATION: **Room 213, 215, 1st Floor East Corridor, 119, 123, 127, 129, 323, 217 - 1928 Bldg.**
MATERIAL QUANTITY: **4800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **06/21/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUIDLING ID: **1410**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Kelvyn Park High School** INSPECTION DATE: **3/9/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **098A**
MATERIAL DESCRIPTION: **12x12 Light Brown w/ White & Dark Strks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Anthophyllite** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 213, 215, 1st Floor East Corridor, 119, 123, 127, 129, 323, 217 - 1928 Bldg.**
MATERIAL QUANTITY: **4800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/09/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUIDLING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **6/21/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **098A**
MATERIAL DESCRIPTION: **12x12 Light Brown w/ White & Dark Strks Floor Tile Mastic**
MATERIAL LOCATION: **Room 213, 215, 1st Floor East Corridor, 119, 123, 127, 129, 323, 217 - 1928 Bldg.**
MATERIAL QUANTITY: **4800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **2** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Repair Damaged ACM and Follow O&M

Management Planner's Signature: _____

Jigar Shah

Date: **06/21/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUIDLING ID: **1410**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Kelvyn Park High School** INSPECTION DATE: **3/9/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **099**
MATERIAL DESCRIPTION: **12x12 Gray Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **3rd Fl: Computer Rm & Off; Rms: 113, 117, 123,, 221 & 227 - 1928 Bldg.**
MATERIAL QUANTITY: **5500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 03/09/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUIDLING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **6/21/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **099**
MATERIAL DESCRIPTION: **12x12 Gray Floor Tile**
MATERIAL LOCATION: **3rd Fl: Computer Rm & Off; Rms: 113, 117, 123,, 221 & 227 - 1928 Bldg.**
MATERIAL QUANTITY: **5500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **06/21/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUIDLING ID: **1410**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Kelvyn Park High School** INSPECTION DATE: **3/9/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **099A**
MATERIAL DESCRIPTION: **12x12 Gray Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **3rd Fl: Computer Rm & Off; Rms: 113, 117, 123, 221 & 227 - 1928 Bldg.**
MATERIAL QUANTITY: **5500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUIDLING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **6/21/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **099A**
MATERIAL DESCRIPTION: **12x12 Gray Floor Tile Mastic**
MATERIAL LOCATION: **3rd Fl: Computer Rm & Off; Rms: 113, 117, 123, 221 & 227 - 1928 Bldg.**
MATERIAL QUANTITY: **5500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **06/21/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUIDLING ID: **1410**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Kelvyn Park High School** INSPECTION DATE: **3/9/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **100**
MATERIAL DESCRIPTION: **12x12' Light Brown VFT - (NOT OBSERVED)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **3rd Floor Corridor to Room 314; Rooms: 121, 223 & 227 - 1928 Bldg.**
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUIDLING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **6/21/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **100**
MATERIAL DESCRIPTION: **12x12' Light Brown VFT - (NOT OBSERVED)**
MATERIAL LOCATION: **3rd Floor Corridor to Room 314; Rooms: 121, 223 & 227 - 1928 Bldg.**
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **06/21/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUIDLING ID: **1410**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Kelvyn Park High School** INSPECTION DATE: **3/9/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **100A**
MATERIAL DESCRIPTION: **12x12 Light Brown Floor Tile Mastic - (NOT OBSERVED)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **3rd Floor Corridor to Room 314; Rooms: 121, & 227 - 1928 Bldg.**

MATERIAL QUANTITY: **3300**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUIDLING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **6/21/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **100A**
MATERIAL DESCRIPTION: **12x12 Light Brown Floor Tile Mastic - (NOT OBSERVED)**
MATERIAL LOCATION: **3rd Floor Corridor to Room 314; Rooms: 121, & 227 - 1928 Bldg.**
MATERIAL QUANTITY: **3300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **06/21/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUIDLING ID: **1410**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Kelvyn Park High School** INSPECTION DATE: **3/9/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **101**
MATERIAL DESCRIPTION: **12x12 Light Pink Floor Tile - (NOT OBSERVED)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Rooms: 113, 125, 221 & 223 - 1928 Bldg.**
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUILDING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **6/21/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **101**
MATERIAL DESCRIPTION: **12x12 Light Pink Floor Tile - (NOT OBSERVED)**
MATERIAL LOCATION: **Rooms: 113, 125, 221 & 223 - 1928 Bldg.**
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **06/21/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUIDLING ID: **1410**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Kelvyn Park High School** INSPECTION DATE: **3/9/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **101A**
MATERIAL DESCRIPTION: **12x12 Light Pink Floor Tile Mastic - (NOT OBSERVED)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms: 113, 125, 221 & 223 - 1928 Bldg.**

MATERIAL QUANTITY: **1600**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/09/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUIDLING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **6/21/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **101A**
MATERIAL DESCRIPTION: **12x12 Light Pink Floor Tile Mastic - (NOT OBSERVED)**
MATERIAL LOCATION: **Rooms: 113, 125, 221 & 223 - 1928 Bldg.**
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **06/21/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUIDLING ID: **1410**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Kelvyn Park High School** INSPECTION DATE: **3/9/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **102**
MATERIAL DESCRIPTION: **12x12 Light Brown w/ Speckles Floor Tile - (NOT OBSERVED)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Rooms: 113, 221, 223, 225 Storage & 227 inner room - 1928 Bldg.
NOT OBSERVED in any of these locations during the 2013 Re-inspection.**

MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/09/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUILDING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **6/21/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **102**
MATERIAL DESCRIPTION: **12x12 Light Brown w/ Speckles Floor Tile - (NOT OBSERVED)**
MATERIAL LOCATION: **Rooms: 113, 221, 223, 225 Storage & 227 inner room - 1928 Bldg.
NOT OBSERVED in any of these locations during the 2013 Re-inspection.**
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **06/21/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUIDLING ID: **1410**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Kelvyn Park High School** INSPECTION DATE: **3/9/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **102A**
MATERIAL DESCRIPTION: **12x12 Light Brown w/ Speckles Floor Tile Mastic - (NOT OBSERVED)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms: 113, 221, 223, 225 Storage & 227 inner room - 1928 Bldg.
NOT OBSERVED in any of these locations during the 2013 Re-inspection.**

MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUILDING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **6/21/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **102A**
MATERIAL DESCRIPTION: **12x12 Light Brown w/ Speckles Floor Tile Mastic - (NOT OBSERVED)**
MATERIAL LOCATION: **Rooms: 113, 221, 223, 225 Storage & 227 inner room - 1928 Bldg.
NOT OBSERVED in any of these locations during the 2013 Re-inspection.**
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **06/21/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUIDLING ID: **1410**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Kelvyn Park High School** INSPECTION DATE: **3/9/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **103**
MATERIAL DESCRIPTION: **12x12 Light Beige w/ White Streaks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Rooms 121, 123 & 125 - 1928 Bldg.**

MATERIAL QUANTITY: **1600**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUILDING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **6/21/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **103**
MATERIAL DESCRIPTION: **12x12 Light Beige w/ White Streaks Floor Tile**
MATERIAL LOCATION: **Rooms 121, 123 & 125 - 1928 Bldg.**

MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **06/21/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUIDLING ID: **1410**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Kelvyn Park High School** INSPECTION DATE: **3/9/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **103A**
MATERIAL DESCRIPTION: **12x12 Beige w/ White Streaks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 121, 123 & 125 - 1928 Bldg.**

MATERIAL QUANTITY: **1600**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUILDING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **6/21/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **103A**
MATERIAL DESCRIPTION: **12x12 Beige w/ White Streaks VFT Mastic**
MATERIAL LOCATION: **Rooms 121, 123 & 125 - 1928 Bldg.**

MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **06/21/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUIDLING ID: **1410**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Kelvyn Park High School** INSPECTION DATE: **3/9/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **104**
MATERIAL DESCRIPTION: **12"x12" Light Blue Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Room 312(not observed), Gym, ROTC, Library (100) - 1918**

MATERIAL QUANTITY: **2150**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUILDING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **6/21/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **104**
MATERIAL DESCRIPTION: **12"x12" Light Blue Floor Tile**
MATERIAL LOCATION: **Room 312(not observed), Gym, ROTC, Library (100) - 1918**
MATERIAL QUANTITY: **2150** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **06/21/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUIDLING ID: **1410**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Kelvyn Park High School** INSPECTION DATE: **3/9/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **105**
MATERIAL DESCRIPTION: **12"x12" Light Blue Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 312(not observed), Gym, ROTC, Library (100) - 1918**

MATERIAL QUANTITY: **2150**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUILDING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **6/21/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **105**
MATERIAL DESCRIPTION: **12"x12" Light Blue Floor Tile Mastic**
MATERIAL LOCATION: **Room 312(not observed), Gym, ROTC, Library (100) - 1918**
MATERIAL QUANTITY: **2150** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **06/21/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUIDLING ID: **1410**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Kelvyn Park High School** INSPECTION DATE: **3/9/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **106**
MATERIAL DESCRIPTION: **12"x12" Tan w/ Brown & White Spots VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **099, 101, 103, 105, 107, 109, 111, 309, 2nd Floor Hall Lockers - 1918
Room 312, Gym, ROTC, Library (100) - 1918
Rooms 121, 123 & 125 - 1928 Bldg.
NOT OBSERVED in 2nd Floor Hall Lockers during the 2013 Re-inspection.**

MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/09/2016

Chicago Public Schools

GSG Consultants, Inc.

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUIDLING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **6/21/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **106**
MATERIAL DESCRIPTION: **12"x12" Tan w/ Brown & White Spots VFT**
MATERIAL LOCATION: **099, 101, 103, 105, 107, 109, 111, 309, 2nd Floor Hall Lockers - 1918
Room 312, Gym, ROTC, Library (100) - 1918
Rooms 121, 123 & 125 - 1928 Bldg.
NOT OBSERVED in 2nd Floor Hall Lockers during the 2013 Re-inspection.**
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/21/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 46191 BUILDING ID: 1410
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Delores Fitzpatrick
SCHOOL NAME: Kelvyn Park High School INSPECTION DATE: 3/9/2016
ADDRESS: 4343 W. Wrightwood Ave. IDPH LICENSE NO: 100-05183

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 107
MATERIAL DESCRIPTION: 12"x12" Tan w/ Brown & White Spots VFT Mastic
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **099, 101, 103, 105, 107, 109, 111, 309, 2nd Floor Hall Lockers - 1918
Room 312, Gym, ROTC, Library (100) - 1918
Rooms 121, 123 & 125 - 1928 Bldg.
NOT OBSERVED in 2nd Floor Hall Lockers during the 2013 Re-inspection.**

MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/09/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUIDLING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **6/21/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **107**
MATERIAL DESCRIPTION: **12"x12" Tan w/ Brown & White Spots VFT Mastic**
MATERIAL LOCATION: **099, 101, 103, 105, 107, 109, 111, 309, 2nd Floor Hall Lockers - 1918
Room 312, Gym, ROTC, Library (100) - 1918
Rooms 121, 123 & 125 - 1928 Bldg.
NOT OBSERVED in 2nd Floor Hall Lockers during the 2013 Re-inspection.**
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/21/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUIDLING ID: **1410**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Kelvyn Park High School** INSPECTION DATE: **3/9/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **108**
MATERIAL DESCRIPTION: **12"x12" Grey W/ Specks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **1st Floor Corridor, Old Engineers Former Office - 1928**
MATERIAL QUANTITY: **6000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 03/09/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUILDING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **6/21/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **108**
MATERIAL DESCRIPTION: **12"x12" Grey W/ Specks VFT**
MATERIAL LOCATION: **1st Floor Corridor, Old Engineers Former Office - 1928**
MATERIAL QUANTITY: **6000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **06/21/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUIDLING ID: **1410**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Kelvyn Park High School** INSPECTION DATE: **3/9/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **109**
MATERIAL DESCRIPTION: **12"x12" Grey W/ Specks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with potential for significant damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st Floor Corridor, Old Engineers Former Office - 1928**
MATERIAL QUANTITY: **6000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/09/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUILDING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **6/21/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **109**
MATERIAL DESCRIPTION: **12"x12" Grey W/ Specks VFT Mastic**
MATERIAL LOCATION: **1st Floor Corridor, Old Engineers Former Office - 1928**
MATERIAL QUANTITY: **6000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **06/21/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUIDLING ID: **1410**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Kelvyn Park High School** INSPECTION DATE: **3/9/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **110**
MATERIAL DESCRIPTION: **Blue Linoleum**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Rooms: 115, 125, 221, 223, 225, 227 1928 Bldg**
MATERIAL QUANTITY: **4800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 03/09/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUILDING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **6/21/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **110**
MATERIAL DESCRIPTION: **Blue Linoleum**
MATERIAL LOCATION: **Rooms: 115, 125, 221, 223, 225, 227 1928 Bldg**
MATERIAL QUANTITY: **4800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **06/21/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUIDLING ID: **1410**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Kelvyn Park High School** INSPECTION DATE: **3/9/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **110 A**
MATERIAL DESCRIPTION: **Blue Linoleum Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms: 115, 125, 221, 223, 225, 227 1928 Bldg**
MATERIAL QUANTITY: **4800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/09/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUILDING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **6/21/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **110 A**
MATERIAL DESCRIPTION: **Blue Linoleum Mastic**
MATERIAL LOCATION: **Rooms: 115, 125, 221, 223, 225, 227 1928 Bldg**
MATERIAL QUANTITY: **4800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **06/21/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUIDLING ID: **1410**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Kelvyn Park High School** INSPECTION DATE: **3/9/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **111**
MATERIAL DESCRIPTION: **12"x12" Black w/White Specks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Music Room (313), 319, 323, 327 -1928 Bldg**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 03/09/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUILDING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **6/21/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **111**
MATERIAL DESCRIPTION: **12"x12" Black w/White Specks Floor Tile**
MATERIAL LOCATION: **Music Room (313), 319, 323, 327 -1928 Bldg**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **06/21/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUIDLING ID: **1410**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Kelvyn Park High School** INSPECTION DATE: **3/9/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **111A**
MATERIAL DESCRIPTION: **12"x12" Black w/White Specks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Music Room (313), 319, 323, 327 -1928 Bldg**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/09/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUILDING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **6/21/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **111A**
MATERIAL DESCRIPTION: **12"x12" Black w/White Specks Floor Tile Mastic**
MATERIAL LOCATION: **Music Room (313), 319, 323, 327 -1928 Bldg**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **06/21/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUIDLING ID: **1410**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Kelvyn Park High School** INSPECTION DATE: **3/9/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **112**
MATERIAL DESCRIPTION: **12"x12" Blue w/White Specks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Music Room (313) - 1928 Bldg**
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/09/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUILDING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **6/21/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **112**
MATERIAL DESCRIPTION: **12"x12" Blue w/White Specks Floor Tile**
MATERIAL LOCATION: **Music Room (313) - 1928 Bldg**
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **06/21/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUIDLING ID: **1410**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Kelvyn Park High School** INSPECTION DATE: **3/9/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **112A**
MATERIAL DESCRIPTION: **12"x12" Blue w/White Specks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Music Room (313) - 1928 Bldg**
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/09/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUILDING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **6/21/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **112A**
MATERIAL DESCRIPTION: **12"x12" Blue w/White Specks Floor Tile Mastic**
MATERIAL LOCATION: **Music Room (313) - 1928 Bldg**
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **06/21/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUIDLING ID: **1410**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Kelvyn Park High School** INSPECTION DATE: **3/9/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **113**
MATERIAL DESCRIPTION: **12"x12" White w/Specks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Room 316, 318, 216, 220 - 1999 Addition**
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/09/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUILDING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **6/21/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **113**
MATERIAL DESCRIPTION: **12"x12" White w/Specks Floor Tile**
MATERIAL LOCATION: **Room 316, 318, 216, 220 - 1999 Addition**
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **06/21/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUIDLING ID: **1410**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Kelvyn Park High School** INSPECTION DATE: **3/9/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **113A**
MATERIAL DESCRIPTION: **12"x12" White w/Specks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 316, 318, 216, 220 - 1999 Addition**
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/09/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUILDING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **6/21/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **113A**
MATERIAL DESCRIPTION: **12"x12" White w/Specks Floor Tile Mastic**
MATERIAL LOCATION: **Room 316, 318, 216, 220 - 1999 Addition**
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **06/21/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUIDLING ID: **1410**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Kelvyn Park High School** INSPECTION DATE: **3/9/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **114**
MATERIAL DESCRIPTION: **12"x12" Light Blue w/Specks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **2nd Floor Lunchroom, room 400 - 1918 Bldg.**
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUILDING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **6/21/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **114**
MATERIAL DESCRIPTION: **12"x12" Light Blue w/Specks Floor Tile**
MATERIAL LOCATION: **2nd Floor Lunchroom, room 400 - 1918 Bldg.**
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **06/21/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUIDLING ID: **1410**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Kelvyn Park High School** INSPECTION DATE: **3/9/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **114A**
MATERIAL DESCRIPTION: **12"x12" Light Blue w/Specks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **2nd Floor Lunchroom, Room 400 - 1918 Bldg.**
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUIDLING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **6/21/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **114A**
MATERIAL DESCRIPTION: **12"x12" Light Blue w/Specks Floor Tile Mastic**
MATERIAL LOCATION: **2nd Floor Lunchroom, Room 400 - 1918 Bldg.**
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **06/21/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUIDLING ID: **1410**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Kelvyn Park High School** INSPECTION DATE: **3/9/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **115**
MATERIAL DESCRIPTION: **Blue Carpet Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Library, Main Office, Principal's Office and Rooms 104 and 211; 205, 207, 209A, 209B - 1918 Bldg**

MATERIAL QUANTITY: **3800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/09/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUILDING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **6/21/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **115**
MATERIAL DESCRIPTION: **Blue Carpet Adhesive**
MATERIAL LOCATION: **Library, Main Office, Principal's Office and Rooms 104 and 211; 205, 207, 209A, 209B - 1918 Bldg**
MATERIAL QUANTITY: **3800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **06/21/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUIDLING ID: **1410**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Kelvyn Park High School** INSPECTION DATE: **3/9/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **116**
MATERIAL DESCRIPTION: **12"x12" Ceramic Tile Grout**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Main Office, Library (100) - 1918 Bldg**
MATERIAL QUANTITY: **1300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/09/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUILDING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **6/21/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **116**
MATERIAL DESCRIPTION: **12"x12" Ceramic Tile Grout**
MATERIAL LOCATION: **Main Office, Library (100) - 1918 Bldg**
MATERIAL QUANTITY: **1300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **06/21/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUIDLING ID: **1410**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Kelvyn Park High School** INSPECTION DATE: **3/9/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **117**
MATERIAL DESCRIPTION: **12"x12" Ceramic Tile Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Main Office, Library (100) - 1918 Bldg**
MATERIAL QUANTITY: **1300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/09/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUILDING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **6/21/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **117**
MATERIAL DESCRIPTION: **12"x12" Ceramic Tile Adhesive**
MATERIAL LOCATION: **Main Office, Library (100) - 1918 Bldg**
MATERIAL QUANTITY: **1300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **06/21/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 46191 BUILDING ID: 1410
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Delores Fitzpatrick
SCHOOL NAME: Kelvyn Park High School INSPECTION DATE: 3/9/2016
ADDRESS: 4343 W. Wrightwood Ave. IDPH LICENSE NO: 100-05183

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 118
MATERIAL DESCRIPTION: 2' X 4' white with swirls, ceiling tile
HISTORICAL AHERA DAMAGE CATEGORY 6
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: Assumed FRIABLE: Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rms 216, 220, 316, 318 - 1999 Bldg.**
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/09/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUILDING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **6/21/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **118**
MATERIAL DESCRIPTION: **2' X 4' white with swirls, ceiling tile**
MATERIAL LOCATION: **Rms 216, 220, 316, 318 - 1999 Bldg.**
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **06/21/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUIDLING ID: **1410**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Kelvyn Park High School** INSPECTION DATE: **3/9/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **119**
MATERIAL DESCRIPTION: **12" X 12" yellow speckle, VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **1st and 2nd floor corridors, Auditorium - 1918 Bldg.**
MATERIAL QUANTITY: **7800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/09/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUILDING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **6/21/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **119**
MATERIAL DESCRIPTION: **12" X 12" yellow speckle, VFT**
MATERIAL LOCATION: **1st and 2nd floor corridors, Auditorium - 1918 Bldg.**
MATERIAL QUANTITY: **7800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **06/21/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 46191 BUILDING ID: 1410
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Delores Fitzpatrick
SCHOOL NAME: Kelvyn Park High School INSPECTION DATE: 3/9/2016
ADDRESS: 4343 W. Wrightwood Ave. IDPH LICENSE NO: 100-05183

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 120
MATERIAL DESCRIPTION: 12" X 12" yellow speckle, mastic
HISTORICAL AHERA DAMAGE CATEGORY 6
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st and 2nd floor corridors, Auditorium - 1918 Bldg.**
MATERIAL QUANTITY: **7800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/09/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUILDING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **6/21/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **120**
MATERIAL DESCRIPTION: **12" X 12" yellow speckle, mastic**
MATERIAL LOCATION: **1st and 2nd floor corridors, Auditorium - 1918 Bldg.**
MATERIAL QUANTITY: **7800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **06/21/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUIDLING ID: **1410**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Kelvyn Park High School** INSPECTION DATE: **3/9/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **121**
MATERIAL DESCRIPTION: **12" X 12" black with white specks, VFT (DUPLICATE OF 001A NOT OBSERVED)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **2nd and 3rd floor corridors - 1928 bldg.**
MATERIAL QUANTITY: **14200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUIDLING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **6/21/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **121**
MATERIAL DESCRIPTION: **12" X 12" black with white specks, VFT (DUPLICATE OF 001A NOT OBSERVED)**
MATERIAL LOCATION: **2nd and 3rd floor corridors - 1928 bldg.**
MATERIAL QUANTITY: **14200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **06/21/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUIDLING ID: **1410**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Kelvyn Park High School** INSPECTION DATE: **3/9/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **122**
MATERIAL DESCRIPTION: **12" X 12" black with white specks, Mastic (DUPLICATE OF 004A, NOT OBSERVED)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **2nd and 3rd floor corridors - 1928 bldg.**
MATERIAL QUANTITY: **14200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 03/09/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUILDING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **6/21/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **122**
MATERIAL DESCRIPTION: **12" X 12" black with white specks, Mastic (DUPLICATE OF 004A, NOT OBSERVED)**
MATERIAL LOCATION: **2nd and 3rd floor corridors - 1928 bldg.**
MATERIAL QUANTITY: **14200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **06/21/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 46191 BUILDING ID: 1410
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Delores Fitzpatrick
SCHOOL NAME: Kelvyn Park High School INSPECTION DATE: 3/9/2016
ADDRESS: 4343 W. Wrightwood Ave. IDPH LICENSE NO: 100-05183

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 123
MATERIAL DESCRIPTION: 12" X 12" yellow speckled VFT
HISTORICAL AHERA DAMAGE CATEGORY 6
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: MODERATE
MATERIAL LOCATION: 2nd and 3rd floor corridors - 1928 bldg.
MATERIAL QUANTITY: 3600 MATERIAL UNITS: SF
DAMAGE QUANTITY: DAMAGE UNITS: SF
COMMENTS:

Inspector's Signature: _____



Date: 03/09/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUILDING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **6/21/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **123**
MATERIAL DESCRIPTION: **12" X 12" yellow speckled VFT**
MATERIAL LOCATION: **2nd and 3rd floor corridors - 1928 bldg.**
MATERIAL QUANTITY: **3600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **06/21/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUIDLING ID: **1410**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Kelvyn Park High School** INSPECTION DATE: **3/9/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **124**
MATERIAL DESCRIPTION: **12" X 12" yellow speckled, Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **2nd and 3rd floor corridors - 1928 bldg.**
MATERIAL QUANTITY: **3600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/09/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUILDING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **6/21/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **124**
MATERIAL DESCRIPTION: **12" X 12" yellow speckled, Mastic**
MATERIAL LOCATION: **2nd and 3rd floor corridors - 1928 bldg.**
MATERIAL QUANTITY: **3600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **06/21/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 46191 BUILDING ID: 1410
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Delores Fitzpatrick
SCHOOL NAME: Kelvyn Park High School INSPECTION DATE: 3/9/2016
ADDRESS: 4343 W. Wrightwood Ave. IDPH LICENSE NO: 100-05183

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 125
MATERIAL DESCRIPTION: 12" X 12" black with dark brown specks, VFT
HISTORICAL AHERA DAMAGE CATEGORY 6
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: MODERATE
MATERIAL LOCATION: Rm 206 - 1918 Bldg.
MATERIAL QUANTITY: 600 MATERIAL UNITS: SF
DAMAGE QUANTITY: DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature: _____



Date: 03/09/2016 _____

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUILDING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **6/21/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **125**
MATERIAL DESCRIPTION: **12" X 12" black with dark brown specks, VFT**
MATERIAL LOCATION: **Rm 206 - 1918 Bldg.**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **06/21/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 46191 BUILDING ID: 1410
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Delores Fitzpatrick
SCHOOL NAME: Kelvyn Park High School INSPECTION DATE: 3/9/2016
ADDRESS: 4343 W. Wrightwood Ave. IDPH LICENSE NO: 100-05183

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 126
MATERIAL DESCRIPTION: 12" X 12" black with dark brown specks, Mastic
HISTORICAL AHERA DAMAGE CATEGORY 6
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW
MATERIAL LOCATION: Rm 206 - 1918 Bldg.
MATERIAL QUANTITY: 600 MATERIAL UNITS: SF
DAMAGE QUANTITY: DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature: _____



Date: 03/09/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUILDING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **6/21/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **126**
MATERIAL DESCRIPTION: **12" X 12" black with dark brown specks, Mastic**
MATERIAL LOCATION: **Rm 206 - 1918 Bldg.**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **06/21/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 46191 BUIDLING ID: 1410
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Delores Fitzpatrick
SCHOOL NAME: Kelvyn Park High School INSPECTION DATE: 3/9/2016
ADDRESS: 4343 W. Wrightwood Ave. IDPH LICENSE NO: 100-05183

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 127
MATERIAL DESCRIPTION: 12" X 12" blue speckled, VFT
HISTORICAL AHERA DAMAGE CATEGORY 6
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: MODERATE
MATERIAL LOCATION: Rm 211 - 1918 Bldg.
MATERIAL QUANTITY: 500 MATERIAL UNITS: SF
DAMAGE QUANTITY: DAMAGE UNITS: SF
COMMENTS:

Inspector's Signature: _____



Date: 03/09/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUILDING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **6/21/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **127**
MATERIAL DESCRIPTION: **12" X 12" blue speckled, VFT**
MATERIAL LOCATION: **Rm 211 - 1918 Bldg.**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **06/21/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 46191 BUILDING ID: 1410
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Delores Fitzpatrick
SCHOOL NAME: Kelvyn Park High School INSPECTION DATE: 3/9/2016
ADDRESS: 4343 W. Wrightwood Ave. IDPH LICENSE NO: 100-05183

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 128
MATERIAL DESCRIPTION: 12" X 12" blue speckled, mastic
HISTORICAL AHERA DAMAGE CATEGORY 6
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW
MATERIAL LOCATION: Rm 211 - 1918 Bldg.
MATERIAL QUANTITY: 500 MATERIAL UNITS: SF
DAMAGE QUANTITY: DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature: _____



Date: 03/09/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUILDING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **6/21/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **128**
MATERIAL DESCRIPTION: **12" X 12" blue speckled, mastic**
MATERIAL LOCATION: **Rm 211 - 1918 Bldg.**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **06/21/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 46191 BUILDING ID: 1410
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Delores Fitzpatrick
SCHOOL NAME: Kelvyn Park High School INSPECTION DATE: 3/9/2016
ADDRESS: 4343 W. Wrightwood Ave. IDPH LICENSE NO: 100-05183

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 129
MATERIAL DESCRIPTION: 12" X 12" gray speckled VFT
HISTORICAL AHERA DAMAGE CATEGORY 6
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: MODERATE
MATERIAL LOCATION: Rm 211 - 1918 Bldg.
MATERIAL QUANTITY: 600 MATERIAL UNITS: SF
DAMAGE QUANTITY: DAMAGE UNITS: SF
COMMENTS:

Inspector's Signature: _____



Date: 03/09/2016 _____

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUILDING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **6/21/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **129**
MATERIAL DESCRIPTION: **12" X 12" gray speckled VFT**
MATERIAL LOCATION: **Rm 211 - 1918 Bldg.**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **06/21/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 46191 BUILDING ID: 1410
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Delores Fitzpatrick
SCHOOL NAME: Kelvyn Park High School INSPECTION DATE: 3/9/2016
ADDRESS: 4343 W. Wrightwood Ave. IDPH LICENSE NO: 100-05183

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 130
MATERIAL DESCRIPTION: 12" X 12" gray speckled, Mastic
HISTORICAL AHERA DAMAGE CATEGORY 6
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW
MATERIAL LOCATION: Rm 211 - 1918 Bldg.
MATERIAL QUANTITY: 600 MATERIAL UNITS: SF
DAMAGE QUANTITY: DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature: _____



Date: 03/09/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUIDLING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **6/21/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **130**
MATERIAL DESCRIPTION: **12" X 12" gray speckled, Mastic**
MATERIAL LOCATION: **Rm 211 - 1918 Bldg.**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **06/21/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 46191 BUILDING ID: 1410
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Delores Fitzpatrick
SCHOOL NAME: Kelvyn Park High School INSPECTION DATE: 3/9/2016
ADDRESS: 4343 W. Wrightwood Ave. IDPH LICENSE NO: 100-05183

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 131
MATERIAL DESCRIPTION: Fume Hood
HISTORICAL AHERA DAMAGE CATEGORY 6
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW
MATERIAL LOCATION: Rm 223 - 1928 Bldg.
MATERIAL QUANTITY: 40 MATERIAL UNITS: SF
DAMAGE QUANTITY: DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature: _____



Date: 03/09/2016 _____

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUILDING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **6/21/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **131**
MATERIAL DESCRIPTION: **Fume Hood**
MATERIAL LOCATION: **Rm 223 - 1928 Bldg.**
MATERIAL QUANTITY: **40** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **06/21/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUIDLING ID: **1410**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Kelvyn Park High School** INSPECTION DATE: **3/9/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **56**
MATERIAL DESCRIPTION: **Aircell Pipe Insulation (Removed)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **SW Unexcavated Area - 1928**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUILDING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **6/21/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **56**
MATERIAL DESCRIPTION: **Aircell Pipe Insulation (Removed)**
MATERIAL LOCATION: **SW Unexcavated Area - 1928**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **06/21/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUIDLING ID: **1410**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Kelvyn Park High School** INSPECTION DATE: **3/9/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **B**
MATERIAL DESCRIPTION: **2'x4' White Wormy Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with potential for significant damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Rooms: 206 Closet, 208 & 398, 302, 304 - 1918 Bldg.**

MATERIAL QUANTITY: **1500**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUILDING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **6/21/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **B**
MATERIAL DESCRIPTION: **2'x4' White Wormy Ceiling Tile**
MATERIAL LOCATION: **Rooms: 206 Closet, 208 & 398, 302, 304 - 1918 Bldg.**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **06/21/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUIDLING ID: **1410**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Kelvyn Park High School** INSPECTION DATE: **3/9/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **C**
MATERIAL DESCRIPTION: **2'x4' Multiple Color 1/4" Wormy Ceiling Tile (NOT OBSERVED)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with potential for significant damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Rooms 200 & 300 - 1918 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____



Date: 03/09/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUILDING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **6/21/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **C**
MATERIAL DESCRIPTION: **2'x4' Multiple Color 1/4" Wormy Ceiling Tile (NOT OBSERVED)**
MATERIAL LOCATION: **Rooms 200 & 300 - 1918 Bldg.**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: **0** DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **06/21/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUIDLING ID: **1410**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Kelvyn Park High School** INSPECTION DATE: **3/9/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **D**
MATERIAL DESCRIPTION: **2'x4' Dk Wht w/Multi Color 1/2" Wormy Ceiling Tile (NOT OBSERVED)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Rooms 104 & 300 - 1918 Bldg.**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 03/09/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUILDING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **6/21/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **D**
MATERIAL DESCRIPTION: **2'x4' Dk Wht w/Multi Color 1/2" Wormy Ceiling Tile (NOT OBSERVED)**
MATERIAL LOCATION: **Rooms 104 & 300 - 1918 Bldg.**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **06/21/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUIDLING ID: **1410**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Kelvyn Park High School** INSPECTION DATE: **3/9/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **E**
MATERIAL DESCRIPTION: **2'x4' Off White Large Wormy Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with potential for significant damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Room 208 - 1918 Bldg.**

MATERIAL QUANTITY: **300**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/09/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUILDING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **6/21/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **E**
MATERIAL DESCRIPTION: **2'x4' Off White Large Wormy Ceiling Tile**
MATERIAL LOCATION: **Room 208 - 1918 Bldg.**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **06/21/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUIDLING ID: **1410**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Kelvyn Park High School** INSPECTION DATE: **3/9/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **F**
MATERIAL DESCRIPTION: **1'x1' Off White Wormy Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with potential for significant damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **ROTC, ROTC Office, Rooms 110 & 212, Engineer's Former Office - 1918 Bldg.**
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/09/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUILDING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **6/21/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **F**
MATERIAL DESCRIPTION: **1'x1' Off White Wormy Ceiling Tile**
MATERIAL LOCATION: **ROTC, ROTC Office, Rooms 110 & 212, Engineer's Former Office - 1918 Bldg.**
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **06/21/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUIDLING ID: **1410**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Kelvyn Park High School** INSPECTION DATE: **3/9/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **G**
MATERIAL DESCRIPTION: **1'x1' Off White Large Wormy Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with potential for significant damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **ROTC, Room 212, Cafeteria by Lunchroom & Auditorium - 1918 Bldg.**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUILDING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **6/21/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **G**
MATERIAL DESCRIPTION: **1'x1' Off White Large Wormy Ceiling Tile**
MATERIAL LOCATION: **ROTC, Room 212, Cafeteria by Lunchroom & Auditorium - 1918 Bldg.**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **06/21/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUIDLING ID: **1410**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Kelvyn Park High School** INSPECTION DATE: **3/9/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **H**
MATERIAL DESCRIPTION: **Spray - On Walls & Beams (NOT OBSERVED)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with potential for significant damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **3rd Floor Computer Room - 1928 Bldg.**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 03/09/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUILDING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **6/21/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **H**
MATERIAL DESCRIPTION: **Spray - On Walls & Beams (NOT OBSERVED)**
MATERIAL LOCATION: **3rd Floor Computer Room - 1928 Bldg.**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **06/21/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUIDLING ID: **1410**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Kelvyn Park High School** INSPECTION DATE: **3/9/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **I**
MATERIAL DESCRIPTION: **18"x18" Dirty White Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with potential for significant damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **3rd Floor Music Room - 1928 Bldg.**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/09/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUILDING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **6/21/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **I**
MATERIAL DESCRIPTION: **18"x18" Dirty White Ceiling Tile**
MATERIAL LOCATION: **3rd Floor Music Room - 1928 Bldg.**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **06/21/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUIDLING ID: **1410**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Kelvyn Park High School** INSPECTION DATE: **3/9/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **J**
MATERIAL DESCRIPTION: **1'x1' Dirty White Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with potential for significant damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Room 314 East & West Vestibule - 1928 Bldg.**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/09/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUILDING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **6/21/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **J**
MATERIAL DESCRIPTION: **1'x1' Dirty White Ceiling Tile**
MATERIAL LOCATION: **Room 314 East & West Vestibule - 1928 Bldg.**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **06/21/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUIDLING ID: **1410**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Kelvyn Park High School** INSPECTION DATE: **3/9/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **K**
MATERIAL DESCRIPTION: **2'x4' Multiple Color 1/2" Wormy Ceiling Tile (NOT OBSERVED)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with potential for significant damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Rms 127 & 220 - 1928 Bldg.**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/09/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUILDING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **6/21/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **K**
MATERIAL DESCRIPTION: **2'x4' Multiple Color 1/2" Wormy Ceiling Tile (NOT OBSERVED)**
MATERIAL LOCATION: **Rms 127 & 220 - 1928 Bldg.**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **06/21/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUIDLING ID: **1410**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Kelvyn Park High School** INSPECTION DATE: **3/9/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **L**
MATERIAL DESCRIPTION: **1'x1' White Wormy Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with potential for significant damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Rooms 123 and 213 - 1928 Bldg.**
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/09/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUILDING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **6/21/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **L**
MATERIAL DESCRIPTION: **1'x1' White Wormy Ceiling Tile**
MATERIAL LOCATION: **Rooms 123 and 213 - 1928 Bldg.**
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **06/21/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUIDLING ID: **1410**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Kelvyn Park High School** INSPECTION DATE: **3/9/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **M**
MATERIAL DESCRIPTION: **Transite Table Tops**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms: 123, 125, 221, 223, 225, 227 - 1928 Bldg. (129 Abated in 2003)**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: **03/09/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUIDLING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **6/21/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **M**
MATERIAL DESCRIPTION: **Transite Table Tops**
MATERIAL LOCATION: **Rooms: 123, 125, 221, 223, 225, 227 - 1928 Bldg. (129 Abated in 2003)**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **06/21/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUIDLING ID: **1410**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Kelvyn Park High School** INSPECTION DATE: **3/9/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **N**
MATERIAL DESCRIPTION: **Sheeted Walls**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st Floor Supply Storage near Exit - 1928 Bldg.**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/09/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUILDING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **6/21/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **N**
MATERIAL DESCRIPTION: **Sheeted Walls**
MATERIAL LOCATION: **1st Floor Supply Storage near Exit - 1928 Bldg.**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **06/21/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUILDING ID: **1410**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Kelvyn Park High School** INSPECTION DATE: **3/9/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **133**
MATERIAL DESCRIPTION: **12x12 Gray, Black and beige VFT Mastic**
MATERIAL LOCATION: **Rooms 327, 323, 319**
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Barely Reachable** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 03/09/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUILDING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **6/21/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **133**
MATERIAL DESCRIPTION: **12x12 Gray, Black and beige VFT Mastic**
MATERIAL LOCATION: **Rooms 327, 323, 319**
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____

Jigar Shah

Date: **06/21/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUILDING ID: **1410**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Kelvyn Park High School** INSPECTION DATE: **3/9/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **137**
MATERIAL DESCRIPTION: **12x12 Gray and Black VFT Mastic**
MATERIAL LOCATION: **Rooms 107G, 205, 206, 211, 303, 304, 308**
MATERIAL QUANTITY: **5600** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Barely Reachable** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 03/09/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUILDING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **6/21/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **137**
MATERIAL DESCRIPTION: **12x12 Gray and Black VFT Mastic**
MATERIAL LOCATION: **Rooms 107G, 205, 206, 211, 303, 304, 308**
MATERIAL QUANTITY: **5600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____

Jigar Shah

Date: **06/21/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUILDING ID: **1410**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Kelvyn Park High School** INSPECTION DATE: **3/9/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **136**
MATERIAL DESCRIPTION: **12x12 Gray and Black VFT**
MATERIAL LOCATION: **Rooms 107G, 205, 206, 211, 303, 304, 308**
MATERIAL QUANTITY: **5600** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Barely Reachable** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 03/09/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUILDING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **6/21/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **136**
MATERIAL DESCRIPTION: **12x12 Gray and Black VFT**
MATERIAL LOCATION: **Rooms 107G, 205, 206, 211, 303, 304, 308**
MATERIAL QUANTITY: **5600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **06/21/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUILDING ID: **1410**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Kelvyn Park High School** INSPECTION DATE: **3/9/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **139**
MATERIAL DESCRIPTION: **12x12 White VFT Mastic**
MATERIAL LOCATION: **1st and 3rd floor corridors**
MATERIAL QUANTITY: **17500** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Barely Reachable** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 03/09/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUILDING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **6/21/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **139**
MATERIAL DESCRIPTION: **12x12 White VFT Mastic**
MATERIAL LOCATION: **1st and 3rd floor corridors**
MATERIAL QUANTITY: **17500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____

Jigar Shah

Date: **06/21/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUILDING ID: **1410**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Kelvyn Park High School** INSPECTION DATE: **3/9/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **135**
MATERIAL DESCRIPTION: **12x12 Gray, Black and White VFT Mastic**
MATERIAL LOCATION: **2nd floor main office, Rooms 105, 312**
MATERIAL QUANTITY: **3350** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Barely Reachable** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 03/09/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUILDING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **6/21/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **135**
MATERIAL DESCRIPTION: **12x12 Gray, Black and White VFT Mastic**
MATERIAL LOCATION: **2nd floor main office, Rooms 105, 312**
MATERIAL QUANTITY: **3350** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____

Jigar Shah

Date: **06/21/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUILDING ID: **1410**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Kelvyn Park High School** INSPECTION DATE: **3/9/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **138**
MATERIAL DESCRIPTION: **12x12 White VFT**
MATERIAL LOCATION: **1st and 3rd floor corridors**
MATERIAL QUANTITY: **17500** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **Yes**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **MODERATE** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 03/09/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUILDING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **6/21/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **138**
MATERIAL DESCRIPTION: **12x12 White VFT**
MATERIAL LOCATION: **1st and 3rd floor corridors**
MATERIAL QUANTITY: **17500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____

Jigar Shah

Date: **06/21/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUILDING ID: **1410**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Kelvyn Park High School** INSPECTION DATE: **3/9/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **132**
MATERIAL DESCRIPTION: **12x12 Gray, Black and beige VFT**
MATERIAL LOCATION: **Rooms, 327, 323, 319**
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 03/09/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUILDING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **6/21/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **132**
MATERIAL DESCRIPTION: **12x12 Gray, Black and beige VFT**
MATERIAL LOCATION: **Rooms, 327, 323, 319**
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____

Jigar Shah

Date: **06/21/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUILDING ID: **1410**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Kelvyn Park High School** INSPECTION DATE: **3/9/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **134**
MATERIAL DESCRIPTION: **12x12 Gray, Black and White VFT**
MATERIAL LOCATION: **2nd floor main office, Rooms 105, 312**
MATERIAL QUANTITY: **3350** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **MODERATE** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 03/09/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46191** BUILDING ID: **1410**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Kelvyn Park High School** REVIEW DATE: **6/21/2016**
ADDRESS: **4343 W. Wrightwood Ave.** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **134**
MATERIAL DESCRIPTION: **12x12 Gray, Black and White VFT**
MATERIAL LOCATION: **2nd floor main office, Rooms 105, 312**
MATERIAL QUANTITY: **3350** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____

Jigar Shah

Date: **06/21/2016**

APPENDIX B

Inspector and Management Planner Licenses

CERTIFICATE OF ACHIEVEMENT ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that DELORES FITZPATRICK
has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the
examination on 02/16/2013 with a minimum score of 70% or better. Training was in accordance
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:
Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.



N. Kennedy

02/16/2013

Course Dates: _____

02/16/2014

Expires: _____

1302BIR20

Certificate Number: _____

Phone Number: (312) 491-4081

Director of Training

Nicholas J. Penell

Doctor of Public Health

FORM # A-010



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • www.dph.illinois.gov



4/20/2016

DELORES FITZPATRICK
 855 WEST ADAMS, SUITE 200
 CHICAGO, IL 60607

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 05183

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE


Front of License			Back of License	
 <p>ASBESTOS PROFESSIONAL LICENSE</p>			<p>ENDORSEMENTS</p>	
<p>ID NUMBER TC0 - 05183</p>	<p>ISSUED 4/20/2016</p>	<p>EXPIRES 05/15/2017</p>	<p>INSPECTOR</p>	<p>TC EXPIRES 2/13/2017</p>
<p>DELORES FITZPATRICK 855 WEST ADAMS, SUITE 200 CHICAGO, IL 60607</p> <p>Environmental Health</p>			<p>PROJECT MANAGER AIR SAMPLING PROFESSIONAL</p> <p>2/6/2017</p>	
			<p>Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health. This license is valid only when accompanied by a valid training course certificate.</p>	

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
 EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH, IMPROVING LIVES
Nationally Accredited by NABE

2016



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Jigar Shah

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 1/27/2016

Exam Date: 1/27/2016

Expiration Date: 1/27/2017

Certificate Number: MPR1601270320


Kathy DeSalvo, Director



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • www.dph.illinois.gov

4/20/2016

JIGAR M SHAH
 855 W ADAMS ST, SUITE 200
 CHICAGO, IL 60607

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 07342

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

		ASBESTOS PROFESSIONAL LICENSE		ENDORSEMENTS	TC EXPIRES
ID NUMBER 109 - 07342	ISSUED 4/20/2016	EXPIRES 05/15/2017		INSPECTOR PROJECT DESIGNER MANAGEMENT PLANNER PROJECT MANAGER AIR SAMPLING PROFESSIONAL	1/19/2017 2/2/2017 1/27/2017 2/26/2017
JIGAR M SHAH 855 W ADAMS ST, SUITE 200 CHICAGO, IL 60607 Environmental Health		Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.			

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
 EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH, IMPROVING LIVES
Nationally Accredited by PHAB

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL		
	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE		
	Loc	Localized
	Dist	Distributed