

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM**

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-0031
SCHOOL NAME: Morgan Park High School
ADDRESS OF SCHOOL: 1744 W. Pryor Ave.
CITY: Chicago, IL, 60643

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **3/18/2013**

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II *(Please type or print)*

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 6/10/2016 ENROLLMENT 1374
IDPH INSPECTOR LICENSE NUMBER: 100-19039
IDPH LICENSED INSPECTOR NAME (Please Print): Wayne Gardner
IDPH MP LICENSE NUMBER: 100-07342
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Jigar Shah

DESIGNATED PERSON (Please Print): Robert Christlieb PHONE: (773) 553-3197



6/10/2016

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Morgan Park High School

1744 W. Pryor Ave.
Chicago, IL, 60643

Unit: 46251
Building ID: 1490

IDPH ID Number: 14-016-2990-0031

REPORT DATE:

Friday, June 10, 2016

Prepared for:

**Chicago Public Schools
125 S. Clark Street
Chicago, IL 60603**

Prepared by:

GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone (312) 733-6262

Fax (312) 733-5612

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

April 20, 2016

Mr. R. Kent Cook
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2016 Three-Year Reinspections

Dear Mr. Cook:

GSG Consultants, Inc., Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 1,2,6 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 46251 Region: 06 IDPH ID: 14-016-2990-0031

School: Morgan Park High School Building ID: 1490

Address: 1744 W. Pryor Ave.

Chicago, IL, 60643

Building Contact: Pinner, Kevin

Contact Phone: 773-535-2547

Current Building Owners: Chicago Public Schools

Review Date: 06/08/2016

Inspector: Wayne Gardner


Inspector IDPH License: 100-19039

Management Planner: Jigar Shah

Management Planner IDPH License: 100-07342

If you have any questions or comments, please contact us at (312) 733-6262

Sincerely,
GSG Consultants, Inc.



Jigar Shah
100-07342

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: April 20, 2016

RE: Morgan Park High School, Unit 46251
1744 W. Pryor Ave.
Chicago, IL, 60643

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2016 asbestos three year re-inspection has been completed at Morgan Park High School , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at Morgan Park High School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Robert Christlieb, the designated Local Education Authority's Designated Person at (773) 553-3197 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Morgan Park High School Unit: 46251 Region: 06
Address: 1744 W. Pryor Ave. Chicago, IL, 60643
IDPH ID: 14-016-2990-0031 Building ID: 1490
Contact: Pinner, Kevin Phone: 773-535-2547

2. Description of Facility

Original Construction: 1914 Additional Construction: 1964
Total Square Footage: 167503 No of Floors: 3
Current Occupancy: 1374

3. LEA Designated Person

Contact: Robert Christlieb Phone: (773) 553-3197
Address: 125 South Clark Street, 17th Floor
Chicago, IL 60603


4. Managing Environmental Consultant

MEC: GSG Consultants, Inc.
Contact: Arturo Saenz
Address 855 W. Adams St., Ste. 200
Phone: (312) 733-6262 Fax: (312) 733-5612

5. Inspector

Inspector Name: Wayne Gardner


Inspector IDPH license # 100-19039

Signature: 
Date: 4/20/2016

6. Management Planner

Management Planner Name: Jigar Shah

Management Planner IDPH license # 100-07342

Signature: 
Date: 06/08/2016

7. Review Date: 06/08/2016

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature: 

Date: 6/10/2016

Name: Robert Christlieb

II. EXECUTIVE SUMMARY

GSG Consultants, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Morgan Park High School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 1490:

C

AIRCELL PIPE INSULATION

B. The following new homogenous areas have been identified for Building 1490:

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

05B	9"x9" Tan Floor Tile
06A	12"x12" White w/Speckles Floor Tile (No ACBM, Per 2015-46251-ICR Samples from 1st,2nd,3rd Fl Corrid)
06B	12"x12" Brown Floor Tile
06C	12"x12" Gray w/Specks Floor Tile
09CC	MASTIC BENEATH 9"X9" TAN FLOOR TILE
105	2'x2' pin hole ceiling tile
106	12"x12" yellow speckled VFT
107	12"x12" yellow speckled VFT MASTIC
108	12"x12" gray speckled VFT
109	12"x12" gray speckled VFT MASTIC
10A	12"x12" Tan Floor Tile Mastic
110	Yellow linoleum
111	12"x12" gray w/ dark gray streaks VFT
112	12"x12" gray w/ dark gray streaks VFT MASTIC
113	14x14 white speckled VFT
114	14x14 white speckled VFT MASTIC
115	14x14 light blue speckled VFT
116	14x14 light blue speckled VFT MASTIC
117	14x14 green speckled VFT
118	14x14 green speckled VFT MASTIC
12A	12"x12" Tan Floor Tile
13A	Brown Baseboard
13B	Black Baseboard
14A	Brown Baseboard Mastic
14B	Black Baseboard Mastic
17A	12"x12" White w/Speckles Fl Tile Mastic (No ACBM, Per 2015-46251-ICR Samples from 1st,2nd,3rd Fl Corrid)
17C	12"x12" Gray w/Specks Floor Tile
18	12"x12" Tan w/ Beige Floor Tile
19	12"x12" Tan w/ Beige Floor Tile Mastic
20	2'x4' Lay In Ceiling Tile (No ACBM, Per 2015-46251-ICR Samples from 1st,2nd,3rd Fl Corrid)
23	Terrazzo
25	Plaster - Walls
A	2' x 2' Lay In Ceiling Panels
B	12"x12" Greenish Floor Tile
CM-1	Rust Carpet Mastic
CM-2	Green Carpet Masitc
CM-3	Multicolor Carpet No Mastic, Carpet Nailed Down

CM-5	Rust Colored Carpet Mastic
D	LAB TABLE TOPS
E	Fitting Insulation on Fiberglass Insulated Piping
F	Fitting Insulation on Fiberglass Insulated Piping
G	Vibration Damper
HA-101	Interior Window Caulk
HA-102	Interior Window Glaze
HA-103	1'x1' Grooved Ceiling Tile Glue
HA-104	Black Sink Undercoating

The following areas were deemed to be inaccessible:

09CC	MASTIC BENEATH 9"X9" TAN FLOOR TILE
19	12"x12" Tan w/ Beige Floor Tile Mastic
22	Spray-on Insulation
HA-103	1'x1' Grooved Ceiling Tile Glue

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Wayne Gardner , IDPH License # 100-19039. The Management Plan was updated by Jigar Shah, IDPH License # 100-07342. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Morgan Park High School Building 1490 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Morgan Park High School Unit 46251 Building ID 1490

Address 1744 W. Pryor Ave. Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
05A	9"X9" GRAY FLOOR TILE	22,130	SF	1st & 2nd FLR CORRIDORS OF 1964 BLDG, 347, 341, 337, BOYS & GIRLS 1ST FLR GYM, LUNCHROOM OFFICE	CHR	MISC	Y	NONE	0		No	ACBM with the potential for damage		MODERATE
05AA	9"x9" Green Floor Tile (Checkerboard Pattern)			Room 218 (1925) ABATED	ABATED	MISC								
05B	9"x9" Tan Floor Tile	4,700	SF	Library, Library Office, Copy Room, Internet Lab	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
05BB	9"x9" Black Floor Tile (Checkerboard Pattern) ABATED			Room 218 (1925) ABATED	ABATED	MISC								
05CC	9"X9" Tan Floor Tile	1,100	SF	ROOMS: 229 & 263	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
06A	12"x12" White w/Speckles Floor Tile (No ACBM, Per 2015-46251-ICR Samples from 1st,2nd,3rd Fl Corrid)	29,350	SF	Throughout Corridors & Classrooms (1925), Rm. 310, 222	ASSUMED	MISC								
06B	12"x12" Brown Floor Tile	11,905	SF	Rooms: 259, 230, 228, 257, 253, 210, 207, 208, 153, 212, 307, 351, and 320	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
06C	12"x12" Gray w/Specks Floor Tile	410	SF	Room 312 (1925)	ASSUMED	MISC		NONE	0		No	ACBM with the potential for damage		MODERATE
09A	MASTIC BENEATH 9"X9" GRAY FLOOR TILE	22,130	SF	1st & 2nd FLR CORRIDORS OF 1964 BLDG, 347, 341, 337, BOYS & GIRLS 1ST FLR GYM, LUNCHROOM OFFICE	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
09AA	9"x9" Green Floor Tile Mastic (Checkerboard Pattern) ABATED			Room 218 (1925) ABATED	ABATED	MISC								
09B	9"X9" Tan Floor Tile Mastic	4,700	SF	Library, Library Office, Copy Room, Internet Lab	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
09BB	9"x9" Black Floor Tile Mastic (Checkerboard Pattern) ABATED			Room 218 (1925) ABATED	ABATED	MISC								
09CC	MASTIC BENEATH 9"X9" TAN FLOOR TILE	1,100	SF	ROOMS 229 & 263	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Morgan Park High School Unit 46251 Building ID 1490

Address 1744 W. Pryor Ave. Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
105	2'x2' pin hole ceiling tile	3,900	SF	3rd fl. corridor, pool, 109- 1025	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
106	12"x12" yellow speckled VFT	13,000	SF	215,217,221,223,225,227,233,234, 235,237,241,243,245,247,331,315,317,319,321,323,325,327, 331,337,339,347 - 1964 bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
107	12"x12" yellow speckled VFT MASTIC	13,000	SF	215,217,221,223,225,227,233,234, 235,237,241,243,245,247,331,315,317,319,321,323,325,327, 331,337,339,347 - 1964 bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
108	12"x12" gray speckled VFT	7,800	SF	215,217,221,223,225,227,233,234, 235,237,241,243,245,247,331,315,317,319,321,323,325,327, 331,337,339,347 - 1964 bldg	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		MODERATE
109	12"x12" gray speckled VFT MASTIC	7,800	SF	215,217,221,223,225,227,233,234, 235,237,241,243,245,247,331,315,317,319,321,323,325,327, 331,337,339,347 - 1964 bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
10A	12"x12" Tan Floor Tile Mastic	1,055	SF	Main Entrance, 141, Office (1964)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
110	Yellow linoleum	1,500	SF	Rm 331- 1964 bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
111	12"x12" gray w/ dark gray streaks VFT	1,000	SF	3rd and 2nd fl. corridors next to elevator- 1964 bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
112	12"x12" gray w/ dark gray streaks VFT MASTIC	1,000	SF	3rd and 3rd fl. corridors next to elevator- 1964 bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
113	14x14 white speckled VFT	1,500	SF	Lunchroom- 1964 bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
114	14x14 white speckled VFT MASTIC	1,500	SF	Lunchroom- 1964 bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
115	14x14 light blue speckled VFT	1,500	SF	Lunchroom- 1964	ASSUMED	MISC	N	NONE	0		No	ACBM with the		MODERATE

Chicago Public Schools

School Morgan Park High School Unit 46251 Building ID 1490

Address 1744 W. Pryor Ave. Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				bldg								potential for damage		
116	14x14 light blue speckled VFT MASTIC	1,500	SF	Lunchroom- 1964 bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
117	14x14 green speckled VFT	1,500	SF	Lunchroom- 1964 bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
118	14x14 green speckled VFT MASTIC	1,500	SF	Lunchroom- 1964	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
12A	12"x12" Tan Floor Tile	1,055	SF	Main Entrance, 141, Office (1964)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
13A	Brown Baseboard	150	LF	Rooms 230, 228, 256, 255 (1925)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
13B	Black Baseboard	290	LF	Across from 114, 357, 355 (1925)	ASSUMED	MISC		NONE	0		No	ACBM with the potential for damage		
14A	Brown Baseboard Mastic	150	LF	Rooms 230, 228, 256, 255 (1925)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
14B	Black Baseboard Mastic	290	LF	Across from 114, 357, 355 (1925)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
17A	12"x12" White w/Speckles Fl Tile Mastic (No ACBM, Per 2015-46251-ICR Samples from 1st,2nd,3rd Fl Corrid)	29,350	SF	Throughout Corridor s&Classrms (1925),Rm. 310 (No ACBM, Per 2015-46251-ICR Samples from 1st,2nd,3rd Fl Corrid)	ASSUMED	MISC								
17B	12"x12" BROWN FLOOR TILE MASTIC	11,905	SF	Rooms: 259, 230, 228, 257, 253, 210, 207, 208, 153, 212, 307, 351.and 320	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
17C	12"x12" Gray w/Specks Floor Tile	410	SF	Room 312 (1925)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
18	12"x12" Tan w/ Beige Floor Tile		SF	Room 298, 398	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
19	12"x12" Tan w/ Beige Floor Tile Mastic		SF	Rooms 298 & 398	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
20	2'x4' Lay In Ceiling Tile (No ACBM, Per 2015-46251-ICR Samples from 1st,2nd,3rd Fl Corrid)	10,000	SF	Throughout 1925 bldg.	ASSUMED	MISC								
21	1' x 1' Ceiling Tile (No ACBM,Per 2015-46251-ICR StairwellSamples)	750	SF	1ST & 2ND FLR HALL BETWEEN OLD AND NEW BLDG		MISC								
22	Spray-on Insulation	10,000	SF	Throughout 1964 Bldg.	CHR	SURFACE	Y	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Morgan Park High School Unit 46251 Building ID 1490

Address 1744 W. Pryor Ave. Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
23	Terrazzo	10,000	SF	1925 Building Hallway - 1st, 2nd and 3rd Floor Corridors	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
24	Plaster - Walls & Ceilings (No ACBM. Per 2015-46251-ICR 1st 2nd 3rd Fl Corrid, Rm357, JaniClset Samples)	100,000	SF	Throughout 1925 Building		SURFACE								
25	Plaster - Walls	100,000	SF	Throughout 1964 Building	ASSUMED	SURFACE	N	NONE	0		No	ACBM with the potential for damage		HIGH
A	2' x 2' Lay In Ceiling Panels	3,480	SF	2ND & 3RD FLR HALLWAYS OF 1964 BLDG	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
B	12"x12" Greenish Floor Tile	535	SF	HALLWAY NEAR NEW ELEVATOR WING	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
C	AIRCELL PIPE INSULATION	205	LF	SOUTH TUNNEL	CHR	TSI	Y	NONE	0		Yes	ACBM with the potential for damage		LOW
CM-1	Rust Carpet Mastic	700	SF	Attendance Office, Assistance Principal's Office (1925)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
CM-2	Green Carpet Mastic	515	SF	Bandroom (1925)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
CM-3	Multicolor Carpet No Mastic, Carpet Nailed Down	1,260	SF	Room 151 (1925)	ASSUMED	MISC		NONE	0		No	ACBM with the potential for damage		MODERATE
CM-5	Rust Colored Carpet Mastic	1,020	SF	Main Office (1964)	ASSUMED	MISC		NONE	0		No	ACBM with the potential for damage		LOW
D	LAB TABLE TOPS	240	SF	SCIENCE CLASSROOMS	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
E	Fitting Insulation on Fiberglass Insulated Piping	1,000	LF	Bldg 1964 - Throughout School	ASSUMED	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
F	Fitting Insulation on Fiberglass Insulated Piping	1,000	SF	Bldg 1925 - Throughout School	ASSUMED	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
G	Vibration Damper	200	SF	Bldg 1964 - Mechanical Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
HA-100	Lining for Room Heating Units	200	SF	Room Heating Units	CHR	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
HA-101	Interior Window Caulk	5,000	LF	Windows Throughout Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
HA-102	Interior Window Glaze	5,000	LF	Windows Throughout Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
HA-103	1'x1' Grooved Ceiling Tile Glue	750	SF	1964 Bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the		MODERATE

Chicago Public Schools

School Morgan Park High School Unit 46251 Building ID 1490

Address 1744 W. Pryor Ave. Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
HA-104	Black Sink Undercoating	5	SF	Room 242	ASSUMED	MISC	N	NONE	0		No	potential for damage ACBM with the potential for damage		LOW

Chicago Public Schools

School Morgan Park High School Unit 46251 Building ID 1490

Address 1744 W. Pryor Ave. Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

Inspector's Comments are Summarized at the End of the Report

Reinspection Date 4/20/2016
Inspector Name <u>Wayne Gardner</u>
100-19039 2/13/2017
Inspector's IDPH License Number / Expiration Date

Inspector's Comments

HA Number:	Inspector Comments:
05A	
05AA	ABATED
05B	
05BB	
05CC	Abated from other rooms EXCEPT ROOMS 229 & 263
06A	No ACBM, Per 2015-46251-ICR Samples from 1st,2nd,3rd Fl Corrid
06B	
06C	
09A	
09AA	
09B	
09BB	
09CC	Abated from other rooms EXCEPT ROOMS 229 & 263
105	
106	
107	
108	
109	
10A	
110	
111	
112	
113	
114	

Chicago Public Schools

School Morgan Park High School Unit 46251 Building ID 1490

Address 1744 W. Pryor Ave. Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
115	
116	
117	
118	
12A	
13A	
13B	
14A	
14B	
17A	No ACBM, Per 2015-46251-ICR Samples from 1st,2nd,3rd Fl Corrid
17B	
17C	
18	
19	
20	No ACBM, Per 2015-46251-ICR Samples from 1st,2nd,3rd Fl Corrid
21	No ACBM, Per 2015-46251-ICR Stairwell Samples
22	
23	
24	No ACBM, Per 2015-46251-ICR 1st 2nd 3rd Fl Corrid, Rm357, JaniClset Samples
25	
A	
B	
C	
CM-1	
CM-2	
CM-3	
CM-5	
D	
E	

Chicago Public Schools

School Morgan Park High School Unit 46251 Building ID 1490

Address 1744 W. Pryor Ave. Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
F	
G	
HA-100	
HA-101	
HA-102	
HA-103	
HA-104	

Table II

Management Planner's Review

Chicago Public Schools

School Morgan Park High School

Unit 46251

Building ID 1490

Address 1744 W. Pryor Ave.

Chicago, IL, 60643

Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
05A	9"X9" GRAY FLOOR TILE	22,130	SF	1st & 2nd FLR CORRIDORS OF 1964 BLDG, 347, 341, 337, BOYS & GIRLS 1ST FLR GYM, LUNCHROOM OFFICE	Chrysotile	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
05AA	9"x9" Green Floor Tile (Checkerboard Pattern)			Room 218 (1925) ABATED	Abated	MISC					
05B	9"x9" Tan Floor Tile	4,700	SF	Library, Library Office, Copy Room, Internet Lab	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
05BB	9"x9" Black Floor Tile (Checkerboard Pattern) ABATED			Room 218 (1925) ABATED	Abated	MISC					
05CC	9"X9" Tan Floor Tile	1,100	SF	ROOMS: 229 & 263	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
06A	12"x12" White w/Speckles Floor Tile (No ACBM, Per 2015-46251-ICR Samples from 1st,2nd,3rd Fl Corrid)	29,350	SF	Throughout Corridors & Classrooms (1925), Rm. 310, 222	Assumed	MISC			SF		
06B	12"x12" Brown Floor Tile	11,905	SF	Rooms: 259, 230, 228, 257, 253, 210, 207, 208, 153, 212, 307, 351, and 320	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
06C	12"x12" Gray w/Specks Floor Tile	410	SF	Room 312 (1925)	Assumed	MISC		0	SF	6 ACBM with the potential for damage	Follow O&M Plan
09A	MASTIC BENEATH 9"X9" GRAY FLOOR TILE	22,130	SF	1st & 2nd FLR CORRIDORS OF 1964 BLDG, 347, 341, 337, BOYS & GIRLS 1ST FLR GYM, LUNCHROOM OFFICE	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
09AA	9"x9" Green Floor Tile Mastic (Checkerboard Pattern) ABATED			Room 218 (1925) ABATED	Abated	MISC					
09B	9"X9" Tan Floor Tile Mastic	4,700	SF	Library, Library Office, Copy Room, Internet Lab	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
09BB	9"x9" Black Floor Tile Mastic (Checkerboard Pattern) ABATED			Room 218 (1925) ABATED	Abated	MISC					
09CC	MASTIC BENEATH 9"X9" TAN FLOOR TILE	1,100	SF	ROOMS 229 & 263	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
105	2'x2' pin hole ceiling tile	3,900	SF	3rd fl. corridor, pool, 109- 1025	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
106	12"x12" yellow speckled VFT	13,000	SF	215,217,221,223,225,227,233,234, 235,237,241,243,245,247,331,315,317, 319,321,323,325,327,331,337,339,347 - 1964 bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
107	12"x12" yellow speckled VFT MASTIC	13,000	SF	215,217,221,223,225,227,233,234, 235,237,241,243,245,247,331,315,317, 319,321,323,325,327,331,337,339,347 - 1964 bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
108	12"x12" gray speckled VFT	7,800	SF	215,217,221,223,225,227,233,234, 235,237,241,243,245,247,331,315,317,	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Morgan Park High School

Unit 46251

Building ID 1490

Address 1744 W. Pryor Ave.

Chicago, IL, 60643

Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				319,321,323,325,327,331,337,339,347 - 1964 bldg							
109	12"x12" gray speckled VFT MASTIC	7,800	SF	215,217,221,223,225,227,233,234, 235,237,241,243,245,247,331,315,317, 319,321,323,325,327,331,337,339,347 - 1964 bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
10A	12"x12" Tan Floor Tile Mastic	1,055	SF	Main Entrance, 141, Office (1964)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
110	Yellow linoleum	1,500	SF	Rm 331- 1964 bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
111	12"x12" gray w/ dark gray streaks VFT	1,000	SF	3rd and 2nd fl. corridors next to elevator- 1964 bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
112	12"x12" gray w/ dark gray streaks VFT MASTIC	1,000	SF	3rd and 3rd fl. corridors next to elevator- 1964 bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
113	14x14 white speckled VFT	1,500	SF	Lunchroom- 1964 bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
114	14x14 white speckled VFT MASTIC	1,500	SF	Lunchroom- 1964 bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
115	14x14 light blue speckled VFT	1,500	SF	Lunchroom- 1964 bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
116	14x14 light blue speckled VFT MASTIC	1,500	SF	Lunchroom- 1964 bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
117	14x14 green speckled VFT	1,500	SF	Lunchroom- 1964 bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
118	14x14 green speckled VFT MASTIC	1,500	SF	Lunchroom- 1964	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
12A	12"x12" Tan Floor Tile	1,055	SF	Main Entrance, 141, Office (1964)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
13A	Brown Baseboard	150	LF	Rooms 230, 228, 256, 255 (1925)	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
13B	Black Baseboard	290	LF	Across from 114, 357, 355 (1925)	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
14A	Brown Baseboard Mastic	150	LF	Rooms 230, 228, 256, 255 (1925)	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
14B	Black Baseboard Mastic	290	LF	Across from 114, 357, 355 (1925)	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
17A	12"x12" White w/Speckles FI Tile Mastic (No ACBM, Per 2015-46251-ICR Samples from 1st,2nd,3rd FI Corrid)	29,350	SF	ThroughoutCorridors&Class'rms (1925),Rm. 310 (No ACBM, Per 2015-46251-ICR Samples from 1st,2nd,3rd FI Corrid)	Assumed	MISC			SF		
17B	12"x12" BROWN FLOOR TILE MASTIC	11,905	SF	Rooms: 259, 230, 228, 257, 253, 210, 207, 208, 153, 212, 307, 351,and 320	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
17C	12"x12" Gray w/Specks Floor Tile	410	SF	Room 312 (1925)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
18	12"x12" Tan w/ Beige Floor Tile		SF	Room 298, 398	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
19	12"x12" Tan w/ Beige Floor Tile Mastic		SF	Rooms 298 & 398	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
20	2'x4' Lay In Ceiling Tile (No ACBM, Per 2015-46251-ICR Samples from 1st,2nd,3rd FI Corrid)	10,000	SF	Throughout 1925 bldg.	Assumed	MISC			SF		
21	1' x 1' Ceiling Tile (No ACBM,Per 2015-46251-ICR StairwellSamples)	750	SF	1ST & 2ND FLR HALL BETWEEN OLD AND NEW BLDG		MISC			SF		

Chicago Public Schools

School Morgan Park High School

Unit 46251

Building ID 1490

Address 1744 W. Pryor Ave.

Chicago, IL, 60643

Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
22	Spray-on Insulation	10,000	SF	Throughout 1964 Bldg.	Chrysotile	SURFACE	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
23	Terrazzo	10,000	SF	1925 Building Hallway - 1st, 2nd and 3rd Floor Corridors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
24	Plaster - Walls & Ceilings (No ACBM, Per 2015-46251-ICR 1st 2nd 3rd Fl Corrid, Rm357, JaniClset Samples)	100,000	SF	Throughout 1925 Building		SURFACE			SF		
25	Plaster - Walls	100,000	SF	Throughout 1964 Building	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
A	2' x 2' Lay In Ceiling Panels	3,480	SF	2ND & 3RD FLR HALLWAYS OF 1964 BLDG	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
B	12"x12" Greenish Floor Tile	535	SF	HALLWAY NEAR NEW ELEVATOR WING	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
C	AIRCELL PIPE INSULATION	205	LF	SOUTH TUNNEL	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
CM-1	Rust Carpet Mastic	700	SF	Attendance Office, Assistance Principal's Office (1925)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
CM-2	Green Carpet Mastic	515	SF	Bandroom (1925)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
CM-3	Multicolor Carpet No Mastic, Carpet Nailed Down	1,260	SF	Room 151 (1925)	Assumed	MISC		0	SF	6 ACBM with the potential for damage	Follow O&M Plan
CM-5	Rust Colored Carpet Mastic	1,020	SF	Main Office (1964)	Assumed	MISC		0	SF	6 ACBM with the potential for damage	Follow O&M Plan
D	LAB TABLE TOPS	240	SF	SCIENCE CLASSROOMS	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
E	Fitting Insulation on Fiberglass Insulated Piping	1,000	LF	Bldg 1964 - Throughout School	Assumed	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
F	Fitting Insulation on Fiberglass Insulated Piping	1,000	SF	Bldg 1925 - Throughout School	Assumed	TSI	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
G	Vibration Damper	200	SF	Bldg 1964 - Mechanical Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
HA-100	Lining for Room Heating Units	200	SF	Room Heating Units	Chrysotile	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
HA-101	Interior Window Caulk	5,000	LF	Windows Throughout Building	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
HA-102	Interior Window Glaze	5,000	LF	Windows Throughout Building	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
HA-103	1'x1' Grooved Ceiling Tile Glue	750	SF	1964 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
HA-104	Black Sink Undercoating	5	SF	Room 242	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Morgan Park High School
Address 1744 W. Pryor Ave.

Unit 46251
 Chicago, IL, 60643

Building ID 1490
Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG Consultants, Inc.
 855 W. Adams St., Ste. 200
 Phone: (312) 733-6262

Fax: (312) 733-5612

Management Planner's Comments Summarized at the End of the Report

Review Date	6/8/2016
Manager Planner Name	Jigar Shah
100-07342	1/19/2017
Manager IDPH License No/Expiration	

HA Number	Management Comments
05A	
05AA	
05B	
05BB	
05CC	
06A	
06B	
06C	
09A	
09AA	
09B	
09BB	
09CC	

Chicago Public Schools

School Morgan Park High School

Unit 46251

Building ID 1490

Address 1744 W. Pryor Ave.

Chicago, IL, 60643

Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
105	
106	
107	
108	
109	
10A	
110	
111	
112	
113	
114	
115	
116	
117	
118	
12A	
13A	
13B	
14A	
14B	
17A	
17B	
17C	
18	
19	
20	
21	

Chicago Public Schools

School Morgan Park High School

Unit 46251

Building ID 1490

Address 1744 W. Pryor Ave.

Chicago, IL, 60643

Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
22	
23	
24	
25	
A	
B	
C	
CM-1	
CM-2	
CM-3	
CM-5	
D	
E	
F	
G	
HA-100	
HA-101	
HA-102	
HA-103	
HA-104	

Chicago Public Schools

GSG Consultants, Inc.

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUIDLING ID: **1490**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**
SCHOOL NAME: **Morgan Park High School** INSPECTION DATE: **4/20/2016**
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-19039**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **05A**
MATERIAL DESCRIPTION: **9"X9" GRAY FLOOR TILE**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **1st & 2nd FLR CORRIDORS OF 1964 BLDG, 347, 341, 337, BOYS & GIRLS 1ST FLR GYM, LUNCHROOM OFFICE**

MATERIAL QUANTITY: **22130** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/20/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUILDING ID: **1490**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Morgan Park High School** REVIEW DATE: **6/8/2016**
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-19039**

HOMOGENEOUS AREA: **05A**
MATERIAL DESCRIPTION: **9"X9" GRAY FLOOR TILE**
MATERIAL LOCATION: **1st & 2nd FLR CORRIDORS OF 1964 BLDG, 347, 341, 337, BOYS & GIRLS 1ST FLR GYM, LUNCHROOM OFFICE**
MATERIAL QUANTITY: **22130** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **06/08/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUIDLING ID: **1490**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**
SCHOOL NAME: **Morgan Park High School** INSPECTION DATE: **4/20/2016**
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-19039**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **05AA**
MATERIAL DESCRIPTION: **9"x9" Green Floor Tile (Checkerboard Pattern)**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 218 (1925) ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **ABATED**

Inspector's Signature:



Date: **04/20/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUIDLING ID: **1490**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Morgan Park High School** REVIEW DATE: **6/8/2016**
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-19039**

HOMOGENEOUS AREA: **05AA**
MATERIAL DESCRIPTION: **9"x9" Green Floor Tile (Checkerboard Pattern)**
MATERIAL LOCATION: **Room 218 (1925) ABATED**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **06/08/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUIDLING ID: **1490**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**
SCHOOL NAME: **Morgan Park High School** INSPECTION DATE: **4/20/2016**
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-19039**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **05B**
MATERIAL DESCRIPTION: **9"x9" Tan Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Library, Library Office, Copy Room, Internet Lab**
MATERIAL QUANTITY: **4700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/20/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUILDING ID: **1490**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Morgan Park High School** REVIEW DATE: **6/8/2016**
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-19039**

HOMOGENEOUS AREA: **05B**
MATERIAL DESCRIPTION: **9"x9" Tan Floor Tile**
MATERIAL LOCATION: **Library, Library Office, Copy Room, Internet Lab**
MATERIAL QUANTITY: **4700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/08/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUILDING ID: **1490**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**
SCHOOL NAME: **Morgan Park High School** INSPECTION DATE: **4/20/2016**
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-19039**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **05BB**
MATERIAL DESCRIPTION: **9"x9" Black Floor Tile (Checkerboard Pattern) ABATED**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 218 (1925) ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/20/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUILDING ID: **1490**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Morgan Park High School** REVIEW DATE: **6/8/2016**
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-19039**

HOMOGENEOUS AREA: **05BB**
MATERIAL DESCRIPTION: **9"x9" Black Floor Tile (Checkerboard Pattern) ABATED**
MATERIAL LOCATION: **Room 218 (1925) ABATED**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/08/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUILDING ID: **1490**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**
SCHOOL NAME: **Morgan Park High School** INSPECTION DATE: **4/20/2016**
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-19039**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **05CC**
MATERIAL DESCRIPTION: **9"X9" Tan Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **ROOMS: 229 & 263**
MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS: **Abated from other rooms EXCEPT ROOMS 229 & 263**

Inspector's Signature:



Date: **04/20/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUIDLING ID: **1490**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Morgan Park High School** REVIEW DATE: **6/8/2016**
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-19039**

HOMOGENEOUS AREA: **05CC**
MATERIAL DESCRIPTION: **9"X9" Tan Floor Tile**
MATERIAL LOCATION: **ROOMS: 229 & 263**
MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/08/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUIDLING ID: **1490**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**
SCHOOL NAME: **Morgan Park High School** INSPECTION DATE: **4/20/2016**
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-19039**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **06A**
MATERIAL DESCRIPTION: **12"x12" White w/Speckles Floor Tile (No ACM, Per 2015-46251-ICR Samples from 1st,2nd,3rd FI Corrid)**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON: **Deterioration**
HISTORICAL RESPONSE ACTION: **Remove**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Corridors & Classrooms (1925), Rm. 310, 222**

MATERIAL QUANTITY: **29350** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **No ACM, Per 2015-46251-ICR Samples from 1st,2nd,3rd FI Corrid**

Inspector's Signature:



Date: **04/20/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUILDING ID: **1490**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Morgan Park High School** REVIEW DATE: **6/8/2016**
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-19039**

HOMOGENEOUS AREA: **06A**
MATERIAL DESCRIPTION: **12"x12" White w/Speckles Floor Tile (No ACBM, Per 2015-46251-ICR Samples from 1st,2nd,3rd Fl Corrid)**
MATERIAL LOCATION: **Throughout Corridors & Classrooms (1925), Rm. 310, 222**
MATERIAL QUANTITY: **29350** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Remove

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **06/08/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUIDLING ID: **1490**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**
SCHOOL NAME: **Morgan Park High School** INSPECTION DATE: **4/20/2016**
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-19039**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **06B**
MATERIAL DESCRIPTION: **12"x12" Brown Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Rooms: 259, 230, 228, 257, 253, 210, 207, 208, 153, 212, 307, 351, and 320**
MATERIAL QUANTITY: **11905** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/20/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUILDING ID: **1490**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Morgan Park High School** REVIEW DATE: **6/8/2016**
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-19039**

HOMOGENEOUS AREA: **06B**
MATERIAL DESCRIPTION: **12"x12" Brown Floor Tile**
MATERIAL LOCATION: **Rooms: 259, 230, 228, 257, 253, 210, 207, 208, 153, 212, 307, 351, and 320**
MATERIAL QUANTITY: **11905** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/08/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUIDLING ID: **1490**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**
SCHOOL NAME: **Morgan Park High School** INSPECTION DATE: **4/20/2016**
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-19039**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **06C**
MATERIAL DESCRIPTION: **12"x12" Gray w/Specks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Room 312 (1925)**
MATERIAL QUANTITY: **410** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: **04/20/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUIDLING ID: **1490**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Morgan Park High School** REVIEW DATE: **6/8/2016**
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-19039**

HOMOGENEOUS AREA: **06C**
MATERIAL DESCRIPTION: **12"x12" Gray w/Specks Floor Tile**
MATERIAL LOCATION: **Room 312 (1925)**
MATERIAL QUANTITY: **410** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/08/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUIDLING ID: **1490**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**
SCHOOL NAME: **Morgan Park High School** INSPECTION DATE: **4/20/2016**
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-19039**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **09A**
MATERIAL DESCRIPTION: **MASTIC BENEATH 9"X9" GRAY FLOOR TILE**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **1st & 2nd FLR CORRIDORS OF 1964 BLDG, 347, 341, 337, BOYS & GIRLS 1ST FLR GYM, LUNCHROOM OFFICE**

MATERIAL QUANTITY: **22130** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/20/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUILDING ID: **1490**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Morgan Park High School** REVIEW DATE: **6/8/2016**
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-19039**

HOMOGENEOUS AREA: **09A**
MATERIAL DESCRIPTION: **MASTIC BENEATH 9"X9" GRAY FLOOR TILE**
MATERIAL LOCATION: **1st & 2nd FLR CORRIDORS OF 1964 BLDG, 347, 341, 337, BOYS & GIRLS 1ST FLR GYM, LUNCHROOM OFFICE**
MATERIAL QUANTITY: **22130** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **06/08/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUIDLING ID: **1490**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**
SCHOOL NAME: **Morgan Park High School** INSPECTION DATE: **4/20/2016**
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-19039**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **09AA**
MATERIAL DESCRIPTION: **9"x9" Green Floor Tile Mastic (Checkerboard Pattern) ABATED**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 218 (1925) ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/20/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUIDLING ID: **1490**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Morgan Park High School** REVIEW DATE: **6/8/2016**
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-19039**

HOMOGENEOUS AREA: **09AA**
MATERIAL DESCRIPTION: **9"x9" Green Floor Tile Mastic (Checkerboard Pattern) ABATED**
MATERIAL LOCATION: **Room 218 (1925) ABATED**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **06/08/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUIDLING ID: **1490**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**
SCHOOL NAME: **Morgan Park High School** INSPECTION DATE: **4/20/2016**
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-19039**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **09B**
MATERIAL DESCRIPTION: **9"X9" Tan Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Library, Library Office, Copy Room, Internet Lab**
MATERIAL QUANTITY: **4700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/20/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUIDLING ID: **1490**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Morgan Park High School** REVIEW DATE: **6/8/2016**
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-19039**

HOMOGENEOUS AREA: **09B**
MATERIAL DESCRIPTION: **9"X9" Tan Floor Tile Mastic**
MATERIAL LOCATION: **Library, Library Office, Copy Room, Internet Lab**
MATERIAL QUANTITY: **4700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/08/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUIDLING ID: **1490**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**
SCHOOL NAME: **Morgan Park High School** INSPECTION DATE: **4/20/2016**
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-19039**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **09BB**
MATERIAL DESCRIPTION: **9"x9" Black Floor Tile Mastic (Checkerboard Pattern) ABATED**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 218 (1925) ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/20/2016**

Chicago Public Schools

GSG Consultants, Inc.

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUIDLING ID: **1490**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Morgan Park High School** REVIEW DATE: **6/8/2016**
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-19039**

HOMOGENEOUS AREA: **09BB**

MATERIAL DESCRIPTION: **9"x9" Black Floor Tile Mastic (Checkerboard Pattern) ABATED**

MATERIAL LOCATION: **Room 218 (1925) ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **06/08/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUIDLING ID: **1490**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**
SCHOOL NAME: **Morgan Park High School** INSPECTION DATE: **4/20/2016**
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-19039**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **09CC**
MATERIAL DESCRIPTION: **MASTIC BENEATH 9"X9" TAN FLOOR TILE**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **ROOMS 229 & 263**
MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS: **Abated from other rooms EXCEPT ROOMS 229 & 263**

Inspector's Signature: _____



Date: 04/20/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUIDLING ID: **1490**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Morgan Park High School** REVIEW DATE: **6/8/2016**
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-19039**

HOMOGENEOUS AREA: **09CC**
MATERIAL DESCRIPTION: **MASTIC BENEATH 9"X9" TAN FLOOR TILE**
MATERIAL LOCATION: **ROOMS 229 & 263**
MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/08/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUIDLING ID: **1490**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**
SCHOOL NAME: **Morgan Park High School** INSPECTION DATE: **4/20/2016**
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-19039**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **105**
MATERIAL DESCRIPTION: **2'x2' pin hole ceiling tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **3rd fl. corridor, pool, 109- 1025**
MATERIAL QUANTITY: **3900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/20/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUIDLING ID: **1490**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Morgan Park High School** REVIEW DATE: **6/8/2016**
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-19039**

HOMOGENEOUS AREA: **105**
MATERIAL DESCRIPTION: **2'x2' pin hole ceiling tile**
MATERIAL LOCATION: **3rd fl. corridor, pool, 109- 1025**
MATERIAL QUANTITY: **3900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/08/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUIDLING ID: **1490**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**
SCHOOL NAME: **Morgan Park High School** INSPECTION DATE: **4/20/2016**
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-19039**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **106**
MATERIAL DESCRIPTION: **12"x12" yellow speckled VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **215,217,221,223,225,227,233,234,
235,237,241,243,245,247,331,315,317,319,321,323,325,327,331,337,339,347 - 1964 bldg**

MATERIAL QUANTITY: **13000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 04/20/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUIDLING ID: **1490**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Morgan Park High School** REVIEW DATE: **6/8/2016**
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-19039**

HOMOGENEOUS AREA: **106**
MATERIAL DESCRIPTION: **12"x12" yellow speckled VFT**
MATERIAL LOCATION: **215,217,221,223,225,227,233,234,
235,237,241,243,245,247,331,315,317,319,321,323,325,327,331,337,339,347 - 1964 bldg**
MATERIAL QUANTITY: **13000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **06/08/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUIDLING ID: **1490**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**
SCHOOL NAME: **Morgan Park High School** INSPECTION DATE: **4/20/2016**
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-19039**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **107**
MATERIAL DESCRIPTION: **12"x12" yellow speckled VFT MASTIC**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **215,217,221,223,225,227,233,234,
235,237,241,243,245,247,331,315,317,319,321,323,325,327,331,337,339,347 - 1964 bldg**

MATERIAL QUANTITY: **13000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/20/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUILDING ID: **1490**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Morgan Park High School** REVIEW DATE: **6/8/2016**
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-19039**

HOMOGENEOUS AREA: **107**
MATERIAL DESCRIPTION: **12"x12" yellow speckled VFT MASTIC**
MATERIAL LOCATION: **215,217,221,223,225,227,233,234,
235,237,241,243,245,247,331,315,317,319,321,323,325,327,331,337,339,347 - 1964 bldg**
MATERIAL QUANTITY: **13000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **06/08/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUIDLING ID: **1490**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**
SCHOOL NAME: **Morgan Park High School** INSPECTION DATE: **4/20/2016**
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-19039**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **108**
MATERIAL DESCRIPTION: **12"x12" gray speckled VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **215,217,221,223,225,227,233,234,
235,237,241,243,245,247,331,315,317,319,321,323,325,327,331,337,339,347 - 1964 bldg**

MATERIAL QUANTITY: **7800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/20/2016**

Chicago Public Schools

GSG Consultants, Inc.

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUIDLING ID: **1490**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Morgan Park High School** REVIEW DATE: **6/8/2016**
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-19039**

HOMOGENEOUS AREA: **108**
MATERIAL DESCRIPTION: **12"x12" gray speckled VFT**
MATERIAL LOCATION: **215,217,221,223,225,227,233,234,
235,237,241,243,245,247,331,315,317,319,321,323,325,327,331,337,339,347 - 1964 bldg**
MATERIAL QUANTITY: **7800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **06/08/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUIDLING ID: **1490**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**
SCHOOL NAME: **Morgan Park High School** INSPECTION DATE: **4/20/2016**
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-19039**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **109**
MATERIAL DESCRIPTION: **12"x12" gray speckled VFT MASTIC**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **215,217,221,223,225,227,233,234,
235,237,241,243,245,247,331,315,317,319,321,323,325,327,331,337,339,347 - 1964 bldg**

MATERIAL QUANTITY: **7800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/20/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUILDING ID: **1490**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Morgan Park High School** REVIEW DATE: **6/8/2016**
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-19039**

HOMOGENEOUS AREA: **109**
MATERIAL DESCRIPTION: **12"x12" gray speckled VFT MASTIC**
MATERIAL LOCATION: **215,217,221,223,225,227,233,234,
235,237,241,243,245,247,331,315,317,319,321,323,325,327,331,337,339,347 - 1964 bldg**
MATERIAL QUANTITY: **7800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **06/08/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUIDLING ID: **1490**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**
SCHOOL NAME: **Morgan Park High School** INSPECTION DATE: **4/20/2016**
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-19039**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10A**
MATERIAL DESCRIPTION: **12"x12" Tan Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Main Entrance, 141, Office (1964)**
MATERIAL QUANTITY: **1055** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/20/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUIDLING ID: **1490**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Morgan Park High School** REVIEW DATE: **6/8/2016**
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-19039**

HOMOGENEOUS AREA: **10A**
MATERIAL DESCRIPTION: **12"x12" Tan Floor Tile Mastic**
MATERIAL LOCATION: **Main Entrance, 141, Office (1964)**
MATERIAL QUANTITY: **1055** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/08/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUIDLING ID: **1490**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**
SCHOOL NAME: **Morgan Park High School** INSPECTION DATE: **4/20/2016**
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-19039**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **110**
MATERIAL DESCRIPTION: **Yellow linoleum**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Rm 331- 1964 bldg**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/20/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUILDING ID: **1490**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Morgan Park High School** REVIEW DATE: **6/8/2016**
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-19039**

HOMOGENEOUS AREA: **110**
MATERIAL DESCRIPTION: **Yellow linoleum**
MATERIAL LOCATION: **Rm 331- 1964 bldg**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/08/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUIDLING ID: **1490**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**
SCHOOL NAME: **Morgan Park High School** INSPECTION DATE: **4/20/2016**
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-19039**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **111**
MATERIAL DESCRIPTION: **12"x12" gray w/ dark gray streaks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **3rd and 2nd fl. corridors next to elevator- 1964 bldg**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/20/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUIDLING ID: **1490**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Morgan Park High School** REVIEW DATE: **6/8/2016**
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-19039**

HOMOGENEOUS AREA: **111**
MATERIAL DESCRIPTION: **12"x12" gray w/ dark gray streaks VFT**
MATERIAL LOCATION: **3rd and 2nd fl. corridors next to elevator- 1964 bldg**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/08/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUIDLING ID: **1490**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**
SCHOOL NAME: **Morgan Park High School** INSPECTION DATE: **4/20/2016**
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-19039**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **112**
MATERIAL DESCRIPTION: **12"x12" gray w/ dark gray streaks VFT MASTIC**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **3rd and 3rd fl. corridors next to elevator- 1964 bldg**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/20/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUIDLING ID: **1490**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Morgan Park High School** REVIEW DATE: **6/8/2016**
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-19039**

HOMOGENEOUS AREA: **112**
MATERIAL DESCRIPTION: **12"x12" gray w/ dark gray streaks VFT MASTIC**
MATERIAL LOCATION: **3rd and 3rd fl. corridors next to elevator- 1964 bldg**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/08/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUIDLING ID: **1490**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**
SCHOOL NAME: **Morgan Park High School** INSPECTION DATE: **4/20/2016**
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-19039**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **113**
MATERIAL DESCRIPTION: **14x14 white speckled VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Lunchroom- 1964 bldg**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/20/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUIDLING ID: **1490**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Morgan Park High School** REVIEW DATE: **6/8/2016**
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-19039**

HOMOGENEOUS AREA: **113**
MATERIAL DESCRIPTION: **14x14 white speckled VFT**
MATERIAL LOCATION: **Lunchroom- 1964 bldg**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/08/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUIDLING ID: **1490**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**
SCHOOL NAME: **Morgan Park High School** INSPECTION DATE: **4/20/2016**
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-19039**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **114**
MATERIAL DESCRIPTION: **14x14 white speckled VFT MASTIC**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Lunchroom- 1964 bldg**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/20/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUIDLING ID: **1490**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Morgan Park High School** REVIEW DATE: **6/8/2016**
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-19039**

HOMOGENEOUS AREA: **114**
MATERIAL DESCRIPTION: **14x14 white speckled VFT MASTIC**
MATERIAL LOCATION: **Lunchroom- 1964 bldg**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/08/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUIDLING ID: **1490**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**
SCHOOL NAME: **Morgan Park High School** INSPECTION DATE: **4/20/2016**
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-19039**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **115**
MATERIAL DESCRIPTION: **14x14 light blue speckled VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Lunchroom- 1964 bldg**

MATERIAL QUANTITY: **1500**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/20/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUIDLING ID: **1490**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Morgan Park High School** REVIEW DATE: **6/8/2016**
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-19039**

HOMOGENEOUS AREA: **115**
MATERIAL DESCRIPTION: **14x14 light blue speckled VFT**
MATERIAL LOCATION: **Lunchroom- 1964 bldg**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/08/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUIDLING ID: **1490**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**
SCHOOL NAME: **Morgan Park High School** INSPECTION DATE: **4/20/2016**
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-19039**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **116**
MATERIAL DESCRIPTION: **14x14 light blue speckled VFT MASTIC**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Lunchroom- 1964 bldg**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/20/2016**

Chicago Public Schools

GSG Consultants, Inc.

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUIDLING ID: **1490**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Morgan Park High School** REVIEW DATE: **6/8/2016**
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-19039**

HOMOGENEOUS AREA: **116**
MATERIAL DESCRIPTION: **14x14 light blue speckled VFT MASTIC**
MATERIAL LOCATION: **Lunchroom- 1964 bldg**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/08/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUIDLING ID: **1490**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**
SCHOOL NAME: **Morgan Park High School** INSPECTION DATE: **4/20/2016**
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-19039**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **117**
MATERIAL DESCRIPTION: **14x14 green speckled VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Lunchroom- 1964 bldg**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 04/20/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUIDLING ID: **1490**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Morgan Park High School** REVIEW DATE: **6/8/2016**
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-19039**

HOMOGENEOUS AREA: **117**
MATERIAL DESCRIPTION: **14x14 green speckled VFT**
MATERIAL LOCATION: **Lunchroom- 1964 bldg**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/08/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUIDLING ID: **1490**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**
SCHOOL NAME: **Morgan Park High School** INSPECTION DATE: **4/20/2016**
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-19039**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **118**
MATERIAL DESCRIPTION: **14x14 green speckled VFT MASTIC**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Lunchroom- 1964**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/20/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUIDLING ID: **1490**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Morgan Park High School** REVIEW DATE: **6/8/2016**
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-19039**

HOMOGENEOUS AREA: **118**
MATERIAL DESCRIPTION: **14x14 green speckled VFT MASTIC**
MATERIAL LOCATION: **Lunchroom- 1964**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/08/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUIDLING ID: **1490**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**
SCHOOL NAME: **Morgan Park High School** INSPECTION DATE: **4/20/2016**
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-19039**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12A**
MATERIAL DESCRIPTION: **12"x12" Tan Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Main Entrance, 141, Office (1964)**
MATERIAL QUANTITY: **1055** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 04/20/2016

Chicago Public Schools

GSG Consultants, Inc.

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUIDLING ID: **1490**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Morgan Park High School** REVIEW DATE: **6/8/2016**
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-19039**

HOMOGENEOUS AREA: **12A**
MATERIAL DESCRIPTION: **12"x12" Tan Floor Tile**
MATERIAL LOCATION: **Main Entrance, 141, Office (1964)**
MATERIAL QUANTITY: **1055** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/08/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUIDLING ID: **1490**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**
SCHOOL NAME: **Morgan Park High School** INSPECTION DATE: **4/20/2016**
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-19039**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13A**
MATERIAL DESCRIPTION: **Brown Baseboard**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 230, 228, 256, 255 (1925)**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **04/20/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUIDLING ID: **1490**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Morgan Park High School** REVIEW DATE: **6/8/2016**
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-19039**

HOMOGENEOUS AREA: **13A**
MATERIAL DESCRIPTION: **Brown Baseboard**
MATERIAL LOCATION: **Rooms 230, 228, 256, 255 (1925)**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/08/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUIDLING ID: **1490**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**
SCHOOL NAME: **Morgan Park High School** INSPECTION DATE: **4/20/2016**
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-19039**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13B**
MATERIAL DESCRIPTION: **Black Baseboard**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Across from 114, 357, 355 (1925)**

MATERIAL QUANTITY: **290**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **04/20/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUIDLING ID: **1490**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Morgan Park High School** REVIEW DATE: **6/8/2016**
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-19039**

HOMOGENEOUS AREA: **13B**
MATERIAL DESCRIPTION: **Black Baseboard**
MATERIAL LOCATION: **Across from 114, 357, 355 (1925)**
MATERIAL QUANTITY: **290** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/08/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUIDLING ID: **1490**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**
SCHOOL NAME: **Morgan Park High School** INSPECTION DATE: **4/20/2016**
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-19039**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14A**
MATERIAL DESCRIPTION: **Brown Baseboard Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 230, 228, 256, 255 (1925)**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **04/20/2016**

Chicago Public Schools

GSG Consultants, Inc.

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUIDLING ID: **1490**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Morgan Park High School** REVIEW DATE: **6/8/2016**
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-19039**

HOMOGENEOUS AREA: **14A**
MATERIAL DESCRIPTION: **Brown Baseboard Mastic**
MATERIAL LOCATION: **Rooms 230, 228, 256, 255 (1925)**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/08/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUIDLING ID: **1490**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**
SCHOOL NAME: **Morgan Park High School** INSPECTION DATE: **4/20/2016**
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-19039**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14B**
MATERIAL DESCRIPTION: **Black Baseboard Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Across from 114, 357, 355 (1925)**
MATERIAL QUANTITY: **290** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **04/20/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUIDLING ID: **1490**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Morgan Park High School** REVIEW DATE: **6/8/2016**
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-19039**

HOMOGENEOUS AREA: **14B**
MATERIAL DESCRIPTION: **Black Baseboard Mastic**
MATERIAL LOCATION: **Across from 114, 357, 355 (1925)**
MATERIAL QUANTITY: **290** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/08/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUIDLING ID: **1490**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**
SCHOOL NAME: **Morgan Park High School** INSPECTION DATE: **4/20/2016**
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-19039**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17A**
MATERIAL DESCRIPTION: **12"x12" White w/Speckles FI Tile Mastic (No ACBM, Per 2015-46251-ICR Samples from 1st,2nd,3rd FI Corrid)**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ThroughoutCorridors&Classr'ms (1925),Rm. 310
(No ACBM, Per 2015-46251-ICR Samples from 1st,2nd,3rd FI Corrid)**

MATERIAL QUANTITY: **29350** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **No ACBM, Per 2015-46251-ICR Samples from 1st,2nd,3rd FI Corrid**

Inspector's Signature:



Date: **04/20/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUILDING ID: **1490**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Morgan Park High School** REVIEW DATE: **6/8/2016**
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-19039**

HOMOGENEOUS AREA: **17A**
MATERIAL DESCRIPTION: **12"x12" White w/Speckles FI Tile Mastic (No ACM, Per 2015-46251-ICR Samples from 1st,2nd,3rd FI Corrid)**
MATERIAL LOCATION: **Throughout Corridors & Classr'ms (1925), Rm. 310 (No ACM, Per 2015-46251-ICR Samples from 1st,2nd,3rd FI Corrid)**
MATERIAL QUANTITY: **29350** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/08/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUIDLING ID: **1490**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**
SCHOOL NAME: **Morgan Park High School** INSPECTION DATE: **4/20/2016**
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-19039**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17B**
MATERIAL DESCRIPTION: **12"x12" BROWN FLOOR TILE MASTIC**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms: 259, 230, 228, 257, 253, 210, 207, 208, 153, 212, 307, 351, and 320**
MATERIAL QUANTITY: **11905** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/20/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUIDLING ID: **1490**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Morgan Park High School** REVIEW DATE: **6/8/2016**
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-19039**

HOMOGENEOUS AREA: **17B**
MATERIAL DESCRIPTION: **12"x12" BROWN FLOOR TILE MASTIC**
MATERIAL LOCATION: **Rooms: 259, 230, 228, 257, 253, 210, 207, 208, 153, 212, 307, 351, and 320**
MATERIAL QUANTITY: **11905** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/08/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUIDLING ID: **1490**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**
SCHOOL NAME: **Morgan Park High School** INSPECTION DATE: **4/20/2016**
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-19039**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17C**
MATERIAL DESCRIPTION: **12"x12" Gray w/Specks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Room 312 (1925)**
MATERIAL QUANTITY: **410** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/20/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUIDLING ID: **1490**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Morgan Park High School** REVIEW DATE: **6/8/2016**
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-19039**

HOMOGENEOUS AREA: **17C**
MATERIAL DESCRIPTION: **12"x12" Gray w/Specks Floor Tile**
MATERIAL LOCATION: **Room 312 (1925)**
MATERIAL QUANTITY: **410** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/08/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUIDLING ID: **1490**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**
SCHOOL NAME: **Morgan Park High School** INSPECTION DATE: **4/20/2016**
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-19039**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18**
MATERIAL DESCRIPTION: **12"x12" Tan w/ Beige Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Room 298, 398**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/20/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUIDLING ID: **1490**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Morgan Park High School** REVIEW DATE: **6/8/2016**
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-19039**

HOMOGENEOUS AREA: **18**
MATERIAL DESCRIPTION: **12"x12" Tan w/ Beige Floor Tile**
MATERIAL LOCATION: **Room 298, 398**
MATERIAL QUANTITY: MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/08/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUIDLING ID: **1490**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**
SCHOOL NAME: **Morgan Park High School** INSPECTION DATE: **4/20/2016**
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-19039**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19**
MATERIAL DESCRIPTION: **12"x12" Tan w/ Beige Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 298 & 398**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 04/20/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUIDLING ID: **1490**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Morgan Park High School** REVIEW DATE: **6/8/2016**
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-19039**

HOMOGENEOUS AREA: **19**
MATERIAL DESCRIPTION: **12"x12" Tan w/ Beige Floor Tile Mastic**
MATERIAL LOCATION: **Rooms 298 & 398**
MATERIAL QUANTITY: MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/08/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUIDLING ID: **1490**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**
SCHOOL NAME: **Morgan Park High School** INSPECTION DATE: **4/20/2016**
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-19039**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**
MATERIAL DESCRIPTION: **2'x4' Lay In Ceiling Tile (No ACBM, Per 2015-46251-ICR Samples from 1st,2nd,3rd FI Corrid)**
HISTORICAL AHERA DAMAGE CATEGORY **Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout 1925 bldg.**

MATERIAL QUANTITY: **10000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **No ACBM, Per 2015-46251-ICR Samples from 1st,2nd,3rd FI Corrid**

Inspector's Signature:



Date: **04/20/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUIDLING ID: **1490**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Morgan Park High School** REVIEW DATE: **6/8/2016**
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-19039**

HOMOGENEOUS AREA: **20**
MATERIAL DESCRIPTION: **2'x4' Lay In Ceiling Tile (No ACM, Per 2015-46251-ICR Samples from 1st,2nd,3rd FI Corrid)**
MATERIAL LOCATION: **Throughout 1925 bldg.**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/08/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUIDLING ID: **1490**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**
SCHOOL NAME: **Morgan Park High School** INSPECTION DATE: **4/20/2016**
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-19039**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21**
MATERIAL DESCRIPTION: **1' x 1' Ceiling Tile (No ACBM, Per 2015-46251-ICR Stairwell Samples)**
HISTORICAL AHERA DAMAGE CATEGORY: **Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1ST & 2ND FLR HALL BETWEEN OLD AND NEW BLDG**

MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **No ACBM, Per 2015-46251-ICR Stairwell Samples**

Inspector's Signature:



Date: **04/20/2016**

Chicago Public Schools

GSG Consultants, Inc.

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUIDLING ID: **1490**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Morgan Park High School** REVIEW DATE: **6/8/2016**
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-19039**

HOMOGENEOUS AREA: **21**
MATERIAL DESCRIPTION: **1' x 1' Ceiling Tile (No ACM, Per 2015-46251-ICR Stairwell Samples)**
MATERIAL LOCATION: **1ST & 2ND FLR HALL BETWEEN OLD AND NEW BLDG**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/08/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUIDLING ID: **1490**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**
SCHOOL NAME: **Morgan Park High School** INSPECTION DATE: **4/20/2016**
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-19039**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22**
MATERIAL DESCRIPTION: **Spray-on Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout 1964 Bldg.**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 04/20/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUIDLING ID: **1490**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Morgan Park High School** REVIEW DATE: **6/8/2016**
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-19039**

HOMOGENEOUS AREA: **22**
MATERIAL DESCRIPTION: **Spray-on Insulation**
MATERIAL LOCATION: **Throughout 1964 Bldg.**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/08/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUIDLING ID: **1490**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**
SCHOOL NAME: **Morgan Park High School** INSPECTION DATE: **4/20/2016**
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-19039**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23**
MATERIAL DESCRIPTION: **Terrazzo**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1925 Building Hallway - 1st, 2nd and 3rd Floor Corridors**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/20/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUILDING ID: **1490**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Morgan Park High School** REVIEW DATE: **6/8/2016**
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-19039**

HOMOGENEOUS AREA: **23**
MATERIAL DESCRIPTION: **Terrazzo**
MATERIAL LOCATION: **1925 Building Hallway - 1st, 2nd and 3rd Floor Corridors**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/08/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUILDING ID: **1490**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**
SCHOOL NAME: **Morgan Park High School** INSPECTION DATE: **4/20/2016**
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-19039**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **24**
MATERIAL DESCRIPTION: **Plaster - Walls & Ceilings (No ACBM, Per 2015-46251-ICR 1st 2nd 3rd FI Corrid, Rm357, JaniClset Samples)**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with potential for significant damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout 1925 Building**

MATERIAL QUANTITY: **100000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **No ACBM, Per 2015-46251-ICR 1st 2nd 3rd FI Corrid, Rm357, JaniClset Samples**

Inspector's Signature:



Date: **04/20/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUILDING ID: **1490**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Morgan Park High School** REVIEW DATE: **6/8/2016**
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-19039**

HOMOGENEOUS AREA: **24**
MATERIAL DESCRIPTION: **Plaster - Walls & Ceilings (No ACBM, Per 2015-46251-ICR 1st 2nd 3rd Fl Corrid, Rm357, JaniClset Samples)**
MATERIAL LOCATION: **Throughout 1925 Building**
MATERIAL QUANTITY: **100000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **06/08/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUIDLING ID: **1490**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**
SCHOOL NAME: **Morgan Park High School** INSPECTION DATE: **4/20/2016**
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-19039**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25**
MATERIAL DESCRIPTION: **Plaster - Walls**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with potential for significant damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **HIGH**
MATERIAL LOCATION: **Throughout 1964 Building**
MATERIAL QUANTITY: **100000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 04/20/2016

Chicago Public Schools

GSG Consultants, Inc.

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUILDING ID: **1490**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Morgan Park High School** REVIEW DATE: **6/8/2016**
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-19039**

HOMOGENEOUS AREA: **25**
MATERIAL DESCRIPTION: **Plaster - Walls**
MATERIAL LOCATION: **Throughout 1964 Building**
MATERIAL QUANTITY: **100000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/08/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUIDLING ID: **1490**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**
SCHOOL NAME: **Morgan Park High School** INSPECTION DATE: **4/20/2016**
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-19039**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **A**
MATERIAL DESCRIPTION: **2' x 2' Lay In Ceiling Panels**
HISTORICAL AHERA DAMAGE CATEGORY **6 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **2ND & 3RD FLR HALLWAYS OF 1964 BLDG**
MATERIAL QUANTITY: **3480** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:



Date: **04/20/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUIDLING ID: **1490**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Morgan Park High School** REVIEW DATE: **6/8/2016**
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-19039**

HOMOGENEOUS AREA: **A**
MATERIAL DESCRIPTION: **2' x 2' Lay In Ceiling Panels**
MATERIAL LOCATION: **2ND & 3RD FLR HALLWAYS OF 1964 BLDG**
MATERIAL QUANTITY: **3480** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/08/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUIDLING ID: **1490**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**
SCHOOL NAME: **Morgan Park High School** INSPECTION DATE: **4/20/2016**
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-19039**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **B**
MATERIAL DESCRIPTION: **12"x12" Greenish Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **HALLWAY NEAR NEW ELEVATOR WING**
MATERIAL QUANTITY: **535** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 04/20/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUIDLING ID: **1490**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Morgan Park High School** REVIEW DATE: **6/8/2016**
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-19039**

HOMOGENEOUS AREA: **B**
MATERIAL DESCRIPTION: **12"x12" Greenish Floor Tile**
MATERIAL LOCATION: **HALLWAY NEAR NEW ELEVATOR WING**
MATERIAL QUANTITY: **535** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/08/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUIDLING ID: **1490**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**
SCHOOL NAME: **Morgan Park High School** INSPECTION DATE: **4/20/2016**
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-19039**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **C**
MATERIAL DESCRIPTION: **AIRCELL PIPE INSULATION**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **SOUTH TUNNEL**
MATERIAL QUANTITY: **205** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **04/20/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUIDLING ID: **1490**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Morgan Park High School** REVIEW DATE: **6/8/2016**
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-19039**

HOMOGENEOUS AREA: **C**
MATERIAL DESCRIPTION: **AIRCELL PIPE INSULATION**
MATERIAL LOCATION: **SOUTH TUNNEL**
MATERIAL QUANTITY: **205** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/08/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUIDLING ID: **1490**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**
SCHOOL NAME: **Morgan Park High School** INSPECTION DATE: **4/20/2016**
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-19039**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **CM-1**
MATERIAL DESCRIPTION: **Rust Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Attendance Office, Assistance Principal's Office (1925)**
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 04/20/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUILDING ID: **1490**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Morgan Park High School** REVIEW DATE: **6/8/2016**
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-19039**

HOMOGENEOUS AREA: **CM-1**
MATERIAL DESCRIPTION: **Rust Carpet Mastic**
MATERIAL LOCATION: **Attendance Office, Assistance Principal's Office (1925)**
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/08/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUIDLING ID: **1490**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**
SCHOOL NAME: **Morgan Park High School** INSPECTION DATE: **4/20/2016**
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-19039**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **CM-2**
MATERIAL DESCRIPTION: **Green Carpet Masitc**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Bandroom (1925)**
MATERIAL QUANTITY: **515** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/20/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUIDLING ID: **1490**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Morgan Park High School** REVIEW DATE: **6/8/2016**
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-19039**

HOMOGENEOUS AREA: **CM-2**
MATERIAL DESCRIPTION: **Green Carpet Masitc**
MATERIAL LOCATION: **Bandroom (1925)**
MATERIAL QUANTITY: **515** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/08/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUIDLING ID: **1490**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**
SCHOOL NAME: **Morgan Park High School** INSPECTION DATE: **4/20/2016**
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-19039**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **CM-3**
MATERIAL DESCRIPTION: **Multicolor Carpet No Mastic, Carpet Nailed Down**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Room 151 (1925)**
MATERIAL QUANTITY: **1260** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/20/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUIDLING ID: **1490**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Morgan Park High School** REVIEW DATE: **6/8/2016**
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-19039**

HOMOGENEOUS AREA: **CM-3**
MATERIAL DESCRIPTION: **Multicolor Carpet No Mastic, Carpet Nailed Down**
MATERIAL LOCATION: **Room 151 (1925)**
MATERIAL QUANTITY: **1260** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/08/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUIDLING ID: **1490**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**
SCHOOL NAME: **Morgan Park High School** INSPECTION DATE: **4/20/2016**
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-19039**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **CM-5**
MATERIAL DESCRIPTION: **Rust Colored Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Main Office (1964)**
MATERIAL QUANTITY: **1020** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:



Date: **04/20/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUIDLING ID: **1490**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Morgan Park High School** REVIEW DATE: **6/8/2016**
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-19039**

HOMOGENEOUS AREA: **CM-5**
MATERIAL DESCRIPTION: **Rust Colored Carpet Mastic**
MATERIAL LOCATION: **Main Office (1964)**
MATERIAL QUANTITY: **1020** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/08/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUIDLING ID: **1490**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**
SCHOOL NAME: **Morgan Park High School** INSPECTION DATE: **4/20/2016**
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-19039**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **D**
MATERIAL DESCRIPTION: **LAB TABLE TOPS**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **SCIENCE CLASSROOMS**
MATERIAL QUANTITY: **240** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/20/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUIDLING ID: **1490**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Morgan Park High School** REVIEW DATE: **6/8/2016**
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-19039**

HOMOGENEOUS AREA: **D**
MATERIAL DESCRIPTION: **LAB TABLE TOPS**
MATERIAL LOCATION: **SCIENCE CLASSROOMS**
MATERIAL QUANTITY: **240** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/08/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUIDLING ID: **1490**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**
SCHOOL NAME: **Morgan Park High School** INSPECTION DATE: **4/20/2016**
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-19039**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **E**
MATERIAL DESCRIPTION: **Fitting Insulation on Fiberglass Insulated Piping**
HISTORICAL AHERA DAMAGE CATEGORY **6 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Bldg 1964 - Throughout School**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **04/20/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUILDING ID: **1490**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Morgan Park High School** REVIEW DATE: **6/8/2016**
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-19039**

HOMOGENEOUS AREA: **E**
MATERIAL DESCRIPTION: **Fitting Insulation on Fiberglass Insulated Piping**
MATERIAL LOCATION: **Bldg 1964 - Throughout School**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/08/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUIDLING ID: **1490**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**
SCHOOL NAME: **Morgan Park High School** INSPECTION DATE: **4/20/2016**
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-19039**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **F**
MATERIAL DESCRIPTION: **Fitting Insulation on Fiberglass Insulated Piping**
HISTORICAL AHERA DAMAGE CATEGORY **6 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Bldg 1925 - Throughout School**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/20/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUILDING ID: **1490**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Morgan Park High School** REVIEW DATE: **6/8/2016**
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-19039**

HOMOGENEOUS AREA: **F**
MATERIAL DESCRIPTION: **Fitting Insulation on Fiberglass Insulated Piping**
MATERIAL LOCATION: **Bldg 1925 - Throughout School**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/08/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUIDLING ID: **1490**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**
SCHOOL NAME: **Morgan Park High School** INSPECTION DATE: **4/20/2016**
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-19039**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **G**
MATERIAL DESCRIPTION: **Vibration Damper**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Bldg 1964 - Mechanical Room**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 04/20/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUIDLING ID: **1490**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Morgan Park High School** REVIEW DATE: **6/8/2016**
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-19039**

HOMOGENEOUS AREA: **G**
MATERIAL DESCRIPTION: **Vibration Damper**
MATERIAL LOCATION: **Bldg 1964 - Mechanical Room**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/08/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUIDLING ID: **1490**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**
SCHOOL NAME: **Morgan Park High School** INSPECTION DATE: **4/20/2016**
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-19039**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **HA-100**
MATERIAL DESCRIPTION: **Lining for Room Heating Units**
HISTORICAL AHERA DAMAGE CATEGORY **6 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room Heating Units**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/20/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUIDLING ID: **1490**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Morgan Park High School** REVIEW DATE: **6/8/2016**
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-19039**

HOMOGENEOUS AREA: **HA-100**
MATERIAL DESCRIPTION: **Lining for Room Heating Units**
MATERIAL LOCATION: **Room Heating Units**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/08/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUILDING ID: **1490**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**
SCHOOL NAME: **Morgan Park High School** INSPECTION DATE: **4/20/2016**
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-19039**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **HA-101**
MATERIAL DESCRIPTION: **Interior Window Caulk**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Windows Throughout Building**

MATERIAL QUANTITY: **5000**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **04/20/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUILDING ID: **1490**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Morgan Park High School** REVIEW DATE: **6/8/2016**
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-19039**

HOMOGENEOUS AREA: **HA-101**
MATERIAL DESCRIPTION: **Interior Window Caulk**
MATERIAL LOCATION: **Windows Throughout Building**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/08/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUILDING ID: **1490**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**
SCHOOL NAME: **Morgan Park High School** INSPECTION DATE: **4/20/2016**
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-19039**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **HA-102**
MATERIAL DESCRIPTION: **Interior Window Glaze**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Windows Throughout Building**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **04/20/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUIDLING ID: **1490**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Morgan Park High School** REVIEW DATE: **6/8/2016**
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-19039**

HOMOGENEOUS AREA: **HA-102**
MATERIAL DESCRIPTION: **Interior Window Glaze**
MATERIAL LOCATION: **Windows Throughout Building**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/08/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUIDLING ID: **1490**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**
SCHOOL NAME: **Morgan Park High School** INSPECTION DATE: **4/20/2016**
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-19039**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **HA-103**
MATERIAL DESCRIPTION: **1'x1' Grooved Ceiling Tile Glue**
HISTORICAL AHERA DAMAGE CATEGORY **6 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **1964 Bldg**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/20/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUILDING ID: **1490**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Morgan Park High School** REVIEW DATE: **6/8/2016**
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-19039**

HOMOGENEOUS AREA: **HA-103**
MATERIAL DESCRIPTION: **1'x1' Grooved Ceiling Tile Glue**
MATERIAL LOCATION: **1964 Bldg**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/08/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUIDLING ID: **1490**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**
SCHOOL NAME: **Morgan Park High School** INSPECTION DATE: **4/20/2016**
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-19039**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **HA-104**
MATERIAL DESCRIPTION: **Black Sink Undercoating**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 242**
MATERIAL QUANTITY: **5** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/20/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46251** BUIDLING ID: **1490**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Morgan Park High School** REVIEW DATE: **6/8/2016**
ADDRESS: **1744 W. Pryor Ave.** IDPH LICENSE NO: **100-19039**

HOMOGENEOUS AREA: **HA-104**
MATERIAL DESCRIPTION: **Black Sink Undercoating**
MATERIAL LOCATION: **Room 242**
MATERIAL QUANTITY: **5** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/08/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

APPENDIX B

Inspector and Management Planner Licenses



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • www.dph.illinois.gov

4/20/2016

DELORES FITZPATRICK
855 WEST ADAMS, SUITE 200
CHICAGO, IL 60607

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 05183

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

		ASBESTOS PROFESSIONAL LICENSE		ENDORSEMENTS	TC EXPIRES
ID NUMBER 00 - 05183	ISSUED 4/20/2016	EXPIRES 05/15/2017		INSPECTOR	2/13/2017
DELORES FITZPATRICK 855 WEST ADAMS, SUITE 200 CHICAGO, IL 60607 Environmental Health				PROJECT MANAGER AIR SAMPLING PROFESSIONAL	2/6/2017
				Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH, IMPROVING LIVES
Nationally Accredited by PHA/E

CERTIFICATE OF ACHIEVEMENT ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that WAYNE GARDNER
has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the
examination on 02/13/2016 with a minimum score of 70% or better. Training was in accordance
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:
Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.

02/13/2016

Course Dates:

02/13/2017

Expires:

1602BIR14

Certificate Number:




A handwritten signature in black ink, appearing to read "N. Peneff".

Director of Training
Nicholas J. Peneff
Doctor of Public Health

Phone: 312-491-0081

FORM # A-010B

2016



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Jigar Shah

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 1/27/2016

Exam Date: 1/27/2016

Expiration Date: 1/27/2017

Certificate Number: MPR1601270320


Kathy DeSalvo, Director



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • www.dph.illinois.gov

4/20/2016

JIGAR M SHAH
855 W ADAMS ST, SUITE 200
CHICAGO, IL 60607

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 07342

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

		ASBESTOS PROFESSIONAL LICENSE		ENDORSEMENTS	TC EXPIRES
ID NUMBER 109 - 07342	ISSUED 4/20/2016	EXPIRES 05/15/2017		INSPECTOR PROJECT DESIGNER MANAGEMENT PLANNER PROJECT MANAGER AIR SAMPLING PROFESSIONAL	1/19/2017 2/2/2017 1/27/2017 2/26/2017
JIGAR M SHAH 855 W ADAMS ST, SUITE 200 CHICAGO, IL 60607 Environmental Health				Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH, IMPROVING LIVES
Nationally Accredited by PHAB

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL		
	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE		
	Loc	Localized
	Dist	Distributed