

ILLINOIS DEPARTMENT OF PUBLIC HEALTH  
AHERA THREE YEAR REINSPECTION  
ASBESTOS ABATEMENT PROGRAM  
SCHOOL INFORMATION FORM

**SECTION I**

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299  
SCHOOL ID NUMBER: 14-016-2990-0036  
SCHOOL NAME: Schurz High School  
ADDRESS OF SCHOOL: 3601 N. Milwaukee Ave.  
CITY: Chicago, IL, 60641

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **4/16/2013**

**If the address on this form is different than the address of the building, submit a written explanation.**

**SECTION II** (Please type or print)

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 5/23/2016 ENROLLMENT 1737  
IDPH INSPECTOR LICENSE NUMBER: 100-11093  
IDPH LICENSED INSPECTOR NAME (Please Print): David Avila  
IDPH MP LICENSE NUMBER: 100-01786  
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Guillermo Garcia

DESIGNATED PERSON (Please Print): Robert Christlieb PHONE: (773) 553-3197



5/23/2016

Signature of Designated Person

Date

**SECTION III**

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: \_\_\_\_\_

School has been closed. Date closed: \_\_\_\_\_

School building has been demolished. Date: \_\_\_\_\_

School building is asbestos free since last reinspection: \_\_\_\_\_

**Please explain in writing why the school building is now asbestos free and include the supporting documentation.**

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

**Explain in writing if the address of the building is different than the address on this form:**

**THREE-YEAR REINSPECTION**

**CHICAGO SCHOOL DIST 299**

**Schurz High School**

3601 N. Milwaukee Ave.  
Chicago, IL, 60641

Unit: 46281  
Building ID: 1530

IDPH ID Number: 14-016-2990-0036

**REPORT DATE:**

Monday, May 23, 2016

**Prepared for:**

**Chicago Public Schools**  
**125 S. Clark Street**  
**Chicago, IL 60603**

**Prepared by:**

**GSG Consultants, Inc.**

855 W. Adams St., Ste. 200

Phone (312) 733-6262

Fax (312) 733-5612

**DO NOT REMOVE FROM SCHOOL  
REQUIRED BY FEDERAL LAW**

April 19, 2016

Mr. R. Kent Cook  
Asbestos Program  
Illinois Department of Public Health  
525 West Jefferson Street  
Springfield, Illinois 62761

Re: Chicago Public Schools - 2016 Three-Year Reinspections

Dear Mr. Cook:

GSG Consultants, Inc., Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 1,2,6 Elementary Schools. Please update your records with the following information.

School District: 299                      Unit: 46281                      Region: 01                      IDPH ID: 14-016-2990-0036

School: Schurz High School                      Building ID: 1530

Address: 3601 N. Milwaukee Ave.

Chicago, IL, 60641

Building Contact: Gonzalez, Ernesto

Contact Phone:

Current Building Owners: Chicago Public Schools

Review Date: 05/17/2016

Inspector: David Avila

Inspector IDPH License: 100-11093

Management Planner: Guillermo Garcia

Management Planner IDPH License: 100-01786

If you have any questions or comments, please contact us at (312) 733-6262

Sincerely,  
GSG Consultants, Inc.



Guillermo Garcia  
100-01786

## **Environmental Notification to Occupants**

To: Faculty, Staff and Parents  
From: Chicago Public Schools  
Date: April 19, 2016

RE: Schurz High School, Unit 46281  
3601 N. Milwaukee Ave.  
Chicago, IL, 60641

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2016 asbestos three year re-inspection has been completed at Schurz High School , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at Schurz High School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Robert Christlieb, the designated Local Education Authority's Designated Person at (773) 553-3197 .

## **Table of Contents**

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

### **APPENDICES:**

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

## SCHOOL AND INSPECTION INFORMATION

### 1. School Information

School: Schurz High School Unit: 46281 Region: 01  
Address: 3601 N. Milwaukee Ave. Chicago, IL, 60641  
IDPH ID: 14-016-2990-0036 Building ID: 1530  
Contact: Gonzalez, Ernesto Phone:

### 2. Description of Facility

Original Construction: 1910 Additional Construction:  
Total Square Footage: 455800 No of Floors: 5  
Current Occupancy: 1737

### 3. LEA Designated Person

Contact: Robert Christlieb Phone: (773) 553-3197  
Address: 125 South Clark Street, 17th Floor  
Chicago, IL 60603


### 4. Managing Environmental Consultant

MEC: GSG Consultants, Inc.  
Contact: Arturo Saenz  
Address 855 W. Adams St., Ste. 200  
Phone: (312) 733-6262 Fax: (312) 733-5612

### 5. Inspector

Inspector Name: David Avila


Inspector IDPH license # 100-11093

Signature:   
Date: 4/19/2016

### 6. Management Planner

Management Planner Name: Guillermo Garcia


Management Planner IDPH license # 100-01786

Signature:   
Date: 05/17/2016

### 7. Review Date: 05/17/2016

### 8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature: 

Date: 5/23/2016

Name: Robert Christlieb

## II. EXECUTIVE SUMMARY

GSG Consultants, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Schurz High School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 1530:

|     |  |
|-----|--|
| 104 | Green Linoleum                                     |
| 105 | Green Linoleum Mastic                              |
| 107 | 12" x 12" Gray w/ White Speck VFT                  |
| 108 | 12" x 12" Gray w/ White Speck VFT Mastic           |
| 109 | 12" x 12" Orange Cork VFT                          |
| 110 | 12" x 12" Orange Cork VFT Mastic                   |
| 111 | Carpet Mastic                                      |
| 25  | 12"x12" Beige w/ Brown & White Streaks VFT         |
| 26  | 12"x 12" Beige w/ Brown & White Streaks VFT Mastic |

|    |   |
|----|---|
| 69 | 9"x9" Green w/ White Streaks VFT        |
| 70 | 9"x9" Green w/ White Streaks VFT Mastic |
| 97 | Tan Spotted Linoleum                    |
| 98 | Tan Spotted Linoleum Mastic             |



B. The following new homogenous areas have been identified for Building 1530:

|     |  |
|-----|--|
| 124 | 12 x 12 Tan with Specks Floor Tile           |
| 125 | 12 x 12 Tan with Specks Floor Tile Mastic    |
| 126 | 12"x12" Brown w/ Specks VFT                  |
| 127 | 12"x12" Brown w/ Specks VFT Mastic           |
| 128 | 12"x12" Light Brown w Gray specks VFT        |
| 129 | 12"x12" Light Brown w Gray specks VFT Mastic |

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

|       |   |
|-------|---|
| 03    | Tan w/ Brown Swirls Linoleum                            |
| 06    | Tan w/ Brown Swirls Linoleum Mastic                     |
| 1009  | Boiler #1 (small)                                       |
| 104   | Green Linoleum  |
| 105   | Green Linoleum Mastic                                   |
| 107   | 12" x 12" Gray w/ White Speck VFT                       |
| 108   | 12" x 12" Gray w/ White Speck VFT Mastic                |
| 109   | 12" x 12" Orange Cork VFT                               |
| 110   | 12" x 12" Orange Cork VFT Mastic                        |
| 111   | Carpet Mastic   |
| 112   | Carpet Adhesive   |
| 113   | 12"X12" Powder-Blue w/White and Blue Streaks VFT        |
| 113M  | 12"X12" Powder-Blue w/White and Blue Streaks VFT Mastic |
| 114   | VFT 12 X 12 Tan w/ white specs w/ Mastic                |
| 115   | Carpet Mastic   |
| 116   | Lab Black Counter Tops                                  |
| 117   | Lab Black Table Tops                                    |
| 118   | VFT 12 X 12 Tan w/ Large White Striations               |
| 118A  | 12 X 12 Tan w/ Large White Striations w/ Mastic         |
| 119   | VFT 12 X 12 Light blue w/ gray & white specs            |
| 119A  | 12 x 12 Light Blue w/ gray & white specs w/ Mastic      |
| 120   | VFT 12 X 12 White w/ Tan Streaks                        |
| 120A  | 12 x 12 white w/ Tan Streaks w/ Mastic                  |
| 121   | VFT 12 x 12 White w/ greens & gray streaks              |
| 121 A | 12 x 12 White w/ Green & Gray Streaks w/ Mastic         |
| 122   | VFT 12 X 12 Tan w/ white Streaks                        |
| 122A  | 12 X 12 Tan w/ White Streaks Mastic                     |
| 123   | Tan Linoleum w/ white & black streaks                   |
| 123A  | Tan Linoleum w/ white & black streaks w/ Mastic         |
| 124   | 12 x 12 Tan with Specks Floor Tile                      |
| 125   | 12 x 12 Tan with Specks Floor Tile Mastic               |
| 126   | 12"x12" Brown w/ Specks VFT                             |
| 127   | 12"x12" Brown w/ Specks VFT Mastic                      |
| 128   | 12"x12" Light Brown w Gray specks VFT                   |
| 129   | 12"x12" Light Brown w Gray specks VFT Mastic            |
| 25    | 12"x12" Beige w/ Brown & White Streaks VFT              |
| 26    | 12"x 12" Beige w/ Brown & White Streaks VFT Mastic      |
| 29    | 12"x12" Gray w/ White Streaks VFT                       |
| 30    | 12"x12" Gray w/ White Streaks VFT Mastic                |

|         |   |
|---------|---|
| 48      | Brown Linoleum Mastic                             |
| 49      | 12"x12" White w/ Blue Speckles VFT                |
| 50      | 12"x12" White w/ Blue Speckles VFT Mastic         |
| 51      | 12"x12" Beige w/ Dark Brown Speckles VFT          |
| 52      | 12"x12" Beige w/ Dark Brown Speckles VFT Mastic   |
| 53      | 12"x12" White w/ Tan Spots VFT                    |
| 54      | 12"x12" White w/ Tan Spots VFT Mastic             |
| 64      | 9'x9" Beige w/ Brown & White Streaks VFT Mastic   |
| 67      | 12"x12" Tan w/ Tan Specks VFT                     |
| 68      | 12"x12" Tan w/ Tan Specks VFT Mastic              |
| 73      | 12"x12" Gray w/ Gray & Black Specks VFT           |
| 74      | 12"x12" Gray w/ Gray & Black Specks VFT Mastic    |
| 75      | 12"x12" Blue w/ White Streaks VFT                 |
| 76      | 12"x12" Blue w/ White Streaks VFT Mastic          |
| 99      | Lab Counter Top                                   |
| FF      | Aircell Pipe Insulation                           |
| GG      | MJP E/F/V on Aircell Pipe Insulation              |
| HA-1000 | 2'x4' white ceiling tiles with random fis & holes |
| HA-1001 | 2"X4" white plain ceiling tile                    |
| HA-1002 | 1'x1' white ceiling tile rand holes               |
| HA-1003 | Glue for 1'x1' white ceilingtile with holes       |
| HA-1004 | 2'x2' white plain ceiling tile                    |
| HA-1005 | 1'x1' white CT with large holes                   |
| HA-1006 | Glue for 1'x1' wh CT with large holes             |
| HA-1007 | 1'x1' wh CT with random fissures                  |
| HA-1008 | Glue for 1'x1' white CT with rand fiss            |
| II      | Cardboard Pipe Insulation (Paper-Wrap Pipe Ins)   |

The following areas were deemed to be inaccessible:

|         |   |
|---------|---|
| CC      | MJP E/F/V on Fiberglass Pipe Insulation     |
| HA-1003 | Glue for 1'x1' white ceilingtile with holes |
| HA-1006 | Glue for 1'x1' wh CT with large holes       |
| HA-1008 | Glue for 1'x1' white CT with rand fiss      |

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by David Avila, IDPH License # 100-11093. The Management Plan was updated by Guillermo Garcia, IDPH License # 100-01786. Inspector and Management Planner Licenses are included in Appendix B.

### **III. METHODOLOGY**

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

### **IV. ABATEMENT HISTORY**

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

### **V. REASSESSMENTS AND RECOMMENDATIONS**

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

### **VI. CONCLUSIONS**

The Schurz High School Building 1530 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

**Table I**  
**Inspector's Reinspection Findings**

---



# Chicago Public Schools

School Schurz High School Unit 46281 Building ID 1530

Address 3601 N. Milwaukee Ave. Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

*Inspector's Comments are Summarized at the End of the Report*

| HA No | Material Description                                    | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category | Damage Category                    | Damage Reason | Disturbance Potential |
|-------|---|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|------------------------------------|---------------|-----------------------|
|       |   |                   |                | 1908  |               |                   |         |             |                 |              |                               |                                    |               |                       |
| 104   | Green Linoleum  | 1,600             | SF             | Room 320, 369, Prep Room, Storage Room - 1923                               | ASSUMED       | MISC              | N       | NONE        | 0               |              | Yes                           | ACBM with the potential for damage |               | MODERATE              |
| 105   | Green Linoleum Mastic                                   | 400               | SF             | Room 320, 369, Prep Room, Storage Room - 1923                               | ASSUMED       | MISC              | N       | NONE        | 0               |              | Yes                           | ACBM with the potential for damage |               | LOW                   |
| 106   | 2" x 2" Ceiling Tile                                    |                   |                | Room 320, 369, Prep Room, Storage Room - 1923                               | NO_ACBM       |                   |         |             |                 |              |                               |                                    |               |                       |
| 107   | 12" x 12" Gray w/ White Speck VFT                       | 1,400             | SF             | Room 216 - 1908   | ASSUMED       | MISC              | N       | NONE        | 0               |              | Yes                           | ACBM with the potential for damage |               | MODERATE              |
| 108   | 12" x 12" Gray w/ White Speck VFT Mastic                | 1,400             | SF             | Room 216 - 1908   | ASSUMED       | MISC              | N       | NONE        | 0               |              | Yes                           | ACBM with the potential for damage |               | LOW                   |
| 109   | 12" x 12" Orange Cork VFT                               | 4,500             | SF             | Library - 1908  | ASSUMED       | MISC              | N       | NONE        | 0               |              | Yes                           | ACBM with the potential for damage |               | MODERATE              |
| 11    | 12"x12" Tan w/ White Streaks VFT                        | 18,061            | SF             | Throughout - 1923 (See Hatching Maps)                                       | CHR           | MISC              | N       | DIST        | 35              |              | No                            | ACBM with the potential for damage | 3             | MODERATE              |
| 110   | 12" x 12" Orange Cork VFT Mastic                        | 4,500             | SF             | Library - 1908  | ASSUMED       | MISC              | N       | NONE        | 0               |              | Yes                           | ACBM with the potential for damage |               | LOW                   |
| 111   | Carpet Mastic   | 4,500             | SF             | Library - 1908  | ASSUMED       | MISC              | N       | NONE        | 0               |              | Yes                           | ACBM with the potential for damage |               | MODERATE              |
| 112   | Carpet Adhesive   | 4,934             | SF             | Main Office, Nurse Office 128, 125A, 114, 110, 115, Teacher/Staff Room, 376 | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 113   | 12"X12" Powder-Blue w/White and Blue Streaks VFT        | 2,000             | SF             | Rm 309 -1915 Addition   | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | MODERATE              |
| 113M  | 12"X12" Powder-Blue w/White and Blue Streaks VFT Mastic | 2,000             | SF             | Rm 309 -1915 Addition   | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 114   | VFT 12 X 12 Tan w/ white specs w/ Mastic                | 700               | SF             | Room 205  | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 115   | Carpet Mastic   | 2,600             | SF             | Room 110, 128, 111, 119, 300  | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 116   | Lab Black Counter Tops                                  | 2,000             | SF             | Rooms 315, 313, 219, 215, 213, 223, 225, 229                                | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 117   | Lab Black Table Tops                                    | 2,000             | SF             | Rooms 315, 313, 219, 215, 213, 223, 225, 229                                | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 118   | VFT 12 X 12 Tan w/ Large White Striations               | 21,000            | SF             | Rooms 220, 305, 308, 310, 320, 321,   | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | MODERATE              |

# Chicago Public Schools

School Schurz High School Unit 46281 Building ID 1530

Address 3601 N. Milwaukee Ave. Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

*Inspector's Comments are Summarized at the End of the Report*

| HA No | Material Description                               | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category | Damage Category                    | Damage Reason | Disturbance Potential |
|-------|--|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|------------------------------------|---------------|-----------------------|
|       |  |                   |                | 322, 332, 353, 355, 361, 358, 364, 368, 377, 379,381, 324, 351, 363, 372, 374, 376, 327, 221, 125, 105 & 108                                     |               |                   |         |             |                 |              |                               |                                    |               |                       |
| 118A  | 12 X 12 Tan w/ Large White Striations w/ Mastic    | 21,000            | SF             | Rooms 220, 305, 308, 310, 320, 321, 322, 332, 353, 355, 361, 358, 364, 368, 377, 379,381, 324, 351, 363, 372, 374, 376, 327, 221, 125, 105 & 108 | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 119   | VFT 12 X 12 Light blue w/ gray & white specs       | 4,000             | SF             | Rooms 219, 217, 213, 123, 122, 323, 229, 227, 223, 225, 309 & 371  | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | MODERATE              |
| 119A  | 12 x 12 Light Blue w/ gray & white specs w/ Mastic | 4,000             | SF             | Rooms 219, 217, 213, 123, 122, 323, 229, 227, 223, 225, 309 & 371  | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 12    | 12"x12" Tan w/ White Streaks VFT Mastic            | 18,061            | SF             | Throughout - 1923 (See Hatching Maps)  | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 120   | VFT 12 X 12 White w/ Tan Streaks                   | 4,000             | SF             | Rooms 311, 336, 338, 334, 129, 131   | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | MODERATE              |
| 120A  | 12 x 12 white w/ Tan Streaks w/ Mastic             | 4,000             | SF             | Rooms 311, 336, 338, 334, 129, 131   | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 121   | VFT 12 x 12 White w/ greens & gray streaks         | 2,200             | SF             | Rooms 312, 314   | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | MODERATE              |
| 121 A | 12 x 12 White w/ Green & Gray Streaks w/ Mastic    | 2,200             | SF             | Rooms 312, 314   | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 122   | VFT 12 X 12 Tan w/ white Streaks                   | 700               | SF             | Room 116   | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | MODERATE              |
| 122A  | 12 X 12 Tan w/ White Streaks Mastic                | 700               | SF             | Room 116   | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 123   | Tan Linoleum w/ white & black streaks              | 700               | SF             | Room 315   | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | MODERATE              |
| 123A  | Tan Linoleum w/ white & black streaks w/ Mastic    | 700               | SF             | Room 315   | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 124   | 12 x 12 Tan with Specks Floor Tile                 | 4,600             | SF             | Cafeteria, Serving Area, Teachers' Lounge  | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | MODERATE              |



# Chicago Public Schools

School Schurz High School Unit 46281 Building ID 1530

Address 3601 N. Milwaukee Ave. Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

*Inspector's Comments are Summarized at the End of the Report*

| HA No | Material Description                            | Material Quantity | Material Units | Material Location                                     | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category | Damage Category                    | Damage Reason | Disturbance Potential |
|-------|---|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|------------------------------------|---------------|-----------------------|
| 125   | 12 x 12 Tan with Specks Floor Tile Mastic       | 4,600             | SF             | Cafeteria, Serving Area, Teachers' Lounge             | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 126   | 12"x12" Brown w/ Specks VFT                     | 300               | SF             | Elevator Lobbies on 1st, 2nd, 3rd, 4th, ad 5th Floors | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | MODERATE              |
| 127   | 12"x12" Brown w/ Specks VFT Mastic              | 300               | SF             | Elevator Lobbies on 1st, 2nd, 3rd, 4th, ad 5th Floors | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 128   | 12"x12" Light Brown w Gray specks VFT           | 600               | SF             | Elevator Lobbies on 1st, 2nd, 3rd, 4th, ad 5th Floors | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | MODERATE              |
| 129   | 12"x12" Light Brown w Gray specks VFT Mastic    | 600               | SF             | Elevator Lobbies on 1st, 2nd, 3rd, 4th, ad 5th Floors | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 13    | 9"x9" Cocoa w/ White & Brown Streaks VFT        | 7,260             | SF             | Rooms 223, 225, 227, 359, 365, 367, 371 - 1923 Bldg   | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | MODERATE              |
| 14    | 9"x9" Cocoa w/ White & Brown Streaks VFT Mastic | 7,260             | SF             | Rooms 223, 225, 227, 359, 365, 367, 371 - 1923 Bldg   | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 15    | Brown Linoleum                                  |                   |                | Gymnasium Office - 1915                               | NO_ACBM       |                   |         |             |                 |              |                               |                                    |               |                       |
| 16    | Brown Linoleum Mastic                           |                   |                | Gymnasium Office - 1915                               | NO_ACBM       |                   |         |             |                 |              |                               |                                    |               |                       |
| 17    | 12"x12" White w/ Light Brown Streaks VFT        | 1,000             | SF             | Room 309 - 1915 Bldg                                  | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | MODERATE              |
| 18    | 12"x12" White w/ Light Brown Streaks VFT Mastic | 1,000             | SF             | Room 309 - 1915 Bldg                                  | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 19    | 9"x9" Red w/ Black & White Specks VFT           | 340               | SF             | Room 301 - 1915 Bldg                                  | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | MODERATE              |
| 20    | 9"x9" Red w/ Black & White Specks VFT Mastic    | 340               | SF             | Room 301 - 1915 Bldg                                  | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 21    | 9"x9" Brown w/ White & Black Streaks VFT        | 20                | SF             | Room 301 - 1915 Bldg                                  | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | MODERATE              |
| 22    | 9"x9" Brown w/ White & Black Streaks VFT Mastic | 20                | SF             | Room 301 - 1915 Bldg                                  | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 23    | 24" X 6" Black VFT                              | 70                | SF             | Room 301 - 1915 Bldg                                  | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | MODERATE              |
| 24    | 24" X 6" Black VFT Mastic                       | 70                | SF             | Room 301 - 1915 Bldg                                  | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 25    | 12"x12" Beige w/ Brown & White Streaks VFT      | 750               | SF             | Room 308 - 1915                                       | ASSUMED       | MISC              | N       | NONE        | 0               |              | Yes                           | ACBM with the potential for damage |               | MODERATE              |
| 26    | 12"x 12" Beige w/ Brown & White Streaks         | 750               | SF             | Room 308 - 1915                                       | ASSUMED       | MISC              | N       | NONE        | 0               |              | Yes                           | ACBM with the                      |               | LOW                   |

# Chicago Public Schools

School Schurz High School Unit 46281 Building ID 1530

Address 3601 N. Milwaukee Ave. Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

*Inspector's Comments are Summarized at the End of the Report*

| HA No | Material Description                                   | Material Quantity | Material Units | Material Location                             | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category | Damage Category                    | Damage Reason | Disturbance Potential |
|-------|--|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|------------------------------------|---------------|-----------------------|
|       | VFT Mastic   |                   |                |   |               |                   |         |             |                 |              |                               | potential for damage               |               |                       |
| 27    | 12"x12" Brown w/ White Specks VFT                      | 1,150             | SF             | 1st, 2nd, & 3rd Floor Corridors - 1915        | CHR           | MISC              | N       | DIST        | 40              |              | No                            | ACBM with the potential for damage | 5             | MODERATE              |
| 28    | 12"x12" Brown w/ White Specks VFT Mastic               | 1,150             | SF             | 1st, 2nd, & 3rd Floor Corridors - 1915        | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 29    | 12"x12" Gray w/ White Streaks VFT                      | 1,600             | SF             | Gymnasium/205 - 1915                          | ASSUMED       | MISC              |         | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | MODERATE              |
| 30    | 12"x12" Gray w/ White Streaks VFT Mastic               | 1,600             | SF             | Gymnasium/205 - 1915                          | ASSUMED       | MISC              |         | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 31    | 12"x12" Beige w/ White & Orange Streaks VFT            | 1,810             | SF             | Room 310 and 341 - 1923                       | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | MODERATE              |
| 32    | 12"x12" Beige w/ White & Orange Streaks VFT Mastic     | 1,810             | SF             | Room 310 and 341 - 1923                       | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 33    | 9"x9" Cocoa w/ White & Brown Short Streaks VFT         | 3,324             | SF             | 3rd Floor Hallway - 1923                      | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | MODERATE              |
| 34    | 9"x9" Cocoa w/ White & Brn Short Strks VFT Mastic      | 3,324             | SF             | 3rd Floor Hallway - 1923                      | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 35    | 12"x 12" Cocoa w/ White & Brown Long Streaks VFT       | 924               | SF             | Room 253 - 1923                               | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 36    | 12"x12" Cocoa w/ Wht. & Brwn. Lng Strks VFT Mastic     | 924               | SF             | Room 253 - 1923                               | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 37    | 12"x12" Gray w/ White & Gray Streaks VFT ABATED        |                   |                | Teachers Room Next to Cafeteria - 1923 ABATED | ABATED        | MISC              |         |             |                 |              |                               |                                    |               |                       |
| 38    | 12"x12" Gray w/ White & Gray Streaks VFT Mastic ABATED |                   |                | Teachers Room Next to Cafeteria - 1923 ABATED | ABATED        | MISC              |         |             |                 |              |                               |                                    |               |                       |
| 39    | 9"x9" Pine Green w/ White Streaks VFT ABATED           |                   |                | Cafeteria - 1923 ABATED                       | ABATED        | MISC              |         |             |                 |              |                               |                                    |               |                       |
| 40    | 9"x9" Pine Green w/ White Streaks VFT Mastic ABATED    |                   |                | Cafeteria - 1923 ABATED                       | ABATED        | MISC              |         |             |                 |              |                               |                                    |               |                       |
| 41    | 9"x9" White w/ Pine Green Streaks VFT ABATED           |                   |                | Cafeteria - 1923 ABATED                       | ABATED        | MISC              |         |             |                 |              |                               |                                    |               |                       |
| 42    | 9"x9" White w/ Pine Green Streaks VFT Mastic ABATED    |                   |                | Cafeteria - 1923 ABATED                       | ABATED        | MISC              |         |             |                 |              |                               |                                    |               |                       |
| 43    | 9"x9" Forest Green VFT ABATED                          |                   |                | Cafeteria - 1923 ABATED                       | ABATED        | MISC              |         |             |                 |              |                               |                                    |               |                       |
| 44    | 9"x9" Forest Green VFT Mastic ABATED                   |                   |                | Cafeteria - 1923 ABATED                       | ABATED        | MISC              |         |             |                 |              |                               |                                    |               |                       |
| 45    | 9"x9" Gray w/ White Streaks VFT ABATED                 |                   |                | Cafeteria - 1923 ABATED                       | ABATED        | MISC              |         |             |                 |              |                               |                                    |               |                       |
| 46    | 9"x9" Gray w/ White Streaks VFT Mastic ABATED          |                   |                | Cafeteria - 1923 ABATED                       | ABATED        | MISC              |         |             |                 |              |                               |                                    |               |                       |
| 47    | Brown Linoleum   | 504               | SF             | Teacher's Rest Area                           | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the                      |               | LOW                   |

# Chicago Public Schools

School Schurz High School Unit 46281 Building ID 1530

Address 3601 N. Milwaukee Ave. Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

*Inspector's Comments are Summarized at the End of the Report*

| HA No | Material Description                            | Material Quantity | Material Units | Material Location                            | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category | Damage Category                    | Damage Reason | Disturbance Potential |
|-------|---|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|------------------------------------|---------------|-----------------------|
|       |   |                   |                | & Room 376 - 1923 NOT OBSERVED               |               |                   |         |             |                 |              |                               | potential for damage               |               |                       |
| 48    | Brown Linoleum Mastic                           | 504               |                | Teacher's Rest Area & Room 376 - 1923        | ASSUMED       | MISC              | N       |             | 0               |              | No                            | ACBM with the potential for damage |               |                       |
| 49    | 12"x12" White w/ Blue Speckles VFT              | 900               | SF             | Room 110 - 1923 Bldg                         | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | MODERATE              |
| 50    | 12"x12" White w/ Blue Speckles VFT Mastic       | 900               | SF             | Room 110 - 1923 Bldg                         | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 51    | 12"x12" Beige w/ Dark Brown Speckles VFT        | 1,800             | SF             | Engineer's Office, Room 342 - 1923           | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 52    | 12"x12" Beige w/ Dark Brown Speckles VFT Mastic | 1,800             | SF             | Engineer's Office, Room 342 - 1923           | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 53    | 12"x12" White w/ Tan Spots VFT                  | 1,800             | SF             | 334, 336, 338, 340 - 1923 Bldg               | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | MODERATE              |
| 54    | 12"x12" White w/ Tan Spots VFT Mastic           | 1,800             | SF             | 334, 336, 338, 340 - 1923 Bldg               | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 55    | 12"x12" Gray w/ White & Brown Spots VFT         | 1,100             | SF             | Rooms 212, 340, 315 - 1923 Bldg              | CHR           | MISC              | N       | DIST        | 300             |              | No                            | ACBM with the potential for damage | 4             | MODERATE              |
| 56    | 12"x12" Gray w/ White & Brown Spots VFT Mastic  | 1,100             | SF             | Rooms 212, 340, 315 - 1923 Bldg              | CHR           | MISC              | N       | DIST        | 300             |              | No                            | ACBM with the potential for damage | 4             | LOW                   |
| 57    | 9"x9" Gray VFT                                  | 750               | SF             | Room 128 - 1923 NOT OBSERVED                 | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | MODERATE              |
| 58    | 9"x9" Gray VFT Mastic                           | 750               | SF             | Room 128 - 1923 NOT OBSERVED                 | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 59    | 12"x12" Brown w/ White Specks VFT               | 4,900             | SF             | 1st Floor through 4th Floor Corridors - 1908 | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | MODERATE              |
| 60    | 12"x12" Brown w/ White Specks VFT Mastic        | 4,900             | SF             | 1st Floor through 4th Floor Corridors - 1908 | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 61    | 12"x12" White w/ Gray Streaks VFT               | 2,500             | SF             | Main Office, Room 315, Room 117 - 1908       | CHR           | MISC              | N       | DIST        | 25              |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 62    | 12"x12" White w/ Gray Streaks VFT Mastic        | 2,500             | SF             | Main Office, Room 315, Room 117 - 1908       | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 63    | 9"x9" Beige w/ Brown & White Streaks VFT        | 350               | SF             | Room 316 - 1908                              | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | MODERATE              |
| 64    | 9"x9" Beige w/ Brown & White Streaks VFT Mastic | 350               | SF             | Room 316 - 1908                              | ASSUMED       | MISC              |         | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 65    | 12"x12" White w/ Tan Specks VFT                 |                   |                | Room 312 - 1908 NOT OBSERVED                 | NO_ACBM       |                   |         |             |                 |              | No                            |                                    |               |                       |
| 66    | 12"x12" White w/ Tan Specks VFT Mastic          |                   |                | Room 312 - 1908 NOT OBSERVED                 | NO_ACBM       |                   |         |             |                 |              | No                            |                                    |               |                       |

# Chicago Public Schools

School Schurz High School Unit 46281 Building ID 1530

Address 3601 N. Milwaukee Ave. Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

*Inspector's Comments are Summarized at the End of the Report*

| HA No | Material Description                           | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category | Damage Category                    | Damage Reason | Disturbance Potential |
|-------|--|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|------------------------------------|---------------|-----------------------|
| 67    | 12"x12" Tan w/ Tan Specks VFT                  | 900               | SF             | Room 322 - 1908   | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 68    | 12"x12" Tan w/ Tan Specks VFT Mastic           | 900               | SF             | Room 322 - 1908   | ASSUMED       | MISC              | N       |             | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 69    | 9"x9" Green w/ White Streaks VFT               | 500               | SF             | Room 114 - 1908   | CHR           | MISC              | N       | NONE        | 0               |              | Yes                           | ACBM with the potential for damage |               | MODERATE              |
| 70    | 9"x9" Green w/ White Streaks VFT Mastic        | 500               | SF             | Room 114 - 1908   | CHR           | MISC              | N       | NONE        | 0               |              | Yes                           | ACBM with the potential for damage |               | LOW                   |
| 71    | 9"x9" Black w/ White Streaks VFT               | 1,300             | SF             | Room 114 - 1908   | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | MODERATE              |
| 72    | 9"x9" Black w/ White Streaks VFT Mastic        | 1,300             | SF             | Room 114 - 1908   | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 73    | 12"x12" Gray w/ Gray & Black Specks VFT        | 600               | SF             | Room 114 - 1908<br>NOT OBSERVED                             | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | MODERATE              |
| 74    | 12"x12" Gray w/ Gray & Black Specks VFT Mastic | 600               | SF             | Room 114 - 1908<br>NOT OBSERVED                             | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 75    | 12"x12" Blue w/ White Streaks VFT              | 600               | SF             | Room 114 - 1908<br>NOT OBSERVED                             | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | MODERATE              |
| 76    | 12"x12" Blue w/ White Streaks VFT Mastic       | 600               | SF             | Room 114 - 1908<br>NOT OBSERVED                             | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 77    | 9"x9" Brown w/ White & Red Streaks VFT         | 650               | SF             | Room 018 & Hallway -1908<br>Room 018 does not exist         | CHR           | MISC              | N       | DIST        | 150             |              | No                            | ACBM with the potential for damage | 3             | MODERATE              |
| 78    | 9"x9" Brown w/ White & Red Streaks VFT Mastic  | 650               | SF             | Room 018 & Hallway - 1908<br>Room 018 does not exist        | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 79    | 9"x9" Tan w/ Brown & White Streaks VFT         | 650               | SF             | Room 018 & Hallway - 1908<br>Room 018 does not exist        | CHR           | MISC              | N       | DIST        | 150             |              | No                            | ACBM with the potential for damage | 3             | MODERATE              |
| 80    | 9"x9" Tan w/ Brown & White Streaks VFT Mastic  | 650               | SF             | Room 018 & Hallway - 1908<br>Room 018 does not exist        | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 81    | 9"x9" Gray w/ White Swirls VFT                 | 1,900             | SF             | Library (Underneath Carpet, HA # 111, # 109 & # 110) - 1908 | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | MODERATE              |
| 82    | 9"x9" Gray w/ White Swirls VFT Mastic          | 1,900             | SF             | Library (Underneath Carpet, HA # 111, # 109 & # 110) - 1908 | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 83    | 9"x9" White w/ Black Swirls VFT                | 1,900             | SF             | Library (Underneath Carpet, HA # 111, #                     | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | MODERATE              |

# Chicago Public Schools

School Schurz High School Unit 46281 Building ID 1530

Address 3601 N. Milwaukee Ave. Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

*Inspector's Comments are Summarized at the End of the Report*

| HA No | Material Description                              | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category | Damage Category                    | Damage Reason | Disturbance Potential |
|-------|---|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|------------------------------------|---------------|-----------------------|
| 84    | 9"x9" White w/ Black Swirls VFT Mastic            | 1,900             | SF             | 109 & # 110) - 1908<br>Library (Underneath Carpet, HA # 111, # 109 & # 110) - 1908 | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 85    | 12"x24" Gray w/ Black & White Swirls VFT          | 200               | SF             | 109 & # 110) - 1908<br>Library (Underneath Carpet, HA # 111, # 109 & # 110) - 1908 | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | MODERATE              |
| 86    | 12"x24" Gray w/ Black & White Swirls VFT Mastic   | 200               | SF             | 109 & # 110) - 1908<br>Library (Underneath Carpet, HA # 111, # 109 & # 110) - 1908 | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 87    | Stair Tread Tile Yellow w/ Gold Specks VFT        | 35                | SF             | 109 & # 110) - 1908<br>Library (Underneath Carpet, HA # 111, # 109 & # 110) - 1908 | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | MODERATE              |
| 88    | Stair Tread Tile Yellow w/ Gold Specks VFT Mastic | 35                | SF             | 109 & # 110) - 1908<br>Library (Underneath Carpet, HA # 111, # 109 & # 110) - 1908 | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 89    | Stair Tread Tile Gray w/ White Marble VFT         | 20                | SF             | 109 & # 110) - 1908<br>Library (Underneath Carpet, HA # 111, # 109 & # 110) - 1908 | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | MODERATE              |
| 90    | Stair Tread Tile Gray w/ White Marble VFT Mastic  | 20                | SF             | 109 & # 110) - 1908<br>Library (Underneath Carpet, HA # 111, # 109 & # 110) - 1908 | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 91    | 12"x12" Tan w/ Red & Black Streaks VFT            | 120               | SF             | Room 115 - 1908  | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 92    | 12"x12" Tan w/ Red & Black Streaks VFT Mastic     | 120               | SF             | Room 115 - 1908  | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 93    | 9"x9" Gray w/ Black & White Streaks VFT           | 120               | SF             | Room 115 - 1908  | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | MODERATE              |
| 94    | 9"x9" Gray w/ Black & White Streaks VFT Mastic    | 120               | SF             | Room 115 - 1908  | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 95    | 9"x9" Dark Green w/ White Streaks VFT             | 500               | SF             | Rooms 121, 121A - 1908   | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 96    | 9"x9" Dark Green w/ White Streaks VFT Mastic      | 500               | SF             | Rooms 121, 121A - 1908   | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 97    | Tan Spotted Linoleum                              | 400               | SF             | Third Floor Men's and Women's Teachers Toilet - 1908                               | CHR           | MISC              | N       | NONE        | 0               |              | Yes                           | ACBM with the potential for damage |               | MODERATE              |
| 98    | Tan Spotted Linoleum Mastic                       | 400               | SF             | Third Floor Men's and Women's Teachers Toilet - 1908                               | CHR           | MISC              | N       | NONE        | 0               |              | Yes                           | ACBM with the potential for damage |               | LOW                   |
| 99    | Lab Counter Top                                   | 100               | SF             | Room 319 - 1908  | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |



# Chicago Public Schools

School Schurz High School Unit 46281 Building ID 1530

Address 3601 N. Milwaukee Ave. Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

*Inspector's Comments are Summarized at the End of the Report*

| HA No   | Material Description                              | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category | Damage Category                    | Damage Reason | Disturbance Potential |
|---------|---|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|------------------------------------|---------------|-----------------------|
| HA-1011 | Transite  | 30                | SF             | 1st floor girl's r/r privacy wall   | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| HH      | MJP E/F/V on Fiberglass Pipe Insulation           | 142               | LF             | Locker Room, 1st Floor Boy's Toilet, Hot & Cold Deck, & Wood Shop Area - 1923; Rms 219, 315, 319 under Classroom Sinks (12 LF); 2nd Floor Girls washroom (5 LF); 3rd Floor Girls Washroom (5 LF). | CHR           | TSI               | Y       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| II      | Cardboard Pipe Insulation (Paper-Wrap Pipe Ins)   | 38                | LF             | Electrical Room Across from Stairway # 4 - 1908   | ASSUMED       | TSI               | Y       | LOC         | 0               |              | No                            | ACBM with the potential for damage |               | MODERATE              |
| JJ      | MJP E/F/V on Cardboard Pipe Insulation(P.wrap PI) | 10                | LF             | Electrical Room Across from Stairway # 4 - 1908   | CHR           | TSI               | Y       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |

# Chicago Public Schools

School Schurz High School Unit 46281 Building ID 1530

Address 3601 N. Milwaukee Ave. Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

*Inspector's Comments are Summarized at the End of the Report*

|   |
|---|
| Reinspection Date <b>4/19/2016</b>                |
| Inspector Name <b>David Avila</b>                 |
| <b>100-11093</b> <b>5/15/2017</b>                 |
| Inspector's IDPH License Number / Expiration Date |

### Inspector's Comments

| HA Number: | Inspector Comments:    |
|------------|------------------------|
| 01         |                        |
| 02         | Not Observed: 320, 321 |
| 03         |                        |
| 04         |                        |
| 05         | Not Observed: 320, 321 |
| 06         |                        |
| 07         |                        |
| 08         |                        |
| 09         |                        |
| 10         |                        |
| 100        |                        |
| 1009       |                        |
| 101        |                        |
| 102        |                        |
| 103        |                        |
| 104        | Not Observed: Room 320 |
| 105        | Not Observed: Room 320 |
| 106        |                        |
| 107        |                        |
| 108        |                        |
| 109        |                        |
| 11         |                        |
| 110        |                        |
| 111        |                        |



# Chicago Public Schools

School Schurz High School Unit 46281 Building ID 1530

Address 3601 N. Milwaukee Ave. Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

*Inspector's Comments are Summarized at the End of the Report*

---

| HA Number: | Inspector Comments:    |
|------------|------------------------|
| 112        |                        |
| 113        |                        |
| 113M       |                        |
| 114        |                        |
| 115        |                        |
| 116        |                        |
| 117        |                        |
| 118        |                        |
| 118A       |                        |
| 119        | Not Observes: Room 323 |
| 119A       | Not Observes: Room 323 |
| 12         |                        |
| 120        |                        |
| 120A       |                        |
| 121        |                        |
| 121 A      |                        |
| 122        |                        |
| 122A       |                        |
| 123        |                        |
| 123A       |                        |
| 124        |                        |
| 125        |                        |
| 126        |                        |
| 127        |                        |
| 128        |                        |
| 129        |                        |
| 13         |                        |
| 14         |                        |
| 15         |                        |

# Chicago Public Schools

School Schurz High School Unit 46281 Building ID 1530

Address 3601 N. Milwaukee Ave. Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

*Inspector's Comments are Summarized at the End of the Report*

---

| HA Number: | Inspector Comments: |
|------------|---------------------|
| 16         |                     |
| 17         |                     |
| 18         |                     |
| 19         |                     |
| 20         |                     |
| 21         |                     |
| 22         |                     |
| 23         |                     |
| 24         |                     |
| 25         |                     |
| 26         |                     |
| 27         |                     |
| 28         |                     |
| 29         |                     |
| 30         |                     |
| 31         |                     |
| 32         |                     |
| 33         |                     |
| 34         |                     |
| 35         |                     |
| 36         |                     |
| 37         |                     |
| 38         |                     |
| 39         |                     |
| 40         |                     |
| 41         |                     |
| 42         |                     |
| 43         |                     |
| 44         |                     |

# Chicago Public Schools

School Schurz High School Unit 46281 Building ID 1530

Address 3601 N. Milwaukee Ave. Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

*Inspector's Comments are Summarized at the End of the Report*

---

| HA Number: | Inspector Comments:              |
|------------|----------------------------------|
| 45         |                                  |
| 46         |                                  |
| 47         | Possibly under the carpet (2016) |
| 48         | Possibly under the carpet (2016) |
| 49         |                                  |
| 50         |                                  |
| 51         |                                  |
| 52         |                                  |
| 53         |                                  |
| 54         |                                  |
| 55         | Not Observed: Room 315           |
| 56         | Not Observed: Room 315           |
| 57         | NOT OBSERVED                     |
| 58         | NOT OBSERVED                     |
| 59         |                                  |
| 60         |                                  |
| 61         | Not Observed: Room 315           |
| 62         | Not Observed: Room 315           |
| 63         |                                  |
| 64         |                                  |
| 65         | NOT OBSERVED (2016)              |
| 66         | NOT OBSERVED                     |
| 67         |                                  |
| 68         |                                  |
| 69         |                                  |
| 70         |                                  |
| 71         |                                  |
| 72         |                                  |
| 73         | NOT OBSERVED                     |

# Chicago Public Schools

School Schurz High School Unit 46281 Building ID 1530

Address 3601 N. Milwaukee Ave. Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

*Inspector's Comments are Summarized at the End of the Report*

---

| HA Number: | Inspector Comments:     |
|------------|-------------------------|
| 74         | NOT OBSERVED            |
| 75         | NOT OBSERVED            |
| 76         | NOT OBSERVED            |
| 77         | Room 018 does not exist |
| 78         | Room 018 does not exist |
| 79         | Room 018 does not exist |
| 80         | Room 018 does not exist |
| 81         |                         |
| 82         |                         |
| 83         |                         |
| 84         |                         |
| 85         |                         |
| 86         |                         |
| 87         |                         |
| 88         |                         |
| 89         |                         |
| 90         |                         |
| 91         |                         |
| 92         |                         |
| 93         |                         |
| 94         |                         |
| 95         |                         |
| 96         |                         |
| 97         |                         |
| 98         |                         |
| 99         |                         |
| AA         |                         |
| BB         |                         |
| CC         |                         |

# Chicago Public Schools

School Schurz High School Unit 46281 Building ID 1530

Address 3601 N. Milwaukee Ave. Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

*Inspector's Comments are Summarized at the End of the Report*

---

| HA Number: | Inspector Comments: |
|------------|---------------------|
| DD         |                     |
| E          |                     |
| EE         |                     |
| F          |                     |
| FF         |                     |
| GG         |                     |
| HA-1000    |                     |
| HA-1001    |                     |
| HA-1002    |                     |
| HA-1003    |                     |
| HA-1004    |                     |
| HA-1005    |                     |
| HA-1006    |                     |
| HA-1007    |                     |
| HA-1008    |                     |
| HA-1010    |                     |
| HA-1010m   |                     |
| HA-1011    |                     |
| HH         |                     |
| II         |                     |
| JJ         |                     |

**Table II**

**Management Planner's Review**

---

# Chicago Public Schools

**School** Schurz High School  
**Address** 3601 N. Milwaukee Ave.

**Unit** 46281  
 Chicago, IL, 60641

**Building ID** 1530  
**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

### Management Planner's Comments Summarized at the End of the Report

| HA Num | Material Description                     | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Quantity | Damage Units | Damage Category                      | Response        |
|--------|--|-------------------|----------------|---|---------------|-------------------|---------|-----------------|--------------|--------------------------------------|-----------------|
| 01     | 12"x12" Tan w/ White Streaks VFT         | 32,604            | SF             | Throughout - 1908 (See Hatching Maps); Corridor at Rm 112                     | Chrysotile    | MISC              | No      | 225             | SF           | 6 ACBM with the potential for damage | Repair          |
| 02     | 9"x9" Brown w/ White Specks VFT          | 2,400             | SF             | Rm 213, 217, 219, 313, 317, 320, 321 - 1908 Bldg.                             | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 03     | Tan w/ Brown Swirls Linoleum             | 2,400             | SF             | 5th Fl Band Rm - 1908 Bldg.   | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 04     | 12"x12" Tan w/ White Streaks VFT Mastic  | 32,604            | SF             | Throughout - 1908 (See Hatching Maps)   | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 05     | 9"x9" Brown w/ White Specks VFT Mastic   | 2,400             | SF             | Rm 213, 217, 219, 313, 317, 320, 321 - 1908 Bldg.                             | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 06     | Tan w/ Brown Swirls Linoleum Mastic      | 2,400             |                | 5th Fl Band Rm - 1908 Bldg.   | Assumed       | MISC              | No      | 0               |              | 6 ACBM with the potential for damage | Follow O&M Plan |
| 07     | 12"x12" Tan w/ White Streaks VFT         | 5,665             | SF             | Rm 305, 1st through 3rd Fl Corridor, 3rd Fl Girls Toilet - 1915 Bldg.         | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 08     | 12"x12" Tan w/ White Streaks VFT Mastic  | 5,665             | SF             | Rm 305, 1st through 3rd Fl Corridor, 3rd Fl Girls Toilet - 1915 Bldg.         | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 09     | 9"x9" Green w/ White Specks VFT          | 340               | SF             | Rm 301 - 1915 Bldg.   | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 10     | 9"x9" Green w/ White Specks VFT Mastic   | 340               | SF             | Rm 301 - 1915 Bldg.   | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 100    | Textured Plaster                         |                   |                | Auditorium - 1923   | No ACBM       |                   |         |                 |              |                                      |                 |
| 1009   | Boiler #1 (small)                        | 350               | SF             |   | Assumed       | TSI               | Yes     | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 101    | Undetermined Size & Color VFT            |                   |                | Fourth Floor Corridor (Underneath HA # 59 & 60) - 1908                        | No ACBM       |                   |         |                 |              |                                      |                 |
| 102    | Undetermined Size & Color VFT Mastic     |                   |                | Fourth Floor Corridor (Underneath HA # 59 & 60) - 1908                        | No ACBM       |                   |         |                 |              |                                      |                 |
| 103    | MJP E/F/V on Fiberglass Pipe Insulation  |                   |                | 1st Floor Men's Faculty Toilet, 2nd & 3rd Floor Girls Toilets (chases) - 1908 |               | TSI               |         |                 |              |                                      |                 |
| 104    | Green Linoleum                           | 1,600             | SF             | Room 320, 369, Prep Room, Storage Room - 1923                                 | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 105    | Green Linoleum Mastic                    | 400               | SF             | Room 320, 369, Prep Room, Storage Room - 1923                                 | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 106    | 2" x 2" Ceiling Tile                     |                   |                | Room 320, 369, Prep Room, Storage Room - 1923                                 | No ACBM       |                   |         |                 |              |                                      |                 |
| 107    | 12" x 12" Gray w/ White Speck VFT        | 1,400             | SF             | Room 216 - 1908   | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 108    | 12" x 12" Gray w/ White Speck VFT Mastic | 1,400             | SF             | Room 216 - 1908   | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 109    | 12" x 12" Orange Cork VFT                | 4,500             | SF             | Library - 1908  | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 11     | 12"x12" Tan w/ White Streaks VFT         | 18,061            | SF             | Throughout - 1923 (See Hatching Maps)   | Chrysotile    | MISC              | No      | 35              | SF           | 6 ACBM with the potential for damage | Repair          |
| 110    | 12" x 12" Orange Cork VFT Mastic         | 4,500             | SF             | Library - 1908  | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |

# Chicago Public Schools

**School** Schurz High School  
**Address** 3601 N. Milwaukee Ave.

**Unit** 46281  
 Chicago, IL, 60641

**Building ID** 1530  
**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

### *Management Planner's Comments Summarized at the End of the Report*

| HA Num | Material Description                                    | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Quantity | Damage Units | Damage Category                      | Response        |
|--------|---|-------------------|----------------|--|---------------|-------------------|---------|-----------------|--------------|--------------------------------------|-----------------|
| 111    | Carpet Mastic   | 4,500             | SF             | Library - 1908   | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 112    | Carpet Adhesive   | 4,934             | SF             | Main Office, Nurse Office 128, 125A, 114, 110, 115, Teacher/Staff Room, 376  | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 113    | 12"X12" Powder-Blue w/White and Blue Streaks VFT        | 2,000             | SF             | Rm 309 -1915 Addition  | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 113M   | 12"X12" Powder-Blue w/White and Blue Streaks VFT Mastic | 2,000             | SF             | Rm 309 -1915 Addition  | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 114    | VFT 12 X 12 Tan w/ white specs w/ Mastic                | 700               | SF             | Room 205   | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 115    | Carpet Mastic   | 2,600             | SF             | Room 110, 128, 111, 119, 300   | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 116    | Lab Black Counter Tops                                  | 2,000             | SF             | Rooms 315, 313, 219, 215, 213, 223, 225, 229   | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 117    | Lab Black Table Tops                                    | 2,000             | SF             | Rooms 315, 313, 219, 215, 213, 223, 225, 229   | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 118    | VFT 12 X 12 Tan w/ Large White Striations               | 21,000            | SF             | Rooms 220, 305, 308, 310, 320, 321, 322, 332, 353, 355, 361, 358, 364, 368, 377, 379,381, 324, 351, 363, 372, 374, 376, 327, 221, 125, 105 & 108 | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 118A   | 12 X 12 Tan w/ Large White Striations w/ Mastic         | 21,000            | SF             | Rooms 220, 305, 308, 310, 320, 321, 322, 332, 353, 355, 361, 358, 364, 368, 377, 379,381, 324, 351, 363, 372, 374, 376, 327, 221, 125, 105 & 108 | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 119    | VFT 12 X 12 Light blue w/ gray & white specs            | 4,000             | SF             | Rooms 219, 217, 213, 123, 122, 323, 229, 227, 223, 225, 309 & 371  | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 119A   | 12 x 12 Light Blue w/ gray & white specs w/ Mastic      | 4,000             | SF             | Rooms 219, 217, 213, 123, 122, 323, 229, 227, 223, 225, 309 & 371  | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 12     | 12"x12" Tan w/ White Streaks VFT Mastic                 | 18,061            | SF             | Throughout - 1923 (See Hatching Maps)  | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 120    | VFT 12 X 12 White w/ Tan Streaks                        | 4,000             | SF             | Rooms 311, 336, 338, 334, 129, 131   | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 120A   | 12 x 12 white w/ Tan Streaks w/ Mastic                  | 4,000             | SF             | Rooms 311, 336, 338, 334, 129, 131   | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 121    | VFT 12 x 12 White w/ greens & gray streaks              | 2,200             | SF             | Rooms 312, 314   | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 121 A  | 12 x 12 White w/ Green & Gray Streaks w/ Mastic         | 2,200             | SF             | Rooms 312, 314   | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 122    | VFT 12 X 12 Tan w/ white Streaks                        | 700               | SF             | Room 116   | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 122A   | 12 X 12 Tan w/ White Streaks Mastic                     | 700               | SF             | Room 116   | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 123    | Tan Linoleum w/ white & black streaks                   | 700               | SF             | Room 315   | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 123A   | Tan Linoleum w/ white & black streaks w/ Mastic         | 700               | SF             | Room 315   | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |



# Chicago Public Schools

**School** Schurz High School  
**Address** 3601 N. Milwaukee Ave.

**Unit** 46281  
 Chicago, IL, 60641

**Building ID** 1530  
**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

### *Management Planner's Comments Summarized at the End of the Report*

| HA Num | Material Description                               | Material Quantity | Material Units | Material Location                                     | Asbestos Type | Material Category | Friable | Damage Quantity | Damage Units | Damage Category                      | Response        |
|--------|--|-------------------|----------------|---|---------------|-------------------|---------|-----------------|--------------|--------------------------------------|-----------------|
| 124    | 12 x 12 Tan with Specks Floor Tile                 | 4,600             | SF             | Cafeteria, Serving Area, Teachers' Lounge             | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 125    | 12 x 12 Tan with Specks Floor Tile Mastic          | 4,600             | SF             | Cafeteria, Serving Area, Teachers' Lounge             | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 126    | 12"x12" Brown w/ Specks VFT                        | 300               | SF             | Elevator Lobbies on 1st, 2nd, 3rd, 4th, ad 5th Floors | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 127    | 12"x12" Brown w/ Specks VFT Mastic                 | 300               | SF             | Elevator Lobbies on 1st, 2nd, 3rd, 4th, ad 5th Floors | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 128    | 12"x12" Light Brown w Gray specks VFT              | 600               | SF             | Elevator Lobbies on 1st, 2nd, 3rd, 4th, ad 5th Floors | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 129    | 12"x12" Light Brown w Gray specks VFT Mastic       | 600               | SF             | Elevator Lobbies on 1st, 2nd, 3rd, 4th, ad 5th Floors | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 13     | 9"x9" Cocoa w/ White & Brown Streaks VFT           | 7,260             | SF             | Rooms 223, 225, 227, 359, 365, 367, 371 - 1923 Bldg   | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 14     | 9"x9" Cocoa w/ White & Brown Streaks VFT Mastic    | 7,260             | SF             | Rooms 223, 225, 227, 359, 365, 367, 371 - 1923 Bldg   | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 15     | Brown Linoleum                                     |                   |                | Gymnasium Office - 1915                               | No ACBM       |                   |         |                 |              |                                      |                 |
| 16     | Brown Linoleum Mastic                              |                   |                | Gymnasium Office - 1915                               | No ACBM       |                   |         |                 |              |                                      |                 |
| 17     | 12"x12" White w/ Light Brown Streaks VFT           | 1,000             | SF             | Room 309 - 1915 Bldg                                  | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 18     | 12"x12" White w/ Light Brown Streaks VFT Mastic    | 1,000             | SF             | Room 309 - 1915 Bldg                                  | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 19     | 9"x9" Red w/ Black & White Specks VFT              | 340               | SF             | Room 301 - 1915 Bldg                                  | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 20     | 9"x9" Red w/ Black & White Specks VFT Mastic       | 340               | SF             | Room 301 - 1915 Bldg                                  | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 21     | 9"x9" Brown w/ White & Black Streaks VFT           | 20                | SF             | Room 301 - 1915 Bldg                                  | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 22     | 9"x9" Brown w/ White & Black Streaks VFT Mastic    | 20                | SF             | Room 301 - 1915 Bldg                                  | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 23     | 24" X 6" Black VFT                                 | 70                | SF             | Room 301 - 1915 Bldg                                  | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 24     | 24" X 6" Black VFT Mastic                          | 70                | SF             | Room 301 - 1915 Bldg                                  | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 25     | 12"x12" Beige w/ Brown & White Streaks VFT         | 750               | SF             | Room 308 - 1915                                       | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 26     | 12"x 12" Beige w/ Brown & White Streaks VFT Mastic | 750               | SF             | Room 308 - 1915                                       | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 27     | 12"x12" Brown w/ White Specks VFT                  | 1,150             | SF             | 1st, 2nd, & 3rd Floor Corridors - 1915                | Chrysotile    | MISC              | No      | 40              | SF           | 6 ACBM with the potential for damage | Repair          |
| 28     | 12"x12" Brown w/ White Specks VFT Mastic           | 1,150             | SF             | 1st, 2nd, & 3rd Floor Corridors - 1915                | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 29     | 12"x12" Gray w/ White Streaks VFT                  | 1,600             | SF             | Gymnasium/205 - 1915                                  | Assumed       | MISC              |         | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 30     | 12"x12" Gray w/ White Streaks VFT Mastic           | 1,600             | SF             | Gymnasium/205 - 1915                                  | Assumed       | MISC              |         | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 31     | 12"x12" Beige w/ White & Orange Streaks VFT        | 1,810             | SF             | Room 310 and 341 - 1923                               | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 32     | 12"x12" Beige w/ White & Orange Streaks VFT        | 1,810             | SF             | Room 310 and 341 - 1923                               | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |

# Chicago Public Schools

**School** Schurz High School  
**Address** 3601 N. Milwaukee Ave.

**Unit** 46281  
 Chicago, IL, 60641

**Building ID** 1530  
**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

### Management Planner's Comments Summarized at the End of the Report

| HA Num | Material Description                                   | Material Quantity | Material Units | Material Location                                  | Asbestos Type | Material Category | Friable | Damage Quantity | Damage Units | Damage Category                      | Response        |
|--------|--|-------------------|----------------|--|---------------|-------------------|---------|-----------------|--------------|--------------------------------------|-----------------|
|        | Mastic   |                   |                |  |               |                   |         |                 |              |                                      |                 |
| 33     | 9"x9" Cocoa w/ White & Brown Short Streaks VFT         | 3,324             | SF             | 3rd Floor Hallway - 1923                           | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 34     | 9"x9" Cocoa w/ White & Brn Short Strks VFT Mastic      | 3,324             | SF             | 3rd Floor Hallway - 1923                           | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 35     | 12"x 12" Cocoa w/ White & Brown Long Streaks VFT       | 924               | SF             | Room 253 - 1923                                    | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 36     | 12"x12" Cocoa w/ Wht. & Brwn. Lng Strks VFT Mastic     | 924               | SF             | Room 253 - 1923                                    | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 37     | 12"x12" Gray w/ White & Gray Streaks VFT ABATED        |                   |                | Teachers Room Next to Cafeteria - 1923 ABATED      | Abated        | MISC              |         |                 |              |                                      |                 |
| 38     | 12"x12" Gray w/ White & Gray Streaks VFT Mastic ABATED |                   |                | Teachers Room Next to Cafeteria - 1923 ABATED      | Abated        | MISC              |         |                 |              |                                      |                 |
| 39     | 9"x9" Pine Green w/ White Streaks VFT ABATED           |                   |                | Cafeteria - 1923 ABATED                            | Abated        | MISC              |         |                 |              |                                      |                 |
| 40     | 9"x9" Pine Green w/ White Streaks VFT Mastic ABATED    |                   |                | Cafeteria - 1923 ABATED                            | Abated        | MISC              |         |                 |              |                                      |                 |
| 41     | 9"x9" White w/ Pine Green Streaks VFT ABATED           |                   |                | Cafeteria - 1923 ABATED                            | Abated        | MISC              |         |                 |              |                                      |                 |
| 42     | 9"x9" White w/ Pine Green Streaks VFT Mastic ABATED    |                   |                | Cafeteria - 1923 ABATED                            | Abated        | MISC              |         |                 |              |                                      |                 |
| 43     | 9"x9" Forest Green VFT ABATED                          |                   |                | Cafeteria - 1923 ABATED                            | Abated        | MISC              |         |                 |              |                                      |                 |
| 44     | 9"x9" Forest Green VFT Mastic ABATED                   |                   |                | Cafeteria - 1923 ABATED                            | Abated        | MISC              |         |                 |              |                                      |                 |
| 45     | 9"x9" Gray w/ White Streaks VFT ABATED                 |                   |                | Cafeteria - 1923 ABATED                            | Abated        | MISC              |         |                 |              |                                      |                 |
| 46     | 9"x9" Gray w/ White Streaks VFT Mastic ABATED          |                   |                | Cafeteria - 1923 ABATED                            | Abated        | MISC              |         |                 |              |                                      |                 |
| 47     | Brown Linoleum   | 504               | SF             | Teacher's Rest Area & Room 376 - 1923 NOT OBSERVED | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 48     | Brown Linoleum Mastic                                  | 504               |                | Teacher's Rest Area & Room 376 - 1923              | Assumed       | MISC              | No      | 0               |              | 6 ACBM with the potential for damage | Follow O&M Plan |
| 49     | 12"x12" White w/ Blue Speckles VFT                     | 900               | SF             | Room 110 - 1923 Bldg                               | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 50     | 12"x12" White w/ Blue Speckles VFT Mastic              | 900               | SF             | Room 110 - 1923 Bldg                               | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 51     | 12"x12" Beige w/ Dark Brown Speckles VFT               | 1,800             | SF             | Engineer's Office, Room 342 - 1923                 | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 52     | 12"x12" Beige w/ Dark Brown Speckles VFT Mastic        | 1,800             | SF             | Engineer's Office, Room 342 - 1923                 | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 53     | 12"x12" White w/ Tan Spots VFT                         | 1,800             | SF             | 334, 336, 338, 340 - 1923 Bldg                     | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 54     | 12"x12" White w/ Tan Spots VFT Mastic                  | 1,800             | SF             | 334, 336, 338, 340 - 1923 Bldg                     | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 55     | 12"x12" Gray w/ White & Brown Spots VFT                | 1,100             | SF             | Rooms 212, 340, 315 - 1923 Bldg                    | Chrysotile    | MISC              | No      | 300             | SF           | 6 ACBM with the potential for damage | Repair          |
| 56     | 12"x12" Gray w/ White & Brown Spots VFT Mastic         | 1,100             | SF             | Rooms 212, 340, 315 - 1923 Bldg                    | Chrysotile    | MISC              | No      | 300             | SF           | 6 ACBM with the potential for damage | Repair          |
| 57     | 9"x9" Gray VFT   | 750               | SF             | Room 128 - 1923 NOT OBSERVED                       | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage |                 |

# Chicago Public Schools

**School** Schurz High School  
**Address** 3601 N. Milwaukee Ave.

**Unit** 46281  
Chicago, IL, 60641

**Building ID** 1530  
**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

### Management Planner's Comments Summarized at the End of the Report

| HA Num | Material Description                            | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Quantity | Damage Units | Damage Category                      | Response        |
|--------|---|-------------------|----------------|---|---------------|-------------------|---------|-----------------|--------------|--------------------------------------|-----------------|
| 58     | 9"x9" Gray VFT Mastic                           | 750               | SF             | Room 128 - 1923 NOT OBSERVED                                | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage |                 |
| 59     | 12"x12" Brown w/ White Specks VFT               | 4,900             | SF             | 1st Floor through 4th Floor Corridors - 1908                | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 60     | 12"x12" Brown w/ White Specks VFT Mastic        | 4,900             | SF             | 1st Floor through 4th Floor Corridors - 1908                | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 61     | 12"x12" White w/ Gray Streaks VFT               | 2,500             | SF             | Main Office, Room 315, Room 117 - 1908                      | Chrysotile    | MISC              | No      | 25              | SF           | 6 ACBM with the potential for damage | Repair          |
| 62     | 12"x12" White w/ Gray Streaks VFT Mastic        | 2,500             | SF             | Main Office, Room 315, Room 117 - 1908                      | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 63     | 9"x9" Beige w/ Brown & White Streaks VFT        | 350               | SF             | Room 316 - 1908   | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 64     | 9"x9" Beige w/ Brown & White Streaks VFT Mastic | 350               | SF             | Room 316 - 1908   | Assumed       | MISC              |         | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 65     | 12"x12" White w/ Tan Specks VFT                 |                   |                | Room 312 - 1908 NOT OBSERVED                                | No ACBM       |                   |         |                 |              |                                      |                 |
| 66     | 12"x12" White w/ Tan Specks VFT Mastic          |                   |                | Room 312 - 1908 NOT OBSERVED                                | No ACBM       |                   |         |                 |              |                                      |                 |
| 67     | 12"x12" Tan w/ Tan Specks VFT                   | 900               | SF             | Room 322 - 1908   | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 68     | 12"x12" Tan w/ Tan Specks VFT Mastic            | 900               | SF             | Room 322 - 1908   | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 69     | 9"x9" Green w/ White Streaks VFT                | 500               | SF             | Room 114 - 1908   | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 70     | 9"x9" Green w/ White Streaks VFT Mastic         | 500               | SF             | Room 114 - 1908   | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 71     | 9"x9" Black w/ White Streaks VFT                | 1,300             | SF             | Room 114 - 1908   | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 72     | 9"x9" Black w/ White Streaks VFT Mastic         | 1,300             | SF             | Room 114 - 1908   | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 73     | 12"x12" Gray w/ Gray & Black Specks VFT         | 600               | SF             | Room 114 - 1908 NOT OBSERVED                                | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage |                 |
| 74     | 12"x12" Gray w/ Gray & Black Specks VFT Mastic  | 600               | SF             | Room 114 - 1908 NOT OBSERVED                                | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage |                 |
| 75     | 12"x12" Blue w/ White Streaks VFT               | 600               | SF             | Room 114 - 1908 NOT OBSERVED                                | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage |                 |
| 76     | 12"x12" Blue w/ White Streaks VFT Mastic        | 600               | SF             | Room 114 - 1908 NOT OBSERVED                                | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage |                 |
| 77     | 9"x9" Brown w/ White & Red Streaks VFT          | 650               | SF             | Room 018 & Hallway -1908 Room 018 does not exist            | Chrysotile    | MISC              | No      | 150             | SF           | 6 ACBM with the potential for damage | Repair          |
| 78     | 9"x9" Brown w/ White & Red Streaks VFT Mastic   | 650               | SF             | Room 018 & Hallway - 1908 Room 018 does not exist           | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 79     | 9"x9" Tan w/ Brown & White Streaks VFT          | 650               | SF             | Room 018 & Hallway - 1908 Room 018 does not exist           | Chrysotile    | MISC              | No      | 150             | SF           | 6 ACBM with the potential for damage | Repair          |
| 80     | 9"x9" Tan w/ Brown & White Streaks VFT Mastic   | 650               | SF             | Room 018 & Hallway - 1908 Room 018 does not exist           | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 81     | 9"x9" Gray w/ White Swirls VFT                  | 1,900             | SF             | Library (Underneath Carpet, HA # 111, # 109 & # 110) - 1908 | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 82     | 9"x9" Gray w/ White Swirls VFT Mastic           | 1,900             | SF             | Library (Underneath Carpet, HA # 111, # 109 & # 110) - 1908 | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |

# Chicago Public Schools

**School** Schurz High School  
**Address** 3601 N. Milwaukee Ave.

**Unit** 46281  
 Chicago, IL, 60641

**Building ID** 1530  
**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

### *Management Planner's Comments Summarized at the End of the Report*

| HA Num | Material Description                              | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Quantity | Damage Units | Damage Category                      | Response        |
|--------|---|-------------------|----------------|---|---------------|-------------------|---------|-----------------|--------------|--------------------------------------|-----------------|
| 83     | 9"x9" White w/ Black Swirls VFT                   | 1,900             | SF             | Library (Underneath Carpet, HA # 111, # 109 & # 110) - 1908                         | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 84     | 9"x9" White w/ Black Swirls VFT Mastic            | 1,900             | SF             | Library (Underneath Carpet, HA # 111, # 109 & # 110) - 1908                         | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 85     | 12"x24" Gray w/ Black & White Swirls VFT          | 200               | SF             | Library (Underneath Carpet, HA # 111, # 109 & # 110) - 1908                         | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 86     | 12"x24" Gray w/ Black & White Swirls VFT Mastic   | 200               | SF             | Library (Underneath Carpet, HA # 111, # 109 & # 110) - 1908                         | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 87     | Stair Tread Tile Yellow w/ Gold Specks VFT        | 35                | SF             | Library (Underneath Carpet, HA # 111, # 109 & # 110) - 1908                         | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 88     | Stair Tread Tile Yellow w/ Gold Specks VFT Mastic | 35                | SF             | Library (Underneath Carpet, HA # 111, # 109 & # 110) - 1908                         | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 89     | Stair Tread Tile Gray w/ White Marble VFT         | 20                | SF             | Library (Underneath Carpet, HA # 111, # 109 & # 110) - 1908                         | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 90     | Stair Tread Tile Gray w/ White Marble VFT Mastic  | 20                | SF             | Library (Underneath Carpet, HA # 111, # 109 & # 110) - 1908                         | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 91     | 12"x12" Tan w/ Red & Black Streaks VFT            | 120               | SF             | Room 115 - 1908   | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 92     | 12"x12" Tan w/ Red & Black Streaks VFT Mastic     | 120               | SF             | Room 115 - 1908   | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 93     | 9"x9" Gray w/ Black & White Streaks VFT           | 120               | SF             | Room 115 - 1908   | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 94     | 9"x9" Gray w/ Black & White Streaks VFT Mastic    | 120               | SF             | Room 115 - 1908   | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 95     | 9"x9" Dark Green w/ White Streaks VFT             | 500               | SF             | Rooms 121, 121A - 1908  | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 96     | 9"x9" Dark Green w/ White Streaks VFT Mastic      | 500               | SF             | Rooms 121, 121A - 1908  | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 97     | Tan Spotted Linoleum                              | 400               | SF             | Third Floor Men's and Women's Teachers Toilet - 1908                                | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 98     | Tan Spotted Linoleum Mastic                       | 400               | SF             | Third Floor Men's and Women's Teachers Toilet - 1908                                | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 99     | Lab Counter Top                                   | 100               | SF             | Room 319 - 1908   | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| AA     | Air Cell Pipe Insulation                          | 14                | LF             | 3rd Floor Janitor's Closet By Room 301- 1915  | Chrysotile    | TSI               | Yes     | 0               | LF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| BB     | MJP E/F/V on Air Cell Pipe Insulation             | 6                 | LF             | 3rd Floor Janitor's Closet By Room 301 - 1915; 1st Floor Girls Toilet Added in 2010 | Chrysotile    | TSI               | Yes     | 0               | LF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| CC     | MJP E/F/V on Fiberglass Pipe Insulation           | 20                | LF             | First Floor Girl's Toilet, First Floor Corridor - 1915                              | Chrysotile    | TSI               | Yes     | 0               | LF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| DD     | MJP E/F/V on Mag Block Pipe Insulation            | 1                 | LF             | Janitor's Closet By Room 301 - 1915   | Chrysotile    | TSI               | Yes     | 0               | LF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| E      | Boiler Gasket                                     | 1                 | SF             | Boiler Room - 1923  | Chrysotile    | TSI               | Yes     | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |

# Chicago Public Schools

**School** Schurz High School  
**Address** 3601 N. Milwaukee Ave.

**Unit** 46281  
 Chicago, IL, 60641

**Building ID** 1530  
**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

### Management Planner's Comments Summarized at the End of the Report

| HA Num   | Material Description                              | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Quantity | Damage Units | Damage Category                      | Response        |
|----------|---|-------------------|----------------|---|---------------|-------------------|---------|-----------------|--------------|--------------------------------------|-----------------|
| EE       | Mag Block Pipe Insulation                         | 14                | LF             | Janitor's Closet By Room 301 - 1915   | Chrysotile    | TSI               | Yes     | 0               | LF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| F        | Boiler Gasket                                     | 1                 | SF             | Boiler Room - 1923  | Chrysotile    | TSI               | Yes     | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| FF       | Aircell Pipe Insulation                           | 10                | LF             | Incinerator Room - 1923   | Assumed       | MISC              | No      | 0               | LF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| GG       | MJP E/F/V on Aircell Pipe Insulation              | 7                 | LF             | Incinerator Room - 1923   | Assumed       | MISC              | No      | 0               | LF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| HA-1000  | 2'x4' white ceiling tiles with random fis & holes | 20,000            | SF             | Throughout  | Assumed       | MISC              | Yes     | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| HA-1001  | 2"X4" white plain ceiling tile                    | 960               | SF             | Teachers' Lunch Room  | Assumed       | MISC              | Yes     | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| HA-1002  | 1'x1' white ceiling tile rand holes               | 1,500             | SF             | Students' Lunch Room  | Assumed       | MISC              | Yes     | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| HA-1003  | Glue for 1'x1' white ceilingtile with holes       | 1,500             | SF             | Students' Lunch Room  | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| HA-1004  | 2'x2' white plain ceiling tile                    | 1,500             | SF             | Kitchen   | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| HA-1005  | 1'x1' white CT with large holes                   | 150               | SF             | Kitchen Manager Office  | Assumed       | MISC              | Yes     | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| HA-1006  | Glue for 1'x1' wh CT with large holes             | 150               | SF             | Kitchen Manager Office  | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| HA-1007  | 1'x1' wh CT with random fissures                  | 1,680             | SF             | Rm. 300 on ceiling and walls  | Assumed       | MISC              | Yes     | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| HA-1008  | Glue for 1'x1' white CT with rand fiss            | 1,680             | SF             | Rm. 300 on ceiling and walls  | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| HA-1010  | 12"x12" yellow VFT NOT OBSERVED                   |                   |                |   |               | MISC              |         |                 |              |                                      |                 |
| HA-1010m | Adhesive for 12"x12" yellow VFT NOT OBSERVED      |                   |                |   |               | MISC              |         |                 |              |                                      |                 |
| HA-1011  | Transite  | 30                | SF             | 1st floor girl's r/r privacy wall   | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| HH       | MJP E/F/V on Fiberglass Pipe Insulation           | 142               | LF             | Locker Room, 1st Floor Boy's Toilet, Hot & Cold Deck, & Wood Shop Area - 1923; Rms 219, 315, 319 under Classroom Sinks (12 LF); 2nd Floor Girls washroom (5 LF); 3rd Floor Girls Washroom (5 LF). | Chrysotile    | TSI               | Yes     | 0               | LF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| II       | Cardboard Pipe Insulation (Paper-Wrap Pipe Ins)   | 38                | LF             | Electrical Room Across from Stairway # 4 - 1908   | Assumed       | TSI               | Yes     | 0               | LF           | 6 ACBM with the potential for damage | Follow O&M Plan |

# Chicago Public Schools

**School** Schurz High School  
**Address** 3601 N. Milwaukee Ave.

**Unit** 46281  
 Chicago, IL, 60641

**Building ID** 1530  
**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

### *Management Planner's Comments Summarized at the End of the Report*

| HA Num | Material Description                              | Material Quantity | Material Units | Material Location                               | Asbestos Type | Material Category | Friable | Damage Quantity | Damage Units | Damage Category                      | Response        |
|--------|---|-------------------|----------------|---|---------------|-------------------|---------|-----------------|--------------|--------------------------------------|-----------------|
| JJ     | MJP E/F/V on Cardboard Pipe Insulation(P.wrap Pl) | 10                | LF             | Electrical Room Across from Stairway # 4 - 1908 | Chrysotile    | TSI               | Yes     | 0               | LF           | 6 ACBM with the potential for damage | Follow O&M Plan |

|                      |                  |
|----------------------|------------------|
| Review Date          | 5/17/2016        |
| Manager Planner Name | Guillermo Garcia |

| HA Number | Management Comments |
|-----------|---------------------|
| 01        |                     |
| 02        |                     |

# Chicago Public Schools

**School** Schurz High School  
**Address** 3601 N. Milwaukee Ave.

**Unit** 46281  
 Chicago, IL, 60641

**Building ID** 1530  
**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

### *Management Planner's Comments Summarized at the End of the Report*

|                                    |           |
|------------------------------------|-----------|
| 100-01786                          | 3/21/2017 |
| Manager IDPH License No/Expiration |           |

| HA Number | Management Comments |
|-----------|---------------------|
| 03        |                     |
| 04        |                     |
| 05        |                     |
| 06        |                     |
| 07        |                     |
| 08        |                     |
| 09        |                     |
| 10        |                     |
| 100       |                     |
| 1009      |                     |
| 101       |                     |
| 102       |                     |
| 103       |                     |
| 104       |                     |
| 105       |                     |
| 106       |                     |
| 107       |                     |
| 108       |                     |
| 109       |                     |
| 11        |                     |
| 110       |                     |
| 111       |                     |
| 112       |                     |
| 113       |                     |
| 113M      |                     |
| 114       |                     |
| 115       |                     |

# Chicago Public Schools

**School** Schurz High School  
**Address** 3601 N. Milwaukee Ave.

**Unit** 46281  
 Chicago, IL, 60641

**Building ID** 1530  
**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

*Management Planner's Comments Summarized at the End of the Report*

| HA Number | Management Comments |
|-----------|---------------------|
| 116       |                     |
| 117       |                     |
| 118       |                     |
| 118A      |                     |
| 119       |                     |
| 119A      |                     |
| 12        |                     |
| 120       |                     |
| 120A      |                     |
| 121       |                     |
| 121 A     |                     |
| 122       |                     |
| 122A      |                     |
| 123       |                     |
| 123A      |                     |
| 124       |                     |
| 125       |                     |
| 126       |                     |
| 127       |                     |
| 128       |                     |
| 129       |                     |
| 13        |                     |
| 14        |                     |
| 15        |                     |
| 16        |                     |
| 17        |                     |
| 18        |                     |



# Chicago Public Schools

**School** Schurz High School  
**Address** 3601 N. Milwaukee Ave.

**Unit** 46281  
 Chicago, IL, 60641

**Building ID** 1530  
**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262                      Fax: (312) 733-5612

*Management Planner's Comments Summarized at the End of the Report*

| HA Number | Management Comments |
|-----------|---------------------|
| 19        |                     |
| 20        |                     |
| 21        |                     |
| 22        |                     |
| 23        |                     |
| 24        |                     |
| 25        |                     |
| 26        |                     |
| 27        |                     |
| 28        |                     |
| 29        |                     |
| 30        |                     |
| 31        |                     |
| 32        |                     |
| 33        |                     |
| 34        |                     |
| 35        |                     |
| 36        |                     |
| 37        |                     |
| 38        |                     |
| 39        |                     |
| 40        |                     |
| 41        |                     |
| 42        |                     |
| 43        |                     |
| 44        |                     |
| 45        |                     |

# Chicago Public Schools

**School** Schurz High School  
**Address** 3601 N. Milwaukee Ave.

**Unit** 46281  
 Chicago, IL, 60641

**Building ID** 1530  
**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

*Management Planner's Comments Summarized at the End of the Report*

| HA Number | Management Comments |
|-----------|---------------------|
| 46        |                     |
| 47        |                     |
| 48        |                     |
| 49        |                     |
| 50        |                     |
| 51        |                     |
| 52        |                     |
| 53        |                     |
| 54        |                     |
| 55        |                     |
| 56        |                     |
| 57        |                     |
| 58        |                     |
| 59        |                     |
| 60        |                     |
| 61        |                     |
| 62        |                     |
| 63        |                     |
| 64        |                     |
| 65        |                     |
| 66        |                     |
| 67        |                     |
| 68        |                     |
| 69        |                     |
| 70        |                     |
| 71        |                     |
| 72        |                     |

# Chicago Public Schools

**School** Schurz High School  
**Address** 3601 N. Milwaukee Ave.

**Unit** 46281  
 Chicago, IL, 60641

**Building ID** 1530  
**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

***Management Planner's Comments Summarized at the End of the Report***

| HA Number | Management Comments |
|-----------|---------------------|
| 73        |                     |
| 74        |                     |
| 75        |                     |
| 76        |                     |
| 77        |                     |
| 78        |                     |
| 79        |                     |
| 80        |                     |
| 81        |                     |
| 82        |                     |
| 83        |                     |
| 84        |                     |
| 85        |                     |
| 86        |                     |
| 87        |                     |
| 88        |                     |
| 89        |                     |
| 90        |                     |
| 91        |                     |
| 92        |                     |
| 93        |                     |
| 94        |                     |
| 95        |                     |
| 96        |                     |
| 97        |                     |
| 98        |                     |
| 99        |                     |

# Chicago Public Schools

**School** Schurz High School  
**Address** 3601 N. Milwaukee Ave.

**Unit** 46281  
 Chicago, IL, 60641

**Building ID** 1530  
**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262                      Fax: (312) 733-5612

***Management Planner's Comments Summarized at the End of the Report***

| HA Number | Management Comments |
|-----------|---------------------|
| AA        |                     |
| BB        |                     |
| CC        |                     |
| DD        |                     |
| E         |                     |
| EE        |                     |
| F         |                     |
| FF        |                     |
| GG        |                     |
| HA-1000   |                     |
| HA-1001   |                     |
| HA-1002   |                     |
| HA-1003   |                     |
| HA-1004   |                     |
| HA-1005   |                     |
| HA-1006   |                     |
| HA-1007   |                     |
| HA-1008   |                     |
| HA-1010   |                     |
| HA-1010m  |                     |
| HA-1011   |                     |
| HH        |                     |
| II        |                     |
| JJ        |                     |

# Chicago Public Schools

**School** Schurz High School

**Unit** 46281

**Building ID** 1530

**Address** 3601 N. Milwaukee Ave.

Chicago, IL, 60641

**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

*Management Planner's Comments Summarized at the End of the Report*

# Chicago Public Schools

GSG Consultants, Inc.

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **01**  
MATERIAL DESCRIPTION: **12"x12" Tan w/ White Streaks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON: **Physical Damage**  
HISTORICAL RESPONSE ACTION: **Repair**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Physical Damage**  
DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Throughout - 1908 (See Hatching Maps); Corridor at Rm 112**  
MATERIAL QUANTITY: **32604** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY:  DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 04/19/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **01**  
MATERIAL DESCRIPTION: **12"x12" Tan w/ White Streaks VFT**  
MATERIAL LOCATION: **Throughout - 1908 (See Hatching Maps); Corridor at Rm 112**  
MATERIAL QUANTITY: **32604** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **225** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **02**  
MATERIAL DESCRIPTION: **9"x9" Brown w/ White Specks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON: **Physical Damage**  
HISTORICAL RESPONSE ACTION: **Repair**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Rm 213, 217, 219, 313, 317, 320, 321 - 1908 Bldg.**

MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not Observed: 320, 321**

Inspector's Signature: \_\_\_\_\_



Date: 04/19/2016



# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **02**  
MATERIAL DESCRIPTION: **9"x9" Brown w/ White Specks VFT**  
MATERIAL LOCATION: **Rm 213, 217, 219, 313, 317, 320, 321 - 1908 Bldg.**  
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **03**  
MATERIAL DESCRIPTION: **Tan w/ Brown Swirls Linoleum**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **5th Fl Band Rm - 1908 Bldg.**  
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 04/19/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **03**  
MATERIAL DESCRIPTION: **Tan w/ Brown Swirls Linoleum**  
MATERIAL LOCATION: **5th FI Band Rm - 1908 Bldg.**  
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **04**  
MATERIAL DESCRIPTION: **12"x12" Tan w/ White Streaks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Throughout - 1908 (See Hatching Maps)**

MATERIAL QUANTITY: **32604**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/19/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **04**  
MATERIAL DESCRIPTION: **12"x12" Tan w/ White Streaks VFT Mastic**  
MATERIAL LOCATION: **Throughout - 1908 (See Hatching Maps)**  
MATERIAL QUANTITY: **32604** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **05**  
MATERIAL DESCRIPTION: **9"x9" Brown w/ White Specks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rm 213, 217, 219, 313, 317, 320, 321 - 1908 Bldg.**  
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **Not Observed: 320, 321**

Inspector's Signature:



Date: **04/19/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **05**  
MATERIAL DESCRIPTION: **9"x9" Brown w/ White Specks VFT Mastic**  
MATERIAL LOCATION: **Rm 213, 217, 219, 313, 317, 320, 321 - 1908 Bldg.**  
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **06**  
MATERIAL DESCRIPTION: **Tan w/ Brown Swirls Linoleum Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **5th Fl Band Rm - 1908 Bldg.**

MATERIAL QUANTITY: **2400**

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/19/2016**



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **06**  
MATERIAL DESCRIPTION: **Tan w/ Brown Swirls Linoleum Mastic**  
MATERIAL LOCATION: **5th FI Band Rm - 1908 Bldg.**  
MATERIAL QUANTITY: **2400** MATERIAL UNITS:  
DAMAGE QUANTITY: **0** DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **07**  
MATERIAL DESCRIPTION: **12"x12" Tan w/ White Streaks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Rm 305, 1st through 3rd Fl Corridor, 3rd Fl Girls Toilet - 1915 Bldg.**  
MATERIAL QUANTITY: **5665** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/19/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **07**  
MATERIAL DESCRIPTION: **12"x12" Tan w/ White Streaks VFT**  
MATERIAL LOCATION: **Rm 305, 1st through 3rd FI Corridor, 3rd FI Girls Toilet - 1915 Bldg.**  
MATERIAL QUANTITY: **5665** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **08**  
MATERIAL DESCRIPTION: **12"x12" Tan w/ White Streaks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rm 305, 1st through 3rd Fl Corridor, 3rd Fl Girls Toilet - 1915 Bldg.**  
MATERIAL QUANTITY: **5665** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 04/19/2016

# Chicago Public Schools

GSG Consultants, Inc.

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **08**  
MATERIAL DESCRIPTION: **12"x12" Tan w/ White Streaks VFT Mastic**  
MATERIAL LOCATION: **Rm 305, 1st through 3rd FI Corridor, 3rd FI Girls Toilet - 1915 Bldg.**  
MATERIAL QUANTITY: **5665** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **09**  
MATERIAL DESCRIPTION: **9"x9" Green w/ White Specks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Rm 301 - 1915 Bldg.**  
MATERIAL QUANTITY: **340** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 04/19/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **09**  
MATERIAL DESCRIPTION: **9"x9" Green w/ White Specks VFT**  
MATERIAL LOCATION: **Rm 301 - 1915 Bldg.**  
MATERIAL QUANTITY: **340** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10**  
MATERIAL DESCRIPTION: **9"x9" Green w/ White Specks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rm 301 - 1915 Bldg.**  
MATERIAL QUANTITY: **340** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/19/2016**



# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **10**  
MATERIAL DESCRIPTION: **9"x9" Green w/ White Specks VFT Mastic**  
MATERIAL LOCATION: **Rm 301 - 1915 Bldg.**  
MATERIAL QUANTITY: **340** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **100**  
MATERIAL DESCRIPTION: **Textured Plaster**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Auditorium - 1923**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/19/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUILDING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **100**  
MATERIAL DESCRIPTION: **Textured Plaster**  
MATERIAL LOCATION: **Auditorium - 1923**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **1009**  
MATERIAL DESCRIPTION: **Boiler #1 (small)**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION:

MATERIAL QUANTITY: **350**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/19/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **1009**  
MATERIAL DESCRIPTION: **Boiler #1 (small)**  
MATERIAL LOCATION:  
MATERIAL QUANTITY: **350** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **101**  
MATERIAL DESCRIPTION: **Undetermined Size & Color VFT**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Fourth Floor Corridor (Underneath HA # 59 & 60) - 1908**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUILDING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **101**  
MATERIAL DESCRIPTION: **Undetermined Size & Color VFT**  
MATERIAL LOCATION: **Fourth Floor Corridor (Underneath HA # 59 & 60) - 1908**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 05/17/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUILDING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **102**  
MATERIAL DESCRIPTION: **Undetermined Size & Color VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Fourth Floor Corridor (Underneath HA # 59 & 60) - 1908**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/19/2016**



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **102**  
MATERIAL DESCRIPTION: **Undetermined Size & Color VFT Mastic**  
MATERIAL LOCATION: **Fourth Floor Corridor (Underneath HA # 59 & 60) - 1908**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 05/17/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **103**  
MATERIAL DESCRIPTION: **MJP E/F/V on Fiberglass Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st Floor Men's Faculty Toliet, 2nd & 3rd Floor Girls Toliets (chases) - 1908**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/19/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUILDING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **103**  
MATERIAL DESCRIPTION: **MJP E/F/V on Fiberglass Pipe Insulation**  
MATERIAL LOCATION: **1st Floor Men's Faculty Toilet, 2nd & 3rd Floor Girls Toilets (chases) - 1908**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **104**  
MATERIAL DESCRIPTION: **Green Linoleum**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Room 320, 369, Prep Room, Storage Room - 1923**  
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **Not Observed: Room 320**

Inspector's Signature:



Date: **04/19/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **104**  
MATERIAL DESCRIPTION: **Green Linoleum**  
MATERIAL LOCATION: **Room 320, 369, Prep Room, Storage Room - 1923**  
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **105**  
MATERIAL DESCRIPTION: **Green Linoleum Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 320, 369, Prep Room, Storage Room - 1923**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **Not Observed: Room 320**

Inspector's Signature:



Date: **04/19/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **105**  
MATERIAL DESCRIPTION: **Green Linoleum Mastic**  
MATERIAL LOCATION: **Room 320, 369, Prep Room, Storage Room - 1923**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **106**  
MATERIAL DESCRIPTION: **2" x 2" Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 320, 369, Prep Room, Storage Room - 1923**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/19/2016**



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **106**  
MATERIAL DESCRIPTION: **2" x 2" Ceiling Tile**  
MATERIAL LOCATION: **Room 320, 369, Prep Room, Storage Room - 1923**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **107**  
MATERIAL DESCRIPTION: **12" x 12" Gray w/ White Speck VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Room 216 - 1908**  
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/19/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **107**  
MATERIAL DESCRIPTION: **12" x 12" Gray w/ White Speck VFT**  
MATERIAL LOCATION: **Room 216 - 1908**  
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **108**  
MATERIAL DESCRIPTION: **12" x 12" Gray w/ White Speck VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 216 - 1908**  
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 04/19/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **108**  
MATERIAL DESCRIPTION: **12" x 12" Gray w/ White Speck VFT Mastic**  
MATERIAL LOCATION: **Room 216 - 1908**  
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **109**  
MATERIAL DESCRIPTION: **12" x 12" Orange Cork VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Library - 1908**  
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 04/19/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **109**  
MATERIAL DESCRIPTION: **12" x 12" Orange Cork VFT**  
MATERIAL LOCATION: **Library - 1908**  
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11**  
MATERIAL DESCRIPTION: **12"x12" Tan w/ White Streaks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON: **Deterioration**  
HISTORICAL RESPONSE ACTION: **Repair**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Deterioration**  
DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Throughout - 1923 (See Hatching Maps)**  
MATERIAL QUANTITY: **18061** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **18061** DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 04/19/2016



# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **11**  
MATERIAL DESCRIPTION: **12"x12" Tan w/ White Streaks VFT**  
MATERIAL LOCATION: **Throughout - 1923 (See Hatching Maps)**  
MATERIAL QUANTITY: **18061** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **35** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **110**  
MATERIAL DESCRIPTION: **12" x 12" Orange Cork VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Library - 1908**  
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 04/19/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **110**  
MATERIAL DESCRIPTION: **12" x 12" Orange Cork VFT Mastic**  
MATERIAL LOCATION: **Library - 1908**  
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **111**  
MATERIAL DESCRIPTION: **Carpet Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Library - 1908**  
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/19/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUILDING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **111**  
MATERIAL DESCRIPTION: **Carpet Mastic**  
MATERIAL LOCATION: **Library - 1908**  
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **112**  
MATERIAL DESCRIPTION: **Carpet Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Main Office, Nurse Office 128, 125A, 114, 110, 115, Teacher/Staff Room, 376**  
MATERIAL QUANTITY: **4934** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 04/19/2016

# Chicago Public Schools

GSG Consultants, Inc.

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **112**  
MATERIAL DESCRIPTION: **Carpet Adhesive**  
MATERIAL LOCATION: **Main Office, Nurse Office 128, 125A, 114, 110, 115, Teacher/Staff Room, 376**  
MATERIAL QUANTITY: **4934** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **113**  
MATERIAL DESCRIPTION: **12"X12" Powder-Blue w/White and Blue Streaks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Rm 309 -1915 Addition**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 04/19/2016



# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **113**  
MATERIAL DESCRIPTION: **12"X12" Powder-Blue w/White and Blue Streaks VFT**  
MATERIAL LOCATION: **Rm 309 -1915 Addition**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **113M**  
MATERIAL DESCRIPTION: **12"X12" Powder-Blue w/White and Blue Streaks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rm 309 -1915 Addition**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 04/19/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **113M**  
MATERIAL DESCRIPTION: **12"X12" Powder-Blue w/White and Blue Streaks VFT Mastic**  
MATERIAL LOCATION: **Rm 309 -1915 Addition**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **114**  
MATERIAL DESCRIPTION: **VFT 12 X 12 Tan w/ white specs w/ Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 205**  
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 04/19/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **114**  
MATERIAL DESCRIPTION: **VFT 12 X 12 Tan w/ white specs w/ Mastic**  
MATERIAL LOCATION: **Room 205**  
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **115**  
MATERIAL DESCRIPTION: **Carpet Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 110, 128, 111, 119, 300**  
MATERIAL QUANTITY: **2600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **115**  
MATERIAL DESCRIPTION: **Carpet Mastic**  
MATERIAL LOCATION: **Room 110, 128, 111, 119, 300**  
MATERIAL QUANTITY: **2600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **116**  
MATERIAL DESCRIPTION: **Lab Black Counter Tops**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 315, 313, 219, 215, 213, 223, 225, 229**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/19/2016**



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **116**  
MATERIAL DESCRIPTION: **Lab Black Counter Tops**  
MATERIAL LOCATION: **Rooms 315, 313, 219, 215, 213, 223, 225, 229**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **117**  
MATERIAL DESCRIPTION: **Lab Black Table Tops**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 315, 313, 219, 215, 213, 223, 225, 229**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/19/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **117**  
MATERIAL DESCRIPTION: **Lab Black Table Tops**  
MATERIAL LOCATION: **Rooms 315, 313, 219, 215, 213, 223, 225, 229**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **118**  
MATERIAL DESCRIPTION: **VFT 12 X 12 Tan w/ Large White Striations**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Rooms 220, 305, 308, 310, 320, 321, 322, 332, 353, 355, 361, 358, 364, 368, 377, 379, 381, 324, 351, 363, 372, 374, 376, 327, 221, 125, 105 & 108**

MATERIAL QUANTITY: **21000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/19/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUILDING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **118**  
MATERIAL DESCRIPTION: **VFT 12 X 12 Tan w/ Large White Striations**  
MATERIAL LOCATION: **Rooms 220, 305, 308, 310, 320, 321, 322, 332, 353, 355, 361, 358, 364, 368, 377, 379, 381, 324, 351, 363, 372, 374, 376, 327, 221, 125, 105 & 108**  
MATERIAL QUANTITY: **21000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **118A**  
MATERIAL DESCRIPTION: **12 X 12 Tan w/ Large White Striations w/ Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 220, 305, 308, 310, 320, 321, 322, 332, 353, 355, 361, 358, 364, 368, 377, 379, 381, 324, 351, 363, 372, 374, 376, 327, 221, 125, 105 & 108**

MATERIAL QUANTITY: **21000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 04/19/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **118A**  
MATERIAL DESCRIPTION: **12 X 12 Tan w/ Large White Striations w/ Mastic**  
MATERIAL LOCATION: **Rooms 220, 305, 308, 310, 320, 321, 322, 332, 353, 355, 361, 358, 364, 368, 377, 379,381, 324, 351, 363, 372, 374, 376, 327, 221, 125, 105 & 108**  
MATERIAL QUANTITY: **21000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **119**  
MATERIAL DESCRIPTION: **VFT 12 X 12 Light blue w/ gray & white specs**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Rooms 219, 217, 213, 123, 122, 323, 229, 227, 223, 225, 309 & 371**  
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **Not Observes: Room 323**

Inspector's Signature:



Date: **04/19/2016**



# Chicago Public Schools

GSG Consultants, Inc.

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **119**  
MATERIAL DESCRIPTION: **VFT 12 X 12 Light blue w/ gray & white specs**  
MATERIAL LOCATION: **Rooms 219, 217, 213, 123, 122, 323, 229, 227, 223, 225, 309 & 371**  
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **119A**  
MATERIAL DESCRIPTION: **12 x 12 Light Blue w/ gray & white specs w/ Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 219, 217, 213, 123, 122, 323, 229, 227, 223, 225, 309 & 371**  
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **Not Observes: Room 323**

Inspector's Signature: \_\_\_\_\_



Date: 04/19/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **119A**  
MATERIAL DESCRIPTION: **12 x 12 Light Blue w/ gray & white specs w/ Mastic**  
MATERIAL LOCATION: **Rooms 219, 217, 213, 123, 122, 323, 229, 227, 223, 225, 309 & 371**  
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12**  
MATERIAL DESCRIPTION: **12"x12" Tan w/ White Streaks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Throughout - 1923 (See Hatching Maps)**

MATERIAL QUANTITY: **18061**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/19/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **12**  
MATERIAL DESCRIPTION: **12"x12" Tan w/ White Streaks VFT Mastic**  
MATERIAL LOCATION: **Throughout - 1923 (See Hatching Maps)**  
MATERIAL QUANTITY: **18061** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **120**  
MATERIAL DESCRIPTION: **VFT 12 X 12 White w/ Tan Streaks**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Rooms 311, 336, 338, 334, 129, 131**  
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 04/19/2016

# Chicago Public Schools

GSG Consultants, Inc.

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **120**  
MATERIAL DESCRIPTION: **VFT 12 X 12 White w/ Tan Streaks**  
MATERIAL LOCATION: **Rooms 311, 336, 338, 334, 129, 131**  
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **120A**  
MATERIAL DESCRIPTION: **12 x 12 white w/ Tan Streaks w/ Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 311, 336, 338, 334, 129, 131**  
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/19/2016**



# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **120A**  
MATERIAL DESCRIPTION: **12 x 12 white w/ Tan Streaks w/ Mastic**  
MATERIAL LOCATION: **Rooms 311, 336, 338, 334, 129, 131**  
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **121**  
MATERIAL DESCRIPTION: **VFT 12 x 12 White w/ greens & gray streaks**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Rooms 312, 314**  
MATERIAL QUANTITY: **2200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 04/19/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **121**  
MATERIAL DESCRIPTION: **VFT 12 x 12 White w/ greens & gray streaks**  
MATERIAL LOCATION: **Rooms 312, 314**  
MATERIAL QUANTITY: **2200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **121 A**  
MATERIAL DESCRIPTION: **12 x 12 White w/ Green & Gray Streaks w/ Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 312, 314**  
MATERIAL QUANTITY: **2200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 04/19/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **121 A**  
MATERIAL DESCRIPTION: **12 x 12 White w/ Green & Gray Streaks w/ Mastic**  
MATERIAL LOCATION: **Rooms 312, 314**  
MATERIAL QUANTITY: **2200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **122**  
MATERIAL DESCRIPTION: **VFT 12 X 12 Tan w/ white Streaks**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Room 116**  
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 04/19/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **122**  
MATERIAL DESCRIPTION: **VFT 12 X 12 Tan w/ white Streaks**  
MATERIAL LOCATION: **Room 116**  
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **122A**  
MATERIAL DESCRIPTION: **12 X 12 Tan w/ White Streaks Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 116**  
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 04/19/2016



# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **122A**  
MATERIAL DESCRIPTION: **12 X 12 Tan w/ White Streaks Mastic**  
MATERIAL LOCATION: **Room 116**  
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **123**  
MATERIAL DESCRIPTION: **Tan Linoleum w/ white & black streaks**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Room 315**  
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/19/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **123**  
MATERIAL DESCRIPTION: **Tan Linoleum w/ white & black streaks**  
MATERIAL LOCATION: **Room 315**  
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **123A**  
MATERIAL DESCRIPTION: **Tan Linoleum w/ white & black streaks w/ Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 315**  
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 04/19/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **123A**  
MATERIAL DESCRIPTION: **Tan Linoleum w/ white & black streaks w/ Mastic**  
MATERIAL LOCATION: **Room 315**  
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13**  
MATERIAL DESCRIPTION: **9"x9" Cocoa w/ White & Brown Streaks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Rooms 223, 225, 227, 359, 365, 367, 371 - 1923 Bldg**  
MATERIAL QUANTITY: **7260** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 04/19/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **13**  
MATERIAL DESCRIPTION: **9"x9" Cocoa w/ White & Brown Streaks VFT**  
MATERIAL LOCATION: **Rooms 223, 225, 227, 359, 365, 367, 371 - 1923 Bldg**  
MATERIAL QUANTITY: **7260** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14**  
MATERIAL DESCRIPTION: **9"x9" Cocoa w/ White & Brown Streaks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 223, 225, 227, 359, 365, 367, 371 - 1923 Bldg**  
MATERIAL QUANTITY: **7260** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 04/19/2016



# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **14**  
MATERIAL DESCRIPTION: **9"x9" Cocoa w/ White & Brown Streaks VFT Mastic**  
MATERIAL LOCATION: **Rooms 223, 225, 227, 359, 365, 367, 371 - 1923 Bldg**  
MATERIAL QUANTITY: **7260** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15**  
MATERIAL DESCRIPTION: **Brown Linoleum**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Gymnasium Office - 1915**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/19/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUILDING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **15**  
MATERIAL DESCRIPTION: **Brown Linoleum**  
MATERIAL LOCATION: **Gymnasium Office - 1915**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 05/17/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16**  
MATERIAL DESCRIPTION: **Brown Linoleum Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Gymnasium Office - 1915**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **16**  
MATERIAL DESCRIPTION: **Brown Linoleum Mastic**  
MATERIAL LOCATION: **Gymnasium Office - 1915**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17**  
MATERIAL DESCRIPTION: **12"x12" White w/ Light Brown Streaks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Room 309 - 1915 Bldg**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **17**  
MATERIAL DESCRIPTION: **12"x12" White w/ Light Brown Streaks VFT**  
MATERIAL LOCATION: **Room 309 - 1915 Bldg**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18**  
MATERIAL DESCRIPTION: **12"x12" White w/ Light Brown Streaks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 309 - 1915 Bldg**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/19/2016**



# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **18**  
MATERIAL DESCRIPTION: **12"x12" White w/ Light Brown Streaks VFT Mastic**  
MATERIAL LOCATION: **Room 309 - 1915 Bldg**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19**  
MATERIAL DESCRIPTION: **9"x9" Red w/ Black & White Specks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Room 301 - 1915 Bldg**

MATERIAL QUANTITY: **340**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 04/19/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **19**  
MATERIAL DESCRIPTION: **9"x9" Red w/ Black & White Specks VFT**  
MATERIAL LOCATION: **Room 301 - 1915 Bldg**  
MATERIAL QUANTITY: **340** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**  
MATERIAL DESCRIPTION: **9"x9" Red w/ Black & White Specks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 301 - 1915 Bldg**  
MATERIAL QUANTITY: **340** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/19/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **20**  
MATERIAL DESCRIPTION: **9"x9" Red w/ Black & White Specks VFT Mastic**  
MATERIAL LOCATION: **Room 301 - 1915 Bldg**  
MATERIAL QUANTITY: **340** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21**  
MATERIAL DESCRIPTION: **9"x9" Brown w/ White & Black Streaks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Room 301 - 1915 Bldg**

MATERIAL QUANTITY: **20**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 04/19/2016

# Chicago Public Schools

GSG Consultants, Inc.

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **21**  
MATERIAL DESCRIPTION: **9"x9" Brown w/ White & Black Streaks VFT**  
MATERIAL LOCATION: **Room 301 - 1915 Bldg**  
MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22**  
MATERIAL DESCRIPTION: **9"x9" Brown w/ White & Black Streaks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 301 - 1915 Bldg**  
MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/19/2016**



# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **22**  
MATERIAL DESCRIPTION: **9"x9" Brown w/ White & Black Streaks VFT Mastic**  
MATERIAL LOCATION: **Room 301 - 1915 Bldg**  
MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23**  
MATERIAL DESCRIPTION: **24" X 6" Black VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Room 301 - 1915 Bldg**  
MATERIAL QUANTITY: **70** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 04/19/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **23**  
MATERIAL DESCRIPTION: **24" X 6" Black VFT**  
MATERIAL LOCATION: **Room 301 - 1915 Bldg**  
MATERIAL QUANTITY: **70** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **24**  
MATERIAL DESCRIPTION: **24" X 6" Black VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 301 - 1915 Bldg**  
MATERIAL QUANTITY: **70** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **24**  
MATERIAL DESCRIPTION: **24" X 6" Black VFT Mastic**  
MATERIAL LOCATION: **Room 301 - 1915 Bldg**  
MATERIAL QUANTITY: **70** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25**  
MATERIAL DESCRIPTION: **12"x12" Beige w/ Brown & White Streaks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Room 308 - 1915**  
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/19/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **25**  
MATERIAL DESCRIPTION: **12"x12" Beige w/ Brown & White Streaks VFT**  
MATERIAL LOCATION: **Room 308 - 1915**  
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26**  
MATERIAL DESCRIPTION: **12"x 12" Beige w/ Brown & White Streaks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 308 - 1915**  
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 04/19/2016



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUILDING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **26**  
MATERIAL DESCRIPTION: **12"x 12" Beige w/ Brown & White Streaks VFT Mastic**  
MATERIAL LOCATION: **Room 308 - 1915**  
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27**  
MATERIAL DESCRIPTION: **12"x12" Brown w/ White Specks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON: **Physical Damage**  
HISTORICAL RESPONSE ACTION: **Repair**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Physical Damage**  
DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **1st, 2nd, & 3rd Floor Corridors - 1915**  
MATERIAL QUANTITY: **1150** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **1150** DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 04/19/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **27**  
MATERIAL DESCRIPTION: **12"x12" Brown w/ White Specks VFT**  
MATERIAL LOCATION: **1st, 2nd, & 3rd Floor Corridors - 1915**  
MATERIAL QUANTITY: **1150** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **40** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28**  
MATERIAL DESCRIPTION: **12"x12" Brown w/ White Specks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st, 2nd, & 3rd Floor Corridors - 1915**  
MATERIAL QUANTITY: **1150** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/19/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **28**  
MATERIAL DESCRIPTION: **12"x12" Brown w/ White Specks VFT Mastic**  
MATERIAL LOCATION: **1st, 2nd, & 3rd Floor Corridors - 1915**  
MATERIAL QUANTITY: **1150** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 46281 BUIDLING ID: 1530  
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: David Avila  
SCHOOL NAME: Schurz High School INSPECTION DATE: 4/19/2016  
ADDRESS: 3601 N. Milwaukee Ave. IDPH LICENSE NO: 100-11093

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 29  
MATERIAL DESCRIPTION: 12"x12" Gray w/ White Streaks VFT  
HISTORICAL AHERA DAMAGE CATEGORY 6  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: Assumed FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: MODERATE

MATERIAL LOCATION: Gymnasium/205 - 1915

MATERIAL QUANTITY: 1600

MATERIAL UNITS: SF

DAMAGE QUANTITY:

DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature:



Date: 04/19/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUILDING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **29**  
MATERIAL DESCRIPTION: **12"x12" Gray w/ White Streaks VFT**  
MATERIAL LOCATION: **Gymnasium/205 - 1915**  
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 46281 BUIDLING ID: 1530  
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: David Avila  
SCHOOL NAME: Schurz High School INSPECTION DATE: 4/19/2016  
ADDRESS: 3601 N. Milwaukee Ave. IDPH LICENSE NO: 100-11093

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 30  
MATERIAL DESCRIPTION: 12"x12" Gray w/ White Streaks VFT Mastic  
HISTORICAL AHERA DAMAGE CATEGORY 6  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: Assumed FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Gymnasium/205 - 1915**

MATERIAL QUANTITY: **1600**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 04/19/2016



# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUILDING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **30**  
MATERIAL DESCRIPTION: **12"x12" Gray w/ White Streaks VFT Mastic**  
MATERIAL LOCATION: **Gymnasium/205 - 1915**  
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **31**  
MATERIAL DESCRIPTION: **12"x12" Beige w/ White & Orange Streaks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Room 310 and 341 - 1923**  
MATERIAL QUANTITY: **1810** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 04/19/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **31**  
MATERIAL DESCRIPTION: **12"x12" Beige w/ White & Orange Streaks VFT**  
MATERIAL LOCATION: **Room 310 and 341 - 1923**  
MATERIAL QUANTITY: **1810** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **32**  
MATERIAL DESCRIPTION: **12"x12" Beige w/ White & Orange Streaks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 310 and 341 - 1923**  
MATERIAL QUANTITY: **1810** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 04/19/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **32**  
MATERIAL DESCRIPTION: **12"x12" Beige w/ White & Orange Streaks VFT Mastic**  
MATERIAL LOCATION: **Room 310 and 341 - 1923**  
MATERIAL QUANTITY: **1810** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **33**  
MATERIAL DESCRIPTION: **9"x9" Cocoa w/ White & Brown Short Streaks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **3rd Floor Hallway - 1923**  
MATERIAL QUANTITY: **3324** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 04/19/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUILDING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **33**  
MATERIAL DESCRIPTION: **9"x9" Cocoa w/ White & Brown Short Streaks VFT**  
MATERIAL LOCATION: **3rd Floor Hallway - 1923**  
MATERIAL QUANTITY: **3324** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **34**  
MATERIAL DESCRIPTION: **9"x9" Cocoa w/ White & Brn Short Strks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **3rd Floor Hallway - 1923**  
MATERIAL QUANTITY: **3324** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 04/19/2016



# Chicago Public Schools

GSG Consultants, Inc.

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **34**  
MATERIAL DESCRIPTION: **9"x9" Cocoa w/ White & Brn Short Strks VFT Mastic**  
MATERIAL LOCATION: **3rd Floor Hallway - 1923**  
MATERIAL QUANTITY: **3324** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **35**  
MATERIAL DESCRIPTION: **12"x 12" Cocoa w/ White & Brown Long Streaks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON: **Other**  
HISTORICAL RESPONSE ACTION: **Repair**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 253 - 1923**

MATERIAL QUANTITY: **924**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 04/19/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **35**  
MATERIAL DESCRIPTION: **12"x 12" Cocoa w/ White & Brown Long Streaks VFT**  
MATERIAL LOCATION: **Room 253 - 1923**  
MATERIAL QUANTITY: **924** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **36**  
MATERIAL DESCRIPTION: **12"x12" Cocoa w/ Wht. & Brwn. Lng Strks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 253 - 1923**  
MATERIAL QUANTITY: **924** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 04/19/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **36**  
MATERIAL DESCRIPTION: **12"x12" Cocoa w/ Wht. & Brwn. Lng Strks VFT Mastic**  
MATERIAL LOCATION: **Room 253 - 1923**  
MATERIAL QUANTITY: **924** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37**  
MATERIAL DESCRIPTION: **12"x12" Gray w/ White & Gray Streaks VFT ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Teachers Room Next to Cafeteria - 1923 ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 04/19/2016

# Chicago Public Schools

GSG Consultants, Inc.

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **37**  
MATERIAL DESCRIPTION: **12"x12" Gray w/ White & Gray Streaks VFT ABATED**  
MATERIAL LOCATION: **Teachers Room Next to Cafeteria - 1923 ABATED**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **38**  
MATERIAL DESCRIPTION: **12"x12" Gray w/ White & Gray Streaks VFT Mastic ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Teachers Room Next to Cafeteria - 1923 ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/19/2016**



# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **38**  
MATERIAL DESCRIPTION: **12"x12" Gray w/ White & Gray Streaks VFT Mastic ABATED**  
MATERIAL LOCATION: **Teachers Room Next to Cafeteria - 1923 ABATED**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **39**  
MATERIAL DESCRIPTION: **9"x9" Pine Green w/ White Streaks VFT ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON: **Deterioration**  
HISTORICAL RESPONSE ACTION: **Repair**  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Cafeteria - 1923 ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **39**  
MATERIAL DESCRIPTION: **9"x9" Pine Green w/ White Streaks VFT ABATED**  
MATERIAL LOCATION: **Cafeteria - 1923 ABATED**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **40**  
MATERIAL DESCRIPTION: **9"x9" Pine Green w/ White Streaks VFT Mastic ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Cafeteria - 1923 ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/19/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUILDING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **40**  
MATERIAL DESCRIPTION: **9"x9" Pine Green w/ White Streaks VFT Mastic ABATED**  
MATERIAL LOCATION: **Cafeteria - 1923 ABATED**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **41**  
MATERIAL DESCRIPTION: **9"x9" White w/ Pine Green Streaks VFT ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON: **Deterioration**  
HISTORICAL RESPONSE ACTION: **Repair**  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Cafeteria - 1923 ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **41**  
MATERIAL DESCRIPTION: **9"x9" White w/ Pine Green Streaks VFT ABATED**  
MATERIAL LOCATION: **Cafeteria - 1923 ABATED**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **42**  
MATERIAL DESCRIPTION: **9"x9" White w/ Pine Green Streaks VFT Mastic ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Cafeteria - 1923 ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/19/2016**



# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUILDING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **42**  
MATERIAL DESCRIPTION: **9"x9" White w/ Pine Green Streaks VFT Mastic ABATED**  
MATERIAL LOCATION: **Cafeteria - 1923 ABATED**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **43**  
MATERIAL DESCRIPTION: **9"x9" Forest Green VFT ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Cafeteria - 1923 ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUILDING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **43**  
MATERIAL DESCRIPTION: **9"x9" Forest Green VFT ABATED**  
MATERIAL LOCATION: **Cafeteria - 1923 ABATED**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **44**  
MATERIAL DESCRIPTION: **9"x9" Forest Green VFT Mastic ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Cafeteria - 1923 ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/19/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **44**  
MATERIAL DESCRIPTION: **9"x9" Forest Green VFT Mastic ABATED**  
MATERIAL LOCATION: **Cafeteria - 1923 ABATED**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **45**  
MATERIAL DESCRIPTION: **9"x9" Gray w/ White Streaks VFT ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Cafeteria - 1923 ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/19/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **45**  
MATERIAL DESCRIPTION: **9"x9" Gray w/ White Streaks VFT ABATED**  
MATERIAL LOCATION: **Cafeteria - 1923 ABATED**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **46**  
MATERIAL DESCRIPTION: **9"x9" Gray w/ White Streaks VFT Mastic ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Cafeteria - 1923 ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/19/2016**



# Chicago Public Schools

GSG Consultants, Inc.

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **46**

MATERIAL DESCRIPTION: **9"x9" Gray w/ White Streaks VFT Mastic ABATED**

MATERIAL LOCATION: **Cafeteria - 1923 ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **47**  
MATERIAL DESCRIPTION: **Brown Linoleum**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Teacher's Rest Area & Room 376 - 1923 NOT OBSERVED**  
MATERIAL QUANTITY: **504** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **Possibly under the carpet (2016)**

Inspector's Signature: \_\_\_\_\_



Date: 04/19/2016

# Chicago Public Schools

GSG Consultants, Inc.

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUILDING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **47**  
MATERIAL DESCRIPTION: **Brown Linoleum**  
MATERIAL LOCATION: **Teacher's Rest Area & Room 376 - 1923 NOT OBSERVED**  
MATERIAL QUANTITY: **504** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **48**  
MATERIAL DESCRIPTION: **Brown Linoleum Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Teacher's Rest Area & Room 376 - 1923**

MATERIAL QUANTITY: **504**

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Possibly under the carpet (2016)**

Inspector's Signature:



Date: **04/19/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUILDING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **48**  
MATERIAL DESCRIPTION: **Brown Linoleum Mastic**  
MATERIAL LOCATION: **Teacher's Rest Area & Room 376 - 1923**  
MATERIAL QUANTITY: **504** MATERIAL UNITS:  
DAMAGE QUANTITY: **0** DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **49**  
MATERIAL DESCRIPTION: **12"x12" White w/ Blue Speckles VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Room 110 - 1923 Bldg**

MATERIAL QUANTITY: **900**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **49**  
MATERIAL DESCRIPTION: **12"x12" White w/ Blue Speckles VFT**  
MATERIAL LOCATION: **Room 110 - 1923 Bldg**  
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 46281    BUILDING ID: 1530  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: David Avila  
SCHOOL NAME: Schurz High School    INSPECTION DATE: 4/19/2016  
ADDRESS: 3601 N. Milwaukee Ave.    IDPH LICENSE NO: 100-11093

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 50  
MATERIAL DESCRIPTION: 12"x12" White w/ Blue Speckles VFT Mastic  
HISTORICAL AHERA DAMAGE CATEGORY 6  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Room 110 - 1923 Bldg  
MATERIAL QUANTITY: 900    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature:



Date: 04/19/2016



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **50**  
MATERIAL DESCRIPTION: **12"x12" White w/ Blue Speckles VFT Mastic**  
MATERIAL LOCATION: **Room 110 - 1923 Bldg**  
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **51**  
MATERIAL DESCRIPTION: **12"x12" Beige w/ Dark Brown Speckles VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Engineer's Office, Room 342 - 1923**

MATERIAL QUANTITY: **1800**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/19/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUILDING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **51**  
MATERIAL DESCRIPTION: **12"x12" Beige w/ Dark Brown Speckles VFT**  
MATERIAL LOCATION: **Engineer's Office, Room 342 - 1923**  
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 05/17/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **52**  
MATERIAL DESCRIPTION: **12"x12" Beige w/ Dark Brown Speckles VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Engineer's Office, Room 342 - 1923**

MATERIAL QUANTITY: **1800**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 04/19/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **52**  
MATERIAL DESCRIPTION: **12"x12" Beige w/ Dark Brown Speckles VFT Mastic**  
MATERIAL LOCATION: **Engineer's Office, Room 342 - 1923**  
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **53**  
MATERIAL DESCRIPTION: **12"x12" White w/ Tan Spots VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **334, 336, 338, 340 - 1923 Bldg**  
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 04/19/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **53**  
MATERIAL DESCRIPTION: **12"x12" White w/ Tan Spots VFT**  
MATERIAL LOCATION: **334, 336, 338, 340 - 1923 Bldg**  
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **54**  
MATERIAL DESCRIPTION: **12"x12" White w/ Tan Spots VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **334, 336, 338, 340 - 1923 Bldg**  
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/19/2016**



# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **54**  
MATERIAL DESCRIPTION: **12"x12" White w/ Tan Spots VFT Mastic**  
MATERIAL LOCATION: **334, 336, 338, 340 - 1923 Bldg**  
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **55**  
MATERIAL DESCRIPTION: **12"x12" Gray w/ White & Brown Spots VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON: **Other**  
HISTORICAL RESPONSE ACTION: **Repair**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Other**  
DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Rooms 212, 340, 315 - 1923 Bldg**  
MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **1100** DAMAGE UNITS: **SF**  
COMMENTS: **Not Observed: Room 315**

Inspector's Signature: \_\_\_\_\_



Date: 04/19/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **55**  
MATERIAL DESCRIPTION: **12"x12" Gray w/ White & Brown Spots VFT**  
MATERIAL LOCATION: **Rooms 212, 340, 315 - 1923 Bldg**  
MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **300** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair**

Comments:

Management Planner's Signature:  Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **56**  
MATERIAL DESCRIPTION: **12"x12" Gray w/ White & Brown Spots VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON: **Other**  
HISTORICAL RESPONSE ACTION: **Repair**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Other**  
DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 212, 340, 315 - 1923 Bldg**  
MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **1100** DAMAGE UNITS: **SF**  
COMMENTS: **Not Observed: Room 315**

Inspector's Signature: \_\_\_\_\_



Date: 04/19/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **56**  
MATERIAL DESCRIPTION: **12"x12" Gray w/ White & Brown Spots VFT Mastic**  
MATERIAL LOCATION: **Rooms 212, 340, 315 - 1923 Bldg**  
MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **300** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **57**  
MATERIAL DESCRIPTION: **9"x9" Gray VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Room 128 - 1923 NOT OBSERVED**  
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **NOT OBSERVED**

Inspector's Signature: \_\_\_\_\_



Date: 04/19/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **57**  
MATERIAL DESCRIPTION: **9"x9" Gray VFT**  
MATERIAL LOCATION: **Room 128 - 1923 NOT OBSERVED**  
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **58**  
MATERIAL DESCRIPTION: **9"x9" Gray VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 128 - 1923 NOT OBSERVED**  
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **NOT OBSERVED**

Inspector's Signature: \_\_\_\_\_



Date: 04/19/2016



# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **58**  
MATERIAL DESCRIPTION: **9"x9" Gray VFT Mastic**  
MATERIAL LOCATION: **Room 128 - 1923 NOT OBSERVED**  
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **59**  
MATERIAL DESCRIPTION: **12"x12" Brown w/ White Specks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **1st Floor through 4th Floor Corridors - 1908**  
MATERIAL QUANTITY: **4900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 04/19/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **59**  
MATERIAL DESCRIPTION: **12"x12" Brown w/ White Specks VFT**  
MATERIAL LOCATION: **1st Floor through 4th Floor Corridors - 1908**  
MATERIAL QUANTITY: **4900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **60**  
MATERIAL DESCRIPTION: **12"x12" Brown w/ White Specks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st Floor through 4th Floor Corridors - 1908**  
MATERIAL QUANTITY: **4900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **60**  
MATERIAL DESCRIPTION: **12"x12" Brown w/ White Specks VFT Mastic**  
MATERIAL LOCATION: **1st Floor through 4th Floor Corridors - 1908**  
MATERIAL QUANTITY: **4900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **61**  
MATERIAL DESCRIPTION: **12"x12" White w/ Gray Streaks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Repair**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Main Office, Room 315, Room 117 - 1908**

MATERIAL QUANTITY: **2500**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Not Observed: Room 315**

Inspector's Signature:



Date: **04/19/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **61**  
MATERIAL DESCRIPTION: **12"x12" White w/ Gray Streaks VFT**  
MATERIAL LOCATION: **Main Office, Room 315, Room 117 - 1908**  
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **25** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **62**  
MATERIAL DESCRIPTION: **12"x12" White w/ Gray Streaks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Main Office, Room 315, Room 117 - 1908**  
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **Not Observed: Room 315**

Inspector's Signature: \_\_\_\_\_



Date: 04/19/2016



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **62**  
MATERIAL DESCRIPTION: **12"x12" White w/ Gray Streaks VFT Mastic**  
MATERIAL LOCATION: **Main Office, Room 315, Room 117 - 1908**  
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **63**  
MATERIAL DESCRIPTION: **9'x9" Beige w/ Brown & White Streaks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Room 316 - 1908**  
MATERIAL QUANTITY: **350** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **63**  
MATERIAL DESCRIPTION: **9'x9" Beige w/ Brown & White Streaks VFT**  
MATERIAL LOCATION: **Room 316 - 1908**  
MATERIAL QUANTITY: **350** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **64**  
MATERIAL DESCRIPTION: **9'x9" Beige w/ Brown & White Streaks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 316 - 1908**  
MATERIAL QUANTITY: **350** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/19/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **64**  
MATERIAL DESCRIPTION: **9'x9" Beige w/ Brown & White Streaks VFT Mastic**  
MATERIAL LOCATION: **Room 316 - 1908**  
MATERIAL QUANTITY: **350** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **65**  
MATERIAL DESCRIPTION: **12"x12" White w/ Tan Specks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 312 - 1908 NOT OBSERVED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **NOT OBSERVED (2016)**

Inspector's Signature:



Date: **04/19/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **65**  
MATERIAL DESCRIPTION: **12"x12" White w/ Tan Specks VFT**  
MATERIAL LOCATION: **Room 312 - 1908 NOT OBSERVED**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **66**  
MATERIAL DESCRIPTION: **12"x12" White w/ Tan Specks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 312 - 1908 NOT OBSERVED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **NOT OBSERVED**

Inspector's Signature:



Date: **04/19/2016**



# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUILDING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **66**  
MATERIAL DESCRIPTION: **12"x12" White w/ Tan Specks VFT Mastic**  
MATERIAL LOCATION: **Room 312 - 1908 NOT OBSERVED**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 05/17/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **67**  
MATERIAL DESCRIPTION: **12"x12" Tan w/ Tan Specks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 322 - 1908**  
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 04/19/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **67**  
MATERIAL DESCRIPTION: **12"x12" Tan w/ Tan Specks VFT**  
MATERIAL LOCATION: **Room 322 - 1908**  
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **68**  
MATERIAL DESCRIPTION: **12"x12" Tan w/ Tan Specks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 322 - 1908**  
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 04/19/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUILDING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **68**  
MATERIAL DESCRIPTION: **12"x12" Tan w/ Tan Specks VFT Mastic**  
MATERIAL LOCATION: **Room 322 - 1908**  
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **69**  
MATERIAL DESCRIPTION: **9"x9" Green w/ White Streaks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Room 114 - 1908**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/19/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **69**  
MATERIAL DESCRIPTION: **9"x9" Green w/ White Streaks VFT**  
MATERIAL LOCATION: **Room 114 - 1908**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **70**  
MATERIAL DESCRIPTION: **9"x9" Green w/ White Streaks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 114 - 1908**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 04/19/2016



# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUILDING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **70**  
MATERIAL DESCRIPTION: **9"x9" Green w/ White Streaks VFT Mastic**  
MATERIAL LOCATION: **Room 114 - 1908**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **71**  
MATERIAL DESCRIPTION: **9"x9" Black w/ White Streaks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Room 114 - 1908**  
MATERIAL QUANTITY: **1300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/19/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **71**  
MATERIAL DESCRIPTION: **9"x9" Black w/ White Streaks VFT**  
MATERIAL LOCATION: **Room 114 - 1908**  
MATERIAL QUANTITY: **1300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **72**  
MATERIAL DESCRIPTION: **9"x9" Black w/ White Streaks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 114 - 1908**  
MATERIAL QUANTITY: **1300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/19/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUILDING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **72**  
MATERIAL DESCRIPTION: **9"x9" Black w/ White Streaks VFT Mastic**  
MATERIAL LOCATION: **Room 114 - 1908**  
MATERIAL QUANTITY: **1300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **73**  
MATERIAL DESCRIPTION: **12"x12" Gray w/ Gray & Black Specks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Room 114 - 1908 NOT OBSERVED**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **NOT OBSERVED**

Inspector's Signature: \_\_\_\_\_



Date: 04/19/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **73**  
MATERIAL DESCRIPTION: **12"x12" Gray w/ Gray & Black Specks VFT**  
MATERIAL LOCATION: **Room 114 - 1908 NOT OBSERVED**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **74**  
MATERIAL DESCRIPTION: **12"x12" Gray w/ Gray & Black Specks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 114 - 1908 NOT OBSERVED**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **NOT OBSERVED**

Inspector's Signature: \_\_\_\_\_



Date: 04/19/2016



# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **74**  
MATERIAL DESCRIPTION: **12"x12" Gray w/ Gray & Black Specks VFT Mastic**  
MATERIAL LOCATION: **Room 114 - 1908 NOT OBSERVED**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **75**  
MATERIAL DESCRIPTION: **12"x12" Blue w/ White Streaks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Room 114 - 1908 NOT OBSERVED**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **NOT OBSERVED**

Inspector's Signature: \_\_\_\_\_



Date: 04/19/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **75**  
MATERIAL DESCRIPTION: **12"x12" Blue w/ White Streaks VFT**  
MATERIAL LOCATION: **Room 114 - 1908 NOT OBSERVED**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **76**  
MATERIAL DESCRIPTION: **12"x12" Blue w/ White Streaks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 114 - 1908 NOT OBSERVED**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **NOT OBSERVED**

Inspector's Signature: \_\_\_\_\_



Date: 04/19/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUILDING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **76**  
MATERIAL DESCRIPTION: **12"x12" Blue w/ White Streaks VFT Mastic**  
MATERIAL LOCATION: **Room 114 - 1908 NOT OBSERVED**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **77**  
MATERIAL DESCRIPTION: **9"x9" Brown w/ White & Red Streaks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON: **Deterioration**  
HISTORICAL RESPONSE ACTION: **Repair**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Deterioration**  
DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Room 018 & Hallway -1908 Room 018 does not exist**  
MATERIAL QUANTITY: **650** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **650** DAMAGE UNITS: **SF**  
COMMENTS: **Room 018 does not exist**

Inspector's Signature: \_\_\_\_\_



Date: 04/19/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **77**  
MATERIAL DESCRIPTION: **9"x9" Brown w/ White & Red Streaks VFT**  
MATERIAL LOCATION: **Room 018 & Hallway -1908 Room 018 does not exist**  
MATERIAL QUANTITY: **650** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **150** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUILDING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **78**  
MATERIAL DESCRIPTION: **9"x9" Brown w/ White & Red Streaks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 018 & Hallway - 1908 Room 018 does not exist**  
MATERIAL QUANTITY: **650** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **Room 018 does not exist**

Inspector's Signature: \_\_\_\_\_



Date: 04/19/2016



# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUILDING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **78**  
MATERIAL DESCRIPTION: **9"x9" Brown w/ White & Red Streaks VFT Mastic**  
MATERIAL LOCATION: **Room 018 & Hallway - 1908 Room 018 does not exist**  
MATERIAL QUANTITY: **650** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **79**  
MATERIAL DESCRIPTION: **9"x9" Tan w/ Brown & White Streaks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON: **Deterioration**  
HISTORICAL RESPONSE ACTION: **Repair**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Deterioration**  
DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Room 018 & Hallway - 1908 Room 018 does not exist**  
MATERIAL QUANTITY: **650** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **650** DAMAGE UNITS: **SF**  
COMMENTS: **Room 018 does not exist**

Inspector's Signature: \_\_\_\_\_



Date: 04/19/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **79**  
MATERIAL DESCRIPTION: **9"x9" Tan w/ Brown & White Streaks VFT**  
MATERIAL LOCATION: **Room 018 & Hallway - 1908 Room 018 does not exist**  
MATERIAL QUANTITY: **650** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **150** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUILDING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **80**  
MATERIAL DESCRIPTION: **9"x9" Tan w/ Brown & White Streaks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 018 & Hallway - 1908 Room 018 does not exist**  
MATERIAL QUANTITY: **650** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **Room 018 does not exist**

Inspector's Signature:



Date: **04/19/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUILDING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **80**  
MATERIAL DESCRIPTION: **9"x9" Tan w/ Brown & White Streaks VFT Mastic**  
MATERIAL LOCATION: **Room 018 & Hallway - 1908 Room 018 does not exist**  
MATERIAL QUANTITY: **650** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **81**  
MATERIAL DESCRIPTION: **9"x9" Gray w/ White Swirls VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Library (Underneath Carpet, HA # 111, # 109 & # 110) - 1908**  
MATERIAL QUANTITY: **1900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **81**  
MATERIAL DESCRIPTION: **9"x9" Gray w/ White Swirls VFT**  
MATERIAL LOCATION: **Library (Underneath Carpet, HA # 111, # 109 & # 110) - 1908**  
MATERIAL QUANTITY: **1900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **82**  
MATERIAL DESCRIPTION: **9"x9" Gray w/ White Swirls VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Library (Underneath Carpet, HA # 111, # 109 & # 110) - 1908**  
MATERIAL QUANTITY: **1900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 04/19/2016



# Chicago Public Schools

GSG Consultants, Inc.

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUILDING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **82**  
MATERIAL DESCRIPTION: **9"x9" Gray w/ White Swirls VFT Mastic**  
MATERIAL LOCATION: **Library (Underneath Carpet, HA # 111, # 109 & # 110) - 1908**  
MATERIAL QUANTITY: **1900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **83**  
MATERIAL DESCRIPTION: **9"x9" White w/ Black Swirls VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Library (Underneath Carpet, HA # 111, # 109 & # 110) - 1908**  
MATERIAL QUANTITY: **1900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 04/19/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUILDING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **83**  
MATERIAL DESCRIPTION: **9"x9" White w/ Black Swirls VFT**  
MATERIAL LOCATION: **Library (Underneath Carpet, HA # 111, # 109 & # 110) - 1908**  
MATERIAL QUANTITY: **1900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **84**  
MATERIAL DESCRIPTION: **9"x9" White w/ Black Swirls VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Library (Underneath Carpet, HA # 111, # 109 & # 110) - 1908**  
MATERIAL QUANTITY: **1900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 04/19/2016

# Chicago Public Schools

GSG Consultants, Inc.

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **84**  
MATERIAL DESCRIPTION: **9"x9" White w/ Black Swirls VFT Mastic**  
MATERIAL LOCATION: **Library (Underneath Carpet, HA # 111, # 109 & # 110) - 1908**  
MATERIAL QUANTITY: **1900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **85**  
MATERIAL DESCRIPTION: **12"x24" Gray w/ Black & White Swirls VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Library (Underneath Carpet, HA # 111, # 109 & # 110) - 1908**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 04/19/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUILDING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **85**  
MATERIAL DESCRIPTION: **12"x24" Gray w/ Black & White Swirls VFT**  
MATERIAL LOCATION: **Library (Underneath Carpet, HA # 111, # 109 & # 110) - 1908**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **86**  
MATERIAL DESCRIPTION: **12"x24" Gray w/ Black & White Swirls VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Library (Underneath Carpet, HA # 111, # 109 & # 110) - 1908**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/19/2016**



# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUILDING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **86**  
MATERIAL DESCRIPTION: **12"x24" Gray w/ Black & White Swirls VFT Mastic**  
MATERIAL LOCATION: **Library (Underneath Carpet, HA # 111, # 109 & # 110) - 1908**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **87**  
MATERIAL DESCRIPTION: **Stair Tread Tile Yellow w/ Gold Specks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Library (Underneath Carpet, HA # 111, # 109 & # 110) - 1908**

MATERIAL QUANTITY: **35** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUILDING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **87**  
MATERIAL DESCRIPTION: **Stair Tread Tile Yellow w/ Gold Specks VFT**  
MATERIAL LOCATION: **Library (Underneath Carpet, HA # 111, # 109 & # 110) - 1908**  
MATERIAL QUANTITY: **35** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **88**  
MATERIAL DESCRIPTION: **Stair Tread Tile Yellow w/ Gold Specks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Library (Underneath Carpet, HA # 111, # 109 & # 110)- 1908**  
MATERIAL QUANTITY: **35** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/19/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUILDING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **88**  
MATERIAL DESCRIPTION: **Stair Tread Tile Yellow w/ Gold Specks VFT Mastic**  
MATERIAL LOCATION: **Library (Underneath Carpet, HA # 111, # 109 & # 110)- 1908**  
MATERIAL QUANTITY: **35** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **89**  
MATERIAL DESCRIPTION: **Stair Tread Tile Gray w/ White Marble VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Library (Underneath Carpet, HA # 111, # 109 & # 110) - 1908**  
MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **89**  
MATERIAL DESCRIPTION: **Stair Tread Tile Gray w/ White Marble VFT**  
MATERIAL LOCATION: **Library (Underneath Carpet, HA # 111, # 109 & # 110) - 1908**  
MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **90**  
MATERIAL DESCRIPTION: **Stair Tread Tile Gray w/ White Marble VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Library (Underneath Carpet, HA # 111, # 109 & # 110) - 1908**  
MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/19/2016**



# Chicago Public Schools

GSG Consultants, Inc.

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **90**  
MATERIAL DESCRIPTION: **Stair Tread Tile Gray w/ White Marble VFT Mastic**  
MATERIAL LOCATION: **Library (Underneath Carpet, HA # 111, # 109 & # 110) - 1908**  
MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **91**  
MATERIAL DESCRIPTION: **12"x12" Tan w/ Red & Black Streaks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 115 - 1908**  
MATERIAL QUANTITY: **120** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/19/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUILDING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **91**  
MATERIAL DESCRIPTION: **12"x12" Tan w/ Red & Black Streaks VFT**  
MATERIAL LOCATION: **Room 115 - 1908**  
MATERIAL QUANTITY: **120** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **92**  
MATERIAL DESCRIPTION: **12"x12" Tan w/ Red & Black Streaks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 115 - 1908**  
MATERIAL QUANTITY: **120** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/19/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **92**  
MATERIAL DESCRIPTION: **12"x12" Tan w/ Red & Black Streaks VFT Mastic**  
MATERIAL LOCATION: **Room 115 - 1908**  
MATERIAL QUANTITY: **120** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **93**  
MATERIAL DESCRIPTION: **9"x9" Gray w/ Black & White Streaks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Room 115 - 1908**  
MATERIAL QUANTITY: **120** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/19/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUILDING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **93**  
MATERIAL DESCRIPTION: **9"x9" Gray w/ Black & White Streaks VFT**  
MATERIAL LOCATION: **Room 115 - 1908**  
MATERIAL QUANTITY: **120** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **94**  
MATERIAL DESCRIPTION: **9"x9" Gray w/ Black & White Streaks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 115 - 1908**  
MATERIAL QUANTITY: **120** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/19/2016**



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **94**  
MATERIAL DESCRIPTION: **9"x9" Gray w/ Black & White Streaks VFT Mastic**  
MATERIAL LOCATION: **Room 115 - 1908**  
MATERIAL QUANTITY: **120** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **95**  
MATERIAL DESCRIPTION: **9"x9" Dark Green w/ White Streaks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 121, 121A - 1908**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 04/19/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **95**  
MATERIAL DESCRIPTION: **9"x9" Dark Green w/ White Streaks VFT**  
MATERIAL LOCATION: **Rooms 121, 121A - 1908**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **96**  
MATERIAL DESCRIPTION: **9"x9" Dark Green w/ White Streaks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 121, 121A - 1908**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 04/19/2016

# Chicago Public Schools

GSG Consultants, Inc.

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **96**  
MATERIAL DESCRIPTION: **9"x9" Dark Green w/ White Streaks VFT Mastic**  
MATERIAL LOCATION: **Rooms 121, 121A - 1908**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **97**  
MATERIAL DESCRIPTION: **Tan Spotted Linoleum**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Third Floor Men's and Women's Teachers Toilet - 1908**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 04/19/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **97**  
MATERIAL DESCRIPTION: **Tan Spotted Linoleum**  
MATERIAL LOCATION: **Third Floor Men's and Women's Teachers Toilet - 1908**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **98**  
MATERIAL DESCRIPTION: **Tan Spotted Linoleum Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Third Floor Men's and Women's Teachers Toilet - 1908**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/19/2016**



# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **98**  
MATERIAL DESCRIPTION: **Tan Spotted Linoleum Mastic**  
MATERIAL LOCATION: **Third Floor Men's and Women's Teachers Toilet - 1908**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **99**  
MATERIAL DESCRIPTION: **Lab Counter Top**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 319 - 1908**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 04/19/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUILDING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **99**  
MATERIAL DESCRIPTION: **Lab Counter Top**  
MATERIAL LOCATION: **Room 319 - 1908**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **AA**  
MATERIAL DESCRIPTION: **Air Cell Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with potential for significant damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **3rd Floor Janitor's Closet By Room 301- 1915**  
MATERIAL QUANTITY: **14** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 04/19/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **AA**  
MATERIAL DESCRIPTION: **Air Cell Pipe Insulation**  
MATERIAL LOCATION: **3rd Floor Janitor's Closet By Room 301- 1915**  
MATERIAL QUANTITY: **14** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **BB**  
MATERIAL DESCRIPTION: **MJP E/F/V on Air Cell Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **3rd Floor Janitor's Closet By Room 301 - 1915; 1st Floor Girls Toilet Added in 2010**  
MATERIAL QUANTITY: **6** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 04/19/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **BB**  
MATERIAL DESCRIPTION: **MJP E/F/V on Air Cell Pipe Insulation**  
MATERIAL LOCATION: **3rd Floor Janitor's Closet By Room 301 - 1915; 1st Floor Girls Toilet Added in 2010**  
MATERIAL QUANTITY: **6** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **CC**  
MATERIAL DESCRIPTION: **MJP E/F/V on Fiberglass Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **First Floor Girl's Toilet, First Floor Corridor - 1915**  
MATERIAL QUANTITY: **20** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 04/19/2016



# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUILDING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **CC**  
MATERIAL DESCRIPTION: **MJP E/F/V on Fiberglass Pipe Insulation**  
MATERIAL LOCATION: **First Floor Girl's Toilet, First Floor Corridor - 1915**  
MATERIAL QUANTITY: **20** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **DD**  
MATERIAL DESCRIPTION: **MJP E/F/V on Mag Block Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Janitor's Closet By Room 301 - 1915**  
MATERIAL QUANTITY: **1** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 04/19/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **DD**  
MATERIAL DESCRIPTION: **MJP E/F/V on Mag Block Pipe Insulation**  
MATERIAL LOCATION: **Janitor's Closet By Room 301 - 1915**  
MATERIAL QUANTITY: **1** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **E**  
MATERIAL DESCRIPTION: **Boiler Gasket**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Boiler Room - 1923**  
MATERIAL QUANTITY: **1** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/19/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **E**  
MATERIAL DESCRIPTION: **Boiler Gasket**  
MATERIAL LOCATION: **Boiler Room - 1923**  
MATERIAL QUANTITY: **1** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **EE**  
MATERIAL DESCRIPTION: **Mag Block Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with potential for significant damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Janitor's Closet By Room 301 - 1915**  
MATERIAL QUANTITY: **14** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 04/19/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **EE**  
MATERIAL DESCRIPTION: **Mag Block Pipe Insulation**  
MATERIAL LOCATION: **Janitor's Closet By Room 301 - 1915**  
MATERIAL QUANTITY: **14** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **F**  
MATERIAL DESCRIPTION: **Boiler Gasket**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with potential for significant damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Boiler Room - 1923**  
MATERIAL QUANTITY: **1** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/19/2016**



# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **F**  
MATERIAL DESCRIPTION: **Boiler Gasket**  
MATERIAL LOCATION: **Boiler Room - 1923**  
MATERIAL QUANTITY: **1** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FF**  
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Incinerator Room - 1923**  
MATERIAL QUANTITY: **10** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 04/19/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUILDING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **FF**  
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**  
MATERIAL LOCATION: **Incinerator Room - 1923**  
MATERIAL QUANTITY: **10** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **GG**  
MATERIAL DESCRIPTION: **MJP E/F/V on Aircell Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Incinerator Room - 1923**  
MATERIAL QUANTITY: **7** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **04/19/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **GG**  
MATERIAL DESCRIPTION: **MJP E/F/V on Aircell Pipe Insulation**  
MATERIAL LOCATION: **Incinerator Room - 1923**  
MATERIAL QUANTITY: **7** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **HA-1000**  
MATERIAL DESCRIPTION: **2'x4' white ceiling tiles with random fis & holes**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout**  
MATERIAL QUANTITY: **20000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 04/19/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **HA-1000**  
MATERIAL DESCRIPTION: **2'x4' white ceiling tiles with random fis & holes**  
MATERIAL LOCATION: **Throughout**  
MATERIAL QUANTITY: **20000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **HA-1001**  
MATERIAL DESCRIPTION: **2"X4" white plain ceiling tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Teachers' Lunch Room**  
MATERIAL QUANTITY: **960** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 04/19/2016



# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUILDING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **HA-1001**  
MATERIAL DESCRIPTION: **2"X4" white plain ceiling tile**  
MATERIAL LOCATION: **Teachers' Lunch Room**  
MATERIAL QUANTITY: **960** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **HA-1002**  
MATERIAL DESCRIPTION: **1'x1' white ceiling tile rand holes**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Students' Lunch Room**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **HA-1002**  
MATERIAL DESCRIPTION: **1'x1' white ceiling tile rand holes**  
MATERIAL LOCATION: **Students' Lunch Room**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUILDING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **HA-1003**  
MATERIAL DESCRIPTION: **Glue for 1'x1' white ceilingtile with holes**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Students' Lunch Room**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/19/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **HA-1003**  
MATERIAL DESCRIPTION: **Glue for 1'x1' white ceilingtile with holes**  
MATERIAL LOCATION: **Students' Lunch Room**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **HA-1004**  
MATERIAL DESCRIPTION: **2'x2' white plain ceiling tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Kitchen**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 04/19/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **HA-1004**  
MATERIAL DESCRIPTION: **2'x2' white plain ceiling tile**  
MATERIAL LOCATION: **Kitchen**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **HA-1005**  
MATERIAL DESCRIPTION: **1'x1' white CT with large holes**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Kitchen Manager Office**  
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 04/19/2016



# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **HA-1005**  
MATERIAL DESCRIPTION: **1'x1' white CT with large holes**  
MATERIAL LOCATION: **Kitchen Manager Office**  
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **HA-1006**  
MATERIAL DESCRIPTION: **Glue for 1'x1' wh CT with large holes**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Kitchen Manager Office**

MATERIAL QUANTITY: **150**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/19/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **HA-1006**  
MATERIAL DESCRIPTION: **Glue for 1'x1' wh CT with large holes**  
MATERIAL LOCATION: **Kitchen Manager Office**  
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **HA-1007**  
MATERIAL DESCRIPTION: **1'x1' wh CT with random fissures**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rm. 300 on ceiling and walls**  
MATERIAL QUANTITY: **1680** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/19/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **HA-1007**  
MATERIAL DESCRIPTION: **1'x1' wh CT with random fissures**  
MATERIAL LOCATION: **Rm. 300 on ceiling and walls**  
MATERIAL QUANTITY: **1680** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **HA-1008**  
MATERIAL DESCRIPTION: **Glue for 1'x1' white CT with rand fiss**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rm. 300 on ceiling and walls**

MATERIAL QUANTITY: **1680**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/19/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **HA-1008**  
MATERIAL DESCRIPTION: **Glue for 1'x1' white CT with rand fiss**  
MATERIAL LOCATION: **Rm. 300 on ceiling and walls**  
MATERIAL QUANTITY: **1680** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **HA-1010**  
MATERIAL DESCRIPTION: **12"x12" yellow VFT NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION:

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/19/2016**



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **HA-1010**

MATERIAL DESCRIPTION: **12"x12" yellow VFT NOT OBSERVED**

MATERIAL LOCATION:

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **HA-1010m**  
MATERIAL DESCRIPTION: **Adhesive for 12"x12" yellow VFT NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION:

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/19/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **HA-1010m**

MATERIAL DESCRIPTION: **Adhesive for 12"x12" yellow VFT NOT OBSERVED**

MATERIAL LOCATION:

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **HA-1011**  
MATERIAL DESCRIPTION: **Transite**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st floor girl's r/r privacy wall**  
MATERIAL QUANTITY: **30** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 04/19/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **HA-1011**  
MATERIAL DESCRIPTION: **Transite**  
MATERIAL LOCATION: **1st floor girl's r/r privacy wall**  
MATERIAL QUANTITY: **30** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **HH**  
MATERIAL DESCRIPTION: **MJP E/F/V on Fiberglass Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Locker Room, 1st Floor Boy's Toilet, Hot & Cold Deck, & Wood Shop Area - 1923; Rms 219, 315, 319 under Classroom Sinks (12 LF); 2nd Floor Girls washroom (5 LF); 3rd Floor Girls Washroom (5 LF).**

MATERIAL QUANTITY: **142** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 04/19/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUILDING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **HH**  
MATERIAL DESCRIPTION: **MJP E/F/V on Fiberglass Pipe Insulation**  
MATERIAL LOCATION: **Locker Room, 1st Floor Boy's Toilet, Hot & Cold Deck, & Wood Shop Area - 1923; Rms 219, 315, 319 under Classroom Sinks (12 LF); 2nd Floor Girls washroom (5 LF); 3rd Floor Girls Washroom (5 LF).**  
MATERIAL QUANTITY: **142** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **II**  
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation (Paper-Wrap Pipe Ins)**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Repair**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Electrical Room Across from Stairway # 4 - 1908**  
MATERIAL QUANTITY: **38** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 04/19/2016



# Chicago Public Schools

GSG Consultants, Inc.

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **II**  
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation (Paper-Wrap Pipe Ins)**  
MATERIAL LOCATION: **Electrical Room Across from Stairway # 4 - 1908**  
MATERIAL QUANTITY: **38** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUIDLING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **JJ**  
MATERIAL DESCRIPTION: **MJP E/F/V on Cardboard Pipe Insulation(P.wrap PI)**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Electrical Room Across from Stairway # 4 - 1908**

MATERIAL QUANTITY: **10** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 04/19/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUILDING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **JJ**  
MATERIAL DESCRIPTION: **MJP E/F/V on Cardboard Pipe Insulation(P.wrap PI)**  
MATERIAL LOCATION: **Electrical Room Across from Stairway # 4 - 1908**  
MATERIAL QUANTITY: **10** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUILDING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **126**  
MATERIAL DESCRIPTION: **12"x12" Brown w/ Specks VFT**  
MATERIAL LOCATION: **Elevator Lobbies on 1st, 2nd, 3rd, 4th, ad 5th Floors**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC** FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **MODERATE** CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: DAMAGE REASON:  
DAMAGE QUANTITY: **0** DAMAGE REASON:  
DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 04/19/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUILDING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **126**  
MATERIAL DESCRIPTION: **12"x12" Brown w/ Specks VFT**  
MATERIAL LOCATION: **Elevator Lobbies on 1st, 2nd, 3rd, 4th, ad 5th Floors**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: **05/17/2016**

# Chicago Public Schools

GSG Consultants, Inc.

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUILDING ID: **1530**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School** INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **129**  
MATERIAL DESCRIPTION: **12"x12" Light Brown w Gray specks VFT Mastic**  
MATERIAL LOCATION: **Elevator Lobbies on 1st, 2nd, 3rd, 4th, ad 5th Floors**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC** FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW** CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: DAMAGE REASON:  
DAMAGE REASON:  
DAMAGE REASON:  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: **04/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUILDING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **129**  
MATERIAL DESCRIPTION: **12"x12" Light Brown w Gray specks VFT Mastic**  
MATERIAL LOCATION: **Elevator Lobbies on 1st, 2nd, 3rd, 4th, ad 5th Floors**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: 05/17/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **46281**    BUILDING ID: **1530**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School**    INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.**    IDPH LICENSE NO: **100-11093**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **127**  
MATERIAL DESCRIPTION: **12"x12" Brown w/ Specks VFT Mastic**  
MATERIAL LOCATION: **Elevator Lobbies on 1st, 2nd, 3rd, 4th, ad 5th Floors**  
MATERIAL QUANTITY: **300**    MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**    FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**    CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY:    DAMAGE REASON:  
DAMAGE QUANTITY: **0**    DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 04/19/2016



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUILDING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **127**  
MATERIAL DESCRIPTION: **12"x12" Brown w/ Specks VFT Mastic**  
MATERIAL LOCATION: **Elevator Lobbies on 1st, 2nd, 3rd, 4th, ad 5th Floors**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: 05/17/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **46281**    BUILDING ID: **1530**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School**    INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.**    IDPH LICENSE NO: **100-11093**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **128**  
MATERIAL DESCRIPTION: **12"x12" Light Brown w Gray specks VFT**  
MATERIAL LOCATION: **Elevator Lobbies on 1st, 2nd, 3rd, 4th, ad 5th Floors**  
MATERIAL QUANTITY: **600**    MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**    FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **MODERATE**    CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY:    DAMAGE REASON:  
DAMAGE QUANTITY: **0**    DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 04/19/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUILDING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **128**  
MATERIAL DESCRIPTION: **12"x12" Light Brown w Gray specks VFT**  
MATERIAL LOCATION: **Elevator Lobbies on 1st, 2nd, 3rd, 4th, ad 5th Floors**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: 05/17/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **46281**    BUILDING ID: **1530**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School**    INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.**    IDPH LICENSE NO: **100-11093**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **124**  
MATERIAL DESCRIPTION: **12 x 12 Tan with Specks Floor Tile**  
MATERIAL LOCATION: **Cafeteria, Serving Area, Teachers' Lounge**  
MATERIAL QUANTITY: **4600**    MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**    FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **MODERATE**    CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY:    DAMAGE REASON:  
DAMAGE QUANTITY: **0**    DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 04/19/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUILDING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **124**  
MATERIAL DESCRIPTION: **12 x 12 Tan with Specks Floor Tile**  
MATERIAL LOCATION: **Cafeteria, Serving Area, Teachers' Lounge**  
MATERIAL QUANTITY: **4600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: 05/17/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **46281**    BUILDING ID: **1530**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Schurz High School**    INSPECTION DATE: **4/19/2016**  
ADDRESS: **3601 N. Milwaukee Ave.**    IDPH LICENSE NO: **100-11093**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **125**  
MATERIAL DESCRIPTION: **12 x 12 Tan with Specks Floor Tile Mastic**  
MATERIAL LOCATION: **Cafeteria, Serving Area, Teachers' Lounge**  
MATERIAL QUANTITY: **4600**    MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**    FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**    CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY:    DAMAGE REASON:  
DAMAGE QUANTITY: **0**    DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 04/19/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46281** BUILDING ID: **1530**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Schurz High School** REVIEW DATE: **5/17/2016**  
ADDRESS: **3601 N. Milwaukee Ave.** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **125**  
MATERIAL DESCRIPTION: **12 x 12 Tan with Specks Floor Tile Mastic**  
MATERIAL LOCATION: **Cafeteria, Serving Area, Teachers' Lounge**  
MATERIAL QUANTITY: **4600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: 05/17/2016

# APPENDIX B

## Inspector and Management Planner Licenses

---



# CERTIFICATE OF ACHIEVEMENT ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that DAVID AVILA  
has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the  
examination on 02/13/2016 with a minimum score of 70% or better. Training was in accordance  
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:  
Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.

02/13/2016

Course Dates:

02/13/2017

Expires:

1602BTR08

Certificate Number:



A handwritten signature in black ink, appearing to read "N. Peneff".

Director of Training  
Nicholas J. Peneff  
Doctor of Public Health

Phone: 312-491-0081

FORM # A-010B

# CERTIFICATE OF ACHIEVEMENT ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that GUILLERMO GARCIA  
has completed the Asbestos Management Planner Refresher course and passed the examination  
on 03/21/2016 with a minimum score of 70% or better. Training was in accordance with U.S.  
E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools: Model  
Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.

03/21/2016

Course Dates:

03/21/2017

Expires:

1603MPR02

Certificate Number:



**PUBLIC HEALTH & SAFETY** inc.

Environmental and Occupational Services  
105 S. Ashland Ave., Chicago, IL 60607

*Nicholas J. Penoff*

Director of Training

Nicholas J. Penoff

Doctor of Public Health

Phone: 312-491-0081

FORM # A-011



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • [www.dph.illinois.gov](http://www.dph.illinois.gov)

4/20/2016

**GUILLERMO GARCIA**  
 855 W ADAMS ST SUITE 100  
 CHICAGO, IL 60607

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 01786

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

**COPY OF THE ASBESTOS PROFESSIONAL LICENSE**

Front of License

Back of License

| Front of License  |                             |                               | Back of License  |                                 |
|---|-----------------------------|-------------------------------|--|---------------------------------|
|  <p><b>ASBESTOS PROFESSIONAL LICENSE</b></p>               |                             |                               | <p><b>ENDORSEMENTS</b></p>   |                                 |
| <p>ID NUMBER<br/>100 - 01733</p>  | <p>ISSUED<br/>4/20/2016</p> | <p>EXPIRES<br/>05/15/2017</p> | <p>INSPECTOR</p>   | <p>TC EXPIRES<br/>3/21/2017</p> |
| <p><b>GUILLERMO GARCIA</b><br/>           855 W ADAMS ST SUITE 100<br/>           CHICAGO, IL 60607<br/>           Environmental Health</p> |                             |                               | <p>MANAGEMENT PLANNER</p>  | <p>3/21/2017</p>                |
|   |                             |                               | <p>PROJECT MANAGER</p>   | <p>2/6/2017</p>                 |
|   |                             |                               | <p>AIR SAMPLING PROFESSIONAL</p>   |                                 |
|   |                             |                               | <p><b>Alteration of this license shall result in legal action</b><br/>           This license issued under authority of the State of Illinois<br/>           Department of Public Health<br/>           This license is valid only when accompanied by a valid<br/>           training course certificate.</p> |                                 |

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: [dph.illinois.gov/topics-services/environmental-health-protection/asbestos](http://dph.illinois.gov/topics-services/environmental-health-protection/asbestos)  
 EMAIL Address: [dph.asbestos@illinois.gov](mailto:dph.asbestos@illinois.gov)

**PROTECTING HEALTH, IMPROVING LIVES**  
*Nationally Accredited by PHAB*

# APPENDIX C

## Laboratory Accreditations

---

# APPENDIX D

## Laboratory Results

---

# APPENDIX E

## Chain of Custody Forms

---

## Three-Year Reinspection Key to Terms

|                          | <b>CODE</b> | <b>KEY</b>                             |
|--------------------------|-------------|--|
| <b>MATERIAL</b>          |             |  |
|                          | ACBM        | Asbestos Containing Building Materials |
| <b>MATERIAL CATEGORY</b> |             |  |
|                          | MISC        | Miscellaneous                          |
|                          | SURF        | Surfacing                              |
|                          | TSI         | Thermal System Insulation              |
| <b>MATERIAL UNITS</b>    |             |  |
|                          | LF          | Linear Feet                            |
|                          | SF          | Square Feet                            |
|                          | CF          | Cubic Feet                             |
| <b>DAMAGE TYPE</b>       |             |  |
|                          | Loc         | Localized                              |
|                          | Dist        | Distributed                            |