

ILLINOIS DEPARTMENT OF PUBLIC HEALTH  
AHERA THREE YEAR REINSPECTION  
ASBESTOS ABATEMENT PROGRAM  
SCHOOL INFORMATION FORM

**SECTION I**

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299  
SCHOOL ID NUMBER: 14-016-2990-0043  
SCHOOL NAME: Taft High School  
ADDRESS OF SCHOOL: 6545 W. Hurlburt St.  
CITY: Chicago, IL, 60631

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **4/9/2013**

**If the address on this form is different than the address of the building, submit a written explanation.**

**SECTION II** (Please type or print)

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 5/23/2016 ENROLLMENT 3263  
IDPH INSPECTOR LICENSE NUMBER: 100-11372  
IDPH LICENSED INSPECTOR NAME (Please Print): Eric Moore  
IDPH MP LICENSE NUMBER: 100-04019  
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Arturo Saenz

DESIGNATED PERSON (Please Print): Robert Christlieb PHONE: (773) 553-3197



5/23/2016

Signature of Designated Person

Date

**SECTION III**

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: \_\_\_\_\_

School has been closed. Date closed: \_\_\_\_\_

School building has been demolished. Date: \_\_\_\_\_

School building is asbestos free since last reinspection: \_\_\_\_\_

**Please explain in writing why the school building is now asbestos free and include the supporting documentation.**

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

**Explain in writing if the address of the building is different than the address on this form:**

**THREE-YEAR REINSPECTION**

**CHICAGO SCHOOL DIST 299**

**Taft High School**

6545 W. Hurlburt St.  
Chicago, IL, 60631

Unit: 46311  
Building ID: 1580

IDPH ID Number: 14-016-2990-0043

**REPORT DATE:**

Monday, May 23, 2016

**Prepared for:**

**Chicago Public Schools**  
**125 S. Clark Street**  
**Chicago, IL 60603**

**Prepared by:**

**GSG Consultants, Inc.**

855 W. Adams St., Ste. 200

Phone (312) 733-6262

Fax (312) 733-5612

**DO NOT REMOVE FROM SCHOOL  
REQUIRED BY FEDERAL LAW**

April 28, 2016

Mr. R. Kent Cook  
Asbestos Program  
Illinois Department of Public Health  
525 West Jefferson Street  
Springfield, Illinois 62761

Re: Chicago Public Schools - 2016 Three-Year Reinspections

Dear Mr. Cook:

GSG Consultants, Inc., Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 1,2,6 Elementary Schools. Please update your records with the following information.

School District: 299                      Unit: 46311                      Region: 01                      IDPH ID: 14-016-2990-0043

School: Taft High School                      Building ID: 1580

Address: 6545 W. Hurlburt St.  
Chicago, IL, 60631

Building Contact: Guerra, Jason                      Contact Phone: 312-505-9963

Current Building Owners: Chicago Public Schools

Review Date: 05/19/2016

Inspector: Eric Moore                      Inspector IDPH License: 100-11372  
Management Planner: Arturo Saenz                      Management Planner IDPH License: 100-04019

If you have any questions or comments, please contact us at (312) 733-6262

Sincerely,  
GSG Consultants, Inc.



Arturo Saenz  
100-04019

## **Environmental Notification to Occupants**

To: Faculty, Staff and Parents  
From: Chicago Public Schools  
Date: April 28, 2016

RE: Taft High School, Unit 46311  
6545 W. Hurlburt St.  
Chicago, IL, 60631

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2016 asbestos three year re-inspection has been completed at Taft High School , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at Taft High School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Robert Christlieb, the designated Local Education Authority's Designated Person at (773) 553-3197 .

## **Table of Contents**

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

### **APPENDICES:**

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

## SCHOOL AND INSPECTION INFORMATION

### 1. School Information

School: Taft High School Unit: 46311 Region: 01  
Address: 6545 W. Hurlburt St. Chicago, IL, 60631  
IDPH ID: 14-016-2990-0043 Building ID: 1580  
Contact: Guerra, Jason Phone: 312-505-9963

### 2. Description of Facility

Original Construction: 1939 Additional Construction: 1959,1974  
Total Square Footage: 175896 No of Floors: 3  
Current Occupancy: 3263

### 3. LEA Designated Person

Contact: Robert Christlieb Phone: (773) 553-3197  
Address: 125 South Clark Street, 17th Floor  
Chicago, IL 60603

### 4. Managing Environmental Consultant

MEC: GSG Consultants, Inc.  
Contact: Arturo Saenz  
Address 855 W. Adams St., Ste. 200  
Phone: (312) 733-6262 Fax: (312) 733-5612

### 5. Inspector

Inspector Name: Eric Moore


Inspector IDPH license # 100-11372

Signature:  
Date: 4/28/2016

### 6. Management Planner

Management Planner Name: Arturo Saenz

Management Planner IDPH license # 100-04019

Signature:   
Date: 05/19/2016

### 7. Review Date: 05/19/2016

### 8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature: 

Date: 5/23/2016

Name: Robert Christlieb

## II. EXECUTIVE SUMMARY

GSG Consultants, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Taft High School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 1580:

B. The following new homogenous areas have been identified for Building 1580:

HA-1005	Beige Linoleum
HA-1006	Grey w White Streaks Linoleum
HA-1007	12"x12" White w/Gray Streaks VFT
HA-1008	12"x12" White w/Gray Streaks VFT Mastic



C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

01	12"x12" White w/ Beige Speckles VFT
04	12"x12" White w/ Beige Streaks VFT
07	12"x12" Dark Gray w/ White Streaks VFT
09	12"x12" Off White w/ Tan Specks VFT
10	12"x12" White w/ Gold Streaks VFT
102	12" x 12" Brown w/ Black Specks VFT
103	12" x 12" Brown w/ Black Specks VFT Mastic
104	12" x 12" White w/ Gray Specks VFT
105	12" x 12" White w/ Gray Specks VFT Mastic
106	12" x 12" Off White w/ Beige Streaks VFT
107	12" x 12" Off White w/ Beige Streaks VFT Mastic
11	12"x12" Light Brown w/ White Streaks VFT
111	12"x12" White w/ Gray Streaks VFT Mastic
112	12"x12" Brown w/ White Streaks VFT Mastic
113	12"x12" Brown w/ Beige Streaks VFT Mastic
114	12"x12" White w/ Beige Streaks VFT Mastic
115	9"x9" Light Brown w/ Beige Streaks VFT
118	12"x12" Off White w/ Tan Specks VFT Mastic
119	12"x12" White w/ Gold Streaks VFT Mastic
12	12"x12" Yellow w/ White Streaks VFT
120	12"x12" Light Brown w/ White Streaks VFT Mastic
121	12"x12" Yellow w/ White Streaks VFT Mastic
122	12"x12" Green Speckles VFT Mastic
123	12"x12" Yellow Speckled VFT Mastic
125	12" x 12" White w/ Light Green Streaks VFT
126	12" x 12" White w/ Light Green Streaks VFT Mastic
13	12"x12" Green Speckles VFT
130	12" x 12" Dark Gray VFT
131	12" x 12" Dark Gray VFT Mastic
133	Carpet Mastic
134	Carpet Mastic
135	Terrazo
136	Terrazo
137	Terrazo
138	Cardboard Pipe Insulation (Paper Wrap on Insulation)
139	MJP E/V/F on Cardboard Pipe Insulation (Paper Wrap on Pipe Insulation)
14	12"x12" Yellow Speckled VFT
140	2'x4' Ceiling tile w/ grooves
141	Carpet MASTIC
142	Carpet MASTIC

143	12"x12" light gray w/ gray streaks VFT
143A	12"x12" light gray w/ gray streaks VFT MASTIC
144	Tectum panels
16	2'x4' Dot Wave Ceiling Tile
17	1'x1' White Smooth Ceiling Tile
31	Hardcoat Plaster
71	MJP E/F/V on Fiberglass Pipe Insulation
72	Hard Coat Plaster
90	12"x12" Tan w/ Brown Streaks VFT
98	2'x4' Dot Wave Ceiling Tile
HA-1000	5'x2.5' ceiling tile with random pinholes
HA-1003	MJP E/V/F on Cardboard Pipe Insulation (Paper Wrap on Insulation)
HA-1005	Beige Linoleum
HA-1006	Grey w White Streaks Linoleum
HA-1007	12"x12" White w/Gray Streaks VFT
HA-1008	12"x12" White w/Gray Streaks VFT Mastic

The following areas were deemed to be inaccessible:

142	Carpet MASTIC
72	Hard Coat Plaster

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Eric Moore, IDPH License # 100-11372. The Management Plan was updated by Arturo Saenz, IDPH License # 100-04019. Inspector and Management Planner Licenses are included in Appendix B.

### **III. METHODOLOGY**

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

### **IV. ABATEMENT HISTORY**

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

### **V. REASSESSMENTS AND RECOMMENDATIONS**

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

### **VI. CONCLUSIONS**

The Taft High School Building 1580 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

**Table I**  
**Inspector's Reinspection Findings**

---

# Chicago Public Schools

School Taft High School Unit 46311 Building ID 1580

Address 6545 W. Hurlburt St. Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
01	12"x12" White w/ Beige Speckles VFT	200	SF	Basement Break Room, 1939 Building	ASSUMED	MISC		NONE	0		No	ACBM with the potential for damage		MODERATE
02	12"x12" White w/ Gray Streaks VFT	34,500	SF	Throughout Building 1939 Building	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
03	12"x12" Brown w/ White Streaks VFT	1,600	SF	Room 119-121 Wood Shop, 1939 Building	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
04	12"x12" White w/ Beige Streaks VFT	700	SF	Engineers Office Room 321, 1939 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
05	12"x12" White w/ Beige Streaks VFT NEVER EXISTED			Room 321, 1939 Building NEVER EXISTED		MISC								
06	9"x9" Light Brown w/ Beige Streaks VFT	100	SF	Engineer's Office Hallway, 1939 Building	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
07	12"x12" Dark Gray w/ White Streaks VFT	98		First Floor Corridor by Mens and Womens Toilet, 1974 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
08	12"x12" Light Gray w/ Gray Speckles VFT	98	SF	Throughout, 1974 Building	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
09	12"x12" Off White w/ Tan Specks VFT	2,000	SF	Room 146, 147, 157A, 247, 2nd Floor Hallway, 1974 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
10	12"x12" White w/ Gold Streaks VFT	2,000	SF	Throughout, 1974 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
100	12"x12" Off White w/ Gray Streaks VFT Mastic	2,000	SF	Rms 214, 216, 300, 300A, and 300L; 1st through 3rd Floor South Corridor - 1939 Building	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
101	2'x4' White w/ Deep Grooves Ceiling Tile			Room 173, 174, 1974 Building	NO_ACBM									
102	12" x 12" Brown w/ Black Specks VFT	1,010	SF	Room 155, 176, 247, Kitchen Office, 1974 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
103	12" x 12" Brown w/ Black Specks VFT Mastic	1,010	SF	Room 155, 176, 247, Kitchen Office, 1974 Building	ASSUMED	MISC		NONE	0		No	ACBM with the potential for damage		LOW
104	12" x 12" White w/ Gray Specks VFT	500	SF	Room 207, Teachers	ASSUMED	MISC		NONE	0		No	ACBM with the		MODERATE

# Chicago Public Schools

School Taft High School Unit 46311 Building ID 1580

Address 6545 W. Hurlburt St. Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Lounge, 1974 Building								potential for damage		
105	12" x 12" White w/ Gray Specks VFT Mastic	500	SF	Room 207, Teachers Lounge, 1974 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
106	12" x 12" Off White w/ Beige Streaks VFT	1,000	SF	Room 149, 150, 152, 154, Main Office, 1974 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
107	12" x 12" Off White w/ Beige Streaks VFT Mastic	1,000	SF	Room 149, 150, 152, 154, Main Office, 1974 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
108	12" x 12" Brown w/ White & Black Specks VFT- NOT OBSERVED			Room 149, 158-160, 1974 Building NOT OBSERVED										
109	12" x 12" Brown w/ White & Black Specks VFT Mastic- NOT OBSERVED			Room 149, 158-160, 1974 Building NOT OBSERVED										
11	12"x12" Light Brown w/ White Streaks VFT	2,000	SF	Room 151, 153, 171, 184, 256, 263, 1974 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
110	12" x 12" White w/ Beige Speckles VFT Mastic- NOT OBSERVED			Room 311, Break Room, 1939 Building NOT OBSERVED										
111	12"x12" White w/ Gray Streaks VFT Mastic	1,000	SF	Throughout Building (See Hatching Maps), 1939 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
112	12"x12" Brown w/ White Streaks VFT Mastic	1,000	SF	Room 119-121 Wood Shop, 1939 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
113	12"x12" Brown w/ Beige Streaks VFT Mastic	650	SF	Room 321, 1939 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
114	12"x12" White w/ Beige Streaks VFT Mastic	650	SF	Room 321, 1939 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
115	9"x9" Light Brown w/ Beige Streaks VFT	100	SF	Engineer's Office Hallway, 1939 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
116	12"x12" Dark Gray w/ White Streaks VFT Mastic	200	SF	First Floor Corridor by Mens and Womens Toilet, 1974 Building	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
117	12"x12" Light Gray w/ Gray Speckles VFT Mastic	23,465	SF	Throughout (See Hatching Maps),	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW







# Chicago Public Schools

School Taft High School Unit 46311 Building ID 1580

Address 6545 W. Hurlburt St. Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
20	1'x1' White w/ Deep Grooves Ceiling Tile			Room 173, 1974 Building	NO_ACBM	MISC								
21	1'x1' White w/ Small Holes Ceiling Tile			Serving Room, Kitchen, 151/183 Hallway, 1974 Building	NO_ACBM									
27	Black Table Tops			Room 300, 302A, 305-307, 1939 Building		MISC								
31	Hardcoat Plaster	2,000	SF	Throughout, 1939 Building	ASSUMED	MISC		NONE	0		No	ACBM with the potential for damage		LOW
55	Drywall Joint Compound			Janitors Closets, Boys and Girls Toilets, 1974 Building	NO_ACBM									
58	MJP E/F/V on Fiberglass Pipe Insulation			Sprinkler Rm, Chiller Rm, W. Crawlspace, Carpenters Shop, Plenum Chamber, 1939 Building		TSI								
61	MJP E/F/V on Fiberglass Pipe Insulation			Sprinkler Room, Carpenter Shop, Basement Corridor, 1974 Building	NO_ACBM									
65	12" x 12" Brown w/ White Streaks VFT	890	SF	Room 342, 1958 Building	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
66	12" x 12" Brown w/ White Streaks VFT Mastic	890	SF	Room 342, 1958 Building	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
67	12" x 12" Light Gray w/ Dark Gray Specks VFT	3,571	SF	Throughout Building (See Hatching Maps), 1958 Building	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
68	12" x 12" Light Gray w/ Drk Gray Specks VFT Mastic	3,571	SF	Throughout Building (See Hatching Maps), 1958 Building	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
69	2' x 4' White w/ Deep Grooves Ceiling Tile			Room 134, 239, 326, 1958 Building	NO_ACBM									
70	1' x 1' White w/ Deep Grooves Ceiling Tile			Gymnasium Lobby, 1958 Building	NO_ACBM									
71	MJP E/F/V on Fiberglass Pipe Insulation	20	LF	Fan Units, Unfinished Pipe Space, Rifle Range,	ASSUMED	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW

# Chicago Public Schools

School Taft High School Unit 46311 Building ID 1580

Address 6545 W. Hurlburt St. Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				1958 Building										
72	Hard Coat Plaster	10,000	SF	Throughout, 1958 Building	ASSUMED	SURFACE	N	NONE	0		No	ACBM with the potential for damage		LOW
73	Exterior Window Glaze			Exterior Windows, 1939 Building	NO_ACBM									
74	Exterior Window Glaze			Exterior Windows, 1958 Building	NO_ACBM									
75	Exterior Window Glaze			Exterior Windows, 1974 Building	NO_ACBM									
76	Exterior Window Caulk			Exterior Windows, 1939 Building	NO_ACBM									
77	Exterior Window Caulk			Exterior Windows, 1958 Building	NO_ACBM									
78	Exterior Window Caulk			Exterior Windows, 1974 Building	NO_ACBM									
79	Interior Window Caulk			Interior Windows, 1939 Building	NO_ACBM									
80	Interior Window Glaze			Interior Windows, 1939 Building	NO_ACBM									
81	Interior Window Glaze			Interior Windows, 1958 Building	NO_ACBM									
82	Interior Window Glaze			Interior Windows, 1974 Building	NO_ACBM									
84	9"x9" Red VFT	10	SF	Stage South Stairwell, 1939 Building	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
85	9"x9" Red VFT Mastic	10	SF	Stage South Stairwell, 1939 Building	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
86	9"x9" Black VFT	10	SF	Stage South Stairwell, 1939 Building	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
87	9"x9" Black VFT Mastic	10	SF	Stage South Stairwell, 1939 Building	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
88	2"x18" Black VFT	36	SF	Stage South Stairwell, 1939 Building	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
89	2"x18" Black VFT Mastic	36	SF	Stage South Stairwell, 1939 Building	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
90	12"x12" Tan w/ Brown Streaks VFT	400	SF	121 Woodshop, 1939 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
91	12"x12" Tan w/ Brown Streaks VFT Mastic	400	SF	121 Woodshop,	CHR	MISC	N	NONE	0		No	ACBM with the		LOW

# Chicago Public Schools

School Taft High School Unit 46311 Building ID 1580

Address 6545 W. Hurlburt St. Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				1939 Building								potential for damage		
92	12"x12" Tan w/ Brown & White Streaks VFT ABATED			Room 117, 1939 Building ABATED	ABATED	MISC								
93	12"x12" Tan w/ Brown & White Streaks VFT Mastic ABATED			Room 117, 1939 Building ABATED	ABATED	MISC								
94	Brown Linoleum- NOT OBSERVED			2nd Floor Teachers Lounge, 1939 Building--NOT OBSERVED										
95	Brown Linoleum Mastic- NOT OBSERVED			2nd Floor Teachers Lounge, 1939 Building NOT OBSERVED										
98	2'x4' Dot Wave Ceiling Tile	1,000	SF	Room 106, 112, 216, 300, 1939 Building	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
99	12"x12" Off White w/ Gray Streaks VFT	2,000	SF	Rms 214, 216, 300, 300A, and 300L; 1st through 3rd Floor South Corridor - 1939 Building	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
HA-1000	5'x2.5' ceiling tile with random pinholes	10,000	SF	throughout 1974 bldg	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
HA-1001	Black table and counter tops ABATED			Rms. 300,302, 302A,305,308,310,312,313,316 ABATED	ABATED	MISC								
HA-1002	Gray lab table and counter tops ABATED			Rm. 183 ABATED	ABATED	MISC								
HA-1003	MJP E/V/F on Cardboard Pipe Insulation (Paper Wrap on Insulation)	155	SF	Chase Behind Rm 134	ASSUMED	TSI	Y	NONE	0		No	ACBM with the potential for damage		MODERATE
HA-1004	Gray transite panel ABATED			Exhaust hood in Rm. 302A ABATED	ABATED	MISC								
HA-1005	Beige Linoleum	1,200	SF	Rooms 311 & 313	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
HA-1006	Grey w White Streaks Linoleum	4,500	SF	Rooms 302, 303, 305, 307, 308, 310, 312, and 316	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
HA-1007	12"x12" White w/Gray Streaks VFT	600	SF	Rm 117	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		MODERATE
HA-1008	12"x12" White w/Gray Streaks VFT Mastic	600	SF	Rm 117	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

# Chicago Public Schools

School Taft High School Unit 46311 Building ID 1580

Address 6545 W. Hurlburt St. Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

*Inspector's Comments are Summarized at the End of the Report*

Reinspection Date <b>4/28/2016</b>
Inspector Name <b>Eric Moore</b>
<b>100-11372</b> <b>12/8/2016</b>
Inspector's IDPH License Number / Expiration Date

### Inspector's Comments

HA Number:	Inspector Comments:
01	
02	
03	
04	
05	
06	
07	
08	
09	
10	
100	
101	
102	
103	
104	
105	
106	
107	
108	NOT OBSERVED
109	NOT OBSERVED
11	
110	NOT OBSERVED
111	
112	

# Chicago Public Schools

School Taft High School Unit 46311 Building ID 1580

Address 6545 W. Hurlburt St. Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
113	
114	
115	
116	
117	
118	
119	
12	
120	
121	
122	
123	
124	
125	
126	
127	
128	
129	
13	
130	
131	
132	
132 A	
133	
134	
135	
136	
137	
138	

# Chicago Public Schools

School Taft High School Unit 46311 Building ID 1580

Address 6545 W. Hurlburt St. Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
139	
14	
140	
141	
142	
143	
143A	
144	
16	
17	
19	
20	
21	
27	
31	
55	
58	
61	
65	
66	
67	
68	
69	
70	
71	
72	
73	
74	
75	

# Chicago Public Schools

School Taft High School Unit 46311 Building ID 1580

Address 6545 W. Hurlburt St. Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
76	
77	
78	
79	
80	
81	
82	
84	
85	
86	
87	
88	
89	
90	
91	
92	
93	
94	
95	
98	
99	
HA-1000	
HA-1001	
HA-1002	
HA-1003	
HA-1004	
HA-1005	
HA-1006	
HA-1007	

# Chicago Public Schools

**School** Taft High School **Unit** 46311 **Building ID** 1580

**Address** 6545 W. Hurlburt St. **Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
HA-1008	



**Table II**

**Management Planner's Review**

---

# Chicago Public Schools

**School** Taft High School  
**Address** 6545 W. Hurlburt St.

**Unit** 46311  
Chicago, IL, 60631

**Building ID** 1580  
**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
01	12"x12" White w/ Beige Speckles VFT	200	SF	Basement Break Room, 1939 Building	Assumed	MISC		0	SF	6 ACBM with the potential for damage	Follow O&M Plan
02	12"x12" White w/ Gray Streaks VFT	34,500	SF	Throughout Building 1939 Building	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
03	12"x12" Brown w/ White Streaks VFT	1,600	SF	Room 119-121 Wood Shop, 1939 Building	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
04	12"x12" White w/ Beige Streaks VFT	700	SF	Engineers Office Room 321, 1939 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
05	12"x12" White w/ Beige Streaks VFT NEVER EXISTED			Room 321, 1939 Building NEVER EXISTED		MISC					
06	9"x9" Light Brown w/ Beige Streaks VFT	100	SF	Engineer's Office Hallway, 1939 Building	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
07	12"x12" Dark Gray w/ White Streaks VFT	98		First Floor Corridor by Mens and Womens Toilet, 1974 Building	Assumed	MISC	No	0		6 ACBM with the potential for damage	Follow O&M Plan
08	12"x12" Light Gray w/ Gray Speckles VFT	98	SF	Throughout, 1974 Building	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
09	12"x12" Off White w/ Tan Specks VFT	2,000	SF	Room 146, 147, 157A, 247, 2nd Floor Hallway, 1974 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
10	12"x12" White w/ Gold Streaks VFT	2,000	SF	Throughout, 1974 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
100	12"x12" Off White w/ Gray Streaks VFT Mastic	2,000	SF	Rms 214, 216, 300, 300A, and 300L; 1st through 3rd Floor South Corridor - 1939 Building	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
101	2'x4' White w/ Deep Grooves Ceiling Tile			Room 173, 174, 1974 Building	No ACBM						
102	12" x 12" Brown w/ Black Specks VFT	1,010	SF	Room 155, 176, 247, Kitchen Office, 1974 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
103	12" x 12" Brown w/ Black Specks VFT Mastic	1,010	SF	Room 155, 176, 247, Kitchen Office, 1974 Building	Assumed	MISC		0	SF	6 ACBM with the potential for damage	Follow O&M Plan
104	12" x 12" White w/ Gray Specks VFT	500	SF	Room 207, Teachers Lounge, 1974 Building	Assumed	MISC		0	SF	6 ACBM with the potential for damage	Follow O&M Plan
105	12" x 12" White w/ Gray Specks VFT Mastic	500	SF	Room 207, Teachers Lounge, 1974 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
106	12" x 12" Off White w/ Beige Streaks VFT	1,000	SF	Room 149, 150, 152, 154, Main Office, 1974 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
107	12" x 12" Off White w/ Beige Streaks VFT Mastic	1,000	SF	Room 149, 150, 152, 154, Main Office, 1974 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
108	12" x 12" Brown w/ White & Black Specks VFT- NOT OBSERVED			Room 149, 158-160, 1974 Building NOT OBSERVED							
109	12" x 12" Brown w/ White & Black Specks VFT Mastic- NOT OBSERVED			Room 149, 158-160, 1974 Building NOT OBSERVED							

# Chicago Public Schools

**School** Taft High School  
**Address** 6545 W. Hurlburt St.

**Unit** 46311  
Chicago, IL, 60631

**Building ID** 1580  
**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
11	12"x12" Light Brown w/ White Streaks VFT	2,000	SF	Room 151, 153, 171, 184, 256, 263, 1974 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
110	12" x 12" White w/ Beige Speckles VFT Mastic- NOT OBSERVED			Room 311, Break Room, 1939 Building NOT OBSERVED							
111	12"x12" White w/ Gray Streaks VFT Mastic	1,000	SF	Throughout Building (See Hatching Maps), 1939 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
112	12"x12" Brown w/ White Streaks VFT Mastic	1,000	SF	Room 119-121 Wood Shop, 1939 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
113	12"x12" Brown w/ Beige Streaks VFT Mastic	650	SF	Room 321, 1939 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
114	12"x12" White w/ Beige Streaks VFT Mastic	650	SF	Room 321, 1939 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
115	9"x9" Light Brown w/ Beige Streaks VFT	100	SF	Engineer's Office Hallway, 1939 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
116	12"x12" Dark Gray w/ White Streaks VFT Mastic	200	SF	First Floor Corridor by Mens and Womens Toilet, 1974 Building	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
117	12"x12" Light Gray w/ Gray Speckles VFT Mastic	23,465	SF	Throughout (See Hatching Maps), 1974 Building	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
118	12"x12" Off White w/ Tan Specks VFT Mastic	2,000	SF	Room 146, 147, 157A, 247, 2nd Floor Hallway, 1974 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
119	12"x12" White w/ Gold Streaks VFT Mastic	2,000	SF	Throughout, 1974 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
12	12"x12" Yellow w/ White Streaks VFT	2,000	SF	Room 151, 153, 171, 184, 256, 283, 1974 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
120	12"x12" Light Brown w/ White Streaks VFT Mastic	2,000	SF	Room 151, 153, 171, 184, 256, 263, 1974 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
121	12"x12" Yellow w/ White Streaks VFT Mastic	2,000	SF	Room 151, 153, 171, 184, 256, 263, 1974 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
122	12"x12" Green Speckles VFT Mastic	6,000	SF	Lunchroom, Lunchroom W. Storeroom, 1974 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
123	12"x12" Yellow Speckled VFT Mastic	3,000	SF	Lunchroom, 1974 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
124	1' x 1' White w/ Deep Grooves Ceiling Tile			Room 187, 1974	No ACBM						
125	12" x 12" White w/ Light Green Streaks VFT	1,500	SF	Room 306, 1939 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
126	12" x 12" White w/ Light Green Streaks VFT Mastic	1,500	SF	Room 306, 1939 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
127	Beige w/ Purple Streaks Linoleum			Room 213, 213 A, 1939 Building	No ACBM						
128	Beige w/ Purple Streaks Linoleum Mastic			Room 213, 213 A, 1939 Building	No ACBM						
129	2' x 4' Dot Ceiling Tile			Room 213, 213 A, 1939 Building	No ACBM						
13	12"x12" Green Speckles VFT	6,000	SF	Lunchroom, Lunchroom W. Storeroom, 1974 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Taft High School  
**Address** 6545 W. Hurlburt St.

**Unit** 46311  
Chicago, IL, 60631

**Building ID** 1580  
**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
130	12" x 12" Dark Gray VFT	700	SF	Room 140, 142, 1958 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
131	12" x 12" Dark Gray VFT Mastic	700	SF	Room 140, 142, 1958 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
132	12 x 12 inch Beige w/Gray & Tan Streaks VFT ABATED			Rooms: 300, 302, 308, 310, 311-313, 316 - 1939 Building ABATED	Abated	MISC					
132 A	12 x 12 inch Beige w/Gray & Tan Streaks VFT Mastic ABATED			Rooms: 300, 302, 308, 310, 311-313, 316 - 1939 Building ABATED	Abated	MISC					
133	Carpet Mastic	8,000	SF	1974 - Choir Room, Band Room, Library, Main Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
134	Carpet Mastic	2,050	SF	1939 - Rooms 206, 208 and 210	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
135	Terrazo	2,000	SF	1979- Stairwells	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
136	Terrazo	2,000	SF	1939 - Halls	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
137	Terrazo	1,000	SF	1958 - Gym Lobby	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
138	Cardboard Pipe Insulation (Paper Wrap on Insulation)	60	LF	Chase Behind Rm 134	Assumed	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
139	MJP E/V/F on Cardboard Pipe Insulation (Paper Wrap on Pipe Insulation)	60	LF	Chase Behind Rm 134	Assumed	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
14	12"x12" Yellow Speckled VFT	3,000	SF	Lunchroom, 1974 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
140	2'x4' Ceiling tile w/ grooves	33,000	SF	Throughout 1939 addition	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
141	Carpet MASTIC	1,500	SF	174, 172, corridor both sides of exit #4, addition 1974	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
142	Carpet MASTIC	1,600	SF	Auditorium between the isles, 230, 330 - addition 1958	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
143	12"x12" light gray w/ gray streaks VFT	27,900	SF	Throughout	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
143A	12"x12" light gray w/ gray streaks VFT MASTIC	27,900	SF	Throughout	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
144	Tectum panels	6,000	SF	Room 218, 222, 126	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
16	2'x4' Dot Wave Ceiling Tile	2,000	SF	First Floor Corridor, Room 114, 212, 302 A, 1939 Building	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
17	1'x1' White Smooth Ceiling Tile	120	SF	Room 320, 1939 Building	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
19	2'x4' White w/ Pin Holes Ceiling Tile (No ACBM)			Room 246, 247, 250, 252, 253, 256, 264, 1974 Building	No ACBM	MISC					
20	1'x1' White w/ Deep Grooves Ceiling Tile			Room 173, 1974 Building	No ACBM	MISC					
21	1'x1' White w/ Small Holes Ceiling Tile			Serving Room, Kitchen, 151/183 Hallway, 1974 Building	No ACBM						
27	Black Table Tops			Room 300, 302A, 305-307, 1939 Building		MISC					
31	Hardcoat Plaster	2,000	SF	Throughout, 1939 Building	Assumed	MISC		0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Taft High School  
**Address** 6545 W. Hurlburt St.

**Unit** 46311  
 Chicago, IL, 60631

**Building ID** 1580  
**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

### *Management Planner's Comments Summarized at the End of the Report*

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
55	Drywall Joint Compound			Janitors Closets, Boys and Girls Toilets, 1974 Building	No ACBM						
58	MJP E/F/V on Fiberglass Pipe Insulation			Sprinkler Rm, Chiller Rm, W. Crawlspace, Carpenters Shop, Plenum Chamber, 1939 Building		TSI					
61	MJP E/F/V on Fiberglass Pipe Insulation			Sprinkler Room, Carpenter Shop, Basement Corridor, 1974 Building	No ACBM						
65	12" x 12" Brown w/ White Streaks VFT	890	SF	Room 342, 1958 Building	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
66	12" x 12" Brown w/ White Streaks VFT Mastic	890	SF	Room 342, 1958 Building	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
67	12" x 12" Light Gray w/ Dark Gray Specks VFT	3,571	SF	Throughout Building (See Hatching Maps), 1958 Building	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
68	12" x 12" Light Gray w/ Drk Gray Specks VFT Mastic	3,571	SF	Throughout Building (See Hatching Maps), 1958 Building	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
69	2' x 4' White w/ Deep Grooves Ceiling Tile			Room 134, 239, 326, 1958 Building	No ACBM						
70	1' x 1' White w/ Deep Grooves Ceiling Tile			Gymnasium Lobby, 1958 Building	No ACBM						
71	MJP E/F/V on Fiberglass Pipe Insulation	20	LF	Fan Units, Unfinished Pipe Space, Rifle Range, 1958 Building	Assumed	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
72	Hard Coat Plaster	10,000	SF	Throughout, 1958 Building	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
73	Exterior Window Glaze			Exterior Windows, 1939 Building	No ACBM						
74	Exterior Window Glaze			Exterior Windows, 1958 Building	No ACBM						
75	Exterior Window Glaze			Exterior Windows, 1974 Building	No ACBM						
76	Exterior Window Caulk			Exterior Windows, 1939 Building	No ACBM						
77	Exterior Window Caulk			Exterior Windows, 1958 Building	No ACBM						
78	Exterior Window Caulk			Exterior Windows, 1974 Building	No ACBM						
79	Interior Window Caulk			Interior Windows, 1939 Building	No ACBM						
80	Interior Window Glaze			Interior Windows, 1939 Building	No ACBM						
81	Interior Window Glaze			Interior Windows, 1958 Building	No ACBM						
82	Interior Window Glaze			Interior Windows, 1974 Building	No ACBM						
84	9"x9" Red VFT	10	SF	Stage South Stairwell, 1939 Building	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
85	9"x9" Red VFT Mastic	10	SF	Stage South Stairwell, 1939 Building	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
86	9"x9" Black VFT	10	SF	Stage South Stairwell, 1939 Building	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
87	9"x9" Black VFT Mastic	10	SF	Stage South Stairwell, 1939 Building	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
88	2"x18" Black VFT	36	SF	Stage South Stairwell, 1939 Building	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
89	2"x18" Black VFT Mastic	36	SF	Stage South Stairwell, 1939 Building	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
90	12"x12" Tan w/ Brown Streaks VFT	400	SF	121 Woodshop, 1939 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Taft High School  
**Address** 6545 W. Hurlburt St.

**Unit** 46311  
 Chicago, IL, 60631

**Building ID** 1580  
**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

### *Management Planner's Comments Summarized at the End of the Report*

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
91	12"x12" Tan w/ Brown Streaks VFT Mastic	400	SF	121 Woodshop, 1939 Building	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
92	12"x12" Tan w/ Brown & White Streaks VFT ABATED			Room 117, 1939 Building ABATED	Abated	MISC					
93	12"x12" Tan w/ Brown & White Streaks VFT Mastic ABATED			Room 117, 1939 Building ABATED	Abated	MISC					
94	Brown Linoleum- NOT OBSERVED			2nd Floor Teachers Lounge, 1939 Building--NOT OBSERVED							
95	Brown Linoleum Mastic- NOT OBSERVED			2nd Floor Teachers Lounge, 1939 Building NOT OBSERVED							
98	2'x4' Dot Wave Ceiling Tile	1,000	SF	Room 106, 112, 216, 300, 1939 Building	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
99	12"x12" Off White w/ Gray Streaks VFT	2,000	SF	Rms 214, 216, 300, 300A, and 300L; 1st through 3rd Floor South Corridor - 1939 Building	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
HA-1000	5'x2.5' ceiling tile with random pinholes	10,000	SF	throughout 1974 bldg	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
HA-1001	Black table and counter tops ABATED			Rms. 300,302, 302A,305,308,310,312,313,316 ABATED	Abated	MISC					
HA-1002	Gray lab table and counter tops ABATED			Rm. 183 ABATED	Abated	MISC					
HA-1003	MJP E/V/F on Cardboard Pipe Insulation (Paper Wrap on Insulation)	155	SF	Chase Behind Rm 134	Assumed	TSI	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
HA-1004	Gray transite panel ABATED			Exhaust hood in Rm. 302A ABATED	Abated	MISC					
HA-1005	Beige Linoleum	1,200	SF	Rooms 311 & 313	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
HA-1006	Grey w White Streaks Linoleum	4,500	SF	Rooms 302, 303, 305, 307, 308, 310, 312, and 316	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
HA-1007	12"x12" White w/Gray Streaks VFT	600	SF	Rm 117	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
HA-1008	12"x12" White w/Gray Streaks VFT Mastic	600	SF	Rm 117	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Taft High School  
**Address** 6545 W. Hurlburt St.

**Unit** 46311  
 Chicago, IL, 60631

**Building ID** 1580  
**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG Consultants, Inc.  
 855 W. Adams St., Ste. 200  
 Phone: (312) 733-6262

Fax: (312) 733-5612

*Management Planner's Comments Summarized at the End of the Report*

Review Date	5/19/2016
Manager Planner Name	Arturo Saenz
100-04019	1/19/2017
Manager IDPH License No/Expiration	

HA Number	Management Comments
01	
02	
03	
04	
05	
06	
07	
08	
09	

# Chicago Public Schools

**School** Taft High School  
**Address** 6545 W. Hurlburt St.

**Unit** 46311  
 Chicago, IL, 60631

**Building ID** 1580  
**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG Consultants, Inc.  
 855 W. Adams St., Ste. 200  
 Phone: (312) 733-6262

Fax: (312) 733-5612

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
10	
100	
101	
102	
103	
104	
105	
106	
107	
108	
109	
11	
110	
111	
112	
113	
114	
115	
116	
117	
118	
119	
12	
120	
121	
122	
123	



# Chicago Public Schools

**School** Taft High School  
**Address** 6545 W. Hurlburt St.

**Unit** 46311  
 Chicago, IL, 60631

**Building ID** 1580  
**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

*Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
124	
125	
126	
127	
128	
129	
13	
130	
131	
132	
132 A	
133	
134	
135	
136	
137	
138	
139	
14	
140	
141	
142	
143	
143A	
144	
16	
17	

# Chicago Public Schools

**School** Taft High School  
**Address** 6545 W. Hurlburt St.

**Unit** 46311  
Chicago, IL, 60631

**Building ID** 1580  
**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
19	
20	
21	
27	
31	
55	
58	
61	
65	
66	
67	
68	
69	
70	
71	
72	
73	
74	
75	
76	
77	
78	
79	
80	
81	
82	
84	

# Chicago Public Schools

**School** Taft High School  
**Address** 6545 W. Hurlburt St.

**Unit** 46311  
 Chicago, IL, 60631

**Building ID** 1580  
**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262                      Fax: (312) 733-5612

*Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
85	
86	
87	
88	
89	
90	
91	
92	
93	
94	
95	
98	
99	
HA-1000	
HA-1001	
HA-1002	
HA-1003	
HA-1004	
HA-1005	
HA-1006	
HA-1007	
HA-1008	

# Chicago Public Schools

GSG Consultants, Inc.

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **Taft High School** INSPECTION DATE: **4/28/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **01**  
MATERIAL DESCRIPTION: **12"x12" White w/ Beige Speckles VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Basement Break Room, 1939 Building**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/28/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Taft High School** REVIEW DATE: **5/19/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **01**  
MATERIAL DESCRIPTION: **12"x12" White w/ Beige Speckles VFT**  
MATERIAL LOCATION: **Basement Break Room, 1939 Building**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **Taft High School** INSPECTION DATE: **4/28/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **02**  
MATERIAL DESCRIPTION: **12"x12" White w/ Gray Streaks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Throughout Building 1939 Building**  
MATERIAL QUANTITY: **34500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/28/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Taft High School** REVIEW DATE: **5/19/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **02**  
MATERIAL DESCRIPTION: **12"x12" White w/ Gray Streaks VFT**  
MATERIAL LOCATION: **Throughout Building 1939 Building**  
MATERIAL QUANTITY: **34500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **Taft High School** INSPECTION DATE: **4/28/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **03**  
MATERIAL DESCRIPTION: **12"x12" Brown w/ White Streaks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Room 119-121 Wood Shop, 1939 Building**  
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/28/2016



# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Taft High School** REVIEW DATE: **5/19/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **03**  
MATERIAL DESCRIPTION: **12"x12" Brown w/ White Streaks VFT**  
MATERIAL LOCATION: **Room 119-121 Wood Shop, 1939 Building**  
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **Taft High School** INSPECTION DATE: **4/28/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **04**  
MATERIAL DESCRIPTION: **12"x12" White w/ Beige Streaks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Engineers Office Room 321, 1939 Building**  
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/28/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUILDING ID: **1580**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Taft High School** REVIEW DATE: **5/19/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **04**  
MATERIAL DESCRIPTION: **12"x12" White w/ Beige Streaks VFT**  
MATERIAL LOCATION: **Engineers Office Room 321, 1939 Building**  
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **Taft High School** INSPECTION DATE: **4/28/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **05**  
MATERIAL DESCRIPTION: **12"x12" White w/ Beige Streaks VFT NEVER EXISTED**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 321, 1939 Building NEVER EXISTED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/28/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUILDING ID: **1580**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Taft High School** REVIEW DATE: **5/19/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **05**

MATERIAL DESCRIPTION: **12"x12" White w/ Beige Streaks VFT NEVER EXISTED**

MATERIAL LOCATION: **Room 321, 1939 Building NEVER EXISTED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **Taft High School** INSPECTION DATE: **4/28/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **06**  
MATERIAL DESCRIPTION: **9"x9" Light Brown w/ Beige Streaks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Engineer's Office Hallway,1939 Building**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/28/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUILDING ID: **1580**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Taft High School** REVIEW DATE: **5/19/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **06**  
MATERIAL DESCRIPTION: **9"x9" Light Brown w/ Beige Streaks VFT**  
MATERIAL LOCATION: **Engineer's Office Hallway, 1939 Building**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **Taft High School** INSPECTION DATE: **4/28/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **07**  
MATERIAL DESCRIPTION: **12"x12" Dark Gray w/ White Streaks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **First Floor Corridor by Mens and Womens Toilet, 1974 Building**  
MATERIAL QUANTITY: **98** MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/28/2016



# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUILDING ID: **1580**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Taft High School** REVIEW DATE: **5/19/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **07**  
MATERIAL DESCRIPTION: **12"x12" Dark Gray w/ White Streaks VFT**  
MATERIAL LOCATION: **First Floor Corridor by Mens and Womens Toilet, 1974 Building**  
MATERIAL QUANTITY: **98** MATERIAL UNITS:  
DAMAGE QUANTITY: **0** DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **Taft High School** INSPECTION DATE: **4/28/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **08**  
MATERIAL DESCRIPTION: **12"x12" Light Gray w/ Gray Speckles VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Throughout, 1974 Building**

MATERIAL QUANTITY: **98** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/28/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Taft High School** REVIEW DATE: **5/19/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **08**  
MATERIAL DESCRIPTION: **12"x12" Light Gray w/ Gray Speckles VFT**  
MATERIAL LOCATION: **Throughout, 1974 Building**  
MATERIAL QUANTITY: **98** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **Taft High School** INSPECTION DATE: **4/28/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **09**  
MATERIAL DESCRIPTION: **12"x12" Off White w/ Tan Specks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Room 146, 147, 157A, 247, 2nd Floor Hallway, 1974 Building**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/28/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Taft High School** REVIEW DATE: **5/19/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **09**  
MATERIAL DESCRIPTION: **12"x12" Off White w/ Tan Specks VFT**  
MATERIAL LOCATION: **Room 146, 147, 157A, 247, 2nd Floor Hallway, 1974 Building**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **Taft High School** INSPECTION DATE: **4/28/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10**  
MATERIAL DESCRIPTION: **12"x12" White w/ Gold Streaks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Throughout, 1974 Building**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/28/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUILDING ID: **1580**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Taft High School** REVIEW DATE: **5/19/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **10**  
MATERIAL DESCRIPTION: **12"x12" White w/ Gold Streaks VFT**  
MATERIAL LOCATION: **Throughout, 1974 Building**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUILDING ID: **1580**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **Taft High School** INSPECTION DATE: **4/28/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **100**  
MATERIAL DESCRIPTION: **12"x12" Off White w/ Gray Streaks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rms 214, 216, 300, 300A, and 300L; 1st through 3rd Floor South Corridor - 1939 Building**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/28/2016



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Taft High School** REVIEW DATE: **5/19/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **100**  
MATERIAL DESCRIPTION: **12"x12" Off White w/ Gray Streaks VFT Mastic**  
MATERIAL LOCATION: **Rms 214, 216, 300, 300A, and 300L; 1st through 3rd Floor South Corridor - 1939 Building**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **Taft High School** INSPECTION DATE: **4/28/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **101**  
MATERIAL DESCRIPTION: **2'x4' White w/ Deep Grooves Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 173, 174, 1974 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **04/28/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUILDING ID: **1580**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Taft High School** REVIEW DATE: **5/19/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **101**  
MATERIAL DESCRIPTION: **2'x4' White w/ Deep Grooves Ceiling Tile**  
MATERIAL LOCATION: **Room 173, 174, 1974 Building**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **Taft High School** INSPECTION DATE: **4/28/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **102**  
MATERIAL DESCRIPTION: **12" x 12" Brown w/ Black Specks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Room 155, 176, 247, Kitchen Office, 1974 Building**  
MATERIAL QUANTITY: **1010** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/28/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUILDING ID: **1580**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Taft High School** REVIEW DATE: **5/19/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **102**  
MATERIAL DESCRIPTION: **12" x 12" Brown w/ Black Specks VFT**  
MATERIAL LOCATION: **Room 155, 176, 247, Kitchen Office, 1974 Building**  
MATERIAL QUANTITY: **1010** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **Taft High School** INSPECTION DATE: **4/28/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **103**  
MATERIAL DESCRIPTION: **12" x 12" Brown w/ Black Specks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 155, 176, 247, Kitchen Office, 1974 Building**  
MATERIAL QUANTITY: **1010** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/28/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Taft High School** REVIEW DATE: **5/19/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **103**  
MATERIAL DESCRIPTION: **12" x 12" Brown w/ Black Specks VFT Mastic**  
MATERIAL LOCATION: **Room 155, 176, 247, Kitchen Office, 1974 Building**  
MATERIAL QUANTITY: **1010** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **Taft High School** INSPECTION DATE: **4/28/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **104**  
MATERIAL DESCRIPTION: **12" x 12" White w/ Gray Specks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Room 207, Teachers Lounge, 1974 Building**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/28/2016



# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Taft High School** REVIEW DATE: **5/19/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **104**  
MATERIAL DESCRIPTION: **12" x 12" White w/ Gray Specks VFT**  
MATERIAL LOCATION: **Room 207, Teachers Lounge, 1974 Building**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **Taft High School** INSPECTION DATE: **4/28/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **105**  
MATERIAL DESCRIPTION: **12" x 12" White w/ Gray Specks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 207, Teachers Lounge, 1974 Building**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/28/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Taft High School** REVIEW DATE: **5/19/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **105**  
MATERIAL DESCRIPTION: **12" x 12" White w/ Gray Specks VFT Mastic**  
MATERIAL LOCATION: **Room 207, Teachers Lounge, 1974 Building**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **Taft High School** INSPECTION DATE: **4/28/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **106**  
MATERIAL DESCRIPTION: **12" x 12" Off White w/ Beige Streaks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Room 149, 150, 152, 154, Main Office, 1974 Building**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/28/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUILDING ID: **1580**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Taft High School** REVIEW DATE: **5/19/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **106**  
MATERIAL DESCRIPTION: **12" x 12" Off White w/ Beige Streaks VFT**  
MATERIAL LOCATION: **Room 149, 150, 152, 154, Main Office, 1974 Building**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **Taft High School** INSPECTION DATE: **4/28/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **107**  
MATERIAL DESCRIPTION: **12" x 12" Off White w/ Beige Streaks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 149, 150, 152, 154, Main Office, 1974 Building**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/28/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUILDING ID: **1580**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Taft High School** REVIEW DATE: **5/19/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **107**  
MATERIAL DESCRIPTION: **12" x 12" Off White w/ Beige Streaks VFT Mastic**  
MATERIAL LOCATION: **Room 149, 150, 152, 154, Main Office, 1974 Building**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **46311**    BUILDING ID: **1580**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **Taft High School**    INSPECTION DATE: **4/28/2016**  
ADDRESS: **6545 W. Hurlburt St.**    IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **108**  
MATERIAL DESCRIPTION: **12" x 12" Brown w/ White & Black Specks VFT- NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE:    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 149, 158-160, 1974 Building NOT OBSERVED**

MATERIAL QUANTITY:    MATERIAL UNITS:

DAMAGE QUANTITY:    DAMAGE UNITS:

COMMENTS: **NOT OBSERVED**

Inspector's Signature: \_\_\_\_\_ Date: **04/28/2016**



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUILDING ID: **1580**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Taft High School** REVIEW DATE: **5/19/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **108**  
MATERIAL DESCRIPTION: **12" x 12" Brown w/ White & Black Specks VFT- NOT OBSERVED**  
MATERIAL LOCATION: **Room 149, 158-160, 1974 Building NOT OBSERVED**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **46311**    BUILDING ID: **1580**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **Taft High School**    INSPECTION DATE: **4/28/2016**  
ADDRESS: **6545 W. Hurlburt St.**    IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **109**  
MATERIAL DESCRIPTION: **12" x 12" Brown w/ White & Black Specks VFT Mastic- NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE:    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 149, 158-160, 1974 Building NOT OBSERVED**

MATERIAL QUANTITY:    MATERIAL UNITS:

DAMAGE QUANTITY:    DAMAGE UNITS:

COMMENTS: **NOT OBSERVED**

Inspector's Signature: \_\_\_\_\_ Date: **04/28/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUILDING ID: **1580**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Taft High School** REVIEW DATE: **5/19/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **109**  
MATERIAL DESCRIPTION: **12" x 12" Brown w/ White & Black Specks VFT Mastic- NOT OBSERVED**  
MATERIAL LOCATION: **Room 149, 158-160, 1974 Building NOT OBSERVED**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **Taft High School** INSPECTION DATE: **4/28/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11**  
MATERIAL DESCRIPTION: **12"x12" Light Brown w/ White Streaks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Room 151, 153, 171, 184, 256, 263, 1974 Building**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/28/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUILDING ID: **1580**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Taft High School** REVIEW DATE: **5/19/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **11**  
MATERIAL DESCRIPTION: **12"x12" Light Brown w/ White Streaks VFT**  
MATERIAL LOCATION: **Room 151, 153, 171, 184, 256, 263, 1974 Building**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **Taft High School** INSPECTION DATE: **4/28/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **110**  
MATERIAL DESCRIPTION: **12" x 12" White w/ Beige Speckles VFT Mastic- NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 311, Break Room, 1939 Building NOT OBSERVED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **NOT OBSERVED**

Inspector's Signature: \_\_\_\_\_ Date: **04/28/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUILDING ID: **1580**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Taft High School** REVIEW DATE: **5/19/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **110**  
MATERIAL DESCRIPTION: **12" x 12" White w/ Beige Speckles VFT Mastic- NOT OBSERVED**  
MATERIAL LOCATION: **Room 311, Break Room, 1939 Building NOT OBSERVED**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **46311**    BUILDING ID: **1580**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **Taft High School**    INSPECTION DATE: **4/28/2016**  
ADDRESS: **6545 W. Hurlburt St.**    IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **111**  
MATERIAL DESCRIPTION: **12"x12" White w/ Gray Streaks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout Building (See Hatching Maps), 1939 Building**  
MATERIAL QUANTITY: **1000**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY:    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/28/2016



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUILDING ID: **1580**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Taft High School** REVIEW DATE: **5/19/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **111**  
MATERIAL DESCRIPTION: **12"x12" White w/ Gray Streaks VFT Mastic**  
MATERIAL LOCATION: **Throughout Building (See Hatching Maps), 1939 Building**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **Taft High School** INSPECTION DATE: **4/28/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **112**  
MATERIAL DESCRIPTION: **12"x12" Brown w/ White Streaks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 119-121 Wood Shop, 1939 Building**

MATERIAL QUANTITY: **1000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 04/28/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUILDING ID: **1580**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Taft High School** REVIEW DATE: **5/19/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **112**  
MATERIAL DESCRIPTION: **12"x12" Brown w/ White Streaks VFT Mastic**  
MATERIAL LOCATION: **Room 119-121 Wood Shop, 1939 Building**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **Taft High School** INSPECTION DATE: **4/28/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **113**  
MATERIAL DESCRIPTION: **12"x12" Brown w/ Beige Streaks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 321, 1939 Building**  
MATERIAL QUANTITY: **650** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/28/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUILDING ID: **1580**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Taft High School** REVIEW DATE: **5/19/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **113**  
MATERIAL DESCRIPTION: **12"x12" Brown w/ Beige Streaks VFT Mastic**  
MATERIAL LOCATION: **Room 321, 1939 Building**  
MATERIAL QUANTITY: **650** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **Taft High School** INSPECTION DATE: **4/28/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **114**  
MATERIAL DESCRIPTION: **12"x12" White w/ Beige Streaks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 321, 1939 Building**  
MATERIAL QUANTITY: **650** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/28/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Taft High School** REVIEW DATE: **5/19/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **114**  
MATERIAL DESCRIPTION: **12"x12" White w/ Beige Streaks VFT Mastic**  
MATERIAL LOCATION: **Room 321, 1939 Building**  
MATERIAL QUANTITY: **650** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **Taft High School** INSPECTION DATE: **4/28/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **115**  
MATERIAL DESCRIPTION: **9"x9" Light Brown w/ Beige Streaks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Engineer's Office Hallway,1939 Building**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/28/2016



# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUILDING ID: **1580**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Taft High School** REVIEW DATE: **5/19/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **115**  
MATERIAL DESCRIPTION: **9"x9" Light Brown w/ Beige Streaks VFT**  
MATERIAL LOCATION: **Engineer's Office Hallway, 1939 Building**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **Taft High School** INSPECTION DATE: **4/28/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **116**  
MATERIAL DESCRIPTION: **12"x12" Dark Gray w/ White Streaks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **First Floor Corridor by Mens and Womens Toilet, 1974 Building**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/28/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUILDING ID: **1580**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Taft High School** REVIEW DATE: **5/19/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **116**  
MATERIAL DESCRIPTION: **12"x12" Dark Gray w/ White Streaks VFT Mastic**  
MATERIAL LOCATION: **First Floor Corridor by Mens and Womens Toilet, 1974 Building**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **Taft High School** INSPECTION DATE: **4/28/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **117**  
MATERIAL DESCRIPTION: **12"x12" Light Gray w/ Gray Speckles VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Throughout (See Hatching Maps), 1974 Building**

MATERIAL QUANTITY: **23465** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/28/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Taft High School** REVIEW DATE: **5/19/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **117**  
MATERIAL DESCRIPTION: **12"x12" Light Gray w/ Gray Speckles VFT Mastic**  
MATERIAL LOCATION: **Throughout (See Hatching Maps), 1974 Building**  
MATERIAL QUANTITY: **23465** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **Taft High School** INSPECTION DATE: **4/28/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **118**  
MATERIAL DESCRIPTION: **12"x12" Off White w/ Tan Specks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 146, 147, 157A, 247, 2nd Floor Hallway, 1974 Building**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/28/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUILDING ID: **1580**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Taft High School** REVIEW DATE: **5/19/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **118**  
MATERIAL DESCRIPTION: **12"x12" Off White w/ Tan Specks VFT Mastic**  
MATERIAL LOCATION: **Room 146, 147, 157A, 247, 2nd Floor Hallway, 1974 Building**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **Taft High School** INSPECTION DATE: **4/28/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **119**  
MATERIAL DESCRIPTION: **12"x12" White w/ Gold Streaks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Throughout, 1974 Building**

MATERIAL QUANTITY: **2000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 04/28/2016



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUILDING ID: **1580**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Taft High School** REVIEW DATE: **5/19/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **119**  
MATERIAL DESCRIPTION: **12"x12" White w/ Gold Streaks VFT Mastic**  
MATERIAL LOCATION: **Throughout, 1974 Building**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **Taft High School** INSPECTION DATE: **4/28/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12**  
MATERIAL DESCRIPTION: **12"x12" Yellow w/ White Streaks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Room 151, 153, 171, 184, 256, 283, 1974 Building**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/28/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Taft High School** REVIEW DATE: **5/19/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **12**  
MATERIAL DESCRIPTION: **12"x12" Yellow w/ White Streaks VFT**  
MATERIAL LOCATION: **Room 151, 153, 171, 184, 256, 283, 1974 Building**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUILDING ID: **1580**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **Taft High School** INSPECTION DATE: **4/28/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **120**  
MATERIAL DESCRIPTION: **12"x12" Light Brown w/ White Streaks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 151, 153, 171, 184, 256, 263, 1974 Building**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/28/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUILDING ID: **1580**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Taft High School** REVIEW DATE: **5/19/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **120**  
MATERIAL DESCRIPTION: **12"x12" Light Brown w/ White Streaks VFT Mastic**  
MATERIAL LOCATION: **Room 151, 153, 171, 184, 256, 263, 1974 Building**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **Taft High School** INSPECTION DATE: **4/28/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **121**  
MATERIAL DESCRIPTION: **12"x12" Yellow w/ White Streaks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 151, 153, 171, 184, 256, 263, 1974 Building**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/28/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Taft High School** REVIEW DATE: **5/19/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **121**  
MATERIAL DESCRIPTION: **12"x12" Yellow w/ White Streaks VFT Mastic**  
MATERIAL LOCATION: **Room 151, 153, 171, 184, 256, 263, 1974 Building**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **Taft High School** INSPECTION DATE: **4/28/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **122**  
MATERIAL DESCRIPTION: **12"x12" Green Speckles VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Lunchroom, Lunchroom W. Storeroom, 1974 Building**  
MATERIAL QUANTITY: **6000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/28/2016



# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Taft High School** REVIEW DATE: **5/19/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **122**  
MATERIAL DESCRIPTION: **12"x12" Green Speckles VFT Mastic**  
MATERIAL LOCATION: **Lunchroom, Lunchroom W. Storeroom, 1974 Building**  
MATERIAL QUANTITY: **6000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **Taft High School** INSPECTION DATE: **4/28/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **123**  
MATERIAL DESCRIPTION: **12"x12" Yellow Speckled VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Lunchroom, 1974 Building**

MATERIAL QUANTITY: **3000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 04/28/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Taft High School** REVIEW DATE: **5/19/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **123**  
MATERIAL DESCRIPTION: **12"x12" Yellow Speckled VFT Mastic**  
MATERIAL LOCATION: **Lunchroom, 1974 Building**  
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **Taft High School** INSPECTION DATE: **4/28/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **124**  
MATERIAL DESCRIPTION: **1' x 1' White w/ Deep Grooves Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 187, 1974**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: **04/28/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Taft High School** REVIEW DATE: **5/19/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **124**  
MATERIAL DESCRIPTION: **1' x 1' White w/ Deep Grooves Ceiling Tile**  
MATERIAL LOCATION: **Room 187, 1974**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **Taft High School** INSPECTION DATE: **4/28/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **125**  
MATERIAL DESCRIPTION: **12" x 12" White w/ Light Green Streaks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Room 306, 1939 Building**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/28/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Taft High School** REVIEW DATE: **5/19/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **125**  
MATERIAL DESCRIPTION: **12" x 12" White w/ Light Green Streaks VFT**  
MATERIAL LOCATION: **Room 306, 1939 Building**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **Taft High School** INSPECTION DATE: **4/28/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **126**  
MATERIAL DESCRIPTION: **12" x 12" White w/ Light Green Streaks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 306, 1939 Building**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/28/2016



# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUILDING ID: **1580**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Taft High School** REVIEW DATE: **5/19/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **126**  
MATERIAL DESCRIPTION: **12" x 12" White w/ Light Green Streaks VFT Mastic**  
MATERIAL LOCATION: **Room 306, 1939 Building**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUILDING ID: **1580**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **Taft High School** INSPECTION DATE: **4/28/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **127**  
MATERIAL DESCRIPTION: **Beige w/ Purple Streaks Linoleum**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 213, 213 A, 1939 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **04/28/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUILDING ID: **1580**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Taft High School** REVIEW DATE: **5/19/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **127**  
MATERIAL DESCRIPTION: **Beige w/ Purple Streaks Linoleum**  
MATERIAL LOCATION: **Room 213, 213 A, 1939 Building**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUILDING ID: **1580**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **Taft High School** INSPECTION DATE: **4/28/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **128**  
MATERIAL DESCRIPTION: **Beige w/ Purple Streaks Linoleum Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 213, 213 A, 1939 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **04/28/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUILDING ID: **1580**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Taft High School** REVIEW DATE: **5/19/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **128**  
MATERIAL DESCRIPTION: **Beige w/ Purple Streaks Linoleum Mastic**  
MATERIAL LOCATION: **Room 213, 213 A, 1939 Building**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUILDING ID: **1580**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **Taft High School** INSPECTION DATE: **4/28/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **129**  
MATERIAL DESCRIPTION: **2' x 4' Dot Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 213, 213 A, 1939 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **04/28/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Taft High School** REVIEW DATE: **5/19/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **129**  
MATERIAL DESCRIPTION: **2' x 4' Dot Ceiling Tile**  
MATERIAL LOCATION: **Room 213, 213 A, 1939 Building**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **Taft High School** INSPECTION DATE: **4/28/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13**  
MATERIAL DESCRIPTION: **12"x12" Green Speckles VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Lunchroom, Lunchroom W. Storeroom, 1974 Building**  
MATERIAL QUANTITY: **6000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/28/2016



# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Taft High School** REVIEW DATE: **5/19/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **13**  
MATERIAL DESCRIPTION: **12"x12" Green Speckles VFT**  
MATERIAL LOCATION: **Lunchroom, Lunchroom W. Storeroom, 1974 Building**  
MATERIAL QUANTITY: **6000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **Taft High School** INSPECTION DATE: **4/28/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **130**  
MATERIAL DESCRIPTION: **12" x 12" Dark Gray VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Room 140, 142, 1958 Building**  
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/28/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Taft High School** REVIEW DATE: **5/19/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **130**  
MATERIAL DESCRIPTION: **12" x 12" Dark Gray VFT**  
MATERIAL LOCATION: **Room 140, 142, 1958 Building**  
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUILDING ID: **1580**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **Taft High School** INSPECTION DATE: **4/28/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **131**  
MATERIAL DESCRIPTION: **12" x 12" Dark Gray VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 140, 142, 1958 Building**  
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/28/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Taft High School** REVIEW DATE: **5/19/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **131**  
MATERIAL DESCRIPTION: **12" x 12" Dark Gray VFT Mastic**  
MATERIAL LOCATION: **Room 140, 142, 1958 Building**  
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **Taft High School** INSPECTION DATE: **4/28/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **132**  
MATERIAL DESCRIPTION: **12 x 12 inch Beige w/Gray & Tan Streaks VFT ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms: 300, 302, 308, 310, 311-313, 316 - 1939 Building ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/28/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Taft High School** REVIEW DATE: **5/19/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **132**  
MATERIAL DESCRIPTION: **12 x 12 inch Beige w/Gray & Tan Streaks VFT ABATED**  
MATERIAL LOCATION: **Rooms: 300, 302, 308, 310, 311-313, 316 - 1939 Building ABATED**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **Taft High School** INSPECTION DATE: **4/28/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **132 A**  
MATERIAL DESCRIPTION: **12 x 12 inch Beige w/Gray & Tan Streaks VFT Mastic ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms: 300, 302, 308, 310, 311-313, 316 - 1939 Building ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/28/2016



# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUILDING ID: **1580**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Taft High School** REVIEW DATE: **5/19/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **132 A**  
MATERIAL DESCRIPTION: **12 x 12 inch Beige w/Gray & Tan Streaks VFT Mastic ABATED**  
MATERIAL LOCATION: **Rooms: 300, 302, 308, 310, 311-313, 316 - 1939 Building ABATED**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **Taft High School** INSPECTION DATE: **4/28/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **133**  
MATERIAL DESCRIPTION: **Carpet Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1974 - Choir Room, Band Room, Library, Main Office**  
MATERIAL QUANTITY: **8000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/28/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Taft High School** REVIEW DATE: **5/19/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **133**  
MATERIAL DESCRIPTION: **Carpet Mastic**  
MATERIAL LOCATION: **1974 - Choir Room, Band Room, Library, Main Office**  
MATERIAL QUANTITY: **8000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **Taft High School** INSPECTION DATE: **4/28/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **134**  
MATERIAL DESCRIPTION: **Carpet Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1939 - Rooms 206, 208 and 210**  
MATERIAL QUANTITY: **2050** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/28/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUILDING ID: **1580**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Taft High School** REVIEW DATE: **5/19/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **134**  
MATERIAL DESCRIPTION: **Carpet Mastic**  
MATERIAL LOCATION: **1939 - Rooms 206, 208 and 210**  
MATERIAL QUANTITY: **2050** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **Taft High School** INSPECTION DATE: **4/28/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **135**  
MATERIAL DESCRIPTION: **Terrazo**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1979- Stairwells**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/28/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUILDING ID: **1580**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Taft High School** REVIEW DATE: **5/19/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **135**  
MATERIAL DESCRIPTION: **Terrazo**  
MATERIAL LOCATION: **1979- Stairwells**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **46311**    BUILDING ID: **1580**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **Taft High School**    INSPECTION DATE: **4/28/2016**  
ADDRESS: **6545 W. Hurlburt St.**    IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **136**  
MATERIAL DESCRIPTION: **Terrazo**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1939 - Halls**  
MATERIAL QUANTITY: **2000**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY:    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/28/2016



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Taft High School** REVIEW DATE: **5/19/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **136**  
MATERIAL DESCRIPTION: **Terrazo**  
MATERIAL LOCATION: **1939 - Halls**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **Taft High School** INSPECTION DATE: **4/28/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **137**  
MATERIAL DESCRIPTION: **Terrazo**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1958 - Gym Lobby**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/28/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUILDING ID: **1580**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Taft High School** REVIEW DATE: **5/19/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **137**  
MATERIAL DESCRIPTION: **Terrazo**  
MATERIAL LOCATION: **1958 - Gym Lobby**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **Taft High School** INSPECTION DATE: **4/28/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **138**  
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation (Paper Wrap on Insulation)**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Chase Behind Rm 134**  
MATERIAL QUANTITY: **60** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/28/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Taft High School** REVIEW DATE: **5/19/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **138**  
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation (Paper Wrap on Insulation)**  
MATERIAL LOCATION: **Chase Behind Rm 134**  
MATERIAL QUANTITY: **60** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **Taft High School** INSPECTION DATE: **4/28/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **139**  
MATERIAL DESCRIPTION: **MJP E/V/F on Cardboard Pipe Insulation (Paper Wrap on Pipe Insulation)**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Chase Behind Rm 134**

MATERIAL QUANTITY: **60**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 04/28/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUILDING ID: **1580**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Taft High School** REVIEW DATE: **5/19/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **139**  
MATERIAL DESCRIPTION: **MJP E/V/F on Cardboard Pipe Insulation (Paper Wrap on Pipe Insulation)**  
MATERIAL LOCATION: **Chase Behind Rm 134**  
MATERIAL QUANTITY: **60** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **Taft High School** INSPECTION DATE: **4/28/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14**  
MATERIAL DESCRIPTION: **12"x12" Yellow Speckled VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Lunchroom, 1974 Building**

MATERIAL QUANTITY: **3000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 04/28/2016



# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUILDING ID: **1580**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Taft High School** REVIEW DATE: **5/19/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **14**  
MATERIAL DESCRIPTION: **12"x12" Yellow Speckled VFT**  
MATERIAL LOCATION: **Lunchroom, 1974 Building**  
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **Taft High School** INSPECTION DATE: **4/28/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **140**  
MATERIAL DESCRIPTION: **2'x4' Ceiling tile w/ grooves**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout 1939 addition**  
MATERIAL QUANTITY: **33000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/28/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUILDING ID: **1580**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Taft High School** REVIEW DATE: **5/19/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **140**  
MATERIAL DESCRIPTION: **2'x4' Ceiling tile w/ grooves**  
MATERIAL LOCATION: **Throughout 1939 addition**  
MATERIAL QUANTITY: **33000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **Taft High School** INSPECTION DATE: **4/28/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **141**  
MATERIAL DESCRIPTION: **Carpet MASTIC**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **174, 172, corridor both sides of exit #4, addition 1974**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/28/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Taft High School** REVIEW DATE: **5/19/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **141**  
MATERIAL DESCRIPTION: **Carpet MASTIC**  
MATERIAL LOCATION: **174, 172, corridor both sides of exit #4, addition 1974**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **Taft High School** INSPECTION DATE: **4/28/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **142**  
MATERIAL DESCRIPTION: **Carpet MASTIC**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Auditorium between the isles, 230, 330 - addition 1958**  
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/28/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Taft High School** REVIEW DATE: **5/19/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **142**  
MATERIAL DESCRIPTION: **Carpet MASTIC**  
MATERIAL LOCATION: **Auditorium between the isles, 230, 330 - addition 1958**  
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **Taft High School** INSPECTION DATE: **4/28/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **143**  
MATERIAL DESCRIPTION: **12"x12" light gray w/ gray streaks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Throughout**

MATERIAL QUANTITY: **27900**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 04/28/2016



# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Taft High School** REVIEW DATE: **5/19/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **143**  
MATERIAL DESCRIPTION: **12"x12" light gray w/ gray streaks VFT**  
MATERIAL LOCATION: **Throughout**  
MATERIAL QUANTITY: **27900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **Taft High School** INSPECTION DATE: **4/28/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **143A**  
MATERIAL DESCRIPTION: **12"x12" light gray w/ gray streaks VFT MASTIC**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Throughout**

MATERIAL QUANTITY: **27900**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 04/28/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Taft High School** REVIEW DATE: **5/19/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **143A**  
MATERIAL DESCRIPTION: **12"x12" light gray w/ gray streaks VFT MASTIC**  
MATERIAL LOCATION: **Throughout**  
MATERIAL QUANTITY: **27900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **Taft High School** INSPECTION DATE: **4/28/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **144**  
MATERIAL DESCRIPTION: **Tectum panels**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 218, 222, 126**  
MATERIAL QUANTITY: **6000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/28/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUILDING ID: **1580**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Taft High School** REVIEW DATE: **5/19/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **144**  
MATERIAL DESCRIPTION: **Tectum panels**  
MATERIAL LOCATION: **Room 218, 222, 126**  
MATERIAL QUANTITY: **6000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **Taft High School** INSPECTION DATE: **4/28/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16**  
MATERIAL DESCRIPTION: **2'x4' Dot Wave Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **First Floor Corridor, Room 114, 212, 302 A, 1939 Building**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/28/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUILDING ID: **1580**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Taft High School** REVIEW DATE: **5/19/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **16**  
MATERIAL DESCRIPTION: **2'x4' Dot Wave Ceiling Tile**  
MATERIAL LOCATION: **First Floor Corridor, Room 114, 212, 302 A, 1939 Building**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **46311**    BUILDING ID: **1580**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **Taft High School**    INSPECTION DATE: **4/28/2016**  
ADDRESS: **6545 W. Hurlburt St.**    IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17**  
MATERIAL DESCRIPTION: **1'x1' White Smooth Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 320, 1939 Building**  
MATERIAL QUANTITY: **120**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY:    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/28/2016



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUILDING ID: **1580**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Taft High School** REVIEW DATE: **5/19/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **17**  
MATERIAL DESCRIPTION: **1'x1' White Smooth Ceiling Tile**  
MATERIAL LOCATION: **Room 320, 1939 Building**  
MATERIAL QUANTITY: **120** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **Taft High School** INSPECTION DATE: **4/28/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19**  
MATERIAL DESCRIPTION: **2'x4' White w/ Pin Holes Ceiling Tile (No ACBM)**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 246, 247, 250, 252, 253, 256, 264, 1974 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **04/28/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Taft High School** REVIEW DATE: **5/19/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **19**  
MATERIAL DESCRIPTION: **2'x4' White w/ Pin Holes Ceiling Tile (No ACBM)**  
MATERIAL LOCATION: **Room 246, 247, 250, 252, 253, 256, 264, 1974 Building**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **Taft High School** INSPECTION DATE: **4/28/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**  
MATERIAL DESCRIPTION: **1'x1' White w/ Deep Grooves Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 173, 1974 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **04/28/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Taft High School** REVIEW DATE: **5/19/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **20**

MATERIAL DESCRIPTION: **1'x1' White w/ Deep Grooves Ceiling Tile**

MATERIAL LOCATION: **Room 173, 1974 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **Taft High School** INSPECTION DATE: **4/28/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21**  
MATERIAL DESCRIPTION: **1'x1' White w/ Small Holes Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Serving Room, Kitchen, 151/183 Hallway, 1974 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **04/28/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Taft High School** REVIEW DATE: **5/19/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **21**  
MATERIAL DESCRIPTION: **1'x1' White w/ Small Holes Ceiling Tile**  
MATERIAL LOCATION: **Serving Room, Kitchen, 151/183 Hallway, 1974 Building**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **46311**    BUILDING ID: **1580**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **Taft High School**    INSPECTION DATE: **4/28/2016**  
ADDRESS: **6545 W. Hurlburt St.**    IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27**  
MATERIAL DESCRIPTION: **Black Table Tops**  
HISTORICAL AHERA DAMAGE CATEGORY: **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE:    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 300, 302A, 305-307, 1939 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **04/28/2016**



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUILDING ID: **1580**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Taft High School** REVIEW DATE: **5/19/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **27**

MATERIAL DESCRIPTION: **Black Table Tops**

MATERIAL LOCATION: **Room 300, 302A, 305-307, 1939 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **Taft High School** INSPECTION DATE: **4/28/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **31**  
MATERIAL DESCRIPTION: **Hardcoat Plaster**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Throughout, 1939 Building**

MATERIAL QUANTITY: **2000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 04/28/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Taft High School** REVIEW DATE: **5/19/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **31**  
MATERIAL DESCRIPTION: **Hardcoat Plaster**  
MATERIAL LOCATION: **Throughout, 1939 Building**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **Taft High School** INSPECTION DATE: **4/28/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **55**  
MATERIAL DESCRIPTION: **Drywall Joint Compound**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Janitors Closets, Boys and Girls Toilets, 1974 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **04/28/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUILDING ID: **1580**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Taft High School** REVIEW DATE: **5/19/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **55**

MATERIAL DESCRIPTION: **Drywall Joint Compound**

MATERIAL LOCATION: **Janitors Closets, Boys and Girls Toilets, 1974 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUILDING ID: **1580**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **Taft High School** INSPECTION DATE: **4/28/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **58**  
MATERIAL DESCRIPTION: **MJP E/F/V on Fiberglass Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Sprinkler Rm, Chiller Rm, W. Crawlspace, Carpenters Shop, Plenum Chamber, 1939 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/28/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Taft High School** REVIEW DATE: **5/19/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **58**  
MATERIAL DESCRIPTION: **MJP E/F/V on Fiberglass Pipe Insulation**  
MATERIAL LOCATION: **Sprinkler Rm, Chiller Rm, W. Crawlspace, Carpenters Shop, Plenum Chamber, 1939 Building**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUILDING ID: **1580**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **Taft High School** INSPECTION DATE: **4/28/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **61**  
MATERIAL DESCRIPTION: **MJP E/F/V on Fiberglass Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Sprinkler Room, Carpenter Shop, Basement Corridor, 1974 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **04/28/2016**



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Taft High School** REVIEW DATE: **5/19/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **61**  
MATERIAL DESCRIPTION: **MJP E/F/V on Fiberglass Pipe Insulation**  
MATERIAL LOCATION: **Sprinkler Room, Carpenter Shop, Basement Corridor, 1974 Building**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **Taft High School** INSPECTION DATE: **4/28/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **65**  
MATERIAL DESCRIPTION: **12" x 12" Brown w/ White Streaks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Room 342, 1958 Building**

MATERIAL QUANTITY: **890**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 04/28/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUILDING ID: **1580**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Taft High School** REVIEW DATE: **5/19/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **65**  
MATERIAL DESCRIPTION: **12" x 12" Brown w/ White Streaks VFT**  
MATERIAL LOCATION: **Room 342, 1958 Building**  
MATERIAL QUANTITY: **890** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **Taft High School** INSPECTION DATE: **4/28/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **66**  
MATERIAL DESCRIPTION: **12" x 12" Brown w/ White Streaks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 342, 1958 Building**

MATERIAL QUANTITY: **890**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 04/28/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUILDING ID: **1580**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Taft High School** REVIEW DATE: **5/19/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **66**  
MATERIAL DESCRIPTION: **12" x 12" Brown w/ White Streaks VFT Mastic**  
MATERIAL LOCATION: **Room 342, 1958 Building**  
MATERIAL QUANTITY: **890** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **Taft High School** INSPECTION DATE: **4/28/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **67**  
MATERIAL DESCRIPTION: **12" x 12" Light Gray w/ Dark Gray Specks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Throughout Building (See Hatching Maps), 1958 Building**  
MATERIAL QUANTITY: **3571** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/28/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUILDING ID: **1580**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Taft High School** REVIEW DATE: **5/19/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **67**  
MATERIAL DESCRIPTION: **12" x 12" Light Gray w/ Dark Gray Specks VFT**  
MATERIAL LOCATION: **Throughout Building (See Hatching Maps), 1958 Building**  
MATERIAL QUANTITY: **3571** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUILDING ID: **1580**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **Taft High School** INSPECTION DATE: **4/28/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **68**  
MATERIAL DESCRIPTION: **12" x 12" Light Gray w/ Drk Gray Specks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Throughout Building (See Hatching Maps), 1958 Building**

MATERIAL QUANTITY: **3571** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/28/2016



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUILDING ID: **1580**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Taft High School** REVIEW DATE: **5/19/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **68**  
MATERIAL DESCRIPTION: **12" x 12" Light Gray w/ Drk Gray Specks VFT Mastic**  
MATERIAL LOCATION: **Throughout Building (See Hatching Maps), 1958 Building**  
MATERIAL QUANTITY: **3571** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **Taft High School** INSPECTION DATE: **4/28/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **69**  
MATERIAL DESCRIPTION: **2' x 4' White w/ Deep Grooves Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 134, 239, 326, 1958 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **04/28/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Taft High School** REVIEW DATE: **5/19/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **69**  
MATERIAL DESCRIPTION: **2' x 4' White w/ Deep Grooves Ceiling Tile**  
MATERIAL LOCATION: **Room 134, 239, 326, 1958 Building**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **Taft High School** INSPECTION DATE: **4/28/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **70**  
MATERIAL DESCRIPTION: **1' x 1' White w/ Deep Grooves Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Gymnasium Lobby, 1958 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **04/28/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Taft High School** REVIEW DATE: **5/19/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **70**  
MATERIAL DESCRIPTION: **1' x 1' White w/ Deep Grooves Ceiling Tile**  
MATERIAL LOCATION: **Gymnasium Lobby, 1958 Building**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **Taft High School** INSPECTION DATE: **4/28/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **71**  
MATERIAL DESCRIPTION: **MJP E/F/V on Fiberglass Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Fan Units, Unfinished Pipe Space, Rifle Range, 1958 Building**  
MATERIAL QUANTITY: **20** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/28/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Taft High School** REVIEW DATE: **5/19/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **71**  
MATERIAL DESCRIPTION: **MJP E/F/V on Fiberglass Pipe Insulation**  
MATERIAL LOCATION: **Fan Units, Unfinished Pipe Space, Rifle Range, 1958 Building**  
MATERIAL QUANTITY: **20** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUILDING ID: **1580**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **Taft High School** INSPECTION DATE: **4/28/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **72**  
MATERIAL DESCRIPTION: **Hard Coat Plaster**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout, 1958 Building**  
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/28/2016



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUILDING ID: **1580**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Taft High School** REVIEW DATE: **5/19/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **72**  
MATERIAL DESCRIPTION: **Hard Coat Plaster**  
MATERIAL LOCATION: **Throughout, 1958 Building**  
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUILDING ID: **1580**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **Taft High School** INSPECTION DATE: **4/28/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **73**  
MATERIAL DESCRIPTION: **Exterior Window Glaze**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior Windows, 1939 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **04/28/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Taft High School** REVIEW DATE: **5/19/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **73**

MATERIAL DESCRIPTION: **Exterior Window Glaze**

MATERIAL LOCATION: **Exterior Windows, 1939 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUILDING ID: **1580**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **Taft High School** INSPECTION DATE: **4/28/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **74**  
MATERIAL DESCRIPTION: **Exterior Window Glaze**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior Windows, 1958 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: **04/28/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUILDING ID: **1580**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Taft High School** REVIEW DATE: **5/19/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **74**

MATERIAL DESCRIPTION: **Exterior Window Glaze**

MATERIAL LOCATION: **Exterior Windows, 1958 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUILDING ID: **1580**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **Taft High School** INSPECTION DATE: **4/28/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **75**  
MATERIAL DESCRIPTION: **Exterior Window Glaze**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior Windows, 1974 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **04/28/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUILDING ID: **1580**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Taft High School** REVIEW DATE: **5/19/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **75**

MATERIAL DESCRIPTION: **Exterior Window Glaze**

MATERIAL LOCATION: **Exterior Windows, 1974 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUILDING ID: **1580**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **Taft High School** INSPECTION DATE: **4/28/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **76**  
MATERIAL DESCRIPTION: **Exterior Window Caulk**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior Windows, 1939 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: **04/28/2016**



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Taft High School** REVIEW DATE: **5/19/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **76**

MATERIAL DESCRIPTION: **Exterior Window Caulk**

MATERIAL LOCATION: **Exterior Windows, 1939 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUILDING ID: **1580**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **Taft High School** INSPECTION DATE: **4/28/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **77**  
MATERIAL DESCRIPTION: **Exterior Window Caulk**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior Windows, 1958 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **04/28/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUILDING ID: **1580**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Taft High School** REVIEW DATE: **5/19/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **77**

MATERIAL DESCRIPTION: **Exterior Window Caulk**

MATERIAL LOCATION: **Exterior Windows, 1958 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUILDING ID: **1580**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **Taft High School** INSPECTION DATE: **4/28/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **78**  
MATERIAL DESCRIPTION: **Exterior Window Caulk**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior Windows, 1974 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **04/28/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Taft High School** REVIEW DATE: **5/19/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **78**

MATERIAL DESCRIPTION: **Exterior Window Caulk**

MATERIAL LOCATION: **Exterior Windows, 1974 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUILDING ID: **1580**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **Taft High School** INSPECTION DATE: **4/28/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **79**  
MATERIAL DESCRIPTION: **Interior Window Caulk**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Interior Windows, 1939 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: **04/28/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Taft High School** REVIEW DATE: **5/19/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **79**  
MATERIAL DESCRIPTION: **Interior Window Caulk**  
MATERIAL LOCATION: **Interior Windows, 1939 Building**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **Taft High School** INSPECTION DATE: **4/28/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **80**  
MATERIAL DESCRIPTION: **Interior Window Glaze**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Interior Windows, 1939 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: **04/28/2016**



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Taft High School** REVIEW DATE: **5/19/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **80**

MATERIAL DESCRIPTION: **Interior Window Glaze**

MATERIAL LOCATION: **Interior Windows, 1939 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUILDING ID: **1580**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **Taft High School** INSPECTION DATE: **4/28/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **81**  
MATERIAL DESCRIPTION: **Interior Window Glaze**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Interior Windows, 1958 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: **04/28/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUILDING ID: **1580**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Taft High School** REVIEW DATE: **5/19/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **81**

MATERIAL DESCRIPTION: **Interior Window Glaze**

MATERIAL LOCATION: **Interior Windows, 1958 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **Taft High School** INSPECTION DATE: **4/28/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **82**  
MATERIAL DESCRIPTION: **Interior Window Glaze**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Interior Windows, 1974 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 04/28/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Taft High School** REVIEW DATE: **5/19/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **82**

MATERIAL DESCRIPTION: **Interior Window Glaze**

MATERIAL LOCATION: **Interior Windows, 1974 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **Taft High School** INSPECTION DATE: **4/28/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **84**  
MATERIAL DESCRIPTION: **9"x9" Red VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Stage South Stairwell, 1939 Building**  
MATERIAL QUANTITY: **10** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/28/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUILDING ID: **1580**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Taft High School** REVIEW DATE: **5/19/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **84**  
MATERIAL DESCRIPTION: **9"x9" Red VFT**  
MATERIAL LOCATION: **Stage South Stairwell, 1939 Building**  
MATERIAL QUANTITY: **10** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **Taft High School** INSPECTION DATE: **4/28/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **85**  
MATERIAL DESCRIPTION: **9"x9" Red VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Stage South Stairwell, 1939 Building**

MATERIAL QUANTITY: **10** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/28/2016



# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUILDING ID: **1580**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Taft High School** REVIEW DATE: **5/19/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **85**  
MATERIAL DESCRIPTION: **9"x9" Red VFT Mastic**  
MATERIAL LOCATION: **Stage South Stairwell, 1939 Building**  
MATERIAL QUANTITY: **10** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **Taft High School** INSPECTION DATE: **4/28/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **86**  
MATERIAL DESCRIPTION: **9"x9" Black VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Stage South Stairwell, 1939 Building**  
MATERIAL QUANTITY: **10** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/28/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUILDING ID: **1580**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Taft High School** REVIEW DATE: **5/19/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **86**  
MATERIAL DESCRIPTION: **9"x9" Black VFT**  
MATERIAL LOCATION: **Stage South Stairwell, 1939 Building**  
MATERIAL QUANTITY: **10** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **Taft High School** INSPECTION DATE: **4/28/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **87**  
MATERIAL DESCRIPTION: **9"x9" Black VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Stage South Stairwell, 1939 Building**

MATERIAL QUANTITY: **10** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/28/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUILDING ID: **1580**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Taft High School** REVIEW DATE: **5/19/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **87**  
MATERIAL DESCRIPTION: **9"x9" Black VFT Mastic**  
MATERIAL LOCATION: **Stage South Stairwell, 1939 Building**  
MATERIAL QUANTITY: **10** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **Taft High School** INSPECTION DATE: **4/28/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **88**  
MATERIAL DESCRIPTION: **2"x18" Black VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Stage South Stairwell, 1939 Building**

MATERIAL QUANTITY: **36** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/28/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Taft High School** REVIEW DATE: **5/19/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **88**  
MATERIAL DESCRIPTION: **2"x18" Black VFT**  
MATERIAL LOCATION: **Stage South Stairwell, 1939 Building**  
MATERIAL QUANTITY: **36** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **Taft High School** INSPECTION DATE: **4/28/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **89**  
MATERIAL DESCRIPTION: **2"x18" Black VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Stage South Stairwell, 1939 Building**

MATERIAL QUANTITY: **36** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/28/2016



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUILDING ID: **1580**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Taft High School** REVIEW DATE: **5/19/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **89**  
MATERIAL DESCRIPTION: **2"x18" Black VFT Mastic**  
MATERIAL LOCATION: **Stage South Stairwell, 1939 Building**  
MATERIAL QUANTITY: **36** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **Taft High School** INSPECTION DATE: **4/28/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **90**  
MATERIAL DESCRIPTION: **12"x12" Tan w/ Brown Streaks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **121 Woodshop, 1939 Building**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/28/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Taft High School** REVIEW DATE: **5/19/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **90**  
MATERIAL DESCRIPTION: **12"x12" Tan w/ Brown Streaks VFT**  
MATERIAL LOCATION: **121 Woodshop, 1939 Building**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUILDING ID: **1580**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **Taft High School** INSPECTION DATE: **4/28/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **91**  
MATERIAL DESCRIPTION: **12"x12" Tan w/ Brown Streaks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **121 Woodshop, 1939 Building**

MATERIAL QUANTITY: **400**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 04/28/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUILDING ID: **1580**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Taft High School** REVIEW DATE: **5/19/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **91**  
MATERIAL DESCRIPTION: **12"x12" Tan w/ Brown Streaks VFT Mastic**  
MATERIAL LOCATION: **121 Woodshop, 1939 Building**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **Taft High School** INSPECTION DATE: **4/28/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **92**  
MATERIAL DESCRIPTION: **12"x12" Tan w/ Brown & White Streaks VFT ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON: **Deterioration**  
HISTORICAL RESPONSE ACTION: **Repair**  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 117, 1939 Building ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **04/28/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUILDING ID: **1580**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Taft High School** REVIEW DATE: **5/19/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **92**  
MATERIAL DESCRIPTION: **12"x12" Tan w/ Brown & White Streaks VFT ABATED**  
MATERIAL LOCATION: **Room 117, 1939 Building ABATED**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **Taft High School** INSPECTION DATE: **4/28/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **93**  
MATERIAL DESCRIPTION: **12"x12" Tan w/ Brown & White Streaks VFT Mastic ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON: **Deterioration**  
HISTORICAL RESPONSE ACTION: **Repair**  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 117, 1939 Building ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **04/28/2016**



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUILDING ID: **1580**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Taft High School** REVIEW DATE: **5/19/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **93**  
MATERIAL DESCRIPTION: **12"x12" Tan w/ Brown & White Streaks VFT Mastic ABATED**  
MATERIAL LOCATION: **Room 117, 1939 Building ABATED**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **Taft High School** INSPECTION DATE: **4/28/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **94**  
MATERIAL DESCRIPTION: **Brown Linoleum- NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **2nd Floor Teachers Lounge, 1939 Building--NOT OBSERVED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **04/28/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUILDING ID: **1580**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Taft High School** REVIEW DATE: **5/19/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **94**

MATERIAL DESCRIPTION: **Brown Linoleum- NOT OBSERVED**

MATERIAL LOCATION: **2nd Floor Teachers Lounge, 1939 Building--NOT OBSERVED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **Taft High School** INSPECTION DATE: **4/28/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **95**  
MATERIAL DESCRIPTION: **Brown Linoleum Mastic- NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **2nd Floor Teachers Lounge, 1939 Building NOT OBSERVED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **04/28/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUILDING ID: **1580**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Taft High School** REVIEW DATE: **5/19/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **95**  
MATERIAL DESCRIPTION: **Brown Linoleum Mastic- NOT OBSERVED**  
MATERIAL LOCATION: **2nd Floor Teachers Lounge, 1939 Building NOT OBSERVED**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **Taft High School** INSPECTION DATE: **4/28/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **98**  
MATERIAL DESCRIPTION: **2'x4' Dot Wave Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 106, 112, 216, 300, 1939 Building**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/28/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Taft High School** REVIEW DATE: **5/19/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **98**  
MATERIAL DESCRIPTION: **2'x4' Dot Wave Ceiling Tile**  
MATERIAL LOCATION: **Room 106, 112, 216, 300, 1939 Building**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **Taft High School** INSPECTION DATE: **4/28/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **99**  
MATERIAL DESCRIPTION: **12"x12" Off White w/ Gray Streaks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Rms 214, 216, 300, 300A, and 300L; 1st through 3rd Floor South Corridor - 1939 Building**

MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/28/2016



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUILDING ID: **1580**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Taft High School** REVIEW DATE: **5/19/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **99**  
MATERIAL DESCRIPTION: **12"x12" Off White w/ Gray Streaks VFT**  
MATERIAL LOCATION: **Rms 214, 216, 300, 300A, and 300L; 1st through 3rd Floor South Corridor - 1939 Building**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **Taft High School** INSPECTION DATE: **4/28/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **HA-1000**  
MATERIAL DESCRIPTION: **5'x2.5' ceiling tile with random pinholes**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **throughout 1974 bldg**  
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/28/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUILDING ID: **1580**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Taft High School** REVIEW DATE: **5/19/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **HA-1000**  
MATERIAL DESCRIPTION: **5'x2.5' ceiling tile with random pinholes**  
MATERIAL LOCATION: **throughout 1974 bldg**  
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **Taft High School** INSPECTION DATE: **4/28/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **HA-1001**  
MATERIAL DESCRIPTION: **Black table and counter tops ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rms. 300,302, 302A,305,308,310,312,313,316 ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/28/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Taft High School** REVIEW DATE: **5/19/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **HA-1001**  
MATERIAL DESCRIPTION: **Black table and counter tops ABATED**  
MATERIAL LOCATION: **Rms. 300,302, 302A,305,308,310,312,313,316 ABATED**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **Taft High School** INSPECTION DATE: **4/28/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **HA-1002**  
MATERIAL DESCRIPTION: **Gray lab table and counter tops ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rm. 183 ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/28/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUILDING ID: **1580**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Taft High School** REVIEW DATE: **5/19/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **HA-1002**  
MATERIAL DESCRIPTION: **Gray lab table and counter tops ABATED**  
MATERIAL LOCATION: **Rm. 183 ABATED**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **Taft High School** INSPECTION DATE: **4/28/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **HA-1003**  
MATERIAL DESCRIPTION: **MJP E/V/F on Cardboard Pipe Insulation (Paper Wrap on Insulation)**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Chase Behind Rm 134**

MATERIAL QUANTITY: **155**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 04/28/2016



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUILDING ID: **1580**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Taft High School** REVIEW DATE: **5/19/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **HA-1003**  
MATERIAL DESCRIPTION: **MJP E/V/F on Cardboard Pipe Insulation (Paper Wrap on Insulation)**  
MATERIAL LOCATION: **Chase Behind Rm 134**  
MATERIAL QUANTITY: **155** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **Taft High School** INSPECTION DATE: **4/28/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **HA-1004**  
MATERIAL DESCRIPTION: **Gray transite panel ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exhaust hood in Rm. 302A ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/28/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUIDLING ID: **1580**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Taft High School** REVIEW DATE: **5/19/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

---

HOMOGENEOUS AREA: **HA-1004**  
MATERIAL DESCRIPTION: **Gray transite panel ABATED**  
MATERIAL LOCATION: **Exhaust hood in Rm. 302A ABATED**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **46311**    BUILDING ID: **1580**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **Taft High School**    INSPECTION DATE: **4/28/2016**  
ADDRESS: **6545 W. Hurlburt St.**    IDPH LICENSE NO: **100-11372**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **HA-1008**  
MATERIAL DESCRIPTION: **12"x12" White w/Gray Streaks VFT Mastic**  
MATERIAL LOCATION: **Rm 117**  
MATERIAL QUANTITY: **600**    MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**    FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**    CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY:    DAMAGE REASON:  
DAMAGE QUANTITY: **0**    DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **04/28/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUILDING ID: **1580**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Taft High School** REVIEW DATE: **5/19/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

HOMOGENEOUS AREA: **HA-1008**

MATERIAL DESCRIPTION: **12"x12" White w/Gray Streaks VFT Mastic**

MATERIAL LOCATION: **Rm 117**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: **05/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **46311**    BUILDING ID: **1580**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **Taft High School**    INSPECTION DATE: **4/28/2016**  
ADDRESS: **6545 W. Hurlburt St.**    IDPH LICENSE NO: **100-11372**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **HA-1005**  
MATERIAL DESCRIPTION: **Beige Linoleum**  
MATERIAL LOCATION: **Rooms 311 & 313**  
MATERIAL QUANTITY: **1200**    MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**    FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **MODERATE**    CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY:    DAMAGE REASON:  
DAMAGE QUANTITY: **0**    DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **04/28/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUILDING ID: **1580**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Taft High School** REVIEW DATE: **5/19/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

HOMOGENEOUS AREA: **HA-1005**  
MATERIAL DESCRIPTION: **Beige Linoleum**  
MATERIAL LOCATION: **Rooms 311 & 313**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: **05/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **46311**    BUILDING ID: **1580**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **Taft High School**    INSPECTION DATE: **4/28/2016**  
ADDRESS: **6545 W. Hurlburt St.**    IDPH LICENSE NO: **100-11372**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **HA-1007**  
MATERIAL DESCRIPTION: **12"x12" White w/Gray Streaks VFT**  
MATERIAL LOCATION: **Rm 117**  
MATERIAL QUANTITY: **600**    MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**    FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **MODERATE**    CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY:    DAMAGE REASON:  
DAMAGE QUANTITY: **0**    DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/28/2016



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUILDING ID: **1580**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Taft High School** REVIEW DATE: **5/19/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

HOMOGENEOUS AREA: **HA-1007**

MATERIAL DESCRIPTION: **12"x12" White w/Gray Streaks VFT**

MATERIAL LOCATION: **Rm 117**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: **05/19/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **46311**    BUILDING ID: **1580**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Eric Moore**  
SCHOOL NAME: **Taft High School**    INSPECTION DATE: **4/28/2016**  
ADDRESS: **6545 W. Hurlburt St.**    IDPH LICENSE NO: **100-11372**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **HA-1006**  
MATERIAL DESCRIPTION: **Grey w White Streaks Linoleum**  
MATERIAL LOCATION: **Rooms 302, 303, 305, 307, 308, 310, 312, and 316**  
MATERIAL QUANTITY: **4500**    MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**    FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **MODERATE**    CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY:    DAMAGE REASON:  
DAMAGE QUANTITY: **0**    DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **04/28/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46311** BUILDING ID: **1580**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Taft High School** REVIEW DATE: **5/19/2016**  
ADDRESS: **6545 W. Hurlburt St.** IDPH LICENSE NO: **100-11372**

HOMOGENEOUS AREA: **HA-1006**  
MATERIAL DESCRIPTION: **Grey w White Streaks Linoleum**  
MATERIAL LOCATION: **Rooms 302, 303, 305, 307, 308, 310, 312, and 316**  
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: **05/19/2016**

# APPENDIX B

## **Inspector and Management Planner Licenses**

---

2015



**OCCUPATIONAL TRAINING & SUPPLY, INC.**

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900

# Asbestos Abatement Supervisor Refresher

Occupational Training & Supply, Inc. certifies that

**Eric Moore**

has successfully completed the Asbestos Abatement Supervisor Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Course Date: 11/30/2015

Exam Date: 11/30/2015

Expiration Date: 11/30/2016

Certificate Number: ASR1511304117

  
Kathy DeSalvo, Director



525-525 West Jefferson Street • Springfield, Illinois 62761-0001 • [www.idph.illinois.gov](http://www.idph.illinois.gov)

4/18/2016

**ERIC D MOORE**  
 855 W Adams Street, Suite 200  
 Chicago, IL 60607



ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 11372

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

**COPY OF THE ASBESTOS PROFESSIONAL LICENSE**

Front of License

Back of License

Front of License			Back of License	
 <p><b>ASBESTOS PROFESSIONAL LICENSE</b></p>			<b>ENDORSEMENTS</b>	<b>TC EXPIRES</b>
<b>ID NUMBER</b> 100 - 11372	<b>ISSUED</b> 4/18/2016	<b>EXPIRES</b> 05/15/2017	INSPECTOR	12/8/2016
<b>ERIC D MOORE</b> 855 W Adams Street, Suite 200 Chicago, IL 60607 Environmental Health			PROJECT MANAGER AIR SAMPLING PROFESSIONAL	11/30/2016
			<b>Alteration of this license shall result in legal action</b> This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: [dph.illinois.gov/topics-services/environmental-health-protection/asbestos](http://dph.illinois.gov/topics-services/environmental-health-protection/asbestos)  
 EMAIL Address: [dph.asbestos@illinois.gov](mailto:dph.asbestos@illinois.gov)

**PROTECTING HEALTH, IMPROVING LIVES**  
*Nationally Accredited by PHAB*



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • www.idph.illinois.gov

4/18/2016

ARTURO SAENZ  
855 W ADAMS ST SUITE 200  
CHICAGO, IL 60607

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 04019

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

 <p><b>ASBESTOS PROFESSIONAL LICENSE</b></p>			<p><b>ENDORSEMENTS</b></p> <p>INSPECTOR</p> <p>MANAGEMENT PLANNER</p> <p>AIR SAMPLING PROFESSIONAL</p> <p><b>Alteration of this license shall result in legal action</b> This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.</p>	<p><b>TC EXPIRES</b></p> <p>1/19/2017</p> <p>1/27/2017</p>
<p>ID NUMBER</p> <p>100 - 04019</p> <p><b>ARTURO SAENZ</b> 855 W ADAMS ST SUITE 200 CHICAGO, IL 60607 Environmental Health</p>	<p><b>ISSUED</b></p> <p>4/18/2016</p>	<p><b>EXPIRES</b></p> <p>05/13/2017</p> 		

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: [dph.illinois.gov/topics-services/environmental-health-protection/asbestos](http://dph.illinois.gov/topics-services/environmental-health-protection/asbestos)  
EMAIL Address: [dph.asbestos@illinois.gov](mailto:dph.asbestos@illinois.gov)

PROTECTING HEALTH, IMPROVING LIVES  
*Nationally Accredited by PHAB*

2016



**OCCUPATIONAL TRAINING & SUPPLY, INC.**

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900

# Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

**Arturo Saenz**

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 1/27/2016

Exam Date: 1/27/2016

Expiration Date: 1/27/2017

Certificate Number: MPR1601270319

---

Kathy DeSalvo, Director



2016



**OCCUPATIONAL TRAINING & SUPPLY, INC.**

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900

# Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

**Jigar Shah**

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 1/27/2016

Exam Date: 1/27/2016

Expiration Date: 1/27/2017

Certificate Number: MPR1601270320

---

Kathy DeSalvo, Director

# APPENDIX C

## Laboratory Accreditations

---

# APPENDIX D

## Laboratory Results

---

# APPENDIX E

## Chain of Custody Forms

---

## Three-Year Reinspection Key to Terms

	<b>CODE</b>	<b>KEY</b>
<b>MATERIAL</b>		
	ACBM	Asbestos Containing Building Materials
<b>MATERIAL CATEGORY</b>		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
<b>MATERIAL UNITS</b>		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
<b>DAMAGE TYPE</b>		
	Loc	Localized
	Dist	Distributed