

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH  
AHERA THREE YEAR REINSPECTION  
ASBESTOS ABATEMENT PROGRAM  
SCHOOL INFORMATION FORM**

**SECTION I**

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299  
SCHOOL ID NUMBER: 14-016-2990-0025  
SCHOOL NAME: Kenwood Academy  
ADDRESS OF SCHOOL: 5015 S. Blackstone  
CITY: Chicago, IL, 60615

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED 2/20/2013

**If the address on this form is different than the address of the building, submit a written explanation.**

---

**SECTION II** *(Please type or print)*

**PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:**

DATE REINSPECTION COMPLETED: 6/8/2016 ENROLLMENT 1766  
IDPH INSPECTOR LICENSE NUMBER: 100-09969  
IDPH LICENSED INSPECTOR NAME (Please Print): Dionne Carey  
IDPH MP LICENSE NUMBER: 100-03613  
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Daniel Juneau

DESIGNATED PERSON (Please Print): Robert Christlieb PHONE: (773) 553-3197



6/8/2016

*Signature of Designated Person*

*Date*

**SECTION III**

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: \_\_\_\_\_

School has been closed. Date closed: \_\_\_\_\_

School building has been demolished. Date: \_\_\_\_\_

School building is asbestos free since last reinspection: \_\_\_\_\_

**Please explain in writing why the school building is now asbestos free and include the supporting documentation.**

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

**Explain in writing if the address of the building is different than the address on this form:**

**THREE-YEAR REINSPECTION**

**CHICAGO SCHOOL DIST 299**

**Kenwood Academy**

5015 S. Blackstone  
Chicago, IL, 60615

Unit: 46361  
Building ID: 1710

IDPH ID Number: 14-016-2990-0025

**REPORT DATE:**

Wednesday, June 08, 2016

**Prepared for:**

**Chicago Public Schools**  
**125 S. Clark Street**  
**Chicago, IL 60603**

**Prepared by:**

**Carnow, Conibear and Associates**

600 West Van Buren St., Ste 500

Phone (312) 762-2900

Fax (312) 782-5145

**DO NOT REMOVE FROM SCHOOL  
REQUIRED BY FEDERAL LAW**



## **Environmental Notification to Occupants**

To: Faculty, Staff and Parents  
From: Chicago Public Schools  
Date: April 18, 2016

RE: Kenwood Academy, Unit 46361  
5015 S. Blackstone  
Chicago, IL, 60615

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2016 asbestos three year re-inspection has been completed at Kenwood Academy , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at Kenwood Academy, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Robert Christlieb, the designated Local Education Authority's Designated Person at (773) 553-3197 .

## **Table of Contents**

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

### **APPENDICES:**

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

## SCHOOL AND INSPECTION INFORMATION

### 1. School Information

School: Kenwood Academy Unit: 46361 Region: 04  
Address: 5015 S. Blackstone Chicago, IL, 60615  
IDPH ID: 14-016-2990-0025 Building ID: 1710  
Contact: Lynch, Michael Phone: 7735387705

### 2. Description of Facility

Original Construction: 1969 Additional Construction:  
Total Square Footage: 66180 No of Floors: 4  
Current Occupancy: 1766

### 3. LEA Designated Person

Contact: Robert Christlieb Phone: (773) 553-3197  
Address: 125 South Clark Street, 17th Floor  
Chicago, IL 60603

### 4. Managing Environmental Consultant

MEC: Carnow, Conibear and Associates  
Contact: Dan Juneau  
Address 600 West Van Buren St., Ste 500  
Phone: (312) 762-2900 Fax: (312) 782-5145

### 5. Inspector

Inspector Name: Dionne Carey


Inspector IDPH license # 100-09969

Signature:   
Date: 4/18/2016

### 6. Management Planner

Management Planner Name: Daniel Juneau

Management Planner IDPH license # 100-03613

Signature:   
Date: 06/08/2016

### 7. Review Date: 06/08/2016

### 8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature:   
Date: 6/8/2016

Name: Robert Christlieb

## II. EXECUTIVE SUMMARY

Carnow, Conibear and Associates was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Kenwood Academy. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 1710:

40	Plaster Ceiling
45	Vibration Gasket
60	2x4 Ceiling tile w/ divots & dots
67	12" x 12" Bright White Floor Tile
68	Mastic Associated w/ 12" x 12" Bright White Floor Tile
69	12" x 12" Blue Floor Tile
70	Mastic Associated w/ 12" x 12" Blue Floor Tile
71	12" x 12" Yellowish Floor Tile
72	Mastic Associated w/ 12" x 12" Yellowish Floor Tile

73	12" x 12" White Floor Tile
74	Mastic Associated w/ 12" x 12" White Floor Tile
75	12 x 12" Light Blue Floor Tile
76	Mastic Associated w/ 12 x 12" Light Blue Floor Tile
77	Blue Carpet Mastic
78	12" x 12" Blue, White, and Beige Floor Tile
79	Mastic Associated w/ 12" x 12" Blue, White, and Beige Floor Tile
80	Carpet Tile Mastic
A-1	2' x 4' Acoustical Ceiling Tiles
A-8	9" x 9" Beige Floor Tile Mastic
B-1	2' x 4' Acoustical Ceiling Tile w/Pinholes
C-E	Tank Insulation
E-B	Fiberglass Pipe Insulation Hard Elbows
E-C	Tank Insulation

B. The following new homogenous areas have been identified for Building 1710:

- 67 12" x 12" Bright White Floor Tile
- 68 Mastic Associated w/ 12" x 12" Bright White Floor Tile
- 69 12" x 12" Blue Floor Tile
- 70 Mastic Associated w/ 12" x 12" Blue Floor Tile
- 71 12" x 12" Yellowish Floor Tile
- 72 Mastic Associated w/ 12" x 12" Yellowish Floor Tile
- 73 12" x 12" White Floor Tile
- 74 Mastic Associated w/ 12" x 12" White Floor Tile
- 75 12 x 12" Light Blue Floor Tile
- 76 Mastic Associated w/ 12 x 12" Light Blue Floor Tile
- 77 Blue Carpet Mastic
- 78 12" x 12" Blue, White, and Beige Floor Tile
- 79 Mastic Associated w/ 12" x 12" Blue, White, and Beige Floor Tile
- 80 Carpet Tile Mastic

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

15	Tectum Tile
16	Transite Table Tops
17	Transite Counter Tops
38	Lab Table Tops
39	Lab Hood
40	Plaster Ceiling
41	Drywall
42	Drywall Joint Compound
43	Transite Ceiling
44	Transite Walls, Chalkboard Masonite
45	Vibration Gasket
46	Lab Hood
48	12" x 12" Cream w/Brown Specks Floor Tile
49	12" x 12" Cream w/Brown Specks Floor Tile Mastic
52	Sink Coating
53	12" x 12" Gray w/Gray Specks Floor Tile
54	12" x 12" Gray w/Gray Specks Floor Tile Mastic
55	Gray Carpet Mastic
56	12x12 Blue Floor Tile
57	12x12 blue floor tile mastic
58	12x12 white ft w/ tan mottle
59	Mastic for 12x12 white floor tile w/ tan mottle
60	2x4 Ceiling tile w/ divots & dots
63	12x12 Cream floor tile w/ brown specks
64	Mastic for 12x12 Cream floor tile w/ brown specks
65	12"x12" Peach VFT
66	12"x12" Peach VFT Mastic
67	12" x 12" Bright White Floor Tile
68	Mastic Associated w/ 12" x 12" Bright White Floor Tile
69	12" x 12" Blue Floor Tile
70	Mastic Associated w/ 12" x 12" Blue Floor Tile
71	12" x 12" Yellowish Floor Tile
72	Mastic Associated w/ 12" x 12" Yellowish Floor Tile
73	12" x 12" White Floor Tile
74	Mastic Associated w/ 12" x 12" White Floor Tile
75	12 x 12" Light Blue Floor Tile
76	Mastic Associated w/ 12 x 12" Light Blue Floor Tile
77	Blue Carpet Mastic
78	12" x 12" Blue, White, and Beige Floor Tile
79	Mastic Associated w/ 12" x 12" Blue, White, and

80	Beige Floor Tile
A-3	Carpet Tile Mastic
A-6.1	Spray-on Fireproofing
A-6.2	12" x 12" Beige Floor Tile
A-6.3	12" x 12" Blue Floor Tile
A-6.4	12" x 12" Beige w/Brown Specks Floor Tile
P	12" x 12" Tan Floor Tile
	Incinerator Stack Insulation

The following areas were deemed to be inaccessible:

49	12" x 12" Cream w/Brown Specks Floor Tile Mastic
54	12" x 12" Gray w/Gray Specks Floor Tile Mastic
57	12x12 blue floor tile mastic
59	Mastic for 12x12 white floor tile w/ tan mottle
64	Mastic for 12x12 Cream floor tile w/ brown specks
66	12"x12" Peach VFT Mastic
68	Mastic Associated w/ 12" x 12" Bright White Floor Tile
70	Mastic Associated w/ 12" x 12" Blue Floor Tile
72	Mastic Associated w/ 12" x 12" Yellowish Floor Tile
74	Mastic Associated w/ 12" x 12" White Floor Tile
76	Mastic Associated w/ 12 x 12" Light Blue Floor Tile
77	Blue Carpet Mastic
79	Mastic Associated w/ 12" x 12" Blue, White, and Beige Floor Tile
80	Carpet Tile Mastic
A-7	12" x 12" Black Floor Tile Mastic
A-7.1	12" x 12" Beige Floor Tile Mastic
A-7.3	12" x 12" Beige w/ Brown Specks Floor Tile Mastic
A-8	9" x 9" Beige Floor Tile Mastic
A-8.1	9" x 9" Brown Floor Tile Mastic

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Dionne Carey, IDPH License # 100-09969. The Management Plan was updated by Daniel Juneau, IDPH License # 100-03613. Inspector and Management Planner Licenses are included in Appendix B.

### **III. METHODOLOGY**

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

### **IV. ABATEMENT HISTORY**

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

### **V. REASSESSMENTS AND RECOMMENDATIONS**

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

### **VI. CONCLUSIONS**

The Kenwood Academy Building 1710 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

**Table I**  
**Inspector's Reinspection Findings**

---





# Chicago Public Schools

School Kenwood Academy Unit 46361 Building ID 1710

Address 5015 S. Blackstone Region 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
48	12" x 12" Cream w/Brown Specks Floor Tile	1,500	SF	Building A Rooms 227 & 234, Building B	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
49	12" x 12" Cream w/Brown Specks Floor Tile Mastic	1,500	SF	Building A Rooms 227 & 234, Building B	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
50	12" x 12" White w/Reddish Specks Floor Tile			Building A Room 134	ABATED	MISC								
51	12" x 12" White w/Reddish Specks Floor Tile Mastic			Building A Room 134	ABATED	MISC								
52	Sink Coating	43	SF	Building A Rooms 234 & 225	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
53	12" x 12" Gray w/Gray Specks Floor Tile	900	SF	Building B Rooms 121	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
54	12" x 12" Gray w/Gray Specks Floor Tile Mastic	900	SF	Building B Rooms 121	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
55	Gray Carpet Mastic			Building B 2nd Floor Faculty Commons	ASSUMED	MISC		None						Moderate
56	12x12 Blue Floor Tile	1,700	SF	ROOMS 321, 324	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
57	12x12 blue floor tile mastic	1,700	SF	rm 321, 324	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
58	12x12 white ft w/ tan mottle	950	SF	rm 128, 128A	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
59	Mastic for 12x12 white floor tile w/ tan mottle	950	SF	rm 128, 128A	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
60	2x4 Ceiling tile w/ divots & dots	2,100	SF	rm 128, 128A, 234	ASSUMED	MISC	Y	NONE	0		Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
61	12x12 Brown Mottle floor tile			rm 134 H	ABATED	MISC								
62	Mastic for 12x12 Brown mottle floor tile			rm 134 H	ABATED	MISC								
63	12x12 Cream floor tile w/ brown specks	1,200	SF	rm 234	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
64	Mastic for 12x12 Cream floor tile w/ brown specks	1,200	SF	rm 234	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
65	12"x12" Peach VFT	500	SF	Faculty Commons	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
66	12"x12" Peach VFT Mastic	500	SF	Faculty Commons	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
67	12" x 12" Bright White Floor Tile	15,100	SF	1st Floor Hallways	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
68	Mastic Associated w/ 12" x 12" Bright White Floor Tile	1,500	SF	1st Floor Hallways	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW

# Chicago Public Schools

School Kenwood Academy Unit 46361 Building ID 1710

Address 5015 S. Blackstone Region 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
69	12" x 12" Blue Floor Tile	9,900	SF	1st Floor Hallways, Rooms 106, 107, 108, 109, 110, 116, 117, 118, 119, 120, and 126	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
70	Mastic Associated w/ 12" x 12" Blue Floor Tile	9,900	SF	1st Floor Hallways, Rooms 106, 107, 108, 109, 110, 116, 117, 118, 119, 120, and 126	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
71	12" x 12" Yellowish Floor Tile	800	SF	Main Office	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
72	Mastic Associated w/ 12" x 12" Yellowish Floor Tile	800	SF	Main Office	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
73	12" x 12" White Floor Tile	2,280	SF	2nd Floor Lunchroom, Kitchen Faculty, Room 127	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
74	Mastic Associated w/ 12" x 12" White Floor Tile	2,280	SF	2nd Floor Lunchroom, Kitchen Faculty, Room 127	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
75	12 x 12" Light Blue Floor Tile	9,000	SF	Lunchroom	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
76	Mastic Associated w/ 12 x 12" Light Blue Floor Tile	9,000	SF	Lunchroom	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
77	Blue Carpet Mastic	700	SF	Auditorium	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
78	12" x 12" Blue, White, and Beige Floor Tile	2,000	SF	Rooms 133 and 134	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
79	Mastic Associated w/ 12" x 12" Blue, White, and Beige Floor Tile	2,000	SF	Rooms 133 and 134	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
80	Carpet Tile Mastic	3,600	SF	Room 122 and Main Office	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
A-1	2' x 4' Acoustical Ceiling Tiles	9,400	SF	Throughout Building A - Offices, Hallways, Classrooms, 325 & 325 Office	CHR	MISC	Y	NONE	0		Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
A-3	Spray-on Fireproofing	10,610	SF	Bldg.D-Rm224,223,Lunchroom,Kitchen,Halls,Boy's/GirlsToilet,Bldg C-East Mech.Rm,237,238, 266, Bldg.A Fan Rm	ASSUMED	SURFACE	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW

# Chicago Public Schools

School Kenwood Academy Unit 46361 Building ID 1710

Address 5015 S. Blackstone Region 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
A-6	12" x 12" Black Floor Tile	2,160	SF	Building B - 1st Floor Passageways	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
A-6.1	12" x 12" Beige Floor Tile	1,900	SF	Building D - District Superintendent's Office & Faculty Service Line	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
A-6.2	12" x 12" Blue Floor Tile	220	SF	Building B - Room 123/MDF Room 121/Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
A-6.3	12" x 12" Beige w/Brown Specks Floor Tile	1,710	SF	Building D-Engineer's Office, Rm. 227	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
A-6.4	12" x 12" Tan Floor Tile	3,885	SF	Building A - Corridors, Rooms 232 and 233, Passageways 1,2,3,4	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
A-7	12" x 12" Black Floor Tile Mastic	2,160	SF	Building B - Passage ways 1 & 2	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
A-7.1	12" x 12" Beige Floor Tile Mastic	1,900	SF	Building D-District Superintendent's Office & Faculty Service Line	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
A-7.2	12" x 12" Blue Floor Tile Mastic			Building B - Room 121/MDF Room 121/Office	NO_ACBM									
A-7.3	12" x 12" Beige w/ Brown Specks Floor Tile Mastic	1,710	SF	Building D-Engineer's Office, Rm. 227	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
A-7.4	12" x 12" Tan Floor Tile Mastic	3,885	SF	Building A - Halls, and Rooms 232 and 233	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
A-8	9" x 9" Beige Floor Tile Mastic	21,000	SF	Buildings D - Hall, A4 Building - Throughout Classrooms, Labs, Offices, Throughout Bldg. B Classrooms	CHR	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
A-8.1	9" x 9" Brown Floor Tile Mastic	22,600	SF	Hallways Throughout Facility, Building A - Room 225	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
A-9	9" x 9" Beige Floor Tile	21,000	SF	Building D-Hall, A4 Building- Throughout Facility Classrooms,	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

# Chicago Public Schools

School Kenwood Academy Unit 46361 Building ID 1710

Address 5015 S. Blackstone Region 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Offices,Labs,Throug hout Bldg.B Classrooms										
A-9.1	9" x 9" Brown Floor Tile	21,000	SF	Hallways Throughout Facility, Building A - Room 225, Room 226	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
A-C	Pipe Insulation			Building A - Penthouse	ABATED	TSI		None						
A-E	Pipe Insulation			Building A - Pipe chases	ABATED	TSI		None						
B(A-2)	Tank Insulation	300	SF	Building B - 4th Floor Boiler Room	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
B(A-3)	Cementitious Insulation (Joint)	250	SF	Building B - 4th Floor Boiler Room	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
B-1	2' x 4' Acoustical Ceiling Tile w/Pinholes	2,250	SF	RM 234, 315, 325	CHR	MISC	Y	DIST	208		Yes	Damaged or significantly damaged friable misc. ACBM	10	MODERATE
B-1.1	2' x 4' Acoustical Ceiling Tile/White Worm Pinhole			Building A - Hall, Rooms 232, 233, 234, 237 & 225	NO_ACBM									
B-D	Pipe Insulation	400	SF	Building B - Boiler Room	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
C-B	Cemetitious Insulation (Joint)			Building C - Roof Drains	CHR	TSI		None						Moderate
C-C	Pipe Insulation			Building C - Throughout Building and Crawlspace	INACCESSI BLE	TSI								Moderate
C-D	Cementitious Insulation on Pipe Joint			Throughout Building C	CHR	TSI		None						Moderate
C-E	Tank Insulation	245	SF	Building C - 3rd Floor Mechanical Room	CHR	TSI	Y	NONE	0		Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
CK-DC	Joint Insulation	500	LF	Building D - Equipment Room	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
CK-DE	Aircell Pipe Insulation			Building D - Cafeteria Pipe Chase	CHR	TSI		None						Moderate
CK-DF	Lag & Joint Cement	50	LF	Building D - Mechanical Room	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable		LOW

# Chicago Public Schools

School Kenwood Academy Unit 46361 Building ID 1710

Address 5015 S. Blackstone Region 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
												suspect ACBM		
CK-DG	Tank Insulation	300	SF	Building D - Mechanical Room	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
E-B	Fiberglass Pipe Insulation Hard Elbows	896	LF	Buildings A, B, C, D	CHR	TSI	Y	LOC	15		Yes	Damaged or significantly damaged friable thermal system insulating ACBM	5	MODERATE
E-C	Tank Insulation	400	SF	Building D - 1st Floor Mechanical Room	CHR	TSI	Y	LOC	5		Yes	Damaged or significantly damaged friable thermal system insulating ACBM	3	MODERATE
P	Incinerator Stack Insulation			Building D - Mechanical Room	ASSUMED	TSI		None						Moderate

# Chicago Public Schools

School Kenwood Academy Unit 46361 Building ID 1710

Address 5015 S. Blackstone Region 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

Reinspection Date <b>4/18/2016</b>
Inspector Name <b>Dionne Carey</b>
<b>100-09969</b> <b>5/15/2017</b>
Inspector's IDPH License Number / Expiration Date

### Inspector's Comments

HA Number:	Inspector Comments:
15	
16	
17	
18	
19	
20	
20.1	
21	
21.1	
22	
23	
24	
25	
26	
27	
28	
30	
31	
31.1	
32	
33	
34	
35	
36	

# Chicago Public Schools

School Kenwood Academy Unit 46361 Building ID 1710

Address 5015 S. Blackstone Region 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
37	
37.1	
38	
39	
40	
41	
42	
43	
44	
45	
46	
47	
48	
49	
50	
51	
52	
53	
54	
55	Not observed 2016
56	
57	
58	
59	
60	
61	
62	
63	
64	

# Chicago Public Schools

School Kenwood Academy Unit 46361 Building ID 1710

Address 5015 S. Blackstone Region 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
65	
66	
67	
68	
69	
70	
71	
72	
73	
74	
75	
76	
77	
78	
79	
80	
A-1	
A-3	
A-6	
A-6.1	
A-6.2	
A-6.3	
A-6.4	
A-7	
A-7.1	
A-7.2	
A-7.3	
A-7.4	
A-8	

# Chicago Public Schools

School Kenwood Academy Unit 46361 Building ID 1710

Address 5015 S. Blackstone Region 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
A-8.1	
A-9	
A-9.1	
A-C	
A-E	
B(A-2)	
B(A-3)	
B-1	
B-1.1	
B-D	
C-B	Not observed 2016
C-C	
C-D	Not observed 2016
C-E	
CK-DC	
CK-DE	Not observed 2016
CK-DF	
CK-DG	
E-B	
E-C	
P	Not observed 2016

**Table II**

**Management Planner's Review**

---

# Chicago Public Schools

School Kenwood Academy

Unit 46361

Building ID 1710

Address 5015 S. Blackstone

Chicago, IL, 60615

Region 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
15	Tectum Tile	18,200	SF	Building. C - Rooms 2nd Floor Boy's Gym, 1st Floor Girl's Gym. Building. A - Room 127	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
16	Transite Table Tops	500	SF	Building B - Rooms 315, 301, 303, 325, 310	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
17	Transite Counter Tops	500	SF	Building B Rooms 305, 315, 315 Storage, 301, 303, 303 Storage, 325, 325 Office, 306, 310	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
18	6" Black Baseboard			District Superintendent's Office	No ACBM						
19	6" Black Baseboard Mastic			District Superintendent's Office	No ACBM						
20	4" Beige Baseboard			Building D	No ACBM						
20.1	4" Brown Baseboard			Building D - Security Office	No ACBM						
21	4" Beige Baseboard Mastic			Building D	No ACBM						
21.1	4" Brown Baseboard Mastic			Building D - Security Office	No ACBM						
22	Roofing Material - Not AHERA			Roof, Building A, B, C, D	No ACBM						
23	Roof Flashing - Not AHERA			Roof Building A, B, C, D	No ACBM						
24	Interior Brick			Building A,B,C,D Throughout	No ACBM						
25	Interior Brick Mortar			Building A,B,C,D - Throughout	No ACBM						
26	Exterior Brick - Not AHERA			Building A,B,C,D Exteriors	No ACBM						
27	Exterior Brick Mortar-Not AHERA			Building A,B,C,D Exteriors	No ACBM						
28	Maroon Carpet Mastic			Building B - Principal's Office, Guidance Counselor's Office, Hall	No ACBM						
30	Blue Carpet Mastic			Building B - Main Office, 1st & 2nd Floor Media Centers	No ACBM						
31	1' x 1' Ceiling Tile			Building D	No ACBM						
31.1	1' x 1' Ceiling Tile Mastic			Building D	No ACBM						
32	2' x 4' White Worm Pinhole Ceiling Tile			Science Rooms (321, 324)	No ACBM						
33	2' x 4' White Worm Pinhole Ceiling Tile			Building B - Rooms 323, 316, 221, 220, 219, 218, and 123	No ACBM						
34	Blue Baseboard			Science Rooms (321, 324)	No ACBM						
35	Drywall			Science Room (321, 324)	No ACBM						
36	Drywall Joint Compound			Science Rooms (321, 324)	No ACBM						
37	Light Blue w/Dark Blue & White Streaks Linoleum			Science Rooms (321, 324)	No ACBM						
37.1	Lt Blue w/Dk Blue & White Streaks Linoleum Mastic			Science Rooms (321, 324)	No ACBM						
38	Lab Table Tops	100	SF	Building B Rooms 305, 315, 301, 303,	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

School Kenwood Academy  
Address 5015 S. Blackstone

Unit 46361  
Chicago, IL, 60615

Building ID 1710  
Region 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				303 Storage, 306, 310, 321 & 324							
39	Lab Hood	20	SF	Science Rooms (324, 321)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
40	Plaster Ceiling	90,000	SF	Throughout Bathrooms	Assumed	SURFACE	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
41	Drywall	2,000	SF	Throughout	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
42	Drywall Joint Compound	2,000	SF	Throughout	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
43	Transite Ceiling	10	SF	Building D Stairwell 13	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
44	Transite Walls, Chalkboard Masonite	800	SF	Building D Lunchroom, Weight Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
45	Vibration Gasket	100	LF	Throughout Mechanical Rooms, MDF Room 123	Assumed	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
46	Lab Hood	50	SF	Building B - Rooms 310, 305, and 315	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
47	Blue Baseboard Mastic			Building B - Science Rooms (324, 321)	No ACBM						
48	12" x 12" Cream w/Brown Specks Floor Tile	1,500	SF	Building A Rooms 227 & 234, Building B	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
49	12" x 12" Cream w/Brown Specks Floor Tile Mastic	1,500	SF	Building A Rooms 227 & 234, Building B	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
50	12" x 12" White w/Reddish Specks Floor Tile			Building A Room 134	Abated	MISC					
51	12" x 12" White w/Reddish Specks Floor Tile Mastic			Building A Room 134	Abated	MISC					
52	Sink Coating	43	SF	Building A Rooms 234 & 225	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
53	12" x 12" Gray w/Gray Specks Floor Tile	900	SF	Building B Rooms 121	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
54	12" x 12" Gray w/Gray Specks Floor Tile Mastic	900	SF	Building B Rooms 121	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
55	Gray Carpet Mastic			Building B 2nd Floor Faculty Commons	Assumed	MISC					
56	12x12 Blue Floor Tile	1,700	SF	ROOMS 321, 324	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
57	12x12 blue floor tile mastic	1,700	SF	rm 321, 324	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
58	12x12 white ft w/ tan mottle	950	SF	rm 128, 128A	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
59	Mastic for 12x12 white floor tile w/ tan mottle	950	SF	rm 128, 128A	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
60	2x4 Ceiling tile w/ divots & dots	2,100	SF	rm 128, 128A, 234	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
61	12x12 Brown Mottle floor tile			rm 134 H	Abated	MISC					
62	Mastic for 12x12 Brown mottle floor tile			rm 134 H	Abated	MISC					
63	12x12 Cream floor tile w/ brown specks	1,200	SF	rm 234	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
64	Mastic for 12x12 Cream floor tile w/ brown specks	1,200	SF	rm 234	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
65	12"x12" Peach VFT	500	SF	Faculty Commons	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
66	12"x12" Peach VFT Mastic	500	SF	Faculty Commons	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Kenwood Academy  
**Address** 5015 S. Blackstone

**Unit** 46361  
Chicago, IL, 60615

**Building ID** 1710  
**Region** 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
67	12" x 12" Bright White Floor Tile	15,100	SF	1st Floor Hallways	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
68	Mastic Associated w/ 12" x 12" Bright White Floor Tile	1,500	SF	1st Floor Hallways	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
69	12" x 12" Blue Floor Tile	9,900	SF	1st Floor Hallways, Rooms 106, 107, 108, 109, 110, 116, 117, 118, 119, 120, and 126	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
70	Mastic Associated w/ 12" x 12" Blue Floor Tile	9,900	SF	1st Floor Hallways, Rooms 106, 107, 108, 109, 110, 116, 117, 118, 119, 120, and 126	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
71	12" x 12" Yellowish Floor Tile	800	SF	Main Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
72	Mastic Associated w/ 12" x 12" Yellowish Floor Tile	800	SF	Main Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
73	12" x 12" White Floor Tile	2,280	SF	2nd Floor Lunchroom, Kitchen Faculty, Room 127	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
74	Mastic Associated w/ 12" x 12" White Floor Tile	2,280	SF	2nd Floor Lunchroom, Kitchen Faculty, Room 127	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
75	12 x 12" Light Blue Floor Tile	9,000	SF	Lunchroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
76	Mastic Associated w/ 12 x 12" Light Blue Floor Tile	9,000	SF	Lunchroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
77	Blue Carpet Mastic	700	SF	Auditorium	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
78	12" x 12" Blue, White, and Beige Floor Tile	2,000	SF	Rooms 133 and 134	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
79	Mastic Associated w/ 12" x 12" Blue, White, and Beige Floor Tile	2,000	SF	Rooms 133 and 134	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
80	Carpet Tile Mastic	3,600	SF	Room 122 and Main Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
A-1	2' x 4' Acoustical Ceiling Tiles	9,400	SF	Throughout Building A - Offices, Hallways, Classrooms, 325 & 325 Office	Chrysotile	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
A-3	Spray-on Fireproofing	10,610	SF	Bldg.D-Rm224,223,Lunchroom,Kitchen,Halls,Boys/GirlsToilet,Bldg C-East Mech.Rm,237,238, 266, Bldg.A Fan Rm	Assumed	SURFACE	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
A-6	12" x 12" Black Floor Tile	2,160	SF	Building B - 1st Floor Passageways	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
A-6.1	12" x 12" Beige Floor Tile	1,900	SF	Building D - District Superintendent's Office & Faculty Service Line	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
A-6.2	12" x 12" Blue Floor Tile	220	SF	Building B - Room 123/MDF Room 121/Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
A-6.3	12" x 12" Beige w/Brown Specks Floor Tile	1,710	SF	Building D-Engineer's Office, Rm. 227	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Kenwood Academy  
**Address** 5015 S. Blackstone

**Unit** 46361  
Chicago, IL, 60615

**Building ID** 1710  
**Region** 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
A-6.4	12" x 12" Tan Floor Tile	3,885	SF	Building A - Corridors, Rooms 232 and 233, Passageways 1,2,3,4	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
A-7	12" x 12" Black Floor Tile Mastic	2,160	SF	Building B - Passage ways 1 & 2	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
A-7.1	12" x 12" Beige Floor Tile Mastic	1,900	SF	Building D-District Superintendent's Office & Faculty Service Line	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
A-7.2	12" x 12" Blue Floor Tile Mastic			Building B - Room 121/MDF Room 121/Office	No ACBM						
A-7.3	12" x 12" Beige w/ Brown Specks Floor Tile Mastic	1,710	SF	Building D-Engineer's Office, Rm. 227	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
A-7.4	12" x 12" Tan Floor Tile Mastic	3,885	SF	Building A - Halls, and Rooms 232 and 233	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
A-8	9" x 9" Beige Floor Tile Mastic	21,000	SF	Buildings D - Hall, A4 Building - Throughout Classrooms, Labs, Offices, Throughout Bldg.B Classrooms	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
A-8.1	9" x 9" Brown Floor Tile Mastic	22,600	SF	Hallways Throughout Facility, Building A - Room 225	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
A-9	9" x 9" Beige Floor Tile	21,000	SF	Building D-Hall, A4 Building- Throughout FacilityClassrooms,Offices,Labs,Througout Bldg.B Classrooms	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
A-9.1	9" x 9" Brown Floor Tile	21,000	SF	Hallways Throughout Facility, Building A - Room 225, Room 226	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
A-C	Pipe Insulation			Building A - Penthouse	Abated	TSI					
A-E	Pipe Insulation			Building A - Pipe chases	Abated	TSI					
B(A-2)	Tank Insulation	300	SF	Building B - 4th Floor Boiler Room	Chrysotile	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
B(A-3)	Cementitious Insulation (Joint)	250	SF	Building B - 4th Floor Boiler Room	Chrysotile	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
B-1	2' x 4' Acoustical Ceiling Tile w/Pinholes	2,250	SF	RM 234, 315, 325	Chrysotile	MISC	Yes	208	SF	4 Damaged or significantly damaged friable misc. ACBM	Remove
B-1.1	2' x 4' Acoustical Ceiling Tile/White Worm Pinhole			Building A - Hall, Rooms 232, 233, 234, 237 & 225	No ACBM						
B-D	Pipe Insulation	400	SF	Building B - Boiler Room	Chrysotile	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
C-B	Cemetitious Insulation (Joint)			Building C - Roof Drains	Chrysotile	TSI					
C-C	Pipe Insulation			Building C - Throughout Building and Crawlspace	Inaccessibl e	TSI					

# Chicago Public Schools

School Kenwood Academy

Unit 46361

Building ID 1710

Address 5015 S. Blackstone

Chicago, IL, 60615

Region 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
C-D	Cementitious Insulation on Pipe Joint			Throughout Building C	Chrysotile	TSI					
C-E	Tank Insulation	245	SF	Building C - 3rd Floor Mechanical Room	Chrysotile	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
CK-DC	Joint Insulation	500	LF	Building D - Equipment Room	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
CK-DE	Aircell Pipe Insulation			Building D - Cafeteria Pipe Chase	Chrysotile	TSI					
CK-DF	Lag & Joint Cement	50	LF	Building D - Mechanical Room	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
CK-DG	Tank Insulation	300	SF	Building D - Mechanical Room	Chrysotile	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
E-B	Fiberglass Pipe Insulation Hard Elbows	896	LF	Buildings A, B, C, D	Chrysotile	TSI	Yes	15	LF	1 Damaged or significantly damaged friable thermal system insulating ACBM	Repair
E-C	Tank Insulation	400	SF	Building D - 1st Floor Mechanical Room	Chrysotile	TSI	Yes	5	SF	1 Damaged or significantly damaged friable thermal system insulating ACBM	Repair
P	Incinerator Stack Insulation			Building D - Mechanical Room	Assumed	TSI					

# Chicago Public Schools

**School** Kenwood Academy  
**Address** 5015 S. Blackstone

**Unit** 46361  
 Chicago, IL, 60615

**Building ID** 1710  
**Region** 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

*Management Planner's Comments Summarized at the End of the Report*

Review Date	6/8/2016
Manager Planner Name	Daniel Juneau
100-03613	5/15/2016
Manager IDPH License No/Expiration	

HA Number	Management Comments
15	
16	
17	
18	
19	
20	
20.1	
21	
21.1	
22	
23	
24	
25	
26	
27	
28	
30	
31	
31.1	
32	
33	
34	

# Chicago Public Schools

**School** Kenwood Academy  
**Address** 5015 S. Blackstone

**Unit** 46361  
 Chicago, IL, 60615

**Building ID** 1710  
**Region** 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
35	
36	
37	
37.1	
38	
39	
40	
41	
42	
43	
44	
45	
46	
47	
48	
49	
50	
51	
52	
53	
54	
55	If identified, implement O&M
56	
57	
58	
59	
60	

# Chicago Public Schools

**School** Kenwood Academy  
**Address** 5015 S. Blackstone

**Unit** 46361  
 Chicago, IL, 60615

**Building ID** 1710  
**Region** 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
61	
62	
63	
64	
65	
66	
67	
68	
69	
70	
71	
72	
73	
74	
75	
76	
77	
78	
79	
80	
A-1	
A-3	
A-6	
A-6.1	
A-6.2	
A-6.3	
A-6.4	

# Chicago Public Schools

**School** Kenwood Academy  
**Address** 5015 S. Blackstone

**Unit** 46361  
 Chicago, IL, 60615

**Building ID** 1710  
**Region** 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
A-7	
A-7.1	
A-7.2	
A-7.3	
A-7.4	
A-8	
A-8.1	
A-9	
A-9.1	
A-C	
A-E	
B(A-2)	
B(A-3)	
B-1	
B-1.1	
B-D	
C-B	If identified, implement O&M
C-C	If identified, implement O&M
C-D	If identified, implement O&M
C-E	
CK-DC	
CK-DE	If identified, implement O&M
CK-DF	
CK-DG	
E-B	Remove or Repair as applicable. Continue O&M.
E-C	Remove or Repair as applicable. Continue O&M.
P	If identified, implement O&M

# Chicago Public Schools

**School** Kenwood Academy

**Unit** 46361

**Building ID** 1710

**Address** 5015 S. Blackstone

Chicago, IL, 60615

**Region** 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

***Management Planner's Comments Summarized at the End of the Report***

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Kenwood Academy** INSPECTION DATE: **4/18/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15**  
MATERIAL DESCRIPTION: **Tectum Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Building. C - Rooms 2nd Floor Boy's Gym, 1st Floor Girl's Gym. Building. A - Room 127**

MATERIAL QUANTITY: **18200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/18/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUILDING ID: **1710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kenwood Academy** REVIEW DATE: **6/8/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **15**  
MATERIAL DESCRIPTION: **Tectum Tile**  
MATERIAL LOCATION: **Building. C - Rooms 2nd Floor Boy's Gym, 1st Floor Girl's Gym. Building. A - Room 127**  
MATERIAL QUANTITY: **18200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/08/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Kenwood Academy** INSPECTION DATE: **4/18/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16**  
MATERIAL DESCRIPTION: **Transite Table Tops**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Building B - Rooms 315, 301, 303, 325, 310**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: **04/18/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUILDING ID: **1710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kenwood Academy** REVIEW DATE: **6/8/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **16**  
MATERIAL DESCRIPTION: **Transite Table Tops**  
MATERIAL LOCATION: **Building B - Rooms 315, 301, 303, 325, 310**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/08/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Kenwood Academy** INSPECTION DATE: **4/18/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17**  
MATERIAL DESCRIPTION: **Transite Counter Tops**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Building B Rooms 305, 315, 315 Storage, 301, 303, 303 Storage, 325, 325 Office, 306, 310**

MATERIAL QUANTITY: **500**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/18/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kenwood Academy** REVIEW DATE: **6/8/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **17**  
MATERIAL DESCRIPTION: **Transite Counter Tops**  
MATERIAL LOCATION: **Building B Rooms 305, 315, 315 Storage, 301, 303, 303 Storage, 325, 325 Office, 306, 310**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/08/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Kenwood Academy** INSPECTION DATE: **4/18/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18**  
MATERIAL DESCRIPTION: **6" Black Baseboard**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **District Superintendent's Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/18/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kenwood Academy** REVIEW DATE: **6/8/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **18**

MATERIAL DESCRIPTION: **6" Black Baseboard**

MATERIAL LOCATION: **District Superintendent's Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/08/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Kenwood Academy** INSPECTION DATE: **4/18/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19**  
MATERIAL DESCRIPTION: **6" Black Baseboard Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **District Superintendent's Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/18/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kenwood Academy** REVIEW DATE: **6/8/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **19**

MATERIAL DESCRIPTION: **6" Black Baseboard Mastic**

MATERIAL LOCATION: **District Superintendent's Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/08/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Kenwood Academy** INSPECTION DATE: **4/18/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**  
MATERIAL DESCRIPTION: **4" Beige Baseboard**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building D**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/18/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kenwood Academy** REVIEW DATE: **6/8/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **20**

MATERIAL DESCRIPTION: **4" Beige Baseboard**

MATERIAL LOCATION: **Building D**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/08/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Kenwood Academy** INSPECTION DATE: **4/18/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20.1**  
MATERIAL DESCRIPTION: **4" Brown Basebaord**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building D - Security Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/18/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kenwood Academy** REVIEW DATE: **6/8/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **20.1**

MATERIAL DESCRIPTION: **4" Brown Basebaord**

MATERIAL LOCATION: **Building D - Security Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/08/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Kenwood Academy** INSPECTION DATE: **4/18/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21**  
MATERIAL DESCRIPTION: **4" Beige Baseboard Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building D**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/18/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kenwood Academy** REVIEW DATE: **6/8/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **21**

MATERIAL DESCRIPTION: **4" Beige Baseboard Mastic**

MATERIAL LOCATION: **Building D**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/08/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Kenwood Academy** INSPECTION DATE: **4/18/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21.1**  
MATERIAL DESCRIPTION: **4" Brown Baseboard Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building D - Security Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/18/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kenwood Academy** REVIEW DATE: **6/8/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **21.1**  
MATERIAL DESCRIPTION: **4" Brown Baseboard Mastic**  
MATERIAL LOCATION: **Building D - Security Office**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/08/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUILDING ID: **1710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Kenwood Academy** INSPECTION DATE: **4/18/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22**  
MATERIAL DESCRIPTION: **Roofing Material - Not AHERA**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Roof, Building A, B, C, D**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/18/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUILDING ID: **1710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kenwood Academy** REVIEW DATE: **6/8/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **22**

MATERIAL DESCRIPTION: **Roofing Material - Not AHERA**

MATERIAL LOCATION: **Roof, Building A, B, C, D**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/08/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Kenwood Academy** INSPECTION DATE: **4/18/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23**  
MATERIAL DESCRIPTION: **Roof Flashing - Not AHERA**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Roof Building A, B, C, D**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/18/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kenwood Academy** REVIEW DATE: **6/8/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **23**

MATERIAL DESCRIPTION: **Roof Flashing - Not AHERA**

MATERIAL LOCATION: **Roof Building A, B, C, D**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/08/2016**

# Chicago Public Schools

## Carnow, Conibear and Associates 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUILDING ID: **1710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Kenwood Academy** INSPECTION DATE: **4/18/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **24**  
MATERIAL DESCRIPTION: **Interior Brick**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building A,B,C,D Throughout**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/18/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kenwood Academy** REVIEW DATE: **6/8/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **24**

MATERIAL DESCRIPTION: **Interior Brick**

MATERIAL LOCATION: **Building A,B,C,D Throughout**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/08/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Kenwood Academy** INSPECTION DATE: **4/18/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25**  
MATERIAL DESCRIPTION: **Interior Brick Mortar**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building A,B,C,D - Throughout**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/18/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kenwood Academy** REVIEW DATE: **6/8/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **25**

MATERIAL DESCRIPTION: **Interior Brick Mortar**

MATERIAL LOCATION: **Building A,B,C,D - Throughout**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/08/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Kenwood Academy** INSPECTION DATE: **4/18/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26**  
MATERIAL DESCRIPTION: **Exterior Brick - Not AHERA**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building A,B,C,D Exteriors**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/18/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kenwood Academy** REVIEW DATE: **6/8/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **26**

MATERIAL DESCRIPTION: **Exterior Brick - Not AHERA**

MATERIAL LOCATION: **Building A,B,C,D Exteriors**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/08/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Kenwood Academy** INSPECTION DATE: **4/18/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27**  
MATERIAL DESCRIPTION: **Exterior Brick Mortar-Not AHERA**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building A,B,C,D Exteriors**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/18/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kenwood Academy** REVIEW DATE: **6/8/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **27**

MATERIAL DESCRIPTION: **Exterior Brick Mortar-Not AHERA**

MATERIAL LOCATION: **Building A,B,C,D Exteriors**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/08/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUILDING ID: **1710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Kenwood Academy** INSPECTION DATE: **4/18/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28**  
MATERIAL DESCRIPTION: **Maroon Carpet Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building B - Principal's Office, Guidance Counselor's Office, Hall**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/18/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kenwood Academy** REVIEW DATE: **6/8/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **28**

MATERIAL DESCRIPTION: **Maroon Carpet Mastic**

MATERIAL LOCATION: **Building B - Principal's Office, Guidance Counselor's Office, Hall**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/08/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Kenwood Academy** INSPECTION DATE: **4/18/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **30**  
MATERIAL DESCRIPTION: **Blue Carpet Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building B - Main Office, 1st & 2nd Floor Media Centers**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/18/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kenwood Academy** REVIEW DATE: **6/8/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **30**

MATERIAL DESCRIPTION: **Blue Carpet Mastic**

MATERIAL LOCATION: **Building B - Main Office, 1st & 2nd Floor Media Centers**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/08/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Kenwood Academy** INSPECTION DATE: **4/18/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **31**  
MATERIAL DESCRIPTION: **1' x 1' Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building D**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/18/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kenwood Academy** REVIEW DATE: **6/8/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **31**

MATERIAL DESCRIPTION: **1' x 1' Ceiling Tile**

MATERIAL LOCATION: **Building D**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/08/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Kenwood Academy** INSPECTION DATE: **4/18/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **31.1**  
MATERIAL DESCRIPTION: **1' x 1' Ceiling Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building D**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/18/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kenwood Academy** REVIEW DATE: **6/8/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **31.1**  
MATERIAL DESCRIPTION: **1' x 1' Ceiling Tile Mastic**  
MATERIAL LOCATION: **Building D**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/08/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Kenwood Academy** INSPECTION DATE: **4/18/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **32**  
MATERIAL DESCRIPTION: **2' x 4' White Worm Pinhole Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Science Rooms (321, 324)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/18/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kenwood Academy** REVIEW DATE: **6/8/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **32**

MATERIAL DESCRIPTION: **2' x 4' White Worm Pinhole Ceiling Tile**

MATERIAL LOCATION: **Science Rooms (321, 324)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/08/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Kenwood Academy** INSPECTION DATE: **4/18/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **33**  
MATERIAL DESCRIPTION: **2' x 4' White Worm Pinhole Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building B - Rooms 323, 316, 221, 220, 219, 218, and 123**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/18/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kenwood Academy** REVIEW DATE: **6/8/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **33**

MATERIAL DESCRIPTION: **2' x 4' White Worm Pinhole Ceiling Tile**

MATERIAL LOCATION: **Building B - Rooms 323, 316, 221, 220, 219, 218, and 123**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/08/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Kenwood Academy** INSPECTION DATE: **4/18/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **34**  
MATERIAL DESCRIPTION: **Blue Baseboard**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Science Rooms (321, 324)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/18/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kenwood Academy** REVIEW DATE: **6/8/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **34**

MATERIAL DESCRIPTION: **Blue Baseboard**

MATERIAL LOCATION: **Science Rooms (321, 324)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/08/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Kenwood Academy** INSPECTION DATE: **4/18/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **35**  
MATERIAL DESCRIPTION: **Drywall**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Science Room (321, 324)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/18/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUILDING ID: **1710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kenwood Academy** REVIEW DATE: **6/8/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **35**

MATERIAL DESCRIPTION: **Drywall**

MATERIAL LOCATION: **Science Room (321, 324)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/08/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Kenwood Academy** INSPECTION DATE: **4/18/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **36**  
MATERIAL DESCRIPTION: **Drywall Joint Compound**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Science Rooms (321, 324)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/18/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kenwood Academy** REVIEW DATE: **6/8/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **36**

MATERIAL DESCRIPTION: **Drywall Joint Compound**

MATERIAL LOCATION: **Science Rooms (321, 324)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/08/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Kenwood Academy** INSPECTION DATE: **4/18/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37**  
MATERIAL DESCRIPTION: **Light Blue w/Dark Blue & White Streaks Linoleum**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Science Rooms (321, 324)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/18/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kenwood Academy** REVIEW DATE: **6/8/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **37**

MATERIAL DESCRIPTION: **Light Blue w/Dark Blue & White Streaks Linoleum**

MATERIAL LOCATION: **Science Rooms (321, 324)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/08/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Kenwood Academy** INSPECTION DATE: **4/18/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37.1**  
MATERIAL DESCRIPTION: **Lt Blue w/Dk Blue & White Streaks Linoleum Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Science Rooms (321, 324)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/18/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kenwood Academy** REVIEW DATE: **6/8/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **37.1**  
MATERIAL DESCRIPTION: **Lt Blue w/Dk Blue & White Streaks Linoleum Mastic**  
MATERIAL LOCATION: **Science Rooms (321, 324)**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/08/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Kenwood Academy** INSPECTION DATE: **4/18/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **38**  
MATERIAL DESCRIPTION: **Lab Table Tops**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Building B Rooms 305, 315, 301, 303, 303 Storage, 306, 310, 321 & 324**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/18/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kenwood Academy** REVIEW DATE: **6/8/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **38**  
MATERIAL DESCRIPTION: **Lab Table Tops**  
MATERIAL LOCATION: **Building B Rooms 305, 315, 301, 303, 303 Storage, 306, 310, 321 & 324**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/08/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Kenwood Academy** INSPECTION DATE: **4/18/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **39**  
MATERIAL DESCRIPTION: **Lab Hood**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Science Rooms (324, 321)**  
MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/18/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kenwood Academy** REVIEW DATE: **6/8/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **39**  
MATERIAL DESCRIPTION: **Lab Hood**  
MATERIAL LOCATION: **Science Rooms (324, 321)**  
MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/08/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Kenwood Academy** INSPECTION DATE: **4/18/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **40**  
MATERIAL DESCRIPTION: **Plaster Ceiling**  
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout Bathrooms**  
MATERIAL QUANTITY: **90000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/18/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kenwood Academy** REVIEW DATE: **6/8/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **40**  
MATERIAL DESCRIPTION: **Plaster Ceiling**  
MATERIAL LOCATION: **Throughout Bathrooms**  
MATERIAL QUANTITY: **90000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/08/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Kenwood Academy** INSPECTION DATE: **4/18/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **41**  
MATERIAL DESCRIPTION: **Drywall**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/18/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kenwood Academy** REVIEW DATE: **6/8/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **41**  
MATERIAL DESCRIPTION: **Drywall**  
MATERIAL LOCATION: **Throughout**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/08/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Kenwood Academy** INSPECTION DATE: **4/18/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **42**  
MATERIAL DESCRIPTION: **Drywall Joint Compound**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/18/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kenwood Academy** REVIEW DATE: **6/8/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **42**  
MATERIAL DESCRIPTION: **Drywall Joint Compound**  
MATERIAL LOCATION: **Throughout**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/08/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Kenwood Academy** INSPECTION DATE: **4/18/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **43**  
MATERIAL DESCRIPTION: **Transite Ceiling**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Building D Stairwell 13**  
MATERIAL QUANTITY: **10** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/18/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kenwood Academy** REVIEW DATE: **6/8/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **43**  
MATERIAL DESCRIPTION: **Transite Ceiling**  
MATERIAL LOCATION: **Building D Stairwell 13**  
MATERIAL QUANTITY: **10** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/08/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Kenwood Academy** INSPECTION DATE: **4/18/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **44**  
MATERIAL DESCRIPTION: **Transite Walls, Chalkboard Masonite**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Building D Lunchroom, Weight Room**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/18/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kenwood Academy** REVIEW DATE: **6/8/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **44**

MATERIAL DESCRIPTION: **Transite Walls, Chalkboard Masonite**

MATERIAL LOCATION: **Building D Lunchroom, Weight Room**

MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/08/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Kenwood Academy** INSPECTION DATE: **4/18/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **45**  
MATERIAL DESCRIPTION: **Vibration Gasket**  
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout Mechanical Rooms, MDF Room 123**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **04/18/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kenwood Academy** REVIEW DATE: **6/8/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **45**  
MATERIAL DESCRIPTION: **Vibration Gasket**  
MATERIAL LOCATION: **Throughout Mechanical Rooms, MDF Room 123**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/08/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Kenwood Academy** INSPECTION DATE: **4/18/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **46**  
MATERIAL DESCRIPTION: **Lab Hood**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Building B - Rooms 310, 305, and 315**  
MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/18/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kenwood Academy** REVIEW DATE: **6/8/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **46**  
MATERIAL DESCRIPTION: **Lab Hood**  
MATERIAL LOCATION: **Building B - Rooms 310, 305, and 315**  
MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/08/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Kenwood Academy** INSPECTION DATE: **4/18/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **47**  
MATERIAL DESCRIPTION: **Blue Baseboard Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building B - Science Rooms (324, 321)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/18/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kenwood Academy** REVIEW DATE: **6/8/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **47**

MATERIAL DESCRIPTION: **Blue Baseboard Mastic**

MATERIAL LOCATION: **Building B - Science Rooms (324, 321)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/08/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUILDING ID: **1710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Kenwood Academy** INSPECTION DATE: **4/18/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **48**  
MATERIAL DESCRIPTION: **12" x 12" Cream w/Brown Specks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Building A Rooms 227 & 234, Building B**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/18/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUILDING ID: **1710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kenwood Academy** REVIEW DATE: **6/8/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **48**  
MATERIAL DESCRIPTION: **12" x 12" Cream w/Brown Specks Floor Tile**  
MATERIAL LOCATION: **Building A Rooms 227 & 234, Building B**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/08/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUILDING ID: **1710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Kenwood Academy** INSPECTION DATE: **4/18/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **49**  
MATERIAL DESCRIPTION: **12" x 12" Cream w/Brown Specks Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Building A Rooms 227 & 234, Building B**

MATERIAL QUANTITY: **1500**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/18/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUILDING ID: **1710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kenwood Academy** REVIEW DATE: **6/8/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **49**  
MATERIAL DESCRIPTION: **12" x 12" Cream w/Brown Specks Floor Tile Mastic**  
MATERIAL LOCATION: **Building A Rooms 227 & 234, Building B**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/08/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Kenwood Academy** INSPECTION DATE: **4/18/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **50**  
MATERIAL DESCRIPTION: **12" x 12" White w/Reddish Specks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building A Room 134**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/18/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kenwood Academy** REVIEW DATE: **6/8/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **50**

MATERIAL DESCRIPTION: **12" x 12" White w/Reddish Specks Floor Tile**

MATERIAL LOCATION: **Building A Room 134**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/08/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Kenwood Academy** INSPECTION DATE: **4/18/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **51**  
MATERIAL DESCRIPTION: **12" x 12" White w/Reddish Specks Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building A Room 134**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/18/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kenwood Academy** REVIEW DATE: **6/8/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **51**

MATERIAL DESCRIPTION: **12" x 12" White w/Reddish Specks Floor Tile Mastic**

MATERIAL LOCATION: **Building A Room 134**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/08/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Kenwood Academy** INSPECTION DATE: **4/18/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **52**  
MATERIAL DESCRIPTION: **Sink Coating**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Building A Rooms 234 & 225**  
MATERIAL QUANTITY: **43** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/18/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kenwood Academy** REVIEW DATE: **6/8/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **52**  
MATERIAL DESCRIPTION: **Sink Coating**  
MATERIAL LOCATION: **Building A Rooms 234 & 225**  
MATERIAL QUANTITY: **43** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/08/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Kenwood Academy** INSPECTION DATE: **4/18/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **53**  
MATERIAL DESCRIPTION: **12" x 12" Gray w/Gray Specks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Building B Rooms 121**  
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/18/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kenwood Academy** REVIEW DATE: **6/8/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **53**  
MATERIAL DESCRIPTION: **12" x 12" Gray w/Gray Specks Floor Tile**  
MATERIAL LOCATION: **Building B Rooms 121**  
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/08/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Kenwood Academy** INSPECTION DATE: **4/18/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **54**  
MATERIAL DESCRIPTION: **12" x 12" Gray w/Gray Specks Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Building B Rooms 121**

MATERIAL QUANTITY: **900**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/18/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kenwood Academy** REVIEW DATE: **6/8/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **54**  
MATERIAL DESCRIPTION: **12" x 12" Gray w/Gray Specks Floor Tile Mastic**  
MATERIAL LOCATION: **Building B Rooms 121**  
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/08/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Kenwood Academy** INSPECTION DATE: **4/18/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **55**  
MATERIAL DESCRIPTION: **Gray Carpet Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Moderate**

MATERIAL LOCATION: **Building B 2nd Floor Faculty Commons**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not observed 2016**

Inspector's Signature:



Date: **04/18/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kenwood Academy** REVIEW DATE: **6/8/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **55**

MATERIAL DESCRIPTION: **Gray Carpet Mastic**

MATERIAL LOCATION: **Building B 2nd Floor Faculty Commons**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

If identified, implement O&M

Management Planner's Signature: \_\_\_\_\_



Date: **06/08/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Kenwood Academy** INSPECTION DATE: **4/18/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **56**  
MATERIAL DESCRIPTION: **12x12 Blue Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **ROOMS 321, 324**  
MATERIAL QUANTITY: **1700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/18/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kenwood Academy** REVIEW DATE: **6/8/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **56**  
MATERIAL DESCRIPTION: **12x12 Blue Floor Tile**  
MATERIAL LOCATION: **ROOMS 321, 324**  
MATERIAL QUANTITY: **1700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/08/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Kenwood Academy** INSPECTION DATE: **4/18/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **57**  
MATERIAL DESCRIPTION: **12x12 blue floor tile mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **rm 321, 324**  
MATERIAL QUANTITY: **1700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/18/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kenwood Academy** REVIEW DATE: **6/8/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **57**  
MATERIAL DESCRIPTION: **12x12 blue floor tile mastic**  
MATERIAL LOCATION: **rm 321, 324**  
MATERIAL QUANTITY: **1700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/08/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Kenwood Academy** INSPECTION DATE: **4/18/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **58**  
MATERIAL DESCRIPTION: **12x12 white ft w/ tan mottle**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **rm 128, 128A**  
MATERIAL QUANTITY: **950** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/18/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kenwood Academy** REVIEW DATE: **6/8/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **58**  
MATERIAL DESCRIPTION: **12x12 white ft w/ tan mottle**  
MATERIAL LOCATION: **rm 128, 128A**  
MATERIAL QUANTITY: **950** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/08/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Kenwood Academy** INSPECTION DATE: **4/18/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **59**  
MATERIAL DESCRIPTION: **Mastic for 12x12 white floor tile w/ tan mottle**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **rm 128, 128A**  
MATERIAL QUANTITY: **950** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/18/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kenwood Academy** REVIEW DATE: **6/8/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **59**  
MATERIAL DESCRIPTION: **Mastic for 12x12 white floor tile w/ tan mottle**  
MATERIAL LOCATION: **rm 128, 128A**  
MATERIAL QUANTITY: **950** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/08/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Kenwood Academy** INSPECTION DATE: **4/18/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **60**  
MATERIAL DESCRIPTION: **2x4 Ceiling tile w/ divots & dots**  
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **rm 128, 128A, 234**  
MATERIAL QUANTITY: **2100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/18/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kenwood Academy** REVIEW DATE: **6/8/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **60**  
MATERIAL DESCRIPTION: **2x4 Ceiling tile w/ divots & dots**  
MATERIAL LOCATION: **rm 128, 128A, 234**  
MATERIAL QUANTITY: **2100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/08/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Kenwood Academy** INSPECTION DATE: **4/18/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **61**  
MATERIAL DESCRIPTION: **12x12 Brown Mottle floor tile**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **rm 134 H**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/18/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kenwood Academy** REVIEW DATE: **6/8/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **61**

MATERIAL DESCRIPTION: **12x12 Brown Mottle floor tile**

MATERIAL LOCATION: **rm 134 H**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/08/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Kenwood Academy** INSPECTION DATE: **4/18/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **62**  
MATERIAL DESCRIPTION: **Mastic for 12x12 Brown mottle floor tile**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **rm 134 H**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/18/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kenwood Academy** REVIEW DATE: **6/8/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **62**

MATERIAL DESCRIPTION: **Mastic for 12x12 Brown mottle floor tile**

MATERIAL LOCATION: **rm 134 H**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/08/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Kenwood Academy** INSPECTION DATE: **4/18/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **63**  
MATERIAL DESCRIPTION: **12x12 Cream floor tile w/ brown specks**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **rm 234**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/18/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kenwood Academy** REVIEW DATE: **6/8/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **63**  
MATERIAL DESCRIPTION: **12x12 Cream floor tile w/ brown specks**  
MATERIAL LOCATION: **rm 234**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/08/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Kenwood Academy** INSPECTION DATE: **4/18/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **64**  
MATERIAL DESCRIPTION: **Mastic for 12x12 Cream floor tile w/ brown specks**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **rm 234**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/18/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kenwood Academy** REVIEW DATE: **6/8/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **64**  
MATERIAL DESCRIPTION: **Mastic for 12x12 Cream floor tile w/ brown specks**  
MATERIAL LOCATION: **rm 234**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/08/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Kenwood Academy** INSPECTION DATE: **4/18/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **65**  
MATERIAL DESCRIPTION: **12"x12" Peach VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Faculty Commons**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/18/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kenwood Academy** REVIEW DATE: **6/8/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **65**  
MATERIAL DESCRIPTION: **12"x12" Peach VFT**  
MATERIAL LOCATION: **Faculty Commons**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/08/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Kenwood Academy** INSPECTION DATE: **4/18/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **66**  
MATERIAL DESCRIPTION: **12"x12" Peach VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Faculty Commons**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/18/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kenwood Academy** REVIEW DATE: **6/8/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **66**  
MATERIAL DESCRIPTION: **12"x12" Peach VFT Mastic**  
MATERIAL LOCATION: **Faculty Commons**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/08/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Kenwood Academy** INSPECTION DATE: **4/18/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **A-1**  
MATERIAL DESCRIPTION: **2' x 4' Acoustical Ceiling Tiles**  
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout Building A - Offices, Hallways, Classrooms, 325 & 325 Office**  
MATERIAL QUANTITY: **9400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/18/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kenwood Academy** REVIEW DATE: **6/8/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **A-1**  
MATERIAL DESCRIPTION: **2' x 4' Acoustical Ceiling Tiles**  
MATERIAL LOCATION: **Throughout Building A - Offices, Hallways, Classrooms, 325 & 325 Office**  
MATERIAL QUANTITY: **9400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/08/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Kenwood Academy** INSPECTION DATE: **4/18/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **A-3**  
MATERIAL DESCRIPTION: **Spray-on Fireproofing**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Bldg.D-Rm224,223,Lunchroom,Kitchen,Halls,Boy's/GirlsToliet,Bldg C-East Mech.Rm,237,238, 266, Bldg.A Fan Rm**

MATERIAL QUANTITY: **10610**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/18/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kenwood Academy** REVIEW DATE: **6/8/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **A-3**  
MATERIAL DESCRIPTION: **Spray-on Fireproofing**  
MATERIAL LOCATION: **Bldg.D-Rm224,223,Lunchroom,Kitchen,Halls,Boy's/GirlsToliet,Bldg C-East Mech.Rm,237,238, 266, Bldg.A Fan Rm**  
MATERIAL QUANTITY: **10610** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/08/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Kenwood Academy** INSPECTION DATE: **4/18/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **A-6**  
MATERIAL DESCRIPTION: **12" x 12" Black Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Building B - 1st Floor Passageways**  
MATERIAL QUANTITY: **2160** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/18/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kenwood Academy** REVIEW DATE: **6/8/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **A-6**  
MATERIAL DESCRIPTION: **12" x 12" Black Floor Tile**  
MATERIAL LOCATION: **Building B - 1st Floor Passageways**  
MATERIAL QUANTITY: **2160** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/08/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Kenwood Academy** INSPECTION DATE: **4/18/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **A-6.1**  
MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Building D - District Superintendent's Office & Faculty Service Line**  
MATERIAL QUANTITY: **1900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/18/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kenwood Academy** REVIEW DATE: **6/8/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **A-6.1**  
MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile**  
MATERIAL LOCATION: **Building D - District Superintendent's Office & Faculty Service Line**  
MATERIAL QUANTITY: **1900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/08/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Kenwood Academy** INSPECTION DATE: **4/18/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **A-6.2**  
MATERIAL DESCRIPTION: **12" x 12" Blue Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Building B - Room 123/MDF Room 121/Office**

MATERIAL QUANTITY: **220** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: **04/18/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kenwood Academy** REVIEW DATE: **6/8/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **A-6.2**  
MATERIAL DESCRIPTION: **12" x 12" Blue Floor Tile**  
MATERIAL LOCATION: **Building B - Room 123/MDF Room 121/Office**  
MATERIAL QUANTITY: **220** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/08/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Kenwood Academy** INSPECTION DATE: **4/18/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **A-6.3**  
MATERIAL DESCRIPTION: **12" x 12" Beige w/Brown Specks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Building D-Engineer's Office, Rm. 227**

MATERIAL QUANTITY: **1710**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/18/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kenwood Academy** REVIEW DATE: **6/8/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **A-6.3**  
MATERIAL DESCRIPTION: **12" x 12" Beige w/Brown Specks Floor Tile**  
MATERIAL LOCATION: **Building D-Engineer's Office, Rm. 227**  
MATERIAL QUANTITY: **1710** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/08/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Kenwood Academy** INSPECTION DATE: **4/18/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **A-6.4**  
MATERIAL DESCRIPTION: **12" x 12" Tan Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Building A - Corridors, Rooms 232 and 233, Passageways 1,2,3,4**  
MATERIAL QUANTITY: **3885** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/18/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kenwood Academy** REVIEW DATE: **6/8/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **A-6.4**  
MATERIAL DESCRIPTION: **12" x 12" Tan Floor Tile**  
MATERIAL LOCATION: **Building A - Corridors, Rooms 232 and 233, Passageways 1,2,3,4**  
MATERIAL QUANTITY: **3885** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/08/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Kenwood Academy** INSPECTION DATE: **4/18/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **A-7**  
MATERIAL DESCRIPTION: **12" x 12" Black Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Building B - Passage ways 1 & 2**

MATERIAL QUANTITY: **2160**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/18/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kenwood Academy** REVIEW DATE: **6/8/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **A-7**  
MATERIAL DESCRIPTION: **12" x 12" Black Floor Tile Mastic**  
MATERIAL LOCATION: **Building B - Passage ways 1 & 2**  
MATERIAL QUANTITY: **2160** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/08/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUILDING ID: **1710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Kenwood Academy** INSPECTION DATE: **4/18/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **A-7.1**  
MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Building D-District Superintendent's Office & Faculty Service Line**  
MATERIAL QUANTITY: **1900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/18/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kenwood Academy** REVIEW DATE: **6/8/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **A-7.1**  
MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile Mastic**  
MATERIAL LOCATION: **Building D-District Superintendent's Office & Faculty Service Line**  
MATERIAL QUANTITY: **1900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/08/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Kenwood Academy** INSPECTION DATE: **4/18/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **A-7.2**  
MATERIAL DESCRIPTION: **12" x 12" Blue Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building B - Room 121/MDF Room 121/Office**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/18/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kenwood Academy** REVIEW DATE: **6/8/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **A-7.2**  
MATERIAL DESCRIPTION: **12" x 12" Blue Floor Tile Mastic**  
MATERIAL LOCATION: **Building B - Room 121/MDF Room 121/Office**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/08/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Kenwood Academy** INSPECTION DATE: **4/18/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **A-7.3**  
MATERIAL DESCRIPTION: **12" x 12" Beige w/ Brown Specks Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Building D-Engineer's Office, Rm. 227**

MATERIAL QUANTITY: **1710**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/18/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUILDING ID: **1710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kenwood Academy** REVIEW DATE: **6/8/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **A-7.3**  
MATERIAL DESCRIPTION: **12" x 12" Beige w/ Brown Specks Floor Tile Mastic**  
MATERIAL LOCATION: **Building D-Engineer's Office, Rm. 227**  
MATERIAL QUANTITY: **1710** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/08/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Kenwood Academy** INSPECTION DATE: **4/18/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **A-7.4**  
MATERIAL DESCRIPTION: **12" x 12" Tan Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Building A - Halls, and Rooms 232 and 233**  
MATERIAL QUANTITY: **3885** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature:



Date: **04/18/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kenwood Academy** REVIEW DATE: **6/8/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **A-7.4**  
MATERIAL DESCRIPTION: **12" x 12" Tan Floor Tile Mastic**  
MATERIAL LOCATION: **Building A - Halls, and Rooms 232 and 233**  
MATERIAL QUANTITY: **3885** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/08/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Kenwood Academy** INSPECTION DATE: **4/18/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **A-8**  
MATERIAL DESCRIPTION: **9" x 9" Beige Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with potential for significant damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Buildings D - Hall, A4 Building - Throughout Classrooms, Labs, Offices, Throughout Bldg.B Classrooms**

MATERIAL QUANTITY: **21000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/18/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kenwood Academy** REVIEW DATE: **6/8/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **A-8**  
MATERIAL DESCRIPTION: **9" x 9" Beige Floor Tile Mastic**  
MATERIAL LOCATION: **Buildings D - Hall, A4 Building - Throughout Classrooms, Labs, Offices, Throughout Bldg.B Classrooms**  
MATERIAL QUANTITY: **21000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/08/2016**

# Chicago Public Schools

## Carnow, Conibear and Associates 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Kenwood Academy** INSPECTION DATE: **4/18/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **A-8.1**  
MATERIAL DESCRIPTION: **9" x 9" Brown Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Hallways Throughout Facility, Building A - Room 225**  
MATERIAL QUANTITY: **22600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/18/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kenwood Academy** REVIEW DATE: **6/8/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **A-8.1**  
MATERIAL DESCRIPTION: **9" x 9" Brown Floor Tile Mastic**  
MATERIAL LOCATION: **Hallways Throughout Facility, Building A - Room 225**  
MATERIAL QUANTITY: **22600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/08/2016**

# Chicago Public Schools

## Carnow, Conibear and Associates 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Kenwood Academy** INSPECTION DATE: **4/18/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **A-9**  
MATERIAL DESCRIPTION: **9" x 9" Beige Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Building D-Hall, A4 Building-Throughout Facility Classrooms, Offices, Labs, Throughout Bldg. B Classrooms**

MATERIAL QUANTITY: **21000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/18/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kenwood Academy** REVIEW DATE: **6/8/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **A-9**  
MATERIAL DESCRIPTION: **9" x 9" Beige Floor Tile**  
MATERIAL LOCATION: **Building D-Hall, A4 Building-Throughout Facility Classrooms, Offices, Labs, Throughout Bldg.B Classrooms**  
MATERIAL QUANTITY: **21000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/08/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Kenwood Academy** INSPECTION DATE: **4/18/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **A-9.1**  
MATERIAL DESCRIPTION: **9" x 9" Brown Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with potential for significant damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Hallways Throughout Facility, Building A - Room 225, Room 226**  
MATERIAL QUANTITY: **21000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/18/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUILDING ID: **1710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kenwood Academy** REVIEW DATE: **6/8/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **A-9.1**  
MATERIAL DESCRIPTION: **9" x 9" Brown Floor Tile**  
MATERIAL LOCATION: **Hallways Throughout Facility, Building A - Room 225, Room 226**  
MATERIAL QUANTITY: **21000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/08/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Kenwood Academy** INSPECTION DATE: **4/18/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **A-C**  
MATERIAL DESCRIPTION: **Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building A - Penthouse**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/18/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kenwood Academy** REVIEW DATE: **6/8/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **A-C**

MATERIAL DESCRIPTION: **Pipe Insulation**

MATERIAL LOCATION: **Building A - Penthouse**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/08/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Kenwood Academy** INSPECTION DATE: **4/18/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **A-E**  
MATERIAL DESCRIPTION: **Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building A - Pipe chases**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/18/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kenwood Academy** REVIEW DATE: **6/8/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **A-E**  
MATERIAL DESCRIPTION: **Pipe Insulation**  
MATERIAL LOCATION: **Building A - Pipe chases**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/08/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Kenwood Academy** INSPECTION DATE: **4/18/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **B(A-2)**  
MATERIAL DESCRIPTION: **Tank Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Building B - 4th Floor Boiler Room**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/18/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kenwood Academy** REVIEW DATE: **6/8/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **B(A-2)**  
MATERIAL DESCRIPTION: **Tank Insulation**  
MATERIAL LOCATION: **Building B - 4th Floor Boiler Room**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/08/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Kenwood Academy** INSPECTION DATE: **4/18/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **B(A-3)**  
MATERIAL DESCRIPTION: **Cementitious Insulation (Joint)**  
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Building B - 4th Floor Boiler Room**  
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/18/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kenwood Academy** REVIEW DATE: **6/8/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **B(A-3)**  
MATERIAL DESCRIPTION: **Cementitious Insulation (Joint)**  
MATERIAL LOCATION: **Building B - 4th Floor Boiler Room**  
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/08/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Kenwood Academy** INSPECTION DATE: **4/18/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **B-1**  
MATERIAL DESCRIPTION: **2' x 4' Acoustical Ceiling Tile w/Pinholes**  
HISTORICAL AHERA DAMAGE CATEGORY **4 ACBM with potential for significant damage**  
HISTORICAL DAMAGE REASON: **Vibration**  
HISTORICAL RESPONSE ACTION: **Remove**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **4. Damaged or significantly damaged friable misc. ACBM**

DAMAGE REASON: **Water**  
DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **RM 234, 315, 325**  
MATERIAL QUANTITY: **2250** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **2250** DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: **04/18/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kenwood Academy** REVIEW DATE: **6/8/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **B-1**  
MATERIAL DESCRIPTION: **2' x 4' Acoustical Ceiling Tile w/Pinholes**  
MATERIAL LOCATION: **RM 234, 315, 325**  
MATERIAL QUANTITY: **2250** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **208** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Remove**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/08/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUILDING ID: **1710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Kenwood Academy** INSPECTION DATE: **4/18/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **B-1.1**  
MATERIAL DESCRIPTION: **2' x 4' Acoustical Ceiling Tile/White Worm Pinhole**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building A - Hall, Rooms 232, 233, 234, 237 & 225**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/18/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUILDING ID: **1710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kenwood Academy** REVIEW DATE: **6/8/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **B-1.1**

MATERIAL DESCRIPTION: **2' x 4' Acoustical Ceiling Tile/White Worm Pinhole**

MATERIAL LOCATION: **Building A - Hall, Rooms 232, 233, 234, 237 & 225**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/08/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Kenwood Academy** INSPECTION DATE: **4/18/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **B-D**  
MATERIAL DESCRIPTION: **Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Building B - Boiler Room**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/18/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUILDING ID: **1710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kenwood Academy** REVIEW DATE: **6/8/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **B-D**  
MATERIAL DESCRIPTION: **Pipe Insulation**  
MATERIAL LOCATION: **Building B - Boiler Room**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/08/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Kenwood Academy** INSPECTION DATE: **4/18/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **C-B**  
MATERIAL DESCRIPTION: **Cemetitious Insulation (Joint)**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Moderate**

MATERIAL LOCATION: **Building C - Roof Drains**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not observed 2016**

Inspector's Signature:



Date: **04/18/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kenwood Academy** REVIEW DATE: **6/8/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **C-B**  
MATERIAL DESCRIPTION: **Cemetitious Insulation (Joint)**  
MATERIAL LOCATION: **Building C - Roof Drains**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

If identified, implement O&M

Management Planner's Signature: \_\_\_\_\_



Date: **06/08/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Kenwood Academy** INSPECTION DATE: **4/18/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **C-C**  
MATERIAL DESCRIPTION: **Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Inaccessible** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Moderate**

MATERIAL LOCATION: **Building C - Throughout Building and Crawlspace**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/18/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUILDING ID: **1710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kenwood Academy** REVIEW DATE: **6/8/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **C-C**  
MATERIAL DESCRIPTION: **Pipe Insulation**  
MATERIAL LOCATION: **Building C - Throughout Building and Crawlspace**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.


The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

If identified, implement O&M

Management Planner's Signature: \_\_\_\_\_



Date: **06/08/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Kenwood Academy** INSPECTION DATE: **4/18/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **C-D**  
MATERIAL DESCRIPTION: **Cementitious Insulation on Pipe Joint**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Moderate**

MATERIAL LOCATION: **Throughout Building C**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not observed 2016**

Inspector's Signature:



Date: **04/18/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kenwood Academy** REVIEW DATE: **6/8/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **C-D**  
MATERIAL DESCRIPTION: **Cementitious Insulation on Pipe Joint**  
MATERIAL LOCATION: **Throughout Building C**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

If identified, implement O&M

Management Planner's Signature: \_\_\_\_\_



Date: **06/08/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Kenwood Academy** INSPECTION DATE: **4/18/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **C-E**  
MATERIAL DESCRIPTION: **Tank Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Building C - 3rd Floor Mechanical Room**  
MATERIAL QUANTITY: **245** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/18/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kenwood Academy** REVIEW DATE: **6/8/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **C-E**  
MATERIAL DESCRIPTION: **Tank Insulation**  
MATERIAL LOCATION: **Building C - 3rd Floor Mechanical Room**  
MATERIAL QUANTITY: **245** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/08/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Kenwood Academy** INSPECTION DATE: **4/18/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **CK-DC**  
MATERIAL DESCRIPTION: **Joint Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Building D - Equipment Room**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **04/18/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kenwood Academy** REVIEW DATE: **6/8/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **CK-DC**

MATERIAL DESCRIPTION: **Joint Insulation**

MATERIAL LOCATION: **Building D - Equipment Room**

MATERIAL QUANTITY: **500**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/08/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Kenwood Academy** INSPECTION DATE: **4/18/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **CK-DE**  
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Moderate**

MATERIAL LOCATION: **Building D - Cafeteria Pipe Chase**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not observed 2016**

Inspector's Signature:



Date: **04/18/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kenwood Academy** REVIEW DATE: **6/8/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **CK-DE**

MATERIAL DESCRIPTION: **Aircell Pipe Insulation**

MATERIAL LOCATION: **Building D - Cafeteria Pipe Chase**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

If identified, implement O&M

Management Planner's Signature: \_\_\_\_\_



Date: **06/08/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Kenwood Academy** INSPECTION DATE: **4/18/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **CK-DF**  
MATERIAL DESCRIPTION: **Lag & Joint Cement**  
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Building D - Mechanical Room**  
MATERIAL QUANTITY: **50** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **04/18/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kenwood Academy** REVIEW DATE: **6/8/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **CK-DF**

MATERIAL DESCRIPTION: **Lag & Joint Cement**

MATERIAL LOCATION: **Building D - Mechanical Room**

MATERIAL QUANTITY: **50**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/08/2016**

# Chicago Public Schools

## Carnow, Conibear and Associates 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Kenwood Academy** INSPECTION DATE: **4/18/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **CK-DG**  
MATERIAL DESCRIPTION: **Tank Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Building D - Mechanical Room**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 04/18/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kenwood Academy** REVIEW DATE: **6/8/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **CK-DG**

MATERIAL DESCRIPTION: **Tank Insulation**

MATERIAL LOCATION: **Building D - Mechanical Room**

MATERIAL QUANTITY: **300**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/08/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Kenwood Academy** INSPECTION DATE: **4/18/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **E-B**  
MATERIAL DESCRIPTION: **Fiberglass Pipe Insulation Hard Elbows**  
HISTORICAL AHERA DAMAGE CATEGORY **1 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON: **Deterioration**  
HISTORICAL RESPONSE ACTION: **Repair**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON: **Physical Damage**  
DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Buildings A, B, C, D**  
MATERIAL QUANTITY: **896** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY:  DAMAGE UNITS: **LF**  
COMMENTS:

Inspector's Signature:



Date: **04/18/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUILDING ID: **1710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kenwood Academy** REVIEW DATE: **6/8/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **E-B**  
MATERIAL DESCRIPTION: **Fiberglass Pipe Insulation Hard Elbows**  
MATERIAL LOCATION: **Buildings A, B, C, D**  
MATERIAL QUANTITY: **896** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **15** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair**

Comments:

Remove or Repair as applicable. Continue O&M.

Management Planner's Signature: \_\_\_\_\_



Date: **06/08/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Kenwood Academy** INSPECTION DATE: **4/18/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **E-C**  
MATERIAL DESCRIPTION: **Tank Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **1 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON: **Deterioration**  
HISTORICAL RESPONSE ACTION: **Repair**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON: **Deterioration**  
DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Building D - 1st Floor Mechanical Room**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY:  DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 04/18/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kenwood Academy** REVIEW DATE: **6/8/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **E-C**  
MATERIAL DESCRIPTION: **Tank Insulation**  
MATERIAL LOCATION: **Building D - 1st Floor Mechanical Room**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **5** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.


The RESPONSE ACTION recommendation is:

**Repair**

Comments:

Remove or Repair as applicable. Continue O&M.

Management Planner's Signature: \_\_\_\_\_



Date: **06/08/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Kenwood Academy** INSPECTION DATE: **4/18/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **P**  
MATERIAL DESCRIPTION: **Incinerator Stack Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Moderate**

MATERIAL LOCATION: **Building D - Mechanical Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not observed 2016**

Inspector's Signature:



Date: **04/18/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUIDLING ID: **1710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kenwood Academy** REVIEW DATE: **6/8/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **P**

MATERIAL DESCRIPTION: **Incinerator Stack Insulation**

MATERIAL LOCATION: **Building D - Mechanical Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

If identified, implement O&M

Management Planner's Signature: \_\_\_\_\_



Date: **06/08/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **46361**      BUILDING ID: **1710**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Kenwood Academy**      INSPECTION DATE: **4/18/2016**  
ADDRESS: **5015 S. Blackstone**      IDPH LICENSE NO: **100-09969**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **71**  
MATERIAL DESCRIPTION: **12" x 12" Yellowish Floor Tile**  
MATERIAL LOCATION: **Main Office**  
MATERIAL QUANTITY: **800**      MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**      FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**      CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**      DAMAGE REASON:  
DAMAGE QUANTITY: **0**      DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Dionne M. Walker*

Date: 04/18/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUILDING ID: **1710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kenwood Academy** REVIEW DATE: **6/8/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **71**

MATERIAL DESCRIPTION: **12" x 12" Yellowish Floor Tile**

MATERIAL LOCATION: **Main Office**

MATERIAL QUANTITY: **800**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: **06/08/2016**



# Chicago Public Schools

## Carnow, Conibear and Associates 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **46361**      BUILDING ID: **1710**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kenwood Academy**      REVIEW DATE: **6/8/2016**  
ADDRESS: **5015 S. Blackstone**      IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **74**  
MATERIAL DESCRIPTION: **Mastic Associated w/ 12" x 12" White Floor Tile**  
MATERIAL LOCATION: **2nd Floor Lunchroom, Kitchen Faculty, Room 127**  
MATERIAL QUANTITY: **2280**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: **06/08/2016**



# Chicago Public Schools

## Carnow, Conibear and Associates 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUILDING ID: **1710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kenwood Academy** REVIEW DATE: **6/8/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **70**

MATERIAL DESCRIPTION: **Mastic Associated w/ 12" x 12" Blue Floor Tile**

MATERIAL LOCATION: **1st Floor Hallways, Rooms 106, 107, 108, 109, 110, 116, 117, 118, 119, 120, and 126**

MATERIAL QUANTITY: **9900** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: **06/08/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUILDING ID: **1710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kenwood Academy** REVIEW DATE: **6/8/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **80**  
MATERIAL DESCRIPTION: **Carpet Tile Mastic**  
MATERIAL LOCATION: **Room 122 and Main Office**  
MATERIAL QUANTITY: **3600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: **06/08/2016**



# Chicago Public Schools

## Carnow, Conibear and Associates 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUILDING ID: **1710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kenwood Academy** REVIEW DATE: **6/8/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **69**

MATERIAL DESCRIPTION: **12" x 12" Blue Floor Tile**

MATERIAL LOCATION: **1st Floor Hallways, Rooms 106, 107, 108, 109, 110, 116, 117, 118, 119, 120, and 126**

MATERIAL QUANTITY: **9900**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: **06/08/2016**



# Chicago Public Schools

## Carnow, Conibear and Associates 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **46361**      BUILDING ID: **1710**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kenwood Academy**      REVIEW DATE: **6/8/2016**  
ADDRESS: **5015 S. Blackstone**      IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **72**  
MATERIAL DESCRIPTION: **Mastic Associated w/ 12" x 12" Yellowish Floor Tile**  
MATERIAL LOCATION: **Main Office**  
MATERIAL QUANTITY: **800**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: 06/08/2016



# Chicago Public Schools

## Carnow, Conibear and Associates 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUILDING ID: **1710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kenwood Academy** REVIEW DATE: **6/8/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **79**

MATERIAL DESCRIPTION: **Mastic Associated w/ 12" x 12" Blue, White, and Beige Floor Tile**

MATERIAL LOCATION: **Rooms 133 and 134**

MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: **06/08/2016**



# Chicago Public Schools

## Carnow, Conibear and Associates 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **46361**      BUILDING ID: **1710**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kenwood Academy**      REVIEW DATE: **6/8/2016**  
ADDRESS: **5015 S. Blackstone**      IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **68**  
MATERIAL DESCRIPTION: **Mastic Associated w/ 12" x 12" Bright White Floor Tile**  
MATERIAL LOCATION: **1st Floor Hallways**  
MATERIAL QUANTITY: **1500**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: **06/08/2016**



# Chicago Public Schools

## Carnow, Conibear and Associates 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUILDING ID: **1710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kenwood Academy** REVIEW DATE: **6/8/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **76**  
MATERIAL DESCRIPTION: **Mastic Associated w/ 12 x 12" Light Blue Floor Tile**  
MATERIAL LOCATION: **Lunchroom**  
MATERIAL QUANTITY: **9000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: 06/08/2016



# Chicago Public Schools

## Carnow, Conibear and Associates 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **46361**      BUILDING ID: **1710**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kenwood Academy**      REVIEW DATE: **6/8/2016**  
ADDRESS: **5015 S. Blackstone**      IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **77**  
MATERIAL DESCRIPTION: **Blue Carpet Mastic**  
MATERIAL LOCATION: **Auditorium**  
MATERIAL QUANTITY: **700**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  \_\_\_\_\_ Date: **06/08/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **46361**    BUILDING ID: **1710**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Kenwood Academy**    INSPECTION DATE: **4/18/2016**  
ADDRESS: **5015 S. Blackstone**    IDPH LICENSE NO: **100-09969**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **73**  
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile**  
MATERIAL LOCATION: **2nd Floor Lunchroom, Kitchen Faculty, Room 127**  
MATERIAL QUANTITY: **2280**    MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**    FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**    CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**    DAMAGE REASON:  
DAMAGE QUANTITY: **0**    DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature:



Date: **04/18/2016**

# Chicago Public Schools

## Carnow, Conibear and Associates 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **46361**      BUILDING ID: **1710**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kenwood Academy**      REVIEW DATE: **6/8/2016**  
ADDRESS: **5015 S. Blackstone**      IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **73**  
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile**  
MATERIAL LOCATION: **2nd Floor Lunchroom, Kitchen Faculty, Room 127**  
MATERIAL QUANTITY: **2280**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: **06/08/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **46361**    BUILDING ID: **1710**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Kenwood Academy**    INSPECTION DATE: **4/18/2016**  
ADDRESS: **5015 S. Blackstone**    IDPH LICENSE NO: **100-09969**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **75**  
MATERIAL DESCRIPTION: **12 x 12" Light Blue Floor Tile**  
MATERIAL LOCATION: **Lunchroom**  
MATERIAL QUANTITY: **9000**    MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**    FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**    CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**    DAMAGE REASON:  
DAMAGE QUANTITY: **0**    DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature:



Date: **04/18/2016**

# Chicago Public Schools

## Carnow, Conibear and Associates 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUILDING ID: **1710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kenwood Academy** REVIEW DATE: **6/8/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **75**  
MATERIAL DESCRIPTION: **12 x 12" Light Blue Floor Tile**  
MATERIAL LOCATION: **Lunchroom**  
MATERIAL QUANTITY: **9000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: **06/08/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **46361**    BUILDING ID: **1710**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Kenwood Academy**    INSPECTION DATE: **4/18/2016**  
ADDRESS: **5015 S. Blackstone**    IDPH LICENSE NO: **100-09969**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **78**  
MATERIAL DESCRIPTION: **12" x 12" Blue, White, and Beige Floor Tile**  
MATERIAL LOCATION: **Rooms 133 and 134**  
MATERIAL QUANTITY: **2000**    MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**    FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**    CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**    DAMAGE REASON:  
DAMAGE QUANTITY: **0**    DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature:



Date: **04/18/2016**

# Chicago Public Schools

## Carnow, Conibear and Associates 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUILDING ID: **1710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kenwood Academy** REVIEW DATE: **6/8/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **78**  
MATERIAL DESCRIPTION: **12" x 12" Blue, White, and Beige Floor Tile**  
MATERIAL LOCATION: **Rooms 133 and 134**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: **06/08/2016**



# Chicago Public Schools

## Carnow, Conibear and Associates 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46361** BUILDING ID: **1710**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kenwood Academy** REVIEW DATE: **6/8/2016**  
ADDRESS: **5015 S. Blackstone** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **67**  
MATERIAL DESCRIPTION: **12" x 12" Bright White Floor Tile**  
MATERIAL LOCATION: **1st Floor Hallways**  
MATERIAL QUANTITY: **15100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: 06/08/2016

# **Chicago Public Schools**

**Carnow, Conibear and Associates**

***2016 AHERA REINSPECTION***

# APPENDIX B

## Inspector and Management Planner Licenses

---

# JAINA ASSOCIATES

THIS IS TO CERTIFY

THAT

**DIONNE L. CAREY**

HAS SUCCESSFULLY COMPLETED THE SAMPLING AND EVALUATING ASBESTOS AIRBORNE DUST - NIOSH 582 EQUIVALENT TRAINING COURSE, AND PASSED THE EXAMINATION WITH A SCORE OF 70% OR ABOVE FOR THE PURPOSE OF CERTIFICATION.

COURSE DATE: May 14 to 17, 2005

EXAM DATE: May 17, 2005

LOCATION: GSG Environmental, Inc.  
855 West Adams Street, Suite 200  
Chicago, Illinois 60607

DIRECTOR  
OF TRAINING:  
  
SANJIV JAIN

CERTIFICATE No.: 05JA-051405  
IDPH COURSE PROVIDER No.: 038



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • [www.dph.illinois.gov](http://www.dph.illinois.gov)

4/18/2016

**DIONNE L CAREY WALKER**  
211 Somerset Drive  
Streamwood, IL 60107

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 09969

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

ASBESTOS PROFESSIONAL LICENSE			ENDORSEMENTS	TC EXPIRES
			INSPECTOR	3/11/2017
ID NUMBER	ISSUED	EXPIRES	PROJECT MANAGER	3/12/2017
100 - 09969	4/18/2016	05/15/2017	AIR SAMPLING PROFESSIONAL	
<b>DIONNE L CAREY WALKER</b>			<b>Alteration of this license shall result in legal action</b>	
211 Somerset Drive			This license issued under authority of the State of Illinois	
Streamwood, IL 60107			Department of Public Health	
Environmental Health			This license is valid only when accompanied by a valid training course certificate.	

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: [dph.illinois.gov/topics-services/environmental-health-protection/asbestos](http://dph.illinois.gov/topics-services/environmental-health-protection/asbestos)  
EMAIL Address: [dph.asbestos@illinois.gov](mailto:dph.asbestos@illinois.gov)

PROTECTING HEALTH, IMPROVING LIVES  
*Nationally Accredited by PHAB*

2016



**OCCUPATIONAL TRAINING & SUPPLY, INC.**

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900

# Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

**Daniel Juneau**

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 1/6/2016

Exam Date: 1/6/2016

Expiration Date: 1/6/2017

Certificate Number: MPR1601060038

  
\_\_\_\_\_  
Kathy DeSalvo, Director

# Daniel Juneau

Illinois Licensed Asbestos Inspector, Management Planner,  
Project Manager, and Air Sampling Professional



## ASBESTOS PROFESSIONAL LICENSE

ID NUMBER  
**100 - 03613**

ISSUED  
**3/16/2015**

EXPIRES  
**05/15/2016**

DANIEL J JUNEAU  
1408 OAKWOOD AVENUE  
DES PLAINES, IL 60016

Environmental Health



### ENDORSEMENTS

### TC EXPIRES

INSPECTOR

12/2/2015

MANAGEMENT PLANNER

1/20/2016

PROJECT MANAGER

12/11/2015

AIR SAMPLING PROFESSIONAL

**Alteration of this license shall result in legal action**  
This license issued under authority of the State of Illinois  
Department of Public Health

This license is valid only when accompanied by a valid  
training course certificate.

**CARNOW  
CONIBEAR**

2015



**OCCUPATIONAL TRAINING & SUPPLY, INC.**

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900

# Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

**Daniel Juneau**

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 12/2/2015

Exam Date: 12/2/2015

Expiration Date: 12/2/2016

Certificate Number: BIR1512024163

  
Kathy DeSalvo, Director

# APPENDIX C

## Laboratory Accreditations

---

# APPENDIX D

## Laboratory Results

---

# APPENDIX E

## Chain of Custody Forms

---

## Three-Year Reinspection Key to Terms

	<b>CODE</b>	<b>KEY</b>
<b>MATERIAL</b>		
	ACBM	Asbestos Containing Building Materials
<b>MATERIAL CATEGORY</b>		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
<b>MATERIAL UNITS</b>		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
<b>DAMAGE TYPE</b>		
	Loc	Localized
	Dist	Distributed