

ILLINOIS DEPARTMENT OF PUBLIC HEALTH  
AHERA THREE YEAR REINSPECTION  
ASBESTOS ABATEMENT PROGRAM  
SCHOOL INFORMATION FORM

**SECTION I**

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299  
SCHOOL ID NUMBER: 14-016-2990-0006  
SCHOOL NAME: Carver Military Academy  
ADDRESS OF SCHOOL: 13100 S. Doty  
CITY: Chicago, IL, 60627

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **5/7/2013**

**If the address on this form is different than the address of the building, submit a written explanation.**

**SECTION II** (Please type or print)

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 6/16/2016 ENROLLMENT 493  
IDPH INSPECTOR LICENSE NUMBER: 100-19039  
IDPH LICENSED INSPECTOR NAME (Please Print): Wayne Gardner  
IDPH MP LICENSE NUMBER: 100-01786  
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Guillermo Garcia

DESIGNATED PERSON (Please Print): Robert Christlieb PHONE: (773) 553-3197



6/16/2016

Signature of Designated Person

Date

**SECTION III**

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: \_\_\_\_\_

School has been closed. Date closed: \_\_\_\_\_

School building has been demolished. Date: \_\_\_\_\_

School building is asbestos free since last reinspection: \_\_\_\_\_

**Please explain in writing why the school building is now asbestos free and include the supporting documentation.**

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

**Explain in writing if the address of the building is different than the address on this form:**

**THREE-YEAR REINSPECTION**

**CHICAGO SCHOOL DIST 299**

**Carver Military Academy**

13100 S. Doty  
Chicago, IL, 60627

Unit: 46381  
Building ID: 1850

IDPH ID Number: 14-016-2990-0006

**REPORT DATE:**

Thursday, June 16, 2016

**Prepared for:**

**Chicago Public Schools  
125 S. Clark Street  
Chicago, IL 60603**

**Prepared by:**

**GSG Consultants, Inc.**

855 W. Adams St., Ste. 200

Phone (312) 733-6262

Fax (312) 733-5612

**DO NOT REMOVE FROM SCHOOL  
REQUIRED BY FEDERAL LAW**



## **Environmental Notification to Occupants**

To: Faculty, Staff and Parents  
From: Chicago Public Schools  
Date: April 05, 2016

RE: Carver Military Academy, Unit 46381  
13100 S. Doty  
Chicago, IL, 60627

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2016 asbestos three year re-inspection has been completed at Carver Military Academy , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at Carver Military Academy, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Robert Christlieb, the designated Local Education Authority's Designated Person at (773) 553-3197 .

## **Table of Contents**

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

### **APPENDICES:**

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

## SCHOOL AND INSPECTION INFORMATION

### 1. School Information

School: Carver Military Academy      Unit: 46381      Region: 06  
Address: 13100 S. Doty      Chicago, IL, 60627  
IDPH ID: 14-016-2990-0006      Building ID: 1850  
Contact: Brown, David      Phone: 7735355250

### 2. Description of Facility

Original Construction: 1955      Additional Construction:  
Total Square Footage: 298689      No of Floors: 3  
Current Occupancy: 493

### 3. LEA Designated Person

Contact: Robert Christlieb      Phone: (773) 553-3197  
Address: 125 South Clark Street, 17th Floor  
Chicago, IL 60603


### 4. Managing Environmental Consultant

MEC: GSG Consultants, Inc.  
Contact: Arturo Saenz      Fax: (312) 733-5612  
Address 855 W. Adams St., Ste. 200  
Phone: (312) 733-6262

### 5. Inspector

Inspector Name: Wayne Gardner


Inspector IDPH license # 100-19039

  
Signature:  
Date: 4/5/2016

### 6. Management Planner

Management Planner Name: Guillermo Garcia

Management Planner IDPH license # 100-01786

  
Signature:  
Date: 05/16/2016

### 7. Review Date: 05/16/2016

### 8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature:



Date: 6/16/2016

Name: Robert Christlieb

## II. EXECUTIVE SUMMARY

GSG Consultants, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Carver Military Academy. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 1850:

015

12x12 Acoustical Ceiling Tile

B. The following new homogenous areas have been identified for Building 1850:



C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

013D	Green Carpet Mastic
014	Spray on Insulation
015	12x12 Acoustical Ceiling Tile
020	12" x 12" Brown with Tan/White Streaks Floor Tile & Adhesive
021	12" x 12" White w/ White & Pink Speckles Floor Tile and Adhesive
022	Insulation on Boiler Exhaust Pipes
023	Insulation on Hot Water Tank
024	MJP E/F/V on Fiberglass Pipe Insulation
025	Tan and Brown Streaked Linoleum & Adhesive
026	1 x 1 Ceiling Tile Splined
027	Beige Terrazzo
028	Drywall
100M	Adhesive for Brown with White Streaks Stair Treads
101	White Woven Insulation on Electrical Copper Wires
102	12"x12" Floor Tile
102M	Adhesive for 12"x12" Floor Tile
104	12 x 12 VFT Gray w/ Mixed Blue Specs
104M	12 x 12 VFT Gray w/ Mixed Blue Specs Mastic
105	12 x 12 VFT Green
105M	12 x 12 VFT Green Mastic
106	12 x 12 Black VFT w/ white
106M	12 x 12 Black VFT w/ White Specs Mastic

The following areas were deemed to be inaccessible:

006A	12x12 Dark Brown Floor Tile Mastic
006B	12x12 Tan FloorTile Mastic
006C	12x12 Olive Green Floor Tile Mastic
006D	12x12 Gray Floor Tile Mastic
006E	12x12 Off White Floor Tile Mastic
013D	Green Carpet Mastic
014	Spray on Insulation
015	12x12 Acoustical Ceiling Tile
100M	Adhesive for Brown with White Streaks Stair Treads
102M	Adhesive for 12"x12" Floor Tile

Materials were also listed as "assumed" if they were in good condition and sampling was not

conducted to avoid damage.

This reinspection was conducted by Wayne Gardner , IDPH License # 100-19039. The Management Plan was updated by Guillermo Garcia, IDPH License # 100-01786. Inspector and Management Planner Licenses are included in Appendix B.

### **III. METHODOLOGY**

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

### **IV. ABATEMENT HISTORY**

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

### **V. REASSESSMENTS AND RECOMMENDATIONS**

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

### **VI. CONCLUSIONS**

The Carver Military Academy Building 1850 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

**Table I**  
**Inspector's Reinspection Findings**

---

# Chicago Public Schools

School Carver Military Academy Unit 46381 Building ID 1850

Address 13100 S. Doty Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
003A	12x12 Dark Brown Floor Tile	14,430	SF	Lunchroom, Gym Office, Attendance Room, Auditorium Basement Hallway	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
003B	12x12 Tan Floor Tile			Attendance Room, Locker Rooms, Health Room, Drivers Ed Room	NO_ACBM	MISC								
003C	12x12 Olive Green Floor Tile	5,000	SF	Gym Balcony, Stairs, Elevators	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
003D	12x12 Gray Floor Tile Mastic			Basement Corridors	NO_ACBM	MISC								
003E	12x12 Off White Floor Tile			Room 109	NO_ACBM	MISC								
006A	12x12 Dark Brown Floor Tile Mastic	14,430	SF	Lunchroom, Gym Office, Attendance Room, Auditorium Basement Hallway	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
006B	12x12 Tan Floor Tile Mastic	10,770	SF	139, Attendance Room, Locker Rooms, Gym Stairs, Balcony to Gym, Health Room, Drivers Ed Rm	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
006C	12x12 Olive Green Floor Tile Mastic	5,000	SF	Gym Balcony, Stairs, Elevators Lobbies	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
006D	12x12 Gray Floor Tile Mastic	700	SF	Basement Corridors	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
006E	12x12 Off White Floor Tile Mastic	800	SF	Room 109	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
013A	Brown Carpet Mastic			Hallway in Front of Office, Room 228, Auditorium and Band Room	NO_ACBM	MISC								
013B	Blue Carpet Mastic			Throughout Classrooms, Main Office, Rooms 214, 216, 138, 206, 208 and 210	NO_ACBM	MISC								
013C	Wine Carpet Mastic			Library	NO_ACBM	MISC								
013D	Green Carpet Mastic	1,070	SF	Teachers Lunch Room and Center Media Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
013H	9x9 Beige w/ Multi-Colored Streaks Floor Tile - NOT OBSERVED	260	SF	1st Floor Women's Washroom and	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

# Chicago Public Schools

School Carver Military Academy Unit 46381 Building ID 1850

Address 13100 S. Doty Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Corridor (West End)										
014	Spray on Insulation	800	SF	Entrance to Auditorium	ASSUMED	SURFACE	Y	NONE	0		No	ACBM with the potential for damage		LOW
015	12x12 Acoustical Ceiling Tile	5,500	SF	throughout Basement, 1st Floor Band Rooms	ASSUMED	MISC	Y	NONE	0		Yes	ACBM with the potential for damage		LOW
020	12" x 12" Brown with Tan/White Streaks Floor Tile & Adhesive	60,000	SF	Basement Hallway, 1st and 2nd Floor Hallways, Drill Hall, 1st Floor Meeting Room, Rooms 206, 208, 216, 218, 228, 109, 136, 138, main office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
021	12" x 12" White w/ White & Pink Speckles Floor Tile and Adhesive	1,000	SF	136	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
022	Insulation on Boiler Exhaust Pipes	100	LF	Boiler Room and Pool Mechanical Room	ASSUMED	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
023	Insulation on Hot Water Tank	200	SF	Pool Mechanical Room	ASSUMED	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
024	MJP E/F/V on Fiberglass Pipe Insulation	200	LF	Boiler Room, Loading Dock/Garage, Pool Mechanical Room	ASSUMED	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
025	Tan and Brown Streaked Linoleum & Adhesive	500	SF	134	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		Low
026	1 x 1 Ceiling Tile Splined	5,000	SF	Basement Hallway and Auditorium	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
027	Beige Terrazzo	10,000	SF	2nd Floor Landings, Rooms 1-10, and Stairs	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
028	Drywall	100,000	SF	Throughout School	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
100M	Adhesive for Brown with White Streaks Stair Treads	1,200	SF	Throughout	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
101	White Woven Insulation on Electrical Copper Wires	100	LF	Auditorium Stage Lights- in Place or Dismantled	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
102	12"x12" Floor Tile	500	SF	Attendance Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
102M	Adhesive for 12"x12" Floor Tile	500	SF	Attendance Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
103	Fireproof Insulation	1,000	SF	Ceiling of the	CHR	SURFACE	Y	DIST	30		No	Damaged friable	5	LOW

# Chicago Public Schools

School Carver Military Academy Unit 46381 Building ID 1850

Address 13100 S. Doty Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Auditorium								surfacing ACBM		
104	12 x 12 VFT Gray w/ Mixed Blue Specs	1,200	SF	Boys Locker Room, Girls Locker Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
104M	12 x 12 VFT Gray w/ Mixed Blue Specs Mastic	1,200	SF	Boys Locker Room, Girls Locker Room	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
105	12 x 12 VFT Green	4,500	SF	Activity Room, 2nd Floor West Gym Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
105M	12 x 12 VFT Green Mastic	4,500	SF	Activity Room, 2nd Floor West Gym Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
106	12 x 12 Black VFT w/ white	1,200	SF	Lunchroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
106M	12 x 12 Black VFT w/ White Specs Mastic	1,200	SF	Lunchroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

# Chicago Public Schools

School Carver Military Academy Unit 46381 Building ID 1850

Address 13100 S. Doty Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

*Inspector's Comments are Summarized at the End of the Report*

Reinspection Date <b>4/5/2016</b>
Inspector Name <b><u>Wayne Gardner</u></b>
<b>100-19039</b> <b>2/13/2017</b>
Inspector's IDPH License Number / Expiration Date

### Inspector's Comments

HA Number:	Inspector Comments:
003A	
003B	
003C	
003D	
003E	
006A	
006B	
006C	
006D	
006E	
013A	
013B	
013C	
013D	
013H	
014	
015	
020	
021	
022	
023	
024	
025	
026	



# Chicago Public Schools

School Carver Military Academy Unit 46381 Building ID 1850

Address 13100 S. Doty Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
027	
028	
100M	
101	
102	
102M	
103	
104	
104M	
105	
105M	
106	
106M	

**Table II**

**Management Planner's Review**

---

# Chicago Public Schools

School Carver Military Academy

Unit 46381

Building ID 1850

Address 13100 S. Doty

Chicago, IL, 60627

Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
003A	12x12 Dark Brown Floor Tile	14,430	SF	Lunchroom, Gym Office, Attendance Room, Auditorium Basement Hallway	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
003B	12x12 Tan Floor Tile			Attendance Room, Locker Rooms, Health Room, Drivers Ed Room	No ACBM	MISC					
003C	12x12 Olive Green Floor Tile	5,000	SF	Gym Balcony, Stairs, Elevators	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
003D	12x12 Gray Floor Tile Mastic			Basement Corridors	No ACBM	MISC					
003E	12x12 Off White Floor Tile			Room 109	No ACBM	MISC					
006A	12x12 Dark Brown Floor Tile Mastic	14,430	SF	Lunchroom, Gym Office, Attendance Room, Auditorium Basement Hallway	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
006B	12x12 Tan Floor Tile Mastic	10,770	SF	139, Attendance Room, Locker Rooms, Gym Stairs, Balcony to Gym, Health Room, Drivers Ed Rm	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
006C	12x12 Olive Green Floor Tile Mastic	5,000	SF	Gym Balcony, Stairs, Elevators Lobbies	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
006D	12x12 Gray Floor Tile Mastic	700	SF	Basement Corridors	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
006E	12x12 Off White Floor Tile Mastic	800	SF	Room 109	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
013A	Brown Carpet Mastic			Hallway in Front of Office, Room 228, Auditorium and Band Room	No ACBM	MISC					
013B	Blue Carpet Mastic			Throughout Classrooms, Main Office, Rooms 214, 216, 138, 206, 208 and 210	No ACBM	MISC					
013C	Wine Carpet Mastic			Library	No ACBM	MISC					
013D	Green Carpet Mastic	1,070	SF	Teachers Lunch Room and Center Media Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
013H	9x9 Beige w/ Multi-Colored Streaks Floor Tile - NOT OBSERVED	260	SF	1st Floor Women's Washroom and Corridor (West End)	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	
014	Spray on Insulation	800	SF	Entrance to Auditorium	Assumed	SURFACE	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
015	12x12 Acoustical Ceiling Tile	5,500	SF	throughout Basement, 1st Floor Band Rooms	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
020	12" x 12" Brown with Tan/White Streaks Floor Tile & Adhesive	60,000	SF	Basement Hallway, 1st and 2nd Floor Hallways, Drill Hall, 1st Floor Meeting Room, Rooms 206, 208, 216, 218, 228, 109, 136, 138, main office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
021	12" x 12" White w/ White & Pink Speckles Floor Tile and Adhesive	1,000	SF	136	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
022	Insulation on Boiler Exhaust Pipes	100	LF	Boiler Room and Pool Mechanical Room	Assumed	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

School Carver Military Academy

Unit 46381

Building ID 1850

Address 13100 S. Doty

Chicago, IL, 60627

Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
023	Insulation on Hot Water Tank	200	SF	Pool Mechanical Room	Assumed	TSI	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
024	MJP E/F/V on Fiberglass Pipe Insulation	200	LF	Boiler Room, Loading Dock/Garage, Pool Mechanical Room	Assumed	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
025	Tan and Brown Streaked Linoleum & Adhesive	500	SF	134	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
026	1 x 1 Ceiling Tile Splined	5,000	SF	Basement Hallway and Auditorium	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
027	Beige Terrazzo	10,000	SF	2nd Floor Landings, Rooms 1-10, and Stairs	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
028	Drywall	100,000	SF	Throughout School	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
100M	Adhesive for Brown with White Streaks Stair Treads	1,200	SF	Throughout	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
101	White Woven Insulation on Electrical Copper Wires	100	LF	Auditorium Stage Lights- in Place or Dismantled	Assumed	MISC	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
102	12"x12" Floor Tile	500	SF	Attendance Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
102M	Adhesive for 12"x12" Floor Tile	500	SF	Attendance Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
103	Fireproof Insulation	1,000	SF	Ceiling of the Auditorium	Chrysotile	SURFACE	Yes	30	SF	2 Damaged friable surfacing ACBM	Remove
104	12 x 12 VFT Gray w/ Mixed Blue Specs	1,200	SF	Boys Locker Room, Girls Locker Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
104M	12 x 12 VFT Gray w/ Mixed Blue Specs Mastic	1,200	SF	Boys Locker Room, Girls Locker Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
105	12 x 12 VFT Green	4,500	SF	Activity Room, 2nd Floor West Gym Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
105M	12 x 12 VFT Green Mastic	4,500	SF	Activity Room, 2nd Floor West Gym Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
106	12 x 12 Black VFT w/ white	1,200	SF	Lunchroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
106M	12 x 12 Black VFT w/ White Specs Mastic	1,200	SF	Lunchroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Carver Military Academy

**Unit** 46381

**Building ID** 1850

**Address** 13100 S. Doty

Chicago, IL, 60627

**Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

*Management Planner's Comments Summarized at the End of the Report*

Review Date	5/16/2016
Manager Planner Name	Guillermo Garcia
100-01786	3/21/2017
Manager IDPH License No/Expiration	

HA Number	Management Comments
003A	
003B	
003C	
003D	
003E	
006A	
006B	
006C	
006D	
006E	
013A	
013B	
013C	
013D	
013H	
014	

# Chicago Public Schools

**School** Carver Military Academy  
**Address** 13100 S. Doty

**Unit** 46381  
 Chicago, IL, 60627

**Building ID** 1850  
**Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
015	
020	
021	
022	
023	
024	
025	
026	
027	
028	
100M	
101	
102	
102M	
103	
104	
104M	
105	
105M	
106	
106M	

# Chicago Public Schools

GSG Consultants, Inc.

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46381** BUIDLING ID: **1850**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**  
SCHOOL NAME: **Carver Military Academy** INSPECTION DATE: **4/5/2016**  
ADDRESS: **13100 S. Doty** IDPH LICENSE NO: **100-19039**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **003A**  
MATERIAL DESCRIPTION: **12x12 Dark Brown Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Lunchroom, Gym Office, Attendance Room, Auditorium Basement Hallway**  
MATERIAL QUANTITY: **14430** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature:



Date: **04/05/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46381** BUILDING ID: **1850**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Carver Military Academy** REVIEW DATE: **5/16/2016**  
ADDRESS: **13100 S. Doty** IDPH LICENSE NO: **100-19039**

---

HOMOGENEOUS AREA: **003A**  
MATERIAL DESCRIPTION: **12x12 Dark Brown Floor Tile**  
MATERIAL LOCATION: **Lunchroom, Gym Office, Attendance Room, Auditorium Basement Hallway**  
MATERIAL QUANTITY: **14430** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/16/2016**



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46381** BUIDLING ID: **1850**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**  
SCHOOL NAME: **Carver Military Academy** INSPECTION DATE: **4/5/2016**  
ADDRESS: **13100 S. Doty** IDPH LICENSE NO: **100-19039**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **003B**  
MATERIAL DESCRIPTION: **12x12 Tan Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Attendance Room, Locker Rooms, Health Room, Drivers Ed Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/05/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46381** BUILDING ID: **1850**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Carver Military Academy** REVIEW DATE: **5/16/2016**  
ADDRESS: **13100 S. Doty** IDPH LICENSE NO: **100-19039**

---

HOMOGENEOUS AREA: **003B**  
MATERIAL DESCRIPTION: **12x12 Tan Floor Tile**  
MATERIAL LOCATION: **Attendance Room, Locker Rooms, Health Room, Drivers Ed Room**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/16/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46381** BUIDLING ID: **1850**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**  
SCHOOL NAME: **Carver Military Academy** INSPECTION DATE: **4/5/2016**  
ADDRESS: **13100 S. Doty** IDPH LICENSE NO: **100-19039**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **003C**  
MATERIAL DESCRIPTION: **12x12 Olive Green Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Gym Balcony, Stairs, Elevators**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/05/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46381** BUIDLING ID: **1850**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Carver Military Academy** REVIEW DATE: **5/16/2016**  
ADDRESS: **13100 S. Doty** IDPH LICENSE NO: **100-19039**

---

HOMOGENEOUS AREA: **003C**  
MATERIAL DESCRIPTION: **12x12 Olive Green Floor Tile**  
MATERIAL LOCATION: **Gym Balcony, Stairs, Elevators**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/16/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46381** BUIDLING ID: **1850**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**  
SCHOOL NAME: **Carver Military Academy** INSPECTION DATE: **4/5/2016**  
ADDRESS: **13100 S. Doty** IDPH LICENSE NO: **100-19039**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **003D**  
MATERIAL DESCRIPTION: **12x12 Gray Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Basement Corridors**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/05/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46381** BUIDLING ID: **1850**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Carver Military Academy** REVIEW DATE: **5/16/2016**  
ADDRESS: **13100 S. Doty** IDPH LICENSE NO: **100-19039**

---

HOMOGENEOUS AREA: **003D**  
MATERIAL DESCRIPTION: **12x12 Gray Floor Tile Mastic**  
MATERIAL LOCATION: **Basement Corridors**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/16/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46381** BUIDLING ID: **1850**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**  
SCHOOL NAME: **Carver Military Academy** INSPECTION DATE: **4/5/2016**  
ADDRESS: **13100 S. Doty** IDPH LICENSE NO: **100-19039**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **003E**  
MATERIAL DESCRIPTION: **12x12 Off White Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 109**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/05/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46381** BUILDING ID: **1850**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Carver Military Academy** REVIEW DATE: **5/16/2016**  
ADDRESS: **13100 S. Doty** IDPH LICENSE NO: **100-19039**

---

HOMOGENEOUS AREA: **003E**  
MATERIAL DESCRIPTION: **12x12 Off White Floor Tile**  
MATERIAL LOCATION: **Room 109**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/16/2016**



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46381** BUIDLING ID: **1850**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**  
SCHOOL NAME: **Carver Military Academy** INSPECTION DATE: **4/5/2016**  
ADDRESS: **13100 S. Doty** IDPH LICENSE NO: **100-19039**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **006A**  
MATERIAL DESCRIPTION: **12x12 Dark Brown Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Lunchroom, Gym Office, Attendance Room, Auditorium Basement Hallway**  
MATERIAL QUANTITY: **14430** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/05/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46381** BUILDING ID: **1850**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Carver Military Academy** REVIEW DATE: **5/16/2016**  
ADDRESS: **13100 S. Doty** IDPH LICENSE NO: **100-19039**

---

HOMOGENEOUS AREA: **006A**  
MATERIAL DESCRIPTION: **12x12 Dark Brown Floor Tile Mastic**  
MATERIAL LOCATION: **Lunchroom, Gym Office, Attendance Room, Auditorium Basement Hallway**  
MATERIAL QUANTITY: **14430** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/16/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46381** BUIDLING ID: **1850**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**  
SCHOOL NAME: **Carver Military Academy** INSPECTION DATE: **4/5/2016**  
ADDRESS: **13100 S. Doty** IDPH LICENSE NO: **100-19039**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **006B**  
MATERIAL DESCRIPTION: **12x12 Tan FloorTile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **139, Attendance Room, Locker Rooms, Gym Stairs, Balcony to Gym, Health Room, Drivers Ed Rm**

MATERIAL QUANTITY: **10770**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/05/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46381** BUIDLING ID: **1850**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Carver Military Academy** REVIEW DATE: **5/16/2016**  
ADDRESS: **13100 S. Doty** IDPH LICENSE NO: **100-19039**

---

HOMOGENEOUS AREA: **006B**  
MATERIAL DESCRIPTION: **12x12 Tan FloorTile Mastic**  
MATERIAL LOCATION: **139, Attendance Room, Locker Rooms, Gym Stairs, Balcony to Gym, Health Room, Drivers Ed Rm**  
MATERIAL QUANTITY: **10770** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/16/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46381** BUIDLING ID: **1850**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**  
SCHOOL NAME: **Carver Military Academy** INSPECTION DATE: **4/5/2016**  
ADDRESS: **13100 S. Doty** IDPH LICENSE NO: **100-19039**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **006C**  
MATERIAL DESCRIPTION: **12x12 Olive Green Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Gym Balcony, Stairs, Elevators Lobbies**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/05/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46381** BUILDING ID: **1850**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Carver Military Academy** REVIEW DATE: **5/16/2016**  
ADDRESS: **13100 S. Doty** IDPH LICENSE NO: **100-19039**

---

HOMOGENEOUS AREA: **006C**  
MATERIAL DESCRIPTION: **12x12 Olive Green Floor Tile Mastic**  
MATERIAL LOCATION: **Gym Balcony, Stairs, Elevators Lobbies**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/16/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46381** BUIDLING ID: **1850**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**  
SCHOOL NAME: **Carver Military Academy** INSPECTION DATE: **4/5/2016**  
ADDRESS: **13100 S. Doty** IDPH LICENSE NO: **100-19039**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **006D**  
MATERIAL DESCRIPTION: **12x12 Gray Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Basement Corridors**  
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/05/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46381** BUILDING ID: **1850**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Carver Military Academy** REVIEW DATE: **5/16/2016**  
ADDRESS: **13100 S. Doty** IDPH LICENSE NO: **100-19039**

---

HOMOGENEOUS AREA: **006D**  
MATERIAL DESCRIPTION: **12x12 Gray Floor Tile Mastic**  
MATERIAL LOCATION: **Basement Corridors**  
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/16/2016**



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46381** BUIDLING ID: **1850**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**  
SCHOOL NAME: **Carver Military Academy** INSPECTION DATE: **4/5/2016**  
ADDRESS: **13100 S. Doty** IDPH LICENSE NO: **100-19039**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **006E**  
MATERIAL DESCRIPTION: **12x12 Off White Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 109**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/05/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46381** BUIDLING ID: **1850**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Carver Military Academy** REVIEW DATE: **5/16/2016**  
ADDRESS: **13100 S. Doty** IDPH LICENSE NO: **100-19039**

---

HOMOGENEOUS AREA: **006E**  
MATERIAL DESCRIPTION: **12x12 Off White Floor Tile Mastic**  
MATERIAL LOCATION: **Room 109**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/16/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46381** BUIDLING ID: **1850**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**  
SCHOOL NAME: **Carver Military Academy** INSPECTION DATE: **4/5/2016**  
ADDRESS: **13100 S. Doty** IDPH LICENSE NO: **100-19039**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **013A**  
MATERIAL DESCRIPTION: **Brown Carpet Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Hallway in Front of Office, Room 228, Auditorium and Band Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/05/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46381** BUIDLING ID: **1850**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Carver Military Academy** REVIEW DATE: **5/16/2016**  
ADDRESS: **13100 S. Doty** IDPH LICENSE NO: **100-19039**

---

HOMOGENEOUS AREA: **013A**  
MATERIAL DESCRIPTION: **Brown Carpet Mastic**  
MATERIAL LOCATION: **Hallway in Front of Office, Room 228, Auditorium and Band Room**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/16/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46381** BUIDLING ID: **1850**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**  
SCHOOL NAME: **Carver Military Academy** INSPECTION DATE: **4/5/2016**  
ADDRESS: **13100 S. Doty** IDPH LICENSE NO: **100-19039**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **013B**  
MATERIAL DESCRIPTION: **Blue Carpet Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Classrooms, Main Office, Rooms 214, 216, 138, 206, 208 and 210**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/05/2016**

---

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46381** BUIDLING ID: **1850**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Carver Military Academy** REVIEW DATE: **5/16/2016**  
ADDRESS: **13100 S. Doty** IDPH LICENSE NO: **100-19039**

---

HOMOGENEOUS AREA: **013B**  
MATERIAL DESCRIPTION: **Blue Carpet Mastic**  
MATERIAL LOCATION: **Throughout Classrooms, Main Office, Rooms 214, 216, 138, 206, 208 and 210**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/16/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46381** BUIDLING ID: **1850**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**  
SCHOOL NAME: **Carver Military Academy** INSPECTION DATE: **4/5/2016**  
ADDRESS: **13100 S. Doty** IDPH LICENSE NO: **100-19039**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **013C**  
MATERIAL DESCRIPTION: **Wine Carpet Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Library**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/05/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46381** BUILDING ID: **1850**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Carver Military Academy** REVIEW DATE: **5/16/2016**  
ADDRESS: **13100 S. Doty** IDPH LICENSE NO: **100-19039**

---

HOMOGENEOUS AREA: **013C**  
MATERIAL DESCRIPTION: **Wine Carpet Mastic**  
MATERIAL LOCATION: **Library**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/16/2016**



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46381** BUIDLING ID: **1850**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**  
SCHOOL NAME: **Carver Military Academy** INSPECTION DATE: **4/5/2016**  
ADDRESS: **13100 S. Doty** IDPH LICENSE NO: **100-19039**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **013D**  
MATERIAL DESCRIPTION: **Green Carpet Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Teachers Lunch Room and Center Media Room**  
MATERIAL QUANTITY: **1070** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/05/2016**

# Chicago Public Schools

GSG Consultants, Inc.

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46381** BUILDING ID: **1850**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Carver Military Academy** REVIEW DATE: **5/16/2016**  
ADDRESS: **13100 S. Doty** IDPH LICENSE NO: **100-19039**

---

HOMOGENEOUS AREA: **013D**  
MATERIAL DESCRIPTION: **Green Carpet Mastic**  
MATERIAL LOCATION: **Teachers Lunch Room and Center Media Room**  
MATERIAL QUANTITY: **1070** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/16/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46381** BUILDING ID: **1850**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**  
SCHOOL NAME: **Carver Military Academy** INSPECTION DATE: **4/5/2016**  
ADDRESS: **13100 S. Doty** IDPH LICENSE NO: **100-19039**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **013H**  
MATERIAL DESCRIPTION: **9x9 Beige w/ Multi-Colored Streaks Floor Tile - NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st Floor Women's Washroom and Corridor (West End)**  
MATERIAL QUANTITY: **260** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/05/2016**

# Chicago Public Schools

GSG Consultants, Inc.

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46381** BUIDLING ID: **1850**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Carver Military Academy** REVIEW DATE: **5/16/2016**  
ADDRESS: **13100 S. Doty** IDPH LICENSE NO: **100-19039**

---

HOMOGENEOUS AREA: **013H**  
MATERIAL DESCRIPTION: **9x9 Beige w/ Multi-Colored Streaks Floor Tile - NOT OBSERVED**  
MATERIAL LOCATION: **1st Floor Women's Washroom and Corridor (West End)**  
MATERIAL QUANTITY: **260** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/16/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46381** BUIDLING ID: **1850**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**  
SCHOOL NAME: **Carver Military Academy** INSPECTION DATE: **4/5/2016**  
ADDRESS: **13100 S. Doty** IDPH LICENSE NO: **100-19039**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **014**  
MATERIAL DESCRIPTION: **Spray on Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Entrance to Auditorium**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/05/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46381** BUILDING ID: **1850**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Carver Military Academy** REVIEW DATE: **5/16/2016**  
ADDRESS: **13100 S. Doty** IDPH LICENSE NO: **100-19039**

---

HOMOGENEOUS AREA: **014**  
MATERIAL DESCRIPTION: **Spray on Insulation**  
MATERIAL LOCATION: **Entrance to Auditorium**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/16/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46381** BUIDLING ID: **1850**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**  
SCHOOL NAME: **Carver Military Academy** INSPECTION DATE: **4/5/2016**  
ADDRESS: **13100 S. Doty** IDPH LICENSE NO: **100-19039**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **015**  
MATERIAL DESCRIPTION: **12x12 Acoustical Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **throughout Basement, 1st fFoor Band Rooms**  
MATERIAL QUANTITY: **5500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/05/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46381** BUILDING ID: **1850**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Carver Military Academy** REVIEW DATE: **5/16/2016**  
ADDRESS: **13100 S. Doty** IDPH LICENSE NO: **100-19039**

---

HOMOGENEOUS AREA: **015**  
MATERIAL DESCRIPTION: **12x12 Acoustical Ceiling Tile**  
MATERIAL LOCATION: **throughout Basement, 1st fFloor Band Rooms**  
MATERIAL QUANTITY: **5500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/16/2016**



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 46381 BUIDLING ID: 1850  
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Wayne Gardner  
SCHOOL NAME: Carver Military Academy INSPECTION DATE: 4/5/2016  
ADDRESS: 13100 S. Doty IDPH LICENSE NO: 100-19039

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 020  
MATERIAL DESCRIPTION: 12" x 12" Brown with Tan/White Streaks Floor Tile & Adhesive  
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Basement Hallway, 1st and 2nd Floor Hallways, Drill Hall, 1st Floor Meeting Room, Rooms 206, 208, 216, 218, 228, 109, 136, 138, main office**

MATERIAL QUANTITY: **60000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: 04/05/2016

# Chicago Public Schools

GSG Consultants, Inc.

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46381** BUILDING ID: **1850**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Carver Military Academy** REVIEW DATE: **5/16/2016**  
ADDRESS: **13100 S. Doty** IDPH LICENSE NO: **100-19039**

---

HOMOGENEOUS AREA: **020**  
MATERIAL DESCRIPTION: **12" x 12" Brown with Tan/White Streaks Floor Tile & Adhesive**  
MATERIAL LOCATION: **Basement Hallway, 1st and 2nd Floor Hallways, Drill Hall, 1st Floor Meeting Room, Rooms 206, 208, 216, 218, 228, 109, 136, 138, main office**  
MATERIAL QUANTITY: **60000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/16/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46381** BUIDLING ID: **1850**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**  
SCHOOL NAME: **Carver Military Academy** INSPECTION DATE: **4/5/2016**  
ADDRESS: **13100 S. Doty** IDPH LICENSE NO: **100-19039**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **021**  
MATERIAL DESCRIPTION: **12" x 12" White w/ White & Pink Speckles Floor Tile and Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **136**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/05/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46381** BUIDLING ID: **1850**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Carver Military Academy** REVIEW DATE: **5/16/2016**  
ADDRESS: **13100 S. Doty** IDPH LICENSE NO: **100-19039**

---

HOMOGENEOUS AREA: **021**  
MATERIAL DESCRIPTION: **12" x 12" White w/ White & Pink Speckles Floor Tile and Adhesive**  
MATERIAL LOCATION: **136**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/16/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46381** BUIDLING ID: **1850**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**  
SCHOOL NAME: **Carver Military Academy** INSPECTION DATE: **4/5/2016**  
ADDRESS: **13100 S. Doty** IDPH LICENSE NO: **100-19039**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **022**  
MATERIAL DESCRIPTION: **Insulation on Boiler Exhaust Pipes**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Boiler Room and Pool Mechanical Room**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 04/05/2016

# Chicago Public Schools

GSG Consultants, Inc.

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46381** BUIDLING ID: **1850**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Carver Military Academy** REVIEW DATE: **5/16/2016**  
ADDRESS: **13100 S. Doty** IDPH LICENSE NO: **100-19039**

---

HOMOGENEOUS AREA: **022**  
MATERIAL DESCRIPTION: **Insulation on Boiler Exhaust Pipes**  
MATERIAL LOCATION: **Boiler Room and Pool Mechanical Room**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/16/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46381** BUIDLING ID: **1850**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**  
SCHOOL NAME: **Carver Military Academy** INSPECTION DATE: **4/5/2016**  
ADDRESS: **13100 S. Doty** IDPH LICENSE NO: **100-19039**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **023**  
MATERIAL DESCRIPTION: **Insulation on Hot Water Tank**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Pool Mechanical Room**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/05/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46381** BUILDING ID: **1850**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Carver Military Academy** REVIEW DATE: **5/16/2016**  
ADDRESS: **13100 S. Doty** IDPH LICENSE NO: **100-19039**

---

HOMOGENEOUS AREA: **023**  
MATERIAL DESCRIPTION: **Insulation on Hot Water Tank**  
MATERIAL LOCATION: **Pool Mechanical Room**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/16/2016**



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46381** BUIDLING ID: **1850**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**  
SCHOOL NAME: **Carver Military Academy** INSPECTION DATE: **4/5/2016**  
ADDRESS: **13100 S. Doty** IDPH LICENSE NO: **100-19039**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **024**  
MATERIAL DESCRIPTION: **MJP E/F/V on Fiberglass Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Boiler Room, Loading Dock/Garage, Pool Mechanical Room**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **04/05/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46381** BUIDLING ID: **1850**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Carver Military Academy** REVIEW DATE: **5/16/2016**  
ADDRESS: **13100 S. Doty** IDPH LICENSE NO: **100-19039**

---

HOMOGENEOUS AREA: **024**  
MATERIAL DESCRIPTION: **MJP E/F/V on Fiberglass Pipe Insulation**  
MATERIAL LOCATION: **Boiler Room, Loading Dock/Garage, Pool Mechanical Room**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/16/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46381** BUIDLING ID: **1850**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**  
SCHOOL NAME: **Carver Military Academy** INSPECTION DATE: **4/5/2016**  
ADDRESS: **13100 S. Doty** IDPH LICENSE NO: **100-19039**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **025**  
MATERIAL DESCRIPTION: **Tan and Brown Streaked Linoleum & Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**  
MATERIAL LOCATION: **134**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/05/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46381** BUIDLING ID: **1850**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Carver Military Academy** REVIEW DATE: **5/16/2016**  
ADDRESS: **13100 S. Doty** IDPH LICENSE NO: **100-19039**

---

HOMOGENEOUS AREA: **025**  
MATERIAL DESCRIPTION: **Tan and Brown Streaked Linoleum & Adhesive**  
MATERIAL LOCATION: **134**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/16/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46381** BUIDLING ID: **1850**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**  
SCHOOL NAME: **Carver Military Academy** INSPECTION DATE: **4/5/2016**  
ADDRESS: **13100 S. Doty** IDPH LICENSE NO: **100-19039**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **026**  
MATERIAL DESCRIPTION: **1 x 1 Ceiling Tile Splined**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Basement Hallway and Auditorium**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/05/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46381** BUIDLING ID: **1850**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Carver Military Academy** REVIEW DATE: **5/16/2016**  
ADDRESS: **13100 S. Doty** IDPH LICENSE NO: **100-19039**

---

HOMOGENEOUS AREA: **026**  
MATERIAL DESCRIPTION: **1 x 1 Ceiling Tile Splined**  
MATERIAL LOCATION: **Basement Hallway and Auditorium**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/16/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46381** BUIDLING ID: **1850**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**  
SCHOOL NAME: **Carver Military Academy** INSPECTION DATE: **4/5/2016**  
ADDRESS: **13100 S. Doty** IDPH LICENSE NO: **100-19039**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **027**  
MATERIAL DESCRIPTION: **Beige Terrazzo**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **2nd Floor Landings, Rooms 1-10, and Stairs**  
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 04/05/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46381** BUIDLING ID: **1850**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Carver Military Academy** REVIEW DATE: **5/16/2016**  
ADDRESS: **13100 S. Doty** IDPH LICENSE NO: **100-19039**

---

HOMOGENEOUS AREA: **027**  
MATERIAL DESCRIPTION: **Beige Terrazzo**  
MATERIAL LOCATION: **2nd Floor Landings, Rooms 1-10, and Stairs**  
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/16/2016**



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46381** BUIDLING ID: **1850**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**  
SCHOOL NAME: **Carver Military Academy** INSPECTION DATE: **4/5/2016**  
ADDRESS: **13100 S. Doty** IDPH LICENSE NO: **100-19039**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **028**  
MATERIAL DESCRIPTION: **Drywall**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout School**  
MATERIAL QUANTITY: **100000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/05/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46381** BUIDLING ID: **1850**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Carver Military Academy** REVIEW DATE: **5/16/2016**  
ADDRESS: **13100 S. Doty** IDPH LICENSE NO: **100-19039**

---

HOMOGENEOUS AREA: **028**  
MATERIAL DESCRIPTION: **Drywall**  
MATERIAL LOCATION: **Throughout School**  
MATERIAL QUANTITY: **100000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/16/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46381** BUILDING ID: **1850**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**  
SCHOOL NAME: **Carver Military Academy** INSPECTION DATE: **4/5/2016**  
ADDRESS: **13100 S. Doty** IDPH LICENSE NO: **100-19039**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **100M**  
MATERIAL DESCRIPTION: **Adhesive for Brown with White Streaks Stair Treads**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/05/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46381** BUIDLING ID: **1850**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Carver Military Academy** REVIEW DATE: **5/16/2016**  
ADDRESS: **13100 S. Doty** IDPH LICENSE NO: **100-19039**

---

HOMOGENEOUS AREA: **100M**  
MATERIAL DESCRIPTION: **Adhesive for Brown with White Streaks Stair Treads**  
MATERIAL LOCATION: **Throughout**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/16/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46381** BUIDLING ID: **1850**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**  
SCHOOL NAME: **Carver Military Academy** INSPECTION DATE: **4/5/2016**  
ADDRESS: **13100 S. Doty** IDPH LICENSE NO: **100-19039**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **101**  
MATERIAL DESCRIPTION: **White Woven Insulation on Electrical Copper Wires**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Auditorium StageLights- in Place or Dismantled**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **04/05/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46381** BUIDLING ID: **1850**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Carver Military Academy** REVIEW DATE: **5/16/2016**  
ADDRESS: **13100 S. Doty** IDPH LICENSE NO: **100-19039**

---

HOMOGENEOUS AREA: **101**  
MATERIAL DESCRIPTION: **White Woven Insulation on Electrical Copper Wires**  
MATERIAL LOCATION: **Auditorium StageLights- in Place or Dismantled**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/16/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46381** BUIDLING ID: **1850**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**  
SCHOOL NAME: **Carver Military Academy** INSPECTION DATE: **4/5/2016**  
ADDRESS: **13100 S. Doty** IDPH LICENSE NO: **100-19039**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **102**  
MATERIAL DESCRIPTION: **12"x12" Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Attendance Office**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/05/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46381** BUIDLING ID: **1850**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Carver Military Academy** REVIEW DATE: **5/16/2016**  
ADDRESS: **13100 S. Doty** IDPH LICENSE NO: **100-19039**

---

HOMOGENEOUS AREA: **102**  
MATERIAL DESCRIPTION: **12"x12" Floor Tile**  
MATERIAL LOCATION: **Attendance Office**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/16/2016**



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46381** BUIDLING ID: **1850**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**  
SCHOOL NAME: **Carver Military Academy** INSPECTION DATE: **4/5/2016**  
ADDRESS: **13100 S. Doty** IDPH LICENSE NO: **100-19039**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **102M**  
MATERIAL DESCRIPTION: **Adhesive for 12"x12" Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Attendance Office**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/05/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46381** BUIDLING ID: **1850**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Carver Military Academy** REVIEW DATE: **5/16/2016**  
ADDRESS: **13100 S. Doty** IDPH LICENSE NO: **100-19039**

---

HOMOGENEOUS AREA: **102M**  
MATERIAL DESCRIPTION: **Adhesive for 12"x12" Floor Tile**  
MATERIAL LOCATION: **Attendance Office**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/16/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46381** BUIDLING ID: **1850**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**  
SCHOOL NAME: **Carver Military Academy** INSPECTION DATE: **4/5/2016**  
ADDRESS: **13100 S. Doty** IDPH LICENSE NO: **100-19039**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **103**  
MATERIAL DESCRIPTION: **Fireproof Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **2 Damaged friable surfacing ACBM**  
HISTORICAL DAMAGE REASON: **Physical Damage**  
HISTORICAL RESPONSE ACTION: **Repair**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **2. Damaged friable surfacing ACBM**

DAMAGE REASON: **Physical Damage**  
DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Ceiling of the Auditorium**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: **04/05/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46381** BUILDING ID: **1850**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Carver Military Academy** REVIEW DATE: **5/16/2016**  
ADDRESS: **13100 S. Doty** IDPH LICENSE NO: **100-19039**

---

HOMOGENEOUS AREA: **103**  
MATERIAL DESCRIPTION: **Fireproof Insulation**  
MATERIAL LOCATION: **Ceiling of the Auditorium**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **30** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/16/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46381** BUIDLING ID: **1850**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**  
SCHOOL NAME: **Carver Military Academy** INSPECTION DATE: **4/5/2016**  
ADDRESS: **13100 S. Doty** IDPH LICENSE NO: **100-19039**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **104**  
MATERIAL DESCRIPTION: **12 x 12 VFT Gray w/ Mixed Blue Specs**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Boys Locker Room, Girls Locker Room**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/05/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46381** BUIDLING ID: **1850**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Carver Military Academy** REVIEW DATE: **5/16/2016**  
ADDRESS: **13100 S. Doty** IDPH LICENSE NO: **100-19039**

---

HOMOGENEOUS AREA: **104**  
MATERIAL DESCRIPTION: **12 x 12 VFT Gray w/ Mixed Blue Specs**  
MATERIAL LOCATION: **Boys Locker Room, Girls Locker Room**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/16/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46381** BUILDING ID: **1850**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**  
SCHOOL NAME: **Carver Military Academy** INSPECTION DATE: **4/5/2016**  
ADDRESS: **13100 S. Doty** IDPH LICENSE NO: **100-19039**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **104M**  
MATERIAL DESCRIPTION: **12 x 12 VFT Gray w/ Mixed Blue Specs Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Boys Locker Room, Girls Locker Room**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/05/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46381** BUIDLING ID: **1850**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Carver Military Academy** REVIEW DATE: **5/16/2016**  
ADDRESS: **13100 S. Doty** IDPH LICENSE NO: **100-19039**

---

HOMOGENEOUS AREA: **104M**  
MATERIAL DESCRIPTION: **12 x 12 VFT Gray w/ Mixed Blue Specs Mastic**  
MATERIAL LOCATION: **Boys Locker Room, Girls Locker Room**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/16/2016**



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46381** BUIDLING ID: **1850**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**  
SCHOOL NAME: **Carver Military Academy** INSPECTION DATE: **4/5/2016**  
ADDRESS: **13100 S. Doty** IDPH LICENSE NO: **100-19039**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **105**  
MATERIAL DESCRIPTION: **12 x 12 VFT Green**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Activity Room, 2nd Floor West Gym Corridor**  
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/05/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46381** BUIDLING ID: **1850**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Carver Military Academy** REVIEW DATE: **5/16/2016**  
ADDRESS: **13100 S. Doty** IDPH LICENSE NO: **100-19039**

---

HOMOGENEOUS AREA: **105**  
MATERIAL DESCRIPTION: **12 x 12 VFT Green**  
MATERIAL LOCATION: **Activity Room, 2nd Floor West Gym Corridor**  
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/16/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46381** BUIDLING ID: **1850**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**  
SCHOOL NAME: **Carver Military Academy** INSPECTION DATE: **4/5/2016**  
ADDRESS: **13100 S. Doty** IDPH LICENSE NO: **100-19039**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **105M**  
MATERIAL DESCRIPTION: **12 x 12 VFT Green Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Activity Room, 2nd Floor West Gym Corridor**  
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/05/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46381** BUIDLING ID: **1850**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Carver Military Academy** REVIEW DATE: **5/16/2016**  
ADDRESS: **13100 S. Doty** IDPH LICENSE NO: **100-19039**

---

HOMOGENEOUS AREA: **105M**  
MATERIAL DESCRIPTION: **12 x 12 VFT Green Mastic**  
MATERIAL LOCATION: **Activity Room, 2nd Floor West Gym Corridor**  
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/16/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46381** BUIDLING ID: **1850**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**  
SCHOOL NAME: **Carver Military Academy** INSPECTION DATE: **4/5/2016**  
ADDRESS: **13100 S. Doty** IDPH LICENSE NO: **100-19039**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **106**  
MATERIAL DESCRIPTION: **12 x 12 Black VFT w/ white**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Lunchroom**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/05/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46381** BUIDLING ID: **1850**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Carver Military Academy** REVIEW DATE: **5/16/2016**  
ADDRESS: **13100 S. Doty** IDPH LICENSE NO: **100-19039**

---

HOMOGENEOUS AREA: **106**  
MATERIAL DESCRIPTION: **12 x 12 Black VFT w/ white**  
MATERIAL LOCATION: **Lunchroom**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/16/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46381** BUIDLING ID: **1850**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**  
SCHOOL NAME: **Carver Military Academy** INSPECTION DATE: **4/5/2016**  
ADDRESS: **13100 S. Doty** IDPH LICENSE NO: **100-19039**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **106M**  
MATERIAL DESCRIPTION: **12 x 12 Black VFT w/ White Specs Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Lunchroom**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/05/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46381** BUIDLING ID: **1850**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Carver Military Academy** REVIEW DATE: **5/16/2016**  
ADDRESS: **13100 S. Doty** IDPH LICENSE NO: **100-19039**

---

HOMOGENEOUS AREA: **106M**  
MATERIAL DESCRIPTION: **12 x 12 Black VFT w/ White Specs Mastic**  
MATERIAL LOCATION: **Lunchroom**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/16/2016**



# Chicago Public Schools

GSG Consultants, Inc.  
*2016 AHERA REINSPECTION*

# APPENDIX B

## Inspector and Management Planner Licenses

---



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • www.dph.illinois.gov

4/20/2016

**DELORES FITZPATRICK**  
855 WEST ADAMS, SUITE 200  
CHICAGO, IL 60607

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 05183

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

**COPY OF THE ASBESTOS PROFESSIONAL LICENSE**

Front of License

Back of License

		<b>ASBESTOS PROFESSIONAL LICENSE</b>		<b>ENDORSEMENTS</b>	<b>TC EXPIRES</b>
<b>ID NUMBER</b> ID - 05183	<b>ISSUED</b> 4/20/2016	<b>EXPIRES</b> 05/15/2017		INSPECTOR	2/13/2017
<b>DELORES FITZPATRICK</b> 855 WEST ADAMS, SUITE 200 CHICAGO, IL 60607 Environmental Health				PROJECT MANAGER AIR SAMPLING PROFESSIONAL	2/6/2017
				<b>Alteration of this license shall result in legal action</b> This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: [dph.illinois.gov/topics-services/environmental-health-protection/asbestos](http://dph.illinois.gov/topics-services/environmental-health-protection/asbestos)  
EMAIL Address: [dph.asbestos@illinois.gov](mailto:dph.asbestos@illinois.gov)

**PROTECTING HEALTH, IMPROVING LIVES**  
*Nationally Accredited by PHA/E*

# CERTIFICATE OF ACHIEVEMENT ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that WAYNE GARDNER  
has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the  
examination on 02/13/2016 with a minimum score of 70% or better. Training was in accordance  
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:  
Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.

02/13/2016

Course Dates:

02/13/2017

Expires:

1602BIR14

Certificate Number:



*N. Penneff*

Director of Training  
Nicholas J. Penneff  
Doctor of Public Health

Phone: 312-491-0081

FORM # A-010B

# CERTIFICATE OF ACHIEVEMENT ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that GUILLERMO GARCIA  
has completed the Asbestos Management Planner Refresher course and passed the examination  
on 03/21/2016 with a minimum score of 70% or better. Training was in accordance with U.S.  
E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools: Model  
Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.

03/21/2016

Course Dates:

03/21/2017

Expires:

1603MPR02

Certificate Number:



**PUBLIC HEALTH & SAFETY inc.**

Environmental and Occupational Services  
105 S. Ashland Ave., Chicago, IL 60607

*Nicholas J. Penoff*

Director of Training

Nicholas J. Penoff

Doctor of Public Health

Phone: 312-491-0081

FORM # A-011



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • [www.dph.illinois.gov](http://www.dph.illinois.gov)

4/20/2016

**GUILLERMO GARCIA**  
 855 W ADAMS ST SUITE 100  
 CHICAGO, IL 60607

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 01786

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

**COPY OF THE ASBESTOS PROFESSIONAL LICENSE**

Front of License

Back of License

Front of License			Back of License	
 <p><b>ASBESTOS PROFESSIONAL LICENSE</b></p>			<p><b>ENDORSEMENTS</b></p>	
<p>ID NUMBER 100 - 01733</p>	<p>ISSUED 4/20/2016</p>	<p>EXPIRES 05/15/2017</p>	<p>INSPECTOR</p>	<p>TC EXPIRES 3/21/2017</p>
<p><b>GUILLERMO GARCIA</b>            855 W ADAMS ST SUITE 100            CHICAGO, IL 60607            Environmental Health</p>			<p>MANAGEMENT PLANNER</p>	<p>3/21/2017</p>
			<p>PROJECT MANAGER</p>	<p>2/6/2017</p>
			<p>AIR SAMPLING PROFESSIONAL</p>	
			<p><b>Alteration of this license shall result in legal action</b>            This license issued under authority of the State of Illinois            Department of Public Health            This license is valid only when accompanied by a valid            training course certificate.</p>	

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: [dph.illinois.gov/topics-services/environmental-health-protection/asbestos](http://dph.illinois.gov/topics-services/environmental-health-protection/asbestos)  
 EMAIL Address: [dph.asbestos@illinois.gov](mailto:dph.asbestos@illinois.gov)

**PROTECTING HEALTH, IMPROVING LIVES**  
*Nationally Accredited by PHAB*

# APPENDIX C

## Laboratory Accreditations

---

# APPENDIX D

## Laboratory Results

---



# APPENDIX E

## Chain of Custody Forms

---

## Three-Year Reinspection Key to Terms

	<b>CODE</b>	<b>KEY</b>
<b>MATERIAL</b>		
	ACBM	Asbestos Containing Building Materials
<b>MATERIAL CATEGORY</b>		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
<b>MATERIAL UNITS</b>		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
<b>DAMAGE TYPE</b>		
	Loc	Localized
	Dist	Distributed