

ILLINOIS DEPARTMENT OF PUBLIC HEALTH  
AHERA THREE YEAR REINSPECTION  
ASBESTOS ABATEMENT PROGRAM  
SCHOOL INFORMATION FORM

**SECTION I**

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299  
SCHOOL ID NUMBER: 14-016-2990-0037  
SCHOOL NAME: Senn Academy  
ADDRESS OF SCHOOL: 5900 N. Glenwood  
CITY: Chicago, IL, 60660

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **4/4/2013**

**If the address on this form is different than the address of the building, submit a written explanation.**

**SECTION II** (Please type or print)

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 5/23/2016 ENROLLMENT 1391  
IDPH INSPECTOR LICENSE NUMBER: 100-11093  
IDPH LICENSED INSPECTOR NAME (Please Print): David Avila  
IDPH MP LICENSE NUMBER: 100-01786  
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Guillermo Garcia

DESIGNATED PERSON (Please Print): Robert Christlieb PHONE: (773) 553-3197



5/23/2016

Signature of Designated Person

Date

**SECTION III**

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: \_\_\_\_\_

School has been closed. Date closed: \_\_\_\_\_

School building has been demolished. Date: \_\_\_\_\_

School building is asbestos free since last reinspection: \_\_\_\_\_

**Please explain in writing why the school building is now asbestos free and include the supporting documentation.**

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

**Explain in writing if the address of the building is different than the address on this form:**

**THREE-YEAR REINSPECTION**

**CHICAGO SCHOOL DIST 299**

**Senn Academy**

5900 N. Glenwood  
Chicago, IL, 60660

Unit: 47061  
Building ID: 1540

IDPH ID Number: 14-016-2990-0037

**REPORT DATE:**

Monday, May 23, 2016

**Prepared for:**

**Chicago Public Schools**  
**125 S. Clark Street**  
**Chicago, IL 60603**

**Prepared by:**

**GSG Consultants, Inc.**

855 W. Adams St., Ste. 200

Phone (312) 733-6262

Fax (312) 733-5612

**DO NOT REMOVE FROM SCHOOL  
REQUIRED BY FEDERAL LAW**

March 16, 2016

Mr. R. Kent Cook  
Asbestos Program  
Illinois Department of Public Health  
525 West Jefferson Street  
Springfield, Illinois 62761

Re: Chicago Public Schools - 2016 Three-Year Reinspections

Dear Mr. Cook:

GSG Consultants, Inc., Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 1,2,6 Elementary Schools. Please update your records with the following information.

School District: 299                  Unit: 47061                          Region: 01                          IDPH ID: 14-016-2990-0037

School: Senn Academy    Building ID: 1540

Address: 5900 N. Glenwood  
Chicago, IL, 60660

Building Contact: Lumanglas, Daniel    Contact Phone: 773-807-1207

Current Building Owners: Chicago Public Schools

Review Date: 05/13/2016

Inspector: David Avila    Inspector IDPH License: 100-11093  
Management Planner: Guillermo Garcia    Management Planner IDPH License: 100-01786

If you have any questions or comments, please contact us at (312) 733-6262

Sincerely,  
GSG Consultants, Inc.



Guillermo Garcia  
100-01786

## **Environmental Notification to Occupants**

To: Faculty, Staff and Parents  
From: Chicago Public Schools  
Date: March 16, 2016

RE: Senn Academy, Unit 47061  
5900 N. Glenwood  
Chicago, IL, 60660

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2016 asbestos three year re-inspection has been completed at Senn Academy , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at Senn Academy, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Robert Christlieb, the designated Local Education Authority's Designated Person at (773) 553-3197 .

## **Table of Contents**

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

### **APPENDICES:**

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

## SCHOOL AND INSPECTION INFORMATION

### 1. School Information

School: Senn Academy  
Address: 5900 N. Glenwood  
IDPH ID: 14-016-2990-0037  
Contact: Lumanglas, Daniel

Unit: 47061  
Chicago, IL, 60660  
Building ID: 1540  
Phone: 773-807-1207

Region: 01

### 2. Description of Facility

Original Construction: 1930  
Total Square Footage: 37798  
Current Occupancy: 1391

Additional Construction: 1913,1931  
No of Floors: 3

### 3. LEA Designated Person

Contact: Robert Christlieb  
Address: 125 South Clark Street, 17th Floor  
Chicago, IL 60603

Phone: (773) 553-3197

### 4. Managing Environmental Consultant


MEC: GSG Consultants, Inc.  
Contact: Arturo Saenz  
Address 855 W. Adams St., Ste. 200  
Phone: (312) 733-6262

Fax: (312) 733-5612

### 5. Inspector

Inspector Name: David Avila


Inspector IDPH license # 100-11093

Signature:   
Date: 3/16/2016

### 6. Management Planner

Management Planner Name: Guillermo Garcia

Management Planner IDPH license # 100-01786

Signature:   
Date: 05/13/2016

### 7. Review Date: 05/13/2016

### 8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature: 

Date: 5/23/2016

Name: Robert Christlieb

## II. EXECUTIVE SUMMARY

GSG Consultants, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Senn Academy. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 1540:

|     |  |
|-----|--|
| 133 | Lt Blue Speckled Linoleum- NOT OBSERVED        |
| 134 | Lt Blue Speckled Linoleum Mastic- NOT OBSERVED |
| 89  | Green Linoleum (Not Observed)                  |

B. The following new homogenous areas have been identified for Building 1540:

|     |  |
|-----|--|
| 175 | 12x12 Blue speckled VFT                            |
| 176 | 12x12 Blue speckled VFT Mastic                     |
| 177 | 12x12 Light Blue w/ Specks VFT                     |
| 178 | 12x12 Light Blue w/ Specks VFT Mastic              |
| 179 | 12x12 Gray w/streaks VFT                           |
| 180 | 12x12 Gray w/streaks VFT Mastic                    |
| 181 | Gray linoleum w/ granite pattern                   |
| 182 | Gray linoleum w/ granite pattern Mastic            |
| 183 | Gray linoleum                                      |
| 184 | Gray linoleum Mastic                               |
| 185 | 12x12 Red w/ streaks VFT                           |
| 186 | 12x12 Red w/specks VFT Mastic                      |
| 187 | 12x12 Yellow w/streaks VFT                         |
| 188 | 12x12 Yellow w/streaks VFT Mastic                  |
| 189 | 12x12 Green w/ streaks VFT                         |
| 190 | 12x12 Green w/ streaks VFT Mastic                  |
| 191 | 12x12 Dark gray linoleum w/ granite pattern        |
| 192 | 12x12 Dark gray linoleum w/ granite pattern Mastic |
| 193 | 12x12 Pink w/ maroon specks VFT                    |
| 194 | 12x12 Pink w/ maroon specks VFT Mastic             |
| 195 | 12x12 Maroon w/ pink specks VFT                    |
| 196 | 12x12 Maroon w/ pink specks VFT Mastic             |



C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

|       |  |
|-------|--|
| 104   | 12"x12" Light Green w/ White Streaks VFT               |
| 105   | 12"x12" Light Green w/ White Streaks VFT Mastic        |
| 106   | 12"x12" Beige w/ Dark & White Streaks VFT              |
| 127   | 12"x12" White w/Beige Streaks VFT- NOT OBSERVED        |
| 127 A | 12"x12" White w/Beige Streaks VFT Mastic- NOT OBSERVED |
| 128   | 12"x12" White w/Blue Streaks VFT                       |
| 128 A | 12 x 12 inch White w/blue Streaks VFT Mastic           |
| 133   | Lt Blue Speckled Linoleum- NOT OBSERVED                |
| 134   | Lt Blue Speckled Linoleum Mastic- NOT OBSERVED         |
| 135   | 12"x12" White w/ Gold Specks VFT- NOT OBSERVED         |
| 136   | 12"x12" White w/ Gold Specks VFT Mastic- NOT OBSERVED  |
| 137   | 2'x4' White Pin-Hole Ceiling Tile                      |
| 138   | 12"x12" White w/ Beige VFT                             |
| 139   | 12"x12" White w/ Beige VFT Mastic                      |
| 140   | 12"x12" Light Gray VFT- NOT OBSERVED                   |
| 141   | 12"x12" Light Gray VFT Mastic- NOT OBSERVED            |
| 142   | 12"x12" Light Blue VFT                                 |
| 143   | 12"x12" Light Blue VFT Mastic                          |
| 144   | 12"x12" Green VFT                                      |
| 145   | 12"x12" Green VFT Mastic                               |
| 146   | 12"x12" White VFT                                      |
| 147   | 12"x12" White VFT Mastic                               |
| 148   | Linoleum, Gray w/Gray Streaks                          |
| 148M  | Linoleum, Gray w/Gray Streaks Mastic                   |
| 149   | Linoleum, Blue Solid (Not Observed)                    |
| 149M  | Linoleum, Blue Solid Mastic (Not Observed)             |
| 150   | 12"X12" VFT-- NOT OBSERVED                             |
| 150M  | 12"X12" VFT Mastic - NOT OBSERVED                      |
| 151   | Solid Gray   |
| 151M  | Solid Gray Mastic                                      |
| 152   | Tan w/Brown Speckles                                   |
| 152M  | Tan w/Brown Speckles Mastic                            |
| 153   | 12"X12" White w/ Tan Speckles VFT                      |
| 153M  | 12"X12" White w/ Tan Speckles VFT Mastic               |
| 154M  | Gold, Blue Carpet                                      |
| 155   | Linoleum, White w/Gray Streaks                         |

|      |   |
|------|---|
| 155M | Linoleum, White w/Gray Streaks Mastic                       |
| 156  | 12"x12" light gray w/ gray and white specks VFT             |
| 156A | 12"x12" light gray w/ gray specks VFT MASTIC                |
| 157  | 2'x4' smooth CT   |
| 158  | 1'x1' CT w/ grooves   |
| 159  | 1'x1' CT w/ grooves above HA 161                            |
| 160  | 2'x4' CT w/ grooves   |
| 161  | 2'x4' CT w/ grooves   |
| 162  | 2'x4' CT pinhole  |
| 163  | 2'x4' CT pinholes   |
| 164  | 12"x12" Tan w/ light brown specks VFT                       |
| 164A | 12"x12" Tan w/ light brown specks VFT MASTIC                |
| 165  | 9"x9" brown w/ yellow design VFT (Not Observed)             |
| 165A | 9"x9" Brown w/ yellow design VFT MASTIC (Not Observed)      |
| 166  | 12"x12" lt. blue w/ blue specks VFT                         |
| 166A | 12"x12" lt. blue w/ blue specks VFT MASTIC                  |
| 167  | 12"x12" white w/light blue, gray and yellow specks VFT      |
| 167A | 12"x12" white w/ lt blue, gray and yellow specks VFT MASTIC |
| 168  | Black lab table tops  |
| 169  | Black lab counter tops                                      |
| 170  | Blue linoleum with MASTIC                                   |
| 171  | 12"x12" gray w/ tan streaks VFT w/ MASTIC                   |
| 172  | Decorative plaster  |
| 173  | Terrazzo  |
| 174  | Terrazzo  |
| 175  | 12x12 Blue speckled VFT                                     |
| 176  | 12x12 Blue speckled VFT Mastic                              |
| 177  | 12x12 Light Blue w/ Specks VFT                              |
| 178  | 12x12 Light Blue w/ Specks VFT Mastic                       |
| 179  | 12x12 Gray w/streaks VFT                                    |
| 180  | 12x12 Gray w/streaks VFT Mastic                             |
| 181  | Gray linoleum w/ granite pattern                            |
| 182  | Gray linoleum w/ granite pattern Mastic                     |
| 183  | Gray linoleum   |
| 184  | Gray linoleum Mastic  |
| 185  | 12x12 Red w/ streaks VFT                                    |
| 186  | 12x12 Red w/specks VFT Mastic                               |
| 187  | 12x12 Yellow w/streaks VFT                                  |
| 188  | 12x12 Yellow w/streaks VFT Mastic                           |
| 189  | 12x12 Green w/ streaks VFT                                  |
| 190  | 12x12 Green w/ streaks VFT Mastic                           |
| 191  | 12x12 Dark gray linoleum w/ granite pattern                 |
| 192  | 12x12 Dark gray linoleum w/ granite pattern Mastic          |
| 193  | 12x12 Pink w/ maroon specks VFT                             |
| 194  | 12x12 Pink w/ maroon specks VFT Mastic                      |

|     |  |
|-----|--|
| 195 | 12x12 Maroon w/ pink specks VFT                                |
| 196 | 12x12 Maroon w/ pink specks VFT Mastic                         |
| 25  | Insulation in Vault Door                                       |
| 64  | 12"x12" Light Brown w/ White Streaks VFT (Not Observed)        |
| 65  | 12"x12" Light Brown w/ White Streaks VFT Mastic (Not Observed) |
| 80  | 12"x12" White w/ Brown Speckles VFT                            |
| 81  | 12"x12" White w/ Brown Speckles VFT Mastic                     |
| 86  | 12"x12" Brown w/ Light Brown Speckles VFT                      |
| 88  | Brown Linoleum   |
| 89  | Green Linoleum (Not Observed)                                  |
| AA  | 12"x 12" green floor tile- NOT OBSERVED                        |
| BB  | Mastic associated with HA AA - NOT OBSERVED                    |
| CC  | Lab counter tops   |
| DD  | Lab tables   |
| EE  | lab fume hoods   |

The following areas were deemed to be inaccessible:

|       |   |
|-------|---|
| 100   | 9"x9" Red w/ White Streaks VFT- NOT OBSERVED                  |
| 101   | 9"x9" Red w/ White Streaks VFT Mastic- NOT OBSERVED           |
| 102   | 9"x9" Gray w/ White Streaks VFT                               |
| 103   | 9"x9" Gray w/ White Streaks VFT Mastic                        |
| 110   | 9"x9" Green w/ White Streaks VFT                              |
| 113   | 12"x12" Lt. Brown w/ Gray Speckles VFT Mastic                 |
| 114   | 12"x12 Beige w/ Brown Streaks VFT- NOT OBSERVED               |
| 123   | 12"x12" Brown VFT Mastic- NOT OBSERVED                        |
| 127 A | 12"x12" White w/Beige Streaks VFT Mastic- NOT OBSERVED        |
| 25    | Insulation in Vault Door                                      |
| 30    | Aircell Pipe Insulation                                       |
| 56    | 9"x9" Brown w/Sreaks VFT Mastic- NOT OBSERVED                 |
| 91    | 12"x12" Peach w/ Speckles VFT Mastic- NOT OBSERVED            |
| 92    | 12"x12" Light Brown w/ Dark Speckles VFT- NOT OBSERVED        |
| 93    | 12"x12" Light Brown w/ Dark Speckles VFT Mastic- NOT OBSERVED |
| 98    | 12"x12" Black w/ White Speckles VFT- NOT OBSERVED             |
| 99    | 12"x12" Black w/ White Speckles VFT Mastic-                   |

## NOT OBSERVED

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by David Avila, IDPH License # 100-11093. The Management Plan was updated by Guillermo Garcia, IDPH License # 100-01786. Inspector and Management Planner Licenses are included in Appendix B.

### **III. METHODOLOGY**

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

### **IV. ABATEMENT HISTORY**

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

### **V. REASSESSMENTS AND RECOMMENDATIONS**

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

### **VI. CONCLUSIONS**

The Senn Academy Building 1540 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

**Table I**  
**Inspector's Reinspection Findings**

---

# Chicago Public Schools

School Senn Academy Unit 47061 Building ID 1540

Address 5900 N. Glenwood Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

*Inspector's Comments are Summarized at the End of the Report*

| HA No | Material Description                                | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category | Damage Category                    | Damage Reason | Disturbance Potential |
|-------|---|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|------------------------------------|---------------|-----------------------|
| 01    | Boiler Lagging (ABATED 2010)                        |                   |                | Boiler # 1 - 1931  | ABATED        | TSI               |         |             |                 |              |                               |                                    |               |                       |
| 02    | Boiler Lagging (ABATED 2010)                        |                   |                | Boiler # 2 - 1931  | ABATED        | TSI               |         |             |                 |              |                               |                                    |               |                       |
| 03    | Boiler Lagging (ABATED 2010)                        |                   |                | Boiler # 3 - 1931  | ABATED        | TSI               |         |             |                 |              |                               |                                    |               |                       |
| 04    | Boiler Lagging (ABATED 2010)                        |                   |                | Boiler # 4 - 1931  | ABATED        | TSI               |         |             |                 |              |                               |                                    |               |                       |
| 05    | Boiler Gasket (ABATED 2010)                         |                   |                | Boiler # 1 - 1931  | ABATED        | TSI               |         |             |                 |              |                               |                                    |               |                       |
| 06    | Boiler Gasket (ABATED 2010)                         |                   |                | Boiler # 2 - 1931  | ABATED        | TSI               |         |             |                 |              |                               |                                    |               |                       |
| 09    | MJP on Fiberglass Pipe Insulation                   | 600               | LF             | Throughout - 1912 (See Hatching Maps)  | CHR           | TSI               | Y       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 10    | MJP on Fiberglass Pipe Insulation                   | 425               | LF             | ROTC Rm, Boiler & Pump Rms, Main Tunnel, 2nd & 3rd Flr S JC Chase, 2nd Flr Boy Tol (N) - 1931; 3rd Floor Unisex Toilet.; 1st Floor Janitor's Closet.; Under Sinks in Rms 310, 352, and 366; BookRoom Between Rm 315 and 317; Mens Rm Next to Rm 322. | CHR           | TSI               | Y       | LOC         | 0               |              | No                            | ACBM with the potential for damage |               | MODERATE              |
| 100   | 9"x9" Red w/ White Streaks VFT- NOT OBSERVED        | 300               | SF             | 115 Kitchen - 1912   | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 1000  | 12"x12" orange/brown VFT- NOT OBSERVED              | 24                | SF             | Rm 180 wooden stage  | CHR           | MISC              | Y       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 1001  | 12"x12" orange/brown VFT black mastic- NOT OBSERVED | 24                | SF             | Rm 180 wooden stage  | CHR           | MISC              | Y       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 101   | 9"x9" Red w/ White Streaks VFT Mastic- NOT OBSERVED | 300               | SF             | 115 Kitchen - 1912   | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 102   | 9"x9" Gray w/ White Streaks VFT                     | 800               | SF             | Rooms 117A - 1912  | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | MODERATE              |
| 103   | 9"x9" Gray w/ White Streaks VFT Mastic              | 800               | SF             | Rooms 117A - 1912  | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 104   | 12"x12" Light Green w/ White Streaks VFT            | 350               | SF             | Room 123A - 1912   | ASSUMED       | MISC              | N       | NONE        | 0               |              |                               | ACBM with the potential for damage |               | MODERATE              |
| 105   | 12"x12" Light Green w/ White Streaks VFT Mastic     | 350               | SF             | Room 123A - 1912   | ASSUMED       | MISC              | N       | NONE        | 0               |              |                               | ACBM with the potential for damage |               | LOW                   |
| 106   | 12"x12" Beige w/ Dark & White Streaks VFT           | 6,100             | SF             | Rooms 127, 129, 131, 132, 133, 134, 137, 139, 135, 190, 239 - 1912   | ASSUMED       | MISC              | N       | NONE        | 0               |              |                               | ACBM with the potential for damage |               | LOW                   |

# Chicago Public Schools

School Senn Academy Unit 47061 Building ID 1540

Address 5900 N. Glenwood Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

*Inspector's Comments are Summarized at the End of the Report*

| HA No | Material Description                                       | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category | Damage Category                    | Damage Reason | Disturbance Potential |
|-------|--|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|------------------------------------|---------------|-----------------------|
| 107   | 12"x12" Beige w/ Dark & White Streaks VFT Mastic           | 6,100             | SF             | Rooms 127, 129, 131, 132, 133, 134, 137, 139, 135, 190, 239 - 1912     | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 108   | 9"x9" Lt. Brown w/ Dark Red Streaks VFT                    | 455               | SF             | Teacher Lunchroom/Lounge - 1912; Rms 300 (under sink), 310 (lab vault) | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 109   | 9"x9" Lt. Brown w/ Dark Red Streaks VFT Mastic             | 455               | SF             | Teacher Lunchroom/Lounge - 1912; Rms 300 (under sink), 310 (lab vault) | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 110   | 9"x9" Green w/ White Streaks VFT                           | 300               | SF             | Teacher Lunchroom/Lounge - 1912  | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 111   | 9"x9" Green w/ White Streaks VFT Mastic                    | 300               | SF             | Teacher Lunchroom/Lounge - 1912  | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               |                       |
| 112   | 12"x12" Lt. Brown w/ Gray Speckles VFT                     | 80                | SF             | 153 Vest., 120 Vest. - 1912  | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 113   | 12"x12" Lt. Brown w/ Gray Speckles VFT Mastic              | 80                | SF             | 153 Vest., 120 Vest. - 1912  | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 114   | 12"x12 Beige w/ Brown Streaks VFT- NOT OBSERVED            | 1,400             | SF             | Rooms 166, & 162 - 1912  | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 115   | 12"x12 Beige w/ Brown Streaks VFT Mastic- NOT OBSERVED     | 1,400             | SF             | Rooms 166, & 162 - 1912  | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 116   | 12"x12" Blue-Gray w/ White Streaks VFT                     | 500               | SF             | Room 373- 1912   | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 117   | 12"x12" Blue-Gray w/ White Streaks VFT Mastic              | 500               | SF             | Room 373- 1912   | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 118   | 12"x12" Dk Gray w/ Beige Streaks VFT- NOT OBSERVED         | 2,000             | SF             | Rooms 176, 174, 180 - 1912   | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | MODERATE              |
| 119   | 12"x12" Dk Gray w/ Beige Streaks VFT Mastic- NOT OBSERVED  | 2,000             | SF             | Rooms 176, 174, 180 - 1912   | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 120   | 12"x12" Lt Gray w/ White Speckles VFT- NOT OBSERVED        | 2,000             | SF             | Rooms 176, 174, 180 - 1912   | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | MODERATE              |
| 121   | 12"x12" Lt Gray w/ White Speckles VFT Mastic- NOT OBSERVED | 2,000             | SF             | Rooms 176, 174, 180 - 1912   | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 122   | 12"x12" Brown VFT- NOT OBSERVED                            | 0                 | SF             | Stage - 1912   | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 123   | 12"x12" Brown VFT Mastic- NOT OBSERVED                     | 0                 | SF             | Stage - 1912   | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |



# Chicago Public Schools

School Senn Academy Unit 47061 Building ID 1540

Address 5900 N. Glenwood Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

*Inspector's Comments are Summarized at the End of the Report*

| HA No | Material Description  | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category | Damage Category                    | Damage Reason | Disturbance Potential |
|-------|---|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|------------------------------------|---------------|-----------------------|
| 124   | 2'x2' Black Border VFT  | 15                | SF             | 115 Kitchen - 1912   | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 125   | 2'x2' Black Border VFT Mastic- NOT OBSERVED                   | 15                | SF             | 115 Kitchen - 1912   | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 126   | 2'x2' Ceiling Tile- NOT OBSERVED                              | 1,700             | SF             | Room 425, & 326 - 1912   | CHR           | MISC              | Y       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 127   | 12"x12" White w/Beige Streaks VFT- NOT OBSERVED               | 1,000             | SF             | Room 377   | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | MODERATE              |
| 127 A | 12"x12" White w/Beige Streaks VFT Mastic- NOT OBSERVED        | 1,000             | SF             | Room 377   | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 128   | 12"x12" White w/Blue Streaks VFT                              | 880               | SF             | Room 351   | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 128 A | 12 x 12 inch White w/blue Streaks VFT Mastic                  | 880               | SF             | Room 351   | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 13    | MJP on Paperwrap Pipe Insulation; 2nd Floor Janitor's Closet. | 370               | LF             | 1st Floor South JC, 238 Chase, 188, Autoshop - 1931 bldg.            | CHR           | TSI               | Y       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | MODERATE              |
| 133   | Lt Blue Speckled Linoleum- NOT OBSERVED                       | 800               | SF             | Room 356 - 1912; Room 326  | ASSUMED       | MISC              | N       | NONE        | 0               |              | Yes                           | ACBM with the potential for damage |               | MODERATE              |
| 134   | Lt Blue Speckled Linoleum Mastic- NOT OBSERVED                | 800               | SF             | Room 356 - 1912; Room 326  | ASSUMED       | MISC              | N       | NONE        | 0               |              | Yes                           | ACBM with the potential for damage |               | MODERATE              |
| 135   | 12"x12" White w/ Gold Specks VFT- NOT OBSERVED                | 1,000             | SF             | Rooms 174, 176, & 180 - 1911   | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 136   | 12"x12" White w/ Gold Specks VFT Mastic- NOT OBSERVED         | 1,000             | SF             | Rooms 174, 176, & 180 - 1911   | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 137   | 2'x4' White Pin-Hole Ceiling Tile                             | 1,000             | SF             | Room 356 - 1912  | ASSUMED       | MISC              | Y       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 138   | 12"x12" White w/ Beige VFT                                    | 2,000             | SF             | 310 & Office, 302, 108, 110 - 1931                                   | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 139   | 12"x12" White w/ Beige VFT Mastic                             | 2,000             | SF             | 310 & Office, 302, 108, 110 - 1931                                   | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 14    | Paperwrap Pipe Insulation                                     | 300               | LF             | ROTC Room, 1st Floor South JC, 238 Chase, 188, Autoshop - 1931 bldg. | CHR           | TSI               | Y       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 140   | 12"x12" Light Gray VFT- NOT OBSERVED                          | 0                 | SF             | 210, & Engineer's Office - 1931                                      | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 141   | 12"x12" Light Gray VFT Mastic- NOT OBSERVED                   | 0                 | SF             | 210, & Engineer's Office - 1931                                      | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 142   | 12"x12" Light Blue VFT  | 900               | SF             | 210, 195A & Engineer's Office - 1931                                 | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |

# Chicago Public Schools

School Senn Academy Unit 47061 Building ID 1540

Address 5900 N. Glenwood Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

*Inspector's Comments are Summarized at the End of the Report*

| HA No | Material Description                       | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category | Damage Category                    | Damage Reason | Disturbance Potential |
|-------|--|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|------------------------------------|---------------|-----------------------|
| 143   | 12"x12" Light Blue VFT Mastic              | 900               | SF             | 210, 195A & Engineer's Office - 1931  | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 144   | 12"x12" Green VFT                          | 300               | SF             | 1st Floor Hall (N&S) - 1931   | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 145   | 12"x12" Green VFT Mastic                   | 300               | SF             | 1st Floor Hall (N&S) - 1931   | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 146   | 12"x12" White VFT                          | 1,000             | SF             | 1st Floor Hall (N&S) - 1931   | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 147   | 12"x12" White VFT Mastic                   | 1,000             | SF             | 1st Floor Hall (N&S) - 1931   | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 148   | Linoleum, Gray w/Gray Streaks              | 3,500             | SF             | Rooms 350, 352, 356 Vault, and 306  | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 148M  | Linoleum, Gray w/Gray Streaks Mastic       | 3,500             | SF             | Rooms 350, 352, 356 Vault, and 306  | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 149   | Linoleum, Blue Solid (Not Observed)        | 2,000             | SF             | Rms 100, 106, and 106 Office  | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 149M  | Linoleum, Blue Solid Mastic (Not Observed) | 2,000             | SF             | Rms 100, 106, and 106 Office  | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 150   | 12"X12" VFT-- NOT OBSERVED                 | 200               | SF             | 3rd Floor Side Corridor, SE to West Naval Area, Border Along N. and S. Walls - NOT OBSERVED | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 150M  | 12"X12" VFT Mastic - NOT OBSERVED          | 200               | SF             | 3rd Floor Side Corridor, SE to West Naval Area, Border Along N. and S. Walls - NOT OBSERVED | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 151   | Solid Gray                                 | 800               | SF             | 3rd Floor Side Corridor, SE to West Naval Area, Center of Corridor                          | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 151M  | Solid Gray Mastic                          | 800               | SF             | 3rd Floor Side Corridor, SE to West Naval Area, Center of Corridor                          | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 152   | Tan w/Brown Speckles                       | 800               | SF             | 3rd Floor Side Corridor-North,Runs East-to-West in Naval Area, Center of Corridor           | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |

# Chicago Public Schools

School Senn Academy Unit 47061 Building ID 1540

Address 5900 N. Glenwood Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

*Inspector's Comments are Summarized at the End of the Report*

| HA No | Material Description                            | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category | Damage Category                    | Damage Reason | Disturbance Potential |
|-------|---|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|------------------------------------|---------------|-----------------------|
| 152M  | Tan w/Brown Speckles Mastic                     | 800               | SF             | 3rd Floor Side Corridor-North,Runs East-to-West in Naval Area, Center of Corridor   | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 153   | 12"x12" White w/ Tan Speckles VFT               | 200               | SF             | 3rd Floor Side Corridor-North,Runs East-to-West in Naval Area, Border Along N. and S. Walls   | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 153M  | 12"x12" White w/ Tan Speckles VFT Mastic        | 200               | SF             | 3rd Floor Side Corridor-North,Runs East-to-West in Naval Area, Border Along N. and S. Walls   | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 154M  | Gold, Blue Carpet                               | 3,800             | SF             | Rms 379, 375, 326, 315, and 272(not observed)   | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 155   | Linoleum, White w/Gray Streaks                  | 750               | SF             | Rm 352  | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 155M  | Linoleum, White w/Gray Streaks Mastic           | 750               | SF             | Rm 352  | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 156   | 12"x12" light gray w/ gray and white specks VFT | 600               | SF             | Room 377  | ASSUMED       | MISC              | N       | NONE        | 0               |              |                               | ACBM with the potential for damage |               | LOW                   |
| 156A  | 12"x12" light gray w/ gray specks VFT MASTIC    | 600               | SF             | Room 377  | ASSUMED       | MISC              | N       | NONE        | 0               |              |                               | ACBM with the potential for damage |               | LOW                   |
| 157   | 2'x4' smooth CT                                 | 700               | SF             | Room 351  | ASSUMED       | MISC              | Y       | NONE        | 0               |              |                               | ACBM with the potential for damage |               | LOW                   |
| 158   | 1'x1' CT w/ grooves                             | 2,600             | SF             | Room 320, 425-1911 bldg   | ASSUMED       | MISC              | Y       | NONE        | 0               |              |                               | ACBM with the potential for damage |               | LOW                   |
| 159   | 1'x1' CT w/ grooves above HA 161                | 1,000             | SF             | Room 108, 148, 149, 146   | ASSUMED       | MISC              | Y       | NONE        | 0               |              |                               | ACBM with the potential for damage |               | LOW                   |
| 160   | 2'x4' CT w/ grooves                             | 22,000            | SF             | Bldg 1930- South wing except women's toilet and 213- 2nd fl. 2nd fl. north wing except boys toilet. 1st fl. south wing except for girls' toilet and engineer room. 1st fl. south wing hallway and rm 145. | ASSUMED       | MISC              | Y       | NONE        | 0               |              |                               | ACBM with the potential for damage |               | LOW                   |

# Chicago Public Schools

School Senn Academy Unit 47061 Building ID 1540

Address 5900 N. Glenwood Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

*Inspector's Comments are Summarized at the End of the Report*

| HA No | Material Description | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category | Damage Category                    | Damage Reason | Disturbance Potential |
|-------|----------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|------------------------------------|---------------|-----------------------|
|       |                      |                   |                | 3rd fl all south wing except for 306, 313, 315 and women's toilet. 3rd fl all north wing except for room 341, 335, 333 and men's toilet.   |               |                   |         |             |                 |              |                               |                                    |               |                       |
| 161   | 2'x4' CT w/ grooves  | 45,000            | SF             | Bldg 1911- Hallway from 319-335 and rooms 350, 353, 322, 326, 328, 330, 332, 334, 335, 325, 319, 358, 363, 367, 369, 373, 375, 379, 372, 374, 378, 380, 376, 258, 260, 261, 262, 264, 234, 266, 272, 276, 278, 273, 275, 277, 281, 222, 219, 221, 227, 231, 233, 230, 236. 2nd fl. hallway from room 319-335, 134, 132, 123A, 123, 121, 172, 174, 176, main office. 1st floor from 119- conference room and rooms 158, 160, 162, 166 | ASSUMED       | MISC              | Y       | NONE        | 0               |              |                               | ACBM with the potential for damage |               | LOW                   |
| 162   | 2'x4' CT pinhole     | 13,000            | SF             | 1911 bldg- 1st fl. hallway from room 158-180 and from heat chamber 3- heat chamber 8. 2nd fl hallway from room 258-280 and hallway along side of auditorium. 3rd fl hallway from room 350-361-380 and from room 369-328 and classrooms 352,364,366.  | ASSUMED       | MISC              | Y       | NONE        | 0               |              |                               | ACBM with the potential for damage |               | LOW                   |
| 163   | 2'x4' CT pinholes    | 4,500             | SF             | Corridor- 1930 bldg.   | ASSUMED       | MISC              | Y       | NONE        | 0               |              |                               | ACBM with the                      |               | LOW                   |

# Chicago Public Schools

School Senn Academy Unit 47061 Building ID 1540

Address 5900 N. Glenwood Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

*Inspector's Comments are Summarized at the End of the Report*

| HA No | Material Description  | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category | Damage Category                    | Damage Reason | Disturbance Potential |
|-------|---|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|------------------------------------|---------------|-----------------------|
|       |   |                   |                | from pump room-room 184, kitchen, cafeteria                                  |               |                   |         |             |                 |              |                               | potential for damage               |               |                       |
| 164   | 12"x12" Tan w/ light brown specks VFT                       | 1,600             | SF             | 119, 121, South corridor- 1912   | ASSUMED       | MISC              | N       | NONE        | 0               |              |                               | ACBM with the potential for damage |               | LOW                   |
| 164A  | 12"x12" Tan w/ light brown specks VFT MASTIC                | 1,600             | SF             | 119, 121, South corridor- 1912   | ASSUMED       | MISC              | N       | NONE        | 0               |              |                               | ACBM with the potential for damage |               | LOW                   |
| 165   | 9"x9" brown w/ yellow design VFT (Not Observed)             | 100               | SF             | Room 123- 1911 bldg  | ASSUMED       | MISC              | N       | NONE        | 0               |              |                               | ACBM with the potential for damage |               | LOW                   |
| 165A  | 9"x9" Brown w/ yellow design VFT MASTIC (Not Observed)      | 100               | SF             | Room 123- 1911 bldg  | ASSUMED       | MISC              | N       | NONE        | 0               |              |                               | ACBM with the potential for damage |               | LOW                   |
| 166   | 12"x12" lt. blue w/ blue specks VFT                         | 500               | SF             | 2nd, 3rd Floor main center corridor, Health Center (144) 1912 bldg           | ASSUMED       | MISC              | N       | NONE        | 0               |              |                               | ACBM with the potential for damage |               | LOW                   |
| 166A  | 12"x12" lt. blue w/ blue specks VFT MASTIC                  | 500               | SF             | 2nd, 3rd Floor main center corridor, Health Center (144) 1912 bldg           | ASSUMED       | MISC              | N       | NONE        | 0               |              |                               | ACBM with the potential for damage |               | LOW                   |
| 167   | 12"x12" white w/light blue, gray and yellow specks VFT      | 7,000             | SF             | 2nd, 3rd Floor main center corridor, Health Center (144), 162, 166 1912 bldg | ASSUMED       | MISC              | N       | NONE        | 0               |              |                               | ACBM with the potential for damage |               | LOW                   |
| 167A  | 12"x12" white w/ lt blue, gray and yellow specks VFT MASTIC | 7,000             | SF             | 2nd, 3rd Floor main center corridor, Health Center (144), 162, 166 1912 bldg | ASSUMED       | MISC              | N       | NONE        | 0               |              |                               | ACBM with the potential for damage |               | LOW                   |
| 168   | Black lab table tops  | 700               | SF             | Room 358, 364, 367   | ASSUMED       | MISC              | N       | NONE        | 0               |              |                               | ACBM with the potential for damage |               | LOW                   |
| 169   | Black lab counter tops                                      | 300               | SF             | Room 358, 364, 367   | ASSUMED       | MISC              | N       | NONE        | 0               |              |                               | ACBM with the potential for damage |               | LOW                   |
| 170   | Blue linoleum with MASTIC                                   | 2,300             | SF             | Rooms 358, 364, 366  | ASSUMED       | MISC              | N       | NONE        | 0               |              |                               | ACBM with the potential for damage |               | LOW                   |
| 171   | 12"x12" gray w/ tan streaks VFT w/ MASTIC                   | 400               | SF             | 170  | ASSUMED       | MISC              | N       | LOC         | 40              |              |                               | ACBM with the potential for damage |               | LOW                   |
| 172   | Decorative plaster  | 1,200             | SF             | Assembly hall, vestibule leading to assembly hall                            | ASSUMED       | MISC              | N       | NONE        | 0               |              |                               | ACBM with the potential for damage |               | LOW                   |
| 173   | Terrazzo  | 2,000             | SF             | Stairwells, 1st fl. corridor west of pump room- 1930 addition                | ASSUMED       | MISC              | N       | NONE        | 0               |              |                               | ACBM with the potential for damage |               | LOW                   |
| 174   | Terrazzo  | 1,000             | SF             | Addition 1912- 1st fl corridors  | ASSUMED       | MISC              | N       | NONE        | 0               |              |                               | ACBM with the potential for damage |               | LOW                   |

# Chicago Public Schools

School Senn Academy Unit 47061 Building ID 1540

Address 5900 N. Glenwood Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

*Inspector's Comments are Summarized at the End of the Report*

| HA No | Material Description                               | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category | Damage Category                    | Damage Reason | Disturbance Potential |
|-------|--|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|------------------------------------|---------------|-----------------------|
| 175   | 12x12 Blue speckled VFT                            | 1,000             | SF             | 3rd Floor NW & W corridor, 2nd floor W & center corridor            | ASSUMED       | MISC              | N       | NONE        | 0               |              |                               | ACBM with the potential for damage |               | LOW                   |
| 176   | 12x12 Blue speckled VFT Mastic                     | 1,000             | SF             | 3rd Floor NW & W corridor, 2nd floor W & center corridor            | ASSUMED       | MISC              | N       | NONE        | 0               |              |                               | ACBM with the potential for damage |               | LOW                   |
| 177   | 12x12 Light Blue w/ Specks VFT                     | 8,000             | SF             | 3rd Floor NW & W corridor, 2nd floor W & center corridor -1911 Bldg | ASSUMED       | MISC              | N       | NONE        | 0               |              |                               | ACBM with the potential for damage |               | MODERATE              |
| 178   | 12x12 Light Blue w/ Specks VFT Mastic              | 8,000             | SF             | 3rd Floor NW & W corridor, 2nd floor W & center corridor -1911 Bldg | ASSUMED       | MISC              | N       | NONE        | 0               |              |                               | ACBM with the potential for damage |               | MODERATE              |
| 179   | 12x12 Gray w/streaks VFT                           | 900               | SF             | Room 221  | ASSUMED       | MISC              | N       | NONE        | 0               |              |                               | ACBM with the potential for damage |               | MODERATE              |
| 180   | 12x12 Gray w/streaks VFT Mastic                    | 900               | SF             | Room 221  | ASSUMED       | MISC              | N       | NONE        | 0               |              |                               | ACBM with the potential for damage |               | LOW                   |
| 181   | Gray linoleum w/ granite pattern                   | 1,200             | SF             | Room 100  | ASSUMED       | MISC              | N       | NONE        | 0               |              |                               | ACBM with the potential for damage |               | MODERATE              |
| 182   | Gray linoleum w/ granite pattern Mastic            | 1,200             | SF             | Room 100  | ASSUMED       | MISC              | N       | NONE        | 0               |              |                               | ACBM with the potential for damage |               | LOW                   |
| 183   | Gray linoleum                                      | 2,400             | SF             | Rooms 105, 105A, 110  | ASSUMED       | MISC              | N       | NONE        | 0               |              |                               | ACBM with the potential for damage |               | MODERATE              |
| 184   | Gray linoleum Mastic                               | 2,400             | SF             | Rooms 105, 105A, 110  | ASSUMED       | MISC              | N       | NONE        | 0               |              |                               | ACBM with the potential for damage |               | LOW                   |
| 185   | 12x12 Red w/ streaks VFT                           | 400               | SF             | Health center (144)   | ASSUMED       | MISC              | N       | NONE        | 0               |              |                               | ACBM with the potential for damage |               | MODERATE              |
| 186   | 12x12 Red w/specks VFT Mastic                      | 400               | SF             | Health center (144)   | ASSUMED       | MISC              | N       | NONE        | 0               |              |                               | ACBM with the potential for damage |               | LOW                   |
| 187   | 12x12 Yellow w/streaks VFT                         | 400               | SF             | Health center (144)   | ASSUMED       | MISC              | N       | NONE        | 0               |              |                               | ACBM with the potential for damage |               | MODERATE              |
| 188   | 12x12 Yellow w/streaks VFT Mastic                  | 400               | SF             | Health center (144)   | ASSUMED       | MISC              | N       | NONE        | 0               |              |                               | ACBM with the potential for damage |               | LOW                   |
| 189   | 12x12 Green w/ streaks VFT                         | 200               | SF             | Health center (144)   | ASSUMED       | MISC              | N       | NONE        | 0               |              |                               | ACBM with the potential for damage |               | MODERATE              |
| 190   | 12x12 Green w/ streaks VFT Mastic                  | 200               | SF             | Health center (144)   | ASSUMED       | MISC              | N       | NONE        | 0               |              |                               | ACBM with the potential for damage |               | LOW                   |
| 191   | 12x12 Dark gray linoleum w/ granite pattern        | 2,000             | SF             | Main office (131-134)   | ASSUMED       | MISC              | N       | NONE        | 0               |              |                               | ACBM with the potential for damage |               | MODERATE              |
| 192   | 12x12 Dark gray linoleum w/ granite pattern Mastic | 2,000             | SF             | Main office (131-134)   | ASSUMED       | MISC              | N       | NONE        | 0               |              |                               | ACBM with the potential for damage |               | LOW                   |
| 193   | 12x12 Pink w/ maroon specks VFT                    | 1,200             | SF             | Room 115  | ASSUMED       | MISC              | N       | NONE        | 0               |              |                               | ACBM with the potential for damage |               | MODERATE              |

# Chicago Public Schools

School Senn Academy Unit 47061 Building ID 1540

Address 5900 N. Glenwood Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

*Inspector's Comments are Summarized at the End of the Report*

| HA No | Material Description                            | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category | Damage Category                    | Damage Reason | Disturbance Potential |
|-------|---|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|------------------------------------|---------------|-----------------------|
| 194   | 12x12 Pink w/ maroon specks VFT Mastic          | 1,200             | SF             | Room 115  | ASSUMED       | MISC              | N       | NONE        | 0               |              |                               | ACBM with the potential for damage |               | LOW                   |
| 195   | 12x12 Maroon w/ pink specks VFT                 | 200               | SF             | Room 115  | ASSUMED       | MISC              | N       | NONE        | 0               |              |                               | ACBM with the potential for damage |               | MODERATE              |
| 196   | 12x12 Maroon w/ pink specks VFT Mastic          | 200               | SF             | Room 115  | ASSUMED       | MISC              | N       | NONE        | 0               |              |                               | ACBM with the potential for damage |               | LOW                   |
| 20    | Mudded Joint Packing on Aircell Pipe Insulation | 603               | LF             | Mixing Room, 219, 319, Auditorium Crawlspace - 1912; Room 120A                                | CHR           | TSI               | Y       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | MODERATE              |
| 25    | Insulation in Vault Door                        | 28                | SF             | 1893 Building: Office   | ASSUMED       | TSI               | Y       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 26    | Mudded Joint Packing on Aircell Insulation      | 300               | LF             | Room 238 Chase, Autoshop, Autoshop Tool Room - 1931   | CHR           | TSI               | Y       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 27    | Aircell Pipe Insulation                         | 1,000             | LF             | Corridor by Main Corridor (N), Room 238 Chase, Room 140, Autoshop & Autoshop Tool Room - 1931 | CHR           | TSI               | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 30    | Aircell Pipe Insulation                         | 2,600             | LF             | Rooms 219, 319, & Auditorium Crawlspace - 1912  | CHR           | MISC              | Y       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 33    | Paperwrap Pipe Insulation                       | 400               | LF             | Auditorium Crawlspace - 1912  | CHR           | TSI               | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 34    | MJP E/F/V on Paperwrap Pipe Insulation          | 50                | LF             | Auditorium Crawlspace - 1912  | CHR           | TSI               | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 39    | Hard Coat Plaster                               |                   |                | Throughout - 1912   | NO_ACBM       |                   |         |             |                 |              | No                            |                                    |               |                       |
| 40    | Hard Coat Plaster                               |                   |                | Throughout - 1931   | NO_ACBM       |                   |         |             |                 |              | No                            |                                    |               |                       |
| 55    | 12"x12" Tan w/Speckles VFT                      | 5,000             | SF             | 3rd Floor Corridor (N), 326, 233, 227, 225 (Library) - 1912                                   | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | MODERATE              |
| 56    | 9"x9" Brown w/Sreaks VFT Mastic- NOT OBSERVED   | 500               | SF             | Rm. 356   | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 57    | 12"x12" Tan W/Speckles VFT Mastic               | 5,000             | SF             | 3rd Floor Corridor (N), 326, 233, 227, 225 (Library) - 1912                                   | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 60    | 9"x9" Maroon VFT                                | 2,100             | SF             | 3rd Floor Hall (S&N), 2nd Floor Hall (N) -1931 Bldg.  | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 61    | 9"x9" Maroon VFT Mastic                         | 2,100             | SF             | 3rd Floor Hall (S&N), 2nd Floor Hall (N) -1931 Bldg.  | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |

# Chicago Public Schools

School Senn Academy Unit 47061 Building ID 1540

Address 5900 N. Glenwood Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

*Inspector's Comments are Summarized at the End of the Report*

| HA No | Material Description   | Material Quantity | Material Units | Material Location                                    | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category | Damage Category                    | Damage Reason | Disturbance Potential |
|-------|--|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|------------------------------------|---------------|-----------------------|
| 62    | 9"x9" Brown w/Streaks VFT NOT OBSERVED                         | 500               | SF             | Rm. 356 NOT OBSERVED                                 | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | MODERATE              |
| 64    | 12"x12" Light Brown w/ White Streaks VFT (Not Observed)        | 200               | SF             | Rooms 100, 106, & 106 Office - 1931                  | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | MODERATE              |
| 65    | 12"x12" Light Brown w/ White Streaks VFT Mastic (Not Observed) | 200               | SF             | Rooms 100, 106, & 106 Office - 1931                  | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | MODERATE              |
| 66    | 9"x9" Black VFT  | 2,000             | SF             | 3rd Floor Hall (S&N), 2nd Floor Hall (N) -1931 Bldg. | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | MODERATE              |
| 67    | 9"x9" Black VFT Mastic   | 2,000             | SF             | 3rd Floor Hall (S&N), 2nd Floor Hall (N) -1931 Bldg. | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 68    | 9"x9" Black w/Large White Streaks VFT                          | 2,000             | SF             | 3rd Floor Hall (S&N) - 1931                          | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | MODERATE              |
| 69    | 9"x9" Black w/Large White Streaks VFT Mastic                   | 2,000             | SF             | 3rd Floor Hall (S&N) - 1931                          | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 70    | 9"x9" Brown w/Large White Streaks VFT                          | 2,000             | SF             | 3rd Floor Hall (S&N), 2nd Floor Hall (N) -1931 Bldg. | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | MODERATE              |
| 71    | 9"x9" Brown w/Large White Streaks VFT Mastic                   | 2,000             | SF             | 3rd Floor Hall (S&N), 2nd Floor Hall (N) -1931 Bldg. | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 72    | 9"x9" Orange w/White VFT                                       | 2,000             | SF             | 3rd Floor Hall (S&N), 2nd Floor Hall (S) -1931 Bldg. | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage | 3             | MODERATE              |
| 73    | 9"x9" Orange w/White Streaks VFT Mastic                        | 2,000             | SF             | 3rd Floor Hall (S&N), 2nd Floor Hall (S) -1931 Bldg. | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 76    | 9"x9" Maroon w/ White Streaks VFT                              | 1,200             | SF             | 2nd Floor Hall (S) - 1931 Bldg.                      | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | MODERATE              |
| 77    | 9"x9" Maroon w/ White Streaks VFT Mastic                       | 1,200             | SF             | 2nd Floor Hall (S) - 1931 Bldg.                      | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 78    | 9"x9" Black w/ Faint White Streaks VFT                         | 3,000             | SF             | 2nd & 3rd Floor Halls (N&S) - 1931                   | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | MODERATE              |
| 79    | 9"x9" Black w/ Faint White Streaks VFT Mastic                  | 3,000             | SF             | 2nd & 3rd Floor Halls (N&S) - 1931                   | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 80    | 12"x12" White w/ Brown Speckles VFT                            | 1,200             | SF             | Room 341 & 213 - 1931                                | ASSUMED       | MISC              | N       | NONE        | 0               |              |                               | ACBM with the potential for damage |               | MODERATE              |
| 81    | 12"x12" White w/ Brown Speckles VFT Mastic                     | 1,200             | SF             | Room 341 & 213 - 1931                                | ASSUMED       | MISC              | N       | NONE        | 0               |              |                               | ACBM with the potential for damage |               | MODERATE              |
| 86    | 12"x12" Brown w/ Light Brown Speckles VFT                      | 600               | SF             | Room 239 - 1931                                      | ASSUMED       | MISC              | N       | NONE        | 0               |              |                               | ACBM with the potential for damage |               | MODERATE              |
| 87    | 12"x12" Brown w/ Light Brown Speckles VFT Mastic               | 600               | SF             | Room 239 - 1931                                      | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |



# Chicago Public Schools

School Senn Academy Unit 47061 Building ID 1540

Address 5900 N. Glenwood Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

*Inspector's Comments are Summarized at the End of the Report*

| HA No | Material Description   | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category | Damage Category                    | Damage Reason | Disturbance Potential |
|-------|--|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|------------------------------------|---------------|-----------------------|
| 88    | Brown Linoleum   | 250               | SF             | 238 North Storage - 1931   | ASSUMED       | MISC              | N       | NONE        | 0               |              |                               | ACBM with the potential for damage |               | MODERATE              |
| 89    | Green Linoleum (Not Observed)                                    | 5,500             | SF             | Main Gym, Office & Locker - 1931                                 | ASSUMED       | MISC              | N       | NONE        | 0               |              | Yes                           | ACBM with the potential for damage |               | LOW                   |
| 90    | 12"x12" Peach w/ Speckles VFT- NOT OBSERVED                      | 700               | SF             | Rooms 352, 379, 350 Storage - 1912                               | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 91    | 12"x12" Peach w/ Speckles VFT Mastic- NOT OBSERVED               | 700               | SF             | Rooms 352, 379, 350 Storage - 1912                               | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 92    | 12"x12" Light Brown w/ Dark Speckles VFT- NOT OBSERVED           | 700               | SF             | Room 355, 373, 375 - 1912  | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 93    | 12"x12" Light Brown w/ Dark Speckles VFT Mastic- NOT OBSERVED    | 700               | SF             | Room 355, 373, 375 - 1912  | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 94    | 12"x12" Beige w/ Dark Speckles VFT                               | 2,000             | SF             | 3rd Floor Corridors, 364 Storage, 223, 221, 117B - 1912          | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 95    | 12"x12" Beige w/ Dark Speckles VFT Mastic                        | 2,000             | SF             | 3rd Floor Corridors, 364 Storage, 223, 221, 117B - 1912          | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 96    | 12"x12" DK Brown w/White & Dark Streaks VFT- NOT OBSERVED        | 1,900             | SF             | 3rd Floor Corridors, 223, 221, 117B - 1912                       | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 97    | 12"x12" DK Brown w/White & Dark Streaks VFT Mastic- NOT OBSERVED | 1,900             | SF             | 3rd Floor Corridors, 223, 221, 117B - 1912                       | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| 98    | 12"x12" Black w/ White Speckles VFT- NOT OBSERVED                | 250               | SF             | 3rd Floor Corridor (N) - 1912                                    | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | MODERATE              |
| 99    | 12"x12" Black w/ White Speckles VFT Mastic- NOT OBSERVED         | 250               | SF             | 3rd Floor Corridor (N) - 1912                                    | CHR           | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| AA    | 12" x 12" green floor tile- NOT OBSERVED                         |                   |                | 3rd floor, side corridor, East to West navy areas                | ASSUMED       |                   |         | None        |                 |              | No                            |                                    |               |                       |
| BB    | Mastic associated with HA AA - NOT OBSERVED                      | 0                 | SF             | 3rd floor, side corridor, East to West navy areas - NOT OBSERVED | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| CC    | Lab counter tops   | 3,500             | SF             | classrooms 100, 106, 108, 110, 302, 310, 350                     | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| DD    | Lab tables   | 2,600             | SF             | Classrooms, 110, 302, 310, 350                                   | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |
| EE    | lab fume hoods   | 750               | SF             | Classrooms 100,106, 350  | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |

# Chicago Public Schools

School Senn Academy Unit 47061 Building ID 1540

Address 5900 N. Glenwood Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

*Inspector's Comments are Summarized at the End of the Report*

|   |
|---|
| Reinspection Date <b>3/16/2016</b>                |
| Inspector Name <b>David Avila</b>                 |
| <b>100-11093</b> <b>5/15/2017</b>                 |
| Inspector's IDPH License Number / Expiration Date |

### Inspector's Comments

| HA Number: | Inspector Comments:                           |
|------------|---|
| 01         |   |
| 02         |   |
| 03         |   |
| 04         |   |
| 05         |   |
| 06         |   |
| 09         |   |
| 10         |   |
| 100        |   |
| 1000       |   |
| 1001       |   |
| 101        |   |
| 102        |   |
| 103        |   |
| 104        |   |
| 105        |   |
| 106        | Not Observed in Rooms 131, 132, 133, 134, 135 |
| 107        | Not Observed in Rooms 131, 132, 133, 134, 135 |
| 108        |   |
| 109        |   |
| 110        |   |
| 111        |   |
| 112        |   |
| 113        |   |

# Chicago Public Schools

School Senn Academy Unit 47061 Building ID 1540

Address 5900 N. Glenwood Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

*Inspector's Comments are Summarized at the End of the Report*

---

| HA Number: | Inspector Comments: |
|------------|---------------------|
| 114        |                     |
| 115        |                     |
| 116        |                     |
| 117        |                     |
| 118        |                     |
| 119        |                     |
| 120        |                     |
| 121        |                     |
| 122        |                     |
| 123        |                     |
| 124        |                     |
| 125        |                     |
| 126        |                     |
| 127        |                     |
| 127 A      |                     |
| 128        |                     |
| 128 A      |                     |
| 13         |                     |
| 133        |                     |
| 134        |                     |
| 135        |                     |
| 136        |                     |
| 137        |                     |
| 138        |                     |
| 139        |                     |
| 14         |                     |
| 140        |                     |
| 141        |                     |
| 142        |                     |

# Chicago Public Schools

School Senn Academy Unit 47061 Building ID 1540

Address 5900 N. Glenwood Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

*Inspector's Comments are Summarized at the End of the Report*

---

| HA Number: | Inspector Comments: |
|------------|---------------------|
| 143        |                     |
| 144        |                     |
| 145        |                     |
| 146        |                     |
| 147        |                     |
| 148        |                     |
| 148M       |                     |
| 149        |                     |
| 149M       |                     |
| 150        |                     |
| 150M       |                     |
| 151        |                     |
| 151M       |                     |
| 152        |                     |
| 152M       |                     |
| 153        |                     |
| 153M       |                     |
| 154M       |                     |
| 155        |                     |
| 155M       |                     |
| 156        |                     |
| 156A       |                     |
| 157        |                     |
| 158        |                     |
| 159        |                     |
| 160        |                     |
| 161        |                     |
| 162        |                     |
| 163        |                     |

# Chicago Public Schools

School Senn Academy Unit 47061 Building ID 1540

Address 5900 N. Glenwood Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

*Inspector's Comments are Summarized at the End of the Report*

---

| HA Number: | Inspector Comments:               |
|------------|-----------------------------------|
| 164        | Not Observed: 119, South Corridor |
| 164A       | Not Observed: 119, South Corridor |
| 165        | No                                |
| 165A       |                                   |
| 166        |                                   |
| 166A       |                                   |
| 167        | Not Observed: Room 166            |
| 167A       | Not Observed: Room 166            |
| 168        |                                   |
| 169        |                                   |
| 170        |                                   |
| 171        |                                   |
| 172        |                                   |
| 173        |                                   |
| 174        |                                   |
| 175        |                                   |
| 176        |                                   |
| 177        |                                   |
| 178        |                                   |
| 179        |                                   |
| 180        |                                   |
| 181        |                                   |
| 182        |                                   |
| 183        |                                   |
| 184        |                                   |
| 185        |                                   |
| 186        |                                   |
| 187        |                                   |
| 188        |                                   |

# Chicago Public Schools

School Senn Academy Unit 47061 Building ID 1540

Address 5900 N. Glenwood Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

*Inspector's Comments are Summarized at the End of the Report*

---

| HA Number: | Inspector Comments: |
|------------|---------------------|
| 189        |                     |
| 190        |                     |
| 191        |                     |
| 192        |                     |
| 193        |                     |
| 194        |                     |
| 195        |                     |
| 196        |                     |
| 20         |                     |
| 25         |                     |
| 26         |                     |
| 27         |                     |
| 30         |                     |
| 33         |                     |
| 34         |                     |
| 39         |                     |
| 40         |                     |
| 55         |                     |
| 56         |                     |
| 57         |                     |
| 60         |                     |
| 61         |                     |
| 62         |                     |
| 64         |                     |
| 65         |                     |
| 66         |                     |
| 67         |                     |
| 68         |                     |
| 69         |                     |

# Chicago Public Schools

School Senn Academy Unit 47061 Building ID 1540

Address 5900 N. Glenwood Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

*Inspector's Comments are Summarized at the End of the Report*

---

| HA Number: | Inspector Comments:                              |
|------------|--|
| 70         |  |
| 71         |  |
| 72         |  |
| 73         |  |
| 76         |  |
| 77         |  |
| 78         |  |
| 79         |  |
| 80         |  |
| 81         |  |
| 86         |  |
| 87         |  |
| 88         |  |
| 89         |  |
| 90         |  |
| 91         |  |
| 92         |  |
| 93         |  |
| 94         | Not Observed: Room 223, 117B, 3rd Floor Corridor |
| 95         | Not Observed: Room 223, 117B, 3rd Floor Corridor |
| 96         |  |
| 97         |  |
| 98         |  |
| 99         |  |
| AA         |  |
| BB         |  |
| CC         |  |
| DD         |  |
| EE         |  |

# Chicago Public Schools

**School** Senn Academy **Unit** 47061 **Building ID** 1540

**Address** 5900 N. Glenwood **Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

*Inspector's Comments are Summarized at the End of the Report*

---



**Table II**

**Management Planner's Review**

---

# Chicago Public Schools

**School** Senn Academy  
**Address** 5900 N. Glenwood

**Unit** 47061  
Chicago, IL, 60660

**Building ID** 1540  
**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

### *Management Planner's Comments Summarized at the End of the Report*

| HA Num | Material Description                                | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Quantity | Damage Units | Damage Category                      | Response        |
|--------|---|-------------------|----------------|---|---------------|-------------------|---------|-----------------|--------------|--------------------------------------|-----------------|
| 01     | Boiler Lagging (ABATED 2010)                        |                   |                | Boiler # 1 - 1931   | Abated        | TSI               |         |                 |              |                                      |                 |
| 02     | Boiler Lagging (ABATED 2010)                        |                   |                | Boiler # 2 - 1931   | Abated        | TSI               |         |                 |              |                                      |                 |
| 03     | Boiler Lagging (ABATED 2010)                        |                   |                | Boiler # 3 - 1931   | Abated        | TSI               |         |                 |              |                                      |                 |
| 04     | Boiler Lagging (ABATED 2010)                        |                   |                | Boiler # 4 - 1931   | Abated        | TSI               |         |                 |              |                                      |                 |
| 05     | Boiler Gasket (ABATED 2010)                         |                   |                | Boiler # 1 - 1931   | Abated        | TSI               |         |                 |              |                                      |                 |
| 06     | Boiler Gasket (ABATED 2010)                         |                   |                | Boiler # 2 - 1931   | Abated        | TSI               |         |                 |              |                                      |                 |
| 09     | MJP on Fiberglass Pipe Insulation                   | 600               | LF             | Throughout - 1912 (See Hatching Maps)   | Chrysotile    | TSI               | Yes     | 0               | LF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 10     | MJP on Fiberglass Pipe Insulation                   | 425               | LF             | ROTC Rm, Boiler & Pump Rms, Main Tunnel, 2nd & 3rd Flr S JC Chase, 2nd Flr Boy Tol (N) - 1931; 3rd Floor Unisex Toilet.; 1st Floor Janitor's Closet; ; Under Sinks in Rms 310, 352, and 366; BookRoom Between Rm 315 and 317; Mens Rm Next to Rm 322. | Chrysotile    | TSI               | Yes     | 0               | LF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 100    | 9"x9" Red w/ White Streaks VFT- NOT OBSERVED        | 300               | SF             | 115 Kitchen - 1912  | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage |                 |
| 1000   | 12"x12" orange/brown VFT- NOT OBSERVED              | 24                | SF             | Rm 180 wooden stage   | Chrysotile    | MISC              | Yes     | 0               | SF           | 6 ACBM with the potential for damage |                 |
| 1001   | 12"x12" orange/brown VFT black mastic- NOT OBSERVED | 24                | SF             | Rm 180 wooden stage   | Chrysotile    | MISC              | Yes     | 0               | SF           | 6 ACBM with the potential for damage |                 |
| 101    | 9"x9" Red w/ White Streaks VFT Mastic- NOT OBSERVED | 300               | SF             | 115 Kitchen - 1912  | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage |                 |
| 102    | 9"x9" Gray w/ White Streaks VFT                     | 800               | SF             | Rooms 117A - 1912   | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 103    | 9"x9" Gray w/ White Streaks VFT Mastic              | 800               | SF             | Rooms 117A - 1912   | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 104    | 12"x12" Light Green w/ White Streaks VFT            | 350               | SF             | Room 123A - 1912  | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 105    | 12"x12" Light Green w/ White Streaks VFT Mastic     | 350               | SF             | Room 123A - 1912  | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 106    | 12"x12" Beige w/ Dark & White Streaks VFT           | 6,100             | SF             | Rooms 127, 129, 131, 132, 133, 134, 137, 139, 135, 190, 239 - 1912  | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 107    | 12"x12" Beige w/ Dark & White Streaks VFT Mastic    | 6,100             | SF             | Rooms 127, 129, 131, 132, 133, 134, 137, 139, 135, 190, 239 - 1912  | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 108    | 9"x9" Lt. Brown w/ Dark Red Streaks VFT             | 455               | SF             | Teacher Lunchroom/Lounge - 1912; Rms 300 (under sink), 310 (lab vault)  | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 109    | 9"x9" Lt. Brown w/ Dark Red Streaks VFT Mastic      | 455               | SF             | Teacher Lunchroom/Lounge - 1912; Rms 300 (under sink), 310 (lab vault)  | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 110    | 9"x9" Green w/ White Streaks VFT                    | 300               | SF             | Teacher Lunchroom/Lounge - 1912   | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 111    | 9"x9" Green w/ White Streaks VFT Mastic             | 300               | SF             | Teacher Lunchroom/Lounge - 1912   | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |

# Chicago Public Schools

School Senn Academy  
Address 5900 N. Glenwood

Unit 47061  
Chicago, IL, 60660

Building ID 1540  
Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

### Management Planner's Comments Summarized at the End of the Report

| HA Num | Material Description  | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Quantity | Damage Units | Damage Category                      | Response        |
|--------|---|-------------------|----------------|---|---------------|-------------------|---------|-----------------|--------------|--------------------------------------|-----------------|
| 112    | 12"x12" Lt. Brown w/ Gray Speckles VFT                        | 80                | SF             | 153 Vest., 120 Vest. - 1912                               | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 113    | 12"x12" Lt. Brown w/ Gray Speckles VFT Mastic                 | 80                | SF             | 153 Vest., 120 Vest. - 1912                               | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 114    | 12"x12 Beige w/ Brown Streaks VFT- NOT OBSERVED               | 1,400             | SF             | Rooms 166, & 162 - 1912                                   | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage |                 |
| 115    | 12"x12 Beige w/ Brown Streaks VFT Mastic- NOT OBSERVED        | 1,400             | SF             | Rooms 166, & 162 - 1912                                   | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage |                 |
| 116    | 12"x12" Blue-Gray w/ White Streaks VFT                        | 500               | SF             | Room 373- 1912  | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 117    | 12"x12" Blue-Gray w/ White Streaks VFT Mastic                 | 500               | SF             | Room 373- 1912  | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 118    | 12"x12" Dk Gray w/ Beige Streaks VFT- NOT OBSERVED            | 2,000             | SF             | Rooms 176, 174, 180 - 1912                                | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage |                 |
| 119    | 12"x12" Dk Gray w/ Beige Streaks VFT Mastic- NOT OBSERVED     | 2,000             | SF             | Rooms 176, 174, 180 - 1912                                | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage |                 |
| 120    | 12"x12" Lt Gray w/ White Speckles VFT- NOT OBSERVED           | 2,000             | SF             | Rooms 176, 174, 180 - 1912                                | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage |                 |
| 121    | 12"x12" Lt Gray w/ White Speckles VFT Mastic- NOT OBSERVED    | 2,000             | SF             | Rooms 176, 174, 180 - 1912                                | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage |                 |
| 122    | 12"x12" Brown VFT- NOT OBSERVED                               | 0                 | SF             | Stage - 1912  | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage |                 |
| 123    | 12"x12" Brown VFT Mastic- NOT OBSERVED                        | 0                 | SF             | Stage - 1912  | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage |                 |
| 124    | 2'x2' Black Border VFT  | 15                | SF             | 115 Kitchen - 1912  | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 125    | 2'x2' Black Border VFT Mastic- NOT OBSERVED                   | 15                | SF             | 115 Kitchen - 1912  | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage |                 |
| 126    | 2'x2' Ceiling Tile- NOT OBSERVED                              | 1,700             | SF             | Room 425, & 326 - 1912                                    | Chrysotile    | MISC              | Yes     | 0               | SF           | 6 ACBM with the potential for damage |                 |
| 127    | 12"x12" White w/Beige Streaks VFT- NOT OBSERVED               | 1,000             | SF             | Room 377  | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage |                 |
| 127 A  | 12"x12" White w/Beige Streaks VFT Mastic- NOT OBSERVED        | 1,000             | SF             | Room 377  | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage |                 |
| 128    | 12"x12" White w/Blue Streaks VFT                              | 880               | SF             | Room 351  | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 128 A  | 12 x 12 inch White w/blue Streaks VFT Mastic                  | 880               | SF             | Room 351  | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 13     | MJP on Paperwrap Pipe Insulation; 2nd Floor Janitor's Closet. | 370               | LF             | 1st Floor South JC, 238 Chase, 188, Autoshop - 1931 bldg. | Chrysotile    | TSI               | Yes     | 0               | LF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 133    | Lt Blue Speckled Linoleum- NOT OBSERVED                       | 800               | SF             | Room 356 - 1912; Room 326                                 | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage |                 |
| 134    | Lt Blue Speckled Linoleum Mastic- NOT OBSERVED                | 800               | SF             | Room 356 - 1912; Room 326                                 | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage |                 |
| 135    | 12"x12" White w/ Gold Specks VFT- NOT OBSERVED                | 1,000             | SF             | Rooms 174, 176, & 180 - 1911                              | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage |                 |
| 136    | 12"x12" White w/ Gold Specks VFT Mastic- NOT OBSERVED         | 1,000             | SF             | Rooms 174, 176, & 180 - 1911                              | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage |                 |

# Chicago Public Schools

**School** Senn Academy  
**Address** 5900 N. Glenwood

**Unit** 47061  
Chicago, IL, 60660

**Building ID** 1540  
**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

### Management Planner's Comments Summarized at the End of the Report

| HA Num | Material Description                        | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Quantity | Damage Units | Damage Category                      | Response        |
|--------|---|-------------------|----------------|---|---------------|-------------------|---------|-----------------|--------------|--------------------------------------|-----------------|
| 137    | 2'x4' White Pin-Hole Ceiling Tile           | 1,000             | SF             | Room 356 - 1912   | Assumed       | MISC              | Yes     | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 138    | 12"x12" White w/ Beige VFT                  | 2,000             | SF             | 310 & Office, 302, 108, 110 - 1931  | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 139    | 12"x12" White w/ Beige VFT Mastic           | 2,000             | SF             | 310 & Office, 302, 108, 110 - 1931  | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 14     | Paperwrap Pipe Insulation                   | 300               | LF             | ROTC Room, 1st Floor South JC, 238 Chase, 188, Autoshop - 1931 bldg.                        | Chrysotile    | TSI               | Yes     | 0               | LF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 140    | 12"x12" Light Gray VFT- NOT OBSERVED        | 0                 | SF             | 210, & Engineer's Office - 1931   | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage |                 |
| 141    | 12"x12" Light Gray VFT Mastic- NOT OBSERVED | 0                 | SF             | 210, & Engineer's Office - 1931   | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage |                 |
| 142    | 12"x12" Light Blue VFT                      | 900               | SF             | 210, 195A & Engineer's Office - 1931  | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 143    | 12"x12" Light Blue VFT Mastic               | 900               | SF             | 210, 195A & Engineer's Office - 1931  | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 144    | 12"x12" Green VFT                           | 300               | SF             | 1st Floor Hall (N&S) - 1931   | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 145    | 12"x12" Green VFT Mastic                    | 300               | SF             | 1st Floor Hall (N&S) - 1931   | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 146    | 12"x12" White VFT                           | 1,000             | SF             | 1st Floor Hall (N&S) - 1931   | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 147    | 12"x12" White VFT Mastic                    | 1,000             | SF             | 1st Floor Hall (N&S) - 1931   | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 148    | Linoleum, Gray w/Gray Streaks               | 3,500             | SF             | Rooms 350, 352, 356 Vault, and 306  | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 148M   | Linoleum, Gray w/Gray Streaks Mastic        | 3,500             | SF             | Rooms 350, 352, 356 Vault, and 306  | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 149    | Linoleum, Blue Solid (Not Observed)         | 2,000             | SF             | Rms 100, 106, and 106 Office  | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage |                 |
| 149M   | Linoleum, Blue Solid Mastic (Not Observed)  | 2,000             | SF             | Rms 100, 106, and 106 Office  | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage |                 |
| 150    | 12"X12" VFT-- NOT OBSERVED                  | 200               | SF             | 3rd Floor Side Corridor, SE to West Naval Area, Border Along N. and S. Walls - NOT OBSERVED | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage |                 |
| 150M   | 12"X12" VFT Mastic - NOT OBSERVED           | 200               | SF             | 3rd Floor Side Corridor, SE to West Naval Area, Border Along N. and S. Walls - NOT OBSERVED | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage |                 |
| 151    | Solid Gray                                  | 800               | SF             | 3rd Floor Side Corridor, SE to West Naval Area, Center of Corridor                          | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 151M   | Solid Gray Mastic                           | 800               | SF             | 3rd Floor Side Corridor, SE to West Naval Area, Center of Corridor                          | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 152    | Tan w/Brown Speckles                        | 800               | SF             | 3rd Floor Side Corridor-North,Runs East-to-West in Naval Area, Center of Corridor           | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 152M   | Tan w/Brown Speckles Mastic                 | 800               | SF             | 3rd Floor Side Corridor-North,Runs East-to-West in Naval Area, Center of Corridor           | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 153    | 12"X12" White w/ Tan Speckles VFT           | 200               | SF             | 3rd Floor Side Corridor-North,Runs East-to-West in Naval Area, Border Along N. and S. Walls | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |

# Chicago Public Schools

School Senn Academy  
Address 5900 N. Glenwood

Unit 47061  
Chicago, IL, 60660

Building ID 1540  
Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

### Management Planner's Comments Summarized at the End of the Report

| HA Num | Material Description                            | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Quantity | Damage Units | Damage Category                      | Response        |
|--------|---|-------------------|----------------|--|---------------|-------------------|---------|-----------------|--------------|--------------------------------------|-----------------|
| 153M   | 12"X12" White w/ Tan Speckles VFT Mastic        | 200               | SF             | 3rd Floor Side Corridor-North,Runs East-to-West in Naval Area, Border Along N. and S. Walls  | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 154M   | Gold, Blue Carpet                               | 3,800             | SF             | Rms 379, 375, 326, 315, and 272(not observed)  | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 155    | Linoleum, White w/Gray Streaks                  | 750               | SF             | Rm 352   | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 155M   | Linoleum, White w/Gray Streaks Mastic           | 750               | SF             | Rm 352   | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 156    | 12"x12" light gray w/ gray and white specks VFT | 600               | SF             | Room 377   | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 156A   | 12"x12" light gray w/ gray specks VFT MASTIC    | 600               | SF             | Room 377   | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 157    | 2'x4' smooth CT                                 | 700               | SF             | Room 351   | Assumed       | MISC              | Yes     | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 158    | 1'x1' CT w/ grooves                             | 2,600             | SF             | Room 320, 425- 1911 bldg   | Assumed       | MISC              | Yes     | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 159    | 1'x1' CT w/ grooves above HA 161                | 1,000             | SF             | Room 108, 148, 149, 146  | Assumed       | MISC              | Yes     | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 160    | 2'x4' CT w/ grooves                             | 22,000            | SF             | Bldg 1930- South wing except women's toilet and 213- 2nd fl. 2nd fl. north wing except boys toilet. 1st fl. south wing except for girls' toilet and engineer room. 1st fl. south wing hallway and rm 145. 3rd fl all south wing except for 306, 313, 315 and women's toilet. 3rd fl all north wing except for room 341, 335, 333 and men's toilet.   | Assumed       | MISC              | Yes     | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 161    | 2'x4' CT w/ grooves                             | 45,000            | SF             | Bldg 1911- Hallway from 319-335 and rooms 350, 353, 322, 326, 328, 330, 332, 334, 335, 325, 319, 358, 363, 367, 369, 373, 375, 379, 372, 374, 378, 380, 376, 258, 260, 261, 262, 264, 234, 266, 272, 276, 278, 273, 275, 277, 281, 222, 219, 221, 227, 231, 233, 230, 236. 2nd fl. hallway from room 319-335. 134, 132, 123A, 123, 121, 172, 174, 176, main office. 1st floor from 119- conference room and rooms 158, 160, 162, 166 | Assumed       | MISC              | Yes     | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 162    | 2'x4' CT pinhole                                | 13,000            | SF             | 1911 bldg- 1st fl. hallway from room 158-180 and from heat chamber 3- heat chamber 8. 2nd fl hallway from  | Assumed       | MISC              | Yes     | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |

# Chicago Public Schools

School Senn Academy  
Address 5900 N. Glenwood

Unit 47061  
Chicago, IL, 60660

Building ID 1540  
Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

### Management Planner's Comments Summarized at the End of the Report

| HA Num | Material Description  | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Quantity | Damage Units | Damage Category                      | Response        |
|--------|---|-------------------|----------------|---|---------------|-------------------|---------|-----------------|--------------|--------------------------------------|-----------------|
|        |   |                   |                | room 258-280 and hallway along side of auditorium. 3rd fl hallway from room 350-361-380 and from room 369-328 and classrooms 352,364,366. |               |                   |         |                 |              |                                      |                 |
| 163    | 2'x4 CT pinholes  | 4,500             | SF             | Corridor- 1930 bldg. from pump room- room 184, kitchen, cafeteria   | Assumed       | MISC              | Yes     | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 164    | 12"x12" Tan w/ light brown specks VFT                       | 1,600             | SF             | 119, 121, South corridor- 1912  | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 164A   | 12"x12" Tan w/ light brown specks VFT MASTIC                | 1,600             | SF             | 119, 121, South corridor- 1912  | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 165    | 9"x9" brown w/ yellow design VFT (Not Observed)             | 100               | SF             | Room 123- 1911 bldg   | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage |                 |
| 165A   | 9"x9" Brown w/ yellow design VFT MASTIC (Not Observed)      | 100               | SF             | Room 123- 1911 bldg   | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage |                 |
| 166    | 12"x12" lt. blue w/ blue specks VFT                         | 500               | SF             | 2nd, 3rd Floor main center corridor, Health Center (144) 1912 bldg  | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 166A   | 12"x12" lt. blue w/ blue specks VFT MASTIC                  | 500               | SF             | 2nd, 3rd Floor main center corridor, Health Center (144) 1912 bldg  | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 167    | 12"x12" white w/light blue, gray and yellow specks VFT      | 7,000             | SF             | 2nd, 3rd Floor main center corridor, Health Center (144), 162, 166 1912 bldg  | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 167A   | 12"x12" white w/ lt blue, gray and yellow specks VFT MASTIC | 7,000             | SF             | 2nd, 3rd Floor main center corridor, Health Center (144), 162, 166 1912 bldg  | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 168    | Black lab table tops  | 700               | SF             | Room 358, 364, 367  | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 169    | Black lab counter tops                                      | 300               | SF             | Room 358, 364, 367  | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 170    | Blue linoleum with MASTIC                                   | 2,300             | SF             | Rooms 358, 364, 366   | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 171    | 12"x12" gray w/ tan streaks VFT w/ MASTIC                   | 400               | SF             | 170   | Assumed       | MISC              | No      | 40              | SF           | 6 ACBM with the potential for damage | Repair          |
| 172    | Decorative plaster  | 1,200             | SF             | Assembly hall, vestibule leading to assembly hall   | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 173    | Terrazzo  | 2,000             | SF             | Stairwells, 1st fl. corridor west of pump room- 1930 addition   | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 174    | Terrazzo  | 1,000             | SF             | Addition 1912- 1st fl corridors   | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 175    | 12x12 Blue speckled VFT                                     | 1,000             | SF             | 3rd Floor NW & W corridor, 2nd floor W & center corridor  | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 176    | 12x12 Blue speckled VFT Mastic                              | 1,000             | SF             | 3rd Floor NW & W corridor, 2nd floor W & center corridor  | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 177    | 12x12 Light Blue w/ Specks VFT                              | 8,000             | SF             | 3rd Floor NW & W corridor, 2nd floor W & center corridor -1911 Bldg   | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |

# Chicago Public Schools

School Senn Academy  
Address 5900 N. Glenwood

Unit 47061  
Chicago, IL, 60660

Building ID 1540  
Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

### Management Planner's Comments Summarized at the End of the Report

| HA Num | Material Description                               | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Quantity | Damage Units | Damage Category                      | Response        |
|--------|--|-------------------|----------------|---|---------------|-------------------|---------|-----------------|--------------|--------------------------------------|-----------------|
| 178    | 12x12 Light Blue w/ Specks VFT Mastic              | 8,000             | SF             | 3rd Floor NW & W corridor, 2nd floor W & center corridor -1911 Bldg                             | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 179    | 12x12 Gray w/streaks VFT                           | 900               | SF             | Room 221  | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 180    | 12x12 Gray w/streaks VFT Mastic                    | 900               | SF             | Room 221  | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 181    | Gray linoleum w/ granite pattern                   | 1,200             | SF             | Room 100  | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 182    | Gray linoleum w/ granite pattern Mastic            | 1,200             | SF             | Room 100  | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 183    | Gray linoleum                                      | 2,400             | SF             | Rooms 105, 105A, 110  | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 184    | Gray linoleum Mastic                               | 2,400             | SF             | Rooms 105, 105A, 110  | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 185    | 12x12 Red w/ streaks VFT                           | 400               | SF             | Health center (144)   | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 186    | 12x12 Red w/specks VFT Mastic                      | 400               | SF             | Health center (144)   | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 187    | 12x12 Yellow w/streaks VFT                         | 400               | SF             | Health center (144)   | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 188    | 12x12 Yellow w/streaks VFT Mastic                  | 400               | SF             | Health center (144)   | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 189    | 12x12 Green w/ streaks VFT                         | 200               | SF             | Health center (144)   | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 190    | 12x12 Green w/ streaks VFT Mastic                  | 200               | SF             | Health center (144)   | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 191    | 12x12 Dark gray linoleum w/ granite pattern        | 2,000             | SF             | Main office (131-134)   | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 192    | 12x12 Dark gray linoleum w/ granite pattern Mastic | 2,000             | SF             | Main office (131-134)   | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 193    | 12x12 Pink w/ maroon specks VFT                    | 1,200             | SF             | Room 115  | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 194    | 12x12 Pink w/ maroon specks VFT Mastic             | 1,200             | SF             | Room 115  | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 195    | 12x12 Maroon w/ pink specks VFT                    | 200               | SF             | Room 115  | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 196    | 12x12 Maroon w/ pink specks VFT Mastic             | 200               | SF             | Room 115  | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 20     | Mudded Joint Packing on Aircell Pipe Insulation    | 603               | LF             | Mixing Room, 219, 319, Auditorium Crawlspace - 1912; Room 120A                                  | Chrysotile    | TSI               | Yes     | 0               | LF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 25     | Insulation in Vault Door                           | 28                | SF             | 1893 Building: Office   | Assumed       | TSI               | Yes     | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 26     | Mudded Joint Packing on Aircell Insulation         | 300               | LF             | Room 238 Chase, Autosshop, Autosshop Tool Room - 1931   | Chrysotile    | TSI               | Yes     | 0               | LF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 27     | Aircell Pipe Insulation                            | 1,000             | LF             | Corridor by Main Corridor (N), Room 238 Chase, Room 140, Autosshop & Autosshop Tool Room - 1931 | Chrysotile    | TSI               | No      | 0               | LF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 30     | Aircell Pipe Insulation                            | 2,600             | LF             | Rooms 219, 319, & Auditorium Crawlspace - 1912  | Chrysotile    | MISC              | Yes     | 0               | LF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 33     | Paperwrap Pipe Insulation                          | 400               | LF             | Auditorium Crawlspace - 1912  | Chrysotile    | TSI               | No      | 0               | LF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 34     | MJP E/F/V on Paperwrap Pipe Insulation             | 50                | LF             | Auditorium Crawlspace - 1912  | Chrysotile    | TSI               | No      | 0               | LF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 39     | Hard Coat Plater                                   |                   |                | Throughout - 1912   | No ACBM       |                   |         |                 |              |                                      |                 |
| 40     | Hard Coat Plaster                                  |                   |                | Throughout - 1931   | No ACBM       |                   |         |                 |              |                                      |                 |
| 55     | 12"x12" Tan w/Speckles VFT                         | 5,000             | SF             | 3rd Floor Corridor (N), 326, 233, 227,  | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |

# Chicago Public Schools

**School** Senn Academy  
**Address** 5900 N. Glenwood

**Unit** 47061  
Chicago, IL, 60660

**Building ID** 1540  
**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

### *Management Planner's Comments Summarized at the End of the Report*

| HA Num | Material Description   | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Quantity | Damage Units | Damage Category                      | Response        |
|--------|--|-------------------|----------------|---|---------------|-------------------|---------|-----------------|--------------|--------------------------------------|-----------------|
|        |  |                   |                | 225 (Library) - 1912  |               |                   |         |                 |              |                                      |                 |
| 56     | 9"x9" Brown w/Sreaks VFT Mastic- NOT OBSERVED                  | 500               | SF             | Rm. 356   | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage |                 |
| 57     | 12"x12" Tan W/Speckles VFT Mastic                              | 5,000             | SF             | 3rd Floor Corridor (N), 326, 233, 227, 225 (Library) - 1912 | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 60     | 9"x9" Maroon VFT   | 2,100             | SF             | 3rd Floor Hall (S&N), 2nd Floor Hall (N) -1931 Bldg.        | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 61     | 9"x9" Maroon VFT Mastic  | 2,100             | SF             | 3rd Floor Hall (S&N), 2nd Floor Hall (N) -1931 Bldg.        | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 62     | 9"x9" Brown w/Streaks VFT NOT OBSERVED                         | 500               | SF             | Rm. 356 NOT OBSERVED  | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage |                 |
| 64     | 12"x12" Light Brown w/ White Streaks VFT (Not Observed)        | 200               | SF             | Rooms 100, 106, & 106 Office - 1931                         | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage |                 |
| 65     | 12"x12" Light Brown w/ White Streaks VFT Mastic (Not Observed) | 200               | SF             | Rooms 100, 106, & 106 Office - 1931                         | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage |                 |
| 66     | 9"x9" Black VFT  | 2,000             | SF             | 3rd Floor Hall (S&N), 2nd Floor Hall (N) -1931 Bldg.        | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 67     | 9"x9" Black VFT Mastic   | 2,000             | SF             | 3rd Floor Hall (S&N), 2nd Floor Hall (N) -1931 Bldg.        | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 68     | 9"x9" Black w/Large White Streaks VFT                          | 2,000             | SF             | 3rd Floor Hall (S&N) - 1931                                 | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 69     | 9"x9" Black w/Large White Streaks VFT Mastic                   | 2,000             | SF             | 3rd Floor Hall (S&N) - 1931                                 | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 70     | 9"x9" Brown w/Large White Streaks VFT                          | 2,000             | SF             | 3rd Floor Hall (S&N), 2nd Floor Hall (N) -1931 Bldg.        | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 71     | 9"x9" Brown w/Large White Streaks VFT Mastic                   | 2,000             | SF             | 3rd Floor Hall (S&N), 2nd Floor Hall (N) -1931 Bldg.        | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 72     | 9"x9" Orange w/White VFT                                       | 2,000             | SF             | 3rd Floor Hall (S&N), 2nd Floor Hall (S) -1931 Bldg.        | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 73     | 9"x9" Orange w/White Streaks VFT Mastic                        | 2,000             | SF             | 3rd Floor Hall (S&N), 2nd Floor Hall (S) -1931 Bldg.        | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 76     | 9"x9" Maroon w/ White Streaks VFT                              | 1,200             | SF             | 2nd Floor Hall (S) -1931 Bldg.                              | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 77     | 9"x9" Maroon w/ White Streaks VFT Mastic                       | 1,200             | SF             | 2nd Floor Hall (S) -1931 Bldg.                              | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 78     | 9"x9" Black w/ Faint White Streaks VFT                         | 3,000             | SF             | 2nd & 3rd Floor Halls (N&S) - 1931                          | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 79     | 9"x9" Black w/ Faint White Streaks VFT Mastic                  | 3,000             | SF             | 2nd & 3rd Floor Halls (N&S) - 1931                          | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 80     | 12"x12" White w/ Brown Speckles VFT                            | 1,200             | SF             | Room 341 & 213 - 1931                                       | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 81     | 12"x12" White w/ Brown Speckles VFT Mastic                     | 1,200             | SF             | Room 341 & 213 - 1931                                       | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 86     | 12"x12" Brown w/ Light Brown Speckles VFT                      | 600               | SF             | Room 239 - 1931   | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 87     | 12"x12" Brown w/ Light Brown Speckles VFT                      | 600               | SF             | Room 239 - 1931   | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |



# Chicago Public Schools

**School** Senn Academy  
**Address** 5900 N. Glenwood

**Unit** 47061  
Chicago, IL, 60660

**Building ID** 1540  
**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

### Management Planner's Comments Summarized at the End of the Report

| HA Num | Material Description   | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Quantity | Damage Units | Damage Category                      | Response        |
|--------|--|-------------------|----------------|--|---------------|-------------------|---------|-----------------|--------------|--------------------------------------|-----------------|
|        | Mastic   |                   |                |  |               |                   |         |                 |              |                                      |                 |
| 88     | Brown Linoleum   | 250               | SF             | 238 North Storage - 1931   | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 89     | Green Linoleum (Not Observed)                                    | 5,500             | SF             | Main Gym, Office & Locker - 1931                                 | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage |                 |
| 90     | 12"x12" Peach w/ Speckles VFT- NOT OBSERVED                      | 700               | SF             | Rooms 352, 379, 350 Storage - 1912                               | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage |                 |
| 91     | 12"x12" Peach w/ Speckles VFT Mastic- NOT OBSERVED               | 700               | SF             | Rooms 352, 379, 350 Storage - 1912                               | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage |                 |
| 92     | 12"x12" Light Brown w/ Dark Speckles VFT- NOT OBSERVED           | 700               | SF             | Room 355, 373, 375 - 1912  | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage |                 |
| 93     | 12"x12" Light Brown w/ Dark Speckles VFT Mastic- NOT OBSERVED    | 700               | SF             | Room 355, 373, 375 - 1912  | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage |                 |
| 94     | 12"x12" Beige w/ Dark Speckles VFT                               | 2,000             | SF             | 3rd Floor Corridors, 364 Storage, 223, 221, 117B - 1912          | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 95     | 12"x12" Beige w/ Dark Speckles VFT Mastic                        | 2,000             | SF             | 3rd Floor Corridors, 364 Storage, 223, 221, 117B - 1912          | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 96     | 12"x12" DK Brown w/White & Dark Streaks VFT- NOT OBSERVED        | 1,900             | SF             | 3rd Floor Corridors, 223, 221, 117B - 1912                       | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage |                 |
| 97     | 12"x12" DK Brown w/White & Dark Streaks VFT Mastic- NOT OBSERVED | 1,900             | SF             | 3rd Floor Corridors, 223, 221, 117B - 1912                       | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage |                 |
| 98     | 12"x12" Black w/ White Speckles VFT- NOT OBSERVED                | 250               | SF             | 3rd Floor Corridor (N) - 1912                                    | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage |                 |
| 99     | 12"x12" Black w/ White Speckles VFT Mastic- NOT OBSERVED         | 250               | SF             | 3rd Floor Corridor (N) - 1912                                    | Chrysotile    | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage |                 |
| AA     | 12"x 12" green floor tile- NOT OBSERVED                          |                   |                | 3rd floor, side corridor, East to West navy areas                | Assumed       |                   |         |                 |              |                                      |                 |
| BB     | Mastic associated with HA AA - NOT OBSERVED                      | 0                 | SF             | 3rd floor, side corridor, East to West navy areas - NOT OBSERVED | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage |                 |
| CC     | Lab counter tops   | 3,500             | SF             | classrooms 100, 106, 108, 110, 302, 310, 350                     | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| DD     | Lab tables   | 2,600             | SF             | Classrooms, 110, 302, 310, 350                                   | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| EE     | lab fume hoods   | 750               | SF             | Classrooms 100,106, 350  | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |

# Chicago Public Schools

**School** Senn Academy  
**Address** 5900 N. Glenwood

**Unit** 47061  
 Chicago, IL, 60660

**Building ID** 1540  
**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG Consultants, Inc.  
 855 W. Adams St., Ste. 200  
 Phone: (312) 733-6262

Fax: (312) 733-5612

*Management Planner's Comments Summarized at the End of the Report*

|                                    |                  |
|------------------------------------|------------------|
| Review Date                        | 5/13/2016        |
| Manager Planner Name               | Guillermo Garcia |
| 100-01786                          | 3/21/2017        |
| Manager IDPH License No/Expiration |                  |

| HA Number | Management Comments |
|-----------|---------------------|
| 01        |                     |
| 02        |                     |
| 03        |                     |
| 04        |                     |
| 05        |                     |
| 06        |                     |
| 09        |                     |
| 10        |                     |
| 100       |                     |
| 1000      |                     |
| 1001      |                     |

# Chicago Public Schools

**School** Senn Academy  
**Address** 5900 N. Glenwood

**Unit** 47061  
 Chicago, IL, 60660

**Building ID** 1540  
**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262                      Fax: (312) 733-5612

*Management Planner's Comments Summarized at the End of the Report*

| HA Number | Management Comments |
|-----------|---------------------|
| 101       |                     |
| 102       |                     |
| 103       |                     |
| 104       |                     |
| 105       |                     |
| 106       |                     |
| 107       |                     |
| 108       |                     |
| 109       |                     |
| 110       |                     |
| 111       |                     |
| 112       |                     |
| 113       |                     |
| 114       |                     |
| 115       |                     |
| 116       |                     |
| 117       |                     |
| 118       |                     |
| 119       |                     |
| 120       |                     |
| 121       |                     |
| 122       |                     |
| 123       |                     |
| 124       |                     |
| 125       |                     |
| 126       |                     |
| 127       |                     |

# Chicago Public Schools

**School** Senn Academy  
**Address** 5900 N. Glenwood

**Unit** 47061  
 Chicago, IL, 60660

**Building ID** 1540  
**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

*Management Planner's Comments Summarized at the End of the Report*

| HA Number | Management Comments |
|-----------|---------------------|
| 127 A     |                     |
| 128       |                     |
| 128 A     |                     |
| 13        |                     |
| 133       |                     |
| 134       |                     |
| 135       |                     |
| 136       |                     |
| 137       |                     |
| 138       |                     |
| 139       |                     |
| 14        |                     |
| 140       |                     |
| 141       |                     |
| 142       |                     |
| 143       |                     |
| 144       |                     |
| 145       |                     |
| 146       |                     |
| 147       |                     |
| 148       |                     |
| 148M      |                     |
| 149       |                     |
| 149M      |                     |
| 150       |                     |
| 150M      |                     |
| 151       |                     |

# Chicago Public Schools

**School** Senn Academy  
**Address** 5900 N. Glenwood

**Unit** 47061  
 Chicago, IL, 60660

**Building ID** 1540  
**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

***Management Planner's Comments Summarized at the End of the Report***

| HA Number | Management Comments |
|-----------|---------------------|
| 151M      |                     |
| 152       |                     |
| 152M      |                     |
| 153       |                     |
| 153M      |                     |
| 154M      |                     |
| 155       |                     |
| 155M      |                     |
| 156       |                     |
| 156A      |                     |
| 157       |                     |
| 158       |                     |
| 159       |                     |
| 160       |                     |
| 161       |                     |
| 162       |                     |
| 163       |                     |
| 164       |                     |
| 164A      |                     |
| 165       |                     |
| 165A      |                     |
| 166       |                     |
| 166A      |                     |
| 167       |                     |
| 167A      |                     |
| 168       |                     |
| 169       |                     |

# Chicago Public Schools

**School** Senn Academy  
**Address** 5900 N. Glenwood

**Unit** 47061  
 Chicago, IL, 60660

**Building ID** 1540  
**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

*Management Planner's Comments Summarized at the End of the Report*

| HA Number | Management Comments |
|-----------|---------------------|
| 170       |                     |
| 171       |                     |
| 172       |                     |
| 173       |                     |
| 174       |                     |
| 175       |                     |
| 176       |                     |
| 177       |                     |
| 178       |                     |
| 179       |                     |
| 180       |                     |
| 181       |                     |
| 182       |                     |
| 183       |                     |
| 184       |                     |
| 185       |                     |
| 186       |                     |
| 187       |                     |
| 188       |                     |
| 189       |                     |
| 190       |                     |
| 191       |                     |
| 192       |                     |
| 193       |                     |
| 194       |                     |
| 195       |                     |
| 196       |                     |

# Chicago Public Schools

**School** Senn Academy  
**Address** 5900 N. Glenwood

**Unit** 47061  
Chicago, IL, 60660

**Building ID** 1540  
**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

### *Management Planner's Comments Summarized at the End of the Report*

| HA Number | Management Comments |
|-----------|---------------------|
| 20        |                     |
| 25        |                     |
| 26        |                     |
| 27        |                     |
| 30        |                     |
| 33        |                     |
| 34        |                     |
| 39        |                     |
| 40        |                     |
| 55        |                     |
| 56        |                     |
| 57        |                     |
| 60        |                     |
| 61        |                     |
| 62        |                     |
| 64        |                     |
| 65        |                     |
| 66        |                     |
| 67        |                     |
| 68        |                     |
| 69        |                     |
| 70        |                     |
| 71        |                     |
| 72        |                     |
| 73        |                     |
| 76        |                     |
| 77        |                     |

# Chicago Public Schools

**School** Senn Academy  
**Address** 5900 N. Glenwood

**Unit** 47061  
Chicago, IL, 60660

**Building ID** 1540  
**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

### *Management Planner's Comments Summarized at the End of the Report*

| HA Number | Management Comments |
|-----------|---------------------|
| 78        |                     |
| 79        |                     |
| 80        |                     |
| 81        |                     |
| 86        |                     |
| 87        |                     |
| 88        |                     |
| 89        |                     |
| 90        |                     |
| 91        |                     |
| 92        |                     |
| 93        |                     |
| 94        |                     |
| 95        |                     |
| 96        |                     |
| 97        |                     |
| 98        |                     |
| 99        |                     |
| AA        |                     |
| BB        |                     |
| CC        |                     |
| DD        |                     |
| EE        |                     |



# Chicago Public Schools

GSG Consultants, Inc.

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **01**  
MATERIAL DESCRIPTION: **Boiler Lagging (ABATED 2010)**  
HISTORICAL AHERA DAMAGE CATEGORY **Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Abated** FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler # 1 - 1931**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/16/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUILDING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **01**

MATERIAL DESCRIPTION: **Boiler Lagging (ABATED 2010)**

MATERIAL LOCATION: **Boiler # 1 - 1931**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **02**  
MATERIAL DESCRIPTION: **Boiler Lagging (ABATED 2010)**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with potential for significant damage**  
HISTORICAL DAMAGE REASON: **Physical Damage**  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler # 2 - 1931**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/16/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUILDING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **02**  
MATERIAL DESCRIPTION: **Boiler Lagging (ABATED 2010)**  
MATERIAL LOCATION: **Boiler # 2 - 1931**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **03**  
MATERIAL DESCRIPTION: **Boiler Lagging (ABATED 2010)**  
HISTORICAL AHERA DAMAGE CATEGORY **Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler # 3 - 1931**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/16/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUILDING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **03**

MATERIAL DESCRIPTION: **Boiler Lagging (ABATED 2010)**

MATERIAL LOCATION: **Boiler # 3 - 1931**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **04**  
MATERIAL DESCRIPTION: **Boiler Lagging (ABATED 2010)**  
HISTORICAL AHERA DAMAGE CATEGORY **Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler # 4 - 1931**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/16/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUILDING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **04**

MATERIAL DESCRIPTION: **Boiler Lagging (ABATED 2010)**

MATERIAL LOCATION: **Boiler # 4 - 1931**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **05**  
MATERIAL DESCRIPTION: **Boiler Gasket (ABATED 2010)**  
HISTORICAL AHERA DAMAGE CATEGORY **Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler # 1 - 1931**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/16/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUILDING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **05**

MATERIAL DESCRIPTION: **Boiler Gasket (ABATED 2010)**

MATERIAL LOCATION: **Boiler # 1 - 1931**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **06**  
MATERIAL DESCRIPTION: **Boiler Gasket (ABATED 2010)**  
HISTORICAL AHERA DAMAGE CATEGORY **Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler # 2 - 1931**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/16/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUILDING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **06**

MATERIAL DESCRIPTION: **Boiler Gasket (ABATED 2010)**

MATERIAL LOCATION: **Boiler # 2 - 1931**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **09**  
MATERIAL DESCRIPTION: **MJP on Fiberglass Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout - 1912 (See Hatching Maps)**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 03/16/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **09**  
MATERIAL DESCRIPTION: **MJP on Fiberglass Pipe Insulation**  
MATERIAL LOCATION: **Throughout - 1912 (See Hatching Maps)**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10**  
MATERIAL DESCRIPTION: **MJP on Fiberglass Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 Damaged or significantly damaged friable thermal system insulating ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Repair**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **ROTC Rm, Boiler & Pump Rms, Main Tunnel, 2nd & 3rd Flr S JC Chase, 2nd Flr Boy Tol (N) - 1931; 3rd Floor Unisex Toilet.; 1st Floor Janitor's Closet; ; Under Sinks in Rms 310, 352, and 366: BookRoom Between Rm 315 and 317; Mens Rm Next to Rm 322.**

MATERIAL QUANTITY: **425** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **03/16/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **10**  
MATERIAL DESCRIPTION: **MJP on Fiberglass Pipe Insulation**  
MATERIAL LOCATION: **ROTC Rm, Boiler & Pump Rms, Main Tunnel, 2nd & 3rd Flr S JC Chase, 2nd Flr Boy Tol (N) - 1931; 3rd Floor Unisex Toilet.; 1st Floor Janitor's Closet; ; Under Sinks in Rms 310, 352, and 366; BookRoom Between Rm 315 and 317; Mens Rm Next to Rm 322.**  
MATERIAL QUANTITY: **425** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **100**  
MATERIAL DESCRIPTION: **9"x9" Red w/ White Streaks VFT- NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **115 Kitchen - 1912**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 03/16/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUILDING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **100**  
MATERIAL DESCRIPTION: **9"x9" Red w/ White Streaks VFT- NOT OBSERVED**  
MATERIAL LOCATION: **115 Kitchen - 1912**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **1000**  
MATERIAL DESCRIPTION: **12"x12" orange/brown VFT- NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rm 180 wooden stage**  
MATERIAL QUANTITY: **24** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/16/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **1000**  
MATERIAL DESCRIPTION: **12"x12" orange/brown VFT- NOT OBSERVED**  
MATERIAL LOCATION: **Rm 180 wooden stage**  
MATERIAL QUANTITY: **24** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **1001**  
MATERIAL DESCRIPTION: **12"x12" orange/brown VFT black mastic- NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rm 180 wooden stage**  
MATERIAL QUANTITY: **24** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/16/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUILDING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **1001**  
MATERIAL DESCRIPTION: **12"x12" orange/brown VFT black mastic- NOT OBSERVED**  
MATERIAL LOCATION: **Rm 180 wooden stage**  
MATERIAL QUANTITY: **24** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **101**  
MATERIAL DESCRIPTION: **9"x9" Red w/ White Streaks VFT Mastic- NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **115 Kitchen - 1912**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 03/16/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **101**  
MATERIAL DESCRIPTION: **9"x9" Red w/ White Streaks VFT Mastic- NOT OBSERVED**  
MATERIAL LOCATION: **115 Kitchen - 1912**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**



# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **102**  
MATERIAL DESCRIPTION: **9"x9" Gray w/ White Streaks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Rooms 117A - 1912**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/16/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUILDING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **102**  
MATERIAL DESCRIPTION: **9"x9" Gray w/ White Streaks VFT**  
MATERIAL LOCATION: **Rooms 117A - 1912**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **103**  
MATERIAL DESCRIPTION: **9"x9" Gray w/ White Streaks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 117A - 1912**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/16/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **103**  
MATERIAL DESCRIPTION: **9"x9" Gray w/ White Streaks VFT Mastic**  
MATERIAL LOCATION: **Rooms 117A - 1912**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **104**  
MATERIAL DESCRIPTION: **12"x12" Light Green w/ White Streaks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Room 123A - 1912**  
MATERIAL QUANTITY: **350** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/16/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUILDING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **104**  
MATERIAL DESCRIPTION: **12"x12" Light Green w/ White Streaks VFT**  
MATERIAL LOCATION: **Room 123A - 1912**  
MATERIAL QUANTITY: **350** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **105**  
MATERIAL DESCRIPTION: **12"x12" Light Green w/ White Streaks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 123A - 1912**  
MATERIAL QUANTITY: **350** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/16/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **105**  
MATERIAL DESCRIPTION: **12"x12" Light Green w/ White Streaks VFT Mastic**  
MATERIAL LOCATION: **Room 123A - 1912**  
MATERIAL QUANTITY: **350** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **106**  
MATERIAL DESCRIPTION: **12"x12" Beige w/ Dark & White Streaks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 127, 129, 131, 132, 133, 134, 137, 139, 135, 190, 239 - 1912**  
MATERIAL QUANTITY: **6100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **Not Observed in Rooms 131, 132, 133, 134, 135**

Inspector's Signature: \_\_\_\_\_



Date: 03/16/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUILDING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **106**  
MATERIAL DESCRIPTION: **12"x12" Beige w/ Dark & White Streaks VFT**  
MATERIAL LOCATION: **Rooms 127, 129, 131, 132, 133, 134, 137, 139, 135, 190, 239 - 1912**  
MATERIAL QUANTITY: **6100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **107**  
MATERIAL DESCRIPTION: **12"x12" Beige w/ Dark & White Streaks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 127, 129, 131, 132, 133, 134, 137, 139, 135, 190, 239 - 1912**  
MATERIAL QUANTITY: **6100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **Not Observed in Rooms 131, 132, 133, 134, 135**

Inspector's Signature: \_\_\_\_\_



Date: 03/16/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **107**  
MATERIAL DESCRIPTION: **12"x12" Beige w/ Dark & White Streaks VFT Mastic**  
MATERIAL LOCATION: **Rooms 127, 129, 131, 132, 133, 134, 137, 139, 135, 190, 239 - 1912**  
MATERIAL QUANTITY: **6100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **108**  
MATERIAL DESCRIPTION: **9"x9" Lt. Brown w/ Dark Red Streaks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Teacher Lunchroom/Lounge - 1912; Rms 300 (under sink), 310 (lab vault)**  
MATERIAL QUANTITY: **455** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/16/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUILDING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **108**  
MATERIAL DESCRIPTION: **9"x9" Lt. Brown w/ Dark Red Streaks VFT**  
MATERIAL LOCATION: **Teacher Lunchroom/Lounge - 1912; Rms 300 (under sink), 310 (lab vault)**  
MATERIAL QUANTITY: **455** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **109**  
MATERIAL DESCRIPTION: **9"x9" Lt. Brown w/ Dark Red Streaks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Teacher Lunchroom/Lounge - 1912; Rms 300 (under sink), 310 (lab vault)**  
MATERIAL QUANTITY: **455** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 03/16/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUILDING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **109**  
MATERIAL DESCRIPTION: **9"x9" Lt. Brown w/ Dark Red Streaks VFT Mastic**  
MATERIAL LOCATION: **Teacher Lunchroom/Lounge - 1912; Rms 300 (under sink), 310 (lab vault)**  
MATERIAL QUANTITY: **455** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **110**  
MATERIAL DESCRIPTION: **9"x9" Green w/ White Streaks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Teacher Lunchroom/Lounge - 1912**

MATERIAL QUANTITY: **300**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/16/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **110**  
MATERIAL DESCRIPTION: **9"x9" Green w/ White Streaks VFT**  
MATERIAL LOCATION: **Teacher Lunchroom/Lounge - 1912**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **111**  
MATERIAL DESCRIPTION: **9"x9" Green w/ White Streaks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Teacher Lunchroom/Lounge - 1912**

MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: **03/16/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **111**  
MATERIAL DESCRIPTION: **9"x9" Green w/ White Streaks VFT Mastic**  
MATERIAL LOCATION: **Teacher Lunchroom/Lounge - 1912**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **112**  
MATERIAL DESCRIPTION: **12"x12" Lt. Brown w/ Gray Speckles VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **153 Vest., 120 Vest. - 1912**  
MATERIAL QUANTITY: **80** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/16/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **112**  
MATERIAL DESCRIPTION: **12"x12" Lt. Brown w/ Gray Speckles VFT**  
MATERIAL LOCATION: **153 Vest., 120 Vest. - 1912**  
MATERIAL QUANTITY: **80** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **113**  
MATERIAL DESCRIPTION: **12"x12" Lt. Brown w/ Gray Speckles VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **153 Vest., 120 Vest. - 1912**  
MATERIAL QUANTITY: **80** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 03/16/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **113**  
MATERIAL DESCRIPTION: **12"x12" Lt. Brown w/ Gray Speckles VFT Mastic**  
MATERIAL LOCATION: **153 Vest., 120 Vest. - 1912**  
MATERIAL QUANTITY: **80** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **114**  
MATERIAL DESCRIPTION: **12"x12 Beige w/ Brown Streaks VFT- NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 166, & 162 - 1912**  
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/16/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **114**  
MATERIAL DESCRIPTION: **12"x12 Beige w/ Brown Streaks VFT- NOT OBSERVED**  
MATERIAL LOCATION: **Rooms 166, & 162 - 1912**  
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **115**  
MATERIAL DESCRIPTION: **12"x12 Beige w/ Brown Streaks VFT Mastic- NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 166, & 162 - 1912**  
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/16/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUILDING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **115**  
MATERIAL DESCRIPTION: **12"x12 Beige w/ Brown Streaks VFT Mastic- NOT OBSERVED**  
MATERIAL LOCATION: **Rooms 166, & 162 - 1912**  
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **116**  
MATERIAL DESCRIPTION: **12"x12" Blue-Gray w/ White Streaks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 373- 1912**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 03/16/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **116**  
MATERIAL DESCRIPTION: **12"x12" Blue-Gray w/ White Streaks VFT**  
MATERIAL LOCATION: **Room 373- 1912**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **117**  
MATERIAL DESCRIPTION: **12"x12" Blue-Gray w/ White Streaks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 373- 1912**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/16/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **117**  
MATERIAL DESCRIPTION: **12"x12" Blue-Gray w/ White Streaks VFT Mastic**  
MATERIAL LOCATION: **Room 373- 1912**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **118**  
MATERIAL DESCRIPTION: **12"x12" Dk Gray w/ Beige Streaks VFT- NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Rooms 176, 174, 180 - 1912**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 03/16/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUILDING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **118**  
MATERIAL DESCRIPTION: **12"x12" Dk Gray w/ Beige Streaks VFT- NOT OBSERVED**  
MATERIAL LOCATION: **Rooms 176, 174, 180 - 1912**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **119**  
MATERIAL DESCRIPTION: **12"x12" Dk Gray w/ Beige Streaks VFT Mastic- NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 176, 174, 180 - 1912**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/16/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **119**  
MATERIAL DESCRIPTION: **12"x12" Dk Gray w/ Beige Streaks VFT Mastic- NOT OBSERVED**  
MATERIAL LOCATION: **Rooms 176, 174, 180 - 1912**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **120**  
MATERIAL DESCRIPTION: **12"x12" Lt Gray w/ White Speckles VFT- NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Rooms 176, 174, 180 - 1912**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 03/16/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **120**  
MATERIAL DESCRIPTION: **12"x12" Lt Gray w/ White Speckles VFT- NOT OBSERVED**  
MATERIAL LOCATION: **Rooms 176, 174, 180 - 1912**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **121**  
MATERIAL DESCRIPTION: **12"x12" Lt Gray w/ White Speckles VFT Mastic- NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 176, 174, 180 - 1912**

MATERIAL QUANTITY: **2000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/16/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **121**  
MATERIAL DESCRIPTION: **12"x12" Lt Gray w/ White Speckles VFT Mastic- NOT OBSERVED**  
MATERIAL LOCATION: **Rooms 176, 174, 180 - 1912**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **122**  
MATERIAL DESCRIPTION: **12"x12" Brown VFT- NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Stage - 1912**  
MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/16/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUILDING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **122**  
MATERIAL DESCRIPTION: **12"x12" Brown VFT- NOT OBSERVED**  
MATERIAL LOCATION: **Stage - 1912**  
MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **123**  
MATERIAL DESCRIPTION: **12"x12" Brown VFT Mastic- NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Stage - 1912**  
MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/16/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **123**  
MATERIAL DESCRIPTION: **12"x12" Brown VFT Mastic- NOT OBSERVED**  
MATERIAL LOCATION: **Stage - 1912**  
MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **124**  
MATERIAL DESCRIPTION: **2'x2' Black Border VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **115 Kitchen - 1912**  
MATERIAL QUANTITY: **15** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/16/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **124**  
MATERIAL DESCRIPTION: **2'x2' Black Border VFT**  
MATERIAL LOCATION: **115 Kitchen - 1912**  
MATERIAL QUANTITY: **15** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **125**  
MATERIAL DESCRIPTION: **2'x2' Black Border VFT Mastic- NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **115 Kitchen - 1912**  
MATERIAL QUANTITY: **15** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 03/16/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **125**  
MATERIAL DESCRIPTION: **2'x2' Black Border VFT Mastic- NOT OBSERVED**  
MATERIAL LOCATION: **115 Kitchen - 1912**  
MATERIAL QUANTITY: **15** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **126**  
MATERIAL DESCRIPTION: **2'x2' Ceiling Tile- NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 425, & 326 - 1912**  
MATERIAL QUANTITY: **1700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/16/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **126**  
MATERIAL DESCRIPTION: **2'x2' Ceiling Tile- NOT OBSERVED**  
MATERIAL LOCATION: **Room 425, & 326 - 1912**  
MATERIAL QUANTITY: **1700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **127**  
MATERIAL DESCRIPTION: **12"x12" White w/Beige Streaks VFT- NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Room 377**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 03/16/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **127**  
MATERIAL DESCRIPTION: **12"x12" White w/Beige Streaks VFT- NOT OBSERVED**  
MATERIAL LOCATION: **Room 377**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **127 A**  
MATERIAL DESCRIPTION: **12"x12" White w/Beige Streaks VFT Mastic- NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 377**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/16/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **127 A**  
MATERIAL DESCRIPTION: **12"x12" White w/Beige Streaks VFT Mastic- NOT OBSERVED**  
MATERIAL LOCATION: **Room 377**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **128**  
MATERIAL DESCRIPTION: **12"x12" White w/Blue Streaks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 351**  
MATERIAL QUANTITY: **880** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/16/2016**

# Chicago Public Schools

GSG Consultants, Inc.

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **128**  
MATERIAL DESCRIPTION: **12"x12" White w/Blue Streaks VFT**  
MATERIAL LOCATION: **Room 351**  
MATERIAL QUANTITY: **880** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **128 A**  
MATERIAL DESCRIPTION: **12 x 12 inch White w/blue Streaks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 351**  
MATERIAL QUANTITY: **880** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 03/16/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **128 A**  
MATERIAL DESCRIPTION: **12 x 12 inch White w/blue Streaks VFT Mastic**  
MATERIAL LOCATION: **Room 351**  
MATERIAL QUANTITY: **880** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13**  
MATERIAL DESCRIPTION: **MJP on Paperwrap Pipe Insulation; 2nd Floor Janitor's Closet.**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with potential for significant damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **1st Floor South JC, 238 Chase, 188, Autosshop - 1931 bldg.**  
MATERIAL QUANTITY: **370** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 03/16/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **13**  
MATERIAL DESCRIPTION: **MJP on Paperwrap Pipe Insulation; 2nd Floor Janitor's Closet.**  
MATERIAL LOCATION: **1st Floor South JC, 238 Chase, 188, Autoshop - 1931 bldg.**  
MATERIAL QUANTITY: **370** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **133**  
MATERIAL DESCRIPTION: **Lt Blue Speckled Linoleum- NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Room 356 - 1912; Room 326**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 03/16/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **133**  
MATERIAL DESCRIPTION: **Lt Blue Speckled Linoleum- NOT OBSERVED**  
MATERIAL LOCATION: **Room 356 - 1912; Room 326**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **134**  
MATERIAL DESCRIPTION: **Lt Blue Speckled Linoleum Mastic- NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Room 356 - 1912; Room 326**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/16/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **134**  
MATERIAL DESCRIPTION: **Lt Blue Speckled Linoleum Mastic- NOT OBSERVED**  
MATERIAL LOCATION: **Room 356 - 1912; Room 326**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **135**  
MATERIAL DESCRIPTION: **12"x12" White w/ Gold Specks VFT- NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 174, 176, & 180 - 1911**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/16/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUILDING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **135**  
MATERIAL DESCRIPTION: **12"x12" White w/ Gold Specks VFT- NOT OBSERVED**  
MATERIAL LOCATION: **Rooms 174, 176, & 180 - 1911**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **136**  
MATERIAL DESCRIPTION: **12"x12" White w/ Gold Specks VFT Mastic- NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 174, 176, & 180 - 1911**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/16/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUILDING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **136**  
MATERIAL DESCRIPTION: **12"x12" White w/ Gold Specks VFT Mastic- NOT OBSERVED**  
MATERIAL LOCATION: **Rooms 174, 176, & 180 - 1911**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **137**  
MATERIAL DESCRIPTION: **2'x4' White Pin-Hole Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 356 - 1912**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 03/16/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **137**  
MATERIAL DESCRIPTION: **2'x4' White Pin-Hole Ceiling Tile**  
MATERIAL LOCATION: **Room 356 - 1912**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **138**  
MATERIAL DESCRIPTION: **12"x12" White w/ Beige VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **310 & Office, 302, 108, 110 - 1931**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/16/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **138**  
MATERIAL DESCRIPTION: **12"x12" White w/ Beige VFT**  
MATERIAL LOCATION: **310 & Office, 302, 108, 110 - 1931**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **139**  
MATERIAL DESCRIPTION: **12"x12" White w/ Beige VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **310 & Office, 302, 108, 110 - 1931**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/16/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **139**  
MATERIAL DESCRIPTION: **12"x12" White w/ Beige VFT Mastic**  
MATERIAL LOCATION: **310 & Office, 302, 108, 110 - 1931**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14**  
MATERIAL DESCRIPTION: **Paperwrap Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **ROTC Room, 1st Floor South JC, 238 Chase, 188, Autoshop - 1931 bldg.**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 03/16/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUILDING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **14**  
MATERIAL DESCRIPTION: **Paperwrap Pipe Insulation**  
MATERIAL LOCATION: **ROTC Room, 1st Floor South JC, 238 Chase, 188, Autoshop - 1931 bldg.**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **140**  
MATERIAL DESCRIPTION: **12"x12" Light Gray VFT- NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **210, & Engineer's Office - 1931**  
MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 03/16/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUILDING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **140**  
MATERIAL DESCRIPTION: **12"x12" Light Gray VFT- NOT OBSERVED**  
MATERIAL LOCATION: **210, & Engineer's Office - 1931**  
MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **141**  
MATERIAL DESCRIPTION: **12"x12" Light Gray VFT Mastic- NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **210, & Engineer's Office - 1931**  
MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/16/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **141**  
MATERIAL DESCRIPTION: **12"x12" Light Gray VFT Mastic- NOT OBSERVED**  
MATERIAL LOCATION: **210, & Engineer's Office - 1931**  
MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **142**  
MATERIAL DESCRIPTION: **12"x12" Light Blue VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **210, 195A & Engineer's Office - 1931**  
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/16/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **142**  
MATERIAL DESCRIPTION: **12"x12" Light Blue VFT**  
MATERIAL LOCATION: **210, 195A & Engineer's Office - 1931**  
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **143**  
MATERIAL DESCRIPTION: **12"x12" Light Blue VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **210, 195A & Engineer's Office - 1931**  
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 03/16/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **143**  
MATERIAL DESCRIPTION: **12"x12" Light Blue VFT Mastic**  
MATERIAL LOCATION: **210, 195A & Engineer's Office - 1931**  
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **144**  
MATERIAL DESCRIPTION: **12"x12" Green VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st Floor Hall (N&S) - 1931**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 03/16/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **144**  
MATERIAL DESCRIPTION: **12"x12" Green VFT**  
MATERIAL LOCATION: **1st Floor Hall (N&S) - 1931**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **145**  
MATERIAL DESCRIPTION: **12"x12" Green VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st Floor Hall (N&S) - 1931**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/16/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUILDING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **145**  
MATERIAL DESCRIPTION: **12"x12" Green VFT Mastic**  
MATERIAL LOCATION: **1st Floor Hall (N&S) - 1931**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **146**  
MATERIAL DESCRIPTION: **12"x12" White VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st Floor Hall (N&S) - 1931**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/16/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **146**  
MATERIAL DESCRIPTION: **12"x12" White VFT**  
MATERIAL LOCATION: **1st Floor Hall (N&S) - 1931**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **147**  
MATERIAL DESCRIPTION: **12"x12" White VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st Floor Hall (N&S) - 1931**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/16/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **147**  
MATERIAL DESCRIPTION: **12"x12" White VFT Mastic**  
MATERIAL LOCATION: **1st Floor Hall (N&S) - 1931**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **148**  
MATERIAL DESCRIPTION: **Linoleum, Gray w/Gray Streaks**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 350, 352, 356 Vault, and 306**  
MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/16/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUILDING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **148**  
MATERIAL DESCRIPTION: **Linoleum, Gray w/Gray Streaks**  
MATERIAL LOCATION: **Rooms 350, 352, 356 Vault, and 306**  
MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **148M**  
MATERIAL DESCRIPTION: **Linoleum, Gray w/Gray Streaks Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 350, 352, 356 Vault, and 306**  
MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/16/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUILDING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **148M**  
MATERIAL DESCRIPTION: **Linoleum, Gray w/Gray Streaks Mastic**  
MATERIAL LOCATION: **Rooms 350, 352, 356 Vault, and 306**  
MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **149**  
MATERIAL DESCRIPTION: **Linoleum, Blue Solid (Not Observed)**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rms 100, 106, and 106 Office**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/16/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **149**  
MATERIAL DESCRIPTION: **Linoleum, Blue Solid (Not Observed)**  
MATERIAL LOCATION: **Rms 100, 106, and 106 Office**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **149M**  
MATERIAL DESCRIPTION: **Linoleum, Blue Solid Mastic (Not Observed)**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rms 100, 106, and 106 Office**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/16/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **149M**  
MATERIAL DESCRIPTION: **Linoleum, Blue Solid Mastic (Not Observed)**  
MATERIAL LOCATION: **Rms 100, 106, and 106 Office**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **150**  
MATERIAL DESCRIPTION: **12"X12" VFT-- NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **3rd Floor Side Corridor, SE to West Naval Area, Border Along N. and S. Walls - NOT OBSERVED**

MATERIAL QUANTITY: **200**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/16/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **150**  
MATERIAL DESCRIPTION: **12"X12" VFT-- NOT OBSERVED**  
MATERIAL LOCATION: **3rd Floor Side Corridor, SE to West Naval Area, Border Along N. and S. Walls - NOT OBSERVED**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **150M**  
MATERIAL DESCRIPTION: **12"X12" VFT Mastic - NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **3rd Floor Side Corridor, SE to West Naval Area, Border Along N. and S. Walls - NOT OBSERVED**

MATERIAL QUANTITY: **200**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/16/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUILDING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **150M**  
MATERIAL DESCRIPTION: **12"X12" VFT Mastic - NOT OBSERVED**  
MATERIAL LOCATION: **3rd Floor Side Corridor, SE to West Naval Area, Border Along N. and S. Walls - NOT OBSERVED**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **151**  
MATERIAL DESCRIPTION: **Solid Gray**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **3rd Floor Side Corridor, SE to West Naval Area, Center of Corridor**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/16/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUILDING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **151**  
MATERIAL DESCRIPTION: **Solid Gray**  
MATERIAL LOCATION: **3rd Floor Side Corridor, SE to West Naval Area, Center of Corridor**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **151M**  
MATERIAL DESCRIPTION: **Solid Gray Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **3rd Floor Side Corridor, SE to West Naval Area, Center of Corridor**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/16/2016**

# Chicago Public Schools

GSG Consultants, Inc.

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUILDING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **151M**  
MATERIAL DESCRIPTION: **Solid Gray Mastic**  
MATERIAL LOCATION: **3rd Floor Side Corridor, SE to West Naval Area, Center of Corridor**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **152**  
MATERIAL DESCRIPTION: **Tan w/Brown Speckles**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **3rd Floor Side Corridor-North,Runs East-to-West in Naval Area, Center of Corridor**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 03/16/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUILDING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **152**  
MATERIAL DESCRIPTION: **Tan w/Brown Speckles**  
MATERIAL LOCATION: **3rd Floor Side Corridor-North,Runs East-to-West in Naval Area, Center of Corridor**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **152M**  
MATERIAL DESCRIPTION: **Tan w/Brown Speckles Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **3rd Floor Side Corridor-North,Runs East-to-West in Naval Area, Center of Corridor**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 03/16/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUILDING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **152M**  
MATERIAL DESCRIPTION: **Tan w/Brown Speckles Mastic**  
MATERIAL LOCATION: **3rd Floor Side Corridor-North,Runs East-to-West in Naval Area, Center of Corridor**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **153**  
MATERIAL DESCRIPTION: **12"X12" White w/ Tan Speckles VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **3rd Floor Side Corridor-North,Runs East-to-West in Naval Area, Border Along N. and S. Walls**

MATERIAL QUANTITY: **200**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/16/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **153**  
MATERIAL DESCRIPTION: **12"X12" White w/ Tan Speckles VFT**  
MATERIAL LOCATION: **3rd Floor Side Corridor-North,Runs East-to-West in Naval Area, Border Along N. and S. Walls**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **153M**  
MATERIAL DESCRIPTION: **12"X12" White w/ Tan Speckles VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **3rd Floor Side Corridor-North,Runs East-to-West in Naval Area, Border Along N. and S. Walls**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/16/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **153M**  
MATERIAL DESCRIPTION: **12"X12" White w/ Tan Speckles VFT Mastic**  
MATERIAL LOCATION: **3rd Floor Side Corridor-North,Runs East-to-West in Naval Area, Border Along N. and S. Walls**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **154M**  
MATERIAL DESCRIPTION: **Gold, Blue Carpet**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rms 379, 375, 326, 315, and 272(not observed)**  
MATERIAL QUANTITY: **3800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 03/16/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUILDING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **154M**  
MATERIAL DESCRIPTION: **Gold, Blue Carpet**  
MATERIAL LOCATION: **Rms 379, 375, 326, 315, and 272(not observed)**  
MATERIAL QUANTITY: **3800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **155**  
MATERIAL DESCRIPTION: **Linoleum, White w/Gray Streaks**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rm 352**  
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/16/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **155**  
MATERIAL DESCRIPTION: **Linoleum, White w/Gray Streaks**  
MATERIAL LOCATION: **Rm 352**  
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **155M**  
MATERIAL DESCRIPTION: **Linoleum, White w/Gray Streaks Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rm 352**  
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 03/16/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **155M**  
MATERIAL DESCRIPTION: **Linoleum, White w/Gray Streaks Mastic**  
MATERIAL LOCATION: **Rm 352**  
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **156**  
MATERIAL DESCRIPTION: **12"x12" light gray w/ gray and white specks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 377**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/16/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUILDING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **156**  
MATERIAL DESCRIPTION: **12"x12" light gray w/ gray and white specks VFT**  
MATERIAL LOCATION: **Room 377**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **156A**  
MATERIAL DESCRIPTION: **12"x12" light gray w/ gray specks VFT MASTIC**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 377**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 03/16/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **156A**  
MATERIAL DESCRIPTION: **12"x12" light gray w/ gray specks VFT MASTIC**  
MATERIAL LOCATION: **Room 377**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **157**  
MATERIAL DESCRIPTION: **2'x4' smooth CT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 351**  
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/16/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUILDING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **157**  
MATERIAL DESCRIPTION: **2'x4' smooth CT**  
MATERIAL LOCATION: **Room 351**  
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **158**  
MATERIAL DESCRIPTION: **1'x1' CT w/ grooves**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 320, 425- 1911 bldg**  
MATERIAL QUANTITY: **2600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/16/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **158**  
MATERIAL DESCRIPTION: **1'x1' CT w/ grooves**  
MATERIAL LOCATION: **Room 320, 425- 1911 bldg**  
MATERIAL QUANTITY: **2600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **159**  
MATERIAL DESCRIPTION: **1'x1' CT w/ grooves above HA 161**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 108, 148, 149, 146**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/16/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **159**  
MATERIAL DESCRIPTION: **1'x1' CT w/ grooves above HA 161**  
MATERIAL LOCATION: **Room 108, 148, 149, 146**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **160**  
MATERIAL DESCRIPTION: **2'x4' CT w/ grooves**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Bldg 1930- South wing except women's toilet and 213- 2nd fl. 2nd fl. north wing except boys toilet. 1st fl. south wing except for girls' toilet and engineer room. 1st fl. south wing hallway and rm 145. 3rd fl all south wing except for 306, 313, 315 and women's toilet. 3rd fl all north wing except for room 341, 335, 333 and men's toilet.**

MATERIAL QUANTITY: **22000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/16/2016**

# Chicago Public Schools

GSG Consultants, Inc.

## 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUILDING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **160**  
MATERIAL DESCRIPTION: **2'x4' CT w/ grooves**  
MATERIAL LOCATION: **Bldg 1930- South wing except women's toilet and 213- 2nd fl. 2nd fl. north wing except boys toilet. 1st fl. south wing except for girls' toilet and engineer room. 1st fl. south wing hallway and rm 145. 3rd fl all south wing except for 306, 313, 315 and women's toilet. 3rd fl all north wing except for room 341, 335, 333 and men's toilet.**  
MATERIAL QUANTITY: **22000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **161**  
MATERIAL DESCRIPTION: **2'x4' CT w/ grooves**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Bldg 1911- Hallway from 319-335 and rooms 350, 353, 322, 326, 328, 330, 332, 334, 335, 325, 319, 358, 363, 367, 369, 373, 375, 379, 372, 374, 378, 380, 376, 258, 260, 261, 262, 264, 234, 266, 272, 276, 278, 273, 275, 277, 281, 222, 219, 221, 227, 231, 233, 230, 236. 2nd fl. hallway from room 319-335. 134, 132, 123A, 123, 121, 172, 174, 176, main office. 1st floor from 119- conference room and rooms 158, 160, 162, 166**

MATERIAL QUANTITY: **45000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/16/2016**

# Chicago Public Schools

GSG Consultants, Inc.

## 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **161**

MATERIAL DESCRIPTION: **2'x4' CT w/ grooves**

MATERIAL LOCATION: **Bldg 1911- Hallway from 319-335 and rooms 350, 353, 322, 326, 328, 330, 332, 334, 335, 325, 319, 358, 363, 367, 369, 373, 375, 379, 372, 374, 378, 380, 376, 258, 260, 261, 262, 264, 234, 266, 272, 276, 278, 273, 275, 277, 281, 222, 219, 221, 227, 231, 233, 230, 236. 2nd fl. hallway from room 319-335. 134, 132, 123A, 123, 121, 172, 174, 176, main office. 1st floor from 119- conference room and rooms 158, 160, 162, 166**

MATERIAL QUANTITY: **45000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **162**  
MATERIAL DESCRIPTION: **2'x4' CT pinhole**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1911 bldg- 1st fl. hallway from room 158-180 and from heat chamber 3- heat chamber 8. 2nd fl hallway from room 258-280 and hallway along side of auditorium. 3rd fl hallway from room 350-361-380 and from room 369-328 and classrooms 352,364,366.**

MATERIAL QUANTITY: **13000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 03/16/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUILDING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **162**  
MATERIAL DESCRIPTION: **2'x4' CT pinhole**  
MATERIAL LOCATION: **1911 bldg- 1st fl. hallway from room 158-180 and from heat chamber 3- heat chamber 8. 2nd fl hallway from room 258-280 and hallway along side of auditorium. 3rd fl hallway from room 350-361-380 and from room 369-328 and classrooms 352,364,366.**  
MATERIAL QUANTITY: **13000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **163**  
MATERIAL DESCRIPTION: **2'x'4 CT pinholes**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Corridor- 1930 bldg. from pump room- room 184, kitchen, cafeteria**  
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/16/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **163**  
MATERIAL DESCRIPTION: **2'x'4 CT pinholes**  
MATERIAL LOCATION: **Corridor- 1930 bldg. from pump room- room 184, kitchen, cafeteria**  
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **164**  
MATERIAL DESCRIPTION: **12"x12" Tan w/ light brown specks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **119, 121, South corridor- 1912**  
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **Not Observed: 119, South Corridor**

Inspector's Signature: \_\_\_\_\_



Date: 03/16/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **164**  
MATERIAL DESCRIPTION: **12"x12" Tan w/ light brown specks VFT**  
MATERIAL LOCATION: **119, 121, South corridor- 1912**  
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **164A**  
MATERIAL DESCRIPTION: **12"x12" Tan w/ light brown specks VFT MASTIC**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **119, 121, South corridor- 1912**  
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **Not Observed: 119, South Corridor**

Inspector's Signature: \_\_\_\_\_



Date: 03/16/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **164A**  
MATERIAL DESCRIPTION: **12"x12" Tan w/ light brown specks VFT MASTIC**  
MATERIAL LOCATION: **119, 121, South corridor- 1912**  
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **165**  
MATERIAL DESCRIPTION: **9"x9" brown w/ yellow design VFT (Not Observed)**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 123- 1911 bldg**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **No**

Inspector's Signature: \_\_\_\_\_



Date: 03/16/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **165**  
MATERIAL DESCRIPTION: **9"x9" brown w/ yellow design VFT (Not Observed)**  
MATERIAL LOCATION: **Room 123- 1911 bldg**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **165A**  
MATERIAL DESCRIPTION: **9"x9" Brown w/ yellow design VFT MASTIC (Not Observed)**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 123- 1911 bldg**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 03/16/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **165A**  
MATERIAL DESCRIPTION: **9"x9" Brown w/ yellow design VFT MASTIC (Not Observed)**  
MATERIAL LOCATION: **Room 123- 1911 bldg**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **166**  
MATERIAL DESCRIPTION: **12"x12" lt. blue w/ blue specks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **2nd, 3rd Floor main center corridor, Health Center (144) 1912 bldg**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 03/16/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **166**  
MATERIAL DESCRIPTION: **12"x12" lt. blue w/ blue specks VFT**  
MATERIAL LOCATION: **2nd, 3rd Floor main center corridor, Health Center (144) 1912 bldg**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **166A**  
MATERIAL DESCRIPTION: **12"x12" lt. blue w/ blue specks VFT MASTIC**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **2nd, 3rd Floor main center corridor, Health Center (144) 1912 bldg**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/16/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUILDING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **166A**  
MATERIAL DESCRIPTION: **12"x12" lt. blue w/ blue specks VFT MASTIC**  
MATERIAL LOCATION: **2nd, 3rd Floor main center corridor, Health Center (144) 1912 bldg**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**



# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **167**  
MATERIAL DESCRIPTION: **12"x12" white w/light blue, gray and yellow specks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **2nd, 3rd Floor main center corridor, Health Center (144), 162, 166 1912 bldg**  
MATERIAL QUANTITY: **7000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **Not Observed: Room 166**

Inspector's Signature: \_\_\_\_\_



Date: 03/16/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **167**  
MATERIAL DESCRIPTION: **12"x12" white w/light blue, gray and yellow specks VFT**  
MATERIAL LOCATION: **2nd, 3rd Floor main center corridor, Health Center (144), 162, 166 1912 bldg**  
MATERIAL QUANTITY: **7000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **167A**  
MATERIAL DESCRIPTION: **12"x12" white w/ lt blue, gray and yellow specks VFT MASTIC**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **2nd, 3rd Floor main center corridor, Health Center (144), 162, 166 1912 bldg**  
MATERIAL QUANTITY: **7000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not Observed: Room 166**

Inspector's Signature: \_\_\_\_\_



Date: 03/16/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **167A**  
MATERIAL DESCRIPTION: **12"x12" white w/ lt blue, gray and yellow specks VFT MASTIC**  
MATERIAL LOCATION: **2nd, 3rd Floor main center corridor, Health Center (144), 162, 166 1912 bldg**  
MATERIAL QUANTITY: **7000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **168**  
MATERIAL DESCRIPTION: **Black lab table tops**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 358, 364, 367**  
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/16/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUILDING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **168**  
MATERIAL DESCRIPTION: **Black lab table tops**  
MATERIAL LOCATION: **Room 358, 364, 367**  
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **169**  
MATERIAL DESCRIPTION: **Black lab counter tops**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 358, 364, 367**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/16/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **169**  
MATERIAL DESCRIPTION: **Black lab counter tops**  
MATERIAL LOCATION: **Room 358, 364, 367**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **170**  
MATERIAL DESCRIPTION: **Blue linoleum with MASTIC**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 358, 364, 366**  
MATERIAL QUANTITY: **2300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/16/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUILDING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **170**  
MATERIAL DESCRIPTION: **Blue linoleum with MASTIC**  
MATERIAL LOCATION: **Rooms 358, 364, 366**  
MATERIAL QUANTITY: **2300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUILDING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **171**  
MATERIAL DESCRIPTION: **12"x12" gray w/ tan streaks VFT w/ MASTIC**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with potential for significant damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Repair**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **170**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/16/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUILDING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **171**  
MATERIAL DESCRIPTION: **12"x12" gray w/ tan streaks VFT w/ MASTIC**  
MATERIAL LOCATION: **170**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **40** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **172**  
MATERIAL DESCRIPTION: **Decorative plaster**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Assembly hall, vestibule leading to assembly hall**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/16/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **172**  
MATERIAL DESCRIPTION: **Decorative plaster**  
MATERIAL LOCATION: **Assembly hall, vestibule leading to assembly hall**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **173**  
MATERIAL DESCRIPTION: **Terrazzo**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Stairwells, 1st fl. corridor west of pump room- 1930 addition**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/16/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **173**  
MATERIAL DESCRIPTION: **Terrazzo**  
MATERIAL LOCATION: **Stairwells, 1st fl. corridor west of pump room- 1930 addition**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **174**  
MATERIAL DESCRIPTION: **Terrazzo**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Addition 1912- 1st fl corridors**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 03/16/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUILDING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **174**  
MATERIAL DESCRIPTION: **Terrazzo**  
MATERIAL LOCATION: **Addition 1912- 1st fl corridors**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**  
MATERIAL DESCRIPTION: **Mudded Joint Packing on Aircell Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Mixing Room, 219, 319, Auditorium Crawlspace - 1912; Room 120A**  
MATERIAL QUANTITY: **603** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 03/16/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUILDING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **20**  
MATERIAL DESCRIPTION: **Mudded Joint Packing on Aircell Pipe Insulation**  
MATERIAL LOCATION: **Mixing Room, 219, 319, Auditorium Crawlspace - 1912; Room 120A**  
MATERIAL QUANTITY: **603** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25**  
MATERIAL DESCRIPTION: **Insulation in Vault Door**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1893 Building: Office**  
MATERIAL QUANTITY: **28** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/16/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUILDING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **25**  
MATERIAL DESCRIPTION: **Insulation in Vault Door**  
MATERIAL LOCATION: **1893 Building: Office**  
MATERIAL QUANTITY: **28** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26**  
MATERIAL DESCRIPTION: **Mudded Joint Packing on Aircell Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 238 Chase, Autoshop, Autoshop Tool Room - 1931**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **03/16/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUILDING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **26**  
MATERIAL DESCRIPTION: **Mudded Joint Packing on Aircell Insulation**  
MATERIAL LOCATION: **Room 238 Chase, Autoshop, Autoshop Tool Room - 1931**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27**  
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Corridor by Main Corridor (N), Room 238 Chase, Room 140, Autoshop & Autoshop Tool Room - 1931**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **03/16/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **27**  
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**  
MATERIAL LOCATION: **Corridor by Main Corridor (N), Room 238 Chase, Room 140, Autosshop & Autosshop Tool Room - 1931**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **30**  
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 Damaged or significantly damaged friable misc. ACBM**  
HISTORICAL DAMAGE REASON: **Delamination  
Physical Damage**  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 219, 319, & Auditorium Crawlspace - 1912**  
MATERIAL QUANTITY: **2600** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **2600** DAMAGE UNITS: **LF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 03/16/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **30**  
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**  
MATERIAL LOCATION: **Rooms 219, 319, & Auditorium Crawlspace - 1912**  
MATERIAL QUANTITY: **2600** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **33**  
MATERIAL DESCRIPTION: **Paperwrap Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Auditorium Crawlspace - 1912**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 03/16/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUILDING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **33**  
MATERIAL DESCRIPTION: **Paperwrap Pipe Insulation**  
MATERIAL LOCATION: **Auditorium Crawlspace - 1912**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **34**  
MATERIAL DESCRIPTION: **MJP E/F/V on Paperwrap Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with potential for significant damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Auditorium Crawlspace - 1912**  
MATERIAL QUANTITY: **50** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 03/16/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **34**  
MATERIAL DESCRIPTION: **MJP E/F/V on Paperwrap Pipe Insulation**  
MATERIAL LOCATION: **Auditorium Crawlspace - 1912**  
MATERIAL QUANTITY: **50** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **39**  
MATERIAL DESCRIPTION: **Hard Coat Plater**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout - 1912**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/16/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUILDING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **39**

MATERIAL DESCRIPTION: **Hard Coat Plater**

MATERIAL LOCATION: **Throughout - 1912**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **40**  
MATERIAL DESCRIPTION: **Hard Coat Plaster**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout - 1931**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/16/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUILDING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **40**  
MATERIAL DESCRIPTION: **Hard Coat Plaster**  
MATERIAL LOCATION: **Throughout - 1931**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **55**  
MATERIAL DESCRIPTION: **12"x12" Tan w/Speckles VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **3rd Floor Corridor (N), 326, 233, 227, 225 (Library) - 1912**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 03/16/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUILDING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **55**  
MATERIAL DESCRIPTION: **12"x12" Tan w/Speckles VFT**  
MATERIAL LOCATION: **3rd Floor Corridor (N), 326, 233, 227, 225 (Library) - 1912**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **56**  
MATERIAL DESCRIPTION: **9"x9" Brown w/Sreaks VFT Mastic- NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rm. 356**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 03/16/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **56**  
MATERIAL DESCRIPTION: **9"x9" Brown w/Sreaks VFT Mastic- NOT OBSERVED**  
MATERIAL LOCATION: **Rm. 356**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **57**  
MATERIAL DESCRIPTION: **12"x12" Tan W/Speckles VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **3rd Floor Corridor (N), 326, 233, 227, 225 (Library) - 1912**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 03/16/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **57**  
MATERIAL DESCRIPTION: **12"x12" Tan W/Speckles VFT Mastic**  
MATERIAL LOCATION: **3rd Floor Corridor (N), 326, 233, 227, 225 (Library) - 1912**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **60**  
MATERIAL DESCRIPTION: **9"x9" Maroon VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **3rd Floor Hall (S&N), 2nd Floor Hall (N) -1931 Bldg.**  
MATERIAL QUANTITY: **2100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/16/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **60**  
MATERIAL DESCRIPTION: **9"x9" Maroon VFT**  
MATERIAL LOCATION: **3rd Floor Hall (S&N), 2nd Floor Hall (N) -1931 Bldg.**  
MATERIAL QUANTITY: **2100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **61**  
MATERIAL DESCRIPTION: **9"x9" Maroon VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **3rd Floor Hall (S&N), 2nd Floor Hall (N) -1931 Bldg.**  
MATERIAL QUANTITY: **2100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/16/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **61**  
MATERIAL DESCRIPTION: **9"x9" Maroon VFT Mastic**  
MATERIAL LOCATION: **3rd Floor Hall (S&N), 2nd Floor Hall (N) -1931 Bldg.**  
MATERIAL QUANTITY: **2100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **62**  
MATERIAL DESCRIPTION: **9"x9" Brown w/Streaks VFT NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Rm. 356 NOT OBSERVED**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/16/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **62**  
MATERIAL DESCRIPTION: **9"x9" Brown w/Streaks VFT NOT OBSERVED**  
MATERIAL LOCATION: **Rm. 356 NOT OBSERVED**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **64**  
MATERIAL DESCRIPTION: **12"x12" Light Brown w/ White Streaks VFT (Not Observed)**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Rooms 100, 106, & 106 Office - 1931**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 03/16/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUILDING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **64**  
MATERIAL DESCRIPTION: **12"x12" Light Brown w/ White Streaks VFT (Not Observed)**  
MATERIAL LOCATION: **Rooms 100, 106, & 106 Office - 1931**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **65**  
MATERIAL DESCRIPTION: **12"x12" Light Brown w/ White Streaks VFT Mastic (Not Observed)**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Rooms 100, 106, & 106 Office - 1931**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/16/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUILDING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **65**  
MATERIAL DESCRIPTION: **12"x12" Light Brown w/ White Streaks VFT Mastic (Not Observed)**  
MATERIAL LOCATION: **Rooms 100, 106, & 106 Office - 1931**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **66**  
MATERIAL DESCRIPTION: **9"x9" Black VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **3rd Floor Hall (S&N), 2nd Floor Hall (N) -1931 Bldg.**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 03/16/2016

# Chicago Public Schools

GSG Consultants, Inc.

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **66**  
MATERIAL DESCRIPTION: **9"x9" Black VFT**  
MATERIAL LOCATION: **3rd Floor Hall (S&N), 2nd Floor Hall (N) -1931 Bldg.**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **67**  
MATERIAL DESCRIPTION: **9"x9" Black VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **3rd Floor Hall (S&N), 2nd Floor Hall (N) -1931 Bldg.**

MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 03/16/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **67**  
MATERIAL DESCRIPTION: **9"x9" Black VFT Mastic**  
MATERIAL LOCATION: **3rd Floor Hall (S&N), 2nd Floor Hall (N) -1931 Bldg.**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **68**  
MATERIAL DESCRIPTION: **9"x9" Black w/Large White Streaks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **3rd Floor Hall (S&N) - 1931**

MATERIAL QUANTITY: **2000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/16/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **68**  
MATERIAL DESCRIPTION: **9"x9" Black w/Large White Streaks VFT**  
MATERIAL LOCATION: **3rd Floor Hall (S&N) - 1931**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **69**  
MATERIAL DESCRIPTION: **9"x9" Black w/Large White Streaks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **3rd Floor Hall (S&N) - 1931**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 03/16/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **69**  
MATERIAL DESCRIPTION: **9"x9" Black w/Large White Streaks VFT Mastic**  
MATERIAL LOCATION: **3rd Floor Hall (S&N) - 1931**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **70**  
MATERIAL DESCRIPTION: **9"x9" Brown w/Large White Streaks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **3rd Floor Hall (S&N), 2nd Floor Hall (N) -1931 Bldg.**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 03/16/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **70**  
MATERIAL DESCRIPTION: **9"x9" Brown w/Large White Streaks VFT**  
MATERIAL LOCATION: **3rd Floor Hall (S&N), 2nd Floor Hall (N) -1931 Bldg.**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **71**  
MATERIAL DESCRIPTION: **9"x9" Brown w/Large White Streaks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **3rd Floor Hall (S&N), 2nd Floor Hall (N) -1931 Bldg.**

MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 03/16/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUILDING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **71**  
MATERIAL DESCRIPTION: **9"x9" Brown w/Large White Streaks VFT Mastic**  
MATERIAL LOCATION: **3rd Floor Hall (S&N), 2nd Floor Hall (N) -1931 Bldg.**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **72**  
MATERIAL DESCRIPTION: **9"x9" Orange w/White VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON: **Deterioration**  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Deterioration**  
DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **3rd Floor Hall (S&N), 2nd Floor Hall (S) -1931 Bldg.**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY:  DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 03/16/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **72**  
MATERIAL DESCRIPTION: **9"x9" Orange w/White VFT**  
MATERIAL LOCATION: **3rd Floor Hall (S&N), 2nd Floor Hall (S) -1931 Bldg.**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **73**  
MATERIAL DESCRIPTION: **9"x9" Orange w/White Streaks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **3rd Floor Hall (S&N), 2nd Floor Hall (S) -1931 Bldg.**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 03/16/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **73**  
MATERIAL DESCRIPTION: **9"x9" Orange w/White Streaks VFT Mastic**  
MATERIAL LOCATION: **3rd Floor Hall (S&N), 2nd Floor Hall (S) -1931 Bldg.**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **76**  
MATERIAL DESCRIPTION: **9"x9" Maroon w/ White Streaks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **2nd Floor Hall (S) -1931 Bldg.**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/16/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **76**  
MATERIAL DESCRIPTION: **9"x9" Maroon w/ White Streaks VFT**  
MATERIAL LOCATION: **2nd Floor Hall (S) -1931 Bldg.**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **77**  
MATERIAL DESCRIPTION: **9"x9" Maroon w/ White Streaks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **2nd Floor Hall (S) -1931 Bldg.**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/16/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **77**  
MATERIAL DESCRIPTION: **9"x9" Maroon w/ White Streaks VFT Mastic**  
MATERIAL LOCATION: **2nd Floor Hall (S) -1931 Bldg.**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **78**  
MATERIAL DESCRIPTION: **9"x9" Black w/ Faint White Streaks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **2nd & 3rd Floor Halls (N&S) - 1931**  
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/16/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **78**  
MATERIAL DESCRIPTION: **9"x9" Black w/ Faint White Streaks VFT**  
MATERIAL LOCATION: **2nd & 3rd Floor Halls (N&S) - 1931**  
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **79**  
MATERIAL DESCRIPTION: **9"x9" Black w/ Faint White Streaks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **2nd & 3rd Floor Halls (N&S) - 1931**  
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 03/16/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **79**  
MATERIAL DESCRIPTION: **9"x9" Black w/ Faint White Streaks VFT Mastic**  
MATERIAL LOCATION: **2nd & 3rd Floor Halls (N&S) - 1931**  
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **80**  
MATERIAL DESCRIPTION: **12"x12" White w/ Brown Speckles VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Room 341 & 213 - 1931**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/16/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **80**  
MATERIAL DESCRIPTION: **12"x12" White w/ Brown Speckles VFT**  
MATERIAL LOCATION: **Room 341 & 213 - 1931**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **81**  
MATERIAL DESCRIPTION: **12"x12" White w/ Brown Speckles VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Room 341 & 213 - 1931**

MATERIAL QUANTITY: **1200**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/16/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUILDING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **81**  
MATERIAL DESCRIPTION: **12"x12" White w/ Brown Speckles VFT Mastic**  
MATERIAL LOCATION: **Room 341 & 213 - 1931**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **86**  
MATERIAL DESCRIPTION: **12"x12" Brown w/ Light Brown Speckles VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Room 239 - 1931**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 03/16/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUILDING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **86**  
MATERIAL DESCRIPTION: **12"x12" Brown w/ Light Brown Speckles VFT**  
MATERIAL LOCATION: **Room 239 - 1931**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **87**  
MATERIAL DESCRIPTION: **12"x12" Brown w/ Light Brown Speckles VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 239 - 1931**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/16/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **87**  
MATERIAL DESCRIPTION: **12"x12" Brown w/ Light Brown Speckles VFT Mastic**  
MATERIAL LOCATION: **Room 239 - 1931**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **88**  
MATERIAL DESCRIPTION: **Brown Linoleum**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **238 North Storage - 1931**

MATERIAL QUANTITY: **250**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/16/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **88**  
MATERIAL DESCRIPTION: **Brown Linoleum**  
MATERIAL LOCATION: **238 North Storage - 1931**  
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **89**  
MATERIAL DESCRIPTION: **Green Linoleum (Not Observed)**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Main Gym, Office & Locker - 1931**  
MATERIAL QUANTITY: **5500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/16/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **89**  
MATERIAL DESCRIPTION: **Green Linoleum (Not Observed)**  
MATERIAL LOCATION: **Main Gym, Office & Locker - 1931**  
MATERIAL QUANTITY: **5500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **90**  
MATERIAL DESCRIPTION: **12"x12" Peach w/ Speckles VFT- NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 352, 379, 350 Storage - 1912**  
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/16/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUILDING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **90**  
MATERIAL DESCRIPTION: **12"x12" Peach w/ Speckles VFT- NOT OBSERVED**  
MATERIAL LOCATION: **Rooms 352, 379, 350 Storage - 1912**  
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **91**  
MATERIAL DESCRIPTION: **12"x12" Peach w/ Speckles VFT Mastic- NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 352, 379, 350 Storage - 1912**

MATERIAL QUANTITY: **700**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/16/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **91**  
MATERIAL DESCRIPTION: **12"x12" Peach w/ Speckles VFT Mastic- NOT OBSERVED**  
MATERIAL LOCATION: **Rooms 352, 379, 350 Storage - 1912**  
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **92**  
MATERIAL DESCRIPTION: **12"x12" Light Brown w/ Dark Speckles VFT- NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 355, 373, 375 - 1912**  
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/16/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **92**  
MATERIAL DESCRIPTION: **12"x12" Light Brown w/ Dark Speckles VFT- NOT OBSERVED**  
MATERIAL LOCATION: **Room 355, 373, 375 - 1912**  
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **93**  
MATERIAL DESCRIPTION: **12"x12" Light Brown w/ Dark Speckles VFT Mastic- NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 355, 373, 375 - 1912**

MATERIAL QUANTITY: **700**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/16/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **93**  
MATERIAL DESCRIPTION: **12"x12" Light Brown w/ Dark Speckles VFT Mastic- NOT OBSERVED**  
MATERIAL LOCATION: **Room 355, 373, 375 - 1912**  
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **94**  
MATERIAL DESCRIPTION: **12"x12" Beige w/ Dark Speckles VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **3rd Floor Corridors, 364 Storage, 223, 221, 117B - 1912**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **Not Observed: Room 223, 117B, 3rd Floor Corridor**

Inspector's Signature: \_\_\_\_\_



Date: 03/16/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUILDING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **94**  
MATERIAL DESCRIPTION: **12"x12" Beige w/ Dark Speckles VFT**  
MATERIAL LOCATION: **3rd Floor Corridors, 364 Storage, 223, 221, 117B - 1912**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **95**  
MATERIAL DESCRIPTION: **12"x12" Beige w/ Dark Speckles VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **3rd Floor Corridors, 364 Storage, 223, 221, 117B - 1912**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **Not Observed: Room 223, 117B, 3rd Floor Corridor**

Inspector's Signature: \_\_\_\_\_



Date: 03/16/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUILDING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **95**  
MATERIAL DESCRIPTION: **12"x12" Beige w/ Dark Speckles VFT Mastic**  
MATERIAL LOCATION: **3rd Floor Corridors, 364 Storage, 223, 221, 117B - 1912**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **96**  
MATERIAL DESCRIPTION: **12"x12" DK Brown w/White & Dark Streaks VFT- NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **3rd Floor Corridors, 223, 221, 117B - 1912**  
MATERIAL QUANTITY: **1900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 03/16/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **96**  
MATERIAL DESCRIPTION: **12"x12" DK Brown w/White & Dark Streaks VFT- NOT OBSERVED**  
MATERIAL LOCATION: **3rd Floor Corridors, 223, 221, 117B - 1912**  
MATERIAL QUANTITY: **1900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **97**  
MATERIAL DESCRIPTION: **12"x12" DK Brown w/White & Dark Streaks VFT Mastic- NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **3rd Floor Corridors, 223, 221, 117B - 1912**

MATERIAL QUANTITY: **1900**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/16/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **97**  
MATERIAL DESCRIPTION: **12"x12" DK Brown w/White & Dark Streaks VFT Mastic- NOT OBSERVED**  
MATERIAL LOCATION: **3rd Floor Corridors, 223, 221, 117B - 1912**  
MATERIAL QUANTITY: **1900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **98**  
MATERIAL DESCRIPTION: **12"x12" Black w/ White Speckles VFT- NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **3rd Floor Corridor (N) - 1912**  
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/16/2016**

# Chicago Public Schools

GSG Consultants, Inc.

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUILDING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **98**  
MATERIAL DESCRIPTION: **12"x12" Black w/ White Speckles VFT- NOT OBSERVED**  
MATERIAL LOCATION: **3rd Floor Corridor (N) - 1912**  
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **99**  
MATERIAL DESCRIPTION: **12"x12" Black w/ White Speckles VFT Mastic- NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **3rd Floor Corridor (N) - 1912**  
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/16/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **99**  
MATERIAL DESCRIPTION: **12"x12" Black w/ White Speckles VFT Mastic- NOT OBSERVED**  
MATERIAL LOCATION: **3rd Floor Corridor (N) - 1912**  
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **AA**  
MATERIAL DESCRIPTION: **12"x 12" green floor tile- NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **3rd floor, side corridor, East to West navy areas**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/16/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **AA**  
MATERIAL DESCRIPTION: **12"x 12" green floor tile- NOT OBSERVED**  
MATERIAL LOCATION: **3rd floor, side corridor, East to West navy areas**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **BB**  
MATERIAL DESCRIPTION: **Mastic associated with HA AA - NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **3rd floor, side corridor, East to West navy areas - NOT OBSERVED**  
MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/16/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **BB**  
MATERIAL DESCRIPTION: **Mastic associated with HA AA - NOT OBSERVED**  
MATERIAL LOCATION: **3rd floor, side corridor, East to West navy areas - NOT OBSERVED**  
MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **CC**  
MATERIAL DESCRIPTION: **Lab counter tops**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **classrooms 100, 106, 108, 110, 302, 310, 350**  
MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/16/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **CC**  
MATERIAL DESCRIPTION: **Lab counter tops**  
MATERIAL LOCATION: **classrooms 100, 106, 108, 110, 302, 310, 350**  
MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **DD**  
MATERIAL DESCRIPTION: **Lab tables**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Classrooms, 110, 302, 310, 350**  
MATERIAL QUANTITY: **2600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 03/16/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **DD**  
MATERIAL DESCRIPTION: **Lab tables**  
MATERIAL LOCATION: **Classrooms, 110, 302, 310, 350**  
MATERIAL QUANTITY: **2600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **EE**  
MATERIAL DESCRIPTION: **lab fume hoods**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Classrooms 100,106, 350**  
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 03/16/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUIDLING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

HOMOGENEOUS AREA: **EE**  
MATERIAL DESCRIPTION: **lab fume hoods**  
MATERIAL LOCATION: **Classrooms 100,106, 350**  
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **47061**    BUILDING ID: **1540**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy**    INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood**    IDPH LICENSE NO: **100-11093**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **175**  
MATERIAL DESCRIPTION: **12x12 Blue speckled VFT**  
MATERIAL LOCATION: **3rd Floor NW & W corridor, 2nd floor W & center corridor**  
MATERIAL QUANTITY: **1000**    MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**    FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**    CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**    DAMAGE REASON:  
DAMAGE QUANTITY: **0**    DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 03/16/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUILDING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **175**  
MATERIAL DESCRIPTION: **12x12 Blue speckled VFT**  
MATERIAL LOCATION: **3rd Floor NW & W corridor, 2nd floor W & center corridor**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: 05/13/2016



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **47061**    BUILDING ID: **1540**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy**    INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood**    IDPH LICENSE NO: **100-11093**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **187**  
MATERIAL DESCRIPTION: **12x12 Yellow w/streaks VFT**  
MATERIAL LOCATION: **Health center (144)**  
MATERIAL QUANTITY: **400**    MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**    FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **MODERATE**    CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**    DAMAGE REASON:  
DAMAGE QUANTITY: **0**    DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: **03/16/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUILDING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **187**  
MATERIAL DESCRIPTION: **12x12 Yellow w/streaks VFT**  
MATERIAL LOCATION: **Health center (144)**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: **05/13/2016**

# Chicago Public Schools

GSG Consultants, Inc.

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **47061**      BUILDING ID: **1540**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy**      INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood**      IDPH LICENSE NO: **100-11093**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **189**  
MATERIAL DESCRIPTION: **12x12 Green w/ streaks VFT**  
MATERIAL LOCATION: **Health center (144)**  
MATERIAL QUANTITY: **200**      MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**      FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **MODERATE**      CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**      DAMAGE REASON:  
DAMAGE QUANTITY: **0**      DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature:



Date: **03/16/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUILDING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **189**  
MATERIAL DESCRIPTION: **12x12 Green w/ streaks VFT**  
MATERIAL LOCATION: **Health center (144)**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **47061**      BUILDING ID: **1540**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy**      INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood**      IDPH LICENSE NO: **100-11093**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **195**  
MATERIAL DESCRIPTION: **12x12 Maroon w/ pink specks VFT**  
MATERIAL LOCATION: **Room 115**  
MATERIAL QUANTITY: **200**      MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**      FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **MODERATE**      CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**      DAMAGE REASON:  
DAMAGE QUANTITY: **0**      DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 03/16/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **47061**      BUILDING ID: **1540**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy**      REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood**      IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **195**  
MATERIAL DESCRIPTION: **12x12 Maroon w/ pink specks VFT**  
MATERIAL LOCATION: **Room 115**  
MATERIAL QUANTITY: **200**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:       Date: **05/13/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **47061**    BUILDING ID: **1540**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy**    INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood**    IDPH LICENSE NO: **100-11093**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **176**  
MATERIAL DESCRIPTION: **12x12 Blue speckled VFT Mastic**  
MATERIAL LOCATION: **3rd Floor NW & W corridor, 2nd floor W & center corridor**  
MATERIAL QUANTITY: **1000**    MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**    FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**    CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Barely Reachable**    DAMAGE REASON:  
DAMAGE QUANTITY: **0**    DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 03/16/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUILDING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **176**  
MATERIAL DESCRIPTION: **12x12 Blue speckled VFT Mastic**  
MATERIAL LOCATION: **3rd Floor NW & W corridor, 2nd floor W & center corridor**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: 05/13/2016



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **47061**    BUILDING ID: **1540**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy**    INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood**    IDPH LICENSE NO: **100-11093**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **178**  
MATERIAL DESCRIPTION: **12x12 Light Blue w/ Specks VFT Mastic**  
MATERIAL LOCATION: **3rd Floor NW & W corridor, 2nd floor W & center corridor -1911 Bldg**  
MATERIAL QUANTITY: **8000**    MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**    FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **MODERATE**    CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Barely Reachable**    DAMAGE REASON:  
DAMAGE QUANTITY: **0**    DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 03/16/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUILDING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **178**  
MATERIAL DESCRIPTION: **12x12 Light Blue w/ Specks VFT Mastic**  
MATERIAL LOCATION: **3rd Floor NW & W corridor, 2nd floor W & center corridor -1911 Bldg**  
MATERIAL QUANTITY: **8000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: 05/13/2016



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUILDING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **182**  
MATERIAL DESCRIPTION: **Gray linoleum w/ granite pattern Mastic**  
MATERIAL LOCATION: **Room 100**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUILDING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **190**  
MATERIAL DESCRIPTION: **12x12 Green w/ streaks VFT Mastic**  
MATERIAL LOCATION: **Health center (144)**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: 05/13/2016



# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **47061**      BUILDING ID: **1540**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy**      REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood**      IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **181**  
MATERIAL DESCRIPTION: **Gray linoleum w/ granite pattern**  
MATERIAL LOCATION: **Room 100**  
MATERIAL QUANTITY: **1200**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:       Date: **05/13/2016**



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **47061**    BUILDING ID: **1540**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy**    INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood**    IDPH LICENSE NO: **100-11093**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **185**  
MATERIAL DESCRIPTION: **12x12 Red w/ streaks VFT**  
MATERIAL LOCATION: **Health center (144)**  
MATERIAL QUANTITY: **400**    MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**    FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **MODERATE**    CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Barely Reachable**    DAMAGE REASON:  
DAMAGE QUANTITY: **0**    DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 03/16/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUILDING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **185**  
MATERIAL DESCRIPTION: **12x12 Red w/ streaks VFT**  
MATERIAL LOCATION: **Health center (144)**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: **05/13/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **47061**    BUILDING ID: **1540**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy**    INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood**    IDPH LICENSE NO: **100-11093**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **191**  
MATERIAL DESCRIPTION: **12x12 Dark gray linoleum w/ granite pattern**  
MATERIAL LOCATION: **Main office (131-134)**  
MATERIAL QUANTITY: **2000**    MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**    FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **MODERATE**    CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**    DAMAGE REASON:  
DAMAGE QUANTITY: **0**    DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 03/16/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUILDING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **191**  
MATERIAL DESCRIPTION: **12x12 Dark gray linoleum w/ granite pattern**  
MATERIAL LOCATION: **Main office (131-134)**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **47061**    BUILDING ID: **1540**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy**    INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood**    IDPH LICENSE NO: **100-11093**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **193**  
MATERIAL DESCRIPTION: **12x12 Pink w/ maroon specks VFT**  
MATERIAL LOCATION: **Room 115**  
MATERIAL QUANTITY: **1200**    MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**    FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **MODERATE**    CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**    DAMAGE REASON:  
DAMAGE QUANTITY: **0**    DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 03/16/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUILDING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **193**

MATERIAL DESCRIPTION: **12x12 Pink w/ maroon specks VFT**

MATERIAL LOCATION: **Room 115**

MATERIAL QUANTITY: **1200**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **47061**    BUILDING ID: **1540**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy**    INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood**    IDPH LICENSE NO: **100-11093**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **194**  
MATERIAL DESCRIPTION: **12x12 Pink w/ maroon specks VFT Mastic**  
MATERIAL LOCATION: **Room 115**  
MATERIAL QUANTITY: **1200**    MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**    FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**    CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Barely Reachable**    DAMAGE REASON:  
DAMAGE QUANTITY: **0**    DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature:



Date: **03/16/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUILDING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **194**  
MATERIAL DESCRIPTION: **12x12 Pink w/ maroon specks VFT Mastic**  
MATERIAL LOCATION: **Room 115**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: **05/13/2016**



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUILDING ID: **1540**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy** INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **179**  
MATERIAL DESCRIPTION: **12x12 Gray w/streaks VFT**  
MATERIAL LOCATION: **Room 221**  
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC** FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **MODERATE** CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach** DAMAGE REASON:  
DAMAGE QUANTITY: **0** DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature:



Date: **03/16/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUILDING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **179**  
MATERIAL DESCRIPTION: **12x12 Gray w/streaks VFT**  
MATERIAL LOCATION: **Room 221**  
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: **05/13/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **47061**    BUILDING ID: **1540**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy**    INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood**    IDPH LICENSE NO: **100-11093**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **177**  
MATERIAL DESCRIPTION: **12x12 Light Blue w/ Specks VFT**  
MATERIAL LOCATION: **3rd Floor NW & W corridor, 2nd floor W & center corridor -1911 Bldg**  
MATERIAL QUANTITY: **8000**    MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**    FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **MODERATE**    CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**    DAMAGE REASON:  
DAMAGE QUANTITY: **0**    DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 03/16/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **47061**      BUILDING ID: **1540**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy**      REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood**      IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **177**  
MATERIAL DESCRIPTION: **12x12 Light Blue w/ Specks VFT**  
MATERIAL LOCATION: **3rd Floor NW & W corridor, 2nd floor W & center corridor -1911 Bldg**  
MATERIAL QUANTITY: **8000**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: 05/13/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **47061**      BUILDING ID: **1540**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy**      INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood**      IDPH LICENSE NO: **100-11093**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **183**  
MATERIAL DESCRIPTION: **Gray linoleum**  
MATERIAL LOCATION: **Rooms 105, 105A, 110**  
MATERIAL QUANTITY: **2400**      MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**      FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **MODERATE**      CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**      DAMAGE REASON:  
DAMAGE QUANTITY: **0**      DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 03/16/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUILDING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **183**  
MATERIAL DESCRIPTION: **Gray linoleum**  
MATERIAL LOCATION: **Rooms 105, 105A, 110**  
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **47061**      BUILDING ID: **1540**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy**      INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood**      IDPH LICENSE NO: **100-11093**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **196**  
MATERIAL DESCRIPTION: **12x12 Maroon w/ pink specks VFT Mastic**  
MATERIAL LOCATION: **Room 115**  
MATERIAL QUANTITY: **200**      MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**      FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**      CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Barely Reachable**      DAMAGE REASON:  
DAMAGE QUANTITY: **0**      DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 03/16/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUILDING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **196**

MATERIAL DESCRIPTION: **12x12 Maroon w/ pink specks VFT Mastic**

MATERIAL LOCATION: **Room 115**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **47061**    BUILDING ID: **1540**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy**    INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood**    IDPH LICENSE NO: **100-11093**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **184**  
MATERIAL DESCRIPTION: **Gray linoleum Mastic**  
MATERIAL LOCATION: **Rooms 105, 105A, 110**  
MATERIAL QUANTITY: **2400**    MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**    FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**    CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Barely Reachable**    DAMAGE REASON:  
DAMAGE QUANTITY: **0**    DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 03/16/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUILDING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **184**  
MATERIAL DESCRIPTION: **Gray linoleum Mastic**  
MATERIAL LOCATION: **Rooms 105, 105A, 110**  
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: **05/13/2016**



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUILDING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **188**  
MATERIAL DESCRIPTION: **12x12 Yellow w/streaks VFT Mastic**  
MATERIAL LOCATION: **Health center (144)**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: 05/13/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **47061**    BUILDING ID: **1540**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy**    INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood**    IDPH LICENSE NO: **100-11093**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **192**  
MATERIAL DESCRIPTION: **12x12 Dark gray linoleum w/ granite pattern Mastic**  
MATERIAL LOCATION: **Main office (131-134)**  
MATERIAL QUANTITY: **2000**    MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**    FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**    CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Barely Reachable**    DAMAGE REASON:  
DAMAGE QUANTITY: **0**    DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature:



Date: **03/16/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUILDING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **192**  
MATERIAL DESCRIPTION: **12x12 Dark gray linoleum w/ granite pattern Mastic**  
MATERIAL LOCATION: **Main office (131-134)**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: **05/13/2016**



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUILDING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **180**  
MATERIAL DESCRIPTION: **12x12 Gray w/streaks VFT Mastic**  
MATERIAL LOCATION: **Room 221**  
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: **05/13/2016**



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **47061**      BUILDING ID: **1540**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **David Avila**  
SCHOOL NAME: **Senn Academy**      INSPECTION DATE: **3/16/2016**  
ADDRESS: **5900 N. Glenwood**      IDPH LICENSE NO: **100-11093**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **186**  
MATERIAL DESCRIPTION: **12x12 Red w/specks VFT Mastic**  
MATERIAL LOCATION: **Health center (144)**  
MATERIAL QUANTITY: **400**      MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**      FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**      CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Barely Reachable**      DAMAGE REASON:  
DAMAGE QUANTITY: **0**      DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 03/16/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47061** BUILDING ID: **1540**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**  
SCHOOL NAME: **Senn Academy** REVIEW DATE: **5/13/2016**  
ADDRESS: **5900 N. Glenwood** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **186**  
MATERIAL DESCRIPTION: **12x12 Red w/specks VFT Mastic**  
MATERIAL LOCATION: **Health center (144)**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: **05/13/2016**

# APPENDIX B

## Inspector and Management Planner Licenses

---

# CERTIFICATE OF ACHIEVEMENT ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that DAVID AVILA  
has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the  
examination on 02/13/2016 with a minimum score of 70% or better. Training was in accordance  
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:  
Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.

02/13/2016

Course Dates:

02/13/2017

Expires:

1602BTR08

Certificate Number:



A handwritten signature in black ink, appearing to read "N. Peneff".

Director of Training  
Nicholas J. Peneff  
Doctor of Public Health

Phone: 312-491-0081

FORM # A-010B

# CERTIFICATE OF ACHIEVEMENT ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that GUILLERMO GARCIA  
has completed the Asbestos Management Planner Refresher course and passed the examination  
on 03/21/2016 with a minimum score of 70% or better. Training was in accordance with U.S.  
E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools: Model  
Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.

03/21/2016

Course Dates:

03/21/2017

Expires:

1603MPR02

Certificate Number:



**PUBLIC HEALTH & SAFETY** inc.

Environmental and Occupational Services  
105 S. Ashland Ave., Chicago, IL 60607

*Nicholas J. Penoff*

Director of Training

Nicholas J. Penoff

Doctor of Public Health

Phone: 312-491-0081

FORM # A-011





525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • [www.dph.illinois.gov](http://www.dph.illinois.gov)

4/20/2016

**GUILLERMO GARCIA**  
 855 W ADAMS ST SUITE 100  
 CHICAGO, IL 60607

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 01786

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

**COPY OF THE ASBESTOS PROFESSIONAL LICENSE**

Front of License

Back of License

| Front of License  |                             |                               | Back of License  |                                 |
|---|-----------------------------|-------------------------------|--|---------------------------------|
|  <p><b>ASBESTOS PROFESSIONAL LICENSE</b></p>               |                             |                               | <p><b>ENDORSEMENTS</b></p>   |                                 |
| <p>ID NUMBER<br/>100 - 01733</p>  | <p>ISSUED<br/>4/20/2016</p> | <p>EXPIRES<br/>05/15/2017</p> | <p>INSPECTOR</p>   | <p>TC EXPIRES<br/>3/21/2017</p> |
| <p><b>GUILLERMO GARCIA</b><br/>           855 W ADAMS ST SUITE 100<br/>           CHICAGO, IL 60607<br/>           Environmental Health</p> |                             |                               | <p>MANAGEMENT PLANNER</p>  | <p>3/21/2017</p>                |
|   |                             |                               | <p>PROJECT MANAGER</p>   | <p>2/6/2017</p>                 |
|   |                             |                               | <p>AIR SAMPLING PROFESSIONAL</p>   |                                 |
|   |                             |                               | <p><b>Alteration of this license shall result in legal action</b><br/>           This license issued under authority of the State of Illinois<br/>           Department of Public Health<br/>           This license is valid only when accompanied by a valid<br/>           training course certificate.</p> |                                 |

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: [dph.illinois.gov/topics-services/environmental-health-protection/asbestos](http://dph.illinois.gov/topics-services/environmental-health-protection/asbestos)  
 EMAIL Address: [dph.asbestos@illinois.gov](mailto:dph.asbestos@illinois.gov)

**PROTECTING HEALTH, IMPROVING LIVES**  
*Nationally Accredited by PHAB*

# APPENDIX C

## Laboratory Accreditations

---

# APPENDIX D

## Laboratory Results

---



# APPENDIX E

## Chain of Custody Forms

---

## Three-Year Reinspection Key to Terms

|                          | <b>CODE</b> | <b>KEY</b>                             |
|--------------------------|-------------|--|
| <b>MATERIAL</b>          |             |  |
|                          | ACBM        | Asbestos Containing Building Materials |
| <b>MATERIAL CATEGORY</b> |             |  |
|                          | MISC        | Miscellaneous                          |
|                          | SURF        | Surfacing                              |
|                          | TSI         | Thermal System Insulation              |
| <b>MATERIAL UNITS</b>    |             |  |
|                          | LF          | Linear Feet                            |
|                          | SF          | Square Feet                            |
|                          | CF          | Cubic Feet                             |
| <b>DAMAGE TYPE</b>       |             |  |
|                          | Loc         | Localized                              |
|                          | Dist        | Distributed                            |