

ILLINOIS DEPARTMENT OF PUBLIC HEALTH  
AHERA THREE YEAR REINSPECTION  
ASBESTOS ABATEMENT PROGRAM  
SCHOOL INFORMATION FORM

**SECTION I**

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299  
SCHOOL ID NUMBER: 14-016-2990-0764  
SCHOOL NAME: Whitney Young Magnet High School  
ADDRESS OF SCHOOL: 211 S. Laflin  
CITY: Chicago, IL, 60607

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **3/8/2013**

**If the address on this form is different than the address of the building, submit a written explanation.**

**SECTION II** (Please type or print)

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 6/2/2016 ENROLLMENT 2107  
IDPH INSPECTOR LICENSE NUMBER: 100-09969  
IDPH LICENSED INSPECTOR NAME (Please Print): Dionne Carey  
IDPH MP LICENSE NUMBER: 100-03613  
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Daniel Juneau

DESIGNATED PERSON (Please Print): Robert Christlieb PHONE: (773) 553-3197



6/2/2016

Signature of Designated Person

Date

**SECTION III**

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: \_\_\_\_\_

School has been closed. Date closed: \_\_\_\_\_

School building has been demolished. Date: \_\_\_\_\_

School building is asbestos free since last reinspection: \_\_\_\_\_

**Please explain in writing why the school building is now asbestos free and include the supporting documentation.**

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

**Explain in writing if the address of the building is different than the address on this form:**

**THREE-YEAR REINSPECTION**

**CHICAGO SCHOOL DIST 299**

**Whitney Young Magnet High School**

211 S. Laflin  
Chicago, IL, 60607

Unit: 47101  
Building ID: 1810

IDPH ID Number: 14-016-2990-0764

**REPORT DATE:**

Thursday, June 02, 2016

**Prepared for:**

**Chicago Public Schools  
125 S. Clark Street  
Chicago, IL 60603**

**Prepared by:**

**Carnow, Conibear and Associates**

600 West Van Buren St., Ste 500

Phone (312) 762-2900

Fax (312) 782-5145

**DO NOT REMOVE FROM SCHOOL  
REQUIRED BY FEDERAL LAW**

May 9, 2016

Mr. R. Kent Cook  
Asbestos Program  
Illinois Department of Public Health  
525 West Jefferson Street  
Springfield, Illinois 62761

Re: Chicago Public Schools - 2016 Three-Year Reinspections

Dear Mr. Cook:

Carnow, Conibear and Associates, Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 3,4,5 Elementary Schools. Please update your records with the following information.

School District: 299            Unit: 47101            Region: 03            IDPH ID: 14-016-2990-0764

School: Whitney Young Magnet High School            Building ID: 1810

Address: 211 S. Laflin

Chicago, IL, 60607

Building Contact: Troche, Nathan

Contact Phone: 773-763-6091

Current Building Owners: Chicago Public Schools

Review Date: 06/02/2016

Inspector: Dionne Carey

Inspector IDPH License: 100-09969

Management Planner: Daniel Juneau

Management Planner IDPH License: 100-03613

If you have any questions or comments, please contact us at (312) 762-2900

Sincerely,  
Carnow, Conibear and Associates



Daniel Juneau  
100-03613

## **Environmental Notification to Occupants**

To: Faculty, Staff and Parents  
From: Chicago Public Schools  
Date: May 09, 2016

RE: Whitney Young Magnet High School, Unit 47101  
211 S. Laflin  
Chicago, IL, 60607

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2016 asbestos three year re-inspection has been completed at Whitney Young Magnet High School , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at Whitney Young Magnet High School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Robert Christlieb, the designated Local Education Authority's Designated Person at (773) 553-3197 .

## **Table of Contents**

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

### **APPENDICES:**

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

## SCHOOL AND INSPECTION INFORMATION

### 1. School Information

School: Whitney Young Magnet High School  
Address: 211 S. Laflin  
IDPH ID: 14-016-2990-0764  
Contact: Troche, Nathan

Unit: 47101  
Chicago, IL, 60607  
Building ID: 1810  
Phone: 773-763-6091

Region: 03

### 2. Description of Facility

Original Construction: 1975  
Total Square Footage:  
Current Occupancy: 2107

Additional Construction: 1975,1975  
No of Floors:

### 3. LEA Designated Person

Contact: Robert Christlieb  
Address: 125 South Clark Street, 17th Floor  
Chicago, IL 60603

Phone: (773) 553-3197

### 4. Managing Environmental Consultant


MEC: Carnow, Conibear and Associates  
Contact: Dan Juneau  
Address 600 West Van Buren St., Ste 500  
Phone: (312) 762-2900

Fax: (312) 782-5145

### 5. Inspector

Inspector Name: Dionne Carey


Inspector IDPH license # 100-09969

Signature:   
Date: 5/9/2016

### 6. Management Planner

Management Planner Name: Daniel Juneau

Management Planner IDPH license # 100-03613

Signature:   
Date: 06/02/2016

### 7. Review Date: 06/02/2016

### 8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature: 

Date: 6/2/2016

Name: Robert Christlieb

## II. EXECUTIVE SUMMARY

Carnow, Conibear and Associates was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Whitney Young Magnet High School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 1810:

153	2' x 4' Ceiling Tile
174	Laminate Roll Adhesive
175	Wood Glue Over Existing
176	Terrazo
177	Ceramic Grout
80	12" x 12" Light Beige w/Light Brown Mastic
U	Joint Compound Off Preformed Pipe Insulation

B. The following new homogenous areas have been identified for Building 1810:

174	Laminate Roll Adhesive
175	Wood Glue Over Existing
176	Terrazo
177	Ceramic Grout



C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

107	12" x 12" Black Streaks Floor Tile
117	12" x 12" Lt brown with dark brown and white Floor Tile
119	12"x12" Dark Ash w/Mud Brown Specks Floor Tile
11B	Expansion Filler Material
12B	Fire Door Insulation
130	Roofing Material (Non AHERA)
131	Roofing Material NON-AHERA
133	12"x12" Soft Beige Floor Tile w/Large Brown Specks
136	Wavy Beige Linoleum
137	Wavy Beige Linoleum Mastic
138	12" x 12" Off White w/Brown Streaks Floor Tile
139	12" x 12" Off White w/Brown Streaks FT Mastic
140	12" x 12" Tan w/Lt. Brown Mix Floor Tile
141	12" x 12" Tan w/Lt. Brown Mix Floor Tile Mastic
142	12" x 12" Red w/Tan Specks Floor Tile
143	12" x 12" Red w/Tan Specks Floor Tile Mastic
144	12" x 12" Blue Mix Floor Tile
145	12" x 12" Blue Mix Floor Tile Mastic
146	12" x 12" Gray Mix Floor Tile
147	12" x 12" Gray Mix Floor Tile Mastic
148	12" x 12" Medium Tan Mix Floor Tile
149	12" x 12" Medium Tan Mix Floor Tile Mastic
150	12" x 12" Black w/Brown Streaks Floor Tile
151	12" x 12" Black w/Brown Streaks Floor Tile Mastic
152	Spray-on Fireproofing
153	2' x 4' Ceiling Tile
154	Tan and red Terrazzo
155	12" x 12" brown with dark brown floor tile
156	12" x 12" brown with dark brown floor tile Mastic
157	12" x 12" Tan/Brown with light brown floor tile
158	Mastic for 12" x 12" Tan/Brown with light brown floor tile
159	Safe door insulation
160	12" x 12" white with brown floor tile
161	Mastic for 12" x 12" white with brown floor tile
162	12" x 12" Blue with gray and dark blue floor tile
163	Mastic for 12" x 12" Blue with gray and dark blue floor tile
164	12" x 12" light brown floor tile
165	Mastic for 12" x 12" light brown floor tile

166	12" x 12" Light gray with dark gray and white floor tile
167	Mastic for 12" x 12" Light gray with dark gray and white floor tile
168	12" x 12" Light Blue with dark blue and white floor tile.
169	Mastic for 12" x 12" Light Blue with dark blue and white floor tile.
170	Brown Carpet Mastic
171	Rubber Floor Mastic
172	Stair Tread Covering
173	Stair Tread Covering Mastic
174	Laminate Roll Adhesive
175	Wood Glue Over Existing
176	Terrazo
177	Ceramic Grout
2	12" x 12" Black Floor Tile
24	12"x12" Off-White w/Light Brown Streaks Floor Tile
26	12" x 12" Sandy Brown & Beige Floor Tile
31	12" x 12" Pearl White Floor Tile
48	12" x 12" Dark Sandy Brown Floor Tile
50	12" x 12" Light Sandy Pink Floor Tile
57	12" x 12" Bluish-Green Floor Tile
61	12" x 12" Soft Beige w/Brown Specks Floor Tile
64	12" x 12" Dark Beige w/Reddish Brown Streaks FT
66	Dark Ash Gray Vinyl Baseboard
67	Dark Ash Gray Vinyl Baseboard Mastic
69	12x12 Light Sandy Off-White w/Lt Brown Streaks FT
7	Fire Door Insulation
71	12" x 12" Off-White & Cream w/Streaks Floor Tile
74	12" x 12" Light Pink w/Beige Streaks Floor Tile
79	Mastic 12" x 12" Brown with dark brown floor tile
84	12"x12" Light Silver w/Multiple Streaks Floor Tile
A	Breeching Insulation
W	12x12 VFT light green
W-1	12x12 VFT light green-MASTIC

The following areas were deemed to be inaccessible:

101	12" x 12" Brown & Black Floor Tile Mastic
108	12" x 12" Black Streaks Mastic
12B	Fire Door Insulation
137	Wavy Beige Linoleum Mastic
139	12" x 12" Off White w/Brown Streaks FT Mastic

143	12" x 12" Red w/Tan Specks Floor Tile Mastic
145	12" x 12" Blue Mix Floor Tile Mastic
147	12" x 12" Gray Mix Floor Tile Mastic
149	12" x 12" Medium Tan Mix Floor Tile Mastic
151	12" x 12" Black w/Brown Streaks Floor Tile Mastic
156	12" x 12" brown with dark brown floor tile Mastic
158	Mastic for 12" x 12" Tan/Brown with light brown floor tile
159	Safe door insulation
161	Mastic for 12" x 12" white with brown floor tile
163	Mastic for 12" x 12" Blue with gray and dark blue floor tile
165	Mastic for 12" x 12" light brown floor tile
167	Mastic for 12" x 12" Light gray with dark gray and white floor tile
169	Mastic for 12" x 12" Light Blue with dark blue and white floor tile.
170	Brown Carpet Mastic
171	Rubber Floor Mastic
172	Stair Tread Covering
173	Stair Tread Covering Mastic
174	Laminate Roll Adhesive
175	Wood Glue Over Existing
27	12" x 12" Sandy Brown & Beige Floor Tile Mastic
47	12" x 12" Sandy Beige w/Lt Brn Streaks FT Mastic
62	12" x 12" Soft Beige w/Brown Specks FT Mastic
67	Dark Ash Gray Vinyl Baseboard Mastic
69.1	12x12 Lt. Sandy Off-Wt w/Lt Brn Streaks FT Mastic
70	12" x 12" Off-White w/Light Brown Streaks Mastic
79	Mastic 12" x 12" Brown with dark brown floor tile
8	12" x 12" Black Floor Tile Mastic
80	12" x 12" Light Beige w/Light Brown Mastic
8B	12"x12"Light Beige FT w/Sandy Brown Streaks Mastic
K	Breeching Insulation

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Dionne Carey, IDPH License # 100-09969. The Management Plan was updated by Daniel Juneau, IDPH License # 100-03613. Inspector and Management Planner Licenses are included in Appendix B.

### **III. METHODOLOGY**

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

### **IV. ABATEMENT HISTORY**

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

### **V. REASSESSMENTS AND RECOMMENDATIONS**

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

### **VI. CONCLUSIONS**

The Whitney Young Magnet High School Building 1810 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

**Table I**  
**Inspector's Reinspection Findings**

---





# Chicago Public Schools

School Whitney Young Magnet High School Unit 47101 Building ID 1810

Address 211 S. Laflin Region 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				288 and 291										
133	12"x12" Soft Beige Floor Tile w/Large Brown Specks	750	SF	Room 179	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
134	12"x12" Soft Beige FT w/Large Brown Specks Mastic	750	SF	Building A Rooms 108, and Building C Room 179	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
135	Chocolate Partition Door Jacket			Rooms 129 and 130	NO_ACBM	MISC								
136	Wavy Beige Linoleum	950	SF	Building A - Rooms 322(Rm 324 is now combined w/ 322)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
137	Wavy Beige Linoleum Mastic	950	SF	Building A - Rooms 322(Rm 324 is now combined w/ 322)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
138	12" x 12" Off White w/Brown Streaks Floor Tile	19,720	SF	Throughout Building C - Classrooms and Corridors	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
139	12" x 12" Off White w/Brown Streaks FT Mastic	19,720	SF	Throughout Building C - Classrooms and Corridors	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
14	Mechanical Unit Vibration Isolator	10	SF	Building A - Mechanical Room by Penthouse on Roof	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
140	12" x 12" Tan w/Lt. Brown Mix Floor Tile	1,200	SF	Building A Rooms 342, and 344	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
141	12" x 12" Tan w/Lt. Brown Mix Floor Tile Mastic	1,200	SF	Building A Room 342, 344	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
142	12" x 12" Red w/Tan Specks Floor Tile	40	SF	Building C Room 184	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
143	12" x 12" Red w/Tan Specks Floor Tile Mastic	40	SF	Building C Room 184	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
144	12" x 12" Blue Mix Floor Tile	330	SF	Building C Room 190	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
145	12" x 12" Blue Mix Floor Tile Mastic	330	SF	Building C Room 190	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
146	12" x 12" Gray Mix Floor Tile	406	SF	Building C Room 190	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
147	12" x 12" Gray Mix Floor Tile Mastic	406	SF	Building C Room 190	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
148	12" x 12" Medium Tan Mix Floor Tile	6,328	SF	Building C Rooms 196, 191, 292, 297, 295, 277, 278, 279.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW



# Chicago Public Schools

School Whitney Young Magnet High School Unit 47101 Building ID 1810

Address 211 S. Laflin Region 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				280, 282										
149	12" x 12" Medium Tan Mix Floor Tile Mastic	6,328	SF	Building C Rooms 196, 191, 292, 297, 295, 277, 278, 279, 280, 282	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
15	Roof Mat Material			Building A - Roof	NO_ACBM	MISC								
150	12" x 12" Black w/Brown Streaks Floor Tile	960	SF	Building A Rooms 347 & 348	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
151	12" x 12" Black w/Brown Streaks Floor Tile Mastic	960	SF	Building A Rooms 347 & 348	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
152	Spray-on Fireproofing	450	SF	Room 050, 018, 010, 007	ASSUMED	SURFACE	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
153	2' x 4' Ceiling Tile	50,000	SF	All Corridors, Classrooms & Offices	ASSUMED	MISC	Y	NONE	0		Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
154	Tan and red Terrazzo	25,000	SF	Building A, B, and C entrances, Building A 1st floor hallway adjacent to Room 110, Auditorium and stairwells	ASSUMED	SURFACE	N	NONE	0		No	ACBM with the potential for damage		LOW
155	12" x 12" brown with dark brown floor tile	1,500	SF	Building A 1st floor Hall and Room 117	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
156	12" x 12" brown with dark brown floor tile Mastic	1,500	SF	Building A 1st floor Hall and Room 117	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
157	12" x 12" Tan/Brown with light brown floor tile	60,000	SF	Building A 1st, 2nd, and 3rd floor corridors. 105, 106, 117, 119, 127, 128, 129, 145, 200, 201, 202, 204-210, 213, 220, 301, 306, 307, 308, 309, 310, 312, 314, 315, 325, 341, 342, 345, 4C, 4D, 2C, 2F	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
158	Mastic for 12" x 12" Tan/Brown with light brown floor tile	60,000	SF	Building A 1st, 2nd, and 3rd floor corridors. 105, 106, 117, 119, 127, 128, 129, 145, 200, 201, 202, 204-210, 213, 220, 301, 306, 307,	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

# Chicago Public Schools

School Whitney Young Magnet High School Unit 47101 Building ID 1810

Address 211 S. Laflin Region 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				308, 309, 310, 312, 314, 315, 325,341, 342, 345, 4C, 4D, 2C, 2F										
159	Safe door insulation	64	SF	Building A Room 134A, Building C room 283C	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
16	RD Unit Gasket Material - Not AHERA			Building A - Roof	NO_ACBM	MISC								
160	12" x 12" white with brown floor tile	1,600	SF	Building C Rooms 290, 291	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
161	Mastic for 12" x 12" white with brown floor tile	1,600	SF	Building C Rooms 290, 291	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
162	12" x 12" Blue with gray and dark blue floor tile	400	SF	Building C Rooms 290, 291	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
163	Mastic for 12" x 12" Blue with gray and dark blue floor tile	400	SF	Building C rooms 290,291	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
164	12" x 12" light brown floor tile	800	SF	Building C Room 178	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
165	Mastic for 12" x 12" light brown floor tile	800	SF	Building C 178	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
166	12" x 12" Light gray with dark gray and white floor tile	600	SF	Building C Room 190	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
167	Mastic for 12" x 12" Light gray with dark gray and white floor tile	600	SF	Building C Room 190	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
168	12" x 12" Light Blue with dark blue and white floor tile.	200	SF	Building C Room 190	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
169	Mastic for 12" x 12" Light Blue with dark blue and white floor tile.	200	SF	Building C Room 190	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
17	Red Mix Carpet Adhesive			Building A - Engineer's Office, 3rd Floor Corridor	NO_ACBM	MISC								
170	Brown Carpet Mastic	4,800	SF	224 Library	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
171	Rubber Floor Mastic	1,100	SF	Room 050	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
172	Stair Tread Covering	350	SF	Physical Education Building by Locker Rooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
173	Stair Tread Covering Mastic	350	SF	Physical Education Building by Locker Rooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
174	Laminate Roll Adhesive	100	SF	Building C - 290 Storage	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
175	Wood Glue Over Existing	750	SF	Building A -	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the		LOW

# Chicago Public Schools

School Whitney Young Magnet High School Unit 47101 Building ID 1810

Address 211 S. Laflin Region 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				220/222 Engineer's Office								potential for damage		
176	Terrazo	5,000	SF	Building C - 1st Floor Theater	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
177	Ceramic Grout	1,000	SF	Building A - Main Office	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
18	Interior Brick			Building A	NO_ACBM	MISC								
18A	Interior Brick			Building C	NO_ACBM	MISC								
19	Interior Brick Mortar			Building A	NO_ACBM	MISC								
19A	Interior Brick Mortar			Building C	NO_ACBM	MISC								
2	12" x 12" Black Floor Tile	2,000	SF	Building A - 1st Blue House, 2nd Red House, 3rd Gold House Dining Areas	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
20	Joint Compound on Sheetrock			Building A - Engineer's Washroom, Rooms 204 and 304	NO_ACBM	TSI								
20A	Joint Compound Off Sheetrock			Building C - 293/294 Partition	NO_ACBM	TSI								
21	Brown Vinyl Baseboard			Building A - Rooms 128, 204, and 304	NO_ACBM	MISC								
21A	Brown Vinyl Baseboard			Building C - Rooms 192, 196, and 198	NO_ACBM	MISC								
22	Brown Vinyl Baseboard Mastic			Building A - Rooms 128, 204, and 304	NO_ACBM	MISC								
22A	Brown Vinyl Baseboard Mastic			Building C - Rooms 192, 196, and 198	NO_ACBM	MISC								
23	Black Sink Top Caulk			Room 320	NO_ACBM	MISC								
23A	Sink Top Bridging Caulk			Rooms 282 and 291	NO_ACBM	MISC								
24	12"x12" Off-White w/Light Brown Streaks Floor Tile	16,049	SF	Building A - Throughout 1st and 3rd Floor, Lower Level	ASSUMED	MISC	N	DIST	3,500		No	ACBM with the potential for damage	2	LOW
25	12"x12" Off-White Floor Tile w/Lt Brn Strks Mastic	16,049	SF	Building A - Throughout 1st and 3rd Floor, Lower Level	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
26	12" x 12" Sandy Brown & Beige Floor Tile	1,600	SF	Building A - Rooms 322 and 324	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
27	12" x 12" Sandy Brown & Beige Floor Tile Mastic	1,600	SF	Building A - Rooms 322(combined w/ 324)	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

# Chicago Public Schools

School Whitney Young Magnet High School Unit 47101 Building ID 1810

Address 211 S. Laflin Region 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
28	Kiln Door Backing			Building A - Room 103	NO_ACBM	MISC								
29	Kiln Interior Material			Building A - Room 103	NO_ACBM	MISC								
2B	12"x12" Lt. Beige w/Sandy Brown Streaks Floor Tile	3,588	SF	Building B - Random Basement Rooms by Corridors	CHR	MISC	N	DIST	100		No	ACBM with the potential for damage	2	LOW
30	Kiln Wiring Insulation	10	LF	Basement Storage Room	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
31	12" x 12" Pearl White Floor Tile			Room 102	ASSUMED	MISC								
32	12" x 12" Pearl White Floor Tile Mastic			Room 102	NO_ACBM	MISC								
33	Gray & Black Mix Carpet Mastic			Rooms 121 and 215	NO_ACBM	MISC								
34	Pink Mix Carpet Adhesive			Room 100	NO_ACBM	MISC								
35	Light Green Carpet Adhesive			Building A - Rooms 101, 122, and 145	NO_ACBM	MISC								
36	Light Blue Mix Carpet Mastic			Building A - Rooms 106 and 143	NO_ACBM	MISC								
37	Light Blue & Beige Mix Carpet Adhesive			Building A - By Elevator, By Room 149	NO_ACBM	MISC								
38	Light Green & Gray Mix Carpet Adhesive			205 Stage	NO_ACBM	MISC								
39	Light Green Vinyl Baseboard			Building A - By Rooms 101, 126, and 139	NO_ACBM	MISC								
40	Light Green Vinyl Baseboard Adhesive			Building A - By Rooms 101, 126, and 139	NO_ACBM	MISC								
41	12" x 12" Cream (w/Beige Streaks) Mix Floor Tile - REMOVED			Elevators	ABATED	MISC								
42	12" x 12" Cream Mix Floor Tile Mastic - ABATED			Building A - Elevators	ABATED	MISC								
43	Green Carpet Adhesive			Rooms 116, 125, and 135	NO_ACBM	MISC								
44	Blue Vinyl Baseboard			Building A - Rooms 116, 125, and 135	NO_ACBM	MISC								
45	Blue Vinyl Baseboard Adhesive			Building A - Rooms 116, 125, and 135	NO_ACBM	MISC								
46	12" x 12" Sandy Beige w/Light Brown Streaks	5,625	SF	Building A - Basement Corridors, Engineer's Office Areas	CHR	MISC	N	DIST	3,000		No	ACBM with the potential for damage	5	LOW
47	12" x 12" Sandy Beige w/Lt Brn Streaks FT Mastic	5,625	SF	Building A - Basement Corridors, Engineer's Office	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW







# Chicago Public Schools

School Whitney Young Magnet High School Unit 47101 Building ID 1810

Address 211 S. Laflin Region 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
97	Cinderblock Mortar			Building A - Engineer's Lunchroom, 3rd Floor Gold House, Dock Area	NO_ACBM	MISC								
98	Cinderblock			LL2 by Elevators, 1st and 2nd Floor Electric Closet	NO_ACBM	MISC								
99	Cinderblock Mortar			LL2 by Elevators, 1st and 2nd Floor Electric Closet	NO_ACBM	MISC								
9A	Black Vinyl Baseboard			Building C - 2nd Floor Dressing Room, Rooms 198 and 282	NO_ACBM	MISC								
9B	Black Vinyl Baseboard			Building B - Rooms 050, 156, 173, and 255	NO_ACBM	MISC								
A	Breeching Insulation			Building B - Basement areas	ASSUMED	TSI								
E	Joint Compound Off Fiberglass Pipe Insulation			Building C - Basement	NO_ACBM	TSI								
G	Water Tank Insulation			Building B - Swimming Pool Tunnel Areas	NO_ACBM	TSI								
I	Hard Joint Compound Off Mag Pipe Insulation			Building B - Swimming Pool Tunnel Areas & Bldg A - Mechanical Room	CHR	TSI								
J	Mag Pipe Insulation			Building B - Swimming Pool Area, Generator Room	NO_ACBM	TSI								
K	Breeching Insulation	20	SF	Building A - Mechanical Room	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
L	Hot Water Tank Insulation			Room B-10	NO_ACBM	TSI								
P	Duct Expansion Material			Building A - Basement Mechanical Area	NO_ACBM	TSI								
P1	Duct Expansion Material			Building B	NO_ACBM	TSI								
Q	Preform Pipe Insulation	125	LF	Building C - Lower Level Basement	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable		LOW





# Chicago Public Schools

School Whitney Young Magnet High School Unit 47101 Building ID 1810  
Address 211 S. Laflin Region 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

Reinspection Date <b>5/9/2016</b>
Inspector Name <b>Dionne Carey</b>
<b>100-09969</b> <b>5/15/2017</b>
Inspector's IDPH License Number / Expiration Date

### Inspector's Comments

HA Number:	Inspector Comments:
8A	Not observed 2016
003A	
1	
100	
101	
102	
103	
104	
105	
106	
107	
108	
109	
10A	
10B	
11	
110	
111	
112	
113	
114	
115	
116	
117	Damage located in Building B - 2nd Floor

# Chicago Public Schools

School Whitney Young Magnet High School Unit 47101 Building ID 1810

Address 211 S. Laflin Region 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
118	
119	
11A	
11B	Not observed 2016
12	
120	
121	
122	
123	
124	
125	
126	
127	
128	
129	
12B	
13	Not observed 2016
130	
131	
132	
133	
134	
135	
136	
137	
138	
139	
14	
140	

# Chicago Public Schools

School Whitney Young Magnet High School Unit 47101 Building ID 1810

Address 211 S. Laflin Region 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
141	
142	
143	
144	
145	
146	
147	
148	
149	
15	
150	
151	
152	
153	
154	
155	
156	
157	
158	
159	
16	
160	
161	
162	
163	
164	
165	
166	
167	

# Chicago Public Schools

School Whitney Young Magnet High School Unit 47101 Building ID 1810

Address 211 S. Laflin Region 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
168	
169	
17	
170	
171	
172	
173	
174	
175	
176	
177	
18	
18A	
19	
19A	
2	
20	
20A	
21	
21A	
22	
22A	
23	
23A	
24	Damage is located in Building A - throughout lower level
25	
26	
27	
28	

# Chicago Public Schools

School Whitney Young Magnet High School Unit 47101 Building ID 1810

Address 211 S. Laflin Region 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
29	
2B	Damage is located in Building B Basement Corridors
30	
31	Not observed 2016
32	
33	
34	
35	
36	
37	
38	
39	
40	
41	
42	
43	
44	
45	
46	Damage located in Building A - throughout lower level
47	
48	Not observed 2016
49	
50	Not observed 2016 - Now wood laminate flooring
51	
52	Not observed 2016 - Now wood laminate flooring
53	
54	
55	
56	

# Chicago Public Schools

School Whitney Young Magnet High School Unit 47101 Building ID 1810

Address 211 S. Laflin Region 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
57	Not observed 2016 - Could be under carpet
58	
59	
6	
60	
61	
62	
63	
64	Not observed 2016
65	Not observed 2016
66	
67	
68	
69	
69.1	
7	
70	
71	
72	
73	
74	
75	
76	
77	
78	
79	
8	
80	
81	

# Chicago Public Schools

School Whitney Young Magnet High School Unit 47101 Building ID 1810

Address 211 S. Laflin Region 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
82	
83	
84	Not observed 2016
85	
86	
87	
88	
89	
8B	
90	
91	
92	
93	
94	
95	
96	
97	
98	
99	
9A	
9B	
A	Not observed 2016
E	
G	
I	Not observed 2016 - Inaccessible
J	
K	
L	
P	



# Chicago Public Schools

School Whitney Young Magnet High School Unit 47101 Building ID 1810

Address 211 S. Laflin Region 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
P1	
Q	
R	
S	
T	Not observed 2016 - Inaccessible
U	
V	
W	Not observed 2016
W-1	Not observed 2016

**Table II**

**Management Planner's Review**

---

# Chicago Public Schools

School Whitney Young Magnet High School

Unit 47101

Building ID 1810

Address 211 S. Laflin

Chicago, IL, 60607

Region 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
8A	12" x 12" Brown w/Beige Floor Tile Mastic			Performing Arts Foyer, 221 & Office, 224, Lecture Hall & Stage, Theater, Kitchen Storage	Chrysotile	MISC					
003A	Spray on Fireproofing			1960 Building	No ACBM	SURFACE					
1	Beige Floor Mat Material			Room 050	No ACBM	MISC					
100	12" x 12" Brown & Black Floor Tile	7	SF	Buildings A and B - West Link Areas	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
101	12" x 12" Brown & Black Floor Tile Mastic	7	SF	Buildings A & B - West Link Areas	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
102	Expansion Filler	80	SF	Buildings A & C - Link Support Columns	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
103	Expansion Filler			Building A - Support Columns	No ACBM	MISC					
104	Breeching Insulation Jacket			Building A - Room 010	No ACBM	MISC					
105	Water Heater Tank Insulation Jacket			Building A - Room 010	No ACBM	TSI					
106	Mechanical Unit Door Lining Insulation			Building A - Roof	No ACBM	MISC					
107	12" x 12" Black Streaks Floor Tile	8,945	SF	Building A - Dining Areas	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
108	12" x 12" Black Streaks Mastic	8,945	SF	Building A - Dining areas	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
109	Sheetrock			Building B- Home Team Locker Room	No ACBM	MISC					
10A	Black Vinyl Baseboard Mastic			Building C - 2nd Floor Dressing Room, Rooms 198 and 282, 344	No ACBM	MISC					
10B	Black Vinyl Baseboard Mastic			Building B - Rooms 050, 156, 173, and 255	No ACBM	MISC					
11	Sheetrock			Building A - Engineer's Washroom, Rooms 204 and 304	No ACBM	MISC					
110	Sheet Rock Joint Compound			Building B- Home Team Locker Room	No ACBM	MISC					
111	Tar-like Covering on Fiberglass Pipe Insulation			Building B - Swimming Pool Tunnel Areas	No ACBM	TSI					
112	Interior Brick			Building B	No ACBM	MISC					
113	Interior Brick Mortar			Building B	No ACBM	MISC					
114	Styrofoam Adhesive on Cinderblock Walls			Building B - Small Gym on East Wall Center	No ACBM	MISC					
115	Blue Carpet w/Multi-Colored Streaks Adhesive			Room 173	No ACBM	MISC					
116	Black Floor Mat Material			Room 169	No ACBM	MISC					
117	12" x 12" lt brown with dark brown and white Floor Tile	6,000	SF	Building B - 2nd Level	Assumed	MISC	No	100	SF	6 ACBM with the potential for damage	Follow O&M Plan
118	12"x12" light brown with dark brown and white			Building B - 2nd Level	No ACBM	MISC					

# Chicago Public Schools

School Whitney Young Magnet High School

Unit 47101

Building ID 1810

Address 211 S. Laflin

Chicago, IL, 60607

Region 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
	Floor Tile Mastic										
119	12"x12" Dark Ash w/Mud Brown Specks Floor Tile	1,860	SF	2nd Floor Bridge Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
11A	Sheetrock			293/294 Partition	No ACBM	MISC					
11B	Expansion Filler Material			Building B - Support Column Corners	Assumed	MISC					
12	Transite Hood Material	112	SF	Building A - Science Labs & Room 328, 320, 322	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
120	12" x 12" Dark Ash FT w/Mud Brown Specks Mastic	1,860	SF	2nd Level Bridge Corridor to Bldg B	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
121	Partition Floor Compound			2nd Floor Bridge Corridor	No ACBM	MISC					
122	Exterior Brick			Building B Exterior	No ACBM	MISC					
123	Exterior Brick Mortar			Building B Exterior	No ACBM	MISC					
124	Cinderblock			Building B	No ACBM	MISC					
125	Cinderblock Mortar			Building B	No ACBM	MISC					
126	Duct Expansion Material			Pool Filter Room	No ACBM	MISC					
127	Hot Water Tank Insulation Jacket			Swimming Pool East Tunnel	No ACBM	TSI					
128	1' x 1' Pigeon Hole Ceiling Tile			Building A - 2nd & 3rd Floor Kitchens	No ACBM	MISC					
129	Ceiling Tile Mat (Under 1x1Pigeonhole Metal Cover)			Building A - 2nd and 3rd Floor Kitchens	No ACBM	MISC					
12B	Fire Door Insulation	48	SF	Building B	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
13	Mechanical Unit Insulation Jacket			Building A - Penthouse/Mechanical Room	Chrysotile	TSI					
130	Roofing Material (Non AHERA)			Building A & C	Assumed	MISC					
131	Roofing Material NON-AHERA			Building B	Assumed	MISC					
132	Black Sink Material			Building C - Rooms 288 and 291	No ACBM	MISC					
133	12"x12" Soft Beige Floor Tile w/Large Brown Specks	750	SF	Room 179	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
134	12"x12" Soft Beige FT w/Large Brown Specks Mastic	750	SF	Building A Rooms 108, and Building C Room 179	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
135	Chocolate Partition Door Jacket			Rooms 129 and 130	No ACBM	MISC					
136	Wavy Beige Linoleum	950	SF	Building A - Rooms 322(Rm 324 is now combined w/ 322)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
137	Wavy Beige Linoleum Mastic	950	SF	Building A - Rooms 322(Rm 324 is now combined w/ 322)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
138	12" x 12" Off White w/Brown Streaks Floor Tile	19,720	SF	Throughout Building C - Classrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

School Whitney Young Magnet High School

Unit 47101

Building ID 1810

Address 211 S. Laflin

Chicago, IL, 60607

Region 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				and Corridors							
139	12" x 12" Off White w/Brown Streaks FT Mastic	19,720	SF	Throughout Building C - Classrooms and Corridors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
14	Mechanical Unit Vibration Isolator	10	SF	Building A - Mechanical Room by Penthouse on Roof	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
140	12" x 12" Tan w/Lt. Brown Mix Floor Tile	1,200	SF	Building A Rooms 342, and 344	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
141	12" x 12" Tan w/Lt. Brown Mix Floor Tile Mastic	1,200	SF	Building A Room 342, 344	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
142	12" x 12" Red w/Tan Specks Floor Tile	40	SF	Building C Room 184	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
143	12" x 12" Red w/Tan Specks Floor Tile Mastic	40	SF	Building C Room 184	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
144	12" x 12" Blue Mix Floor Tile	330	SF	Building C Room 190	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
145	12" x 12" Blue Mix Floor Tile Mastic	330	SF	Building C Room 190	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
146	12" x 12" Gray Mix Floor Tile	406	SF	Building C Room 190	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
147	12" x 12" Gray Mix Floor Tile Mastic	406	SF	Building C Room 190	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
148	12" x 12" Medium Tan Mix Floor Tile	6,328	SF	Building C Rooms 196, 191, 292, 297, 295, 277, 278, 279, 280, 282	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
149	12" x 12" Medium Tan Mix Floor Tile Mastic	6,328	SF	Building C Rooms 196, 191, 292, 297, 295, 277, 278, 279, 280, 282	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
15	Roof Mat Material			Building A - Roof	No ACBM	MISC					
150	12" x 12" Black w/Brown Streaks Floor Tile	960	SF	Building A Rooms 347 & 348	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
151	12" x 12" Black w/Brown Streaks Floor Tile Mastic	960	SF	Building A Rooms 347 & 348	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
152	Spray-on Fireproofing	450	SF	Room 050, 018, 010, 007	Assumed	SURFACE	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
153	2' x 4' Ceiling Tile	50,000	SF	All Corridors, Classrooms & Offices	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
154	Tan and red Terrazzo	25,000	SF	Building A, B, and C entrances, Building A 1st floor hallway adjacent to Room 110, Auditorium and stairwells	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
155	12" x 12" brown with dark brown floor tile	1,500	SF	Building A 1st floor Hall and Room 117	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
156	12" x 12" brown with dark brown floor tile Mastic	1,500	SF	Building A 1st floor Hall and Room 117	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
157	12" x 12" Tan/Brown with light brown floor tile	60,000	SF	Building A 1st, 2nd, and 3rd floor corridors. 105, 106, 117, 119, 127, 128, 129, 145, 200, 201, 202, 204-210, 213, 220, 301, 306, 307, 308, 309, 310, 312, 314, 315, 325,341, 342, 345, 4C, 4D, 2C, 2F	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

School Whitney Young Magnet High School

Unit 47101

Building ID 1810

Address 211 S. Laflin

Chicago, IL, 60607

Region 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
158	Mastic for 12" x 12" Tan/Brown with light brown floor tile	60,000	SF	Building A 1st, 2nd, and 3rd floor corridors. 105, 106, 117, 119, 127, 128, 129, 145, 200, 201, 202, 204-210, 213, 220, 301, 306, 307, 308, 309, 310, 312, 314, 315, 325,341, 342, 345, 4C, 4D, 2C, 2F	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
159	Safe door insulation	64	SF	Building A Room 134A, Building C room 283C	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
16	RD Unit Gasket Material - Not AHERA			Building A - Roof	No ACBM	MISC					
160	12" x 12" white with brown floor tile	1,600	SF	Building C Rooms 290, 291	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
161	Mastic for 12" x 12" white with brown floor tile	1,600	SF	Building C Rooms 290, 291	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
162	12" x 12" Blue with gray and dark blue floor tile	400	SF	Building C Rooms 290, 291	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
163	Mastic for 12" x 12" Blue with gray and dark blue floor tile	400	SF	Building C rooms 290,291	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
164	12" x 12" light brown floor tile	800	SF	Building C Room 178	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
165	Mastic for 12" x 12" light brown floor tile	800	SF	Building C 178	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
166	12" x 12" Light gray with dark gray and white floor tile	600	SF	Building C Room 190	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
167	Mastic for 12" x 12" Light gray with dark gray and white floor tile	600	SF	Building C Room 190	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
168	12" x 12" Light Blue with dark blue and white floor tile.	200	SF	Building C Room 190	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
169	Mastic for 12" x 12" Light Blue with dark blue and white floor tile.	200	SF	Building C Room 190	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
17	Red Mix Carpet Adhesive			Building A - Engineer's Office, 3rd Floor Corridor	No ACBM	MISC					
170	Brown Carpet Mastic	4,800	SF	224 Library	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
171	Rubber Floor Mastic	1,100	SF	Room 050	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
172	Stair Tread Covering	350	SF	Physical Education Building by Locker Rooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
173	Stair Tread Covering Mastic	350	SF	Physical Education Building by Locker Rooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
174	Laminate Roll Adhesive	100	SF	Building C - 290 Storage	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
175	Wood Glue Over Existing	750	SF	Building A - 220/222 Engineer's Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
176	Terrazo	5,000	SF	Building C - 1st Floor Theater	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

School Whitney Young Magnet  
High School

Unit 47101

Building ID 1810

Address 211 S. Laflin

Chicago, IL, 60607

Region 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
177	Ceramic Grout	1,000	SF	Building A - Main Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
18	Interior Brick			Building A	No ACBM	MISC					
18A	Interior Brick			Building C	No ACBM	MISC					
19	Interior Brick Mortar			Building A	No ACBM	MISC					
19A	Interior Brick Mortar			Building C	No ACBM	MISC					
2	12" x 12" Black Floor Tile	2,000	SF	Building, A - 1st Blue House, 2nd Red House, 3rd Gold House Dining Areas	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
20	Joint Compound on Sheetrock			Building A - Engineer's Washroom, Rooms 204 and 304	No ACBM	TSI					
20A	Joint Compound Off Sheetrock			Building C - 293/294 Partition	No ACBM	TSI					
21	Brown Vinyl Baseboard			Building A - Rooms 128, 204, and 304	No ACBM	MISC					
21A	Brown Vinyl Baseboard			Building C - Rooms 192, 196, and 198	No ACBM	MISC					
22	Brown Vinyl Baseboard Mastic			Building A - Rooms 128, 204, and 304	No ACBM	MISC					
22A	Brown Vinyl Baseboard Mastic			Building C - Rooms 192, 196, and 198	No ACBM	MISC					
23	Black Sink Top Caulk			Room 320	No ACBM	MISC					
23A	Sink Top Bridging Caulk			Rooms 282 and 291	No ACBM	MISC					
24	12"x12" Off-White w/Light Brown Streaks Floor Tile	16,049	SF	Building A - Throughout 1st and 3rd Floor, Lower Level	Assumed	MISC	No	3,500	SF	6 ACBM with the potential for damage	Follow O&M Plan
25	12"x12" Off-White Floor Tile w/Lt Brn Strks Mastic	16,049	SF	Building A - Throughout 1st and 3rd Floor, Lower Level	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
26	12" x 12" Sandy Brown & Beige Floor Tile	1,600	SF	Building A - Rooms 322 and 324	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
27	12" x 12" Sandy Brown & Beige Floor Tile Mastic	1,600	SF	Building A - Rooms 322(combined w/ 324)	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
28	Kiln Door Backing			Building A - Room 103	No ACBM	MISC					
29	Kiln Interior Material			Building A - Room 103	No ACBM	MISC					
2B	12"x12" Lt. Beige w/Sandy Brown Streaks Floor Tile	3,588	SF	Building B - Random Basement Rooms by Corridors	Chrysotile	MISC	No	100	SF	6 ACBM with the potential for damage	Follow O&M Plan
30	Kiln Wiring Insulation	10	LF	Basement Storage Room	Chrysotile	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
31	12" x 12" Pearl White Floor Tile			Room 102	Assumed	MISC					
32	12" x 12" Pearl White Floor Tile Mastic			Room 102	No ACBM	MISC					
33	Gray & Black Mix Carpet Mastic			Rooms 121 and 215	No ACBM	MISC					
34	Pink Mix Carpet Adhesive			Room 100	No ACBM	MISC					
35	Light Green Carpet Adhesive			Building A - Rooms 101, 122, and 145	No ACBM	MISC					
36	Light Blue Mix Carpet Mastic			Building A - Rooms 106 and 143	No ACBM	MISC					

# Chicago Public Schools

School Whitney Young Magnet  
High School

Unit 47101

Building ID 1810

Address 211 S. Laflin

Chicago, IL, 60607

Region 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
37	Light Blue & Beige Mix Carpet Adhesive			Building A - By Elevator, By Room 149	No ACBM	MISC					
38	Light Green & Gray Mix Carpet Adhesive			205 Stage	No ACBM	MISC					
39	Light Green Vinyl Baseboard			Building A - By Rooms 101, 126, and 139	No ACBM	MISC					
40	Light Green Vinyl Baseboard Adhesive			Building A - By Rooms 101, 126, and 139	No ACBM	MISC					
41	12" x 12" Cream (w/Beige Streaks) Mix Floor Tile - REMOVED			Elevators	Abated	MISC					
42	12" x 12" Cream Mix Floor Tile Mastic - ABATED			Building A - Elevators	Abated	MISC					
43	Green Carpet Adhesive			Rooms 116, 125, and 135	No ACBM	MISC					
44	Blue Vinyl Baseboard			Building A - Rooms 116, 125, and 135	No ACBM	MISC					
45	Blue Vinyl Baseboard Adhesive			Building A - Rooms 116, 125, and 135	No ACBM	MISC					
46	12" x 12" Sandy Beige w/Light Brown Streaks	5,625	SF	Building A - Basement Corridors, Engineer's Office Areas	Chrysotile	MISC	No	3,000	SF	6 ACBM with the potential for damage	Follow O&M Plan
47	12" x 12" Sandy Beige w/Lt Brn Streaks FT Mastic	5,625	SF	Building A - Basement Corridors, Engineer's Office Areas	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
48	12" x 12" Dark Sandy Brown Floor Tile			Building A - Corridors by Engineer's Office, Rooms 011 and 014	Assumed	MISC					
49	12" x 12" Dark Sandy Brown Floor Tile Mastic	62	SF	Corridors by Engineer's Office, Rooms 011, 013, and 014	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
50	12" x 12" Light Sandy Pink Floor Tile			Engineer's Lunchroom	Assumed	MISC					
51	12" x 12" Light Sandy Pink Floor Tile Mastic			Engineer's Lunchroom	No ACBM	MISC					
52	12" x 12" Sandy Peach Floor Tile			Building A - Engineer's Lunchroom	Chrysotile	MISC					
53	12" x 12" Sandy Peach Floor Tile Mastic			Engineer's Lunchroom	No ACBM	MISC					
54	Bright Orange Carpet Adhesive			Rooms 128 A and 128 B	No ACBM	MISC					
55	Black Sandy Mix Carpet Adhesive			Room 105/107	No ACBM	MISC					
56	Multi-Colored Carpet Adhesive			Rooms 118/120 offices	No ACBM	MISC					
57	12" x 12" Bluish-Green Floor Tile			Rooms 118/120	Assumed	MISC					
58	12" x 12" Bluish-Green Floor Tile Mastic			Room 118/120	No ACBM	MISC					
59	Maroon Carpet Adhesive			Room 109	No ACBM	MISC					
6	Black Table Top Material	16	SF	Building C - Room 179	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
60	Black/Yellow/Red Mix Carpet Adhesive			Room 139	No ACBM	MISC					
61	12" x 12" Soft Beige w/Brown Specks Floor Tile	600	SF	Room 108	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
62	12" x 12" Soft Beige w/Brown Specks FT Mastic	60	SF	Building A - Room 108	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan



# Chicago Public Schools

School Whitney Young Magnet High School

Unit 47101

Building ID 1810

Address 211 S. Laflin

Chicago, IL, 60607

Region 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
63	Light Green Carpet Adhesive			Principal's Office	No ACBM	MISC					
64	12" x 12" Dark Beige w/Reddish Brown Streaks FT			Building A - Corridor by 012	Assumed	MISC					
65	12"x12" Dark Beige w/Reddish Brown Streaks Mastic			Building A - Corridor by Room 012	Chrysotile	MISC					
66	Dark Ash Gray Vinyl Baseboard	200	LF	Building C - Rooms 012, 290, and 299	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
67	Dark Ash Gray Vinyl Baseboard Mastic	200	LF	Building C - Rooms 012, 290, and 299	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
68	Building Partition Floor Compound			Building C - 2nd Floor A and C Tunnel	No ACBM	MISC					
69	12x12 Light Sandy Off-White w/Lt Brown Streaks FT	9,350	SF	Building C - 2nd Floor Bridge & Corridor, Rooms 177, 179, 276, 293, 294, 196, 197, 198 and 1st floor corridor adjacent to 199	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
69.1	12x12 Lt. Sandy Off-Wt w/Lt Brn Streaks FT Mastic	9,350	SF	Building C - 2nd Floor Bridge & Corridor, Rooms 177, 179, 196, 197, 198, 276, 293, 294 and 1st floor corridor adjacent to 199	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
7	Fire Door Insulation	52	SF	Building A - Randomly Distributed	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
70	12" x 12" Off-White w/Light Brown Streaks Mastic	18,700	SF	Building C - 2nd Floor Bridge & Corridor, Rooms 177, 179, 276, 294, 293	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
71	12" x 12" Off-White & Cream w/Streaks Floor Tile	8,000	SF	Building C - Rooms 175, 181, 275, 277-280 282, 288, 292, 295, 297, and 298	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
72	12" x 12" Off-White & Cream w/Streaks FT Mastic			Building C - Rooms 175, 181, 275, 277-280 282, 288, 292, 295, 297, and 298	No ACBM	MISC					
73	Peach Fire Rated Curtain Material			Building C - Rooms 275, 282, and 295	No ACBM	MISC					
74	12" x 12" Light Pink w/Beige Streaks Floor Tile	60	SF	Building C - Elevators	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
75	12x12 Light Pink w/Beige Streaks Floor Tile Mastic			Building C - Elevators	No ACBM	MISC					
76	Light Green & Gray Vinyl Baseboard			Rooms 278, 282, and 286	No ACBM	MISC					
77	Light Green & Gray Vinyl Baseboard Adhesive			Rooms 278, 282, and 286	No ACBM	MISC					
78	Bright Orange Carpet Adhesive			Room 290	No ACBM	MISC					
79	Mastic 12" x 12" Brown with dark brown floor tile	1,500	SF	Building A 1st floor hallway and room 117	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
8	12" x 12" Black Floor Tile Mastic	19,875	SF	Building A - 1st Blue House (Area where columns are painted blue)	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
80	12" x 12" Light Beige w/Light Brown Mastic	10,285	SF	Building C - Rooms 198 and 298, 1st Floor Stage Back Areas	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Whitney Young Magnet High School

**Unit** 47101

**Building ID** 1810

**Address** 211 S. Laflin

Chicago, IL, 60607

**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
81	Light Blue Carpet Adhesive			Rooms 196 and 198	No ACBM	MISC					
82	Light Blue Vinyl Baseboard			Rooms 196 and 198	No ACBM	MISC					
83	Light Blue Vinyl Baseboard Adhesive			Rooms 196 and 198	No ACBM	MISC					
84	12"x12" Light Silver w/Multiple Streaks Floor Tile			1st Floor Theater	Assumed	MISC					
85	12"x12" Light Silver w/Multiple Streaks FT Mastic			First Floor Theatre	No ACBM	MISC					
86	Floor Cap Material & Adhesive			Theater, Auditorium Stage	No ACBM	MISC					
87	Floor Cap Material Adhesive			Theater, Auditorium Stage	No ACBM	MISC					
88	Light Red Mix Carpet Adhesive			Auditorium	No ACBM	MISC					
89	Ash Mix Carpet Adhesive			Room 186, Back Stage Area	No ACBM	MISC					
8B	12"x12"Light Beige FT w/Sandy Brown Streaks Mastic	3,588	SF	Building B - Random Basement Rooms by Corridors	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
90	Light Brown & Pink Mix Carpet Adhesive			Room 188, A/V Equipment Room Areas	No ACBM	MISC					
91	Chocolate Brown Vinyl Baseboard			Room 188, A/V room	No ACBM	MISC					
92	Chocolate Brown Vinyl Baseboard Adhesive			Room 188, A/V Room	No ACBM	MISC					
93	Motor Interior Insulation			LL1 Elevator Motor Room	No ACBM	MISC					
94	Exterior Brick			Building C Exterior	No ACBM	MISC					
95	Exterior Brick Mortar			Building C Exterior	No ACBM	MISC					
96	Cinderblock			Building A - Engineer's Lunchroom, 3rd Floor Gold House, Dock Area	No ACBM	MISC					
97	Cinderblock Mortar			Building A - Engineer's Lunchroom, 3rd Floor Gold House, Dock Area	No ACBM	MISC					
98	Cinderblock			LL2 by Elevators, 1st and 2nd Floor Electric Closet	No ACBM	MISC					
99	Cinderblock Mortar			LL2 by Elevators, 1st and 2nd Floor Electric Closet	No ACBM	MISC					
9A	Black Vinyl Baseboard			Building C - 2nd Floor Dressing Room, Rooms 198 and 282	No ACBM	MISC					
9B	Black Vinyl Baseboard			Building B - Rooms 050, 156, 173, and 255	No ACBM	MISC					
A	Breeching Insulation			Building B-Basement areas	Assumed	TSI					
E	Joint Compound Off Fiberglass Pipe Insulation			Building C - Basement	No ACBM	TSI					
G	Water Tank Insulation			Building B - Swimming Pool Tunnel Areas	No ACBM	TSI					

# Chicago Public Schools

School Whitney Young Magnet  
High School

Unit 47101

Building ID 1810

Address 211 S. Laflin

Chicago, IL, 60607

Region 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
I	Hard Joint Compound Off Mag Pipe Insulation			Building B- Swimming Pool Tunnel Areas & Bldg A-Mechanical Room	Chrysotile	TSI					
J	Mag Pipe Insulation			Building B - Swimming Pool Area, Generator Room	No ACBM	TSI					
K	Breeching Insulation	20	SF	Building A - Mechanical Room	Chrysotile	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
L	Hot Water Tank Insulation			Room B-10	No ACBM	TSI					
P	Duct Expansion Material			Building A - Basement Mechanical Area	No ACBM	TSI					
P1	Duct Expansion Material			Building B	No ACBM	TSI					
Q	Preform Pipe Insulation	125	LF	Building C - Lower Level Basement Areas, Above Ceiling Throughout Building	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
R	Acoustical Door Packing Material			Building C - Rooms 196 and 198	No ACBM	MISC					
S	Acoustical Door Packing			Building A - Room 139	No ACBM	MISC					
T	Mechanical Unit Insulation			Building A - Mechanical Room on Roof	Amosite, Chrysotile	TSI					
U	Joint Compound Off Preformed Pipe Insulation	50	LF	Building C - Lower Level Basement Areas	Chrysotile	TSI	Yes	8	LF	1 Damaged or significantly damaged friable thermal system insulating ACBM	Remove
V	Joint Compound Off Tar Covering on Fiberglass Pipe			Swimming Pool Tunnels	No ACBM	MISC					
W	12x12 VFT light green			Room 178	Assumed	MISC					
W-1	12x12 VFT light green-MASTIC			Room 178	Assumed	MISC					

# Chicago Public Schools

**School** Whitney Young Magnet  
High School

**Unit** 47101

**Building ID** 1810

**Address** 211 S. Laflin

Chicago, IL, 60607

**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

*Management Planner's Comments Summarized at the End of the Report*

Review Date	6/2/2016
Manager Planner Name	Daniel Juneau
100-03613	5/15/2016
Manager IDPH License No/Expiration	

HA Number	Management Comments
8A	If identified, implement O&M
003A	
1	
100	
101	
102	
103	
104	
105	
106	
107	
108	
109	
10A	
10B	

# Chicago Public Schools

**School** Whitney Young Magnet  
High School

**Unit** 47101

**Building ID** 1810

**Address** 211 S. Laflin

Chicago, IL, 60607

**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
11	
110	
111	
112	
113	
114	
115	
116	
117	
118	
119	
11A	
11B	If identified, implement O&M
12	
120	
121	
122	
123	
124	
125	
126	
127	
128	
129	
12B	
13	If identified, implement O&M

# Chicago Public Schools

**School** Whitney Young Magnet  
High School

**Unit** 47101

**Building ID** 1810

**Address** 211 S. Laflin

Chicago, IL, 60607

**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
130	
131	
132	
133	
134	
135	
136	
137	
138	
139	
14	
140	
141	
142	
143	
144	
145	
146	
147	
148	
149	
15	
150	
151	
152	
153	

# Chicago Public Schools

**School** Whitney Young Magnet  
High School

**Unit** 47101

**Building ID** 1810

**Address** 211 S. Laflin

Chicago, IL, 60607

**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
154	
155	
156	
157	
158	
159	
16	
160	
161	
162	
163	
164	
165	
166	
167	
168	
169	
17	
170	
171	
172	
173	
174	
175	
176	
177	

# Chicago Public Schools

**School** Whitney Young Magnet  
High School

**Unit** 47101

**Building ID** 1810

**Address** 211 S. Laflin

Chicago, IL, 60607

**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
18	
18A	
19	
19A	
2	
20	
20A	
21	
21A	
22	
22A	
23	
23A	
24	
25	
26	
27	
28	
29	
2B	
30	
31	If identified, implement O&M
32	
33	
34	
35	



# Chicago Public Schools

**School** Whitney Young Magnet  
High School

**Unit** 47101

**Building ID** 1810

**Address** 211 S. Laflin

Chicago, IL, 60607

**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
36	
37	
38	
39	
40	
41	
42	
43	
44	
45	
46	
47	
48	If identified, implement O&M
49	
50	If identified, implement O&M
51	
52	If identified, implement O&M
53	
54	
55	
56	
57	If identified, implement O&M
58	
59	
6	
60	

# Chicago Public Schools

**School** Whitney Young Magnet  
High School

**Unit** 47101

**Building ID** 1810

**Address** 211 S. Laflin

Chicago, IL, 60607

**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
61	
62	
63	
64	If identified, implement O&M
65	If identified, implement O&M
66	
67	
68	
69	
69.1	
7	
70	
71	
72	
73	
74	
75	
76	
77	
78	
79	
8	
80	
81	
82	
83	

# Chicago Public Schools

**School** Whitney Young Magnet  
High School

**Unit** 47101

**Building ID** 1810

**Address** 211 S. Laflin

Chicago, IL, 60607

**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
84	If identified, implement O&M
85	
86	
87	
88	
89	
8B	
90	
91	
92	
93	
94	
95	
96	
97	
98	
99	
9A	
9B	
A	If identified, implement O&M
E	
G	
I	If identified, implement O&M
J	
K	
L	

# Chicago Public Schools

**School** Whitney Young Magnet  
High School

**Unit** 47101

**Building ID** 1810

**Address** 211 S. Laflin

Chicago, IL, 60607

**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
P	
P1	
Q	
R	
S	
T	If identified, implement O&M
U	Repair or Remove as applicable. Continue O&M
V	
W	If identified, implement O&M
W-1	If identified, implement O&M

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **8A**  
MATERIAL DESCRIPTION: **12" x 12" Brown w/Beige Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Performing Arts Foyer, 221 & Office, 224, Lecture Hall & Stage, Theater, Kitchen Storage**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not observed 2016**

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **8A**  
MATERIAL DESCRIPTION: **12" x 12" Brown w/Beige Floor Tile Mastic**  
MATERIAL LOCATION: **Performing Arts Foyer, 221 & Office, 224, Lecture Hall & Stage, Theater, Kitchen Storage**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.


The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

If identified, implement O&M

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **003A**  
MATERIAL DESCRIPTION: **Spray on Fireproofing**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1960 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **003A**

MATERIAL DESCRIPTION: **Spray on Fireproofing**

MATERIAL LOCATION: **1960 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **1**  
MATERIAL DESCRIPTION: **Beige Floor Mat Material**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 050**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **1**  
MATERIAL DESCRIPTION: **Beige Floor Mat Material**  
MATERIAL LOCATION: **Room 050**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **100**  
MATERIAL DESCRIPTION: **12" x 12" Brown & Black Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Buildings A and B - West Link Areas**  
MATERIAL QUANTITY: **7** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **100**  
MATERIAL DESCRIPTION: **12" x 12" Brown & Black Floor Tile**  
MATERIAL LOCATION: **Buildings A and B - West Link Areas**  
MATERIAL QUANTITY: **7** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **101**  
MATERIAL DESCRIPTION: **12" x 12" Brown & Black Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Buildings A & B - West Link Areas**

MATERIAL QUANTITY: **7** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 05/09/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **101**  
MATERIAL DESCRIPTION: **12" x 12" Brown & Black Floor Tile Mastic**  
MATERIAL LOCATION: **Buildings A & B - West Link Areas**  
MATERIAL QUANTITY: **7** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **102**  
MATERIAL DESCRIPTION: **Expansion Filler**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Buildings A & C - Link Support Columns**  
MATERIAL QUANTITY: **80** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **102**  
MATERIAL DESCRIPTION: **Expansion Filler**  
MATERIAL LOCATION: **Buildings A & C - Link Support Columns**  
MATERIAL QUANTITY: **80** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **103**  
MATERIAL DESCRIPTION: **Expansion Filler**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building A - Support Columns**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **103**  
MATERIAL DESCRIPTION: **Expansion Filler**  
MATERIAL LOCATION: **Building A - Support Columns**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **104**  
MATERIAL DESCRIPTION: **Breeching Insulation Jacket**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building A - Room 010**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **104**  
MATERIAL DESCRIPTION: **Breeching Insulation Jacket**  
MATERIAL LOCATION: **Building A - Room 010**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **105**  
MATERIAL DESCRIPTION: **Water Heater Tank Insulation Jacket**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building A - Room 010**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **105**  
MATERIAL DESCRIPTION: **Water Heater Tank Insulation Jacket**  
MATERIAL LOCATION: **Building A - Room 010**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **106**  
MATERIAL DESCRIPTION: **Mechanical Unit Door Lining Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building A - Roof**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **106**  
MATERIAL DESCRIPTION: **Mechanical Unit Door Lining Insulation**  
MATERIAL LOCATION: **Building A - Roof**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **107**  
MATERIAL DESCRIPTION: **12" x 12" Black Streaks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Building A - Dining Areas**  
MATERIAL QUANTITY: **8945** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **107**  
MATERIAL DESCRIPTION: **12" x 12" Black Streaks Floor Tile**  
MATERIAL LOCATION: **Building A - Dining Areas**  
MATERIAL QUANTITY: **8945** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **108**  
MATERIAL DESCRIPTION: **12" x 12" Black Streaks Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Building A - Dining areas**  
MATERIAL QUANTITY: **8945** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **108**  
MATERIAL DESCRIPTION: **12" x 12" Black Streaks Mastic**  
MATERIAL LOCATION: **Building A - Dining areas**  
MATERIAL QUANTITY: **8945** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **109**  
MATERIAL DESCRIPTION: **Sheetrock**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building B- Home Team Locker Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **109**  
MATERIAL DESCRIPTION: **Sheetrock**  
MATERIAL LOCATION: **Building B- Home Team Locker Room**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10A**  
MATERIAL DESCRIPTION: **Black Vinyl Baseboard Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building C - 2nd Floor Dressing Room, Rooms 198 and 282, 344**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **10A**  
MATERIAL DESCRIPTION: **Black Vinyl Baseboard Mastic**  
MATERIAL LOCATION: **Building C - 2nd Floor Dressing Room, Rooms 198 and 282, 344**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10B**  
MATERIAL DESCRIPTION: **Black Vinyl Baseboard Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building B - Rooms 050, 156, 173, and 255**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **10B**  
MATERIAL DESCRIPTION: **Black Vinyl Baseboard Mastic**  
MATERIAL LOCATION: **Building B - Rooms 050, 156, 173, and 255**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11**  
MATERIAL DESCRIPTION: **Sheetrock**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building A - Engineer's Washroom, Rooms 204 and 304**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **11**  
MATERIAL DESCRIPTION: **Sheetrock**  
MATERIAL LOCATION: **Building A - Engineer's Washroom, Rooms 204 and 304**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **110**  
MATERIAL DESCRIPTION: **Sheet Rock Joint Compound**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building B- Home Team Locker Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **110**  
MATERIAL DESCRIPTION: **Sheet Rock Joint Compound**  
MATERIAL LOCATION: **Building B- Home Team Locker Room**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **111**  
MATERIAL DESCRIPTION: **Tar-like Covering on Fiberglass Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building B - Swimming Pool Tunnel Areas**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **111**  
MATERIAL DESCRIPTION: **Tar-like Covering on Fiberglass Pipe Insulation**  
MATERIAL LOCATION: **Building B - Swimming Pool Tunnel Areas**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **112**  
MATERIAL DESCRIPTION: **Interior Brick**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building B**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **112**  
MATERIAL DESCRIPTION: **Interior Brick**  
MATERIAL LOCATION: **Building B**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **113**  
MATERIAL DESCRIPTION: **Interior Brick Mortar**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building B**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **113**  
MATERIAL DESCRIPTION: **Interior Brick Mortar**  
MATERIAL LOCATION: **Building B**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **114**  
MATERIAL DESCRIPTION: **Styrofoam Adhesive on Cinderblock Walls**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building B - Small Gym on East Wall Center**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **114**  
MATERIAL DESCRIPTION: **Styrofoam Adhesive on Cinderblock Walls**  
MATERIAL LOCATION: **Building B - Small Gym on East Wall Center**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **115**  
MATERIAL DESCRIPTION: **Blue Carpet w/Multi-Colored Streaks Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 173**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **115**  
MATERIAL DESCRIPTION: **Blue Carpet w/Multi-Colored Streaks Adhesive**  
MATERIAL LOCATION: **Room 173**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **116**  
MATERIAL DESCRIPTION: **Black Floor Mat Material**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 169**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **116**  
MATERIAL DESCRIPTION: **Black Floor Mat Material**  
MATERIAL LOCATION: **Room 169**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **117**  
MATERIAL DESCRIPTION: **12" x 12" lt brown with dark brown and white Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Delamination  
Deterioration**  
DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Building B - 2nd Level**  
MATERIAL QUANTITY: **6000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **Damage located in Building B - 2nd Floor**

Inspector's Signature: \_\_\_\_\_



Date: 05/09/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **117**  
MATERIAL DESCRIPTION: **12" x 12" lt brown with dark brown and white Floor Tile**  
MATERIAL LOCATION: **Building B - 2nd Level**  
MATERIAL QUANTITY: **6000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **100** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **118**  
MATERIAL DESCRIPTION: **12"x12" light brown with dark brown and white Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building B - 2nd Level**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **118**  
MATERIAL DESCRIPTION: **12"x12" light brown with dark brown and white Floor Tile Mastic**  
MATERIAL LOCATION: **Building B - 2nd Level**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **119**  
MATERIAL DESCRIPTION: **12"x12" Dark Ash w/Mud Brown Specks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **2nd Floor Bridge Corridor**  
MATERIAL QUANTITY: **1860** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **119**  
MATERIAL DESCRIPTION: **12"x12" Dark Ash w/Mud Brown Specks Floor Tile**  
MATERIAL LOCATION: **2nd Floor Bridge Corridor**  
MATERIAL QUANTITY: **1860** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11A**  
MATERIAL DESCRIPTION: **Sheetrock**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **293/294 Partition**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **11A**

MATERIAL DESCRIPTION: **Sheetrock**

MATERIAL LOCATION: **293/294 Partition**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11B**  
MATERIAL DESCRIPTION: **Expansion Filler Material**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building B - Support Column Corners**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not observed 2016**

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **11B**  
MATERIAL DESCRIPTION: **Expansion Filler Material**  
MATERIAL LOCATION: **Building B - Support Column Corners**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

If identified, implement O&M

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12**  
MATERIAL DESCRIPTION: **Transite Hood Material**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Building A - Science Labs & Room 328, 320, 322**

MATERIAL QUANTITY: **112** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **12**  
MATERIAL DESCRIPTION: **Transite Hood Material**  
MATERIAL LOCATION: **Building A - Science Labs & Room 328, 320, 322**  
MATERIAL QUANTITY: **112** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **120**  
MATERIAL DESCRIPTION: **12" x 12" Dark Ash FT w/Mud Brown Specks Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **2nd Level Bridge Corridor to Bldg B**  
MATERIAL QUANTITY: **1860** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **120**  
MATERIAL DESCRIPTION: **12" x 12" Dark Ash FT w/Mud Brown Specks Mastic**  
MATERIAL LOCATION: **2nd Level Bridge Corridor to Bldg B**  
MATERIAL QUANTITY: **1860** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **121**  
MATERIAL DESCRIPTION: **Partition Floor Compound**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **2nd Floor Bridge Corridor**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **121**  
MATERIAL DESCRIPTION: **Partition Floor Compound**  
MATERIAL LOCATION: **2nd Floor Bridge Corridor**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **122**  
MATERIAL DESCRIPTION: **Exterior Brick**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building B Exterior**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **122**  
MATERIAL DESCRIPTION: **Exterior Brick**  
MATERIAL LOCATION: **Building B Exterior**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **123**  
MATERIAL DESCRIPTION: **Exterior Brick Mortar**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building B Exterior**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **123**  
MATERIAL DESCRIPTION: **Exterior Brick Mortar**  
MATERIAL LOCATION: **Building B Exterior**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **124**  
MATERIAL DESCRIPTION: **Cinderblock**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building B**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **124**  
MATERIAL DESCRIPTION: **Cinderblock**  
MATERIAL LOCATION: **Building B**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **125**  
MATERIAL DESCRIPTION: **Cinderblock Mortar**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building B**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **125**  
MATERIAL DESCRIPTION: **Cinderblock Mortar**  
MATERIAL LOCATION: **Building B**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **126**  
MATERIAL DESCRIPTION: **Duct Expansion Material**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Pool Filter Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **126**  
MATERIAL DESCRIPTION: **Duct Expansion Material**  
MATERIAL LOCATION: **Pool Filter Room**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **127**  
MATERIAL DESCRIPTION: **Hot Water Tank Insulation Jacket**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Swimming Pool East Tunnel**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **127**  
MATERIAL DESCRIPTION: **Hot Water Tank Insulation Jacket**  
MATERIAL LOCATION: **Swimming Pool East Tunnel**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **128**  
MATERIAL DESCRIPTION: **1' x 1' Pigeon Hole Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building A - 2nd & 3rd Floor Kitchens**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **128**  
MATERIAL DESCRIPTION: **1' x 1' Pigeon Hole Ceiling Tile**  
MATERIAL LOCATION: **Building A - 2nd & 3rd Floor Kitchens**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **129**  
MATERIAL DESCRIPTION: **Ceiling Tile Mat (Under 1x1Pigeonhole Metal Cover)**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building A - 2nd and 3rd Floor Kitchens**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **129**  
MATERIAL DESCRIPTION: **Ceiling Tile Mat (Under 1x1Pigeonhole Metal Cover)**  
MATERIAL LOCATION: **Building A - 2nd and 3rd Floor Kitchens**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12B**  
MATERIAL DESCRIPTION: **Fire Door Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Building B**  
MATERIAL QUANTITY: **48** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **12B**  
MATERIAL DESCRIPTION: **Fire Door Insulation**  
MATERIAL LOCATION: **Building B**  
MATERIAL QUANTITY: **48** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

## Carnow, Conibear and Associates 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13**  
MATERIAL DESCRIPTION: **Mechanical Unit Insulation Jacket**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building A - Penthouse/Mechanical Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not observed 2016**

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **13**  
MATERIAL DESCRIPTION: **Mechanical Unit Insulation Jacket**  
MATERIAL LOCATION: **Building A - Penthouse/Mechanical Room**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

If identified, implement O&M

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **130**  
MATERIAL DESCRIPTION: **Roofing Material (Non AHERA)**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building A & C**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **130**  
MATERIAL DESCRIPTION: **Roofing Material (Non AHERA)**  
MATERIAL LOCATION: **Building A & C**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **131**  
MATERIAL DESCRIPTION: **Roofing Material NON-AHERA**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building B**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **131**  
MATERIAL DESCRIPTION: **Roofing Material NON-AHERA**  
MATERIAL LOCATION: **Building B**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **132**  
MATERIAL DESCRIPTION: **Black Sink Material**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building C - Rooms 288 and 291**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **132**  
MATERIAL DESCRIPTION: **Black Sink Material**  
MATERIAL LOCATION: **Building C - Rooms 288 and 291**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **133**  
MATERIAL DESCRIPTION: **12"x12" Soft Beige Floor Tile w/Large Brown Specks**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 179**  
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **133**  
MATERIAL DESCRIPTION: **12"x12" Soft Beige Floor Tile w/Large Brown Specks**  
MATERIAL LOCATION: **Room 179**  
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **134**  
MATERIAL DESCRIPTION: **12"x12" Soft Beige FT w/Large Brown Specks Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Building A Rooms 108, and Building C Room 179**

MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **134**  
MATERIAL DESCRIPTION: **12"x12" Soft Beige FT w/Large Brown Specks Mastic**  
MATERIAL LOCATION: **Building A Rooms 108, and Building C Room 179**  
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **135**  
MATERIAL DESCRIPTION: **Chocolate Partition Door Jacket**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 129 and 130**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **135**  
MATERIAL DESCRIPTION: **Chocolate Partition Door Jacket**  
MATERIAL LOCATION: **Rooms 129 and 130**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

## Carnow, Conibear and Associates 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **136**  
MATERIAL DESCRIPTION: **Wavy Beige Linoleum**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Building A - Rooms 322(Rm 324 is now combined w/ 322)**  
MATERIAL QUANTITY: **950** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 05/09/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **136**  
MATERIAL DESCRIPTION: **Wavy Beige Linoleum**  
MATERIAL LOCATION: **Building A - Rooms 322(Rm 324 is now combined w/ 322)**  
MATERIAL QUANTITY: **950** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **137**  
MATERIAL DESCRIPTION: **Wavy Beige Linoleum Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Building A - Rooms 322(Rm 324 is now combined w/ 322)**  
MATERIAL QUANTITY: **950** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **137**  
MATERIAL DESCRIPTION: **Wavy Beige Linoleum Mastic**  
MATERIAL LOCATION: **Building A - Rooms 322(Rm 324 is now combined w/ 322)**  
MATERIAL QUANTITY: **950** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

## Carnow, Conibear and Associates 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **138**  
MATERIAL DESCRIPTION: **12" x 12" Off White w/Brown Streaks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Throughout Building C - Classrooms and Corridors**

MATERIAL QUANTITY: **19720**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **138**  
MATERIAL DESCRIPTION: **12" x 12" Off White w/Brown Streaks Floor Tile**  
MATERIAL LOCATION: **Throughout Building C - Classrooms and Corridors**  
MATERIAL QUANTITY: **19720** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**



# Chicago Public Schools

## Carnow, Conibear and Associates 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **139**  
MATERIAL DESCRIPTION: **12" x 12" Off White w/Brown Streaks FT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Throughout Building C - Classrooms and Corridors**

MATERIAL QUANTITY: **19720**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **139**  
MATERIAL DESCRIPTION: **12" x 12" Off White w/Brown Streaks FT Mastic**  
MATERIAL LOCATION: **Throughout Building C - Classrooms and Corridors**  
MATERIAL QUANTITY: **19720** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14**  
MATERIAL DESCRIPTION: **Mechanical Unit Vibration Isolator**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Building A - Mechanical Room by Penthouse on Roof**  
MATERIAL QUANTITY: **10** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **14**  
MATERIAL DESCRIPTION: **Mechanical Unit Vibration Isolator**  
MATERIAL LOCATION: **Building A - Mechanical Room by Penthouse on Roof**  
MATERIAL QUANTITY: **10** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **140**  
MATERIAL DESCRIPTION: **12" x 12" Tan w/Lt. Brown Mix Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Building A Rooms 342, and 344**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **140**  
MATERIAL DESCRIPTION: **12" x 12" Tan w/Lt. Brown Mix Floor Tile**  
MATERIAL LOCATION: **Building A Rooms 342, and 344**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **141**  
MATERIAL DESCRIPTION: **12" x 12" Tan w/Lt. Brown Mix Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Building A Room 342, 344**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **141**  
MATERIAL DESCRIPTION: **12" x 12" Tan w/Lt. Brown Mix Floor Tile Mastic**  
MATERIAL LOCATION: **Building A Room 342, 344**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **142**  
MATERIAL DESCRIPTION: **12" x 12" Red w/Tan Specks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Building C Room 184**

MATERIAL QUANTITY: **40**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **142**  
MATERIAL DESCRIPTION: **12" x 12" Red w/Tan Specks Floor Tile**  
MATERIAL LOCATION: **Building C Room 184**  
MATERIAL QUANTITY: **40** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

## Carnow, Conibear and Associates 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **143**  
MATERIAL DESCRIPTION: **12" x 12" Red w/Tan Specks Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Building C Room 184**  
MATERIAL QUANTITY: **40** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 05/09/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **143**  
MATERIAL DESCRIPTION: **12" x 12" Red w/Tan Specks Floor Tile Mastic**  
MATERIAL LOCATION: **Building C Room 184**  
MATERIAL QUANTITY: **40** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **144**  
MATERIAL DESCRIPTION: **12" x 12" Blue Mix Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Building C Room 190**  
MATERIAL QUANTITY: **330** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 05/09/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **144**  
MATERIAL DESCRIPTION: **12" x 12" Blue Mix Floor Tile**  
MATERIAL LOCATION: **Building C Room 190**  
MATERIAL QUANTITY: **330** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **145**  
MATERIAL DESCRIPTION: **12" x 12" Blue Mix Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Building C Room 190**  
MATERIAL QUANTITY: **330** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **145**  
MATERIAL DESCRIPTION: **12" x 12" Blue Mix Floor Tile Mastic**  
MATERIAL LOCATION: **Building C Room 190**  
MATERIAL QUANTITY: **330** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **146**  
MATERIAL DESCRIPTION: **12" x 12" Gray Mix Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Building C Room 190**  
MATERIAL QUANTITY: **406** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **146**  
MATERIAL DESCRIPTION: **12" x 12" Gray Mix Floor Tile**  
MATERIAL LOCATION: **Building C Room 190**  
MATERIAL QUANTITY: **406** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

## Carnow, Conibear and Associates 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **147**  
MATERIAL DESCRIPTION: **12" x 12" Gray Mix Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Building C Room 190**  
MATERIAL QUANTITY: **406** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 05/09/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **147**  
MATERIAL DESCRIPTION: **12" x 12" Gray Mix Floor Tile Mastic**  
MATERIAL LOCATION: **Building C Room 190**  
MATERIAL QUANTITY: **406** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

## Carnow, Conibear and Associates 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **148**  
MATERIAL DESCRIPTION: **12" x 12" Medium Tan Mix Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Building C Rooms 196, 191, 292, 297, 295, 277, 278, 279, 280, 282**  
MATERIAL QUANTITY: **6328** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **148**  
MATERIAL DESCRIPTION: **12" x 12" Medium Tan Mix Floor Tile**  
MATERIAL LOCATION: **Building C Rooms 196, 191, 292, 297, 295, 277, 278, 279, 280, 282**  
MATERIAL QUANTITY: **6328** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **149**  
MATERIAL DESCRIPTION: **12" x 12" Medium Tan Mix Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Building C Rooms 196, 191, 292, 297, 295, 277, 278, 279, 280, 282**  
MATERIAL QUANTITY: **6328** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **149**  
MATERIAL DESCRIPTION: **12" x 12" Medium Tan Mix Floor Tile Mastic**  
MATERIAL LOCATION: **Building C Rooms 196, 191, 292, 297, 295, 277, 278, 279, 280, 282**  
MATERIAL QUANTITY: **6328** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15**  
MATERIAL DESCRIPTION: **Roof Mat Material**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building A - Roof**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **15**

MATERIAL DESCRIPTION: **Roof Mat Material**

MATERIAL LOCATION: **Building A - Roof**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **150**  
MATERIAL DESCRIPTION: **12" x 12" Black w/Brown Streaks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Building A Rooms 347 & 348**  
MATERIAL QUANTITY: **960** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **150**  
MATERIAL DESCRIPTION: **12" x 12" Black w/Brown Streaks Floor Tile**  
MATERIAL LOCATION: **Building A Rooms 347 & 348**  
MATERIAL QUANTITY: **960** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **151**  
MATERIAL DESCRIPTION: **12" x 12" Black w/Brown Streaks Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Building A Rooms 347 & 348**  
MATERIAL QUANTITY: **960** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **151**  
MATERIAL DESCRIPTION: **12" x 12" Black w/Brown Streaks Floor Tile Mastic**  
MATERIAL LOCATION: **Building A Rooms 347 & 348**  
MATERIAL QUANTITY: **960** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **152**  
MATERIAL DESCRIPTION: **Spray-on Fireproofing**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 050, 018, 010, 007**  
MATERIAL QUANTITY: **450** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 05/09/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **152**  
MATERIAL DESCRIPTION: **Spray-on Fireproofing**  
MATERIAL LOCATION: **Room 050, 018, 010, 007**  
MATERIAL QUANTITY: **450** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **153**  
MATERIAL DESCRIPTION: **2' x 4' Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with potential for significant damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **All Corridors, Classrooms & Offices**  
MATERIAL QUANTITY: **50000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 05/09/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **153**  
MATERIAL DESCRIPTION: **2' x 4' Ceiling Tile**  
MATERIAL LOCATION: **All Corridors, Classrooms & Offices**  
MATERIAL QUANTITY: **50000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **154**  
MATERIAL DESCRIPTION: **Tan and red Terrazzo**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Building A, B, and C entrances, Building A 1st floor hallway adjacent to Room 110, Auditorium and stairwells**

MATERIAL QUANTITY: **25000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **154**  
MATERIAL DESCRIPTION: **Tan and red Terrazzo**  
MATERIAL LOCATION: **Building A, B, and C entrances, Building A 1st floor hallway adjacent to Room 110, Auditorium and stairwells**  
MATERIAL QUANTITY: **25000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **155**  
MATERIAL DESCRIPTION: **12" x 12" brown with dark brown floor tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Building A 1st floor Hall and Room 117**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **155**  
MATERIAL DESCRIPTION: **12" x 12" brown with dark brown floor tile**  
MATERIAL LOCATION: **Building A 1st floor Hall and Room 117**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **156**  
MATERIAL DESCRIPTION: **12" x 12" brown with dark brown floor tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Building A 1st floor Hall and Room 117**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **156**  
MATERIAL DESCRIPTION: **12" x 12" brown with dark brown floor tile Mastic**  
MATERIAL LOCATION: **Building A 1st floor Hall and Room 117**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **157**  
MATERIAL DESCRIPTION: **12" x 12" Tan/Brown with light brown floor tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Building A 1st, 2nd, and 3rd floor corridors. 105, 106, 117, 119, 127, 128, 129, 145, 200, 201, 202, 204-210, 213, 220, 301, 306, 307, 308, 309, 310, 312, 314, 315, 325,341, 342, 345, 4C, 4D, 2C, 2F**

MATERIAL QUANTITY: **60000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **157**  
MATERIAL DESCRIPTION: **12" x 12" Tan/Brown with light brown floor tile**  
MATERIAL LOCATION: **Building A 1st, 2nd, and 3rd floor corridors. 105, 106, 117, 119, 127, 128, 129, 145, 200, 201, 202, 204-210, 213, 220, 301, 306, 307, 308, 309, 310, 312, 314, 315, 325,341, 342, 345, 4C, 4D, 2C, 2F**  
MATERIAL QUANTITY: **60000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **158**  
MATERIAL DESCRIPTION: **Mastic for 12" x 12" Tan/Brown with light brown floor tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Building A 1st, 2nd, and 3rd floor corridors. 105, 106, 117, 119, 127, 128, 129, 145, 200, 201, 202, 204-210, 213, 220, 301, 306, 307, 308, 309, 310, 312, 314, 315, 325,341, 342, 345, 4C, 4D, 2C, 2F**

MATERIAL QUANTITY: **60000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **158**  
MATERIAL DESCRIPTION: **Mastic for 12" x 12" Tan/Brown with light brown floor tile**  
MATERIAL LOCATION: **Building A 1st, 2nd, and 3rd floor corridors. 105, 106, 117, 119, 127, 128, 129, 145, 200, 201, 202, 204-210, 213, 220, 301, 306, 307, 308, 309, 310, 312, 314, 315, 325,341, 342, 345, 4C, 4D, 2C, 2F**  
MATERIAL QUANTITY: **60000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **159**  
MATERIAL DESCRIPTION: **Safe door insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Building A Room 134A, Building C room 283C**  
MATERIAL QUANTITY: **64** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **159**  
MATERIAL DESCRIPTION: **Safe door insulation**  
MATERIAL LOCATION: **Building A Room 134A, Building C room 283C**  
MATERIAL QUANTITY: **64** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16**  
MATERIAL DESCRIPTION: **RD Unit Gasket Material - Not AHERA**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building A - Roof**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **16**  
MATERIAL DESCRIPTION: **RD Unit Gasket Material - Not AHERA**  
MATERIAL LOCATION: **Building A - Roof**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **160**  
MATERIAL DESCRIPTION: **12" x 12" white with brown floor tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Building C Rooms 290, 291**  
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **160**  
MATERIAL DESCRIPTION: **12" x 12" white with brown floor tile**  
MATERIAL LOCATION: **Building C Rooms 290, 291**  
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **161**  
MATERIAL DESCRIPTION: **Mastic for 12" x 12" white with brown floor tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Building C Rooms 290, 291**  
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **161**  
MATERIAL DESCRIPTION: **Mastic for 12" x 12" white with brown floor tile**  
MATERIAL LOCATION: **Building C Rooms 290, 291**  
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **162**  
MATERIAL DESCRIPTION: **12" x 12" Blue with gray and dark blue floor tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Building C Rooms 290, 291**

MATERIAL QUANTITY: **400**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **162**  
MATERIAL DESCRIPTION: **12" x 12" Blue with gray and dark blue floor tile**  
MATERIAL LOCATION: **Building C Rooms 290, 291**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **163**  
MATERIAL DESCRIPTION: **Mastic for 12" x 12" Blue with gray and dark blue floor tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Building C rooms 290,291**

MATERIAL QUANTITY: **400**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **163**  
MATERIAL DESCRIPTION: **Mastic for 12" x 12" Blue with gray and dark blue floor tile**  
MATERIAL LOCATION: **Building C rooms 290,291**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **164**  
MATERIAL DESCRIPTION: **12" x 12" :ight brown floor tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Building C Room 178**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **164**  
MATERIAL DESCRIPTION: **12" x 12" light brown floor tile**  
MATERIAL LOCATION: **Building C Room 178**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **165**  
MATERIAL DESCRIPTION: **Mastic for 12" x 12" light brown floor tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Building C 178**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **165**  
MATERIAL DESCRIPTION: **Mastic for 12" x 12" light brown floor tile**  
MATERIAL LOCATION: **Building C 178**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **166**  
MATERIAL DESCRIPTION: **12" x 12" Light gray with dark gray and white floor tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Building C Room 190**

MATERIAL QUANTITY: **600**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **166**  
MATERIAL DESCRIPTION: **12" x 12" Light gray with dark gray and white floor tile**  
MATERIAL LOCATION: **Building C Room 190**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **167**  
MATERIAL DESCRIPTION: **Mastic for 12" x 12" Light gray with dark gray and white floor tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Building C Room 190**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **167**  
MATERIAL DESCRIPTION: **Mastic for 12" x 12" Light gray with dark gray and white floor tile**  
MATERIAL LOCATION: **Building C Room 190**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **168**  
MATERIAL DESCRIPTION: **12" x 12" Light Blue with dark blue and white floor tile.**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Building C Room 190**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 05/09/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **168**  
MATERIAL DESCRIPTION: **12" x 12" Light Blue with dark blue and white floor tile.**  
MATERIAL LOCATION: **Building C Room 190**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **169**  
MATERIAL DESCRIPTION: **Mastic for 12" x 12" Light Blue with dark blue and white floor tile.**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Building C Room 190**

MATERIAL QUANTITY: **200**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **169**  
MATERIAL DESCRIPTION: **Mastic for 12" x 12" Light Blue with dark blue and white floor tile.**  
MATERIAL LOCATION: **Building C Room 190**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17**  
MATERIAL DESCRIPTION: **Red Mix Carpet Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building A - Engineer's Office, 3rd Floor Corridor**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **17**  
MATERIAL DESCRIPTION: **Red Mix Carpet Adhesive**  
MATERIAL LOCATION: **Building A - Engineer's Office, 3rd Floor Corridor**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **170**  
MATERIAL DESCRIPTION: **Brown Carpet Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **224 Library**  
MATERIAL QUANTITY: **4800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **170**  
MATERIAL DESCRIPTION: **Brown Carpet Mastic**  
MATERIAL LOCATION: **224 Library**  
MATERIAL QUANTITY: **4800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **171**  
MATERIAL DESCRIPTION: **Rubber Floor Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 050**  
MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **171**  
MATERIAL DESCRIPTION: **Rubber Floor Mastic**  
MATERIAL LOCATION: **Room 050**  
MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **172**  
MATERIAL DESCRIPTION: **Stair Tread Covering**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Physical Education Building by Locker Rooms**  
MATERIAL QUANTITY: **350** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **172**  
MATERIAL DESCRIPTION: **Stair Tread Covering**  
MATERIAL LOCATION: **Physical Education Building by Locker Rooms**  
MATERIAL QUANTITY: **350** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **173**  
MATERIAL DESCRIPTION: **Stair Tread Covering Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Physical Education Building by Locker Rooms**  
MATERIAL QUANTITY: **350** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **173**  
MATERIAL DESCRIPTION: **Stair Tread Covering Mastic**  
MATERIAL LOCATION: **Physical Education Building by Locker Rooms**  
MATERIAL QUANTITY: **350** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18**  
MATERIAL DESCRIPTION: **Interior Brick**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building A**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **18**  
MATERIAL DESCRIPTION: **Interior Brick**  
MATERIAL LOCATION: **Building A**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18A**  
MATERIAL DESCRIPTION: **Interior Brick**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building C**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **18A**

MATERIAL DESCRIPTION: **Interior Brick**

MATERIAL LOCATION: **Building C**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19**  
MATERIAL DESCRIPTION: **Interior Brick Mortar**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building A**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **19**

MATERIAL DESCRIPTION: **Interior Brick Mortar**

MATERIAL LOCATION: **Building A**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19A**  
MATERIAL DESCRIPTION: **Interior Brick Mortar**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building C**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **19A**  
MATERIAL DESCRIPTION: **Interior Brick Mortar**  
MATERIAL LOCATION: **Building C**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **2**  
MATERIAL DESCRIPTION: **12" x 12" Black Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Building. A - 1st Blue House, 2nd Red House, 3rd Gold House Dining Areas**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **2**  
MATERIAL DESCRIPTION: **12" x 12" Black Floor Tile**  
MATERIAL LOCATION: **Building. A - 1st Blue House, 2nd Red House, 3rd Gold House Dining Areas**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**  
MATERIAL DESCRIPTION: **Joint Compound on Sheetrock**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building A - Engineer's Washroom, Rooms 204 and 304**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **20**  
MATERIAL DESCRIPTION: **Joint Compound on Sheetrock**  
MATERIAL LOCATION: **Building A - Engineer's Washroom, Rooms 204 and 304**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20A**  
MATERIAL DESCRIPTION: **Joint Compound Off Sheetrock**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building C - 293/294 Partition**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **20A**  
MATERIAL DESCRIPTION: **Joint Compound Off Sheetrock**  
MATERIAL LOCATION: **Building C - 293/294 Partition**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

## Carnow, Conibear and Associates 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21**  
MATERIAL DESCRIPTION: **Brown Vinyl Baseboard**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building A - Rooms 128, 204, and 304**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **21**

MATERIAL DESCRIPTION: **Brown Vinyl Baseboard**

MATERIAL LOCATION: **Building A - Rooms 128, 204, and 304**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21A**  
MATERIAL DESCRIPTION: **Brown Vinyl Baseboard**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building C - Rooms 192, 196, and 198**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **21A**  
MATERIAL DESCRIPTION: **Brown Vinyl Baseboard**  
MATERIAL LOCATION: **Building C - Rooms 192, 196, and 198**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22**  
MATERIAL DESCRIPTION: **Brown Vinyl Baseboard Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building A - Rooms 128, 204, and 304**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **22**  
MATERIAL DESCRIPTION: **Brown Vinyl Baseboard Mastic**  
MATERIAL LOCATION: **Building A - Rooms 128, 204, and 304**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22A**  
MATERIAL DESCRIPTION: **Brown Vinyl Baseboard Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building C - Rooms 192, 196, and 198**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **22A**  
MATERIAL DESCRIPTION: **Brown Vinyl Baseboard Mastic**  
MATERIAL LOCATION: **Building C - Rooms 192, 196, and 198**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23**  
MATERIAL DESCRIPTION: **Black Sink Top Caulk**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 320**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **23**

MATERIAL DESCRIPTION: **Black Sink Top Caulk**

MATERIAL LOCATION: **Room 320**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23A**  
MATERIAL DESCRIPTION: **Sink Top Bridging Caulk**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 282 and 291**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **23A**  
MATERIAL DESCRIPTION: **Sink Top Bridging Caulk**  
MATERIAL LOCATION: **Rooms 282 and 291**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**



# Chicago Public Schools

## Carnow, Conibear and Associates 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **24**  
MATERIAL DESCRIPTION: **12"x12" Off-White w/Light Brown Streaks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Delamination  
Deterioration**  
DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Building A - Throughout 1st and 3rd Floor, Lower Level**  
MATERIAL QUANTITY: **16049** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **Damage is located in Building A - throughout lower level**

Inspector's Signature: \_\_\_\_\_



Date: 05/09/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **24**  
MATERIAL DESCRIPTION: **12"x12" Off-White w/Light Brown Streaks Floor Tile**  
MATERIAL LOCATION: **Building A - Throughout 1st and 3rd Floor, Lower Level**  
MATERIAL QUANTITY: **16049** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **3500** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25**  
MATERIAL DESCRIPTION: **12"x12" Off-White Floor Tile w/Lt Brn Strks Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Building A - Throughout 1st and 3rd Floor, Lower Level**  
MATERIAL QUANTITY: **16049** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 05/09/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **25**  
MATERIAL DESCRIPTION: **12"x12" Off-White Floor Tile w/Lt Brn Strks Mastic**  
MATERIAL LOCATION: **Building A - Throughout 1st and 3rd Floor, Lower Level**  
MATERIAL QUANTITY: **16049** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

## Carnow, Conibear and Associates 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26**  
MATERIAL DESCRIPTION: **12" x 12" Sandy Brown & Beige Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Building A - Rooms 322 and 324**  
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **26**  
MATERIAL DESCRIPTION: **12" x 12" Sandy Brown & Beige Floor Tile**  
MATERIAL LOCATION: **Building A - Rooms 322 and 324**  
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

## Carnow, Conibear and Associates 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27**  
MATERIAL DESCRIPTION: **12" x 12" Sandy Brown & Beige Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Building A - Rooms 322(combined w/ 324)**  
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **27**  
MATERIAL DESCRIPTION: **12" x 12" Sandy Brown & Beige Floor Tile Mastic**  
MATERIAL LOCATION: **Building A - Rooms 322(combined w/ 324)**  
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28**  
MATERIAL DESCRIPTION: **Kiln Door Backing**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building A - Room 103**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **28**

MATERIAL DESCRIPTION: **Kiln Door Backing**

MATERIAL LOCATION: **Building A - Room 103**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **29**  
MATERIAL DESCRIPTION: **Kiln Interior Material**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building A - Room 103**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **29**

MATERIAL DESCRIPTION: **Kiln Interior Material**

MATERIAL LOCATION: **Building A - Room 103**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **2B**  
MATERIAL DESCRIPTION: **12"x12" Lt. Beige w/Sandy Brown Streaks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Remove**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Delamination  
Deterioration**  
DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Building B - Random Basement Rooms by Corridors**  
MATERIAL QUANTITY: **3588** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **Damage is located in Building B Basement Corridors**

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **2B**  
MATERIAL DESCRIPTION: **12"x12" Lt. Beige w/Sandy Brown Streaks Floor Tile**  
MATERIAL LOCATION: **Building B - Random Basement Rooms by Corridors**  
MATERIAL QUANTITY: **3588** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **100** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Remove**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **30**  
MATERIAL DESCRIPTION: **Kiln Wiring Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Basement Storage Room**  
MATERIAL QUANTITY: **10** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **30**  
MATERIAL DESCRIPTION: **Kiln Wiring Insulation**  
MATERIAL LOCATION: **Basement Storage Room**  
MATERIAL QUANTITY: **10** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **31**  
MATERIAL DESCRIPTION: **12" x 12" Pearl White Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 102**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2016**

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **31**

MATERIAL DESCRIPTION: **12" x 12" Pearl White Floor Tile**

MATERIAL LOCATION: **Room 102**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.


The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

If identified, implement O&M

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **32**  
MATERIAL DESCRIPTION: **12" x 12" Pearl White Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 102**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **32**  
MATERIAL DESCRIPTION: **12" x 12" Pearl White Floor Tile Mastic**  
MATERIAL LOCATION: **Room 102**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **33**  
MATERIAL DESCRIPTION: **Gray & Black Mix Carpet Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 121 and 215**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **33**  
MATERIAL DESCRIPTION: **Gray & Black Mix Carpet Mastic**  
MATERIAL LOCATION: **Rooms 121 and 215**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **34**  
MATERIAL DESCRIPTION: **Pink Mix Carpet Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 100**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **34**  
MATERIAL DESCRIPTION: **Pink Mix Carpet Adhesive**  
MATERIAL LOCATION: **Room 100**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **35**  
MATERIAL DESCRIPTION: **Light Green Carpet Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building A - Rooms 101, 122, and 145**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **35**  
MATERIAL DESCRIPTION: **Light Green Carpet Adhesive**  
MATERIAL LOCATION: **Building A - Rooms 101, 122, and 145**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **36**  
MATERIAL DESCRIPTION: **Light Blue Mix Carpet Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building A - Rooms 106 and 143**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **36**  
MATERIAL DESCRIPTION: **Light Blue Mix Carpet Mastic**  
MATERIAL LOCATION: **Building A - Rooms 106 and 143**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37**  
MATERIAL DESCRIPTION: **Light Blue & Beige Mix Carpet Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building A - By Elevator, By Room 149**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **37**  
MATERIAL DESCRIPTION: **Light Blue & Beige Mix Carpet Adhesive**  
MATERIAL LOCATION: **Building A - By Elevator, By Room 149**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **38**  
MATERIAL DESCRIPTION: **Light Green & Gray Mix Carpet Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **205 Stage**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **38**  
MATERIAL DESCRIPTION: **Light Green & Gray Mix Carpet Adhesive**  
MATERIAL LOCATION: **205 Stage**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **39**  
MATERIAL DESCRIPTION: **Light Green Vinyl Baseboard**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building A - By Rooms 101, 126, and 139**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **39**  
MATERIAL DESCRIPTION: **Light Green Vinyl Baseboard**  
MATERIAL LOCATION: **Building A - By Rooms 101, 126, and 139**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **40**  
MATERIAL DESCRIPTION: **Light Green Vinyl Baseboard Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building A - By Rooms 101, 126, and 139**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **40**  
MATERIAL DESCRIPTION: **Light Green Vinyl Baseboard Adhesive**  
MATERIAL LOCATION: **Building A - By Rooms 101, 126, and 139**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **41**  
MATERIAL DESCRIPTION: **12" x 12" Cream (w/Beige Streaks) Mix Floor Tile - REMOVED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Elevators**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **41**  
MATERIAL DESCRIPTION: **12" x 12" Cream (w/Beige Streaks) Mix Floor Tile - REMOVED**  
MATERIAL LOCATION: **Elevators**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **42**  
MATERIAL DESCRIPTION: **12" x 12" Cream Mix Floor Tile Mastic - ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building A - Elevators**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **42**

MATERIAL DESCRIPTION: **12" x 12" Cream Mix Floor Tile Mastic - ABATED**

MATERIAL LOCATION: **Building A - Elevators**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **43**  
MATERIAL DESCRIPTION: **Green Carpet Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 116, 125, and 135**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **43**  
MATERIAL DESCRIPTION: **Green Carpet Adhesive**  
MATERIAL LOCATION: **Rooms 116, 125, and 135**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **44**  
MATERIAL DESCRIPTION: **Blue Vinyl Baseboard**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building A - Rooms 116, 125, and 135**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **44**  
MATERIAL DESCRIPTION: **Blue Vinyl Baseboard**  
MATERIAL LOCATION: **Building A - Rooms 116, 125, and 135**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **45**  
MATERIAL DESCRIPTION: **Blue Vinyl Baseboard Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building A - Rooms 116, 125, and 135**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **45**

MATERIAL DESCRIPTION: **Blue Vinyl Baseboard Adhesive**

MATERIAL LOCATION: **Building A - Rooms 116, 125, and 135**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **46**  
MATERIAL DESCRIPTION: **12" x 12" Sandy Beige w/Light Brown Streaks**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON: **Physical Damage**  
HISTORICAL RESPONSE ACTION: **Remove**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Physical Damage  
Deterioration**  
DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Building A - Basement Corridors, Engineer's Office Areas**  
MATERIAL QUANTITY: **5625** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **5625** DAMAGE UNITS: **SF**  
COMMENTS: **Damage located in Building A - throughout lower level**

Inspector's Signature: \_\_\_\_\_



Date: 05/09/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **46**  
MATERIAL DESCRIPTION: **12" x 12" Sandy Beige w/Light Brown Streaks**  
MATERIAL LOCATION: **Building A - Basement Corridors, Engineer's Office Areas**  
MATERIAL QUANTITY: **5625** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **3000** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Remove**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**



# Chicago Public Schools

## Carnow, Conibear and Associates 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **47**  
MATERIAL DESCRIPTION: **12" x 12" Sandy Beige w/Lt Brn Streaks FT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Building A - Basement Corridors, Engineer's Office Areas**  
MATERIAL QUANTITY: **5625** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **47**  
MATERIAL DESCRIPTION: **12" x 12" Sandy Beige w/Lt Brn Streaks FT Mastic**  
MATERIAL LOCATION: **Building A - Basement Corridors, Engineer's Office Areas**  
MATERIAL QUANTITY: **5625** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **48**  
MATERIAL DESCRIPTION: **12" x 12" Dark Sandy Brown Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building A - Corridors by Engineer's Office, Rooms 011 and 014**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not observed 2016**

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **48**  
MATERIAL DESCRIPTION: **12" x 12" Dark Sandy Brown Floor Tile**  
MATERIAL LOCATION: **Building A - Corridors by Engineer's Office, Rooms 011 and 014**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

If identified, implement O&M

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **49**  
MATERIAL DESCRIPTION: **12" x 12" Dark Sandy Brown Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Corridors by Engineer's Office, Rooms 011, 013, and 014**  
MATERIAL QUANTITY: **62** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **49**  
MATERIAL DESCRIPTION: **12" x 12" Dark Sandy Brown Floor Tile Mastic**  
MATERIAL LOCATION: **Corridors by Engineer's Office, Rooms 011, 013, and 014**  
MATERIAL QUANTITY: **62** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **50**  
MATERIAL DESCRIPTION: **12" x 12" Light Sandy Pink Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Engineer's Lunchroom**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not observed 2016 - Now wood laminate flooring**

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **50**  
MATERIAL DESCRIPTION: **12" x 12" Light Sandy Pink Floor Tile**  
MATERIAL LOCATION: **Engineer's Lunchroom**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.


The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

If identified, implement O&M

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **51**  
MATERIAL DESCRIPTION: **12" x 12" Light Sandy Pink Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Engineer's Lunchroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **51**  
MATERIAL DESCRIPTION: **12" x 12" Light Sandy Pink Floor Tile Mastic**  
MATERIAL LOCATION: **Engineer's Lunchroom**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **52**  
MATERIAL DESCRIPTION: **12" x 12" Sandy Peach Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building A - Engineer's Lunchroom**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not observed 2016 - Now wood laminate flooring**

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **52**  
MATERIAL DESCRIPTION: **12" x 12" Sandy Peach Floor Tile**  
MATERIAL LOCATION: **Building A - Engineer's Lunchroom**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.


The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

If identified, implement O&M

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **53**  
MATERIAL DESCRIPTION: **12" x 12" Sandy Peach Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Engineer's Lunchroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **53**  
MATERIAL DESCRIPTION: **12" x 12" Sandy Peach Floor Tile Mastic**  
MATERIAL LOCATION: **Engineer's Lunchroom**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **54**  
MATERIAL DESCRIPTION: **Bright Orange Carpet Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 128 A and 128 B**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **54**

MATERIAL DESCRIPTION: **Bright Orange Carpet Adhesive**

MATERIAL LOCATION: **Rooms 128 A and 128 B**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **55**  
MATERIAL DESCRIPTION: **Black Sandy Mix Carpet Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 105/107**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **55**

MATERIAL DESCRIPTION: **Black Sandy Mix Carpet Adhesive**

MATERIAL LOCATION: **Room 105/107**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **56**  
MATERIAL DESCRIPTION: **Multi-Colored Carpet Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 118/120 offices**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **56**

MATERIAL DESCRIPTION: **Multi-Colored Carpet Adhesive**

MATERIAL LOCATION: **Rooms 118/120 offices**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

## Carnow, Conibear and Associates 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **57**  
MATERIAL DESCRIPTION: **12" x 12" Bluish-Green Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 118/120**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2016 - Could be under carpet**

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **57**

MATERIAL DESCRIPTION: **12" x 12" Bluish-Green Floor Tile**

MATERIAL LOCATION: **Rooms 118/120**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.


The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

If identified, implement O&M

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **58**  
MATERIAL DESCRIPTION: **12" x 12" Bluish-Green Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 118/120**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **58**  
MATERIAL DESCRIPTION: **12" x 12" Bluish-Green Floor Tile Mastic**  
MATERIAL LOCATION: **Room 118/120**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **59**  
MATERIAL DESCRIPTION: **Maroon Carpet Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 109**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **59**

MATERIAL DESCRIPTION: **Maroon Carpet Adhesive**

MATERIAL LOCATION: **Room 109**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **6**  
MATERIAL DESCRIPTION: **Black Table Top Material**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Building C - Room 179**  
MATERIAL QUANTITY: **16** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 05/09/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **6**  
MATERIAL DESCRIPTION: **Black Table Top Material**  
MATERIAL LOCATION: **Building C - Room 179**  
MATERIAL QUANTITY: **16** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **60**  
MATERIAL DESCRIPTION: **Black/Yellow/Red Mix Carpet Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 139**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **60**  
MATERIAL DESCRIPTION: **Black/Yellow/Red Mix Carpet Adhesive**  
MATERIAL LOCATION: **Room 139**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **61**  
MATERIAL DESCRIPTION: **12" x 12" Soft Beige w/Brown Specks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 108**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **61**  
MATERIAL DESCRIPTION: **12" x 12" Soft Beige w/Brown Specks Floor Tile**  
MATERIAL LOCATION: **Room 108**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **62**  
MATERIAL DESCRIPTION: **12" x 12" Soft Beige w/Brown Specks FT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Building A - Room 108**

MATERIAL QUANTITY: **60**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **62**  
MATERIAL DESCRIPTION: **12" x 12" Soft Beige w/Brown Specks FT Mastic**  
MATERIAL LOCATION: **Building A - Room 108**  
MATERIAL QUANTITY: **60** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **63**  
MATERIAL DESCRIPTION: **Light Green Carpet Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Principal's Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **63**

MATERIAL DESCRIPTION: **Light Green Carpet Adhesive**

MATERIAL LOCATION: **Principal's Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **64**  
MATERIAL DESCRIPTION: **12" x 12" Dark Beige w/Reddish Brown Streaks FT**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building A - Corridor by 012**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2016**

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **64**  
MATERIAL DESCRIPTION: **12" x 12" Dark Beige w/Reddish Brown Streaks FT**  
MATERIAL LOCATION: **Building A - Corridor by 012**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.


The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

If identified, implement O&M

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **65**  
MATERIAL DESCRIPTION: **12"x12" Dark Beige w/Reddish Brown Streaks Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building A - Corridor by Room 012**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not observed 2016**

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **65**  
MATERIAL DESCRIPTION: **12"x12" Dark Beige w/Reddish Brown Streaks Mastic**  
MATERIAL LOCATION: **Building A - Corridor by Room 012**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

If identified, implement O&M

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **66**  
MATERIAL DESCRIPTION: **Dark Ash Gray Vinyl Baseboard**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Building C - Rooms 012, 290, and 299**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **66**  
MATERIAL DESCRIPTION: **Dark Ash Gray Vinyl Baseboard**  
MATERIAL LOCATION: **Building C - Rooms 012, 290, and 299**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **67**  
MATERIAL DESCRIPTION: **Dark Ash Gray Vinyl Baseboard Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Building C - Rooms 012, 290, and 299**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **67**  
MATERIAL DESCRIPTION: **Dark Ash Gray Vinyl Baseboard Mastic**  
MATERIAL LOCATION: **Building C - Rooms 012, 290, and 299**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

## Carnow, Conibear and Associates 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **68**  
MATERIAL DESCRIPTION: **Building Partition Floor Compound**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building C - 2nd Floor A and C Tunnel**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **68**  
MATERIAL DESCRIPTION: **Building Partition Floor Compound**  
MATERIAL LOCATION: **Building C - 2nd Floor A and C Tunnel**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **69**  
MATERIAL DESCRIPTION: **12x12 Light Sandy Off-White w/Lt Brown Streaks FT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Building C - 2nd Floor Bridge & Corridor, Rooms 177, 179, 276, 293, 294, 196, 197, 198 and 1st floor corridor adjacent to 199**

MATERIAL QUANTITY: **9350** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **69**  
MATERIAL DESCRIPTION: **12x12 Light Sandy Off-White w/Lt Brown Streaks FT**  
MATERIAL LOCATION: **Building C - 2nd Floor Bridge & Corridor, Rooms 177, 179, 276, 293, 294, 196, 197, 198 and 1st floor corridor adjacent to 199**  
MATERIAL QUANTITY: **9350** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**



# Chicago Public Schools

## Carnow, Conibear and Associates 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **69.1**  
MATERIAL DESCRIPTION: **12x12 Lt. Sandy Off-Wt w/Lt Brn Streaks FT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Building C - 2nd Floor Bridge & Corridor, Rooms 177, 179, 196, 197, 198, 276, 293, 294 and 1st floor corridor adjacent to 199**

MATERIAL QUANTITY: **9350** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **69.1**  
MATERIAL DESCRIPTION: **12x12 Lt. Sandy Off-Wt w/Lt Brn Streaks FT Mastic**  
MATERIAL LOCATION: **Building C - 2nd Floor Bridge & Corridor, Rooms 177, 179, 196, 197, 198, 276, 293, 294 and 1st floor corridor adjacent to 199**  
MATERIAL QUANTITY: **9350** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **7**  
MATERIAL DESCRIPTION: **Fire Door Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Building A - Randomly Distributed**  
MATERIAL QUANTITY: **52** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **7**  
MATERIAL DESCRIPTION: **Fire Door Insulation**  
MATERIAL LOCATION: **Building A - Randomly Distributed**  
MATERIAL QUANTITY: **52** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **70**  
MATERIAL DESCRIPTION: **12" x 12" Off-White w/Light Brown Streaks Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Building C - 2nd Floor Bridge & Corridor, Rooms 177, 179, 276, 294, 293**  
MATERIAL QUANTITY: **18700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **70**  
MATERIAL DESCRIPTION: **12" x 12" Off-White w/Light Brown Streaks Mastic**  
MATERIAL LOCATION: **Building C - 2nd Floor Bridge & Corridor, Rooms 177, 179, 276, 294, 293**  
MATERIAL QUANTITY: **18700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **71**  
MATERIAL DESCRIPTION: **12" x 12" Off-White & Cream w/Streaks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Building C - Rooms 175, 181, 275, 277-280 282, 288, 292, 295, 297, and 298**  
MATERIAL QUANTITY: **8000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **71**  
MATERIAL DESCRIPTION: **12" x 12" Off-White & Cream w/Streaks Floor Tile**  
MATERIAL LOCATION: **Building C - Rooms 175, 181, 275, 277-280 282, 288, 292, 295, 297, and 298**  
MATERIAL QUANTITY: **8000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **72**  
MATERIAL DESCRIPTION: **12" x 12" Off-White & Cream w/Streaks FT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building C - Rooms 175, 181, 275, 277-280 282, 288, 292, 295, 297, and 298**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **72**  
MATERIAL DESCRIPTION: **12" x 12" Off-White & Cream w/Streaks FT Mastic**  
MATERIAL LOCATION: **Building C - Rooms 175, 181, 275, 277-280 282, 288, 292, 295, 297, and 298**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **73**  
MATERIAL DESCRIPTION: **Peach Fire Rated Curtain Material**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building C - Rooms 275, 282, and 295**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **73**  
MATERIAL DESCRIPTION: **Peach Fire Rated Curtain Material**  
MATERIAL LOCATION: **Building C - Rooms 275, 282, and 295**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **74**  
MATERIAL DESCRIPTION: **12" x 12" Light Pink w/Beige Streaks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Building C - Elevators**  
MATERIAL QUANTITY: **60** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **74**  
MATERIAL DESCRIPTION: **12" x 12" Light Pink w/Beige Streaks Floor Tile**  
MATERIAL LOCATION: **Building C - Elevators**  
MATERIAL QUANTITY: **60** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **75**  
MATERIAL DESCRIPTION: **12x12 Light Pink w/Beige Streaks Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building C - Elevators**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **75**  
MATERIAL DESCRIPTION: **12x12 Light Pink w/Beige Streaks Floor Tile Mastic**  
MATERIAL LOCATION: **Building C - Elevators**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**



# Chicago Public Schools

## Carnow, Conibear and Associates 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **76**  
MATERIAL DESCRIPTION: **Light Green & Gray Vinyl Baseboard**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 278, 282, and 286**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **76**

MATERIAL DESCRIPTION: **Light Green & Gray Vinyl Baseboard**

MATERIAL LOCATION: **Rooms 278, 282, and 286**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **77**  
MATERIAL DESCRIPTION: **Light Green & Gray Vinyl Baseboard Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 278, 282, and 286**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **77**

MATERIAL DESCRIPTION: **Light Green & Gray Vinyl Baseboard Adhesive**

MATERIAL LOCATION: **Rooms 278, 282, and 286**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **78**  
MATERIAL DESCRIPTION: **Bright Orange Carpet Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 290**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **78**  
MATERIAL DESCRIPTION: **Bright Orange Carpet Adhesive**  
MATERIAL LOCATION: **Room 290**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **79**  
MATERIAL DESCRIPTION: **Mastic 12" x 12" Brown with dark brown floor tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Building A 1st floor hallway and room 117**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 05/09/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **79**  
MATERIAL DESCRIPTION: **Mastic 12" x 12" Brown with dark brown floor tile**  
MATERIAL LOCATION: **Building A 1st floor hallway and room 117**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **8**  
MATERIAL DESCRIPTION: **12" x 12" Black Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Building A - 1st Blue House (Area where columns are painted blue)**  
MATERIAL QUANTITY: **19875** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **8**  
MATERIAL DESCRIPTION: **12" x 12" Black Floor Tile Mastic**  
MATERIAL LOCATION: **Building A - 1st Blue House (Area where columns are painted blue)**  
MATERIAL QUANTITY: **19875** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **80**  
MATERIAL DESCRIPTION: **12" x 12" Light Beige w/Light Brown Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Building C - Rooms 198 and 298, 1st Floor Stage Back Areas**  
MATERIAL QUANTITY: **10285** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **80**  
MATERIAL DESCRIPTION: **12" x 12" Light Beige w/Light Brown Mastic**  
MATERIAL LOCATION: **Building C - Rooms 198 and 298, 1st Floor Stage Back Areas**  
MATERIAL QUANTITY: **10285** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **81**  
MATERIAL DESCRIPTION: **Light Blue Carpet Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 196 and 198**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **81**  
MATERIAL DESCRIPTION: **Light Blue Carpet Adhesive**  
MATERIAL LOCATION: **Rooms 196 and 198**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **82**  
MATERIAL DESCRIPTION: **Light Blue Vinyl Baseboard**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 196 and 198**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **82**  
MATERIAL DESCRIPTION: **Light Blue Vinyl Baseboard**  
MATERIAL LOCATION: **Rooms 196 and 198**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **83**  
MATERIAL DESCRIPTION: **Light Blue Vinyl Baseboard Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 196 and 198**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **83**

MATERIAL DESCRIPTION: **Light Blue Vinyl Baseboard Adhesive**

MATERIAL LOCATION: **Rooms 196 and 198**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

## Carnow, Conibear and Associates 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **84**  
MATERIAL DESCRIPTION: **12"x12" Light Silver w/Multiple Streaks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st Floor Theater**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2016**

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **84**

MATERIAL DESCRIPTION: **12"x12" Light Silver w/Multiple Streaks Floor Tile**

MATERIAL LOCATION: **1st Floor Theater**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

If identified, implement O&M

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **85**  
MATERIAL DESCRIPTION: **12"x12" Light Silver w/Multiple Streaks FT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **First Floor Theatre**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **85**

MATERIAL DESCRIPTION: **12"x12" Light Silver w/Multiple Streaks FT Mastic**

MATERIAL LOCATION: **First Floor Theatre**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **86**  
MATERIAL DESCRIPTION: **Floor Cap Material & Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Theater, Auditorium Stage**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **86**

MATERIAL DESCRIPTION: **Floor Cap Material & Adhesive**

MATERIAL LOCATION: **Theater, Auditorium Stage**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **87**  
MATERIAL DESCRIPTION: **Floor Cap Material Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Theater, Auditorium Stage**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **87**

MATERIAL DESCRIPTION: **Floor Cap Material Adhesive**

MATERIAL LOCATION: **Theater, Auditorium Stage**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **88**  
MATERIAL DESCRIPTION: **Light Red Mix Carpet Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Auditorium**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **88**

MATERIAL DESCRIPTION: **Light Red Mix Carpet Adhesive**

MATERIAL LOCATION: **Auditorium**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **89**  
MATERIAL DESCRIPTION: **Ash Mix Carpet Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 186, Back Stage Area**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **89**

MATERIAL DESCRIPTION: **Ash Mix Carpet Adhesive**

MATERIAL LOCATION: **Room 186, Back Stage Area**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

## Carnow, Conibear and Associates 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **8B**  
MATERIAL DESCRIPTION: **12"x12"Light Beige FT w/Sandy Brown Streaks Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Building B - Random Basement Rooms by Corridors**  
MATERIAL QUANTITY: **3588** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **8B**  
MATERIAL DESCRIPTION: **12"x12"Light Beige FT w/Sandy Brown Streaks Mastic**  
MATERIAL LOCATION: **Building B - Random Basement Rooms by Corridors**  
MATERIAL QUANTITY: **3588** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **90**  
MATERIAL DESCRIPTION: **Light Brown & Pink Mix Carpet Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 188, A/V Equipment Room Areas**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **90**  
MATERIAL DESCRIPTION: **Light Brown & Pink Mix Carpet Adhesive**  
MATERIAL LOCATION: **Room 188, A/V Equipment Room Areas**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **91**  
MATERIAL DESCRIPTION: **Chocolate Brown Vinyl Baseboard**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 188, A/V room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **91**  
MATERIAL DESCRIPTION: **Chocolate Brown Vinyl Baseboard**  
MATERIAL LOCATION: **Room 188, A/V room**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **92**  
MATERIAL DESCRIPTION: **Chocolate Brown Vinyl Baseboard Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 188, A/V Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **92**

MATERIAL DESCRIPTION: **Chocolate Brown Vinyl Baseboard Adhesive**

MATERIAL LOCATION: **Room 188, A/V Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **93**  
MATERIAL DESCRIPTION: **Motor Interior Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **LL1 Elevator Motor Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **93**

MATERIAL DESCRIPTION: **Motor Interior Insulation**

MATERIAL LOCATION: **LL1 Elevator Motor Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **94**  
MATERIAL DESCRIPTION: **Exterior Brick**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building C Exterior**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **94**

MATERIAL DESCRIPTION: **Exterior Brick**

MATERIAL LOCATION: **Building C Exterior**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **95**  
MATERIAL DESCRIPTION: **Exterior Brick Mortar**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building C Exterior**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **95**

MATERIAL DESCRIPTION: **Exterior Brick Mortar**

MATERIAL LOCATION: **Building C Exterior**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **96**  
MATERIAL DESCRIPTION: **Cinderblock**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building A - Engineer's Lunchroom, 3rd Floor Gold House, Dock Area**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **96**  
MATERIAL DESCRIPTION: **Cinderblock**  
MATERIAL LOCATION: **Building A - Engineer's Lunchroom, 3rd Floor Gold House, Dock Area**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **97**  
MATERIAL DESCRIPTION: **Cinderblock Mortar**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building A - Engineer's Lunchroom, 3rd Floor Gold House, Dock Area**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **97**  
MATERIAL DESCRIPTION: **Cinderblock Mortar**  
MATERIAL LOCATION: **Building A - Engineer's Lunchroom, 3rd Floor Gold House, Dock Area**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **98**  
MATERIAL DESCRIPTION: **Cinderblock**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **LL2 by Elevators, 1st and 2nd Floor Electric Closet**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **98**  
MATERIAL DESCRIPTION: **Cinderblock**  
MATERIAL LOCATION: **LL2 by Elevators, 1st and 2nd Floor Electric Closet**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **99**  
MATERIAL DESCRIPTION: **Cinderblock Mortar**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **LL2 by Elevators, 1st and 2nd Floor Electric Closet**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **99**  
MATERIAL DESCRIPTION: **Cinderblock Mortar**  
MATERIAL LOCATION: **LL2 by Elevators, 1st and 2nd Floor Electric Closet**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

## Carnow, Conibear and Associates 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **9A**  
MATERIAL DESCRIPTION: **Black Vinyl Baseboard**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building C - 2nd Floor Dressing Room, Rooms 198 and 282**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **9A**  
MATERIAL DESCRIPTION: **Black Vinyl Baseboard**  
MATERIAL LOCATION: **Building C - 2nd Floor Dressing Room, Rooms 198 and 282**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **9B**  
MATERIAL DESCRIPTION: **Black Vinyl Baseboard**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building B - Rooms 050, 156, 173, and 255**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **9B**  
MATERIAL DESCRIPTION: **Black Vinyl Baseboard**  
MATERIAL LOCATION: **Building B - Rooms 050, 156, 173, and 255**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **A**  
MATERIAL DESCRIPTION: **Breeching Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY: **Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building B-Basement areas**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2016**

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **A**  
MATERIAL DESCRIPTION: **Breeching Insulation**  
MATERIAL LOCATION: **Building B-Basement areas**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

If identified, implement O&M

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **E**  
MATERIAL DESCRIPTION: **Joint Compound Off Fiberglass Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building C - Basement**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **E**

MATERIAL DESCRIPTION: **Joint Compound Off Fiberglass Pipe Insulation**

MATERIAL LOCATION: **Building C - Basement**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **G**  
MATERIAL DESCRIPTION: **Water Tank Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building B - Swimming Pool Tunnel Areas**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **G**  
MATERIAL DESCRIPTION: **Water Tank Insulation**  
MATERIAL LOCATION: **Building B - Swimming Pool Tunnel Areas**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

## Carnow, Conibear and Associates 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **I**  
MATERIAL DESCRIPTION: **Hard Joint Compound Off Mag Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY: **Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building B- Swimming Pool Tunnel Areas & Bldg A-Mechanical Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not observed 2016 - Inaccessible**

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **I**  
MATERIAL DESCRIPTION: **Hard Joint Compound Off Mag Pipe Insulation**  
MATERIAL LOCATION: **Building B- Swimming Pool Tunnel Areas & Bldg A-Mechanical Room**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.


The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

If identified, implement O&M

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **J**  
MATERIAL DESCRIPTION: **Mag Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building B - Swimming Pool Area, Generator Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **J**  
MATERIAL DESCRIPTION: **Mag Pipe Insulation**  
MATERIAL LOCATION: **Building B - Swimming Pool Area, Generator Room**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **K**  
MATERIAL DESCRIPTION: **Breeching Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Building A - Mechanical Room**  
MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **K**  
MATERIAL DESCRIPTION: **Breeching Insulation**  
MATERIAL LOCATION: **Building A - Mechanical Room**  
MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **L**  
MATERIAL DESCRIPTION: **Hot Water Tank Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room B-10**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **L**

MATERIAL DESCRIPTION: **Hot Water Tank Insulation**

MATERIAL LOCATION: **Room B-10**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **P**  
MATERIAL DESCRIPTION: **Duct Expansion Material**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building A - Basement Mechanical Area**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **P**  
MATERIAL DESCRIPTION: **Duct Expansion Material**  
MATERIAL LOCATION: **Building A - Basement Mechanical Area**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **P1**  
MATERIAL DESCRIPTION: **Duct Expansion Material**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building B**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **P1**  
MATERIAL DESCRIPTION: **Duct Expansion Material**  
MATERIAL LOCATION: **Building B**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **Q**  
MATERIAL DESCRIPTION: **Preform Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Building C - Lower Level Basement Areas, Above Ceiling Throughout Building**  
MATERIAL QUANTITY: **125** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **Q**  
MATERIAL DESCRIPTION: **Preform Pipe Insulation**  
MATERIAL LOCATION: **Building C - Lower Level Basement Areas, Above Ceiling Throughout Building**  
MATERIAL QUANTITY: **125** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **R**  
MATERIAL DESCRIPTION: **Acoustical Door Packing Material**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building C - Rooms 196 and 198**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **R**  
MATERIAL DESCRIPTION: **Acoustical Door Packing Material**  
MATERIAL LOCATION: **Building C - Rooms 196 and 198**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **S**  
MATERIAL DESCRIPTION: **Acoustical Door Packing**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building A - Room 139**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **S**  
MATERIAL DESCRIPTION: **Acoustical Door Packing**  
MATERIAL LOCATION: **Building A - Room 139**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **T**  
MATERIAL DESCRIPTION: **Mechanical Unit Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Amosite, Chrysotile** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building A - Mechanical Room on Roof**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not observed 2016 - Inaccessible**

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **T**  
MATERIAL DESCRIPTION: **Mechanical Unit Insulation**  
MATERIAL LOCATION: **Building A - Mechanical Room on Roof**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

If identified, implement O&M

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **U**  
MATERIAL DESCRIPTION: **Joint Compound Off Preformed Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **1 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON: **Delamination  
Deterioration  
Physical Damage**  
DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Building C - Lower Level Basement Areas**  
MATERIAL QUANTITY: **50** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**  
COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **U**  
MATERIAL DESCRIPTION: **Joint Compound Off Preformed Pipe Insulation**  
MATERIAL LOCATION: **Building C - Lower Level Basement Areas**  
MATERIAL QUANTITY: **50** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **8** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.


The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Repair or Remove as applicable. Continue O&M

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **V**  
MATERIAL DESCRIPTION: **Joint Compound Off Tar Covering on Fiberglass Pipe**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Swimming Pool Tunnels**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **V**  
MATERIAL DESCRIPTION: **Joint Compound Off Tar Covering on Fiberglass Pipe**  
MATERIAL LOCATION: **Swimming Pool Tunnels**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **W**  
MATERIAL DESCRIPTION: **12x12 VFT light green**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 178**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2016**

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **W**  
MATERIAL DESCRIPTION: **12x12 VFT light green**  
MATERIAL LOCATION: **Room 178**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

If identified, implement O&M

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School** INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **W-1**  
MATERIAL DESCRIPTION: **12x12 VFT light green-MASTIC**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 178**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2016**

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUIDLING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **W-1**  
MATERIAL DESCRIPTION: **12x12 VFT light green-MASTIC**  
MATERIAL LOCATION: **Room 178**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

If identified, implement O&M

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **47101**      BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School**      INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin**      IDPH LICENSE NO: **100-09969**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **175**  
MATERIAL DESCRIPTION: **Wood Glue Over Existing**  
MATERIAL LOCATION: **Building A - 220/222 Engineer's Office**  
MATERIAL QUANTITY: **750**      MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**      FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**      CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Not Reachable**      DAMAGE REASON:  
DAMAGE QUANTITY: **0**      DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **175**  
MATERIAL DESCRIPTION: **Wood Glue Over Existing**  
MATERIAL LOCATION: **Building A - 220/222 Engineer's Office**  
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: 06/02/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **47101**      BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School**      INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin**      IDPH LICENSE NO: **100-09969**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **177**  
MATERIAL DESCRIPTION: **Ceramic Grout**  
MATERIAL LOCATION: **Building A - Main Office**  
MATERIAL QUANTITY: **1000**      MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**      FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**      CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**      DAMAGE REASON:  
DAMAGE QUANTITY: **0**      DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Dionne G. Walker*

Date: 05/09/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**  
ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **177**

MATERIAL DESCRIPTION: **Ceramic Grout**

MATERIAL LOCATION: **Building A - Main Office**

MATERIAL QUANTITY: **1000**

MATERIAL UNITS:

**SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS:

**SF**


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **47101**      BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School**      INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin**      IDPH LICENSE NO: **100-09969**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **176**  
MATERIAL DESCRIPTION: **Terrazo**  
MATERIAL LOCATION: **Building C - 1st Floor Theater**  
MATERIAL QUANTITY: **5000**      MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**      FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**      CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**      DAMAGE REASON:  
DAMAGE QUANTITY: **0**      DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Dionne G. Walker*

Date: 05/09/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**

SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**

ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **176**

MATERIAL DESCRIPTION: **Terrazo**

MATERIAL LOCATION: **Building C - 1st Floor Theater**

MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **47101**      BUILDING ID: **1810**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **Whitney Young Magnet High School**      INSPECTION DATE: **5/9/2016**  
ADDRESS: **211 S. Laflin**      IDPH LICENSE NO: **100-09969**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **174**  
MATERIAL DESCRIPTION: **Laminate Roll Adhesive**  
MATERIAL LOCATION: **Building C - 290 Storage**  
MATERIAL QUANTITY: **100**      MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**      FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**      CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Not Reachable**      DAMAGE REASON:  
DAMAGE QUANTITY: **0**      DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature:



Date: **05/09/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47101** BUILDING ID: **1810**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**

SCHOOL NAME: **Whitney Young Magnet High School** REVIEW DATE: **6/2/2016**

ADDRESS: **211 S. Laflin** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **174**

MATERIAL DESCRIPTION: **Laminate Roll Adhesive**

MATERIAL LOCATION: **Building C - 290 Storage**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: **06/02/2016**

# APPENDIX B

## Inspector and Management Planner Licenses

---

# JAINA ASSOCIATES

THIS IS TO CERTIFY

THAT

**DIONNE L. CAREY**

HAS SUCCESSFULLY COMPLETED THE SAMPLING AND EVALUATING ASBESTOS AIRBORNE DUST - NIOSH 582 EQUIVALENT TRAINING COURSE, AND PASSED THE EXAMINATION WITH A SCORE OF 70% OR ABOVE FOR THE PURPOSE OF CERTIFICATION.

COURSE DATE: May 14 to 17, 2005

EXAM DATE: May 17, 2005

LOCATION: GSG Environmental, Inc.  
855 West Adams Street, Suite 200  
Chicago, Illinois 60607

DIRECTOR  
OF TRAINING:  
  
SANJIV JAIN

CERTIFICATE No.: 05JA-051405  
IDPH COURSE PROVIDER No.: 038



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • [www.dph.illinois.gov](http://www.dph.illinois.gov)

4/18/2016

**DIONNE L CAREY WALKER**  
211 Somerset Drive  
Streamwood, IL 60107

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 09969

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

ASBESTOS PROFESSIONAL LICENSE			ENDORSEMENTS	TC EXPIRES
			INSPECTOR	3/11/2017
ID NUMBER	ISSUED	EXPIRES	PROJECT MANAGER	3/12/2017
100 - 09969	4/18/2016	05/15/2017	AIR SAMPLING PROFESSIONAL	
<b>DIONNE L CAREY WALKER</b>			<b>Alteration of this license shall result in legal action</b>	
211 Somerset Drive			This license issued under authority of the State of Illinois	
Streamwood, IL 60107			Department of Public Health	
Environmental Health			This license is valid only when accompanied by a valid training course certificate.	

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: [dph.illinois.gov/topics-services/environmental-health-protection/asbestos](http://dph.illinois.gov/topics-services/environmental-health-protection/asbestos)  
EMAIL Address: [dph.asbestos@illinois.gov](mailto:dph.asbestos@illinois.gov)

PROTECTING HEALTH, IMPROVING LIVES  
*Nationally Accredited by PHAB*

2016



**OCCUPATIONAL TRAINING & SUPPLY, INC.**

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900

# Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

**Daniel Juneau**


has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 1/6/2016

Exam Date: 1/6/2016

Expiration Date: 1/6/2017

Certificate Number: MPR1601060038

  
\_\_\_\_\_  
Kathy DeSalvo, Director

# Daniel Juneau

Illinois Licensed Asbestos Inspector, Management Planner,  
Project Manager, and Air Sampling Professional



## ASBESTOS PROFESSIONAL LICENSE

ID NUMBER  
**100 - 03613**

ISSUED  
**3/16/2015**

EXPIRES  
**05/15/2016**

DANIEL J JUNEAU  
1408 OAKWOOD AVENUE  
DES PLAINES, IL 60016

Environmental Health



### ENDORSEMENTS

### TC EXPIRES

INSPECTOR

12/2/2015

MANAGEMENT PLANNER

1/20/2016

PROJECT MANAGER

12/11/2015

AIR SAMPLING PROFESSIONAL

**Alteration of this license shall result in legal action**  
This license issued under authority of the State of Illinois  
Department of Public Health

This license is valid only when accompanied by a valid  
training course certificate.

**CARNOW  
CONIBEAR**

2015



**OCCUPATIONAL TRAINING & SUPPLY, INC.**

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900

# Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

**Daniel Juneau**


has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 12/2/2015

Exam Date: 12/2/2015

Expiration Date: 12/2/2016

Certificate Number: BIR1512024163

  
\_\_\_\_\_  
Kathy DeSalvo, Director



# APPENDIX C

## Laboratory Accreditations

---

# APPENDIX D

## Laboratory Results

---

# APPENDIX E

## Chain of Custody Forms

---

## Three-Year Reinspection Key to Terms

	<b>CODE</b>	<b>KEY</b>
<b>MATERIAL</b>		
	ACBM	Asbestos Containing Building Materials
<b>MATERIAL CATEGORY</b>		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
<b>MATERIAL UNITS</b>		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
<b>DAMAGE TYPE</b>		
	Loc	Localized
	Dist	Distributed