

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM**

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-
SCHOOL NAME: The Academy for Global Citizenship NEW
ADDRESS OF SCHOOL: 4647 West 47th Street
CITY: Chicago, IL, 60632

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **4/29/2013**

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II *(Please type or print)*

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 4/26/2016 ENROLLMENT 461
IDPH INSPECTOR LICENSE NUMBER: 100-08864
IDPH LICENSED INSPECTOR NAME (Please Print): Robert DeBord
IDPH MP LICENSE NUMBER: 100-09870
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Todd Huffer

DESIGNATED PERSON (Please Print): Robert Christlieb PHONE: (773) 553-3197



4/26/2016

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

The Academy for Global Citizenship NEW

4647 West 47th Street
Chicago, IL, 60632

Unit: 63011
Building ID: 2025

IDPH ID Number: 14-016-2990-

REPORT DATE:

Tuesday, April 26, 2016

Prepared for:

Chicago Public Schools
125 S. Clark Street
Chicago, IL 60603

Prepared by:

Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone (312) 762-2900

Fax (312) 782-5145

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

March 24, 2016

Mr. R. Kent Cook
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2016 Three-Year Reinspections

Dear Mr. Cook:

Carnow, Conibear and Associates, Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 3,4,5 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 63011 Region: 04 IDPH ID: 14-016-2990-

School: The Academy for Global Citizenship NEW Building ID: 2025

Address: 4647 West 47th Street
Chicago, IL, 60632

Building Contact: Contact Phone:

Current Building Owners: Chicago Public Schools

Review Date: 04/26/2016

Inspector: Robert DeBord Inspector IDPH License: 100-08864
Management Planner: Todd Huffer Management Planner IDPH License: 100-09870

If you have any questions or comments, please contact us at (312) 762-2900

Sincerely,
Carnow, Conibear and Associates



Todd Huffer
100-09870

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: March 24, 2016

RE: The Academy for Global Citizenship NEW, Unit 63011
4647 West 47th Street
Chicago, IL, 60632

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2016 asbestos three year re-inspection has been completed at The Academy for Global Citizenship NEW , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at The Academy for Global Citizenship NEW, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Robert Christlieb, the designated Local Education Authority's Designated Person at (773) 553-3197 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: The Academy for Global Citizenship NEW Unit: 63011 Region: 04
Address: 4647 West 47th Street Chicago, IL, 60632
IDPH ID: 14-016-2990- Building ID: 2025
Contact: Phone:

2. Description of Facility

Original Construction: Additional Construction:
Total Square Footage: 11000 No of Floors:
Current Occupancy: 461

3. LEA Designated Person

Contact: Robert Christlieb Phone: (773) 553-3197
Address: 125 South Clark Street, 17th Floor
Chicago, IL 60603

4. Managing Environmental Consultant

MEC: Carnow, Conibear and Associates
Contact: Dan Juneau
Address 600 West Van Buren St., Ste 500
Phone: (312) 762-2900 Fax: (312) 782-5145

5. Inspector

Inspector Name: Robert DeBord

Inspector IDPH license # 100-08864

Signature:
Date: 3/24/2016

6. Management Planner

Management Planner Name: Todd Huffer

Management Planner IDPH license # 100-09870

Signature: 
Date: 04/26/2016

7. Review Date: 04/26/2016

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature:



Date: 4/26/2016

Name: Robert Christlieb

II. EXECUTIVE SUMMARY

Carnow, Conibear and Associates was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the The Academy for Global Citizenship NEW. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 2025:

- | | |
|---|---|
| 1 | 12" x 12" Gray w/ White Floor Tile |
| 3 | 12" x 12" Off-White w/ Gray Specks Floor Tile |

B. The following new homogenous areas have been identified for Building 2025:

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

- 1 12" x 12" Gray w/ White Floor Tile
- 10 12" x 12" Beige Mix Floor Tile Mastic
- 11 4" Beige Vinyl Baseboard
- 12 4" Beige Vinyl Baseboard Mastic
- 13 4" White (Painted Brown) Vinyl Baseboard
- 14 4" White (Painted Brown) Vinyl Baseboard Mastic
- 15 Carpet Mastic
- 16 2' x 2' Lightly Textured Ceiling Tile
- 17 2' x 4' Fissured Pinhole Ceiling Tiles
- 18 Red Pipe Sealant
- 19 Interior Door Caulk
- 2 12" x 12" Gray w/ White Floor Tile Mastic
- 20 Drywall
- 21 Drywall Compound
- 22 Drywall Tape
- 3 12" x 12" Off-White w/ Gray Specks Floor Tile
- 4 12" x 12" Off-White w/ Gray Specks Floor Tile Mastic
- 5 12" x 12" Gray Marbled Floor Tile
- 6 12" x 12" Gray Marbled Floor Tile Mastic
- 7 12" x 12" Light Gray w/ Dark Gray Specks Floor Tile
- 8 12" x 12" Light Gray w/ Dark Gray Specks Floor Tile Mastic
- 9 12" x 12" Beige Mix Floor Tile

The following areas were deemed to be inaccessible:

- 10 12" x 12" Beige Mix Floor Tile Mastic
- 12 4" Beige Vinyl Baseboard Mastic
- 14 4" White (Painted Brown) Vinyl Baseboard Mastic
- 15 Carpet Mastic
- 2 12" x 12" Gray w/ White Floor Tile Mastic
- 4 12" x 12" Off-White w/ Gray Specks Floor Tile Mastic
- 6 12" x 12" Gray Marbled Floor Tile Mastic
- 8 12" x 12" Light Gray w/ Dark Gray Specks Floor Tile Mastic

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Robert DeBord, IDPH License # 100-08864. The Management Plan was updated by Todd Huffer, IDPH License # 100-09870. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The The Academy for Global Citizenship NEW Building 2025 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School The Academy for Global Citizenship NEW Unit 63011 Building ID 2025

Address 4647 West 47th Street Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
1	12" x 12" Gray w/ White Floor Tile	4,000	SF	Rms. 104-106, Storage by 106, Conference Room A, Rm. 107 and B, Rm. 108, Office B (under carpet), Reception Area by Office B	ASSUMED	MISC	N	DIST	8		Yes	ACBM with the potential for damage	5	MODERATE
10	12" x 12" Beige Mix Floor Tile Mastic	100	SF	East Entrance Vestibule	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
11	4" Beige Vinyl Baseboard	1,200	LF	Throughout Classrooms, Offices, and Hallways	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
12	4" Beige Vinyl Baseboard Mastic	1,200	LF	Throughout Classrooms, Offices, and Hallways	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
13	4" White (Painted Brown) Vinyl Baseboard	200	LF	Multi-Purpose Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
14	4" White (Painted Brown) Vinyl Baseboard Mastic	200	LF	Multi-Purpose Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
15	Carpet Mastic	500	SF	Office's A, B, C	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
16	2' x 2' Lightly Textured Ceiling Tile	5,000	SF	Rms. 101-103, Multi-Purpose Room, Reception Area, and Hallways	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
17	2' x 4' Fissured Pinhole Ceiling Tiles	600	SF	Office's A, B, C & South Hallway	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
18	Red Pipe Sealant	50	LF	Throughout Building Above Drop Ceilings	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
19	Interior Door Caulk	100	LF	All Doors	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
2	12" x 12" Gray w/ White Floor Tile Mastic	4,000	SF	Rms. 104-106, Storage by 106, Conference Room A, Rm. 107 and B, Rm. 108, Office B (under carpet), Reception Area by Office B	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
20	Drywall	120,000	SF	Throughout Building	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW

Chicago Public Schools

School The Academy for Global Citizenship NEW Unit 63011 Building ID 2025

Address 4647 West 47th Street Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
21	Drywall Compound	60,000	LF	Throughout Building	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACM or friable suspect ACM		LOW
22	Drywall Tape	60,000	LF	Throughout Building	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACM or friable suspect ACM		LOW
3	12" x 12" Off-White w/ Gray Specks Floor Tile	5,000	SF	Rms. 101-103, Multi-Purpose Room, Kitchen, and Hallways	ASSUMED	MISC	N	DIST	4		Yes	ACBM with the potential for damage	5	MODERATE
4	12" x 12" Off-White w/ Gray Specks Floor Tile Mastic	5,000	SF	Rms. 101-103, Multi-Purpose Room, Kitchen, and Hallways	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
5	12" x 12" Gray Marbled Floor Tile	350	SF	Multi-Purpose Room Storage	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
6	12" x 12" Gray Marbled Floor Tile Mastic	350	SF	Multi-Purpose Room Storage	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
7	12" x 12" Light Gray w/ Dark Gray Specks Floor Tile	50	SF	Kitchen (Patching under sinks)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
8	12" x 12" Light Gray w/ Dark Gray Specks Floor Tile Mastic	50	SF	Kitchen (Patching under sinks)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
9	12" x 12" Beige Mix Floor Tile	100	SF	East Entrance Vestibule	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School The Academy for Global Citizenship NEW Unit 63011 Building ID 2025
Address 4647 West 47th Street Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

Reinspection Date 3/24/2016
Inspector Name Robert DeBord
100-08864 5/15/2016
Inspector's IDPH License Number / Expiration Date

Inspector's Comments

HA Number:	Inspector Comments:
1	Damage is located in the N. Hallway by women's restroom and Rm. 105
10	
11	
12	
13	
14	
15	
16	
17	
18	
19	
2	
20	
21	
22	
3	Damage located in Rm. 103 entrance and S. Hallway
4	
5	
6	
7	
8	
9	

Chicago Public Schools

School The Academy for Global Citizenship NEW **Unit** 63011 **Building ID** 2025

Address 4647 West 47th Street **Region** 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

Table II

Management Planner's Review

Chicago Public Schools

School The Academy for Global
Citizenship NEW

Unit 63011

Building ID 2025

Address 4647 West 47th Street

Chicago, IL, 60632

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
1	12" x 12" Gray w/ White Floor Tile	4,000	SF	Rms. 104-106, Storage by 106, Conference Room A, Rm. 107 and B, Rm. 108, Office B (under carpet), Reception Area by Office B	Assumed	MISC	No	8	SF	6 ACBM with the potential for damage	Follow O&M Plan
10	12" x 12" Beige Mix Floor Tile Mastic	100	SF	East Entrance Vestibule	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
11	4" Beige Vinyl Baseboard	1,200	LF	Throughout Classrooms, Offices, and Hallways	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
12	4" Beige Vinyl Baseboard Mastic	1,200	LF	Throughout Classrooms, Offices, and Hallways	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
13	4" White (Painted Brown) Vinyl Baseboard	200	LF	Multi-Purpose Room	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
14	4" White (Painted Brown) Vinyl Baseboard Mastic	200	LF	Multi-Purpose Room	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
15	Carpet Mastic	500	SF	Office's A, B, C	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
16	2' x 2' Lightly Textured Ceiling Tile	5,000	SF	Rms. 101-103, Multi-Purpose Room, Reception Area, and Hallways	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
17	2' x 4' Fissured Pinhole Ceiling Tiles	600	SF	Office's A, B, C & South Hallway	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
18	Red Pipe Sealant	50	LF	Throughout Building Above Drop Ceilings	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
19	Interior Door Caulk	100	LF	All Doors	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
2	12" x 12" Gray w/ White Floor Tile Mastic	4,000	SF	Rms. 104-106, Storage by 106, Conference Room A, Rm. 107 and B, Rm. 108, Office B (under carpet), Reception Area by Office B	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
20	Drywall	120,000	SF	Throughout Building	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
21	Drywall Compound	60,000	LF	Throughout Building	Assumed	MISC	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
22	Drywall Tape	60,000	LF	Throughout Building	Assumed	MISC	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
3	12" x 12" Off-White w/ Gray Specks Floor Tile	5,000	SF	Rms. 101-103, Multi-Purpose Room, Kitchen, and Hallways	Assumed	MISC	No	4	SF	6 ACBM with the potential for damage	Follow O&M Plan
4	12" x 12" Off-White w/ Gray Specks Floor Tile Mastic	5,000	SF	Rms. 101-103, Multi-Purpose Room, Kitchen, and Hallways	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
5	12" x 12" Gray Marbled Floor Tile	350	SF	Multi-Purpose Room Storage	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
6	12" x 12" Gray Marbled Floor Tile Mastic	350	SF	Multi-Purpose Room Storage	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School The Academy for Global
Citizenship NEW

Unit 63011

Building ID 2025

Address 4647 West 47th Street

Chicago, IL, 60632

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
7	12" x 12" Light Gray w/ Dark Gray Specks Floor Tile	50	SF	Kitchen (Patching under sinks)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
8	12" x 12" Light Gray w/ Dark Gray Specks Floor Tile Mastic	50	SF	Kitchen (Patching under sinks)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
9	12" x 12" Beige Mix Floor Tile	100	SF	East Entrance Vestibule	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School The Academy for Global
Citizenship NEW

Unit 63011

Building ID 2025

Address 4647 West 47th Street

Chicago, IL, 60632

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

Review Date	4/26/2016
Manager Planner Name	Todd Huffer
100-09870	5/15/2016
Manager IDPH License No/Expiration	

HA Number	Management Comments
1	Damage is located in the N. Hallway by women's restroom and Rm. 105. Replace damaged and continue O&M.
10	
11	
12	
13	
14	
15	
16	
17	
18	
19	
2	
20	
21	
22	
3	Damage located in Rm. 103 entrance and S. Hallway. Replace damaged and continue O&M
4	
5	
6	
7	
8	
9	

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **63011** BUIDLING ID: **2025**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **The Academy for Global Citizenship** INSPECTION DATE: **3/24/2016**
NEW
ADDRESS: **4647 West 47th Street** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **1**
MATERIAL DESCRIPTION: **12" x 12" Gray w/ White Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Physical Damage**
DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Rms. 104-106, Storage by 106, Conference Room A, Rm. 107 and B, Rm. 108, Office B (under carpet), Reception Area by Office B**
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS: **Damage is located in the N. Hallway by women's restroom and Rm. 105**

Inspector's Signature: _____ Date: 03/24/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **63011** BUIDLING ID: **2025**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **The Academy for Global Citizenship NEW** REVIEW DATE: **4/26/2016**
ADDRESS: **4647 West 47th Street** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **1**
MATERIAL DESCRIPTION: **12" x 12" Gray w/ White Floor Tile**
MATERIAL LOCATION: **Rms. 104-106, Storage by 106, Conference Room A, Rm. 107 and B, Rm. 108, Office B (under carpet), Reception Area by Office B**
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **8** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Damage is located in the N. Hallway by women's restroom and Rm. 105. Replace damaged and continue O&M.

Management Planner's Signature: _____



Date: **04/26/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **63011** BUIDLING ID: **2025**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **The Academy for Global Citizenship** INSPECTION DATE: **3/24/2016**
NEW
ADDRESS: **4647 West 47th Street** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10**
MATERIAL DESCRIPTION: **12" x 12" Beige Mix Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **East Entrance Vestibule**

MATERIAL QUANTITY: **100**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 03/24/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **63011** BUILDING ID: **2025**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **The Academy for
Global Citizenship
NEW** REVIEW DATE: **4/26/2016**
ADDRESS: **4647 West 47th Street** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **10**
MATERIAL DESCRIPTION: **12" x 12" Beige Mix Floor Tile Mastic**
MATERIAL LOCATION: **East Entrance Vestibule**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/26/2016**

Chicago Public Schools

Carnow, Conibear and Associates 2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **63011** BUIDLING ID: **2025**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **The Academy for Global Citizenship** INSPECTION DATE: **3/24/2016**
NEW
ADDRESS: **4647 West 47th Street** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11**
MATERIAL DESCRIPTION: **4" Beige Vinyl Baseboard**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Throughout Classrooms, Offices, and Hallways**

MATERIAL QUANTITY: **1200** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 03/24/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **63011** BUILDING ID: **2025**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **The Academy for
Global Citizenship
NEW** REVIEW DATE: **4/26/2016**
ADDRESS: **4647 West 47th Street** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **11**
MATERIAL DESCRIPTION: **4" Beige Vinyl Baseboard**
MATERIAL LOCATION: **Throughout Classrooms, Offices, and Hallways**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/26/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **63011** BUIDLING ID: **2025**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **The Academy for Global Citizenship** INSPECTION DATE: **3/24/2016**
NEW
ADDRESS: **4647 West 47th Street** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12**
MATERIAL DESCRIPTION: **4" Beige Vinyl Baseboard Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Throughout Classrooms, Offices, and Hallways**

MATERIAL QUANTITY: **1200** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 03/24/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **63011** BUILDING ID: **2025**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **The Academy for
Global Citizenship
NEW** REVIEW DATE: **4/26/2016**
ADDRESS: **4647 West 47th Street** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **12**
MATERIAL DESCRIPTION: **4" Beige Vinyl Baseboard Mastic**
MATERIAL LOCATION: **Throughout Classrooms, Offices, and Hallways**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/26/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **63011** BUIDLING ID: **2025**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **The Academy for Global Citizenship** INSPECTION DATE: **3/24/2016**
NEW
ADDRESS: **4647 West 47th Street** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13**
MATERIAL DESCRIPTION: **4" White (Painted Brown) Vinyl Baseboard**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Multi-Purpose Room**

MATERIAL QUANTITY: **200**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____

Date: 03/24/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **63011** BUILDING ID: **2025**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **The Academy for Global Citizenship NEW** REVIEW DATE: **4/26/2016**
ADDRESS: **4647 West 47th Street** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **13**
MATERIAL DESCRIPTION: **4" White (Painted Brown) Vinyl Baseboard**
MATERIAL LOCATION: **Multi-Purpose Room**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/26/2016**

Chicago Public Schools

Carnow, Conibear and Associates 2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **63011** BUIDLING ID: **2025**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **The Academy for Global Citizenship
NEW** INSPECTION DATE: **3/24/2016**
ADDRESS: **4647 West 47th Street** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14**
MATERIAL DESCRIPTION: **4" White (Painted Brown) Vinyl Baseboard Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Multi-Purpose Room**

MATERIAL QUANTITY: **200**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____

Date: 03/24/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **63011** BUILDING ID: **2025**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **The Academy for Global Citizenship NEW** REVIEW DATE: **4/26/2016**
ADDRESS: **4647 West 47th Street** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **14**
MATERIAL DESCRIPTION: **4" White (Painted Brown) Vinyl Baseboard Mastic**
MATERIAL LOCATION: **Multi-Purpose Room**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/26/2016**

Chicago Public Schools

Carnow, Conibear and Associates 2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **63011** BUIDLING ID: **2025**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **The Academy for Global Citizenship
NEW** INSPECTION DATE: **3/24/2016**
ADDRESS: **4647 West 47th Street** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15**
MATERIAL DESCRIPTION: **Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Office's A, B, C**

MATERIAL QUANTITY: **500**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 03/24/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **63011** BUILDING ID: **2025**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **The Academy for
Global Citizenship
NEW** REVIEW DATE: **4/26/2016**
ADDRESS: **4647 West 47th Street** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **15**
MATERIAL DESCRIPTION: **Carpet Mastic**
MATERIAL LOCATION: **Office's A, B, C**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/26/2016**

Chicago Public Schools

Carnow, Conibear and Associates 2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **63011** BUIDLING ID: **2025**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **The Academy for Global Citizenship** INSPECTION DATE: **3/24/2016**
NEW
ADDRESS: **4647 West 47th Street** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16**
MATERIAL DESCRIPTION: **2' x 2' Lightly Textured Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rms. 101-103, Multi-Purpose Room, Reception Area, and Hallways**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 03/24/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **63011** BUILDING ID: **2025**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **The Academy for Global Citizenship NEW** REVIEW DATE: **4/26/2016**
ADDRESS: **4647 West 47th Street** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **16**
MATERIAL DESCRIPTION: **2' x 2' Lightly Textured Ceiling Tile**
MATERIAL LOCATION: **Rms. 101-103, Multi-Purpose Room, Reception Area, and Hallways**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/26/2016**

Chicago Public Schools

Carnow, Conibear and Associates 2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **63011** BUIDLING ID: **2025**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **The Academy for Global Citizenship** INSPECTION DATE: **3/24/2016**
NEW
ADDRESS: **4647 West 47th Street** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17**
MATERIAL DESCRIPTION: **2' x 4' Fissured Pinhole Ceiling Tiles**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Office's A, B, C & South Hallway**

MATERIAL QUANTITY: **600**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 03/24/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **63011** BUIDLING ID: **2025**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **The Academy for
Global Citizenship
NEW** REVIEW DATE: **4/26/2016**
ADDRESS: **4647 West 47th Street** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **17**
MATERIAL DESCRIPTION: **2' x 4' Fissured Pinhole Ceiling Tiles**
MATERIAL LOCATION: **Office's A, B, C & South Hallway**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/26/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **63011** BUIDLING ID: **2025**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **The Academy for Global Citizenship** INSPECTION DATE: **3/24/2016**
NEW
ADDRESS: **4647 West 47th Street** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18**
MATERIAL DESCRIPTION: **Red Pipe Sealant**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Throughout Building Above Drop Ceilings**

MATERIAL QUANTITY: **50** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 03/24/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **63011** BUILDING ID: **2025**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **The Academy for Global Citizenship NEW** REVIEW DATE: **4/26/2016**
ADDRESS: **4647 West 47th Street** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **18**
MATERIAL DESCRIPTION: **Red Pipe Sealant**
MATERIAL LOCATION: **Throughout Building Above Drop Ceilings**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/26/2016**

Chicago Public Schools

Carnow, Conibear and Associates 2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **63011** BUIDLING ID: **2025**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **The Academy for Global Citizenship** INSPECTION DATE: **3/24/2016**
NEW
ADDRESS: **4647 West 47th Street** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19**
MATERIAL DESCRIPTION: **Interior Door Caulk**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **All Doors**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 03/24/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **63011** BUILDING ID: **2025**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **The Academy for Global Citizenship NEW** REVIEW DATE: **4/26/2016**
ADDRESS: **4647 West 47th Street** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **19**
MATERIAL DESCRIPTION: **Interior Door Caulk**
MATERIAL LOCATION: **All Doors**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/26/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **63011** BUIDLING ID: **2025**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **The Academy for Global Citizenship** INSPECTION DATE: **3/24/2016**
NEW
ADDRESS: **4647 West 47th Street** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **2**
MATERIAL DESCRIPTION: **12" x 12" Gray w/ White Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rms. 104-106, Storage by 106, Conference Room A, Rm. 107 and B, Rm. 108, Office B (under carpet), Reception Area by Office B**

MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/24/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **63011** BUIDLING ID: **2025**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **The Academy for
Global Citizenship
NEW** REVIEW DATE: **4/26/2016**
ADDRESS: **4647 West 47th Street** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **2**
MATERIAL DESCRIPTION: **12" x 12" Gray w/ White Floor Tile Mastic**
MATERIAL LOCATION: **Rms. 104-106, Storage by 106, Conference Room A, Rm. 107 and B, Rm. 108, Office B (under
carpet), Reception Area by Office B**
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/26/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **63011** BUIDLING ID: **2025**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **The Academy for Global Citizenship** INSPECTION DATE: **3/24/2016**
NEW
ADDRESS: **4647 West 47th Street** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**
MATERIAL DESCRIPTION: **Drywall**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY: **120000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 03/24/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **63011** BUILDING ID: **2025**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **The Academy for Global Citizenship NEW** REVIEW DATE: **4/26/2016**
ADDRESS: **4647 West 47th Street** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **20**
MATERIAL DESCRIPTION: **Drywall**
MATERIAL LOCATION: **Throughout Building**
MATERIAL QUANTITY: **120000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/26/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **63011** BUIDLING ID: **2025**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **The Academy for Global Citizenship** INSPECTION DATE: **3/24/2016**
NEW
ADDRESS: **4647 West 47th Street** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21**
MATERIAL DESCRIPTION: **Drywall Compound**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY: **60000**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____

Date: 03/24/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **63011** BUILDING ID: **2025**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **The Academy for
Global Citizenship
NEW** REVIEW DATE: **4/26/2016**
ADDRESS: **4647 West 47th Street** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **21**
MATERIAL DESCRIPTION: **Drywall Compound**
MATERIAL LOCATION: **Throughout Building**
MATERIAL QUANTITY: **60000** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/26/2016**

Chicago Public Schools

Carnow, Conibear and Associates 2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **63011** BUIDLING ID: **2025**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **The Academy for Global Citizenship** INSPECTION DATE: **3/24/2016**
NEW
ADDRESS: **4647 West 47th Street** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22**
MATERIAL DESCRIPTION: **Drywall Tape**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY: **60000**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____

Date: 03/24/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **63011** BUILDING ID: **2025**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **The Academy for Global Citizenship NEW** REVIEW DATE: **4/26/2016**
ADDRESS: **4647 West 47th Street** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **22**
MATERIAL DESCRIPTION: **Drywall Tape**
MATERIAL LOCATION: **Throughout Building**
MATERIAL QUANTITY: **60000** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/26/2016**

Chicago Public Schools

Carnow, Conibear and Associates 2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **63011** BUIDLING ID: **2025**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **The Academy for Global Citizenship
NEW** INSPECTION DATE: **3/24/2016**
ADDRESS: **4647 West 47th Street** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **3**
MATERIAL DESCRIPTION: **12" x 12" Off-White w/ Gray Specks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Physical Damage**
DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Rms. 101-103, Multi-Purpose Room, Kitchen, and Hallways**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS: **Damage located in Rm. 103 entrance and S. Hallway**

Inspector's Signature: _____ Date: 03/24/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **63011** BUILDING ID: **2025**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **The Academy for Global Citizenship NEW** REVIEW DATE: **4/26/2016**
ADDRESS: **4647 West 47th Street** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **3**
MATERIAL DESCRIPTION: **12" x 12" Off-White w/ Gray Specks Floor Tile**
MATERIAL LOCATION: **Rms. 101-103, Multi-Purpose Room, Kitchen, and Hallways**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **4** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Damage located in Rm. 103 entrance and S. Hallway. Replace damaged and continue O&M

Management Planner's Signature: _____



Date: **04/26/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **63011** BUIDLING ID: **2025**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **The Academy for Global Citizenship** INSPECTION DATE: **3/24/2016**
NEW
ADDRESS: **4647 West 47th Street** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **4**
MATERIAL DESCRIPTION: **12" x 12" Off-White w/ Gray Specks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rms. 101-103, Multi-Purpose Room, Kitchen, and Hallways**

MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 03/24/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **63011** BUILDING ID: **2025**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **The Academy for Global Citizenship NEW** REVIEW DATE: **4/26/2016**
ADDRESS: **4647 West 47th Street** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **4**
MATERIAL DESCRIPTION: **12" x 12" Off-White w/ Gray Specks Floor Tile Mastic**
MATERIAL LOCATION: **Rms. 101-103, Multi-Purpose Room, Kitchen, and Hallways**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/26/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **63011** BUIDLING ID: **2025**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **The Academy for Global Citizenship** INSPECTION DATE: **3/24/2016**
NEW
ADDRESS: **4647 West 47th Street** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **5**
MATERIAL DESCRIPTION: **12" x 12" Gray Marbled Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Multi-Purpose Room Storage**

MATERIAL QUANTITY: **350**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 03/24/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **63011** BUILDING ID: **2025**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **The Academy for Global Citizenship NEW** REVIEW DATE: **4/26/2016**
ADDRESS: **4647 West 47th Street** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **5**
MATERIAL DESCRIPTION: **12" x 12" Gray Marbled Floor Tile**
MATERIAL LOCATION: **Multi-Purpose Room Storage**
MATERIAL QUANTITY: **350** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/26/2016**

Chicago Public Schools

Carnow, Conibear and Associates 2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **63011** BUIDLING ID: **2025**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **The Academy for Global Citizenship
NEW** INSPECTION DATE: **3/24/2016**
ADDRESS: **4647 West 47th Street** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **6**
MATERIAL DESCRIPTION: **12" x 12" Gray Marbled Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Multi-Purpose Room Storage**

MATERIAL QUANTITY: **350**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 03/24/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **63011** BUILDING ID: **2025**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **The Academy for Global Citizenship NEW** REVIEW DATE: **4/26/2016**
ADDRESS: **4647 West 47th Street** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **6**
MATERIAL DESCRIPTION: **12" x 12" Gray Marbled Floor Tile Mastic**
MATERIAL LOCATION: **Multi-Purpose Room Storage**
MATERIAL QUANTITY: **350** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/26/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **63011** BUIDLING ID: **2025**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **The Academy for Global Citizenship** INSPECTION DATE: **3/24/2016**
NEW
ADDRESS: **4647 West 47th Street** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **7**
MATERIAL DESCRIPTION: **12" x 12" Light Gray w/ Dark Gray Specks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Kitchen (Patching under sinks)**

MATERIAL QUANTITY: **50**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 03/24/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **63011** BUILDING ID: **2025**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **The Academy for Global Citizenship NEW** REVIEW DATE: **4/26/2016**
ADDRESS: **4647 West 47th Street** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **7**
MATERIAL DESCRIPTION: **12" x 12" Light Gray w/ Dark Gray Specks Floor Tile**
MATERIAL LOCATION: **Kitchen (Patching under sinks)**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/26/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **63011** BUIDLING ID: **2025**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **The Academy for Global Citizenship** INSPECTION DATE: **3/24/2016**
NEW
ADDRESS: **4647 West 47th Street** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **8**
MATERIAL DESCRIPTION: **12" x 12" Light Gray w/ Dark Gray Specks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Kitchen (Patching under sinks)**

MATERIAL QUANTITY: **50**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 03/24/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **63011** BUIDLING ID: **2025**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **The Academy for
Global Citizenship
NEW** REVIEW DATE: **4/26/2016**
ADDRESS: **4647 West 47th Street** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **8**
MATERIAL DESCRIPTION: **12" x 12" Light Gray w/ Dark Gray Specks Floor Tile Mastic**
MATERIAL LOCATION: **Kitchen (Patching under sinks)**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/26/2016**

Chicago Public Schools

Carnow, Conibear and Associates 2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **63011** BUILDING ID: **2025**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **The Academy for Global Citizenship
NEW** INSPECTION DATE: **3/24/2016**
ADDRESS: **4647 West 47th Street** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **9**
MATERIAL DESCRIPTION: **12" x 12" Beige Mix Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **East Entrance Vestibule**

MATERIAL QUANTITY: **100**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 03/24/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **63011** BUILDING ID: **2025**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **The Academy for Global Citizenship NEW** REVIEW DATE: **4/26/2016**
ADDRESS: **4647 West 47th Street** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **9**
MATERIAL DESCRIPTION: **12" x 12" Beige Mix Floor Tile**
MATERIAL LOCATION: **East Entrance Vestibule**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **04/26/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

APPENDIX B

Inspector and Management Planner Licenses

2015



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Robert DeBord

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Course Date: 12/2/2015

Exam Date: 12/2/2015

Expiration Date: 12/2/2016

Certificate Number: BIR1512024160


Kathy DeSalvo, Director

Robert De Bord
Illinois Licensed Asbestos Inspector, Project Manager, and
Air Sampling Professional



**ASBESTOS
PROFESSIONAL
LICENSE**

ID NUMBER ISSUED EXPIRES
100 - 08864 **5/27/2015** **05/15/2016**

ROBERT W DE BORD
301 MIAMI ST
PARK FOREST, IL 60466
Environmental Health



ENDORSEMENTS	TC EXPIRES
INSPECTOR	2/13/2016
PROJECT MANAGER AIR SAMPLING PROFESSIONAL	2/12/2016

Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois
Department of Public Health
This license is valid only when accompanied by a valid
training course certificate.

**CARNOW
CONIBEAR**

2015



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Todd Huffer

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 12/2/2015

Exam Date: 12/2/2015

Expiration Date: 12/2/2016

Certificate Number: BIR1512024161



Kathy DeSalvo, Director

Todd Huffer

Illinois Licensed Asbestos Inspector, Management Planner,
Project Manager, and Air Sampling Professional



ASBESTOS PROFESSIONAL LICENSE

ID NUMBER
100 - 09870

ISSUED
3/16/2015

EXPIRES
05/15/2016

TODD T HUFFER
315 HATLEN COURT
MT. PROSPECT, IL 60056

Environmental Health



ENDORSEMENTS

TC EXPIRES

INSPECTOR

12/2/2015

MANAGEMENT PLANNER

2/20/2016

PROJECT MANAGER

12/11/2015

AIR SAMPLING PROFESSIONAL

Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois
Department of Public Health

This license is valid only when accompanied by a valid
training course certificate.

**CARNOW
CONIBEAR**

2016



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Todd Huffer

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 1/27/2016

Exam Date: 1/27/2016

Expiration Date: 1/27/2017

Certificate Number: MPR1601270318

Kathy DeSalvo, Director

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL		
	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE		
	Loc	Localized
	Dist	Distributed