

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH  
AHERA THREE YEAR REINSPECTION  
ASBESTOS ABATEMENT PROGRAM  
SCHOOL INFORMATION FORM**

**SECTION I**

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299  
SCHOOL ID NUMBER: 14-016-2990-2051  
SCHOOL NAME: Addams School  
ADDRESS OF SCHOOL: 10810 S. Avenue H  
CITY: Chicago, IL, 60617

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **5/6/2016**

**If the address on this form is different than the address of the building, submit a written explanation.**

---

**SECTION II** *(Please type or print)*

**PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:**

DATE REINSPECTION COMPLETED: 10/1/2019 ENROLLMENT 689  
IDPH INSPECTOR LICENSE NUMBER: 100-09106  
IDPH LICENSED INSPECTOR NAME(Please Print): Michael Hasier  
IDPH MP LICENSE NUMBER: 100-00746  
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Amy Williams

DESIGNATED PERSON (Please Print): Robert Christlieb PHONE: (773) 553-3197



10/1/2019

*Signature of Designated Person*

*Date*

**SECTION III**

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: \_\_\_\_\_

School has been closed. Date closed: \_\_\_\_\_

School building has been demolished. Date: \_\_\_\_\_

School building is asbestos free since last reinspection: \_\_\_\_\_

**Please explain in writing why the school building is now asbestos free and include the supporting documentation.**

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

**Explain in writing if the address of the building is different than the address on this form:**

---

---

---

**THREE-YEAR REINSPECTION**

**CHICAGO SCHOOL DIST 299**

**Addams School**

10810 S. Avenue H  
Chicago, IL, 60617

Unit: 22021  
Building ID: 2020

IDPH ID Number: 14-016-2990-2051

**REPORT DATE:**

Tuesday, October 01, 2019

**Prepared for:**

**Chicago Public Schools  
42 West Madison Street  
Chicago, IL 60602**

**Prepared by:**

**TEM Environmental, Inc.**

174 N. Brandon Drive

Glendale Heights, IL, 60139

Phone 630-790-0880

Fax 630-790-0882

**DO NOT REMOVE FROM SCHOOL  
REQUIRED BY FEDERAL LAW**

October 3, 2019

Mr. Glen E. Garner  
Asbestos Program  
Illinois Department of Public Health  
525 West Jefferson Street  
Springfield, Illinois 62761

Re: Chicago Public Schools - 2019 Three-Year Reinspections

Dear Mr. Glen:

TEM Environmental, Inc. , Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 5, 6 Elementary Schools. Please update your records with the following information.

School District: 299              Unit: 22021              Region: 06              IDPH ID:14-016-2990-2051

School: Addams School              Building ID: 2020

Address: 10810 S. Avenue H

Chicago, IL, 60617

Building Contact:

Contact Phone:

Current Building Owners: Chicago Public Schools

Review Date: 10/30/2019

Inspector: Michael Hasier

Inspector IDPH License: 100-09106

Management Planner: Amy Williams

Management Planner IDPH License: 100-00746

If you have any questions or comments, please contact us at 630-790-0880

Sincerely,  
TEM Environmental, Inc.

Amy Williams  
100-00746

## **Environmental Notification to Occupants**

To: Faculty, Staff and Parents  
From: Chicago Public Schools  
Date: October 03, 2019

RE: Addams School, Unit 22021  
10810 S. Avenue H  
Chicago, IL, 60617

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2019 asbestos three year re-inspection has been completed at Addams School, following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at Addams School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Robert Christlieb, the designated Local Education Authority's Designated Person at (773) 553-3197 .

## **Table of Contents**

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

### **APPENDICES:**

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

## SCHOOL AND INSPECTION INFORMATION

### 1. School Information

School: Addams School Unit: 22021 Region: 06  
Address: 10810 S. Avenue H Chicago, IL, 60617  
IDPH ID: 14-016-2990-2051 Building ID: 2020  
Contact: Phone:

### 2. Description of Facility

Original Construction: 1994 Additional Construction: 1948  
Total Square Footage: 3959 No of Floors: 1  
Current Occupancy: 689

### 3. LEA Designated Person

Contact: Robert Christlieb Phone: (773) 553-3197  
Address: 42 West Madison Street  
Chicago, IL 60602

### 4. Managing Environmental Consultant

MEC: TEM Environmental, Inc.  
Contact: Steven Geneser  
Address 174 N. Brandon Drive  
Glendale Heights, IL, 60139  
Phone: 630-790-0880 Fax: 630-790-0882

### 5. Inspector

Inspector Name: Michael Hasier

Inspector IDPH license # 100-09106

Signature:  
Date: 10/3/2019

### 6. Management Planner

Management Planner Name: Amy Williams

Management Planner IDPH license # 100-00746

Signature:  
Date: 10/30/2019

### 7. Review Date:10/30/2019

### 8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature:



Date: 10/1/2019

Name: Robert Christlieb

## II. EXECUTIVE SUMMARY

TEM Environmental, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Addams School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.85 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas(HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 2020:

02A	12x12 Beige Floor Tile
04A	12x12 Beige Floor Tile Mastic
09	2'x2' Smooth White Ceiling Tile
10	2'x2' White Ceiling Tile
11	2'x4' White Ceiling Tile
12	Solid Ceiling Panels
13	2'x2' White Ceiling Tile
14	2'x2' White Ceiling Tile
A	Aircell Pipe Insulation

- C Mudded Fittings/Elbows on Aircell Pipe Runs
- D Aircell Duct Wrap
- F Duct Manifold



B. The following new homogenous areas have been identified for Building 2020:

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

02	12x12 Off-White Floor Tile
02A	12x12 Beige Floor Tile
03	Blue Carpet/Tan Mastic (Not Observed)
04	12x12 Off-White Floor Tile Mastic
04A	12x12 Beige Floor Tile Mastic
05	Beige Baseboard
05A	Gray Baseboard
05B	Beige Baseboard
06	Beige Baseboard Mastic
06A	Gray Baseboard Mastic
06C	Beige Baseboard Mastic
07	Tan Linoleum
07A	Brown Linoleum (Not Observed)
07B	12x12 Tan Floor Tile w/Streaks
07C	12x12 White Floor w/Black Specks Floor Tile
07D	12x12 Beige Floor Tile w/Streaks
08	Tan Linoleum Mastic
08A	Brown Linoleum Mastic (Not Observed)
08C	12x12 White Floor w/Black Specks Floor Tile Mastic
08D	12x12 Beige Floor Tile w/Streaks Mastic
09	2'x2' Smooth White Ceiling Tile
10	2'x2' White Ceiling Tile
11	2'x4' White Ceiling Tile
12	Solid Ceiling Panels
13	2'x2' White Ceiling Tile
14	2'x2' White Ceiling Tile
15A	Beige Baseboard
15B	Beige Baseboard Mastic
16A	12x12 White Speckled Floor Tile
16B	12x12 White Speckled Floor Tile Mastic
17	Blue Linoleum
18	Pink Linoleum
19	Plaster
20	12x12 White w/Blue Specks Vinyl Floor Tile
21	12x12 White w/Blue Specks Vinyl Floor Tile Mastic
8B	12x12 Tan Floor Tile w/Streaks Mastic
F	Duct Manifold

The following areas were deemed to be inaccessible:

03	Blue Carpet/Tan Mastic (Not Observed)
04	12x12 Off-White Floor Tile Mastic
04A	12x12 Beige Floor Tile Mastic
06	Beige Baseboard Mastic
06A	Gray Baseboard Mastic
06C	Beige Baseboard Mastic
08	Tan Linoleum Mastic
08C	12x12 White Floor w/Black Specks Floor Tile Mastic
08D	12x12 Beige Floor Tile w/Streaks Mastic
15B	Beige Baseboard Mastic
16B	12x12 White Speckled Floor Tile Mastic
21	12x12 White w/Blue Specks Vinyl Floor Tile Mastic
8B	12x12 Tan Floor Tile w/Streaks Mastic

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Michael Hasier, IDPH License # 100-09106. The Management Plan was updated by Amy Williams, IDPH License # 100-00746. Inspector and Management Planner Licenses are included in Appendix B.

### **III. METHODOLOGY**

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

### **IV. ABATEMENT HISTORY**

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

### **V. REASSESSMENTS AND RECOMMENDATIONS**

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

### **VI. CONCLUSIONS**

The Addams School Building 2020 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. Atimely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

**Table I**  
**Inspector's Reinspection Findings**

---

# Chicago Public Schools

School Addams School Unit 22021 Building ID 2020

Address 10810 S. Avenue H Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
02	12x12 Off-White Floor Tile	1,700	SF	1st Floor Corridor and Teachers' Lounge; Office (Wood Tile over VFT)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
02A	12x12 Beige Floor Tile	2,450	SF	2nd Floor Corridor, Room 203 (27 x 23), Room 202, Room 200 (33x6)	ASSUMED	MISC	N	DIST	120		Yes	ACBM with potential for significant damage	5	MODERATE
03	Blue Carpet/Tan Mastic (Not Observed)	2,000	SF	Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
04	12x12 Off-White Floor Tile Mastic	1,500	SF	1st Floor Corridor and Teachers' Lounge	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
04A	12x12 Beige Floor Tile Mastic	1,650	SF	2nd Floor Corridor	ASSUMED	MISC	N	NONE	120		Yes	ACBM with potential for significant damage		LOW
05	Beige Baseboard	900	LF	Kitchen, Cafeteria, and 1st Floor Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
05A	Gray Baseboard	1,210	LF	1996 Annex-Corridor and All Classrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
05B	Beige Baseboard	325	LF	Rooms 120-123	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
06	Beige Baseboard Mastic	900	LF	Kitchen, Cafeteria, and 1st Floor Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
06A	Gray Baseboard Mastic	1,210	LF	1996 Annex-Corridor and All Classrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
06C	Beige Baseboard Mastic	325	LF	Mobile Unit- Rooms 120-123	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
07	Tan Linoleum	1,600	SF	Kitchen	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
07A	Brown Linoleum (Not Observed)			Cafeteria	ASSUMED	MISC								
07B	12x12 Tan Floor Tile w/Streaks	580	SF	1995 Addition-Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
07C	12x12 White Floor w/Black Specks Floor Tile	2,490	SF	Throughout 1996 Annex- All Classrooms and Corridors	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
07D	12x12 Beige Floor Tile w/Streaks	5,000	SF	Mobile Unit Rooms 120-123	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
08	Tan Linoleum Mastic	1,600	SF	Kitchen	ASSUMED	MISC	N	NONE	0		No	ACBM with the		LOW

# Chicago Public Schools

School Addams School Unit 22021 Building ID 2020

Address 10810 S. Avenue H Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
												potential for damage		
08A	Brown Linoleum Mastic (Not Observed)			Cafeteria	ASSUMED	MISC								
08C	12x12 White Floor w/Black Specks Floor Tile Mastic	2,490	SF	Throughout 1996 Annex. All Classrooms and Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
08D	12x12 Beige Floor Tile w/Streaks Mastic	5,000	SF	Mobile Unit- Rooms 120-123	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
09	2'x2' Smooth White Ceiling Tile	770	SF	1995 Addition-Kitchen	ASSUMED	MISC	Y	NONE	0		Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
10	2'x2' White Ceiling Tile	2,100	SF	1995 Addition-Cafeteria	ASSUMED	MISC	Y	NONE	0		Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
11	2'x4' White Ceiling Tile	2,340	SF	1996 Annex-Corridor and All Classrooms (Except 115)	ASSUMED	MISC	Y	NONE	0		Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
12	Solid Ceiling Panels	2,500	SF	North Mobile Unit - Rooms 120 & 121	ASSUMED	MISC	Y	NONE	0		Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
13	2'x2' White Ceiling Tile	2,500	SF	South Mobile Unit-Rooms 122 & 123	ASSUMED	MISC	Y	NONE	0		Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
14	2'x2' White Ceiling Tile	5,000	SF	East Mobile Unit	ASSUMED	MISC	Y	NONE	0		Yes	Any remaining friable ACBM or friable suspect ACBM		MODERATE
15A	Beige Baseboard	3,000	LF	East Mobile Unit	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
15B	Beige Baseboard Mastic	3,000	LF	East Mobile Unit	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
16A	12x12 White Speckled Floor Tile	5,000	SF	East Mobile Unit	ASSUMED	MISC	N	DIST	50		No	ACBM with the potential for damage	5	LOW
16B	12x12 White Speckled Floor Tile Mastic	5,000	SF	East Mobile Unit	ASSUMED	MISC	N	NONE	50		No	ACBM with the potential for damage		LOW
17	Blue Linoleum	400	SF	East Mobile Unit-Boys' Restroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
18	Pink Linoleum	400	SF	East Mobile Unit-Girls' Restroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
19	Plaster	60,000	SF	Main Building	ASSUMED	SURFACE	N	NONE	0		No	ACBM with the potential for damage		LOW
20	12x12 White w/Blue Specks Vinyl Floor Tile	2,400	SF	Cafeteria	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
21	12x12 White w/Blue Specks Vinyl Floor	2,400	SF	Cafeteria	ASSUMED	MISC	N	NONE	0		No	ACBM with the		LOW

# Chicago Public Schools

School Addams School Unit 22021 Building ID 2020

Address 10810 S. Avenue H Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
	Tile Mastic											potential for damage		
8B	12x12 Tan Floor Tile w/Streaks Mastic	580	SF	1995 Addition-Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
A	Aircell Pipe Insulation	840	SF	Basement, Pipe Chase/Air Tunnel, Crawlspace	CHR	TSI	Y	NONE	0		Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
B	Cardboard Pipe Wrap	800	LF	Basement	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
C	Mudded Fittings/Elbows on Aircell Pipe Runs	878	LF	Basement Pipe Chases, Air Tunnel, Crawlspace	CHR	TSI	Y	NONE	0		Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
D	Aircell Duct Wrap	300	SF	Basement and Unexcavated Area, Crawlspace	CHR	TSI	Y	NONE	0		Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
E	Mag Block Pipe Insulation ABATED			Boiler Room	ABATED	TSI								
F	Duct Manifold	3	LF	Fan Room	ASSUMED	TSI	Y	NONE	0		Yes	Any remaining friable ACBM or friable suspect ACBM		LOW



# Chicago Public Schools

School Addams School Unit 22021 Building ID 2020

Address 10810 S. Avenue H Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

Reinspection Date <b>10/3/2019</b>
Inspector Name <b>Michael Hasier</b>
<b>100-09106</b> <b>5/15/2020</b>
Inspector's IDPH License Number / Expiration Date

### Inspector's Comments

HA Number:	Inspector Comments:
02	
02A	Room 202 & 203
03	
04	
04A	Room 202 & 203
05	
05A	
05B	
06	
06A	
06C	
07	
07A	
07B	
07C	
07D	
08	
08A	
08C	
08D	
09	
10	
11	

# Chicago Public Schools

School Addams School Unit 22021 Building ID 2020

Address 10810 S. Avenue H Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
12	
13	
14	
15A	
15B	
16A	Damage Throughout
16B	Damage Throughout
17	
18	
19	
20	
21	
8B	
A	
B	
C	
D	
E	
F	

**Table II**

**Management Planner's Review**

---

# Chicago Public Schools

**School** Addams School  
**Address** 10810 S. Avenue H

**Unit** 22021  
Chicago, IL, 60617

**Building ID** 2020  
**Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

### Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
02	12x12 Off-White Floor Tile	1,700	SF	1st Floor Corridor and Teachers' Lounge; Office (Wood Tile over VFT)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
02A	12x12 Beige Floor Tile	2,450	SF	2nd Floor Corridor, Room 203 (27 x 23), Room 202, Room 200 (33x6)	Assumed	MISC	No	120	SF	5 ACBM with potential for significant damage	Follow O&M Plan
03	Blue Carpet/Tan Mastic (Not Observed)	2,000	SF	Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
04	12x12 Off-White Floor Tile Mastic	1,500	SF	1st Floor Corridor and Teachers' Lounge	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
04A	12x12 Beige Floor Tile Mastic	1,650	SF	2nd Floor Corridor	Assumed	MISC	No	120	SF	5 ACBM with potential for significant damage	Follow O&M Plan
05	Beige Baseboard	900	LF	Kitchen, Cafeteria, and 1st Floor Corridor	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
05A	Gray Baseboard	1,210	LF	1996 Annex- Corridor and All Classrooms	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
05B	Beige Baseboard	325	LF	Rooms 120-123	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
06	Beige Baseboard Mastic	900	LF	Kitchen, Cafeteria, and 1st Floor Corridor	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
06A	Gray Baseboard Mastic	1,210	LF	1996 Annex- Corridor and All Classrooms	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
06C	Beige Baseboard Mastic	325	LF	Mobile Unit- Rooms 120-123	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
07	Tan Linoleum	1,600	SF	Kitchen	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
07A	Brown Linoleum (Not Observed)			Cafeteria	Assumed	MISC					
07B	12x12 Tan Floor Tile w/Streaks	580	SF	1995 Addition- Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
07C	12x12 White Floor w/Black Specks Floor Tile	2,490	SF	Throughout 1996 Annex- All Classrooms and Corridors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
07D	12x12 Beige Floor Tile w/Streaks	5,000	SF	Mobile Unit Rooms 120-123	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
08	Tan Linoleum Mastic	1,600	SF	Kitchen	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
08A	Brown Linoleum Mastic (Not Observed)			Cafeteria	Assumed	MISC					
08C	12x12 White Floor w/Black Specks Floor Tile Mastic	2,490	SF	Throughout 1996 Annex, All Classrooms and Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
08D	12x12 Beige Floor Tile w/Streaks Mastic	5,000	SF	Mobile Unit- Rooms 120-123	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
09	2'x2' Smooth White Ceiling Tile	770	SF	1995 Addition- Kitchen	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
10	2'x2' White Ceiling Tile	2,100	SF	1995 Addition- Cafeteria	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan

# Chicago Public Schools

**School** Addams School  
**Address** 10810 S. Avenue H

**Unit** 22021  
Chicago, IL, 60617

**Building ID** 2020  
**Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

### Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
11	2'x4' White Ceiling Tile	2,340	SF	1996 Annex- Corridor and All Classrooms (Except 115)	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
12	Solid Ceiling Panels	2,500	SF	North Mobile Unit - Rooms 120 & 121	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
13	2'x2' White Ceiling Tile	2,500	SF	South Mobile Unit- Rooms 122 & 123	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
14	2'x2' White Ceiling Tile	5,000	SF	East Mobile Unit	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
15A	Beige Baseboard	3,000	LF	East Mobile Unit	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
15B	Beige Baseboard Mastic	3,000	LF	East Mobile Unit	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
16A	12x12 White Speckled Floor Tile	5,000	SF	East Mobile Unit	Assumed	MISC	No	50	SF	6 ACBM with the potential for damage	Follow O&M Plan
16B	12x12 White Speckled Floor Tile Mastic	5,000	SF	East Mobile Unit	Assumed	MISC	No	50	SF	6 ACBM with the potential for damage	Follow O&M Plan
17	Blue Linoleum	400	SF	East Mobile Unit- Boys' Restroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
18	Pink Linoleum	400	SF	East Mobile Unit- Girls' Restroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
19	Plaster	60,000	SF	Main Building	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
20	12x12 White w/Blue Specks Vinyl Floor Tile	2,400	SF	Cafeteria	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
21	12x12 White w/Blue Specks Vinyl Floor Tile Mastic	2,400	SF	Cafeteria	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
8B	12x12 Tan Floor Tile w/Streaks Mastic	580	SF	1995 Addition- Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
A	Aircell Pipe Insulation	840	SF	Basement, Pipe Chase/Air Tunnel, Crawlspace	Chrysotile	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
B	Cardboard Pipe Wrap	800	LF	Basement	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
C	Mudded Fittings/Elbows on Aircell Pipe Runs	878	LF	Basement Pipe Chases, Air Tunnel, Crawlspace	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
D	Aircell Duct Wrap	300	SF	Basement and Unexcavated Area, Crawlspace	Chrysotile	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
E	Mag Block Pipe Insulation ABATED			Boiler Room	Abated	TSI					
F	Duct Manifold	3	LF	Fan Room	Assumed	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan

# Chicago Public Schools

**School** Addams School  
**Address** 10810 S. Avenue H

**Unit** 22021  
 Chicago, IL, 60617

**Building ID** 2020  
**Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.  
 174 N. Brandon Drive Glendale Heights, IL, 60139  
 Phone: 630-790-0880 Fax: 630-790-0882

*Management Planner's Comments Summarized at the End of the Report*

Review Date	10/30/2019
Manager Planner Name	Amy Williams
100-00746	5/15/2020
Manager IDPH License No/Expiration	

HA Number	Management Comments
02	
02A	
03	
04	
04A	
05	
05A	
05B	

# Chicago Public Schools

**School** Addams School  
**Address** 10810 S. Avenue H

**Unit** 22021  
Chicago, IL, 60617

**Building ID** 2020  
**Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
06	
06A	
06C	
07	
07A	
07B	
07C	
07D	
08	
08A	
08C	
08D	
09	
10	
11	
12	
13	
14	
15A	
15B	
16A	
16B	
17	
18	
19	
20	

# Chicago Public Schools

**School** Addams School  
**Address** 10810 S. Avenue H

**Unit** 22021  
Chicago, IL, 60617

**Building ID** 2020  
**Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
21	
8B	
A	
B	
C	
D	
E	
F	



# Chicago Public Schools

TEM Environmental, Inc.

## 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **22021**    BUILDING ID: **2020**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Addams School**    INSPECTION DATE: **10/3/2019**  
ADDRESS: **10810 S. Avenue H**    IDPH LICENSE NO: **100-09106**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **02**  
MATERIAL DESCRIPTION: **12x12 Off-White Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st Floor Corridor and Teachers' Lounge; Office (Wood Tile over VFT)**  
MATERIAL QUANTITY: **1700**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/03/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUIDLING ID: **2020**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Addams School** REVIEW DATE: **10/30/2019**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **02**  
MATERIAL DESCRIPTION: **12x12 Off-White Floor Tile**  
MATERIAL LOCATION: **1st Floor Corridor and Teachers' Lounge; Office (Wood Tile over VFT)**  
MATERIAL QUANTITY: **1700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/30/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUIDLING ID: **2020**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Addams School** INSPECTION DATE: **10/3/2019**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-09106**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **02A**  
MATERIAL DESCRIPTION: **12x12 Beige Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **5 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON: **Physical Damage**  
DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **2nd Floor Corridor, Room 203 (27 x 23), Room 202, Room 200 (33x6)**  
MATERIAL QUANTITY: **2450** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **120** DAMAGE UNITS: **SF**  
COMMENTS: **Room 202 & 203**

Inspector's Signature: \_\_\_\_\_ Date: **10/03/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUIDLING ID: **2020**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Addams School** REVIEW DATE: **10/30/2019**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **02A**  
MATERIAL DESCRIPTION: **12x12 Beige Floor Tile**  
MATERIAL LOCATION: **2nd Floor Corridor, Room 203 (27 x 23), Room 202, Room 200 (33x6)**  
MATERIAL QUANTITY: **2450** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **120** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/30/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **22021**    BUILDING ID: **2020**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Addams School**    INSPECTION DATE: **10/3/2019**  
ADDRESS: **10810 S. Avenue H**    IDPH LICENSE NO: **100-09106**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **03**  
MATERIAL DESCRIPTION: **Blue Carpet/Tan Mastic (Not Observed)**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Office**  
MATERIAL QUANTITY: **2000**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/03/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUIDLING ID: **2020**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Addams School** REVIEW DATE: **10/30/2019**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **03**  
MATERIAL DESCRIPTION: **Blue Carpet/Tan Mastic (Not Observed)**  
MATERIAL LOCATION: **Office**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/30/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUIDLING ID: **2020**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Addams School** INSPECTION DATE: **10/3/2019**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-09106**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **04**  
MATERIAL DESCRIPTION: **12x12 Off-White Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st Floor Corridor and Teachers' Lounge**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/03/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUIDLING ID: **2020**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Addams School** REVIEW DATE: **10/30/2019**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **04**  
MATERIAL DESCRIPTION: **12x12 Off-White Floor Tile Mastic**  
MATERIAL LOCATION: **1st Floor Corridor and Teachers' Lounge**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/30/2019**



# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUIDLING ID: **2020**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Addams School** INSPECTION DATE: **10/3/2019**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-09106**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **04A**  
MATERIAL DESCRIPTION: **12x12 Beige Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **5 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **2nd Floor Corridor**  
MATERIAL QUANTITY: **1650** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **120** DAMAGE UNITS: **SF**  
COMMENTS: **Room 202 & 203**

Inspector's Signature: \_\_\_\_\_ Date: 10/03/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUIDLING ID: **2020**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Addams School** REVIEW DATE: **10/30/2019**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **04A**  
MATERIAL DESCRIPTION: **12x12 Beige Floor Tile Mastic**  
MATERIAL LOCATION: **2nd Floor Corridor**  
MATERIAL QUANTITY: **1650** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **120** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/30/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **22021**    BUILDING ID: **2020**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Addams School**    INSPECTION DATE: **10/3/2019**  
ADDRESS: **10810 S. Avenue H**    IDPH LICENSE NO: **100-09106**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **05**  
MATERIAL DESCRIPTION: **Beige Baseboard**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Kitchen, Cafeteria, and 1st Floor Corridor**  
MATERIAL QUANTITY: **900**    MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/03/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUIDLING ID: **2020**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Addams School** REVIEW DATE: **10/30/2019**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **05**  
MATERIAL DESCRIPTION: **Beige Baseboard**  
MATERIAL LOCATION: **Kitchen, Cafeteria, and 1st Floor Corridor**  
MATERIAL QUANTITY: **900** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/30/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **22021**    BUILDING ID: **2020**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Addams School**    INSPECTION DATE: **10/3/2019**  
ADDRESS: **10810 S. Avenue H**    IDPH LICENSE NO: **100-09106**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **05A**  
MATERIAL DESCRIPTION: **Gray Baseboard**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1996 Annex- Corridor and All Classrooms**  
MATERIAL QUANTITY: **1210**    MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/03/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUIDLING ID: **2020**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Addams School** REVIEW DATE: **10/30/2019**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **05A**  
MATERIAL DESCRIPTION: **Gray Baseboard**  
MATERIAL LOCATION: **1996 Annex- Corridor and All Classrooms**  
MATERIAL QUANTITY: **1210** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/30/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **22021**    BUILDING ID: **2020**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Addams School**    INSPECTION DATE: **10/3/2019**  
ADDRESS: **10810 S. Avenue H**    IDPH LICENSE NO: **100-09106**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **05B**  
MATERIAL DESCRIPTION: **Beige Baseboard**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 120-123**  
MATERIAL QUANTITY: **325**    MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/03/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUIDLING ID: **2020**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Addams School** REVIEW DATE: **10/30/2019**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **05B**  
MATERIAL DESCRIPTION: **Beige Baseboard**  
MATERIAL LOCATION: **Rooms 120-123**  
MATERIAL QUANTITY: **325** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/30/2019**



# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **22021**    BUILDING ID: **2020**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Addams School**    INSPECTION DATE: **10/3/2019**  
ADDRESS: **10810 S. Avenue H**    IDPH LICENSE NO: **100-09106**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **06**  
MATERIAL DESCRIPTION: **Beige Baseboard Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Kitchen, Cafeteria, and 1st Floor Corridor**  
MATERIAL QUANTITY: **900**    MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/03/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUIDLING ID: **2020**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Addams School** REVIEW DATE: **10/30/2019**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **06**  
MATERIAL DESCRIPTION: **Beige Baseboard Mastic**  
MATERIAL LOCATION: **Kitchen, Cafeteria, and 1st Floor Corridor**  
MATERIAL QUANTITY: **900** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/30/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUIDLING ID: **2020**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Addams School** INSPECTION DATE: **10/3/2019**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-09106**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **06A**  
MATERIAL DESCRIPTION: **Gray Baseboard Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1996 Annex- Corridor and All Classrooms**  
MATERIAL QUANTITY: **1210** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/03/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUIDLING ID: **2020**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Addams School** REVIEW DATE: **10/30/2019**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **06A**  
MATERIAL DESCRIPTION: **Gray Baseboard Mastic**  
MATERIAL LOCATION: **1996 Annex- Corridor and All Classrooms**  
MATERIAL QUANTITY: **1210** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/30/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUIDLING ID: **2020**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Addams School** INSPECTION DATE: **10/3/2019**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-09106**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **06C**  
MATERIAL DESCRIPTION: **Beige Baseboard Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Mobile Unit- Rooms 120-123**  
MATERIAL QUANTITY: **325** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/03/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUIDLING ID: **2020**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Addams School** REVIEW DATE: **10/30/2019**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **06C**  
MATERIAL DESCRIPTION: **Beige Baseboard Mastic**  
MATERIAL LOCATION: **Mobile Unit- Rooms 120-123**  
MATERIAL QUANTITY: **325** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/30/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUIDLING ID: **2020**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Addams School** INSPECTION DATE: **10/3/2019**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-09106**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **07**  
MATERIAL DESCRIPTION: **Tan Linoleum**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Kitchen**  
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/03/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUIDLING ID: **2020**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Addams School** REVIEW DATE: **10/30/2019**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **07**  
MATERIAL DESCRIPTION: **Tan Linoleum**  
MATERIAL LOCATION: **Kitchen**  
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/30/2019**



# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **22021**    BUIDLING ID: **2020**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Addams School**    INSPECTION DATE: **10/3/2019**  
ADDRESS: **10810 S. Avenue H**    IDPH LICENSE NO: **100-09106**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **07A**  
MATERIAL DESCRIPTION: **Brown Linoleum (Not Observed)**  
HISTORICAL AHERA DAMAGE CATEGORY: **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Cafeteria**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 10/03/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUILDING ID: **2020**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Addams School** REVIEW DATE: **10/30/2019**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **07A**

MATERIAL DESCRIPTION: **Brown Linoleum (Not Observed)**

MATERIAL LOCATION: **Cafeteria**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/30/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUIDLING ID: **2020**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Addams School** INSPECTION DATE: **10/3/2019**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-09106**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **07B**  
MATERIAL DESCRIPTION: **12x12 Tan Floor Tile w/Streaks**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1995 Addition- Corridor**  
MATERIAL QUANTITY: **580** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/03/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUIDLING ID: **2020**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Addams School** REVIEW DATE: **10/30/2019**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **07B**  
MATERIAL DESCRIPTION: **12x12 Tan Floor Tile w/Streaks**  
MATERIAL LOCATION: **1995 Addition- Corridor**  
MATERIAL QUANTITY: **580** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/30/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **22021**    BUILDING ID: **2020**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Addams School**    INSPECTION DATE: **10/3/2019**  
ADDRESS: **10810 S. Avenue H**    IDPH LICENSE NO: **100-09106**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **07C**  
MATERIAL DESCRIPTION: **12x12 White Floor w/Black Specks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout 1996 Annex- All Classrooms and Corridors**  
MATERIAL QUANTITY: **2490**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/03/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUIDLING ID: **2020**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Addams School** REVIEW DATE: **10/30/2019**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **07C**  
MATERIAL DESCRIPTION: **12x12 White Floor w/Black Specks Floor Tile**  
MATERIAL LOCATION: **Throughout 1996 Annex- All Classrooms and Corridors**  
MATERIAL QUANTITY: **2490** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/30/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUIDLING ID: **2020**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Addams School** INSPECTION DATE: **10/3/2019**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-09106**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **07D**  
MATERIAL DESCRIPTION: **12x12 Beige Floor Tile w/Streaks**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Mobile Unit Rooms 120-123**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/03/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUIDLING ID: **2020**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Addams School** REVIEW DATE: **10/30/2019**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **07D**  
MATERIAL DESCRIPTION: **12x12 Beige Floor Tile w/Streaks**  
MATERIAL LOCATION: **Mobile Unit Rooms 120-123**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/30/2019**



# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUIDLING ID: **2020**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Addams School** INSPECTION DATE: **10/3/2019**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-09106**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **08**  
MATERIAL DESCRIPTION: **Tan Linoleum Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Kitchen**  
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/03/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUIDLING ID: **2020**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Addams School** REVIEW DATE: **10/30/2019**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **08**  
MATERIAL DESCRIPTION: **Tan Linoleum Mastic**  
MATERIAL LOCATION: **Kitchen**  
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/30/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **22021**    BUIDLING ID: **2020**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Addams School**    INSPECTION DATE: **10/3/2019**  
ADDRESS: **10810 S. Avenue H**    IDPH LICENSE NO: **100-09106**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **08A**  
MATERIAL DESCRIPTION: **Brown Linoleum Mastic (Not Observed)**  
HISTORICAL AHERA DAMAGE CATEGORY: **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Cafeteria**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/03/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUILDING ID: **2020**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Addams School** REVIEW DATE: **10/30/2019**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **08A**

MATERIAL DESCRIPTION: **Brown Linoleum Mastic (Not Observed)**

MATERIAL LOCATION: **Cafeteria**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/30/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **22021**    BUILDING ID: **2020**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Addams School**    INSPECTION DATE: **10/3/2019**  
ADDRESS: **10810 S. Avenue H**    IDPH LICENSE NO: **100-09106**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **08C**  
MATERIAL DESCRIPTION: **12x12 White Floor w/Black Specks Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout 1996 Annex, All Classrooms and Corridor**  
MATERIAL QUANTITY: **2490**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/03/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUIDLING ID: **2020**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Addams School** REVIEW DATE: **10/30/2019**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **08C**  
MATERIAL DESCRIPTION: **12x12 White Floor w/Black Specks Floor Tile Mastic**  
MATERIAL LOCATION: **Throughout 1996 Annex, All Classrooms and Corridor**  
MATERIAL QUANTITY: **2490** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/30/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUIDLING ID: **2020**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Addams School** INSPECTION DATE: **10/3/2019**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-09106**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **08D**  
MATERIAL DESCRIPTION: **12x12 Beige Floor Tile w/Streaks Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Mobile Unit- Rooms 120-123**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/03/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUIDLING ID: **2020**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Addams School** REVIEW DATE: **10/30/2019**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **08D**  
MATERIAL DESCRIPTION: **12x12 Beige Floor Tile w/Streaks Mastic**  
MATERIAL LOCATION: **Mobile Unit- Rooms 120-123**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/30/2019**



# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **22021**    BUIDLING ID: **2020**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Addams School**    INSPECTION DATE: **10/3/2019**  
ADDRESS: **10810 S. Avenue H**    IDPH LICENSE NO: **100-09106**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **09**  
MATERIAL DESCRIPTION: **2'x2' Smooth White Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY: **7 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1995 Addition- Kitchen**  
MATERIAL QUANTITY: **770**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/03/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUIDLING ID: **2020**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Addams School** REVIEW DATE: **10/30/2019**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **09**  
MATERIAL DESCRIPTION: **2'x2' Smooth White Ceiling Tile**  
MATERIAL LOCATION: **1995 Addition- Kitchen**  
MATERIAL QUANTITY: **770** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/30/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUIDLING ID: **2020**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Addams School** INSPECTION DATE: **10/3/2019**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-09106**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10**  
MATERIAL DESCRIPTION: **2'x2' White Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1995 Addition- Cafeteria**  
MATERIAL QUANTITY: **2100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/03/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUIDLING ID: **2020**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Addams School** REVIEW DATE: **10/30/2019**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **10**  
MATERIAL DESCRIPTION: **2'x2' White Ceiling Tile**  
MATERIAL LOCATION: **1995 Addition- Cafeteria**  
MATERIAL QUANTITY: **2100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/30/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **22021**    BUIDLING ID: **2020**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Addams School**    INSPECTION DATE: **10/3/2019**  
ADDRESS: **10810 S. Avenue H**    IDPH LICENSE NO: **100-09106**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11**  
MATERIAL DESCRIPTION: **2'x4' White Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY: **7 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **Yes**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1996 Annex- Corridor and All Classrooms (Except 115)**  
MATERIAL QUANTITY: **2340**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/03/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUIDLING ID: **2020**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Addams School** REVIEW DATE: **10/30/2019**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **11**  
MATERIAL DESCRIPTION: **2'x4' White Ceiling Tile**  
MATERIAL LOCATION: **1996 Annex- Corridor and All Classrooms (Except 115)**  
MATERIAL QUANTITY: **2340** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/30/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **22021**    BUILDING ID: **2020**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Addams School**    INSPECTION DATE: **10/3/2019**  
ADDRESS: **10810 S. Avenue H**    IDPH LICENSE NO: **100-09106**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12**  
MATERIAL DESCRIPTION: **Solid Ceiling Panels**  
HISTORICAL AHERA DAMAGE CATEGORY: **7 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **Yes**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **North Mobile Unit - Rooms 120 & 121**  
MATERIAL QUANTITY: **2500**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/03/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUIDLING ID: **2020**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Addams School** REVIEW DATE: **10/30/2019**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **12**  
MATERIAL DESCRIPTION: **Solid Ceiling Panels**  
MATERIAL LOCATION: **North Mobile Unit - Rooms 120 & 121**  
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/30/2019**



# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **22021**    BUILDING ID: **2020**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Addams School**    INSPECTION DATE: **10/3/2019**  
ADDRESS: **10810 S. Avenue H**    IDPH LICENSE NO: **100-09106**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13**  
MATERIAL DESCRIPTION: **2'x2' White Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY: **7 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **Yes**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **South Mobile Unit- Rooms 122 & 123**  
MATERIAL QUANTITY: **2500**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/03/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUIDLING ID: **2020**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Addams School** REVIEW DATE: **10/30/2019**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **13**  
MATERIAL DESCRIPTION: **2'x2' White Ceiling Tile**  
MATERIAL LOCATION: **South Mobile Unit- Rooms 122 & 123**  
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/30/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **22021**    BUILDING ID: **2020**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Addams School**    INSPECTION DATE: **10/3/2019**  
ADDRESS: **10810 S. Avenue H**    IDPH LICENSE NO: **100-09106**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14**  
MATERIAL DESCRIPTION: **2'x2' White Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY: **7 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **Yes**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **East Mobile Unit**  
MATERIAL QUANTITY: **5000**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/03/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUIDLING ID: **2020**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Addams School** REVIEW DATE: **10/30/2019**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **14**  
MATERIAL DESCRIPTION: **2'x2' White Ceiling Tile**  
MATERIAL LOCATION: **East Mobile Unit**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/30/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **22021**    BUILDING ID: **2020**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Addams School**    INSPECTION DATE: **10/3/2019**  
ADDRESS: **10810 S. Avenue H**    IDPH LICENSE NO: **100-09106**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15A**  
MATERIAL DESCRIPTION: **Beige Baseboard**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **East Mobile Unit**  
MATERIAL QUANTITY: **3000**    MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/03/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUILDING ID: **2020**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Addams School** REVIEW DATE: **10/30/2019**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **15A**  
MATERIAL DESCRIPTION: **Beige Baseboard**  
MATERIAL LOCATION: **East Mobile Unit**  
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/30/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **22021**    BUILDING ID: **2020**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Addams School**    INSPECTION DATE: **10/3/2019**  
ADDRESS: **10810 S. Avenue H**    IDPH LICENSE NO: **100-09106**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15B**  
MATERIAL DESCRIPTION: **Beige Baseboard Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **East Mobile Unit**  
MATERIAL QUANTITY: **3000**    MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/03/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUIDLING ID: **2020**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Addams School** REVIEW DATE: **10/30/2019**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **15B**  
MATERIAL DESCRIPTION: **Beige Baseboard Mastic**  
MATERIAL LOCATION: **East Mobile Unit**  
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/30/2019**



# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUIDLING ID: **2020**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Addams School** INSPECTION DATE: **10/3/2019**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-09106**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16A**  
MATERIAL DESCRIPTION: **12x12 White Speckled Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Physical Damage**  
DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **East Mobile Unit**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **50** DAMAGE UNITS: **SF**  
COMMENTS: **Damage Throughout**

Inspector's Signature: \_\_\_\_\_ Date: 10/03/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUIDLING ID: **2020**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Addams School** REVIEW DATE: **10/30/2019**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **16A**  
MATERIAL DESCRIPTION: **12x12 White Speckled Floor Tile**  
MATERIAL LOCATION: **East Mobile Unit**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **50** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/30/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUIDLING ID: **2020**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Addams School** INSPECTION DATE: **10/3/2019**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-09106**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16B**  
MATERIAL DESCRIPTION: **12x12 White Speckled Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **East Mobile Unit**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **50** DAMAGE UNITS: **SF**  
COMMENTS: **Damage Throughout**

Inspector's Signature: \_\_\_\_\_ Date: 10/03/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUIDLING ID: **2020**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Addams School** REVIEW DATE: **10/30/2019**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **16B**  
MATERIAL DESCRIPTION: **12x12 White Speckled Floor Tile Mastic**  
MATERIAL LOCATION: **East Mobile Unit**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **50** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/30/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **22021**    BUILDING ID: **2020**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Addams School**    INSPECTION DATE: **10/3/2019**  
ADDRESS: **10810 S. Avenue H**    IDPH LICENSE NO: **100-09106**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17**  
MATERIAL DESCRIPTION: **Blue Linoleum**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **East Mobile Unit- Boys' Restroom**  
MATERIAL QUANTITY: **400**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/03/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUIDLING ID: **2020**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Addams School** REVIEW DATE: **10/30/2019**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **17**  
MATERIAL DESCRIPTION: **Blue Linoleum**  
MATERIAL LOCATION: **East Mobile Unit- Boys' Restroom**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/30/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **22021**    BUIDLING ID: **2020**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Addams School**    INSPECTION DATE: **10/3/2019**  
ADDRESS: **10810 S. Avenue H**    IDPH LICENSE NO: **100-09106**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18**  
MATERIAL DESCRIPTION: **Pink Linoleum**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **East Mobile Unit- Girls' Restroom**  
MATERIAL QUANTITY: **400**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/03/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUIDLING ID: **2020**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Addams School** REVIEW DATE: **10/30/2019**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **18**  
MATERIAL DESCRIPTION: **Pink Linoleum**  
MATERIAL LOCATION: **East Mobile Unit- Girls' Restroom**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/30/2019**



# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **22021**    BUILDING ID: **2020**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Addams School**    INSPECTION DATE: **10/3/2019**  
ADDRESS: **10810 S. Avenue H**    IDPH LICENSE NO: **100-09106**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19**  
MATERIAL DESCRIPTION: **Plaster**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Main Building**  
MATERIAL QUANTITY: **60000**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/03/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUIDLING ID: **2020**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Addams School** REVIEW DATE: **10/30/2019**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **19**  
MATERIAL DESCRIPTION: **Plaster**  
MATERIAL LOCATION: **Main Building**  
MATERIAL QUANTITY: **60000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/30/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **22021**    BUILDING ID: **2020**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Addams School**    INSPECTION DATE: **10/3/2019**  
ADDRESS: **10810 S. Avenue H**    IDPH LICENSE NO: **100-09106**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**  
MATERIAL DESCRIPTION: **12x12 White w/Blue Specks Vinyl Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Cafeteria**  
MATERIAL QUANTITY: **2400**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/03/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUIDLING ID: **2020**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Addams School** REVIEW DATE: **10/30/2019**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **20**  
MATERIAL DESCRIPTION: **12x12 White w/Blue Specks Vinyl Floor Tile**  
MATERIAL LOCATION: **Cafeteria**  
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/30/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUIDLING ID: **2020**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Addams School** INSPECTION DATE: **10/3/2019**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-09106**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21**  
MATERIAL DESCRIPTION: **12x12 White w/Blue Specks Vinyl Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Cafeteria**  
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/03/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUIDLING ID: **2020**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Addams School** REVIEW DATE: **10/30/2019**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **21**  
MATERIAL DESCRIPTION: **12x12 White w/Blue Specks Vinyl Floor Tile Mastic**  
MATERIAL LOCATION: **Cafeteria**  
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/30/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **22021**    BUIDLING ID: **2020**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Addams School**    INSPECTION DATE: **10/3/2019**  
ADDRESS: **10810 S. Avenue H**    IDPH LICENSE NO: **100-09106**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **8B**  
MATERIAL DESCRIPTION: **12x12 Tan Floor Tile w/Streaks Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1995 Addition- Corridor**  
MATERIAL QUANTITY: **580**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/03/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUIDLING ID: **2020**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Addams School** REVIEW DATE: **10/30/2019**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **8B**  
MATERIAL DESCRIPTION: **12x12 Tan Floor Tile w/Streaks Mastic**  
MATERIAL LOCATION: **1995 Addition- Corridor**  
MATERIAL QUANTITY: **580** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/30/2019**



# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **22021**    BUIDLING ID: **2020**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Addams School**    INSPECTION DATE: **10/3/2019**  
ADDRESS: **10810 S. Avenue H**    IDPH LICENSE NO: **100-09106**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **A**  
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY: **7 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile**    FRIABLE: **Yes**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Basement, Pipe Chase/Air Tunnel, Crawlspace**  
MATERIAL QUANTITY: **840**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **10/03/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUIDLING ID: **2020**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Addams School** REVIEW DATE: **10/30/2019**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **A**  
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**  
MATERIAL LOCATION: **Basement, Pipe Chase/Air Tunnel, Crawlspace**  
MATERIAL QUANTITY: **840** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/30/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUIDLING ID: **2020**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Addams School** INSPECTION DATE: **10/3/2019**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-09106**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **B**  
MATERIAL DESCRIPTION: **Cardboard Pipe Wrap**  
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Basement**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/03/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUIDLING ID: **2020**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Addams School** REVIEW DATE: **10/30/2019**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **B**  
MATERIAL DESCRIPTION: **Cardboard Pipe Wrap**  
MATERIAL LOCATION: **Basement**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/30/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **22021**    BUILDING ID: **2020**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Addams School**    INSPECTION DATE: **10/3/2019**  
ADDRESS: **10810 S. Avenue H**    IDPH LICENSE NO: **100-09106**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **C**  
MATERIAL DESCRIPTION: **Mudded Fittings/Elbows on Aircell Pipe Runs**  
HISTORICAL AHERA DAMAGE CATEGORY: **7 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile**    FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Basement Pipe Chases, Air Tunnel, Crawlspace**  
MATERIAL QUANTITY: **878**    MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/03/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUIDLING ID: **2020**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Addams School** REVIEW DATE: **10/30/2019**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **C**  
MATERIAL DESCRIPTION: **Mudded Fittings/Elbows on Aircell Pipe Runs**  
MATERIAL LOCATION: **Basement Pipe Chases, Air Tunnel, Crawlspace**  
MATERIAL QUANTITY: **878** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/30/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **22021**    BUIDLING ID: **2020**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Addams School**    INSPECTION DATE: **10/3/2019**  
ADDRESS: **10810 S. Avenue H**    IDPH LICENSE NO: **100-09106**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **D**  
MATERIAL DESCRIPTION: **Aircell Duct Wrap**  
HISTORICAL AHERA DAMAGE CATEGORY: **7 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile**    FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Basement and Unexcavated Area, Crawlspace**  
MATERIAL QUANTITY: **300**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/03/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUIDLING ID: **2020**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Addams School** REVIEW DATE: **10/30/2019**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **D**  
MATERIAL DESCRIPTION: **Aircell Duct Wrap**  
MATERIAL LOCATION: **Basement and Unexcavated Area, Crawlspace**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/30/2019**



# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUIDLING ID: **2020**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Addams School** INSPECTION DATE: **10/3/2019**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-09106**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **E**  
MATERIAL DESCRIPTION: **Mag Block Pipe Insulation ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **10/03/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUILDING ID: **2020**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Addams School** REVIEW DATE: **10/30/2019**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **E**

MATERIAL DESCRIPTION: **Mag Block Pipe Insulation ABATED**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/30/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUIDLING ID: **2020**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Addams School** INSPECTION DATE: **10/3/2019**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-09106**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **F**  
MATERIAL DESCRIPTION: **Duct Manifold**  
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Fan Room**  
MATERIAL QUANTITY: **3** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/03/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22021** BUIDLING ID: **2020**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Addams School** REVIEW DATE: **10/30/2019**  
ADDRESS: **10810 S. Avenue H** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **F**  
MATERIAL DESCRIPTION: **Duct Manifold**  
MATERIAL LOCATION: **Fan Room**  
MATERIAL QUANTITY: **3** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/30/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
*2019 AHERA REINSPECTION*

# APPENDIX B

## Inspector and Management Planner Licenses


---

# CERTIFICATE OF ACHIEVEMENT ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that MICHAEL HASIER  
has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the  
examination on 05/01/2019 with a minimum score of 70% or better. Training was in accordance  
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:  
Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.

05/01/2019  
Course Dates:  
05/01/2020  
Expires:  
1905BIR02  
Certificate Number:



Office: 312-491-0081  
Fax: 312-421-2901

Director of Training

Nicholas J. Peneff

Doctor of Public Health

Phone: 312-491-0081

FORM # A-010B

# COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License



## ASBESTOS PROFESSIONAL LICENSE

ENDORSEMENTS	TC EXPIRES
SUPERVISOR/WORKER	3/1/2020
INSPECTOR	5/1/2020

ID NUMBER	ISSUED	EXPIRES
100 - 09106	5/8/2019	05/15/2020

**MICHAEL S HASIER**  
444 OLD BARN RD., APT. B  
BARRINGTON, IL 60010

Environmental Health



PROJECT MANAGER 3/1/2020

AIR SAMPLING PROFESSIONAL

Alteration of this license shall result in legal action  
This license issued under authority of the State of Illinois  
Department of Public Health

This license is valid only when accompanied by a valid  
training course certificate.



**Reliable  
Environmental  
Solutions, Inc.** **RES**

*This is to certify that* **Amy J. Williams**

*has on 04/03/19, in Springfield, Illinois,  
completed the requirements for asbestos accreditation under Section 206 of TSCA Title II*

**Asbestos Building Inspector Refresher Training**

*as accredited by the State of Illinois and approved by the U.S.E.P.A. under 40 CFR 763 (AHERA)  
and passed the associated examination with a score of 70% or higher*

Course Date: April 03, 2019

**COURSE LENGTH: 4 HOURS**

Examination Date: April 03, 2019

Expiration Date: April 03, 2020

*William S. Williams*

Certificate Number: BIR/0808

Training Program Manager, William S. Williams

4211 Westgate Drive, Springfield, Illinois ☐ 217.787.9800 ☐ 217.787.9801 FAX ☐ [www.ReliableEnv.com](http://www.ReliableEnv.com)



2539 Vandalia Street, Collinsville, IL 62234 \* Phone: 618-855-8764

Environmental and Occupational Safety & Health Training

*Does hereby certify*

**William Williams**

4211 Westgate Drive, Springfield, IL 62711

*Has successfully completed and passed the course examination with at least  
70% for re-accreditation under AHERA (Title II)*

**Asbestos Management Planner Refresher**

**Class Date:** 02/15/2019  
**Examination Date:** 02/15/2019  
**STC Certificate Number:** STC-20190215-000527AMPR  
**Certification Expiration:** 02/15/2020

David M. Mendoza – President/Training Director  
Certified Environmental Specialist  
OSHA Authorized Instructor

# COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License



## ASBESTOS PROFESSIONAL LICENSE

### ENDORSEMENTS

### TC EXPIRES

ID NUMBER	ISSUED	EXPIRES
100 - 00746	4/11/2019	05/15/2020

INSPECTOR

4/21/2019

MANAGEMENT PLANNER

4/21/2019

PROJECT MANAGER

4/2/2020


AIR SAMPLING PROFESSIONAL

**AMY J WILLIAMS**

1408 S CLAY

JACKSONVILLE, IL 62650

Environmental Health



**Alteration of this license shall result in legal action**  
This license issued under authority of the State of Illinois  
Department of Public Health  
This license is valid only when accompanied by a valid  
training course certificate.

# APPENDIX C

## Laboratory Accreditations

---

# APPENDIX D

## Laboratory Results

---

# APPENDIX E

## Chain of Custody Forms

---

## Three-Year Reinspection Key to Terms

	<b>CODE</b>	<b>KEY</b>
<b>MATERIAL</b>		
	ACBM	Asbestos Containing Building Materials
<b>MATERIAL CATEGORY</b>		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
<b>MATERIAL UNITS</b>		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
<b>DAMAGE TYPE</b>		
	Loc	Localized
	Dist	Distributed