

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH  
AHERA THREE YEAR REINSPECTION  
ASBESTOS ABATEMENT PROGRAM  
SCHOOL INFORMATION FORM**

**SECTION I**

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299  
SCHOOL ID NUMBER: 14-016-2990-2059  
SCHOOL NAME: Armstrong School  
ADDRESS OF SCHOOL: 2111 West Estes Avenue  
CITY: Chicago, IL, 60645

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **3/24/2016**

**If the address on this form is different than the address of the building, submit a written explanation.**

---

**SECTION II** *(Please type or print)*

**PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:**

DATE REINSPECTION COMPLETED: 10/1/2019 ENROLLMENT 1244  
IDPH INSPECTOR LICENSE NUMBER: 100-11089  
IDPH LICENSED INSPECTOR NAME(Please Print): Panfilo Carrazco  
IDPH MP LICENSE NUMBER: 100-04019  
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Arturo Saenz

DESIGNATED PERSON (Please Print): Robert Christlieb PHONE: (773) 553-3197



10/1/2019

*Signature of Designated Person*

*Date*

**SECTION III**

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: \_\_\_\_\_

School has been closed. Date closed: \_\_\_\_\_

School building has been demolished. Date: \_\_\_\_\_

School building is asbestos free since last reinspection: \_\_\_\_\_

**Please explain in writing why the school building is now asbestos free and include the supporting documentation.**

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

**Explain in writing if the address of the building is different than the address on this form:**

---

---

---

**THREE-YEAR REINSPECTION**

**CHICAGO SCHOOL DIST 299**

**Armstrong School**

2111 West Estes Avenue  
Chicago, IL, 60645

Unit: 22081  
Building ID: 2080

IDPH ID Number: 14-016-2990-2059

**REPORT DATE:**

Tuesday, October 01, 2019

**Prepared for:**

**Chicago Public Schools  
42 West Madison Street  
Chicago, IL 60602**

**Prepared by:**

**GSG-Probe Consulting, Inc.**

2942 W. Van Buren

Chicago, IL, 60612

Phone 3123197575

Fax

**DO NOT REMOVE FROM SCHOOL  
REQUIRED BY FEDERAL LAW**

October 28, 2019

Mr. Glen E. Garner  
Asbestos Program  
Illinois Department of Public Health  
525 West Jefferson Street  
Springfield, Illinois 62761

Re: Chicago Public Schools - 2019 Three-Year Reinspections

Dear Mr. Glen:

GSG-Probe Consulting, Inc., Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 1, 2 Elementary Schools. Please update your records with the following information.

School District: 299            Unit: 22081            Region: 01            IDPH ID:14-016-2990-2059

School: Armstrong School            Building ID: 2080

Address: 2111 West Estes Avenue  
Chicago, IL, 60645

Building Contact:            Contact Phone:

Current Building Owners: Chicago Public Schools

Review Date: 11/13/2019

Inspector: Panfilo Carrazco            Inspector IDPH License: 100-11089  
Management Planner: Arturo Saenz            Management Planner IDPH License: 100-04019

If you have any questions or comments, please contact us at 3123197575

Sincerely,  
GSG-Probe Consulting, Inc.

Arturo Saenz  
100-04019

## **Environmental Notification to Occupants**

To: Faculty, Staff and Parents  
From: Chicago Public Schools  
Date: October 28, 2019

RE: Armstrong School, Unit 22081  
2111 West Estes Avenue  
Chicago, IL, 60645

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2019 asbestos three year re-inspection has been completed at Armstrong School, following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at Armstrong School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Robert Christlieb, the designated Local Education Authority's Designated Person at (773) 553-3197 .

## **Table of Contents**

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

### **APPENDICES:**

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

## SCHOOL AND INSPECTION INFORMATION

### 1. School Information

School: Armstrong School Unit: 22081 Region: 01  
Address: 2111 West Estes Avenue Chicago, IL, 60645  
IDPH ID: 14-016-2990-2059 Building ID: 2080  
Contact: Phone:

### 2. Description of Facility

Original Construction: Additional Construction:  
Total Square Footage: No of Floors:  
Current Occupancy: 1244

### 3. LEA Designated Person

Contact: Robert Christlieb Phone: (773) 553-3197  
Address: 42 West Madison Street  
Chicago, IL 60602

### 4. Managing Environmental Consultant

MEC: GSG-Probe Consulting, Inc.  
Contact: Jigar Shah  
Address 2942 W. Van Buren  
Chicago, IL, 60612  
Phone: 3123197575 Fax:

### 5. Inspector

Inspector Name: Panfilo Carrazco

Inspector IDPH license # 100-11089  
Signature:  
Date: 10/28/2019

### 6. Management Planner

Management Planner Name: Arturo Saenz

Management Planner IDPH license # 100-04019  
Signature:  
Date: 11/13/2019

### 7. Review Date:11/13/2019

### 8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature:  Date: 10/1/2019  
Name: Robert Christlieb

## II. EXECUTIVE SUMMARY

GSG-Probe Consulting, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Armstrong School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.85 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 2080:

B. The following new homogenous areas have been identified for Building 2080:

55	12" x 12" Beige w/ White & Brown Streaks VFT
55A	12" x 12" Beige w/ White & Brown Streaks VFT Mastic
56	2' x 4' Smooth Ceiling Tile
57	2' x 4' Fissured w/ 1" Dividing Line Ceiling Tile
58	Red Fire Stop Sealant
59	Gray Sealant
60	Sink Undercoating
61	Vinyl Baseboard Mastic
62	Drywall System
63	Gray Linoleum
63A	Gray Linoleum Mastic



C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

11	12"x12" Off-White VFT Mastic (Under Carpet)
14A	12"x12" Light Brown VFT
15	12"x12" Peach w/ White Streaks VFT
15A	12"x12" Peach w/ White Streaks VFT Mastic
16	12"x12" Tan w/ Tan Streaks VFT
16A	12"x12" Tan w/ Tan Streaks VFT Mastic
18	12"x12" Light Grey VFT
18A	12"x12" Light Grey VFT Mastic
19	12"x12" Green Painted VFT
19A	12"x12" Green Painted VFT Mastic
20	12"x12" Tan w/ Brown Spots VFT
20A	12"x12" Tan w/ Brown Spots VFT Mastic
22	12"x12" Off White VFT
23	12"x12" Off White VFT Mastic
24	12"x12" Gray VFT
25	12"x12" Gray VFT Mastic
26	12"x12" Black VFT
27	12"x12" Black VFT Mastic
35	12"x12" Sand VFT
36	12"x12" Sand VFT Mastic
47	2'x4' Ceiling Tile
48	12" x 12" Gray Floor tile
48 A	12" x 12" Gray Floor tile Mastic
49	Terrazzo
50	Fire Doors
51	12" x 12" Sand VFT
51A	12" x 12" Sand VFT Mastic
52	2' x 4' Tectum Ceiling Tile
53	Drywall System
54	Boiler Gaskets
55	12" x 12" Beige w/ White & Brown Streaks VFT
55A	12" x 12" Beige w/ White & Brown Streaks VFT Mastic
56	2' x 4' Smooth Ceiling Tile
57	2' x 4' Fissured w/ 1" Dividing Line Ceiling Tile
58	Red Fire Stop Sealant
59	Gray Sealant
60	Sink Undercoating
61	Vinyl Baseboard Mastic
62	Drywall System
63	Gray Linoleum
63A	Gray Linoleum Mastic

M

Sheet Rock

The following areas were deemed to be inaccessible:

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Panfilo Carrazco, IDPH License # 100-11089. The Management Plan was updated by Arturo Saenz, IDPH License # 100-04019. Inspector and Management Planner Licenses are included in Appendix B.

### **III. METHODOLOGY**

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

### **IV. ABATEMENT HISTORY**

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

### **V. REASSESSMENTS AND RECOMMENDATIONS**

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

### **VI. CONCLUSIONS**

The Armstrong School Building 2080 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. Atimely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

**Table I**  
**Inspector's Reinspection Findings**

---

# Chicago Public Schools

School Armstrong School Unit 22081 Building ID 2080

Address 2111 West Estes Avenue Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
01	9"x9" Green VFT	80	SF	Engineering Closet - 1916 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
02	12"x12" Tan VFT	160	SF	Room 211 (Adj. Rm.) - 1916 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
03	9"x9" Green VFT Mastic	80	SF	Engineering Closet - 1916 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
04	12"x12" Tan VFT Mastic	160	SF	Room 211 (Adj. Rm.) - 1916 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
05	Tan Linoleum	455	SF	Stage Area - 1916 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
06	Tan Linoleum Mastic	455	SF	Stage Area - 1916 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
06A	Hard Coat Plaster			Throughout - 1916 Bldg.	NO_ACBM									
07	18"x6" Dark Brown VFT	85	SF	Room 211 (Adj. Rm.) - 1916 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
08	18"x6" Dark Brown VFT Mastic	85	SF	Room 211 (Adj. Rm.) - 1916 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
09	12"x12" Brown VFT	160	SF	Room 211 (Adj. Rm.) - 1916 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
10	12"x12" Brown VFT Mastic	160	SF	Room 211 (Adj. Rm.) - 1916 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
11	12"x12" Off-White VFT Mastic (Under Carpet)	400	SF	Room 200 - 1916 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
11A	12"x12" Off-White VFT	400	SF	Room 200 - 1916 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
12	12"x12" Gray w/ White Streaks VFT	460	SF	1st Floor Girls Toilet, Auditorium Dressing Room - 1916 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
13	12"x12" Grey w/ White Streaks VFT Mastic	460	SF	1st Floor Girls Toilet, Auditorium Dressing Room - 1916 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
14	12"x12" Light Brown VFT Mastic	380	SF	Engineers Office - 1916 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
14A	12"x12" Light Brown VFT	380	SF	Engineers Office - 1916 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
15	12"x12" Peach w/ White Streaks VFT	800	SF	Rooms 99, 100, 300 - 1916 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
15A	12"x12" Peach w/ White Streaks VFT Mastic	800	SF	Rooms 99, 100, 300 - 1916 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
16	12"x12" Tan w/ Tan Streaks VFT	2,200	SF	Rooms 201, 203, & Old Principals	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE

# Chicago Public Schools

School Armstrong School Unit 22081 Building ID 2080

Address 2111 West Estes Avenue Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Office, Closet & Toilet Bldg - 1916 Bldg.										
16A	12"x12" Tan w/ Tan Streaks VFT Mastic	2,200	SF	Rooms 201, 203, & Old Principals Office, Closet & Toilet Bldg - 1916 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
17				Room 308 - 1916 Bldg. (This room has Hardwood Floor as of 2013 3 yr)	NO_ACBM	MISC		None						Moderate
17A				Room 308 - 1916 Bldg. (This room has Hardwood Floor)	NO_ACBM	MISC		None						Moderate
18	12"x12" Light Grey VFT	300	SF	Room 311 (Adj. Rm.) - 1916 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
18A	12"x12" Light Grey VFT Mastic	300	SF	Room 311 (Adj. Rm.) - 1916 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
19	12"x12" Green Painted VFT	75	SF	Room 105 Toilet - 1916 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
19A	12"x12" Green Painted VFT Mastic	75	SF	Room 105 Toilet - 1916 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
20	12"x12" Tan w/ Brown Spots VFT	1,000	SF	106 (Social Room), Engineer's Office, & Outer Office, Room 99 - 1916 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
20A	12"x12" Tan w/ Brown Spots VFT Mastic	1,000	SF	106 (Social Room), Engineer's Office, & Outer Office, Room 99 - 1916 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
21	Carpet Mastic			Rooms 101, 102, & Gym/Auditorium - 1916 Bldg.	NO_ACBM									
22	12"x12" Off White VFT	1,500	SF	Teachers Lounge, Multipurpose Room, Corridor - 1993 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
23	12"x12" Off White VFT Mastic	1,500	SF	Teachers Lounge, Multipurpose Room, Corridor - 1993 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
24	12"x12" Gray VFT	8	SF	Multipurpose Room,	ASSUMED	MISC	N	NONE	0		No	ACBM with the		MODERATE



# Chicago Public Schools

School Armstrong School Unit 22081 Building ID 2080

Address 2111 West Estes Avenue Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Bldg.										
40	Vinyl Baseboard Mastic			Throughout - 1999 Bldg.	NO_ACBM									
41	Spray-On Insulation			Throughout Above Ceilings on Metal Beams - 1999 Bldg.	NO_ACBM									
42	Carpet Mastic			222 (Library), Faculty Room, Main Office Area - 1999 Bldg.	NO_ACBM									
43	Drywall			Throughout - 1999 Bldg.	NO_ACBM									
44	Drywall Compound			Throughout - 1999 Bldg.	NO_ACBM									
45	2'x4' Grooved Ceiling Tile			Throughout - 1999 Bldg.	NO_ACBM									
46	2'x4' Smooth White Ceiling Tile			Serving Area, Kitchen, Kitchen JC, Kitchen Toilet, Kitchen Storage, Kitchen Office, Dishwash - 1999 Bldg.	NO_ACBM									
47	2'x4' Ceiling Tile	8,000	SF	1st, 2nd and 3rd Fl. Classrooms & Corridors - 1916 Bldg.	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
48	12" x 12" Gray Floor tile	700	SF	Room 307	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
48 A	12" x 12" Gray Floor tile Mastic	700	SF	Room 307	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
49	Terrazzo	15,000	SF	Corridors, Stairwells, Boys & Girls toilets & faculty restrooms - 1999 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
50	Fire Doors	50	EA	Stairwells, lunchroom, between 1916 & 1999 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
51	12" x 12" Sand VFT	800	SF	Rooms 300, 200 - 1916 Bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
51A	12" x 12" Sand VFT Mastic	800	SF	Rooms 300, 200 - 1916 Bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
52	2' x 4' Tectum Ceiling Tile	3,000	SF	Assembly Hall/Gym	ASSUMED	MISC	Y	NONE	0		No	ACBM with the		LOW



# Chicago Public Schools

School Armstrong School Unit 22081 Building ID 2080

Address 2111 West Estes Avenue Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				- 1916 Bldg								potential for damage		
53	Drywall System	5,000	SF	Main Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
54	Boiler Gaskets	15	LF	Boiler Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
55	12" x 12" Beige w/ White & Brown Streaks VFT	400	SF	Auditorium Changing Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
55A	12" x 12" Beige w/ White & Brown Streaks VFT Mastic	400	SF	Auditorium Changing Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
56	2' x 4' Smooth Ceiling Tile	500	SF	Kitchen, Serving Area & Dishwashing Room	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
57	2' x 4' Fissured w/ 1" Dividing Line Ceiling Tile	800	SF	Room 310 & Hall, Room 210 & Hall	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
58	Red Fire Stop Sealant	100	EA	Throughout Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
59	Gray Sealant	2,000	LF	on Ducts above ceilings, Penthouse Mechanical Room - 1999 Bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
60	Sink Undercoating	12	SF	Corridor by Room 103	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
61	Vinyl Baseboard Mastic	300	LF	Room 310 & Hall; Room 210 & Hall	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
62	Drywall System	300	SF	Room 310 & Hall; Room 210 & Hall	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
63	Gray Linoleum	3,000	SF	Lunchroom, Serving Area Hallway	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
63A	Gray Linoleum Mastic	3,000	SF	Lunchroom, Serving Area Hallway	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
J	MJP E/F/V on Fiberglass Pipe Insulation	120	FITTING	Boiler Room, 2nd & 3rd Fl Girls Toilets, Engine Room, & Fan Area - 1916 Bldg.	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
M	Sheet Rock	100	SF	Above 3rd Floor Ceilings - 1916 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

# Chicago Public Schools

School Armstrong School Unit 22081 Building ID 2080

Address 2111 West Estes Avenue Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

*Inspector's Comments are Summarized at the End of the Report*

Reinspection Date <b>10/28/2019</b>
Inspector Name <b>Panfilo Carrazco</b>
<b>100-11089</b> <b>5/15/2020</b>
Inspector's IDPH License Number / Expiration Date

### Inspector's Comments

HA Number:	Inspector Comments:
01	
02	
03	
04	
05	
06	
06A	
07	
08	
09	
10	
11	
11A	
12	
13	
14	
14A	
15	
15A	
16	
16A	
17	
17A	

# Chicago Public Schools

School Armstrong School Unit 22081 Building ID 2080

Address 2111 West Estes Avenue Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
18	
18A	
19	
19A	
20	
20A	
21	
22	
23	
24	
25	
26	
27	
28	
29	
30	
31	
32	
33	
34	
35	
36	
37	
38	
39	
40	
41	
42	
43	

# Chicago Public Schools

School Armstrong School Unit 22081 Building ID 2080

Address 2111 West Estes Avenue Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
44	
45	
46	
47	
48	
48 A	
49	
50	
51	
51A	
52	
53	
54	
55	
55A	
56	
57	
58	
59	
60	
61	
62	
63	
63A	
J	
M	

# Chicago Public Schools

**School** Armstrong School **Unit** 22081 **Building ID** 2080

**Address** 2111 West Estes Avenue **Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

*Inspector's Comments are Summarized at the End of the Report*

---

**Table II**

**Management Planner's Review**

---

# Chicago Public Schools

**School** Armstrong School  
**Address** 2111 West Estes Avenue

**Unit** 22081  
 Chicago, IL, 60645

**Building ID** 2080  
**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575

Fax:

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
01	9"x9" Green VFT	80	SF	Engineering Closet - 1916 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
02	12"x12" Tan VFT	160	SF	Room 211 (Adj. Rm.) - 1916 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
03	9"x9" Green VFT Mastic	80	SF	Engineering Closet - 1916 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
04	12"x12" Tan VFT Mastic	160	SF	Room 211 (Adj. Rm.) - 1916 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
05	Tan Linoleum	455	SF	Stage Area - 1916 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
06	Tan Linoleum Mastic	455	SF	Stage Area - 1916 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
06A	Hard Coat Plaster			Throughout - 1916 Bldg.	No ACBM						
07	18"x6" Dark Brown VFT	85	SF	Room 211 (Adj. Rm.) - 1916 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
08	18"x6" Dark Brown VFT Mastic	85	SF	Room 211 (Adj. Rm.) - 1916 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
09	12"x12" Brown VFT	160	SF	Room 211 (Adj. Rm.) - 1916 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
10	12"x12" Brown VFT Mastic	160	SF	Room 211 (Adj. Rm.) - 1916 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
11	12"x12" Off-White VFT Mastic (Under Carpet)	400	SF	Room 200 - 1916 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
11A	12"x12" Off-White VFT	400	SF	Room 200 - 1916 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
12	12"x12" Gray w/ White Streaks VFT	460	SF	1st Floor Girls Toilet, Auditorium Dressing Room - 1916 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
13	12"x12" Grey w/ White Streaks VFT Mastic	460	SF	1st Floor Girls Toilet, Auditorium Dressing Room - 1916 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
14	12"x12" Light Brown VFT Mastic	380	SF	Engineers Office - 1916 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
14A	12"x12" Light Brown VFT	380	SF	Engineers Office - 1916 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
15	12"x12" Peach w/ White Streaks VFT	800	SF	Rooms 99, 100, 300 - 1916 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
15A	12"x12" Peach w/ White Streaks VFT Mastic	800	SF	Rooms 99, 100, 300 - 1916 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
16	12"x12" Tan w/ Tan Streaks VFT	2,200	SF	Rooms 201, 203, & Old Principals Office, Closet & Toilet Bldg - 1916 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
16A	12"x12" Tan w/ Tan Streaks VFT Mastic	2,200	SF	Rooms 201, 203, & Old Principals Office, Closet & Toilet Bldg - 1916 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
17				Room 308 - 1916 Bldg. (This room has Hardwood Floor as of 2013 3 yr)	No ACBM	MISC					
17A				Room 308 - 1916 Bldg. (This room has Hardwood Floor)	No ACBM	MISC					
18	12"x12" Light Grey VFT	300	SF	Room 311 (Adj. Rm.) - 1916 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
18A	12"x12" Light Grey VFT Mastic	300	SF	Room 311 (Adj. Rm.) - 1916 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
19	12"x12" Green Painted VFT	75	SF	Room 105 Toilet - 1916 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Armstrong School  
**Address** 2111 West Estes Avenue

**Unit** 22081  
Chicago, IL, 60645

**Building ID** 2080  
**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575

Fax:

### Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
19A	12"x12" Green Painted VFT Mastic	75	SF	Room 105 Toilet - 1916 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
20	12"x12" Tan w/ Brown Spots VFT	1,000	SF	106 (Social Room), Engineer's Office, & Outer Office, Room 99 - 1916 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
20A	12"x12" Tan w/ Brown Spots VFT Mastic	1,000	SF	106 (Social Room), Engineer's Office, & Outer Office, Room 99 - 1916 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
21	Carpet Mastic			Rooms 101, 102, & Gym/Auditorium - 1916 Bldg.	No ACBM						
22	12"x12" Off White VFT	1,500	SF	Teachers Lounge, Multipurpose Room, Corridor - 1993 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
23	12"x12" Off White VFT Mastic	1,500	SF	Teachers Lounge, Multipurpose Room, Corridor - 1993 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
24	12"x12" Gray VFT	8	SF	Multipurpose Room, Corridor - 1993 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
25	12"x12" Gray VFT Mastic	8	SF	Multipurpose Room, Corridor - 1993 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
26	12"x12" Black VFT	1,500	SF	Teachers Lounge, Multipurpose Room, Corridor - 1993 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
27	12"x12" Black VFT Mastic	1,500	SF	Teachers Lounge, Multipurpose Room, Corridor - 1993 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
28	Vinyl Baseboards			Throughout - 1993 Bldg.	No ACBM						
29	Vinyl Baseboard Mastic			Throughout - 1993 Bldg.	No ACBM						
30	2'x2' Grooved Ceiling Tile			Teacher's Lounge, Multipurpose Room, Corridor - 1993 Bldg.	No ACBM						
31	Black w/ Dots Linoleum			Boys & Girls Toilets - 1993 Bldg.	No ACBM						
32	Black w/ Dots Linoleum Mastic			Boys & Girls Toilets - 1993 Bldg.	No ACBM						
33	Drywall			Boys & Girls Toilets - 1993 Bldg.	No ACBM						
34	Drywall Compound			Boys & Girls Toilets - 1993 Bldg.	No ACBM						
35	12"x12" Sand VFT	10,000	SF	Throughout Classrooms - 1999 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
36	12"x12" Sand VFT Mastic	10,000	SF	Throughout Classrooms - 1999 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
37	Green Linoleum			Serving Area, Lunchroom, Kitchen Corridor - 1999 Bldg.	No ACBM						
38	Green Linoleum Mastic			Serving Area, Lunchroom, Kitchen Corridor - 1999 Bldg.	No ACBM						
39	Vinyl Baseboards			Throughout - 1999 Bldg.	No ACBM						



# Chicago Public Schools

**School** Armstrong School  
**Address** 2111 West Estes Avenue

**Unit** 22081  
Chicago, IL, 60645

**Building ID** 2080  
**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575

Fax:

### Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
40	Vinyl Baseboard Mastic			Throughout - 1999 Bldg.	No ACBM						
41	Spray-On Insulation			Throughout Above Ceilings on Metal Beams - 1999 Bldg.	No ACBM						
42	Carpet Mastic			222 (Library), Faculty Room, Main Office Area - 1999 Bldg.	No ACBM						
43	Drywall			Throughout - 1999 Bldg.	No ACBM						
44	Drywall Compound			Throughout - 1999 Bldg.	No ACBM						
45	2'x4' Grooved Ceiling Tile			Throughout - 1999 Bldg.	No ACBM						
46	2'x4' Smooth White Ceiling Tile			Serving Area, Kitchen, Kitchen JC, Kitchen Toilet, Kitchen Storage, Kitchen Office, Dishwash - 1999 Bldg.	No ACBM						
47	2'x4' Ceiling Tile	8,000	SF	1st, 2nd and 3rd Fl. Classrooms & Corridors - 1916 Bldg.	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
48	12" x 12" Gray Floor tile	700	SF	Room 307	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
48 A	12" x 12" Gray Floor tile Mastic	700	SF	Room 307	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
49	Terrazzo	15,000	SF	Corridors, Stairwells, Boys & Girls toilets & faculty restrooms - 1999 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
50	Fire Doors	50	EA	Stairwells, lunchroom, between 1916 & 1999 Bldg.	Assumed	MISC	No	0	EA	6 ACBM with the potential for damage	Follow O&M Plan
51	12" x 12" Sand VFT	800	SF	Rooms 300, 200 - 1916 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
51A	12" x 12" Sand VFT Mastic	800	SF	Rooms 300, 200 - 1916 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
52	2' x 4' Tectum Ceiling Tile	3,000	SF	Assembly Hall/Gym - 1916 Bldg	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
53	Drywall System	5,000	SF	Main Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
54	Boiler Gaskets	15	LF	Boiler Room	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
55	12" x 12" Beige w/ White & Brown Streaks VFT	400	SF	Auditorium Changing Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
55A	12" x 12" Beige w/ White & Brown Streaks VFT Mastic	400	SF	Auditorium Changing Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
56	2' x 4' Smooth Ceiling Tile	500	SF	Kitchen, Serving Area & Dishwashing Room	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
57	2' x 4' Fissured w/ 1" Dividing Line Ceiling Tile	800	SF	Room 310 & Hall, Room 210 & Hall	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
58	Red Fire Stop Sealant	100	EA	Throughout Building	Assumed	MISC	No	0	EA	6 ACBM with the potential for damage	Follow O&M Plan
59	Gray Sealant	2,000	LF	on Ducts above ceilings, Penthouse Mechanical Room - 1999 Bldg	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
60	Sink Undercoating	12	SF	Corridor by Room 103	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Armstrong School  
**Address** 2111 West Estes Avenue

**Unit** 22081  
 Chicago, IL, 60645

**Building ID** 2080  
**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575

Fax:

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
61	Vinyl Baseboard Mastic	300	LF	Room 310 & Hall; Room 210 & Hall	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
62	Drywall System	300	SF	Room 310 & Hall; Room 210 & Hall	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
63	Gray Linoleum	3,000	SF	Lunchroom, Serving Area Hallway	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
63A	Gray Linoleum Mastic	3,000	SF	Lunchroom, Serving Area Hallway	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
J	MJP E/F/V on Fiberglass Pipe Insulation	120	FITTING	Boiler Room, 2nd & 3rd FI Girls Toilets, Engine Room, & Fan Area - 1916 Bldg.	Chrysotile	TSI	Yes	0	FITTING	6 ACBM with the potential for damage	Follow O&M Plan
M	Sheet Rock	100	SF	Above 3rd Floor Ceilings - 1916 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Armstrong School  
**Address** 2111 West Estes Avenue

**Unit** 22081  
 Chicago, IL, 60645

**Building ID** 2080  
**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG-Probe Consulting, Inc.  
 2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

### *Management Planner's Comments Summarized at the End of the Report*

Review Date	11/13/2019
Manager Planner Name	Arturo Saenz
100-04019	5/15/2020
Manager IDPH License No/Expiration	

HA Number	Management Comments
01	
02	
03	
04	
05	
06	
06A	
07	
08	
09	
10	
11	
11A	
12	
13	
14	
14A	
15	
15A	
16	
16A	
17	
17A	
18	
18A	

# Chicago Public Schools

**School** Armstrong School  
**Address** 2111 West Estes Avenue

**Unit** 22081  
 Chicago, IL, 60645

**Building ID** 2080  
**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG-Probe Consulting, Inc.  
 2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
19	
19A	
20	
20A	
21	
22	
23	
24	
25	
26	
27	
28	
29	
30	
31	
32	
33	
34	
35	
36	
37	
38	
39	
40	
41	
42	

# Chicago Public Schools

**School** Armstrong School  
**Address** 2111 West Estes Avenue

**Unit** 22081  
Chicago, IL, 60645

**Building ID** 2080  
**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG-Probe Consulting, Inc.  
2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
43	
44	
45	
46	
47	
48	
48 A	
49	
50	
51	
51A	
52	
53	
54	
55	
55A	
56	
57	
58	
59	
60	
61	
62	
63	
63A	
J	

# Chicago Public Schools

**School** Armstrong School  
**Address** 2111 West Estes Avenue

**Unit** 22081  
Chicago, IL, 60645

**Building ID** 2080  
**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG-Probe Consulting, Inc.  
2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
M	

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **22081**    BUILDING ID: **2080**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Armstrong School**    INSPECTION DATE: **10/28/2019**  
ADDRESS: **2111 West Estes Avenue**    IDPH LICENSE NO: **100-11089**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **01**  
MATERIAL DESCRIPTION: **9"x9" Green VFT**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile**    FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Engineering Closet - 1916 Bldg.**

MATERIAL QUANTITY: **80**    MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **10/28/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Armstrong School** REVIEW DATE: **11/13/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **01**  
MATERIAL DESCRIPTION: **9"x9" Green VFT**  
MATERIAL LOCATION: **Engineering Closet - 1916 Bldg.**  
MATERIAL QUANTITY: **80** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/13/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Armstrong School** INSPECTION DATE: **10/28/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **02**  
MATERIAL DESCRIPTION: **12"x12" Tan VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Room 211 (Adj. Rm.) - 1916 Bldg.**  
MATERIAL QUANTITY: **160** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/28/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Armstrong School** REVIEW DATE: **11/13/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **02**  
MATERIAL DESCRIPTION: **12"x12" Tan VFT**  
MATERIAL LOCATION: **Room 211 (Adj. Rm.) - 1916 Bldg.**  
MATERIAL QUANTITY: **160** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/13/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Armstrong School** INSPECTION DATE: **10/28/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **03**  
MATERIAL DESCRIPTION: **9"x9" Green VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Engineering Closet - 1916 Bldg.**  
MATERIAL QUANTITY: **80** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/28/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Armstrong School** REVIEW DATE: **11/13/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **03**  
MATERIAL DESCRIPTION: **9"x9" Green VFT Mastic**  
MATERIAL LOCATION: **Engineering Closet - 1916 Bldg.**  
MATERIAL QUANTITY: **80** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/13/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Armstrong School** INSPECTION DATE: **10/28/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **04**  
MATERIAL DESCRIPTION: **12"x12" Tan VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 211 (Adj. Rm.) - 1916 Bldg.**  
MATERIAL QUANTITY: **160** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/28/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Armstrong School** REVIEW DATE: **11/13/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **04**  
MATERIAL DESCRIPTION: **12"x12" Tan VFT Mastic**  
MATERIAL LOCATION: **Room 211 (Adj. Rm.) - 1916 Bldg.**  
MATERIAL QUANTITY: **160** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/13/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Armstrong School** INSPECTION DATE: **10/28/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **05**  
MATERIAL DESCRIPTION: **Tan Linoleum**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Stage Area - 1916 Bldg.**  
MATERIAL QUANTITY: **455** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/28/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Armstrong School** REVIEW DATE: **11/13/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **05**  
MATERIAL DESCRIPTION: **Tan Linoleum**  
MATERIAL LOCATION: **Stage Area - 1916 Bldg.**  
MATERIAL QUANTITY: **455** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/13/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Armstrong School** INSPECTION DATE: **10/28/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **06**  
MATERIAL DESCRIPTION: **Tan Linoleum Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Stage Area - 1916 Bldg.**  
MATERIAL QUANTITY: **455** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/28/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Armstrong School** REVIEW DATE: **11/13/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **06**  
MATERIAL DESCRIPTION: **Tan Linoleum Mastic**  
MATERIAL LOCATION: **Stage Area - 1916 Bldg.**  
MATERIAL QUANTITY: **455** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/13/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **22081**    BUILDING ID: **2080**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Armstrong School**    INSPECTION DATE: **10/28/2019**  
ADDRESS: **2111 West Estes Avenue**    IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **06A**  
MATERIAL DESCRIPTION: **Hard Coat Plaster**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM**    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout - 1916 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **10/28/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Armstrong School** REVIEW DATE: **11/13/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **06A**  
MATERIAL DESCRIPTION: **Hard Coat Plaster**  
MATERIAL LOCATION: **Throughout - 1916 Bldg.**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/13/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Armstrong School** INSPECTION DATE: **10/28/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **07**  
MATERIAL DESCRIPTION: **18"x6" Dark Brown VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Room 211 (Adj. Rm.) - 1916 Bldg.**  
MATERIAL QUANTITY: **85** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/28/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Armstrong School** REVIEW DATE: **11/13/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **07**  
MATERIAL DESCRIPTION: **18"x6" Dark Brown VFT**  
MATERIAL LOCATION: **Room 211 (Adj. Rm.) - 1916 Bldg.**  
MATERIAL QUANTITY: **85** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/13/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Armstrong School** INSPECTION DATE: **10/28/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **08**  
MATERIAL DESCRIPTION: **18"x6" Dark Brown VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 211 (Adj. Rm.) - 1916 Bldg.**  
MATERIAL QUANTITY: **85** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/28/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Armstrong School** REVIEW DATE: **11/13/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **08**  
MATERIAL DESCRIPTION: **18"x6" Dark Brown VFT Mastic**  
MATERIAL LOCATION: **Room 211 (Adj. Rm.) - 1916 Bldg.**  
MATERIAL QUANTITY: **85** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/13/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Armstrong School** INSPECTION DATE: **10/28/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **09**  
MATERIAL DESCRIPTION: **12"x12" Brown VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Room 211 (Adj. Rm.) - 1916 Bldg.**  
MATERIAL QUANTITY: **160** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/28/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Armstrong School** REVIEW DATE: **11/13/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **09**  
MATERIAL DESCRIPTION: **12"x12" Brown VFT**  
MATERIAL LOCATION: **Room 211 (Adj. Rm.) - 1916 Bldg.**  
MATERIAL QUANTITY: **160** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/13/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Armstrong School** INSPECTION DATE: **10/28/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10**  
MATERIAL DESCRIPTION: **12"x12" Brown VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 211 (Adj. Rm.) - 1916 Bldg.**  
MATERIAL QUANTITY: **160** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/28/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Armstrong School** REVIEW DATE: **11/13/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **10**  
MATERIAL DESCRIPTION: **12"x12" Brown VFT Mastic**  
MATERIAL LOCATION: **Room 211 (Adj. Rm.) - 1916 Bldg.**  
MATERIAL QUANTITY: **160** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/13/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Armstrong School** INSPECTION DATE: **10/28/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11**  
MATERIAL DESCRIPTION: **12"x12" Off-White VFT Mastic (Under Carpet)**  
HISTORICAL AHERA DAMAGE CATEGORY **6**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 200 - 1916 Bldg.**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/28/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Armstrong School** REVIEW DATE: **11/13/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **11**  
MATERIAL DESCRIPTION: **12"x12" Off-White VFT Mastic (Under Carpet)**  
MATERIAL LOCATION: **Room 200 - 1916 Bldg.**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/13/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Armstrong School** INSPECTION DATE: **10/28/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11A**  
MATERIAL DESCRIPTION: **12"x12" Off-White VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 200 - 1916 Bldg.**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/28/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Armstrong School** REVIEW DATE: **11/13/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **11A**  
MATERIAL DESCRIPTION: **12"x12" Off-White VFT**  
MATERIAL LOCATION: **Room 200 - 1916 Bldg.**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/13/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Armstrong School** INSPECTION DATE: **10/28/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12**  
MATERIAL DESCRIPTION: **12"x12" Gray w/ White Streaks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **1st Floor Girls Toilet, Auditorium Dressing Room - 1916 Bldg.**  
MATERIAL QUANTITY: **460** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/28/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Armstrong School** REVIEW DATE: **11/13/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **12**  
MATERIAL DESCRIPTION: **12"x12" Gray w/ White Streaks VFT**  
MATERIAL LOCATION: **1st Floor Girls Toilet, Auditorium Dressing Room - 1916 Bldg.**  
MATERIAL QUANTITY: **460** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/13/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Armstrong School** INSPECTION DATE: **10/28/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13**  
MATERIAL DESCRIPTION: **12"x12" Grey w/ White Streaks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st Floor Girls Toilet, Auditorium Dressing Room - 1916 Bldg.**  
MATERIAL QUANTITY: **460** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/28/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Armstrong School** REVIEW DATE: **11/13/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **13**  
MATERIAL DESCRIPTION: **12"x12" Grey w/ White Streaks VFT Mastic**  
MATERIAL LOCATION: **1st Floor Girls Toilet, Auditorium Dressing Room - 1916 Bldg.**  
MATERIAL QUANTITY: **460** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/13/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Armstrong School** INSPECTION DATE: **10/28/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14**  
MATERIAL DESCRIPTION: **12"x12" Light Brown VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Engineers Office - 1916 Bldg.**  
MATERIAL QUANTITY: **380** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/28/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Armstrong School** REVIEW DATE: **11/13/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **14**  
MATERIAL DESCRIPTION: **12"x12" Light Brown VFT Mastic**  
MATERIAL LOCATION: **Engineers Office - 1916 Bldg.**  
MATERIAL QUANTITY: **380** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/13/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Armstrong School** INSPECTION DATE: **10/28/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14A**  
MATERIAL DESCRIPTION: **12"x12" Light Brown VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Engineers Office - 1916 Bldg.**  
MATERIAL QUANTITY: **380** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/28/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Armstrong School** REVIEW DATE: **11/13/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **14A**  
MATERIAL DESCRIPTION: **12"x12" Light Brown VFT**  
MATERIAL LOCATION: **Engineers Office - 1916 Bldg.**  
MATERIAL QUANTITY: **380** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/13/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **22081**    BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Armstrong School**    INSPECTION DATE: **10/28/2019**  
ADDRESS: **2111 West Estes Avenue**    IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15**  
MATERIAL DESCRIPTION: **12"x12" Peach w/ White Streaks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Rooms 99, 100, 300 - 1916 Bldg.**  
MATERIAL QUANTITY: **800**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/28/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Armstrong School** REVIEW DATE: **11/13/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **15**  
MATERIAL DESCRIPTION: **12"x12" Peach w/ White Streaks VFT**  
MATERIAL LOCATION: **Rooms 99, 100, 300 - 1916 Bldg.**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/13/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Armstrong School** INSPECTION DATE: **10/28/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15A**  
MATERIAL DESCRIPTION: **12"x12" Peach w/ White Streaks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 99, 100, 300 - 1916 Bldg.**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/28/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Armstrong School** REVIEW DATE: **11/13/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **15A**  
MATERIAL DESCRIPTION: **12"x12" Peach w/ White Streaks VFT Mastic**  
MATERIAL LOCATION: **Rooms 99, 100, 300 - 1916 Bldg.**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/13/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Armstrong School** INSPECTION DATE: **10/28/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16**  
MATERIAL DESCRIPTION: **12"x12" Tan w/ Tan Streaks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Rooms 201, 203, & Old Principals Office, Closet & Toilet Bldg - 1916 Bldg.**  
MATERIAL QUANTITY: **2200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/28/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Armstrong School** REVIEW DATE: **11/13/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **16**  
MATERIAL DESCRIPTION: **12"x12" Tan w/ Tan Streaks VFT**  
MATERIAL LOCATION: **Rooms 201, 203, & Old Principals Office, Closet & Toilet Bldg - 1916 Bldg.**  
MATERIAL QUANTITY: **2200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/13/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Armstrong School** INSPECTION DATE: **10/28/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16A**  
MATERIAL DESCRIPTION: **12"x12" Tan w/ Tan Streaks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 201, 203, & Old Principals Office, Closet & Toilet Bldg - 1916 Bldg.**  
MATERIAL QUANTITY: **2200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/28/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Armstrong School** REVIEW DATE: **11/13/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **16A**  
MATERIAL DESCRIPTION: **12"x12" Tan w/ Tan Streaks VFT Mastic**  
MATERIAL LOCATION: **Rooms 201, 203, & Old Principals Office, Closet & Toilet Bldg - 1916 Bldg.**  
MATERIAL QUANTITY: **2200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/13/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Armstrong School** INSPECTION DATE: **10/28/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17**  
MATERIAL DESCRIPTION:  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Moderate**

MATERIAL LOCATION: **Room 308 - 1916 Bldg. (This room has Hardwood Floor as of 2013 3 yr)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **10/28/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Armstrong School** REVIEW DATE: **11/13/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **17**

MATERIAL DESCRIPTION:

MATERIAL LOCATION: **Room 308 - 1916 Bldg. (This room has Hardwood Floor as of 2013 3 yr)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/13/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Armstrong School** INSPECTION DATE: **10/28/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17A**  
MATERIAL DESCRIPTION:  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:  
DISTURBANCE POTENTIAL: **Moderate**  
MATERIAL LOCATION: **Room 308 - 1916 Bldg. (This room has Hardwood Floor)**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **10/28/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Armstrong School** REVIEW DATE: **11/13/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **17A**

MATERIAL DESCRIPTION:

MATERIAL LOCATION: **Room 308 - 1916 Bldg. (This room has Hardwood Floor)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: 11/13/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Armstrong School** INSPECTION DATE: **10/28/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18**  
MATERIAL DESCRIPTION: **12"x12" Light Grey VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Room 311 (Adj. Rm.) - 1916 Bldg.**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/28/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Armstrong School** REVIEW DATE: **11/13/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **18**  
MATERIAL DESCRIPTION: **12"x12" Light Grey VFT**  
MATERIAL LOCATION: **Room 311 (Adj. Rm.) - 1916 Bldg.**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/13/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Armstrong School** INSPECTION DATE: **10/28/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18A**  
MATERIAL DESCRIPTION: **12"x12" Light Grey VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 311 (Adj. Rm.) - 1916 Bldg.**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/28/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Armstrong School** REVIEW DATE: **11/13/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **18A**  
MATERIAL DESCRIPTION: **12"x12" Light Grey VFT Mastic**  
MATERIAL LOCATION: **Room 311 (Adj. Rm.) - 1916 Bldg.**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/13/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Armstrong School** INSPECTION DATE: **10/28/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19**  
MATERIAL DESCRIPTION: **12"x12" Green Painted VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Room 105 Toliet - 1916 Bldg.**  
MATERIAL QUANTITY: **75** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/28/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Armstrong School** REVIEW DATE: **11/13/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **19**  
MATERIAL DESCRIPTION: **12"x12" Green Painted VFT**  
MATERIAL LOCATION: **Room 105 Toliet - 1916 Bldg.**  
MATERIAL QUANTITY: **75** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/13/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Armstrong School** INSPECTION DATE: **10/28/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19A**  
MATERIAL DESCRIPTION: **12"x12" Green Painted VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 105 Toliet - 1916 Bldg.**  
MATERIAL QUANTITY: **75** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/28/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Armstrong School** REVIEW DATE: **11/13/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **19A**  
MATERIAL DESCRIPTION: **12"x12" Green Painted VFT Mastic**  
MATERIAL LOCATION: **Room 105 Toliet - 1916 Bldg.**  
MATERIAL QUANTITY: **75** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/13/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Armstrong School** INSPECTION DATE: **10/28/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**  
MATERIAL DESCRIPTION: **12"x12" Tan w/ Brown Spots VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **106 (Social Room), Engineer's Office, & Outer Office, Room 99 - 1916 Bldg.**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/28/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Armstrong School** REVIEW DATE: **11/13/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **20**  
MATERIAL DESCRIPTION: **12"x12" Tan w/ Brown Spots VFT**  
MATERIAL LOCATION: **106 (Social Room), Engineer's Office, & Outer Office, Room 99 - 1916 Bldg.**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/13/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Armstrong School** INSPECTION DATE: **10/28/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20A**  
MATERIAL DESCRIPTION: **12"x12" Tan w/ Brown Spots VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **106 (Social Room), Engineer's Office, & Outer Office, Room 99 - 1916 Bldg.**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/28/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Armstrong School** REVIEW DATE: **11/13/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **20A**  
MATERIAL DESCRIPTION: **12"x12" Tan w/ Brown Spots VFT Mastic**  
MATERIAL LOCATION: **106 (Social Room), Engineer's Office, & Outer Office, Room 99 - 1916 Bldg.**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/13/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Armstrong School** INSPECTION DATE: **10/28/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21**  
MATERIAL DESCRIPTION: **Carpet Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 101, 102, & Gym/Auditorium - 1916 Bldg.**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **10/28/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Armstrong School** REVIEW DATE: **11/13/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **21**

MATERIAL DESCRIPTION: **Carpet Mastic**

MATERIAL LOCATION: **Rooms 101, 102, & Gym/Auditorium - 1916 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/13/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Armstrong School** INSPECTION DATE: **10/28/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22**  
MATERIAL DESCRIPTION: **12"x12" Off White VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Teachers Lounge, Multipurpose Room, Corridor - 1993 Bldg.**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/28/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Armstrong School** REVIEW DATE: **11/13/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **22**  
MATERIAL DESCRIPTION: **12"x12" Off White VFT**  
MATERIAL LOCATION: **Teachers Lounge, Multipurpose Room, Corridor - 1993 Bldg.**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/13/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Armstrong School** INSPECTION DATE: **10/28/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23**  
MATERIAL DESCRIPTION: **12"x12" Off White VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Teachers Lounge, Multipurpose Room, Corridor - 1993 Bldg.**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/28/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Armstrong School** REVIEW DATE: **11/13/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **23**  
MATERIAL DESCRIPTION: **12"x12" Off White VFT Mastic**  
MATERIAL LOCATION: **Teachers Lounge, Multipurpose Room, Corridor - 1993 Bldg.**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/13/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Armstrong School** INSPECTION DATE: **10/28/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **24**  
MATERIAL DESCRIPTION: **12"x12" Gray VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Multipurpose Room, Corridor - 1993 Bldg.**  
MATERIAL QUANTITY: **8** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/28/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Armstrong School** REVIEW DATE: **11/13/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **24**  
MATERIAL DESCRIPTION: **12"x12" Gray VFT**  
MATERIAL LOCATION: **Multipurpose Room, Corridor - 1993 Bldg.**  
MATERIAL QUANTITY: **8** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/13/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Armstrong School** INSPECTION DATE: **10/28/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25**  
MATERIAL DESCRIPTION: **12"x12" Gray VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Multipurpose Room, Corridor - 1993 Bldg.**  
MATERIAL QUANTITY: **8** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/28/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Armstrong School** REVIEW DATE: **11/13/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **25**  
MATERIAL DESCRIPTION: **12"x12" Gray VFT Mastic**  
MATERIAL LOCATION: **Multipurpose Room, Corridor - 1993 Bldg.**  
MATERIAL QUANTITY: **8** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/13/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Armstrong School** INSPECTION DATE: **10/28/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26**  
MATERIAL DESCRIPTION: **12"x12" Black VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Teachers Lounge, Multipurpose Room, Corridor - 1993 Bldg.**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/28/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Armstrong School** REVIEW DATE: **11/13/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **26**  
MATERIAL DESCRIPTION: **12"x12" Black VFT**  
MATERIAL LOCATION: **Teachers Lounge, Multipurpose Room, Corridor - 1993 Bldg.**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/13/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Armstrong School** INSPECTION DATE: **10/28/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27**  
MATERIAL DESCRIPTION: **12"x12" Black VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Teachers Lounge, Multipurpose Room, Corridor - 1993 Bldg.**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/28/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Armstrong School** REVIEW DATE: **11/13/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **27**  
MATERIAL DESCRIPTION: **12"x12" Black VFT Mastic**  
MATERIAL LOCATION: **Teachers Lounge, Multipurpose Room, Corridor - 1993 Bldg.**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/13/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Armstrong School** INSPECTION DATE: **10/28/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28**  
MATERIAL DESCRIPTION: **Vinyl Baseboards**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout - 1993 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **10/28/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Armstrong School** REVIEW DATE: **11/13/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **28**  
MATERIAL DESCRIPTION: **Vinyl Baseboards**  
MATERIAL LOCATION: **Throughout - 1993 Bldg.**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/13/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Armstrong School** INSPECTION DATE: **10/28/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **29**  
MATERIAL DESCRIPTION: **Vinyl Baseboard Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout - 1993 Bldg.**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **10/28/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Armstrong School** REVIEW DATE: **11/13/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **29**  
MATERIAL DESCRIPTION: **Vinyl Baseboard Mastic**  
MATERIAL LOCATION: **Throughout - 1993 Bldg.**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/13/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Armstrong School** INSPECTION DATE: **10/28/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **30**  
MATERIAL DESCRIPTION: **2'x2' Grooved Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Teacher's Lounge, Multipurpose Room, Corridor - 1993 Bldg.**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **10/28/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Armstrong School** REVIEW DATE: **11/13/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **30**

MATERIAL DESCRIPTION: **2'x2' Grooved Ceiling Tile**

MATERIAL LOCATION: **Teacher's Lounge, Multipurpose Room, Corridor - 1993 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: 11/13/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Armstrong School** INSPECTION DATE: **10/28/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **31**  
MATERIAL DESCRIPTION: **Black w/ Dots Linoleum**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boys & Girls Toliets - 1993 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **10/28/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Armstrong School** REVIEW DATE: **11/13/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **31**

MATERIAL DESCRIPTION: **Black w/ Dots Linoleum**

MATERIAL LOCATION: **Boys & Girls Toliets - 1993 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/13/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Armstrong School** INSPECTION DATE: **10/28/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **32**  
MATERIAL DESCRIPTION: **Black w/ Dots Linoleum Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boys & Girls Toliets - 1993 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **10/28/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Armstrong School** REVIEW DATE: **11/13/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **32**

MATERIAL DESCRIPTION: **Black w/ Dots Linoleum Mastic**

MATERIAL LOCATION: **Boys & Girls Toliets - 1993 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/13/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Armstrong School** INSPECTION DATE: **10/28/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **33**  
MATERIAL DESCRIPTION: **Drywall**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boys & Girls Toliets - 1993 Bldg.**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **10/28/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Armstrong School** REVIEW DATE: **11/13/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **33**

MATERIAL DESCRIPTION: **Drywall**

MATERIAL LOCATION: **Boys & Girls Toliets - 1993 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/13/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Armstrong School** INSPECTION DATE: **10/28/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **34**  
MATERIAL DESCRIPTION: **Drywall Compound**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boys & Girls Toliets - 1993 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **10/28/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Armstrong School** REVIEW DATE: **11/13/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **34**

MATERIAL DESCRIPTION: **Drywall Compound**

MATERIAL LOCATION: **Boys & Girls Toliets - 1993 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/13/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Armstrong School** INSPECTION DATE: **10/28/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **35**  
MATERIAL DESCRIPTION: **12"x12" Sand VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Throughout Classrooms - 1999 Bldg.**  
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/28/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Armstrong School** REVIEW DATE: **11/13/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **35**  
MATERIAL DESCRIPTION: **12"x12" Sand VFT**  
MATERIAL LOCATION: **Throughout Classrooms - 1999 Bldg.**  
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/13/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Armstrong School** INSPECTION DATE: **10/28/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **36**  
MATERIAL DESCRIPTION: **12"x12" Sand VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout Classrooms - 1999 Bldg.**  
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/28/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Armstrong School** REVIEW DATE: **11/13/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **36**  
MATERIAL DESCRIPTION: **12"x12" Sand VFT Mastic**  
MATERIAL LOCATION: **Throughout Classrooms - 1999 Bldg.**  
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/13/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Armstrong School** INSPECTION DATE: **10/28/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37**  
MATERIAL DESCRIPTION: **Green Linoleum**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Serving Area, Lunchroom, Kitchen Corridor - 1999 Bldg.**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **10/28/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Armstrong School** REVIEW DATE: **11/13/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **37**

MATERIAL DESCRIPTION: **Green Linoleum**

MATERIAL LOCATION: **Serving Area, Lunchroom, Kitchen Corridor - 1999 Bldg.**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/13/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Armstrong School** INSPECTION DATE: **10/28/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **38**  
MATERIAL DESCRIPTION: **Green Linoleum Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Serving Area, Lunchroom, Kitchen Corridor - 1999 Bldg.**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **10/28/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Armstrong School** REVIEW DATE: **11/13/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **38**  
MATERIAL DESCRIPTION: **Green Linoleum Mastic**  
MATERIAL LOCATION: **Serving Area, Lunchroom, Kitchen Corridor - 1999 Bldg.**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/13/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Armstrong School** INSPECTION DATE: **10/28/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **39**  
MATERIAL DESCRIPTION: **Vinyl Baseboards**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout - 1999 Bldg.**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/28/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Armstrong School** REVIEW DATE: **11/13/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **39**

MATERIAL DESCRIPTION: **Vinyl Baseboards**

MATERIAL LOCATION: **Throughout - 1999 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/13/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Armstrong School** INSPECTION DATE: **10/28/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **40**  
MATERIAL DESCRIPTION: **Vinyl Baseboard Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout - 1999 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **10/28/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Armstrong School** REVIEW DATE: **11/13/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **40**  
MATERIAL DESCRIPTION: **Vinyl Baseboard Mastic**  
MATERIAL LOCATION: **Throughout - 1999 Bldg.**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: 11/13/2019



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Armstrong School** INSPECTION DATE: **10/28/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **41**  
MATERIAL DESCRIPTION: **Spray-On Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Above Ceilings on Metal Beams - 1999 Bldg.**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **10/28/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Armstrong School** REVIEW DATE: **11/13/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **41**  
MATERIAL DESCRIPTION: **Spray-On Insulation**  
MATERIAL LOCATION: **Throughout Above Ceilings on Metal Beams - 1999 Bldg.**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: 11/13/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Armstrong School** INSPECTION DATE: **10/28/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **42**  
MATERIAL DESCRIPTION: **Carpet Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **222 (Library), Faculty Room, Main Office Area - 1999 Bldg.**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **10/28/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Armstrong School** REVIEW DATE: **11/13/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **42**

MATERIAL DESCRIPTION: **Carpet Mastic**

MATERIAL LOCATION: **222 (Library), Faculty Room, Main Office Area - 1999 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/13/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Armstrong School** INSPECTION DATE: **10/28/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **43**  
MATERIAL DESCRIPTION: **Drywall**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout - 1999 Bldg.**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **10/28/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Armstrong School** REVIEW DATE: **11/13/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **43**

MATERIAL DESCRIPTION: **Drywall**

MATERIAL LOCATION: **Throughout - 1999 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/13/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Armstrong School** INSPECTION DATE: **10/28/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **44**  
MATERIAL DESCRIPTION: **Drywall Compound**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout - 1999 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **10/28/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Armstrong School** REVIEW DATE: **11/13/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **44**  
MATERIAL DESCRIPTION: **Drywall Compound**  
MATERIAL LOCATION: **Throughout - 1999 Bldg.**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/13/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Armstrong School** INSPECTION DATE: **10/28/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **45**  
MATERIAL DESCRIPTION: **2'x4' Grooved Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout - 1999 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **10/28/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Armstrong School** REVIEW DATE: **11/13/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **45**

MATERIAL DESCRIPTION: **2'x4' Grooved Ceiling Tile**

MATERIAL LOCATION: **Throughout - 1999 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/13/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Armstrong School** INSPECTION DATE: **10/28/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **46**  
MATERIAL DESCRIPTION: **2'x4' Smooth White Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Serving Area, Kitchen, Kitchen JC, Kitchen Toliet, Kitchen Storage, Kitchen Office, Dishwash - 1999 Bldg.**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/28/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Armstrong School** REVIEW DATE: **11/13/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **46**

MATERIAL DESCRIPTION: **2'x4' Smooth White Ceiling Tile**

MATERIAL LOCATION: **Serving Area, Kitchen, Kitchen JC, Kitchen Tiolet, Kitchen Storage, Kitchen Office, Dishwash - 1999 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: 11/13/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Armstrong School** INSPECTION DATE: **10/28/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **47**  
MATERIAL DESCRIPTION: **2'x4' Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st, 2nd and 3rd Fl. Classrooms & Corridors - 1916 Bldg.**  
MATERIAL QUANTITY: **8000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/28/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Armstrong School** REVIEW DATE: **11/13/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **47**  
MATERIAL DESCRIPTION: **2'x4' Ceiling Tile**  
MATERIAL LOCATION: **1st, 2nd and 3rd Fl. Classrooms & Corridors - 1916 Bldg.**  
MATERIAL QUANTITY: **8000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/13/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Armstrong School** INSPECTION DATE: **10/28/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **48**  
MATERIAL DESCRIPTION: **12" x 12" Gray Floor tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Room 307**  
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/28/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Armstrong School** REVIEW DATE: **11/13/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **48**  
MATERIAL DESCRIPTION: **12" x 12" Gray Floor tile**  
MATERIAL LOCATION: **Room 307**  
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/13/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Armstrong School** INSPECTION DATE: **10/28/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **48 A**  
MATERIAL DESCRIPTION: **12" x 12" Gray Floor tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 307**  
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/28/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Armstrong School** REVIEW DATE: **11/13/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **48 A**  
MATERIAL DESCRIPTION: **12" x 12" Gray Floor tile Mastic**  
MATERIAL LOCATION: **Room 307**  
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/13/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Armstrong School** INSPECTION DATE: **10/28/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **49**  
MATERIAL DESCRIPTION: **Terrazzo**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Corridors, Stairwells, Boys & Girls toilets & faculty restrooms - 1999 Bldg.**  
MATERIAL QUANTITY: **15000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/28/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Armstrong School** REVIEW DATE: **11/13/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **49**  
MATERIAL DESCRIPTION: **Terrazzo**  
MATERIAL LOCATION: **Corridors, Stairwells, Boys & Girls toilets & faculty restrooms - 1999 Bldg.**  
MATERIAL QUANTITY: **15000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/13/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Armstrong School** INSPECTION DATE: **10/28/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **50**  
MATERIAL DESCRIPTION: **Fire Doors**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Stairwells, lunchroom, between 1916 & 1999 Bldg.**  
MATERIAL QUANTITY: **50** MATERIAL UNITS: **EA**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/28/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Armstrong School** REVIEW DATE: **11/13/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **50**  
MATERIAL DESCRIPTION: **Fire Doors**  
MATERIAL LOCATION: **Stairwells, lunchroom, between 1916 & 1999 Bldg.**  
MATERIAL QUANTITY: **50** MATERIAL UNITS: **EA**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/13/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Armstrong School** INSPECTION DATE: **10/28/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **51**  
MATERIAL DESCRIPTION: **12" x 12" Sand VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Rooms 300, 200 - 1916 Bldg**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/28/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Armstrong School** REVIEW DATE: **11/13/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **51**  
MATERIAL DESCRIPTION: **12" x 12" Sand VFT**  
MATERIAL LOCATION: **Rooms 300, 200 - 1916 Bldg**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/13/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Armstrong School** INSPECTION DATE: **10/28/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **51A**  
MATERIAL DESCRIPTION: **12" x 12" Sand VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 300, 200 - 1916 Bldg**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/28/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Armstrong School** REVIEW DATE: **11/13/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **51A**  
MATERIAL DESCRIPTION: **12" x 12" Sand VFT Mastic**  
MATERIAL LOCATION: **Rooms 300, 200 - 1916 Bldg**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/13/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Armstrong School** INSPECTION DATE: **10/28/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **52**  
MATERIAL DESCRIPTION: **2' x 4' Tectum Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Assembly Hall/Gym - 1916 Bldg**  
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/28/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Armstrong School** REVIEW DATE: **11/13/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **52**  
MATERIAL DESCRIPTION: **2' x 4' Tectum Ceiling Tile**  
MATERIAL LOCATION: **Assembly Hall/Gym - 1916 Bldg**  
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/13/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Armstrong School** INSPECTION DATE: **10/28/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **53**  
MATERIAL DESCRIPTION: **Drywall System**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Main Building**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/28/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Armstrong School** REVIEW DATE: **11/13/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **53**  
MATERIAL DESCRIPTION: **Drywall System**  
MATERIAL LOCATION: **Main Building**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/13/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **22081**    BUILDING ID: **2080**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Armstrong School**    INSPECTION DATE: **10/28/2019**  
ADDRESS: **2111 West Estes Avenue**    IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **54**  
MATERIAL DESCRIPTION: **Boiler Gaskets**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Boiler Room**  
MATERIAL QUANTITY: **15**    MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/28/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Armstrong School** REVIEW DATE: **11/13/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **54**  
MATERIAL DESCRIPTION: **Boiler Gaskets**  
MATERIAL LOCATION: **Boiler Room**  
MATERIAL QUANTITY: **15** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/13/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Armstrong School** INSPECTION DATE: **10/28/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **J**  
MATERIAL DESCRIPTION: **MJP E/F/V on Fiberglass Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 Damaged or significantly damaged friable misc. ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Repair**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Boiler Room, 2nd & 3rd FI Girls Toilets, Engine Room, & Fan Area - 1916 Bldg.**  
MATERIAL QUANTITY: **120** MATERIAL UNITS: **FITTING**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **FITTING**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/28/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Armstrong School** REVIEW DATE: **11/13/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **J**  
MATERIAL DESCRIPTION: **MJP E/F/V on Fiberglass Pipe Insulation**  
MATERIAL LOCATION: **Boiler Room, 2nd & 3rd FI Girls Toilets, Engine Room, & Fan Area - 1916 Bldg.**  
MATERIAL QUANTITY: **120** MATERIAL UNITS: **FITTING**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **FITTING**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/13/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Armstrong School** INSPECTION DATE: **10/28/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **M**  
MATERIAL DESCRIPTION: **Sheet Rock**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Above 3rd Floor Ceilings - 1916 Bldg.**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/28/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUIDLING ID: **2080**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Armstrong School** REVIEW DATE: **11/13/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **M**  
MATERIAL DESCRIPTION: **Sheet Rock**  
MATERIAL LOCATION: **Above 3rd Floor Ceilings - 1916 Bldg.**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/13/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.

*2019 AHERA REINSPECTION*



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **22081**      BUILDING ID: **2080**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Armstrong School**      REVIEW DATE: **11/13/2019**  
ADDRESS: **2111 West Estes Avenue**      IDPH LICENSE NO: **100-11089**

HOMOGENEOUS AREA: **60**  
MATERIAL DESCRIPTION: **Sink Undercoating**  
MATERIAL LOCATION: **Corridor by Room 103**  
MATERIAL QUANTITY: **12**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **11/13/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **22081**    BUILDING ID: **2080**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Armstrong School**    INSPECTION DATE: **10/28/2019**  
ADDRESS: **2111 West Estes Avenue**    IDPH LICENSE NO: **100-11089**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **63A**  
MATERIAL DESCRIPTION: **Gray Linoleum Mastic**  
MATERIAL LOCATION: **Lunchroom, Serving Area Hallway**  
MATERIAL QUANTITY: **3000**    MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**    FRIABLE:  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**    CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**    DAMAGE REASON:  
DAMAGE QUANTITY: **0**    DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/28/2019



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **22081**    BUILDING ID: **2080**  
CITY/STATE: **Chicago, Illinois**    MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Armstrong School**    REVIEW DATE: **11/13/2019**  
ADDRESS: **2111 West Estes Avenue**    IDPH LICENSE NO: **100-11089**

HOMOGENEOUS AREA: **63A**  
MATERIAL DESCRIPTION: **Gray Linoleum Mastic**  
MATERIAL LOCATION: **Lunchroom, Serving Area Hallway**  
MATERIAL QUANTITY: **3000**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: 11/13/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **22081**    BUILDING ID: **2080**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Armstrong School**    INSPECTION DATE: **10/28/2019**  
ADDRESS: **2111 West Estes Avenue**    IDPH LICENSE NO: **100-11089**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **58**  
MATERIAL DESCRIPTION: **Red Fire Stop Sealant**  
MATERIAL LOCATION: **Throughout Building**  
MATERIAL QUANTITY: **100**    MATERIAL UNITS: **EA**  
MATERIAL CATEGORY: **MISC**    FRIABLE:  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**    CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**    DAMAGE REASON:  
DAMAGE QUANTITY: **0**    DAMAGE REASON:  
DAMAGE UNITS: **EA**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/28/2019





# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUILDING ID: **2080**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Armstrong School** REVIEW DATE: **11/13/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

HOMOGENEOUS AREA: **55A**  
MATERIAL DESCRIPTION: **12" x 12" Beige w/ White & Brown Streaks VFT Mastic**  
MATERIAL LOCATION: **Auditorium Changing Room**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **11/13/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **22081**    BUILDING ID: **2080**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Armstrong School**    INSPECTION DATE: **10/28/2019**  
ADDRESS: **2111 West Estes Avenue**    IDPH LICENSE NO: **100-11089**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **62**  
MATERIAL DESCRIPTION: **Drywall System**  
MATERIAL LOCATION: **Room 310 & Hall; Room 210 & Hall**  
MATERIAL QUANTITY: **300**    MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**    FRIABLE:  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**    CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**    DAMAGE REASON:  
DAMAGE QUANTITY: **0**    DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/28/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **22081**    BUILDING ID: **2080**  
CITY/STATE: **Chicago, Illinois**    MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Armstrong School**    REVIEW DATE: **11/13/2019**  
ADDRESS: **2111 West Estes Avenue**    IDPH LICENSE NO: **100-11089**

HOMOGENEOUS AREA: **62**  
MATERIAL DESCRIPTION: **Drywall System**  
MATERIAL LOCATION: **Room 310 & Hall; Room 210 & Hall**  
MATERIAL QUANTITY: **300**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **11/13/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **22081**    BUILDING ID: **2080**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Armstrong School**    INSPECTION DATE: **10/28/2019**  
ADDRESS: **2111 West Estes Avenue**    IDPH LICENSE NO: **100-11089**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **63**  
MATERIAL DESCRIPTION: **Gray Linoleum**  
MATERIAL LOCATION: **Lunchroom, Serving Area Hallway**  
MATERIAL QUANTITY: **3000**    MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**    FRIABLE:  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**    CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**    DAMAGE REASON:  
DAMAGE QUANTITY: **0**    DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/28/2019











# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **22081**      BUILDING ID: **2080**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Armstrong School**      REVIEW DATE: **11/13/2019**  
ADDRESS: **2111 West Estes Avenue**      IDPH LICENSE NO: **100-11089**

HOMOGENEOUS AREA: **57**  
MATERIAL DESCRIPTION: **2' x 4' Fissured w/ 1" Dividing Line Ceiling Tile**  
MATERIAL LOCATION: **Room 310 & Hall, Room 210 & Hall**  
MATERIAL QUANTITY: **800**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **11/13/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **22081**    BUILDING ID: **2080**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Armstrong School**    INSPECTION DATE: **10/28/2019**  
ADDRESS: **2111 West Estes Avenue**    IDPH LICENSE NO: **100-11089**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **59**  
MATERIAL DESCRIPTION: **Gray Sealant**  
MATERIAL LOCATION: **on Ducts above ceilings, Penthouse Mechanical Room - 1999 Bldg**  
MATERIAL QUANTITY: **2000**    MATERIAL UNITS: **LF**  
MATERIAL CATEGORY: **MISC**    FRIABLE:  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**    CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**    DAMAGE REASON:  
DAMAGE QUANTITY: **0**    DAMAGE REASON:  
DAMAGE UNITS: **LF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/28/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUILDING ID: **2080**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Armstrong School** REVIEW DATE: **11/13/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

HOMOGENEOUS AREA: **59**  
MATERIAL DESCRIPTION: **Gray Sealant**  
MATERIAL LOCATION: **on Ducts above ceilings, Penthouse Mechanical Room - 1999 Bldg**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: 11/13/2019





# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22081** BUILDING ID: **2080**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Armstrong School** REVIEW DATE: **11/13/2019**  
ADDRESS: **2111 West Estes Avenue** IDPH LICENSE NO: **100-11089**

HOMOGENEOUS AREA: **55**  
MATERIAL DESCRIPTION: **12" x 12" Beige w/ White & Brown Streaks VFT**  
MATERIAL LOCATION: **Auditorium Changing Room**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **11/13/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **22081**    BUILDING ID: **2080**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Armstrong School**    INSPECTION DATE: **10/28/2019**  
ADDRESS: **2111 West Estes Avenue**    IDPH LICENSE NO: **100-11089**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **56**  
MATERIAL DESCRIPTION: **2' x 4' Smooth Ceiling Tile**  
MATERIAL LOCATION: **Kitchen, Serving Area & Dishwashing Room**  
MATERIAL QUANTITY: **500**    MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**    FRIABLE:  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**    CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**    DAMAGE REASON:  
DAMAGE QUANTITY: **0**    DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/28/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **22081**      BUILDING ID: **2080**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Armstrong School**      REVIEW DATE: **11/13/2019**  
ADDRESS: **2111 West Estes Avenue**      IDPH LICENSE NO: **100-11089**

HOMOGENEOUS AREA: **56**  
MATERIAL DESCRIPTION: **2' x 4' Smooth Ceiling Tile**  
MATERIAL LOCATION: **Kitchen, Serving Area & Dishwashing Room**  
MATERIAL QUANTITY: **500**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **11/13/2019**

# APPENDIX B

## Inspector and Management Planner Licenses

---

# CERTIFICATE OF ACHIEVEMENT ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that PANFILO CARRAZCO  
has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the  
examination on 02/13/2016 with a minimum score of 70% or better. Training was in accordance  
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:  
Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.

02/13/2016

Course Dates:

02/13/2017

Expires:

1602BIR10

Certificate Number:



*N. Penneff*

Director of Training  
Nicholas J. Penneff  
Doctor of Public Health

Phone: 312-491-0081

FORM # A-010B



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • [www.dph.illinois.gov](http://www.dph.illinois.gov)

**PANFILO CARRAZCO**  
855 W ADAMS STREET, SUITE 200  
CHICAGO, IL 60607

4/28/2017


ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 11089

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

**COPY OF THE ASBESTOS PROFESSIONAL LICENSE**

Front of License

Back of License

		<b>ASBESTOS PROFESSIONAL LICENSE</b>		<b>ENDORSEMENTS</b>	<b>TC EXPIRES</b>
<b>ID NUMBER</b> 100 - 11089	<b>ISSUED</b> 4/28/2017	<b>EXPIRES</b> 05/15/2018		INSPECTOR	2/11/2018
<b>PANFILO CARRAZCO</b> 855 W ADAMS STREET, SUITE CHICAGO, IL 60607 Environmental Health:				PROJECT MANAGER AIR SAMPLING PROFESSIONAL	2/4/2018
				<b>Alteration of this license shall result in legal action</b> This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: [dph.illinois.gov/topics-services/environmental-health-protection/asbestos](http://dph.illinois.gov/topics-services/environmental-health-protection/asbestos)  
EMAIL Address: [dph.asbestos@illinois.gov](mailto:dph.asbestos@illinois.gov)

**PROTECTING HEALTH, IMPROVING LIVES**

*Nationally Accredited by PHAB*

# CERTIFICATE OF ACHIEVEMENT ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that PANILO CARRAZCO  
has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the  
examination on 02/09/2019 with a minimum score of 70% or better. Training was in accordance  
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:  
Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.



02/09/2019

Course Dates:

02/09/2020

Expires:

1902BIR08

Certificate Number:

Director of Training  
Nicholas J. Peneff  
Doctor of Public Health

Phone: 312-491-0081

FORM # A-010B





525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • [www.dph.illinois.gov](http://www.dph.illinois.gov)

**PANFILO CARRAZCO**  
2942 W VAN BUREN ST  
CHICAGO, IL 60612

4/19/2019

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 11089

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

**COPY OF THE ASBESTOS PROFESSIONAL LICENSE**

Front of License

Back of License

 <b>ASBESTOS PROFESSIONAL LICENSE</b>			<b>ENDORSEMENTS</b>	<b>TC EXPIRES</b>
<b>ID NUMBER</b> 100 - 11089	<b>ISSUED</b> 4/19/2019	<b>EXPIRES</b> 05/15/2020	INSPECTOR	2/9/2020
<b>PANFILO CARRAZCO</b> 2942 W VAN BUREN ST CHICAGO, IL 60612 Environmental Health			PROJECT MANAGER AIR SAMPLING PROFESSIONAL	2/2/2020
			<b>Alteration of this license shall result in legal action</b> This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: [dph.illinois.gov/topics-services/environmental-health-protection/asbestos](http://dph.illinois.gov/topics-services/environmental-health-protection/asbestos)  
EMAIL Address: [dph.asbestos@illinois.gov](mailto:dph.asbestos@illinois.gov)

**PROTECTING HEALTH, IMPROVING LIVES**  
*Nationally Accredited by PHAB*





535-535 West Jefferson Street • Springfield, Illinois 62761-0201 • [www.dph.illinois.gov](http://www.dph.illinois.gov)

4/18/2016

**PANFILO CARRAZCO**  
855 W ADAMS STREET, SUITE 200  
CHICAGO, IL 60607

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 11089

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

**COPY OF THE ASBESTOS PROFESSIONAL LICENSE**

Front of License

Back of License

ASBESTOS PROFESSIONAL LICENSE			ENDORSEMENTS	TC EXPIRES
ID NUMBER	ISSUED	EXPIRES	INSPECTOR	2/13/2017
100 - 11089	4/18/2016	05/15/2017	PROJECT MANAGER	2/6/2017
<b>PANFILO CARRAZCO</b> 855 W ADAMS STREET, SUITE CHICAGO, IL 60607 Environmental Health			AIR SAMPLING PROFESSIONAL	
			<b>Alteration of this license shall result in legal action</b> This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: [dph.illinois.gov/topics-services/environmental-health-protection/asbestos](http://dph.illinois.gov/topics-services/environmental-health-protection/asbestos)  
EMAIL Address: [dph.asbestos@illinois.gov](mailto:dph.asbestos@illinois.gov)

**PROTECTING HEALTH. IMPROVING LIVES**  
*Nationally Accredited by PHAB*

2019



**OCCUPATIONAL TRAINING & SUPPLY, INC.**

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900 ♦ www.otssafety.com

# Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

**Arturo Saenz**

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 2/28/2019

Exam Date: 2/28/2019

Expiration Date: 2/28/2020

Certificate Number: MPR1902280693

---

Kathy DeSalvo, Director



**ASBESTOS  
PROFESSIONAL  
LICENSE**

<b>ID NUMBER</b>	<b>ISSUED</b>	<b>EXPIRES</b>
100 - 04019	4/30/2019	05/15/2020

**ARTURO SAENZ**  
2942 W VAN BUREN ST  
CHICAGO, IL 60612  
Environmental Health



<b>ENDORSEMENTS</b>	<b>TC EXPIRES</b>
---------------------	-------------------

INSPECTOR	2/28/2020
MANAGEMENT PLANNER	2/28/2020

AIR SAMPLING PROFESSIONAL

**Alteration of this license shall result in legal action**  
This license issued under authority of the State of Illinois  
Department of Public Health  
This license is valid only when accompanied by a valid  
training course certificate.

# APPENDIX C

## Laboratory Accreditations

---

# APPENDIX D

## Laboratory Results

---

# APPENDIX E

## Chain of Custody Forms

---

## Three-Year Reinspection Key to Terms

	<b>CODE</b>	<b>KEY</b>
<b>MATERIAL</b>		
	ACBM	Asbestos Containing Building Materials
<b>MATERIAL CATEGORY</b>		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
<b>MATERIAL UNITS</b>		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
<b>DAMAGE TYPE</b>		
	Loc	Localized
	Dist	Distributed