

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH  
AHERA THREE YEAR REINSPECTION  
ASBESTOS ABATEMENT PROGRAM  
SCHOOL INFORMATION FORM**

**SECTION I**

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299  
SCHOOL ID NUMBER: 14-016-2990-2066  
SCHOOL NAME: Barnard School  
ADDRESS OF SCHOOL: 10354 S. Charles  
CITY: Chicago, IL, 60643

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **4/26/2016**

**If the address on this form is different than the address of the building, submit a written explanation.**

---

**SECTION II** *(Please type or print)*

**PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:**

DATE REINSPECTION COMPLETED: 10/1/2019 ENROLLMENT 288  
IDPH INSPECTOR LICENSE NUMBER: 100-11102  
IDPH LICENSED INSPECTOR NAME(Please Print): Elmer Spraggins II  
IDPH MP LICENSE NUMBER: 100-00440  
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Shawn Brown

DESIGNATED PERSON (Please Print): Robert Christlieb PHONE: (773) 553-3197



10/1/2019

*Signature of Designated Person*

*Date*

**SECTION III**

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: \_\_\_\_\_

School has been closed. Date closed: \_\_\_\_\_

School building has been demolished. Date: \_\_\_\_\_

School building is asbestos free since last reinspection: \_\_\_\_\_

**Please explain in writing why the school building is now asbestos free and include the supporting documentation.**

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

**Explain in writing if the address of the building is different than the address on this form:**

---

---

---

**THREE-YEAR REINSPECTION**

**CHICAGO SCHOOL DIST 299**

**Barnard School**

10354 S. Charles  
Chicago, IL, 60643

Unit: 22131  
Building ID: 2150

IDPH ID Number: 14-016-2990-2066

**REPORT DATE:**

Tuesday, October 01, 2019

**Prepared for:**

**Chicago Public Schools  
42 West Madison Street  
Chicago, IL 60602**

**Prepared by:**

**TEM Environmental, Inc.**

174 N. Brandon Drive

Glendale Heights, IL, 60139

Phone 630-790-0880

Fax 630-790-0882

**DO NOT REMOVE FROM SCHOOL  
REQUIRED BY FEDERAL LAW**



## **Environmental Notification to Occupants**

To: Faculty, Staff and Parents  
From: Chicago Public Schools  
Date: August 07, 2019

RE: Barnard School, Unit 22131  
10354 S. Charles  
Chicago, IL, 60643

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2019 asbestos three year re-inspection has been completed at Barnard School, following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at Barnard School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Robert Christlieb, the designated Local Education Authority's Designated Person at (773) 553-3197 .

## **Table of Contents**

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

### **APPENDICES:**

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

## SCHOOL AND INSPECTION INFORMATION

### 1. School Information

School: Barnard School Unit: 22131 Region: 06  
Address: 10354 S. Charles Chicago, IL, 60643  
IDPH ID: 14-016-2990-2066 Building ID: 2150  
Contact: Dunne, Michael Phone: 708 243 7885

### 2. Description of Facility

Original Construction: 1929 Additional Construction:  
Total Square Footage: 47741 No of Floors: 3  
Current Occupancy: 288

### 3. LEA Designated Person

Contact: Robert Christlieb Phone: (773) 553-3197  
Address: 42 West Madison Street  
Chicago, IL 60602

### 4. Managing Environmental Consultant

MEC: TEM Environmental, Inc.  
Contact: Steven Geneser  
Address 174 N. Brandon Drive  
Glendale Heights, IL, 60139  
Phone: 630-790-0880 Fax: 630-790-0882

### 5. Inspector

Inspector Name: Elmer Spraggins II

Inspector IDPH license # 100-11102

Signature:  
Date: 8/7/2019

### 6. Management Planner

Management Planner Name: Shawn Brown

Management Planner IDPH license # 100-00440

Signature:  
Date: 08/29/2019

### 7. Review Date:08/29/2019

### 8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature:



Date: 10/1/2019

Name: Robert Christlieb

## II. EXECUTIVE SUMMARY

TEM Environmental, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Barnard School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.85 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas(HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 2150:

29	2'x2' White Ceiling Tile
34	1x1 White w/Wormholes Ceiling Tile
C	Aircell Pipe Insulation
D	MJP E/F/V on Aircell Pipe Insulation

B. The following new homogenous areas have been identified for Building 2150:

08	Light Green Carpet Mastic
11	Blue Carpet Mastic



C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

01E	12x12 Dark Blue & Light Blue Floor Tile
02B	12x12 Red & Brown/Cream Floor Tile (Marble Pattern)
02C	12x12 Light Brown & Cream Floor Tile
02E	9x9 Red & Black Floor Tile
06E	12x12 Dark Blue & Light Blue Floor Tile Mastic
07A	12x12 Off-White Floor Tile Mastic
07B	12x12 Red & Brown/Cream Floor Tile Mastic (Marble Pattern)
07C	12x12 Light Brown & Cream Floor Tile Mastic
07E	9x9 Red & Black Floor Tile Mastic
08	Light Green Carpet Mastic
09	Carpet Mastic
10	12x12 Brown Floor Tile
10A	12x12 Brown, Beige & Tan Floor Tile Mastic
10B	12x12 Beige Floor Tile
10C	12x12 Tan Floor Tile
11	Blue Carpet Mastic
12	Green Carpet Mastic
13	9x9 Brown Floor Tile
14	9x9 Brown Floor Tile Mastic
15	9x9 Tan Floor Tile
16	9x9 Tan Floor Tile Mastic
17	12x12 Green Floor Tile
18	12x12 Green Floor Tile Mastic
19	Gray & White Speckled Terrazzo Flooring
20	Plaster
21	Green w/White & Black Speckles Terrazzo Flooring
22	Light Green w/Dark Green Speckles Terrazzo Flooring
23	Light Grey w/Pearl Speckles Terrazzo Flooring
24	Mint Green w/White Speckles Terrazzo Flooring
25	Tan Vibration Gasket
26	Red Vibration Gasket
27	12x18 Black Border Tile
28	12x18 Black Border Tile Mastic
29	2'x2' White Ceiling Tile
32	12x12 Tan Vinyl Floor Tile
33	12x12 Tan Vinyl Floor Tile Mastic
34	1x1 White w/Wormholes Ceiling Tile
35	1x1 White w/Wormholes Ceiling Tile Glue Pucks
36	12x12 Cream w/Gray Specks Vinyl Floor Tile

37	12x12 Cream w/Gray Specks Vinyl Floor Tile Mastic
38	12x12 Creamy Brown Specks Vinyl Floor Tile
39	12x12 Creamy Brown Specks Vinyl Floor Tile Mastic
B	MJP E/F/V on Fiberglass

The following areas were deemed to be inaccessible:

06	Tile Mastic
06B	9x9 Green Floor Tile Mastic
06D	9x9 Dark Brown & Red Floor Tile Mastic
06E	12x12 Dark Blue & Light Blue Floor Tile Mastic
07	12x12 Tan Floor Tile Mastic
07A	12x12 Off-White Floor Tile Mastic
07B	12x12 Red & Brown/Cream Floor Tile Mastic (Marble Pattern)
07C	12x12 Light Brown & Cream Floor Tile Mastic
07D	12x12 Red & Black Floor Tile Mastic
07E	9x9 Red & Black Floor Tile Mastic
10A	12x12 Brown, Beige & Tan Floor Tile Mastic
11	Blue Carpet Mastic
12	Green Carpet Mastic
14	9x9 Brown Floor Tile Mastic
16	9x9 Tan Floor Tile Mastic
18	12x12 Green Floor Tile Mastic
28	12x18 Black Border Tile Mastic
33	12x12 Tan Vinyl Floor Tile Mastic
35	1x1 White w/Wormholes Ceiling Tile Glue Pucks
37	12x12 Cream w/Gray Specks Vinyl Floor Tile Mastic
39	12x12 Creamy Brown Specks Vinyl Floor Tile Mastic
C	Aircell Pipe Insulation
D	MJP E/F/V on Aircell Pipe Insulation

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Elmer Spraggins II, IDPH License # 100-11102. The Management Plan was updated by Shawn Brown, IDPH License # 100-00440. Inspector and Management Planner Licenses are included in Appendix B.

### **III. METHODOLOGY**

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

### **IV. ABATEMENT HISTORY**

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

### **V. REASSESSMENTS AND RECOMMENDATIONS**

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

### **VI. CONCLUSIONS**

The Barnard School Building 2150 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. Atimely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

**Table I**  
**Inspector's Reinspection Findings**

---

# Chicago Public Schools

School Barnard School Unit 22131 Building ID 2150

Address 10354 S. Charles Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
01	12x12 Brown w/Tan Floor Tile ABATED 2010				ABATED	MISC								
01A	9x9 Red & Black Floor Tile ABATED			203	ABATED									
01B	9x9 Green Floor Tile	1,150	SF	Basement, Teacher's Lounge, 004, 204	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
01C	9x9 Dark & Light Green Floor Tile ABATED				ABATED									
01D	9x9 Dark Brown & Red Floor Tile	140	SF	Stair Landing Outside Gym	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
01E	12x12 Dark Blue & Light Blue Floor Tile	704	SF	105	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
02	12x12 Tan Floor Tile	2,675	SF	Basement Corridor, Pre-Kindergarten Room	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
02A	12x12 Off-White Floor Tile	800	SF	Basement Room 002	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
02B	12x12 Red & Brown/Cream Floor Tile (Marble Pattern)	671	SF	Room 400	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
02C	12x12 Light Brown & Cream Floor Tile	700	SF	Room 108	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
02D	12x12 Red & Black Floor Tile	2,378	SF	Auditorium	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
02E	9x9 Red & Black Floor Tile	350	SF	Assistant Principal's Office, 003	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
06	Tile Mastic	4,907	SF	1st and 2nd Floor Corridors & Lunchroom Office	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
06A	9x9 Red & Black Floor Tile Mastic ABATED			Room 203	ABATED									
06B	9x9 Green Floor Tile Mastic	1,150	SF	Teachers' Lounge-Basement, 004, 204	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
06C	9x9 Dark & Light Green Floor Tile Mastic ABATED			Main Office	ABATED									
06D	9x9 Dark Brown & Red Floor Tile Mastic	140	SF	Stair Landing Outside Gym	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
06E	12x12 Dark Blue & Light Blue Floor Tile Mastic	704	SF	105	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
07	12x12 Tan Floor Tile Mastic	2,756	SF	Basement Corridor, Pre-Kindergarten	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
07A	12x12 Off-White Floor Tile Mastic	800	SF	Basement- Room 002	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
07B	12x12 Red & Brown/Cream Floor Tile Mastic (Marble Pattern)	671	SF	Room 400	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
07C	12x12 Light Brown & Cream Floor Tile	700	SF	Room 108	ASSUMED	MISC	N	NONE	0		No	ACBM with the		LOW

# Chicago Public Schools

School Barnard School Unit 22131 Building ID 2150

Address 10354 S. Charles Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
	Mastic											potential for damage		
07D	12x12 Red & Black Floor Tile Mastic	2,376	SF	Auditorium	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
07E	9x9 Red & Black Floor Tile Mastic	350	SF	Assistant Principals Office, 003	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
08	Light Green Carpet Mastic			Room 208	ASSUMED	MISC			0					
09	Carpet Mastic			Room 302	ASSUMED	MISC								
10	12x12 Brown Floor Tile	100	SF	3rd Floor Warming Kitchen	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
10A	12x12 Brown, Beige & Tan Floor Tile Mastic	300	SF	3rd Floor Warming Kitchen	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
10B	12x12 Beige Floor Tile	100	SF	3rd Floor Warming Kitchen	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
10C	12x12 Tan Floor Tile	100	SF	3rd Floor Warming Kitchen	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
11	Blue Carpet Mastic	936	SF	Room 204	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
12	Green Carpet Mastic	108	SF	Principal's Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
13	9x9 Brown Floor Tile	200	SF	Engineer's Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
14	9x9 Brown Floor Tile Mastic	200	SF	Engineer's Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
15	9x9 Tan Floor Tile	200	SF	Engineer's Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
16	9x9 Tan Floor Tile Mastic	200	SF	Engineer's Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
17	12x12 Green Floor Tile	350	SF	Basement Room 001	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
18	12x12 Green Floor Tile Mastic	350	SF	Basement Room 001	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
19	Gray & White Speckled Terrazzo Flooring	1,138	SF	South Stairwell	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
20	Plaster	42,500	SF	Throughout Walls and Ceilings	ASSUMED	SURFACE	N	NONE	0		No	ACBM with the potential for damage		LOW
21	Green w/White & Black Speckles Terrazzo Flooring	2,092	SF	North Stairwell	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
22	Light Green w/Dark Green Speckles Terrazzo Flooring	460	SF	Elevator Hall	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
23	Light Grey w/Pearl Speckles Terrazzo Flooring	200	SF	Elevator Hall	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
24	Mint Green w/White Speckles Terrazzo Flooring	600	SF	North Corridor Border	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
25	Tan Vibration Gasket	4	LF	Attic	ASSUMED	MISC	N	NONE	0		No	ACBM with the		LOW

# Chicago Public Schools

School Barnard School Unit 22131 Building ID 2150

Address 10354 S. Charles Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
												potential for damage		
26	Red Vibration Gasket	4	LF	Attic	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
27	12x18 Black Border Tile	350	SF	Engineer's Office, Gym Stairs, and Auditorium	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
28	12x18 Black Border Tile Mastic	350	SF	Engineer's Office, Auditorium, and Gym Stairs	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
29	2'x2' White Ceiling Tile	200	SF	West Entrance	ASSUMED	MISC	Y	NONE	0		Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
30	12x12 Maroon Vinyl Floor Tile ABATED			1st and 2nd Floor Corridor, Lunchroom Office 211, Outside Room 400 Landing	ABATED	MISC								
31	12x12 Maroon Vinyl Floor Tile Mastic ABATED			1st and 2nd Floor Corridor, Lunchroom Office 211, Outside Room 400 Landing	ABATED	MISC								
32	12x12 Tan Vinyl Floor Tile	5,000	SF	1st and 2nd Floor Corridors, Lunchroom Office (211), Landing outside Room 400	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
33	12x12 Tan Vinyl Floor Tile Mastic	5,000	SF	1st and 2nd Floor Corridors, Lunchroom Office (211), Landing outside of Room 400	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
34	1x1 White w/Wormholes Ceiling Tile	500	SF	Room 204, Library	ASSUMED	MISC	Y	NONE	0		Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
35	1x1 White w/Wormholes Ceiling Tile Glue Pucks	500	SF	Room 204, Library	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
36	12x12 Cream w/Gray Specks Vinyl Floor Tile	1,500	SF	Room 208	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
37	12x12 Cream w/Gray Specks Vinyl Floor Tile Mastic	1,500	SF	Room 208	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
38	12x12 Creamy Brown Specks Vinyl Floor Tile	250	SF	IB Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
39	12x12 Creamy Brown Specks Vinyl Floor	250	SF	IB Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the		LOW

# Chicago Public Schools

School Barnard School Unit 22131 Building ID 2150

Address 10354 S. Charles Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
	Tile Mastic											potential for damage		
B	MJP E/F/V on Fiberglass	350	LF	Mechanical Areas, Boiler Rooms	ASSUMED	TSI	Y	LOC	10		No	Damaged or significantly damaged friable thermal system insulating ACBM	5	MODERATE
C	Aircell Pipe Insulation	450	LF	Attic	CHR	TSI	Y	NONE	0		Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
D	MJP E/F/V on Aircell Pipe Insulation	25	LF	Attic	CHR	TSI	Y	NONE	0		Yes	Any remaining friable ACBM or friable suspect ACBM		LOW



# Chicago Public Schools

School Barnard School Unit 22131 Building ID 2150

Address 10354 S. Charles Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

Reinspection Date <b>8/7/2019</b>
Inspector Name <b><u>Elmer Spraggins II</u></b>
<b><u>100-11102</u></b> <b><u>5/15/2020</u></b>
Inspector's IDPH License Number / Expiration Date

### Inspector's Comments

HA Number:	Inspector Comments:
01	
01A	
01B	
01C	
01D	
01E	
02	
02A	
02B	
02C	
02D	Auditorium wood floor
02E	Wood floor
06	
06A	
06B	
06C	
06D	
06E	
07	
07A	
07B	
07C	
07D	

# Chicago Public Schools

School Barnard School Unit 22131 Building ID 2150

Address 10354 S. Charles Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
07E	
08	Not Observed 2019
09	Not Observed 2019
10	
10A	
10B	
10C	
11	
12	
13	
14	
15	
16	
17	
18	
19	
20	
21	
22	
23	
24	
25	
26	
27	
28	
29	
30	
31	
32	

# Chicago Public Schools

School Barnard School Unit 22131 Building ID 2150

Address 10354 S. Charles Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
33	
34	
35	
36	
37	
38	
39	
B	
C	Not Accessible 2019
D	Not Accessible 2019

**Table II**

**Management Planner's Review**

---

# Chicago Public Schools

**School** Barnard School  
**Address** 10354 S. Charles

**Unit** 22131  
Chicago, IL, 60643

**Building ID** 2150  
**Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

### Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
01	12x12 Brown w/Tan Floor Tile ABATED 2010				Abated	MISC					
01A	9x9 Red & Black Floor Tile ABATED			203	Abated						
01B	9x9 Green Floor Tile	1,150	SF	Basement, Teacher's Lounge, 004, 204	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
01C	9x9 Dark & Light Green Floor Tile ABATED				Abated						
01D	9x9 Dark Brown & Red Floor Tile	140	SF	Stair Landing Outside Gym	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
01E	12x12 Dark Blue & Light Blue Floor Tile	704	SF	105	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
02	12x12 Tan Floor Tile	2,675	SF	Basement Corridor, Pre-Kindergarten Room	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
02A	12x12 Off-White Floor Tile	800	SF	Basement Room 002	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
02B	12x12 Red & Brown/Cream Floor Tile (Marble Pattern)	671	SF	Room 400	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
02C	12x12 Light Brown & Cream Floor Tile	700	SF	Room 108	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
02D	12x12 Red & Black Floor Tile	2,378	SF	Auditorium	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
02E	9x9 Red & Black Floor Tile	350	SF	Assistant Principal's Office, 003	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
06	Tile Mastic	4,907	SF	1st and 2nd Floor Corridors & Lunchroom Office	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
06A	9x9 Red & Black Floor Tile Mastic ABATED			Room 203	Abated						
06B	9x9 Green Floor Tile Mastic	1,150	SF	Teachers' Lounge- Basement, 004, 204	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
06C	9x9 Dark & Light Green Floor Tile Mastic ABATED			Main Office	Abated						
06D	9x9 Dark Brown & Red Floor Tile Mastic	140	SF	Stair Landing Outside Gym	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
06E	12x12 Dark Blue & Light Blue Floor Tile Mastic	704	SF	105	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
07	12x12 Tan Floor Tile Mastic	2,756	SF	Basement Corridor, Pre-Kindergarten	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
07A	12x12 Off-White Floor Tile Mastic	800	SF	Basement- Room 002	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
07B	12x12 Red & Brown/Cream Floor Tile Mastic (Marble Pattern)	671	SF	Room 400	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
07C	12x12 Light Brown & Cream Floor Tile Mastic	700	SF	Room 108	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
07D	12x12 Red & Black Floor Tile Mastic	2,376	SF	Auditorium	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
07E	9x9 Red & Black Floor Tile Mastic	350	SF	Assistant Principals Office, 003	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
08	Light Green Carpet Mastic			Room 208	Assumed	MISC		0			
09	Carpet Mastic			Room 302	Assumed	MISC					
10	12x12 Brown Floor Tile	100	SF	3rd Floor Warming Kitchen	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
10A	12x12 Brown, Beige & Tan Floor Tile Mastic	300	SF	3rd Floor Warming Kitchen	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
10B	12x12 Beige Floor Tile	100	SF	3rd Floor Warming Kitchen	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

School Barnard School

Unit 22131

Building ID 2150

Address 10354 S. Charles

Chicago, IL, 60643

Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

### Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
10C	12x12 Tan Floor Tile	100	SF	3rd Floor Warming Kitchen	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
11	Blue Carpet Mastic	936	SF	Room 204	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
12	Green Carpet Mastic	108	SF	Principal's Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
13	9x9 Brown Floor Tile	200	SF	Engineer's Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
14	9x9 Brown Floor Tile Mastic	200	SF	Engineer's Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
15	9x9 Tan Floor Tile	200	SF	Engineer's Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
16	9x9 Tan Floor Tile Mastic	200	SF	Engineer's Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
17	12x12 Green Floor Tile	350	SF	Basement Room 001	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
18	12x12 Green Floor Tile Mastic	350	SF	Basement Room 001	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
19	Gray & White Speckled Terrazzo Flooring	1,138	SF	South Stairwell	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
20	Plaster	42,500	SF	Throughout Walls and Ceilings	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
21	Green w/White & Black Speckles Terrazzo Flooring	2,092	SF	North Stairwell	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
22	Light Green w/Dark Green Speckles Terrazzo Flooring	460	SF	Elevator Hall	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
23	Light Grey w/Pearl Speckles Terrazzo Flooring	200	SF	Elevator Hall	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
24	Mint Green w/White Speckles Terrazzo Flooring	600	SF	North Corridor Border	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
25	Tan Vibration Gasket	4	LF	Attic	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
26	Red Vibration Gasket	4	LF	Attic	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
27	12x18 Black Border Tile	350	SF	Engineer's Office, Gym Stairs, and Auditorium	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
28	12x18 Black Border Tile Mastic	350	SF	Engineer's Office, Auditorium, and Gym Stairs	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
29	2'x2' White Ceiling Tile	200	SF	West Entrance	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
30	12x12 Maroon Vinyl Floor Tile ABATED			1st and 2nd Floor Corridor, Lunchroom Office 211, Outside Room 400 Landing	Abated	MISC					
31	12x12 Maroon Vinyl Floor Tile Mastic ABATED			1st and 2nd Floor Corridor, Lunchroom Office 211, Outside Room 400 Landing	Abated	MISC					
32	12x12 Tan Vinyl Floor Tile	5,000	SF	1st and 2nd Floor Corridors, Lunchroom Office (211), Landing outside Room 400	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
33	12x12 Tan Vinyl Floor Tile Mastic	5,000	SF	1st and 2nd Floor Corridors, Lunchroom Office (211), Landing	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Barnard School  
**Address** 10354 S. Charles

**Unit** 22131  
 Chicago, IL, 60643

**Building ID** 2150  
**Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				outside of Room 400							
34	1x1 White w/Wormholes Ceiling Tile	500	SF	Room 204, Library	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
35	1x1 White w/Wormholes Ceiling Tile Glue Pucks	500	SF	Room 204, Library	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
36	12x12 Cream w/Gray Specks Vinyl Floor Tile	1,500	SF	Room 208	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
37	12x12 Cream w/Gray Specks Vinyl Floor Tile Mastic	1,500	SF	Room 208	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
38	12x12 Creamy Brown Specks Vinyl Floor Tile	250	SF	IB Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
39	12x12 Creamy Brown Specks Vinyl Floor Tile Mastic	250	SF	IB Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
B	MJP E/F/V on Fiberglass	350	LF	Mechanical Areas, Boiler Rooms	Assumed	TSI	Yes	10	LF	1 Damaged or significantly damaged friable thermal system insulating ACBM	Repair
C	Aircell Pipe Insulation	450	LF	Attic	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
D	MJP E/F/V on Aircell Pipe Insulation	25	LF	Attic	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan

# Chicago Public Schools

**School** Barnard School  
**Address** 10354 S. Charles

**Unit** 22131  
 Chicago, IL, 60643

**Building ID** 2150  
**Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

*Management Planner's Comments Summarized at the End of the Report*

Review Date	08/29/2019
Manager Planner Name	Shawn Brown
100-00440	5/15/2020
Manager IDPH License No/Expiration	

HA Number	Management Comments
01	
01A	
01B	
01C	
01D	
01E	
02	
02A	
02B	
02C	
02D	
02E	
06	
06A	
06B	
06C	
06D	
06E	
07	



# Chicago Public Schools

**School** Barnard School  
**Address** 10354 S. Charles

**Unit** 22131  
Chicago, IL, 60643

**Building ID** 2150  
**Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
07A	
07B	
07C	
07D	
07E	
08	
09	
10	
10A	
10B	
10C	
11	
12	
13	
14	
15	
16	
17	
18	
19	
20	
21	
22	
23	
24	
25	

# Chicago Public Schools

**School** Barnard School  
**Address** 10354 S. Charles

**Unit** 22131  
Chicago, IL, 60643

**Building ID** 2150  
**Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
26	
27	
28	
29	
30	
31	
32	
33	
34	
35	
36	
37	
38	
39	
B	
C	
D	

# Chicago Public Schools

TEM Environmental, Inc.

## 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22131** BUIDLING ID: **2150**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Barnard School** INSPECTION DATE: **8/7/2019**  
ADDRESS: **10354 S. Charles** IDPH LICENSE NO: **100-11102**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **01**  
MATERIAL DESCRIPTION: **12x12 Brown w/Tan Floor Tile ABATED 2010**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION:

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **08/07/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22131** BUIDLING ID: **2150**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Barnard School** REVIEW DATE: **8/29/2019**  
ADDRESS: **10354 S. Charles** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **01**

MATERIAL DESCRIPTION: **12x12 Brown w/Tan Floor Tile ABATED 2010**

MATERIAL LOCATION:

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **08/29/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22131** BUIDLING ID: **2150**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Barnard School** INSPECTION DATE: **8/7/2019**  
ADDRESS: **10354 S. Charles** IDPH LICENSE NO: **100-11102**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **01A**  
MATERIAL DESCRIPTION: **9x9 Red & Black Floor Tile ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **203**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **08/07/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22131** BUIDLING ID: **2150**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Barnard School** REVIEW DATE: **8/29/2019**  
ADDRESS: **10354 S. Charles** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **01A**

MATERIAL DESCRIPTION: **9x9 Red & Black Floor Tile ABATED**

MATERIAL LOCATION: **203**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **08/29/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22131** BUIDLING ID: **2150**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Barnard School** INSPECTION DATE: **8/7/2019**  
ADDRESS: **10354 S. Charles** IDPH LICENSE NO: **100-11102**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **01B**  
MATERIAL DESCRIPTION: **9x9 Green Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Basement, Teacher's Lounge, 004, 204**  
MATERIAL QUANTITY: **1150** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/07/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22131** BUIDLING ID: **2150**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Barnard School** REVIEW DATE: **8/29/2019**  
ADDRESS: **10354 S. Charles** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **01B**  
MATERIAL DESCRIPTION: **9x9 Green Floor Tile**  
MATERIAL LOCATION: **Basement, Teacher's Lounge, 004, 204**  
MATERIAL QUANTITY: **1150** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **08/29/2019**



# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22131** BUIDLING ID: **2150**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Barnard School** INSPECTION DATE: **8/7/2019**  
ADDRESS: **10354 S. Charles** IDPH LICENSE NO: **100-11102**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **01C**  
MATERIAL DESCRIPTION: **9x9 Dark & Light Green Floor Tile ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION:

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **08/07/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22131** BUIDLING ID: **2150**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Barnard School** REVIEW DATE: **8/29/2019**  
ADDRESS: **10354 S. Charles** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **01C**

MATERIAL DESCRIPTION: **9x9 Dark & Light Green Floor Tile ABATED**

MATERIAL LOCATION:

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **08/29/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22131** BUIDLING ID: **2150**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Barnard School** INSPECTION DATE: **8/7/2019**  
ADDRESS: **10354 S. Charles** IDPH LICENSE NO: **100-11102**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **01D**  
MATERIAL DESCRIPTION: **9x9 Dark Brown & Red Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Stair Landing Outside Gym**  
MATERIAL QUANTITY: **140** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **08/07/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22131** BUIDLING ID: **2150**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Barnard School** REVIEW DATE: **8/29/2019**  
ADDRESS: **10354 S. Charles** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **01D**  
MATERIAL DESCRIPTION: **9x9 Dark Brown & Red Floor Tile**  
MATERIAL LOCATION: **Stair Landing Outside Gym**  
MATERIAL QUANTITY: **140** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **08/29/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22131** BUIDLING ID: **2150**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Barnard School** INSPECTION DATE: **8/7/2019**  
ADDRESS: **10354 S. Charles** IDPH LICENSE NO: **100-11102**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **01E**  
MATERIAL DESCRIPTION: **12x12 Dark Blue & Light Blue Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **105**  
MATERIAL QUANTITY: **704** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/07/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22131** BUILDING ID: **2150**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Barnard School** REVIEW DATE: **8/29/2019**  
ADDRESS: **10354 S. Charles** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **01E**  
MATERIAL DESCRIPTION: **12x12 Dark Blue & Light Blue Floor Tile**  
MATERIAL LOCATION: **105**  
MATERIAL QUANTITY: **704** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **08/29/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22131** BUIDLING ID: **2150**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Barnard School** INSPECTION DATE: **8/7/2019**  
ADDRESS: **10354 S. Charles** IDPH LICENSE NO: **100-11102**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **02**  
MATERIAL DESCRIPTION: **12x12 Tan Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Basement Corridor, Pre-Kindergarten Room**  
MATERIAL QUANTITY: **2675** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/07/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22131** BUIDLING ID: **2150**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Barnard School** REVIEW DATE: **8/29/2019**  
ADDRESS: **10354 S. Charles** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **02**  
MATERIAL DESCRIPTION: **12x12 Tan Floor Tile**  
MATERIAL LOCATION: **Basement Corridor, Pre-Kindergarten Room**  
MATERIAL QUANTITY: **2675** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **08/29/2019**



# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22131** BUIDLING ID: **2150**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Barnard School** INSPECTION DATE: **8/7/2019**  
ADDRESS: **10354 S. Charles** IDPH LICENSE NO: **100-11102**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **02A**  
MATERIAL DESCRIPTION: **12x12 Off-White Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Basement Room 002**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/07/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22131** BUIDLING ID: **2150**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Barnard School** REVIEW DATE: **8/29/2019**  
ADDRESS: **10354 S. Charles** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **02A**  
MATERIAL DESCRIPTION: **12x12 Off-White Floor Tile**  
MATERIAL LOCATION: **Basement Room 002**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **08/29/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22131** BUIDLING ID: **2150**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Barnard School** INSPECTION DATE: **8/7/2019**  
ADDRESS: **10354 S. Charles** IDPH LICENSE NO: **100-11102**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **02B**  
MATERIAL DESCRIPTION: **12x12 Red & Brown/Cream Floor Tile (Marble Pattern)**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 400**  
MATERIAL QUANTITY: **671** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **08/07/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22131** BUIDLING ID: **2150**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Barnard School** REVIEW DATE: **8/29/2019**  
ADDRESS: **10354 S. Charles** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **02B**  
MATERIAL DESCRIPTION: **12x12 Red & Brown/Cream Floor Tile (Marble Pattern)**  
MATERIAL LOCATION: **Room 400**  
MATERIAL QUANTITY: **671** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **08/29/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **22131**    BUIDLING ID: **2150**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Barnard School**    INSPECTION DATE: **8/7/2019**  
ADDRESS: **10354 S. Charles**    IDPH LICENSE NO: **100-11102**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **02C**  
MATERIAL DESCRIPTION: **12x12 Light Brown & Cream Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 108**  
MATERIAL QUANTITY: **700**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **08/07/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22131** BUIDLING ID: **2150**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Barnard School** REVIEW DATE: **8/29/2019**  
ADDRESS: **10354 S. Charles** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **02C**  
MATERIAL DESCRIPTION: **12x12 Light Brown & Cream Floor Tile**  
MATERIAL LOCATION: **Room 108**  
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **08/29/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **22131**    BUILDING ID: **2150**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Barnard School**    INSPECTION DATE: **8/7/2019**  
ADDRESS: **10354 S. Charles**    IDPH LICENSE NO: **100-11102**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **02D**  
MATERIAL DESCRIPTION: **12x12 Red & Black Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile**    FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Auditorium**  
MATERIAL QUANTITY: **2378**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**  
COMMENTS: **Auditorium wood floor**

Inspector's Signature: \_\_\_\_\_ Date: 08/07/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22131** BUIDLING ID: **2150**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Barnard School** REVIEW DATE: **8/29/2019**  
ADDRESS: **10354 S. Charles** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **02D**  
MATERIAL DESCRIPTION: **12x12 Red & Black Floor Tile**  
MATERIAL LOCATION: **Auditorium**  
MATERIAL QUANTITY: **2378** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **08/29/2019**



# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22131** BUIDLING ID: **2150**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Barnard School** INSPECTION DATE: **8/7/2019**  
ADDRESS: **10354 S. Charles** IDPH LICENSE NO: **100-11102**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **02E**  
MATERIAL DESCRIPTION: **9x9 Red & Black Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Asstistant Principal's Office, 003**  
MATERIAL QUANTITY: **350** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**  
COMMENTS: **Wood floor**

Inspector's Signature: \_\_\_\_\_ Date: **08/07/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22131** BUIDLING ID: **2150**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Barnard School** REVIEW DATE: **8/29/2019**  
ADDRESS: **10354 S. Charles** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **02E**  
MATERIAL DESCRIPTION: **9x9 Red & Black Floor Tile**  
MATERIAL LOCATION: **Asstistant Principal's Office, 003**  
MATERIAL QUANTITY: **350** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **08/29/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22131** BUIDLING ID: **2150**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Barnard School** INSPECTION DATE: **8/7/2019**  
ADDRESS: **10354 S. Charles** IDPH LICENSE NO: **100-11102**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **06**  
MATERIAL DESCRIPTION: **Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st and 2nd Floor Corridors & Lunchroom Office**  
MATERIAL QUANTITY: **4907** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **08/07/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22131** BUIDLING ID: **2150**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Barnard School** REVIEW DATE: **8/29/2019**  
ADDRESS: **10354 S. Charles** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **06**  
MATERIAL DESCRIPTION: **Tile Mastic**  
MATERIAL LOCATION: **1st and 2nd Floor Corridors & Lunchroom Office**  
MATERIAL QUANTITY: **4907** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **08/29/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22131** BUIDLING ID: **2150**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Barnard School** INSPECTION DATE: **8/7/2019**  
ADDRESS: **10354 S. Charles** IDPH LICENSE NO: **100-11102**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **06A**  
MATERIAL DESCRIPTION: **9x9 Red & Black Floor Tile Mastic ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 203**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **08/07/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22131** BUIDLING ID: **2150**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Barnard School** REVIEW DATE: **8/29/2019**  
ADDRESS: **10354 S. Charles** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **06A**

MATERIAL DESCRIPTION: **9x9 Red & Black Floor Tile Mastic ABATED**

MATERIAL LOCATION: **Room 203**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **08/29/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22131** BUIDLING ID: **2150**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Barnard School** INSPECTION DATE: **8/7/2019**  
ADDRESS: **10354 S. Charles** IDPH LICENSE NO: **100-11102**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **06B**  
MATERIAL DESCRIPTION: **9x9 Green Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Teachers' Lounge- Basement, 004, 204**  
MATERIAL QUANTITY: **1150** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/07/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22131** BUILDING ID: **2150**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Barnard School** REVIEW DATE: **8/29/2019**  
ADDRESS: **10354 S. Charles** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **06B**  
MATERIAL DESCRIPTION: **9x9 Green Floor Tile Mastic**  
MATERIAL LOCATION: **Teachers' Lounge- Basement, 004, 204**  
MATERIAL QUANTITY: **1150** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **08/29/2019**



# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22131** BUIDLING ID: **2150**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Barnard School** INSPECTION DATE: **8/7/2019**  
ADDRESS: **10354 S. Charles** IDPH LICENSE NO: **100-11102**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **06C**  
MATERIAL DESCRIPTION: **9x9 Dark & Light Green Floor Tile Mastic ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Main Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **08/07/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22131** BUIDLING ID: **2150**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Barnard School** REVIEW DATE: **8/29/2019**  
ADDRESS: **10354 S. Charles** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **06C**

MATERIAL DESCRIPTION: **9x9 Dark & Light Green Floor Tile Mastic ABATED**

MATERIAL LOCATION: **Main Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **08/29/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22131** BUIDLING ID: **2150**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Barnard School** INSPECTION DATE: **8/7/2019**  
ADDRESS: **10354 S. Charles** IDPH LICENSE NO: **100-11102**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **06D**  
MATERIAL DESCRIPTION: **9x9 Dark Brown & Red Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Stair Landing Outside Gym**  
MATERIAL QUANTITY: **140** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/07/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22131** BUIDLING ID: **2150**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Barnard School** REVIEW DATE: **8/29/2019**  
ADDRESS: **10354 S. Charles** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **06D**  
MATERIAL DESCRIPTION: **9x9 Dark Brown & Red Floor Tile Mastic**  
MATERIAL LOCATION: **Stair Landing Outside Gym**  
MATERIAL QUANTITY: **140** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **08/29/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22131** BUIDLING ID: **2150**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Barnard School** INSPECTION DATE: **8/7/2019**  
ADDRESS: **10354 S. Charles** IDPH LICENSE NO: **100-11102**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **06E**  
MATERIAL DESCRIPTION: **12x12 Dark Blue & Light Blue Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **105**  
MATERIAL QUANTITY: **704** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **08/07/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22131** BUIDLING ID: **2150**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Barnard School** REVIEW DATE: **8/29/2019**  
ADDRESS: **10354 S. Charles** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **06E**  
MATERIAL DESCRIPTION: **12x12 Dark Blue & Light Blue Floor Tile Mastic**  
MATERIAL LOCATION: **105**  
MATERIAL QUANTITY: **704** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **08/29/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22131** BUIDLING ID: **2150**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Barnard School** INSPECTION DATE: **8/7/2019**  
ADDRESS: **10354 S. Charles** IDPH LICENSE NO: **100-11102**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **07**  
MATERIAL DESCRIPTION: **12x12 Tan Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Basement Corridor, Pre-Kindergarten**  
MATERIAL QUANTITY: **2756** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/07/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22131** BUILDING ID: **2150**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Barnard School** REVIEW DATE: **8/29/2019**  
ADDRESS: **10354 S. Charles** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **07**  
MATERIAL DESCRIPTION: **12x12 Tan Floor Tile Mastic**  
MATERIAL LOCATION: **Basement Corridor, Pre-Kindergarten**  
MATERIAL QUANTITY: **2756** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **08/29/2019**



# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22131** BUIDLING ID: **2150**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Barnard School** INSPECTION DATE: **8/7/2019**  
ADDRESS: **10354 S. Charles** IDPH LICENSE NO: **100-11102**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **07A**  
MATERIAL DESCRIPTION: **12x12 Off-White Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Basement- Room 002**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/07/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22131** BUIDLING ID: **2150**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Barnard School** REVIEW DATE: **8/29/2019**  
ADDRESS: **10354 S. Charles** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **07A**  
MATERIAL DESCRIPTION: **12x12 Off-White Floor Tile Mastic**  
MATERIAL LOCATION: **Basement- Room 002**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **08/29/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **22131**    BUILDING ID: **2150**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Barnard School**    INSPECTION DATE: **8/7/2019**  
ADDRESS: **10354 S. Charles**    IDPH LICENSE NO: **100-11102**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **07B**  
MATERIAL DESCRIPTION: **12x12 Red & Brown/Cream Floor Tile Mastic (Marble Pattern)**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 400**  
MATERIAL QUANTITY: **671**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **08/07/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22131** BUILDING ID: **2150**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Barnard School** REVIEW DATE: **8/29/2019**  
ADDRESS: **10354 S. Charles** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **07B**  
MATERIAL DESCRIPTION: **12x12 Red & Brown/Cream Floor Tile Mastic (Marble Pattern)**  
MATERIAL LOCATION: **Room 400**  
MATERIAL QUANTITY: **671** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **08/29/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22131** BUIDLING ID: **2150**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Barnard School** INSPECTION DATE: **8/7/2019**  
ADDRESS: **10354 S. Charles** IDPH LICENSE NO: **100-11102**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **07C**  
MATERIAL DESCRIPTION: **12x12 Light Brown & Cream Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 108**  
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/07/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22131** BUIDLING ID: **2150**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Barnard School** REVIEW DATE: **8/29/2019**  
ADDRESS: **10354 S. Charles** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **07C**  
MATERIAL DESCRIPTION: **12x12 Light Brown & Cream Floor Tile Mastic**  
MATERIAL LOCATION: **Room 108**  
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **08/29/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **22131**    BUIDLING ID: **2150**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Barnard School**    INSPECTION DATE: **8/7/2019**  
ADDRESS: **10354 S. Charles**    IDPH LICENSE NO: **100-11102**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **07D**  
MATERIAL DESCRIPTION: **12x12 Red & Black Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile**    FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Auditorium**  
MATERIAL QUANTITY: **2376**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/07/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22131** BUILDING ID: **2150**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Barnard School** REVIEW DATE: **8/29/2019**  
ADDRESS: **10354 S. Charles** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **07D**  
MATERIAL DESCRIPTION: **12x12 Red & Black Floor Tile Mastic**  
MATERIAL LOCATION: **Auditorium**  
MATERIAL QUANTITY: **2376** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **08/29/2019**



# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **22131**    BUILDING ID: **2150**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Barnard School**    INSPECTION DATE: **8/7/2019**  
ADDRESS: **10354 S. Charles**    IDPH LICENSE NO: **100-11102**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **07E**  
MATERIAL DESCRIPTION: **9x9 Red & Black Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Assistant Principals Office, 003**  
MATERIAL QUANTITY: **350**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **08/07/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22131** BUIDLING ID: **2150**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Barnard School** REVIEW DATE: **8/29/2019**  
ADDRESS: **10354 S. Charles** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **07E**  
MATERIAL DESCRIPTION: **9x9 Red & Black Floor Tile Mastic**  
MATERIAL LOCATION: **Assistant Principals Office, 003**  
MATERIAL QUANTITY: **350** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **08/29/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22131** BUIDLING ID: **2150**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Barnard School** INSPECTION DATE: **8/7/2019**  
ADDRESS: **10354 S. Charles** IDPH LICENSE NO: **100-11102**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **09**  
MATERIAL DESCRIPTION: **Carpet Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 302**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed 2019**

Inspector's Signature: \_\_\_\_\_ Date: **08/07/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22131** BUIDLING ID: **2150**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Barnard School** REVIEW DATE: **8/29/2019**  
ADDRESS: **10354 S. Charles** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **09**

MATERIAL DESCRIPTION: **Carpet Mastic**

MATERIAL LOCATION: **Room 302**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **08/29/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22131** BUIDLING ID: **2150**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Barnard School** INSPECTION DATE: **8/7/2019**  
ADDRESS: **10354 S. Charles** IDPH LICENSE NO: **100-11102**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10**  
MATERIAL DESCRIPTION: **12x12 Brown Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **3rd Floor Warming Kitchen**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **08/07/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22131** BUILDING ID: **2150**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Barnard School** REVIEW DATE: **8/29/2019**  
ADDRESS: **10354 S. Charles** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **10**  
MATERIAL DESCRIPTION: **12x12 Brown Floor Tile**  
MATERIAL LOCATION: **3rd Floor Warming Kitchen**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **08/29/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22131** BUIDLING ID: **2150**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Barnard School** INSPECTION DATE: **8/7/2019**  
ADDRESS: **10354 S. Charles** IDPH LICENSE NO: **100-11102**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10A**  
MATERIAL DESCRIPTION: **12x12 Brown, Beige & Tan Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **3rd Floor Warming Kitchen**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/07/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22131** BUIDLING ID: **2150**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Barnard School** REVIEW DATE: **8/29/2019**  
ADDRESS: **10354 S. Charles** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **10A**  
MATERIAL DESCRIPTION: **12x12 Brown, Beige & Tan Floor Tile Mastic**  
MATERIAL LOCATION: **3rd Floor Warming Kitchen**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **08/29/2019**



# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **22131**    BUIDLING ID: **2150**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Barnard School**    INSPECTION DATE: **8/7/2019**  
ADDRESS: **10354 S. Charles**    IDPH LICENSE NO: **100-11102**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10B**  
MATERIAL DESCRIPTION: **12x12 Beige Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **3rd Floor Warming Kitchen**  
MATERIAL QUANTITY: **100**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/07/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22131** BUIDLING ID: **2150**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Barnard School** REVIEW DATE: **8/29/2019**  
ADDRESS: **10354 S. Charles** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **10B**  
MATERIAL DESCRIPTION: **12x12 Beige Floor Tile**  
MATERIAL LOCATION: **3rd Floor Warming Kitchen**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **08/29/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22131** BUIDLING ID: **2150**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Barnard School** INSPECTION DATE: **8/7/2019**  
ADDRESS: **10354 S. Charles** IDPH LICENSE NO: **100-11102**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10C**  
MATERIAL DESCRIPTION: **12x12 Tan Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **3rd Floor Warming Kitchen**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **08/07/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22131** BUILDING ID: **2150**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Barnard School** REVIEW DATE: **8/29/2019**  
ADDRESS: **10354 S. Charles** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **10C**  
MATERIAL DESCRIPTION: **12x12 Tan Floor Tile**  
MATERIAL LOCATION: **3rd Floor Warming Kitchen**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **08/29/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22131** BUIDLING ID: **2150**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Barnard School** INSPECTION DATE: **8/7/2019**  
ADDRESS: **10354 S. Charles** IDPH LICENSE NO: **100-11102**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12**  
MATERIAL DESCRIPTION: **Green Carpet Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Principal's Office**  
MATERIAL QUANTITY: **108** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/07/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22131** BUILDING ID: **2150**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Barnard School** REVIEW DATE: **8/29/2019**  
ADDRESS: **10354 S. Charles** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **12**  
MATERIAL DESCRIPTION: **Green Carpet Mastic**  
MATERIAL LOCATION: **Principal's Office**  
MATERIAL QUANTITY: **108** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **08/29/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22131** BUIDLING ID: **2150**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Barnard School** INSPECTION DATE: **8/7/2019**  
ADDRESS: **10354 S. Charles** IDPH LICENSE NO: **100-11102**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13**  
MATERIAL DESCRIPTION: **9x9 Brown Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Engineer's Office**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **08/07/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22131** BUILDING ID: **2150**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Barnard School** REVIEW DATE: **8/29/2019**  
ADDRESS: **10354 S. Charles** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **13**  
MATERIAL DESCRIPTION: **9x9 Brown Floor Tile**  
MATERIAL LOCATION: **Engineer's Office**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **08/29/2019**



# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **22131**    BUILDING ID: **2150**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Barnard School**    INSPECTION DATE: **8/7/2019**  
ADDRESS: **10354 S. Charles**    IDPH LICENSE NO: **100-11102**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14**  
MATERIAL DESCRIPTION: **9x9 Brown Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Engineer's Office**  
MATERIAL QUANTITY: **200**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **08/07/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22131** BUILDING ID: **2150**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Barnard School** REVIEW DATE: **8/29/2019**  
ADDRESS: **10354 S. Charles** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **14**  
MATERIAL DESCRIPTION: **9x9 Brown Floor Tile Mastic**  
MATERIAL LOCATION: **Engineer's Office**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **08/29/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22131** BUIDLING ID: **2150**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Barnard School** INSPECTION DATE: **8/7/2019**  
ADDRESS: **10354 S. Charles** IDPH LICENSE NO: **100-11102**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15**  
MATERIAL DESCRIPTION: **9x9 Tan Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Engineer's Office**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **08/07/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22131** BUIDLING ID: **2150**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Barnard School** REVIEW DATE: **8/29/2019**  
ADDRESS: **10354 S. Charles** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **15**  
MATERIAL DESCRIPTION: **9x9 Tan Floor Tile**  
MATERIAL LOCATION: **Engineer's Office**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **08/29/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22131** BUIDLING ID: **2150**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Barnard School** INSPECTION DATE: **8/7/2019**  
ADDRESS: **10354 S. Charles** IDPH LICENSE NO: **100-11102**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16**  
MATERIAL DESCRIPTION: **9x9 Tan Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Engineer's Office**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/07/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22131** BUIDLING ID: **2150**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Barnard School** REVIEW DATE: **8/29/2019**  
ADDRESS: **10354 S. Charles** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **16**  
MATERIAL DESCRIPTION: **9x9 Tan Floor Tile Mastic**  
MATERIAL LOCATION: **Engineer's Office**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **08/29/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **22131**    BUIDLING ID: **2150**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Barnard School**    INSPECTION DATE: **8/7/2019**  
ADDRESS: **10354 S. Charles**    IDPH LICENSE NO: **100-11102**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17**  
MATERIAL DESCRIPTION: **12x12 Green Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Basement Room 001**  
MATERIAL QUANTITY: **350**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/07/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22131** BUIDLING ID: **2150**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Barnard School** REVIEW DATE: **8/29/2019**  
ADDRESS: **10354 S. Charles** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **17**  
MATERIAL DESCRIPTION: **12x12 Green Floor Tile**  
MATERIAL LOCATION: **Basement Room 001**  
MATERIAL QUANTITY: **350** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **08/29/2019**



# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **22131**    BUIDLING ID: **2150**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Barnard School**    INSPECTION DATE: **8/7/2019**  
ADDRESS: **10354 S. Charles**    IDPH LICENSE NO: **100-11102**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18**  
MATERIAL DESCRIPTION: **12x12 Green Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Basement Room 001**  
MATERIAL QUANTITY: **350**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/07/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22131** BUIDLING ID: **2150**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Barnard School** REVIEW DATE: **8/29/2019**  
ADDRESS: **10354 S. Charles** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **18**  
MATERIAL DESCRIPTION: **12x12 Green Floor Tile Mastic**  
MATERIAL LOCATION: **Basement Room 001**  
MATERIAL QUANTITY: **350** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **08/29/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22131** BUIDLING ID: **2150**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Barnard School** INSPECTION DATE: **8/7/2019**  
ADDRESS: **10354 S. Charles** IDPH LICENSE NO: **100-11102**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19**  
MATERIAL DESCRIPTION: **Gray & White Speckled Terrazzo Flooring**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **South Stairwell**  
MATERIAL QUANTITY: **1138** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **08/07/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22131** BUILDING ID: **2150**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Barnard School** REVIEW DATE: **8/29/2019**  
ADDRESS: **10354 S. Charles** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **19**  
MATERIAL DESCRIPTION: **Gray & White Speckled Terrazzo Flooring**  
MATERIAL LOCATION: **South Stairwell**  
MATERIAL QUANTITY: **1138** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **08/29/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22131** BUIDLING ID: **2150**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Barnard School** INSPECTION DATE: **8/7/2019**  
ADDRESS: **10354 S. Charles** IDPH LICENSE NO: **100-11102**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**  
MATERIAL DESCRIPTION: **Plaster**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout Walls and Ceilings**  
MATERIAL QUANTITY: **42500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **08/07/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22131** BUIDLING ID: **2150**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Barnard School** REVIEW DATE: **8/29/2019**  
ADDRESS: **10354 S. Charles** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **20**  
MATERIAL DESCRIPTION: **Plaster**  
MATERIAL LOCATION: **Throughout Walls and Ceilings**  
MATERIAL QUANTITY: **42500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **08/29/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22131** BUIDLING ID: **2150**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Barnard School** INSPECTION DATE: **8/7/2019**  
ADDRESS: **10354 S. Charles** IDPH LICENSE NO: **100-11102**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21**  
MATERIAL DESCRIPTION: **Green w/White & Black Speckles Terrazzo Flooring**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **North Stairwell**  
MATERIAL QUANTITY: **2092** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **08/07/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22131** BUIDLING ID: **2150**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Barnard School** REVIEW DATE: **8/29/2019**  
ADDRESS: **10354 S. Charles** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **21**  
MATERIAL DESCRIPTION: **Green w/White & Black Speckles Terrazzo Flooring**  
MATERIAL LOCATION: **North Stairwell**  
MATERIAL QUANTITY: **2092** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **08/29/2019**



# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22131** BUIDLING ID: **2150**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Barnard School** INSPECTION DATE: **8/7/2019**  
ADDRESS: **10354 S. Charles** IDPH LICENSE NO: **100-11102**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22**  
MATERIAL DESCRIPTION: **Light Green w/Dark Green Speckles Terrazzo Flooring**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Elevator Hall**  
MATERIAL QUANTITY: **460** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/07/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22131** BUIDLING ID: **2150**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Barnard School** REVIEW DATE: **8/29/2019**  
ADDRESS: **10354 S. Charles** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **22**  
MATERIAL DESCRIPTION: **Light Green w/Dark Green Speckles Terrazzo Flooring**  
MATERIAL LOCATION: **Elevator Hall**  
MATERIAL QUANTITY: **460** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **08/29/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22131** BUIDLING ID: **2150**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Barnard School** INSPECTION DATE: **8/7/2019**  
ADDRESS: **10354 S. Charles** IDPH LICENSE NO: **100-11102**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23**  
MATERIAL DESCRIPTION: **Light Grey w/Pearl Speckles Terrazzo Flooring**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Elevator Hall**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **08/07/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22131** BUILDING ID: **2150**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Barnard School** REVIEW DATE: **8/29/2019**  
ADDRESS: **10354 S. Charles** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **23**  
MATERIAL DESCRIPTION: **Light Grey w/Pearl Speckles Terrazzo Flooring**  
MATERIAL LOCATION: **Elevator Hall**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **08/29/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22131** BUIDLING ID: **2150**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Barnard School** INSPECTION DATE: **8/7/2019**  
ADDRESS: **10354 S. Charles** IDPH LICENSE NO: **100-11102**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **24**  
MATERIAL DESCRIPTION: **Mint Green w/White Speckles Terrazzo Flooring**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **North Corridor Border**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **08/07/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22131** BUIDLING ID: **2150**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Barnard School** REVIEW DATE: **8/29/2019**  
ADDRESS: **10354 S. Charles** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **24**  
MATERIAL DESCRIPTION: **Mint Green w/White Speckles Terrazzo Flooring**  
MATERIAL LOCATION: **North Corridor Border**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **08/29/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22131** BUIDLING ID: **2150**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Barnard School** INSPECTION DATE: **8/7/2019**  
ADDRESS: **10354 S. Charles** IDPH LICENSE NO: **100-11102**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25**  
MATERIAL DESCRIPTION: **Tan Vibration Gasket**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Attic**  
MATERIAL QUANTITY: **4** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/07/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22131** BUIDLING ID: **2150**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Barnard School** REVIEW DATE: **8/29/2019**  
ADDRESS: **10354 S. Charles** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **25**

MATERIAL DESCRIPTION: **Tan Vibration Gasket**

MATERIAL LOCATION: **Attic**

MATERIAL QUANTITY: **4**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **08/29/2019**



# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **22131**    BUIDLING ID: **2150**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Barnard School**    INSPECTION DATE: **8/7/2019**  
ADDRESS: **10354 S. Charles**    IDPH LICENSE NO: **100-11102**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26**  
MATERIAL DESCRIPTION: **Red Vibration Gasket**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Attic**  
MATERIAL QUANTITY: **4**    MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/07/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22131** BUIDLING ID: **2150**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Barnard School** REVIEW DATE: **8/29/2019**  
ADDRESS: **10354 S. Charles** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **26**

MATERIAL DESCRIPTION: **Red Vibration Gasket**

MATERIAL LOCATION: **Attic**

MATERIAL QUANTITY: **4**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **08/29/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22131** BUIDLING ID: **2150**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Barnard School** INSPECTION DATE: **8/7/2019**  
ADDRESS: **10354 S. Charles** IDPH LICENSE NO: **100-11102**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27**  
MATERIAL DESCRIPTION: **12x18 Black Border Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Engineer's Office, Gym Stairs, and Auditorium**  
MATERIAL QUANTITY: **350** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/07/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22131** BUILDING ID: **2150**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Barnard School** REVIEW DATE: **8/29/2019**  
ADDRESS: **10354 S. Charles** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **27**  
MATERIAL DESCRIPTION: **12x18 Black Border Tile**  
MATERIAL LOCATION: **Engineer's Office, Gym Stairs, and Auditorium**  
MATERIAL QUANTITY: **350** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **08/29/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22131** BUIDLING ID: **2150**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Barnard School** INSPECTION DATE: **8/7/2019**  
ADDRESS: **10354 S. Charles** IDPH LICENSE NO: **100-11102**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28**  
MATERIAL DESCRIPTION: **12x18 Black Border Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Engineer's Office, Auditorium, and Gym Stairs**  
MATERIAL QUANTITY: **350** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **08/07/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22131** BUILDING ID: **2150**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Barnard School** REVIEW DATE: **8/29/2019**  
ADDRESS: **10354 S. Charles** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **28**  
MATERIAL DESCRIPTION: **12x18 Black Border Tile Mastic**  
MATERIAL LOCATION: **Engineer's Office, Auditorium, and Gym Stairs**  
MATERIAL QUANTITY: **350** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **08/29/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **22131**    BUILDING ID: **2150**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Barnard School**    INSPECTION DATE: **8/7/2019**  
ADDRESS: **10354 S. Charles**    IDPH LICENSE NO: **100-11102**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **29**  
MATERIAL DESCRIPTION: **2'x2' White Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY: **7 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **West Entrance**  
MATERIAL QUANTITY: **200**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **08/07/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22131** BUIDLING ID: **2150**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Barnard School** REVIEW DATE: **8/29/2019**  
ADDRESS: **10354 S. Charles** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **29**  
MATERIAL DESCRIPTION: **2'x2' White Ceiling Tile**  
MATERIAL LOCATION: **West Entrance**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **08/29/2019**



# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22131** BUIDLING ID: **2150**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Barnard School** INSPECTION DATE: **8/7/2019**  
ADDRESS: **10354 S. Charles** IDPH LICENSE NO: **100-11102**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **30**  
MATERIAL DESCRIPTION: **12x12 Maroon Vinyl Floor Tile ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st and 2nd Floor Corridor, Lunchroom Office 211, Outside Room 400 Landing**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **08/07/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22131** BUIDLING ID: **2150**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Barnard School** REVIEW DATE: **8/29/2019**  
ADDRESS: **10354 S. Charles** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **30**  
MATERIAL DESCRIPTION: **12x12 Maroon Vinyl Floor Tile ABATED**  
MATERIAL LOCATION: **1st and 2nd Floor Corridor, Lunchroom Office 211, Outside Room 400 Landing**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **08/29/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22131** BUIDLING ID: **2150**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Barnard School** INSPECTION DATE: **8/7/2019**  
ADDRESS: **10354 S. Charles** IDPH LICENSE NO: **100-11102**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **31**  
MATERIAL DESCRIPTION: **12x12 Maroon Vinyl Floor Tile Mastic ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st and 2nd Floor Corridor, Lunchroom Office 211, Outside Room 400 Landing**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **08/07/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22131** BUIDLING ID: **2150**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Barnard School** REVIEW DATE: **8/29/2019**  
ADDRESS: **10354 S. Charles** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **31**  
MATERIAL DESCRIPTION: **12x12 Maroon Vinyl Floor Tile Mastic ABATED**  
MATERIAL LOCATION: **1st and 2nd Floor Corridor, Lunchroom Office 211, Outside Room 400 Landing**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **08/29/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22131** BUIDLING ID: **2150**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Barnard School** INSPECTION DATE: **8/7/2019**  
ADDRESS: **10354 S. Charles** IDPH LICENSE NO: **100-11102**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **32**  
MATERIAL DESCRIPTION: **12x12 Tan Vinyl Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st and 2nd Floor Corridors, Lunchroom Office (211), Landing outside Room 400**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **08/07/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22131** BUIDLING ID: **2150**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Barnard School** REVIEW DATE: **8/29/2019**  
ADDRESS: **10354 S. Charles** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **32**  
MATERIAL DESCRIPTION: **12x12 Tan Vinyl Floor Tile**  
MATERIAL LOCATION: **1st and 2nd Floor Corridors, Lunchroom Office (211), Landing outside Room 400**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **08/29/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22131** BUIDLING ID: **2150**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Barnard School** INSPECTION DATE: **8/7/2019**  
ADDRESS: **10354 S. Charles** IDPH LICENSE NO: **100-11102**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **33**  
MATERIAL DESCRIPTION: **12x12 Tan Vinyl Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st and 2nd Floor Corridors, Lunchroom Office (211), Landing outside of Room 400**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **08/07/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22131** BUIDLING ID: **2150**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Barnard School** REVIEW DATE: **8/29/2019**  
ADDRESS: **10354 S. Charles** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **33**  
MATERIAL DESCRIPTION: **12x12 Tan Vinyl Floor Tile Mastic**  
MATERIAL LOCATION: **1st and 2nd Floor Corridors, Lunchroom Office (211), Landing outside of Room 400**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **08/29/2019**



# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22131** BUIDLING ID: **2150**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Barnard School** INSPECTION DATE: **8/7/2019**  
ADDRESS: **10354 S. Charles** IDPH LICENSE NO: **100-11102**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **34**  
MATERIAL DESCRIPTION: **1x1 White w/Wormholes Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 204, Library**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **08/07/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22131** BUIDLING ID: **2150**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Barnard School** REVIEW DATE: **8/29/2019**  
ADDRESS: **10354 S. Charles** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **34**  
MATERIAL DESCRIPTION: **1x1 White w/Wormholes Ceiling Tile**  
MATERIAL LOCATION: **Room 204, Library**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **08/29/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22131** BUIDLING ID: **2150**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Barnard School** INSPECTION DATE: **8/7/2019**  
ADDRESS: **10354 S. Charles** IDPH LICENSE NO: **100-11102**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **35**  
MATERIAL DESCRIPTION: **1x1 White w/Wormholes Ceiling Tile Glue Pucks**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 204, Library**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **08/07/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22131** BUILDING ID: **2150**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Barnard School** REVIEW DATE: **8/29/2019**  
ADDRESS: **10354 S. Charles** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **35**  
MATERIAL DESCRIPTION: **1x1 White w/Wormholes Ceiling Tile Glue Pucks**  
MATERIAL LOCATION: **Room 204, Library**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **08/29/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22131** BUIDLING ID: **2150**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Barnard School** INSPECTION DATE: **8/7/2019**  
ADDRESS: **10354 S. Charles** IDPH LICENSE NO: **100-11102**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **36**  
MATERIAL DESCRIPTION: **12x12 Cream w/Gray Specks Vinyl Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 208**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **08/07/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22131** BUIDLING ID: **2150**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Barnard School** REVIEW DATE: **8/29/2019**  
ADDRESS: **10354 S. Charles** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **36**  
MATERIAL DESCRIPTION: **12x12 Cream w/Gray Specks Vinyl Floor Tile**  
MATERIAL LOCATION: **Room 208**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **08/29/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22131** BUIDLING ID: **2150**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Barnard School** INSPECTION DATE: **8/7/2019**  
ADDRESS: **10354 S. Charles** IDPH LICENSE NO: **100-11102**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37**  
MATERIAL DESCRIPTION: **12x12 Cream w/Gray Specks Vinyl Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 208**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/07/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22131** BUIDLING ID: **2150**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Barnard School** REVIEW DATE: **8/29/2019**  
ADDRESS: **10354 S. Charles** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **37**  
MATERIAL DESCRIPTION: **12x12 Cream w/Gray Specks Vinyl Floor Tile Mastic**  
MATERIAL LOCATION: **Room 208**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **08/29/2019**



# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22131** BUIDLING ID: **2150**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Barnard School** INSPECTION DATE: **8/7/2019**  
ADDRESS: **10354 S. Charles** IDPH LICENSE NO: **100-11102**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **38**  
MATERIAL DESCRIPTION: **12x12 Creamy Brown Specks Vinyl Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **IB Office**  
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **08/07/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22131** BUIDLING ID: **2150**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Barnard School** REVIEW DATE: **8/29/2019**  
ADDRESS: **10354 S. Charles** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **38**  
MATERIAL DESCRIPTION: **12x12 Creamy Brown Specks Vinyl Floor Tile**  
MATERIAL LOCATION: **IB Office**  
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **08/29/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **22131**    BUILDING ID: **2150**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Barnard School**    INSPECTION DATE: **8/7/2019**  
ADDRESS: **10354 S. Charles**    IDPH LICENSE NO: **100-11102**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **39**  
MATERIAL DESCRIPTION: **12x12 Creamy Brown Specks Vinyl Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **IB Office**  
MATERIAL QUANTITY: **250**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **08/07/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22131** BUIDLING ID: **2150**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Barnard School** REVIEW DATE: **8/29/2019**  
ADDRESS: **10354 S. Charles** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **39**  
MATERIAL DESCRIPTION: **12x12 Creamy Brown Specks Vinyl Floor Tile Mastic**  
MATERIAL LOCATION: **IB Office**  
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **08/29/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22131** BUIDLING ID: **2150**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Barnard School** INSPECTION DATE: **8/7/2019**  
ADDRESS: **10354 S. Charles** IDPH LICENSE NO: **100-11102**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **B**  
MATERIAL DESCRIPTION: **MJP E/F/V on Fiberglass**  
HISTORICAL AHERA DAMAGE CATEGORY **1 Damaged or significantly damaged friable thermal system insulating ACBM**  
HISTORICAL DAMAGE REASON: **Physical Damage Deterioration**  
HISTORICAL RESPONSE ACTION: **Repair**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON: **Physical Damage Deterioration**  
DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Mechanical Areas, Boiler Rooms**  
MATERIAL QUANTITY: **350** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **10** DAMAGE UNITS: **LF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **08/07/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22131** BUIDLING ID: **2150**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Barnard School** REVIEW DATE: **8/29/2019**  
ADDRESS: **10354 S. Charles** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **B**  
MATERIAL DESCRIPTION: **MJP E/F/V on Fiberglass**  
MATERIAL LOCATION: **Mechanical Areas, Boiler Rooms**  
MATERIAL QUANTITY: **350** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **10** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **08/29/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22131** BUIDLING ID: **2150**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Barnard School** INSPECTION DATE: **8/7/2019**  
ADDRESS: **10354 S. Charles** IDPH LICENSE NO: **100-11102**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **C**  
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Attic**  
MATERIAL QUANTITY: **450** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**  
COMMENTS: **Not Accessible 2019**

Inspector's Signature: \_\_\_\_\_ Date: **08/07/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22131** BUIDLING ID: **2150**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Barnard School** REVIEW DATE: **8/29/2019**  
ADDRESS: **10354 S. Charles** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **C**  
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**  
MATERIAL LOCATION: **Attic**  
MATERIAL QUANTITY: **450** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **08/29/2019**



# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **22131**    BUIDLING ID: **2150**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Barnard School**    INSPECTION DATE: **8/7/2019**  
ADDRESS: **10354 S. Charles**    IDPH LICENSE NO: **100-11102**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **D**  
MATERIAL DESCRIPTION: **MJP E/F/V on Aircell Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY: **7 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile**    FRIABLE: **Yes**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Attic**  
MATERIAL QUANTITY: **25**    MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **LF**  
COMMENTS: **Not Accessible 2019**

Inspector's Signature: \_\_\_\_\_ Date: **08/07/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22131** BUIDLING ID: **2150**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Barnard School** REVIEW DATE: **8/29/2019**  
ADDRESS: **10354 S. Charles** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **D**  
MATERIAL DESCRIPTION: **MJP E/F/V on Aircell Pipe Insulation**  
MATERIAL LOCATION: **Attic**  
MATERIAL QUANTITY: **25** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **08/29/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
*2019 AHERA REINSPECTION*

# Chicago Public Schools

**TEM Environmental, Inc.  
2019 AHERA REINSPECTION**

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **22131**      BUILDING ID: **2150**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Barnard School**      INSPECTION DATE: **8/7/2019**  
ADDRESS: **10354 S. Charles**      IDPH LICENSE NO: **100-11102**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **08**

MATERIAL DESCRIPTION: **Light Green Carpet Mastic**

MATERIAL LOCATION: **Room 208**

MATERIAL QUANTITY:      MATERIAL UNITS:

MATERIAL CATEGORY: **MISC**      FRIABLE:

ASBESTOS TYPE: **Assumed**

DISTURBANCE POTENTIAL:      CONDITION:

AHERA DAMAGE CATEGORY:

ACCESSIBILITY:      DAMAGE REASON:  
DAMAGE REASON:  
DAMAGE QUANTITY: **0**      DAMAGE REASON:  
DAMAGE UNITS:

COMMENTS:  
Not Observed 2019

Inspector's Signature: \_\_\_\_\_ Date: **08/07/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **22131**      BUILDING ID: **2150**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Barnard School**      REVIEW DATE: **8/29/2019**  
ADDRESS: **10354 S. Charles**      IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **08**

MATERIAL DESCRIPTION: **Light Green Carpet Mastic**

MATERIAL LOCATION: **Room 208**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY: **0**

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **08/29/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22131** BUILDING ID: **2150**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Barnard School** INSPECTION DATE: **8/7/2019**  
ADDRESS: **10354 S. Charles** IDPH LICENSE NO: **100-11102**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **11**  
MATERIAL DESCRIPTION: **Blue Carpet Mastic**  
MATERIAL LOCATION: **Room 204**  
MATERIAL QUANTITY: **936** MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC** FRIABLE:  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW** CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Not Reachable** DAMAGE REASON:  
DAMAGE QUANTITY: **0** DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/07/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **22131**      BUILDING ID: **2150**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Barnard School**      REVIEW DATE: **8/29/2019**  
ADDRESS: **10354 S. Charles**      IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **11**  
MATERIAL DESCRIPTION: **Blue Carpet Mastic**  
MATERIAL LOCATION: **Room 204**  
MATERIAL QUANTITY: **936**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **08/29/2019**

# APPENDIX B

## Inspector and Management Planner Licenses

---



# CERTIFICATE OF ACHIEVEMENT ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that ELMER SPRAGGINS II  
has completed the ASBESTOS INSPECTOR'S INITIAL course and successfully passed the  
examination on 01/30/2019 with a minimum score of 70% or better. Training was in accordance  
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:  
Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.

01/28/2019-01/30/2019

Course Dates:

01/30/2020

Expires:

1901BI06

Certificate Number:



**PUBLIC HEALTH & SAFETY** inc.

Environmental and Occupational Services  
275 Ashland Ave., Chicago, IL 60607

[www.public-health-safety.com](http://www.public-health-safety.com)

Office: 312-491-0081

Fax: 312-421-2921

Director of Training

Nicholas J. Peneff

Doctor of Public Health



Phone: 312-491-0081

FORM # A-010

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

	<b>ASBESTOS PROFESSIONAL LICENSE</b>	<b>ENDORSEMENTS</b>	<b>TC EXPIRES</b>
ID NUMBER	ISSUED	EXPIRES	
100 - 11102	4/16/2019	05/15/2020	1/30/2020
<b>ELMER SPRAGGINS II</b>		INSPECTOR	
12823 S GREEN		PROJECT MANAGER	3/29/2020
CHICAGO, IL 60643		AIR SAMPLING PROFESSIONAL	
Environmental Health		<b>Alteration of this license shall result in legal action</b> This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	

# CERTIFICATE OF ACHIEVEMENT

## ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that SHAWN L. BROWN  
has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the  
examination on 03/18/2019 with a minimum score of 70% or better. Training was in accordance  
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:  
Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.

03/18/2019

Course Dates:

03/18/2020

Expires:

1903BIR03

Certificate Number:



**PUBLIC HEALTH & SAFETY** Inc.

Environmental and Occupational Services  
37 S. Ashland Ave., Chicago, IL 60607

[www.public-health-safety.com](http://www.public-health-safety.com)

Office: 312-491-0081  
Fax: 312-421-2901

Director of Training

Nicholas J. Penelf

Doctor of Public Health

Phone: 312-491-0081

FORM # A-010B

# CERTIFICATE OF ACHIEVEMENT ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that SHAWN L. BROWN  
has completed the Asbestos Management Planner Refresher course and passed the examination  
on 03/18/2019 with a minimum score of 70% or better. Training was in accordance with U.S.  
E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools: Model  
Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.

03/18/2019

Course Dates:

03/18/2020

Expires:

1903MPR01

Certificate Number:



**PUBLIC HEALTH & SAFETY** inc.

Environmental and Occupational Services  
371 S. Ashland Ave., Chicago, IL 60607

[www.public-health-safety.com](http://www.public-health-safety.com)

Office: 312-491-0081  
Fax: 312-421-2501

Director of Training

Nicholas J. Peneff

Doctor of Public Health

Phone: 312-491-0081

FORM # A-011

# COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

	<b>ASBESTOS PROFESSIONAL LICENSE</b>	<b>ENDORSEMENTS</b>	<b>TC EXPIRES</b>	
ID NUMBER	ISSUED	EXPIRES	INSPECTOR	3/19/2019
100 - 02950	3/6/2019	05/15/2020	PROJECT MANAGER	4/9/2019
<b>KEITH CLOUGH</b>			AIR SAMPLING PROFESSIONAL	
524 HOMELAND RD			<b>Alteration of this license shall result in legal action</b> This license issued under authority of the State of Illinois Department of Public Health	
MATTESON, IL 60443			This license is valid only when accompanied by a valid training course certificate.	
Environmental Health				

# APPENDIX C

## Laboratory Accreditations

---

# APPENDIX D

## Laboratory Results

---

# APPENDIX E

## Chain of Custody Forms

---



## Three-Year Reinspection Key to Terms

	<b>CODE</b>	<b>KEY</b>
<b>MATERIAL</b>		
	ACBM	Asbestos Containing Building Materials
<b>MATERIAL CATEGORY</b>		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
<b>MATERIAL UNITS</b>		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
<b>DAMAGE TYPE</b>		
	Loc	Localized
	Dist	Distributed