

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM**

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-2775
SCHOOL NAME: Joplin School
ADDRESS OF SCHOOL: 7931 S. Honore
CITY: Chicago, IL, 60620

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **3/23/2016**

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II *(Please type or print)*

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 10/1/2019 ENROLLMENT 415
IDPH INSPECTOR LICENSE NUMBER: 100-07839
IDPH LICENSED INSPECTOR NAME(Please Print): Lisa Laney
IDPH MP LICENSE NUMBER: 100-00746
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Amy Williams

DESIGNATED PERSON (Please Print): Robert Christlieb PHONE: (773) 553-3197



10/1/2019

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Joplin School

7931 S. Honore
Chicago, IL, 60620

Unit: 22281
Building ID: 2330

IDPH ID Number: 14-016-2990-2775

REPORT DATE:

Tuesday, October 01, 2019

Prepared for:

**Chicago Public Schools
42 West Madison Street
Chicago, IL 60602**

Prepared by:

TEM Environmental, Inc.

174 N. Brandon Drive

Glendale Heights, IL, 60139

Phone 630-790-0880

Fax 630-790-0882

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

August 29, 2019

Mr. Glen E. Garner
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2019 Three-Year Reinspections

Dear Mr. Glen:

TEM Environmental, Inc. , Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 5, 6 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 22281 Region: 05 IDPH ID:14-016-2990-2775

School: Joplin School Building ID: 2330

Address: 7931 S. Honore
Chicago, IL, 60620

Building Contact: Contact Phone:

Current Building Owners: Chicago Public Schools

Review Date: 09/28/2019

Inspector: Lisa Laney Inspector IDPH License: 100-07839
Management Planner: Amy Williams Management Planner IDPH License: 100-00746

If you have any questions or comments, please contact us at 630-790-0880

Sincerely,
TEM Environmental, Inc.

Amy Williams
100-00746

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: August 29, 2019

RE: Joplin School, Unit 22281
7931 S. Honore
Chicago, IL, 60620

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2019 asbestos three year re-inspection has been completed at Joplin School, following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at Joplin School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Robert Christlieb, the designated Local Education Authority's Designated Person at (773) 553-3197 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Joplin School
Address: 7931 S. Honore
IDPH ID: 14-016-2990-2775
Contact:

Unit: 22281
Chicago, IL, 60620
Building ID: 2330
Phone:

Region: 05

2. Description of Facility

Original Construction: 1957
Total Square Footage: 77483
Current Occupancy: 415

Additional Construction:
No of Floors: 3

3. LEA Designated Person

Contact: Robert Christlieb
Address: 42 West Madison Street
Chicago, IL 60602

Phone: (773) 553-3197

4. Managing Environmental Consultant

MEC: TEM Environmental, Inc.
Contact: Steven Geneser
Address 174 N. Brandon Drive
Glendale Heights, IL, 60139
Phone: 630-790-0880

Fax: 630-790-0882

5. Inspector

Inspector Name: Lisa Laney

Inspector IDPH license # 100-07839

Signature:
Date: 8/29/2019

6. Management Planner

Management Planner Name: Amy Williams

Management Planner IDPH license # 100-00746

Signature:
Date: 09/28/2019

7. Review Date: 09/28/2019

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature:



Date: 10/1/2019

Name: Robert Christlieb

II. EXECUTIVE SUMMARY

TEM Environmental, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Joplin School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.85 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas(HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 2330:

G	Tank insulation
H	Aircell Pipe Insulation

B. The following new homogenous areas have been identified for Building 2330:

22	12x12 Tan Mottled Vinyl Floor Tile
22M	12x12 Tan Mottled Vinyl Floor Tile Mastic
Q	Plaster
R	Window Glazing
S	Transite Fume Hoods

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

07	1'x1' Ceiling Tile
08	9x9 Beige w/Multicolor Specks Mastic
09	12x12 Cream w/Light & Dark Specks Vinyl Floor Tile Mastic
10	Baseboard Mastic
11	Baseboard
12	Vibration Joint Dampener
13	Stair Tread
14	Window Sills
21	12x12 Gray w/White Specks Floor Tile
22	12x12 Tan Mottled Vinyl Floor Tile
22M	12x12 Tan Mottled Vinyl Floor Tile Mastic
B	Boiler Insulation-NOT OBSERVED
BFT-1	12x12 Rust Floor Tile
BFTM	12x12 Rust Floor Tile Mastic
C	Boiler Insulation-NOT OBSERVED
CS	Spray-On Insulation
D	Duct Insulation/Boiler Breeching
E	Tank Insulation
FT-11	Brown w/Wavy Multicolored Streaks Linoleum
FT-12	9x9 Chocolate w/Cream & Orange Streaks Floor Tile
FT-16	12x12 Cream w/Tan Flecks Floor Tile Checkerboard Pattern
FT-8	9x9 Tan Streaked Floor Tile
FT-9	12x12 Tan w/Cream Streaks Floor Tile
FTM-1	9x9 Dark Cream w/Red & Black Streaks Floor Tile Mastic
FTM-10	9x9 Beige w/Green Streaks Floor Tile Mastic
FTM-12	9x9 Chocolate w/Cream & Orange Streaks Floor Tile Mastic
FTM-13	9x9 Dark Cream w/Brown & Cream Streaks Floor Tile Mastic
FTM-14	12x12 Dark Brownish Gray w/Light and Dark Specks Floor Tile Mastic
FTM-3	9x9 Floor Tile Mastic
FTM-6	9x9 Cream w/Multicolored Spots Floor Tile Mastic
FTM-7	9x9 Dark Grayish Brown w/Black, Peach & Cream Streaks Mastic
FTM-8	9x9 Tan Streaked Floor Tile Mastic
FTM-9	12x12 Tan w/Cream Streaks Floor Tile Mastic
G	Tank insulation

H	Aircell Pipe Insulation
I	Fittings
J	Cardboard Insulation-NOT OBSERVED
K	Fittings Cementious - NOT OBSERVED
N	Boiler Gaskets
P	Blue Carpet Mastic
Q	Plaster
R	Window Glazing
S	Transite Fume Hoods
TS-1	Transite Table Tops
WC	Window Caulk

The following areas were deemed to be inaccessible:

08	9x9 Beige w/Multicolor Specks Mastic
09	12x12 Cream w/Light & Dark Specks Vinyl Floor Tile Mastic
10	Baseboard Mastic
12	Vibration Joint Dampener
22M	12x12 Tan Mottled Vinyl Floor Tile Mastic
BFTM	12x12 Rust Floor Tile Mastic
CS	Spray-On Insulation
D	Duct Insulation/Boiler Breeching
E	Tank Insulation
FTM-1	9x9 Dark Cream w/Red & Black Streaks Floor Tile Mastic
FTM-10	9x9 Beige w/Green Streaks Floor Tile Mastic
FTM-11	Stair Tread Mastic
FTM-12	9x9 Chocolate w/Cream & Orange Streaks Floor Tile Mastic
FTM-13	9x9 Dark Cream w/Brown & Cream Streaks Floor Tile Mastic
FTM-14	12x12 Dark Brownish Gray w/Light and Dark Specks Floor Tile Mastic
FTM-16	12x12 Cream w/Tan Flecks Floor Tile Checkerboard Pattern Mastic
FTM-2	9x9 Dark Green w/Cream Streaks Floor Tile Mastic
FTM-3	9x9 Floor Tile Mastic
FTM-4	12x12 Light and Dark Tan Speckled Floor Tile Mastic
FTM-5	9x9 Dark Green w/Fat White Splotches Floor Tile Mastic
FTM-6	9x9 Cream w/Multicolored Spots Floor Tile Mastic
FTM-7	9x9 Dark Grayish Brown w/Black, Peach & Cream Streaks Mastic
FTM-8	9x9 Tan Streaked Floor Tile Mastic

FTM-9	12x12 Tan w/Cream Streaks Floor Tile Mastic
N	Boiler Gaskets
O	Radiator Insulation
P	Blue Carpet Mastic

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Lisa Laney, IDPH License # 100-07839. The Management Plan was updated by Amy Williams, IDPH License # 100-00746. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:	8/26/2019
	8/26/2019
	8/26/2019
	8/26/2019

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Joplin School Building 2330 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. Atimely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Joplin School Unit 22281 Building ID 2330

Address 7931 S. Honore Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
03	9x9 Beige w/Multicolor Speckles Floor Tile	6,000	SF	2nd & 3rd Floor Hallways and Room 215	CHR	MISC	N	DIST	25		No	ACBM with the potential for damage	5	LOW
04	12x12 Cream w/Light & Dark Specks Vinyl Floor Tile	1,000	SF	South Hallway to Room 218	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
05	Acoustical Plaster	25,000	SF	Hallways and Throughout Classrooms	CHR	SURFACE	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
07	1'x1' Ceiling Tile	16,000	SF	2nd & 3rd Floor Classrooms, Gym, Lunchroom & Kitchen	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
08	9x9 Beige w/Multicolor Specks Mastic	6,000	SF	2nd & 3rd Floor Hallways, and Room 215	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
09	12x12 Cream w/Light & Dark Specks Vinyl Floor Tile Mastic	1,000	SF	South Hallway to Room 218	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
10	Baseboard Mastic	800	LF	Throughout Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
11	Baseboard	800	LF	Throughout Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
12	Vibration Joint Dampener	300	SF	Basement	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
13	Stair Tread	48	SF	Gym	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
14	Window Sills	600	SF	Throughout School	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
21	12x12 Gray w/White Specks Floor Tile	8,868	SF	see comments	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
22	12x12 Tan Mottled Vinyl Floor Tile	3,900	SF	Rooms 107, 108, 204, 207, 209, 215	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
22M	12x12 Tan Mottled Vinyl Floor Tile Mastic	3,900	SF	Rooms 107, 108, 204, 207, 209, 215	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
B	Boiler Insulation-NOT OBSERVED			Boiler Room- #1 Boiler	ASSUMED	TSI		None						
BFT-1	12x12 Rust Floor Tile	4,500	SF	Rooms 109-113, Hallway	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
BFTM	12x12 Rust Floor Tile Mastic	4,500	SF	Rooms 109-113, Hallway	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
C	Boiler Insulation-NOT OBSERVED			Boiler Room- #2 Boiler	ASSUMED	TSI		None						
CS	Spray-On Insulation	20	SF	Room 111 Foyer	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW

Chicago Public Schools

School Joplin School Unit 22281 Building ID 2330

Address 7931 S. Honore Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
D	Duct Insulation/Boiler Breeching	100	SF	Boiler Room	ASSUMED	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
E	Tank Insulation	300	SF	Boiler Room	ASSUMED	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
FT-1	9x9 Dark Cream w/Red & Black Streaks Floor Tile	1,500	SF	Rooms 105 & 106	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FT-10	9x9 Beige w/Green Streaks Floor Tile	150	SF	Room 203	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FT-11	Brown w/Wavy Multicolored Streaks Linoleum	150	SF	Southeast and Southwest Stairs	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FT-12	9x9 Chocolate w/Cream & Orange Streaks Floor Tile	200	SF	South Hall Stair Landings	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FT-13	9x9 Dark Cream w/Brown & Cream Streaks Floor Tile	2,500	SF	Rooms 302, 303 & 304	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FT-14	12x12 Dark Brownish Gray w/Light and Dark Specks Floor Tile	600	SF	Room 307	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FT-16	12x12 Cream w/Tan Flecks Floor Tile Checkerboard Pattern	300	SF	Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FT-2	9x9 Dark Green w/Cream Streaks Floor Tile	1,900	SF	Balcony and Gym Storage Area, Vault, Rooms 100, 200, 212 & 214	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FT-4	12x12 Light and Dark Tan Speckled Floor Tile	2,800	SF	Lunchroom, Room 210	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FT-5	9x9 Dark Green w/Fat White Splotches Floor Tile	900	SF	Kitchen	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FT-6	9x9 Cream w/Multicolored Spots Floor Tile	1,600	SF	Room 107, 213 & 309	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FT-7	9x9 Dark Grayish Brown w/Black, Peach & Cream Streaks	5,200	SF	Rooms 108, 204, 207, 209, 305, 306, 310	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FT-8	9x9 Tan Streaked Floor Tile	3,600	SF	Closet in 205, Closet Outside 215, Closet in 108, Closet 218	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FT-9	12x12 Tan w/Cream Streaks Floor Tile	900	SF	Closet, and under carpet in 205	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FTM-1	9x9 Dark Cream w/Red & Black Streaks Floor Tile Mastic	1,700	SF	Rooms 105 & 106	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FTM-10	9x9 Beige w/Green Streaks Floor Tile Mastic	150	SF	Room 203	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FTM-11	Stair Tread Mastic	150	SF	Southeast and Southwest Stairs	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Joplin School Unit 22281 Building ID 2330

Address 7931 S. Honore Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
FTM-12	9x9 Chocolate w/Cream & Orange Streaks Floor Tile Mastic	250	SF	South Hall Stair Landings	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FTM-13	9x9 Dark Cream w/Brown & Cream Streaks Floor Tile Mastic	2,500	SF	Rooms 302, 303 & 304	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FTM-14	12x12 Dark Brownish Gray w/Light and Dark Specks Floor Tile Mastic	600	SF	Room 307	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FTM-16	12x12 Cream w/Tan Flecks Floor Tile Checkerboard Pattern Mastic	300	SF	Office	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FTM-2	9x9 Dark Green w/Cream Streaks Floor Tile Mastic	1,900	SF	Balcony and Gym Storage Area, Vault, Rooms 100, 200, 212 & 214	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FTM-3	9x9 Floor Tile Mastic	5,200	SF	Rooms 200, 212, 214 & 301	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FTM-4	12x12 Light and Dark Tan Speckled Floor Tile Mastic	2,800	SF	Lunchroom, Room 210	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FTM-5	9x9 Dark Green w/Fat White Splotches Floor Tile Mastic	1,300	SF	Kitchen	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FTM-6	9x9 Cream w/Multicolored Spots Floor Tile Mastic	1,600	SF	Rooms 107, 213 & 309	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FTM-7	9x9 Dark Grayish Brown w/Black, Peach & Cream Streaks Mastic	6,000	SF	Rooms 108, 204, 207, 209, 305, 306, 310	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FTM-8	9x9 Tan Streaked Floor Tile Mastic	3,600	SF	Closet in 205, Closet outside 215, Closet in 108, Closet 218,	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FTM-9	12x12 Tan w/Cream Streaks Floor Tile Mastic	900	SF	Closet, and under Carpet in 205	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
G	Tank insulation	500	SF	Boiler Room	ASSUMED	TSI	Y	LOC	10		Yes	Damaged or significantly damaged friable thermal system insulating ACBM	5	MODERATE
H	Aircell Pipe Insulation	1,000	LF	Basement Boiler Room Crawlspace	ASSUMED	TSI	Y	LOC	100		Yes	Damaged or significantly damaged friable thermal system insulating ACBM	5	MODERATE
I	Fittings	200	SF	Boiler Room Crawlspace	ASSUMED	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
J	Cardboard Insulation-NOT OBSERVED			Boiler Room Crawlspace	ASSUMED	TSI		None						
K	Fittings Cementious - NOT OBSERVED			Boiler Room Crawlspace	ASSUMED	TSI								
N	Boiler Gaskets	125	SF	Boiler Room	ASSUMED	TSI	N	LOC	10		No	Damaged or significantly damaged	3	MODERATE

Chicago Public Schools

School Joplin School Unit 22281 Building ID 2330

Address 7931 S. Honore Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
												friable thermal system insulating ACM		
O	Radiator Insulation	20	SF	Throughout Building	CHR	MISC	Y	NONE	0		No	Any remaining friable ACM or friable suspect ACM		LOW
P	Blue Carpet Mastic	1,200	SF	Rooms 101, 105 & 213	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
Q	Plaster	10,000	SF	Throughout Building	ASSUMED	MISC	Y	LOC	100		No	Damaged or significantly damaged friable misc. ACM	3	MODERATE
R	Window Glazing	250	LF	Basement	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
S	Transite Fume Hoods	50	SF	Science Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
TS-1	Transite Table Tops	15	SF	Room 311	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
WC	Window Caulk	400	SF	Throughout School	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Joplin School Unit 22281 Building ID 2330
Address 7931 S. Honore Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

Reinspection Date 8/29/2019
Inspector Name Lisa Laney
100-07839 5/15/2020
Inspector's IDPH License Number / Expiration Date

Inspector's Comments

HA Number:	Inspector Comments:
03	Damage in 2nd floor Hallway, Room 215, & 3rd Floor hall, 25 sq ft of damage
04	
05	
07	
08	
09	
10	
11	
12	
13	
14	
21	
22	
22M	
B	Not Observed Multiple Years
BFT-1	
BFTM	
C	Not Observed Multiple Years
CS	
D	
E	
FT-1	
FT-10	

Chicago Public Schools

School Joplin School **Unit** 22281 **Building ID** 2330
Address 7931 S. Honore **Region** 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
FT-11	
FT-12	
FT-13	
FT-14	
FT-16	
FT-2	Damage Abated 2019
FT-4	
FT-5	Damaged Area Abated 2019-Partial Abatement
FT-6	Not observed in 107, no abatement record
FT-7	Not Observed in 108, 204, 207, 209. No Abatement Record
FT-8	
FT-9	
FTM-1	
FTM-10	
FTM-11	
FTM-12	
FTM-13	
FTM-14	
FTM-16	
FTM-2	
FTM-3	
FTM-4	
FTM-5	
FTM-6	VFT not observed in 107
FTM-7	VFT Not observed in 108, 204, 207, 209, no abatement record
FTM-8	
FTM-9	
G	Damage in Incinerator Room
H	Basement Storage & Bathroom

Chicago Public Schools

School Joplin School **Unit** 22281 **Building ID** 2330
Address 7931 S. Honore **Region** 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
I	
J	Not Observed Multiple Years
K	Not Observed Multiple Years
N	
O	
P	
Q	Basement Stairwell Damage-Remove Damaged Friable material
R	
S	
TS-1	
WC	

Table II

Management Planner's Review

Chicago Public Schools

School Joplin School
Address 7931 S. Honore

Unit 22281
Chicago, IL, 60620

Building ID 2330
Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
03	9x9 Beige w/Multicolor Speckles Floor Tile	6,000	SF	2nd & 3rd Floor Hallways and Room 215	Chrysotile	MISC	No	25	SF	6 ACBM with the potential for damage	Follow O&M Plan
04	12x12 Cream w/Light & Dark Specks Vinyl Floor Tile	1,000	SF	South Hallway to Room 218	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
05	Acoustical Plaster	25,000	SF	Hallways and Throughout Classrooms	Chrysotile	SURFACE	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
07	1'x1' Ceiling Tile	16,000	SF	2nd & 3rd Floor Classrooms, Gym, Lunchroom & Kitchen	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
08	9x9 Beige w/Multicolor Specks Mastic	6,000	SF	2nd & 3rd Floor Hallways, and Room 215	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
09	12x12 Cream w/Light & Dark Specks Vinyl Floor Tile Mastic	1,000	SF	South Hallway to Room 218	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
10	Baseboard Mastic	800	LF	Throughout Building	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
11	Baseboard	800	LF	Throughout Building	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
12	Vibration Joint Dampener	300	SF	Basement	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
13	Stair Tread	48	SF	Gym	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
14	Window Sills	600	SF	Throughout School	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
21	12x12 Gray w/White Specks Floor Tile	8,868	SF	see comments	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
22	12x12 Tan Mottled Vinyl Floor Tile	3,900	SF	Rooms 107, 108, 204, 207, 209, 215	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
22M	12x12 Tan Mottled Vinyl Floor Tile Mastic	3,900	SF	Rooms 107, 108, 204, 207, 209, 215	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
B	Boiler Insulation-NOT OBSERVED			Boiler Room- #1 Boiler	Assumed	TSI					
BFT-1	12x12 Rust Floor Tile	4,500	SF	Rooms 109-113, Hallway	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
BFTM	12x12 Rust Floor Tile Mastic	4,500	SF	Rooms 109-113, Hallway	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
C	Boiler Insulation-NOT OBSERVED			Boiler Room- #2 Boiler	Assumed	TSI					
CS	Spray-On Insulation	20	SF	Room 111 Foyer	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
D	Duct Insulation/Boiler Breeching	100	SF	Boiler Room	Assumed	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
E	Tank Insulation	300	SF	Boiler Room	Assumed	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
FT-1	9x9 Dark Cream w/Red & Black Streaks Floor Tile	1,500	SF	Rooms 105 & 106	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FT-10	9x9 Beige w/Green Streaks Floor Tile	150	SF	Room 203	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FT-11	Brown w/Wavy Multicolored Streaks Linoleum	150	SF	Southeast and Southwest Stairs	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Joplin School
Address 7931 S. Honore

Unit 22281
Chicago, IL, 60620

Building ID 2330
Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
FT-12	9x9 Chocolate w/Cream & Orange Streaks Floor Tile	200	SF	South Hall Stair Landings	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FT-13	9x9 Dark Cream w/Brown & Cream Streaks Floor Tile	2,500	SF	Rooms 302, 303 & 304	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FT-14	12x12 Dark Brownish Gray w/Light and Dark Specks Floor Tile	600	SF	Room 307	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FT-16	12x12 Cream w/Tan Flecks Floor Tile Checkerbaoard Pattern	300	SF	Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FT-2	9x9 Dark Green w/Cream Streaks Floor Tile	1,900	SF	Balcony and Gym Storage Area, Vault, Rooms 100, 200, 212 & 214	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FT-4	12x12 Light and Dark Tan Speckled Floor Tile	2,800	SF	Lunchroom, Room 210	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FT-5	9x9 Dark Green w/Fat White Splotches Floor Tile	900	SF	Kitchen	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FT-6	9x9 Cream w/Multicolored Spots Floor Tile	1,600	SF	Room 107, 213 & 309	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FT-7	9x9 Dark Grayish Brown w/Black, Peach & Cream Streaks	5,200	SF	Rooms 108, 204, 207, 209, 305, 306, 310	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FT-8	9x9 Tan Streaked Floor Tile	3,600	SF	Closet in 205, Closet Outside 215, Closet in 108, Closet 218	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FT-9	12x12 Tan w/Cream Streaks Floor Tile	900	SF	Closet, and under carpet in 205	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FTM-1	9x9 Dark Cream w/Red & Black Streaks Floor Tile Mastic	1,700	SF	Rooms 105 & 106	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FTM-10	9x9 Beige w/Green Streaks Floor Tile Mastic	150	SF	Room 203	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FTM-11	Stair Tread Mastic	150	SF	Southeast and Southwest Stairs	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FTM-12	9x9 Chocolate w/Cream & Orange Streaks Floor Tile Mastic	250	SF	South Hall Stair Landings	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FTM-13	9x9 Dark Cream w/Brown & Cream Streaks Floor Tile Mastic	2,500	SF	Rooms 302, 303 & 304	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FTM-14	12x12 Dark Brownish Gray w/Light and Dark Specks Floor Tile Mastic	600	SF	Room 307	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FTM-16	12x12 Cream w/Tan Flecks Floor Tile Checkerbaoard Pattern Mastic	300	SF	Office	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FTM-2	9x9 Dark Green w/Cream Streaks Floor Tile Mastic	1,900	SF	Balcony and Gym Storage Area, Vault, Rooms 100, 200, 212 & 214	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FTM-3	9x9 Floor Tile Mastic	5,200	SF	Rooms 200, 212, 214 & 301	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FTM-4	12x12 Light and Dark Tan Speckled Floor Tile Mastic	2,800	SF	Lunchroom, Room 210	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Joplin School
Address 7931 S. Honore

Unit 22281
Chicago, IL, 60620

Building ID 2330
Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.
174 N. Brandon Drive Glendale Heights, IL, 60139
Phone: 630-790-0880 Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
FTM-5	9x9 Dark Green w/Fat White Splotches Floor Tile Mastic	1,300	SF	Kitchen	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FTM-6	9x9 Cream w/Multicolored Spots Floor Tile Mastic	1,600	SF	Rooms 107, 213 & 309	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FTM-7	9x9 Dark Grayish Brown w/Black, Peach & Cream Streaks Mastic	6,000	SF	Rooms 108, 204, 207, 209, 305, 306, 310	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FTM-8	9x9 Tan Streaked Floor Tile Mastic	3,600	SF	Closet in 205, Closet outside 215, Closet in 108, Closet 218,	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FTM-9	12x12 Tan w/Cream Streaks Floor Tile Mastic	900	SF	Closet, and under Carpet in 205	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
G	Tank insulation	500	SF	Boiler Room	Assumed	TSI	Yes	10	SF	1 Damaged or significantly damaged friable thermal system insulating ACBM	Repair
H	Aircell Pipe Insulation	1,000	LF	Basement Boiler Room Crawlspace	Assumed	TSI	Yes	100	LF	1 Damaged or significantly damaged friable thermal system insulating ACBM	Repair
I	Fittings	200	SF	Boiler Room Crawlspace	Assumed	TSI	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
J	Cardboard Insulation-NOT OBSERVED			Boiler Room Crawlspace	Assumed	TSI					
K	Fittings Cementious - NOT OBSERVED			Boiler Room Crawlspace	Assumed	TSI					
N	Boiler Gaskets	125	SF	Boiler Room	Assumed	TSI	No	10	SF	1 Damaged or significantly damaged friable thermal system insulating ACBM	Repair
O	Radiator Insulation	20	SF	Throughout Building	Chrysotile	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
P	Blue Carpet Mastic	1,200	SF	Rooms 101, 105 & 213	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
Q	Plaster	10,000	SF	Throughout Building	Assumed	MISC	Yes	100	SF	4 Damaged or significantly damaged friable misc. ACBM	Remove
R	Window Glazing	250	LF	Basement	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
S	Transite Fume Hoods	50	SF	Science Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
TS-1	Transite Table Tops	15	SF	Room 311	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
WC	Window Caulk	400	SF	Throughout School	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Joplin School
Address 7931 S. Honore

Unit 22281
Chicago, IL, 60620

Building ID 2330
Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.
174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

Review Date	09/28/2019
Manager Planner Name	Amy Williams
100-00746	5/15/2020
Manager IDPH License No/Expiration	

HA Number	Management Comments
03	
04	
05	
07	
08	
09	
10	
11	
12	
13	
14	
21	
22	

Chicago Public Schools

School Joplin School
Address 7931 S. Honore

Unit 22281
Chicago, IL, 60620

Building ID 2330
Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.
174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
22M	
B	
BFT-1	
BFTM	
C	
CS	
D	
E	
FT-1	
FT-10	
FT-11	
FT-12	
FT-13	
FT-14	
FT-16	
FT-2	
FT-4	
FT-5	
FT-6	
FT-7	
FT-8	
FT-9	
FTM-1	
FTM-10	
FTM-11	
FTM-12	

Chicago Public Schools

School Joplin School
Address 7931 S. Honore

Unit 22281
Chicago, IL, 60620

Building ID 2330
Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.
174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
FTM-13	
FTM-14	
FTM-16	
FTM-2	
FTM-3	
FTM-4	
FTM-5	
FTM-6	
FTM-7	
FTM-8	
FTM-9	
G	
H	
I	
J	
K	
N	
O	
P	
Q	
R	
S	
TS-1	
WC	

Chicago Public Schools

School

Joplin School

Unit

22281

Building ID

2330

Address

7931 S. Honore

Chicago, IL, 60620

Region

05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC)

TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone:

630-790-0880

Fax:

630-790-0882

Management Planner's Comments Summarized at the End of the Report

Chicago Public Schools

TEM Environmental, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Lisa Laney		
SCHOOL NAME:	Joplin School	INSPECTION DATE:	8/29/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	03		
MATERIAL DESCRIPTION:	9x9 Beige w/Multicolor Speckles Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:	Physical Damage		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:	Physical Damage		
DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	2nd & 3rd Floor Hallways and Room 215		
MATERIAL QUANTITY:	6000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	25	DAMAGE UNITS:	SF
COMMENTS:	Damage in 2nd floor Hallway, Room 215, & 3rd Floor hall, 25 sq ft of damage		

Inspector's Signature: _____ Date: 08/29/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Joplin School	REVIEW DATE:	9/28/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

HOMOGENEOUS AREA:	03				
MATERIAL DESCRIPTION:	9x9 Beige w/Multicolor Speckles Floor Tile				
MATERIAL LOCATION:	2nd & 3rd Floor Hallways and Room 215				
MATERIAL QUANTITY:	6000	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	25	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 09/28/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Lisa Laney		
SCHOOL NAME:	Joplin School	INSPECTION DATE:	8/29/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	04		
MATERIAL DESCRIPTION:	12x12 Cream w/Light & Dark Specks Vinyl Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	South Hallway to Room 218		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 08/29/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Joplin School	REVIEW DATE:	9/28/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

HOMOGENEOUS AREA:	04				
MATERIAL DESCRIPTION:	12x12 Cream w/Light & Dark Specks Vinyl Floor Tile				
MATERIAL LOCATION:	South Hallway to Room 218				
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/28/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Lisa Laney		
SCHOOL NAME:	Joplin School	INSPECTION DATE:	8/29/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	05		
MATERIAL DESCRIPTION:	Acoustical Plaster		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Hallways and Throughout Classrooms		
MATERIAL QUANTITY:	25000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 08/29/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Joplin School	REVIEW DATE:	9/28/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

HOMOGENEOUS AREA:	05				
MATERIAL DESCRIPTION:	Acoustical Plaster				
MATERIAL LOCATION:	Hallways and Throughout Classrooms				
MATERIAL QUANTITY:	25000	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 09/28/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Lisa Laney		
SCHOOL NAME:	Joplin School	INSPECTION DATE:	8/29/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	07		
MATERIAL DESCRIPTION:	1'x1' Ceiling Tile		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	2nd & 3rd Floor Classrooms, Gym, Lunchroom & Kitchen		
MATERIAL QUANTITY:	16000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 08/29/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Joplin School	REVIEW DATE:	9/28/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

HOMOGENEOUS AREA:	07		
MATERIAL DESCRIPTION:	1'x1' Ceiling Tile		
MATERIAL LOCATION:	2nd & 3rd Floor Classrooms, Gym, Lunchroom & Kitchen		
MATERIAL QUANTITY:	16000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/28/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Lisa Laney		
SCHOOL NAME:	Joplin School	INSPECTION DATE:	8/29/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	08		
MATERIAL DESCRIPTION:	9x9 Beige w/Multicolor Specks Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	2nd & 3rd Floor Hallways, and Room 215		
MATERIAL QUANTITY:	6000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 08/29/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Joplin School	REVIEW DATE:	9/28/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

HOMOGENEOUS AREA:	08				
MATERIAL DESCRIPTION:	9x9 Beige w/Multicolor Specks Mastic				
MATERIAL LOCATION:	2nd & 3rd Floor Hallways, and Room 215				
MATERIAL QUANTITY:	6000	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 09/28/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Lisa Laney		
SCHOOL NAME:	Joplin School	INSPECTION DATE:	8/29/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	09		
MATERIAL DESCRIPTION:	12x12 Cream w/Light & Dark Specks Vinyl Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	South Hallway to Room 218		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 08/29/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Joplin School	REVIEW DATE:	9/28/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

HOMOGENEOUS AREA:	09				
MATERIAL DESCRIPTION:	12x12 Cream w/Light & Dark Specks Vinyl Floor Tile Mastic				
MATERIAL LOCATION:	South Hallway to Room 218				
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 09/28/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Lisa Laney		
SCHOOL NAME:	Joplin School	INSPECTION DATE:	8/29/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	10		
MATERIAL DESCRIPTION:	Baseboard Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout Building		
MATERIAL QUANTITY:	800	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature: _____ Date: 08/29/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Joplin School	REVIEW DATE:	9/28/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

HOMOGENEOUS AREA:	10		
MATERIAL DESCRIPTION:	Baseboard Mastic		
MATERIAL LOCATION:	Throughout Building		
MATERIAL QUANTITY:	800	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 09/28/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Lisa Laney		
SCHOOL NAME:	Joplin School	INSPECTION DATE:	8/29/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	11		
MATERIAL DESCRIPTION:	Baseboard		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout Building		
MATERIAL QUANTITY:	800	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature: _____ Date: 08/29/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Joplin School	REVIEW DATE:	9/28/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

HOMOGENEOUS AREA:	11		
MATERIAL DESCRIPTION:	Baseboard		
MATERIAL LOCATION:	Throughout Building		
MATERIAL QUANTITY:	800	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/28/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Lisa Laney		
SCHOOL NAME:	Joplin School	INSPECTION DATE:	8/29/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	12		
MATERIAL DESCRIPTION:	Vibration Joint Dampener		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Basement		
MATERIAL QUANTITY:	300	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

COMMENTS:

Inspector's Signature: _____ Date: 08/29/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Joplin School	REVIEW DATE:	9/28/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

HOMOGENEOUS AREA:	12		
MATERIAL DESCRIPTION:	Vibration Joint Dampener		
MATERIAL LOCATION:	Basement		
MATERIAL QUANTITY:	300	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/28/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Lisa Laney		
SCHOOL NAME:	Joplin School	INSPECTION DATE:	8/29/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	13		
MATERIAL DESCRIPTION:	Stair Tread		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Gym		
MATERIAL QUANTITY:	48	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

COMMENTS:

Inspector's Signature: _____ Date: 08/29/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Joplin School	REVIEW DATE:	9/28/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

HOMOGENEOUS AREA:	13		
MATERIAL DESCRIPTION:	Stair Tread		
MATERIAL LOCATION:	Gym		
MATERIAL QUANTITY:	48	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 09/28/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Lisa Laney		
SCHOOL NAME:	Joplin School	INSPECTION DATE:	8/29/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	14		
MATERIAL DESCRIPTION:	Window Sills		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout School		
MATERIAL QUANTITY:	600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 08/29/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Joplin School	REVIEW DATE:	9/28/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

HOMOGENEOUS AREA:	14		
MATERIAL DESCRIPTION:	Window Sills		
MATERIAL LOCATION:	Throughout School		
MATERIAL QUANTITY:	600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/28/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Lisa Laney		
SCHOOL NAME:	Joplin School	INSPECTION DATE:	8/29/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	21		
MATERIAL DESCRIPTION:	12x12 Gray w/White Specks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	see comments		
MATERIAL QUANTITY:	8868	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 08/29/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Joplin School	REVIEW DATE:	9/28/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

HOMOGENEOUS AREA:	21		
MATERIAL DESCRIPTION:	12x12 Gray w/White Specks Floor Tile		
MATERIAL LOCATION:	see comments		
MATERIAL QUANTITY:	8868	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/28/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Lisa Laney		
SCHOOL NAME:	Joplin School	INSPECTION DATE:	8/29/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	B	
MATERIAL DESCRIPTION:	Boiler Insulation-NOT OBSERVED	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Boiler Room- #1 Boiler

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Not Observed Multiple Years

Inspector's Signature: _____ Date: 08/29/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Joplin School	REVIEW DATE:	9/28/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

HOMOGENEOUS AREA: **B**

MATERIAL DESCRIPTION: **Boiler Insulation-NOT OBSERVED**

MATERIAL LOCATION: **Boiler Room- #1 Boiler**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/28/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Lisa Laney		
SCHOOL NAME:	Joplin School	INSPECTION DATE:	8/29/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	BFT-1		
MATERIAL DESCRIPTION:	12x12 Rust Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 109-113, Hallway		
MATERIAL QUANTITY:	4500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 08/29/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Joplin School	REVIEW DATE:	9/28/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

HOMOGENEOUS AREA:	BFT-1		
MATERIAL DESCRIPTION:	12x12 Rust Floor Tile		
MATERIAL LOCATION:	Rooms 109-113, Hallway		
MATERIAL QUANTITY:	4500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/28/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Lisa Laney		
SCHOOL NAME:	Joplin School	INSPECTION DATE:	8/29/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	BFTM		
MATERIAL DESCRIPTION:	12x12 Rust Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 109-113, Hallway		
MATERIAL QUANTITY:	4500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 08/29/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Joplin School	REVIEW DATE:	9/28/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

HOMOGENEOUS AREA:	BFTM		
MATERIAL DESCRIPTION:	12x12 Rust Floor Tile Mastic		
MATERIAL LOCATION:	Rooms 109-113, Hallway		
MATERIAL QUANTITY:	4500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/28/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22281** BUILDING ID: **2330**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**
SCHOOL NAME: **Joplin School** INSPECTION DATE: **8/29/2019**
ADDRESS: **7931 S. Honore** IDPH LICENSE NO: **100-07839**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **C**
MATERIAL DESCRIPTION: **Boiler Insulation-NOT OBSERVED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room- #2 Boiler**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed Multiple Years**

Inspector's Signature: _____ Date: **08/29/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Joplin School	REVIEW DATE:	9/28/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

HOMOGENEOUS AREA: **C**

MATERIAL DESCRIPTION: **Boiler Insulation-NOT OBSERVED**

MATERIAL LOCATION: **Boiler Room- #2 Boiler**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/28/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Lisa Laney		
SCHOOL NAME:	Joplin School	INSPECTION DATE:	8/29/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	CS		
MATERIAL DESCRIPTION:	Spray-On Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 111 Foyer		
MATERIAL QUANTITY:	20	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 08/29/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Joplin School	REVIEW DATE:	9/28/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

HOMOGENEOUS AREA:	CS				
MATERIAL DESCRIPTION:	Spray-On Insulation				
MATERIAL LOCATION:	Room 111 Foyer				
MATERIAL QUANTITY:	20	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 09/28/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Lisa Laney		
SCHOOL NAME:	Joplin School	INSPECTION DATE:	8/29/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	D		
MATERIAL DESCRIPTION:	Duct Insulation/Boiler Breeching		
HISTORICAL AHERA DAMAGE CATEGORY	7 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Boiler Room		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 08/29/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Joplin School	REVIEW DATE:	9/28/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

HOMOGENEOUS AREA:	D		
MATERIAL DESCRIPTION:	Duct Insulation/Boiler Breeching		
MATERIAL LOCATION:	Boiler Room		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/28/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Lisa Laney		
SCHOOL NAME:	Joplin School	INSPECTION DATE:	8/29/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	E		
MATERIAL DESCRIPTION:	Tank Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	7 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Boiler Room		
MATERIAL QUANTITY:	300	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 08/29/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Joplin School	REVIEW DATE:	9/28/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

HOMOGENEOUS AREA:	E				
MATERIAL DESCRIPTION:	Tank Insulation				
MATERIAL LOCATION:	Boiler Room				
MATERIAL QUANTITY:	300	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/28/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Lisa Laney		
SCHOOL NAME:	Joplin School	INSPECTION DATE:	8/29/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	FT-1		
MATERIAL DESCRIPTION:	9x9 Dark Cream w/Red & Black Streaks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 105 & 106		
MATERIAL QUANTITY:	1500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 08/29/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Joplin School	REVIEW DATE:	9/28/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

HOMOGENEOUS AREA: FT-1

MATERIAL DESCRIPTION: 9x9 Dark Cream w/Red & Black Streaks Floor Tile

MATERIAL LOCATION: Rooms 105 & 106

MATERIAL QUANTITY: 1500

MATERIAL UNITS: SF

DAMAGE QUANTITY: 0

DAMAGE UNITS: SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 09/28/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Lisa Laney		
SCHOOL NAME:	Joplin School	INSPECTION DATE:	8/29/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	FT-10		
MATERIAL DESCRIPTION:	9x9 Beige w/Green Streaks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 203		
MATERIAL QUANTITY:	150	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 08/29/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Joplin School	REVIEW DATE:	9/28/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

HOMOGENEOUS AREA: FT-10

MATERIAL DESCRIPTION: 9x9 Beige w/Green Streaks Floor Tile

MATERIAL LOCATION: Room 203

MATERIAL QUANTITY: 150

MATERIAL UNITS: SF

DAMAGE QUANTITY: 0

DAMAGE UNITS: SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 09/28/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Lisa Laney		
SCHOOL NAME:	Joplin School	INSPECTION DATE:	8/29/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	FT-11		
MATERIAL DESCRIPTION:	Brown w/Wavy Multicolored Streaks Linoleum		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Southeast and Southwest Stairs		
MATERIAL QUANTITY:	150	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 08/29/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Joplin School	REVIEW DATE:	9/28/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

HOMOGENEOUS AREA: **FT-11**

MATERIAL DESCRIPTION: **Brown w/Wavy Multicolored Streaks Linoleum**

MATERIAL LOCATION: **Southeast and Southwest Stairs**

MATERIAL QUANTITY:	150	MATERIAL UNITS:	SF
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/28/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Lisa Laney		
SCHOOL NAME:	Joplin School	INSPECTION DATE:	8/29/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	FT-12		
MATERIAL DESCRIPTION:	9x9 Chocolate w/Cream & Orange Streaks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	South Hall Stair Landings		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 08/29/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Joplin School	REVIEW DATE:	9/28/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

HOMOGENEOUS AREA: FT-12

MATERIAL DESCRIPTION: 9x9 Chocolate w/Cream & Orange Streaks Floor Tile

MATERIAL LOCATION: South Hall Stair Landings

MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
--------------------	-----	-----------------	----

DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
------------------	---	---------------	----

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 09/28/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Lisa Laney		
SCHOOL NAME:	Joplin School	INSPECTION DATE:	8/29/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	FT-13		
MATERIAL DESCRIPTION:	9x9 Dark Cream w/Brown & Cream Streaks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 302, 303 & 304		
MATERIAL QUANTITY:	2500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 08/29/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Joplin School	REVIEW DATE:	9/28/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

HOMOGENEOUS AREA:	FT-13		
MATERIAL DESCRIPTION:	9x9 Dark Cream w/Brown & Cream Streaks Floor Tile		
MATERIAL LOCATION:	Rooms 302, 303 & 304		
MATERIAL QUANTITY:	2500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/28/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Lisa Laney		
SCHOOL NAME:	Joplin School	INSPECTION DATE:	8/29/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	FT-14		
MATERIAL DESCRIPTION:	12x12 Dark Brownish Gray w/Light and Dark Specks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 307		
MATERIAL QUANTITY:	600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 08/29/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Joplin School	REVIEW DATE:	9/28/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

HOMOGENEOUS AREA: FT-14

MATERIAL DESCRIPTION: 12x12 Dark Brownish Gray w/Light and Dark Specks Floor Tile

MATERIAL LOCATION: Room 307

MATERIAL QUANTITY:	600	MATERIAL UNITS:	SF
--------------------	-----	-----------------	----

DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
------------------	---	---------------	----

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 09/28/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Lisa Laney		
SCHOOL NAME:	Joplin School	INSPECTION DATE:	8/29/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	FT-16		
MATERIAL DESCRIPTION:	12x12 Cream w/Tan Flecks Floor Tile Checkerboard Pattern		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Office**

MATERIAL QUANTITY: **300**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/29/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Joplin School	REVIEW DATE:	9/28/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

HOMOGENEOUS AREA: FT-16

MATERIAL DESCRIPTION: 12x12 Cream w/Tan Flecks Floor Tile Checkerboard Pattern

MATERIAL LOCATION: Office

MATERIAL QUANTITY:	300	MATERIAL UNITS:	SF
--------------------	-----	-----------------	----

DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
------------------	---	---------------	----

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 09/28/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Lisa Laney		
SCHOOL NAME:	Joplin School	INSPECTION DATE:	8/29/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	FT-2		
MATERIAL DESCRIPTION:	9x9 Dark Green w/Cream Streaks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Balcony and Gym Storage Area, Vault, Rooms 100, 200, 212 & 214		
MATERIAL QUANTITY:	1900	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:	Damage Abated 2019		

Inspector's Signature: _____ Date: 08/29/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Joplin School	REVIEW DATE:	9/28/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

HOMOGENEOUS AREA:	FT-2		
MATERIAL DESCRIPTION:	9x9 Dark Green w/Cream Streaks Floor Tile		
MATERIAL LOCATION:	Balcony and Gym Storage Area, Vault, Rooms 100, 200, 212 & 214		
MATERIAL QUANTITY:	1900	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/28/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Lisa Laney		
SCHOOL NAME:	Joplin School	INSPECTION DATE:	8/29/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	FT-4		
MATERIAL DESCRIPTION:	12x12 Light and Dark Tan Speckled Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Lunchroom, Room 210		
MATERIAL QUANTITY:	2800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 08/29/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Joplin School	REVIEW DATE:	9/28/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

HOMOGENEOUS AREA:	FT-4				
MATERIAL DESCRIPTION:	12x12 Light and Dark Tan Speckled Floor Tile				
MATERIAL LOCATION:	Lunchroom, Room 210				
MATERIAL QUANTITY:	2800	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 09/28/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Lisa Laney		
SCHOOL NAME:	Joplin School	INSPECTION DATE:	8/29/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	FT-5		
MATERIAL DESCRIPTION:	9x9 Dark Green w/Fat White Splotches Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Kitchen		
MATERIAL QUANTITY:	900	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:	Damaged Area Abated 2019-Partial Abatement		

Inspector's Signature: _____ Date: 08/29/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Joplin School	REVIEW DATE:	9/28/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

HOMOGENEOUS AREA: FT-5

MATERIAL DESCRIPTION: 9x9 Dark Green w/Fat White Splotches Floor Tile

MATERIAL LOCATION: Kitchen

MATERIAL QUANTITY:	900	MATERIAL UNITS:	SF
--------------------	-----	-----------------	----

DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
------------------	---	---------------	----

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 09/28/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Lisa Laney		
SCHOOL NAME:	Joplin School	INSPECTION DATE:	8/29/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	FT-6		
MATERIAL DESCRIPTION:	9x9 Cream w/Multicolored Spots Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 107, 213 & 309		
MATERIAL QUANTITY:	1600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:	Not observed in 107, no abatement record		

Inspector's Signature: _____ Date: 08/29/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Joplin School	REVIEW DATE:	9/28/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

HOMOGENEOUS AREA:	FT-6				
MATERIAL DESCRIPTION:	9x9 Cream w/Multicolored Spots Floor Tile				
MATERIAL LOCATION:	Room 107, 213 & 309				
MATERIAL QUANTITY:	1600	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/28/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Lisa Laney		
SCHOOL NAME:	Joplin School	INSPECTION DATE:	8/29/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	FT-7		
MATERIAL DESCRIPTION:	9x9 Dark Grayish Brown w/Black, Peach & Cream Streaks		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 108, 204, 207, 209, 305, 306, 310		
MATERIAL QUANTITY:	5200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:	Not Observed in 108, 204, 207, 209. No Abatement Record		

Inspector's Signature: _____ Date: 08/29/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Joplin School	REVIEW DATE:	9/28/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

HOMOGENEOUS AREA:	FT-7		
MATERIAL DESCRIPTION:	9x9 Dark Grayish Brown w/Black, Peach & Cream Streaks		
MATERIAL LOCATION:	Rooms 108, 204, 207, 209, 305, 306, 310		
MATERIAL QUANTITY:	5200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/28/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Lisa Laney		
SCHOOL NAME:	Joplin School	INSPECTION DATE:	8/29/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	FT-8		
MATERIAL DESCRIPTION:	9x9 Tan Streaked Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Closet in 205, Closet Outside 215, Closet in 108, Closet 218		
MATERIAL QUANTITY:	3600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 08/29/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Joplin School	REVIEW DATE:	9/28/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

HOMOGENEOUS AREA:	FT-8				
MATERIAL DESCRIPTION:	9x9 Tan Streaked Floor Tile				
MATERIAL LOCATION:	Closet in 205, Closet Outside 215, Closet in 108, Closet 218				
MATERIAL QUANTITY:	3600	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 09/28/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Lisa Laney		
SCHOOL NAME:	Joplin School	INSPECTION DATE:	8/29/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	FT-9		
MATERIAL DESCRIPTION:	12x12 Tan w/Cream Streaks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Closet, and under carpet in 205		
MATERIAL QUANTITY:	900	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 08/29/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Joplin School	REVIEW DATE:	9/28/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

HOMOGENEOUS AREA:	FT-9				
MATERIAL DESCRIPTION:	12x12 Tan w/Cream Streaks Floor Tile				
MATERIAL LOCATION:	Closet, and under carpet in 205				
MATERIAL QUANTITY:	900	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 09/28/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Lisa Laney		
SCHOOL NAME:	Joplin School	INSPECTION DATE:	8/29/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	FTM-1		
MATERIAL DESCRIPTION:	9x9 Dark Cream w/Red & Black Streaks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 105 & 106		
MATERIAL QUANTITY:	1700	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 08/29/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Joplin School	REVIEW DATE:	9/28/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

HOMOGENEOUS AREA:	FTM-1				
MATERIAL DESCRIPTION:	9x9 Dark Cream w/Red & Black Streaks Floor Tile Mastic				
MATERIAL LOCATION:	Rooms 105 & 106				
MATERIAL QUANTITY:	1700	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 09/28/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Lisa Laney		
SCHOOL NAME:	Joplin School	INSPECTION DATE:	8/29/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	FTM-10		
MATERIAL DESCRIPTION:	9x9 Beige w/Green Streaks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 203		
MATERIAL QUANTITY:	150	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 08/29/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Joplin School	REVIEW DATE:	9/28/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

HOMOGENEOUS AREA: **FTM-10**

MATERIAL DESCRIPTION: **9x9 Beige w/Green Streaks Floor Tile Mastic**

MATERIAL LOCATION: **Room 203**

MATERIAL QUANTITY: **150**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/28/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Lisa Laney		
SCHOOL NAME:	Joplin School	INSPECTION DATE:	8/29/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	FTM-11		
MATERIAL DESCRIPTION:	Stair Tread Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Southeast and Southwest Stairs		
MATERIAL QUANTITY:	150	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 08/29/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Joplin School	REVIEW DATE:	9/28/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

HOMOGENEOUS AREA:	FTM-11		
MATERIAL DESCRIPTION:	Stair Tread Mastic		
MATERIAL LOCATION:	Southeast and Southwest Stairs		
MATERIAL QUANTITY:	150	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/28/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Lisa Laney		
SCHOOL NAME:	Joplin School	INSPECTION DATE:	8/29/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	FTM-12		
MATERIAL DESCRIPTION:	9x9 Chocolate w/Cream & Orange Streaks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	South Hall Stair Landings		
MATERIAL QUANTITY:	250	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 08/29/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Joplin School	REVIEW DATE:	9/28/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

HOMOGENEOUS AREA: **FTM-12**

MATERIAL DESCRIPTION: **9x9 Chocolate w/Cream & Orange Streaks Floor Tile Mastic**

MATERIAL LOCATION: **South Hall Stair Landings**

MATERIAL QUANTITY:	250	MATERIAL UNITS:	SF
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/28/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Lisa Laney		
SCHOOL NAME:	Joplin School	INSPECTION DATE:	8/29/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	FTM-13		
MATERIAL DESCRIPTION:	9x9 Dark Cream w/Brown & Cream Streaks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 302, 303 & 304		
MATERIAL QUANTITY:	2500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 08/29/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Joplin School	REVIEW DATE:	9/28/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

HOMOGENEOUS AREA: **FTM-13**

MATERIAL DESCRIPTION: **9x9 Dark Cream w/Brown & Cream Streaks Floor Tile Mastic**

MATERIAL LOCATION: **Rooms 302, 303 & 304**

MATERIAL QUANTITY: **2500**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/28/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Lisa Laney		
SCHOOL NAME:	Joplin School	INSPECTION DATE:	8/29/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	FTM-14		
MATERIAL DESCRIPTION:	12x12 Dark Brownish Gray w/Light and Dark Specks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 307		
MATERIAL QUANTITY:	600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

COMMENTS:

Inspector's Signature: _____ Date: 08/29/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Joplin School	REVIEW DATE:	9/28/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

HOMOGENEOUS AREA:	FTM-14				
MATERIAL DESCRIPTION:	12x12 Dark Brownish Gray w/Light and Dark Specks Floor Tile Mastic				
MATERIAL LOCATION:	Room 307				
MATERIAL QUANTITY:	600	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/28/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Lisa Laney		
SCHOOL NAME:	Joplin School	INSPECTION DATE:	8/29/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	FTM-16		
MATERIAL DESCRIPTION:	12x12 Cream w/Tan Flecks Floor Tile Checkerboard Pattern Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Office**

MATERIAL QUANTITY: **300**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/29/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Joplin School	REVIEW DATE:	9/28/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

HOMOGENEOUS AREA:	FTM-16				
MATERIAL DESCRIPTION:	12x12 Cream w/Tan Flecks Floor Tile Checkerboard Pattern Mastic				
MATERIAL LOCATION:	Office				
MATERIAL QUANTITY:	300	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/28/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Lisa Laney		
SCHOOL NAME:	Joplin School	INSPECTION DATE:	8/29/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	FTM-2		
MATERIAL DESCRIPTION:	9x9 Dark Green w/Cream Streaks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Balcony and Gym Storage Area, Vault, Rooms 100, 200, 212 & 214		
MATERIAL QUANTITY:	1900	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 08/29/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Joplin School	REVIEW DATE:	9/28/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

HOMOGENEOUS AREA:	FTM-2				
MATERIAL DESCRIPTION:	9x9 Dark Green w/Cream Streaks Floor Tile Mastic				
MATERIAL LOCATION:	Balcony and Gym Storage Area, Vault, Rooms 100, 200, 212 & 214				
MATERIAL QUANTITY:	1900	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 09/28/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Lisa Laney		
SCHOOL NAME:	Joplin School	INSPECTION DATE:	8/29/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	FTM-3		
MATERIAL DESCRIPTION:	9x9 Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 200, 212, 214 & 301		
MATERIAL QUANTITY:	5200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 08/29/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Joplin School	REVIEW DATE:	9/28/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

HOMOGENEOUS AREA:	FTM-3				
MATERIAL DESCRIPTION:	9x9 Floor Tile Mastic				
MATERIAL LOCATION:	Rooms 200, 212, 214 & 301				
MATERIAL QUANTITY:	5200	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 09/28/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Lisa Laney		
SCHOOL NAME:	Joplin School	INSPECTION DATE:	8/29/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	FTM-4		
MATERIAL DESCRIPTION:	12x12 Light and Dark Tan Speckled Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Lunchroom, Room 210		
MATERIAL QUANTITY:	2800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 08/29/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Joplin School	REVIEW DATE:	9/28/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

HOMOGENEOUS AREA: **FTM-4**

MATERIAL DESCRIPTION: **12x12 Light and Dark Tan Speckled Floor Tile Mastic**

MATERIAL LOCATION: **Lunchroom, Room 210**

MATERIAL QUANTITY: **2800**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/28/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Lisa Laney		
SCHOOL NAME:	Joplin School	INSPECTION DATE:	8/29/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	FTM-5		
MATERIAL DESCRIPTION:	9x9 Dark Green w/Fat White Splotches Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Kitchen		
MATERIAL QUANTITY:	1300	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

COMMENTS:

Inspector's Signature: _____ Date: 08/29/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Joplin School	REVIEW DATE:	9/28/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

HOMOGENEOUS AREA:	FTM-5				
MATERIAL DESCRIPTION:	9x9 Dark Green w/Fat White Splotches Floor Tile Mastic				
MATERIAL LOCATION:	Kitchen				
MATERIAL QUANTITY:	1300	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/28/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Lisa Laney		
SCHOOL NAME:	Joplin School	INSPECTION DATE:	8/29/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	FTM-6		
MATERIAL DESCRIPTION:	9x9 Cream w/Multicolored Spots Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 107, 213 & 309		
MATERIAL QUANTITY:	1600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:	VFT not observed in 107		

Inspector's Signature: _____ Date: 08/29/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Joplin School	REVIEW DATE:	9/28/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

HOMOGENEOUS AREA: **FTM-6**

MATERIAL DESCRIPTION: **9x9 Cream w/Multicolored Spots Floor Tile Mastic**

MATERIAL LOCATION: **Rooms 107, 213 & 309**

MATERIAL QUANTITY: **1600**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/28/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22281** BUILDING ID: **2330**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**
SCHOOL NAME: **Joplin School** INSPECTION DATE: **8/29/2019**
ADDRESS: **7931 S. Honore** IDPH LICENSE NO: **100-07839**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FTM-7**
MATERIAL DESCRIPTION: **9x9 Dark Grayish Brown w/Black, Peach & Cream Streaks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 108, 204, 207, 209, 305, 306, 310**
MATERIAL QUANTITY: **6000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**
COMMENTS: **VFT Not observed in 108, 204, 207, 209, no abatement record**

Inspector's Signature: _____ Date: **08/29/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Joplin School	REVIEW DATE:	9/28/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

HOMOGENEOUS AREA:	FTM-7		
MATERIAL DESCRIPTION:	9x9 Dark Grayish Brown w/Black, Peach & Cream Streaks Mastic		
MATERIAL LOCATION:	Rooms 108, 204, 207, 209, 305, 306, 310		
MATERIAL QUANTITY:	6000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/28/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Lisa Laney		
SCHOOL NAME:	Joplin School	INSPECTION DATE:	8/29/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	FTM-8		
MATERIAL DESCRIPTION:	9x9 Tan Streaked Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Closet in 205, Closet outside 215, Closet in 108, Closet 218,		
MATERIAL QUANTITY:	3600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 08/29/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Joplin School	REVIEW DATE:	9/28/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

HOMOGENEOUS AREA:	FTM-8		
MATERIAL DESCRIPTION:	9x9 Tan Streaked Floor Tile Mastic		
MATERIAL LOCATION:	Closet in 205, Closet outside 215, Closet in 108, Closet 218,		
MATERIAL QUANTITY:	3600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/28/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Lisa Laney		
SCHOOL NAME:	Joplin School	INSPECTION DATE:	8/29/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	FTM-9		
MATERIAL DESCRIPTION:	12x12 Tan w/Cream Streaks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Closet, and under Carpet in 205		
MATERIAL QUANTITY:	900	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 08/29/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Joplin School	REVIEW DATE:	9/28/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

HOMOGENEOUS AREA: **FTM-9**

MATERIAL DESCRIPTION: **12x12 Tan w/Cream Streaks Floor Tile Mastic**

MATERIAL LOCATION: **Closet, and under Carpet in 205**

MATERIAL QUANTITY:	900	MATERIAL UNITS:	SF
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/28/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Lisa Laney		
SCHOOL NAME:	Joplin School	INSPECTION DATE:	8/29/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	G		
MATERIAL DESCRIPTION:	Tank insulation		
HISTORICAL AHERA DAMAGE CATEGORY	1		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON:	Physical Damage		
DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Boiler Room		
MATERIAL QUANTITY:	500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	10	DAMAGE UNITS:	SF
COMMENTS:	Damage in Incinerator Room		

Inspector's Signature: _____ Date: 08/29/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Joplin School	REVIEW DATE:	9/28/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

HOMOGENEOUS AREA: **G**

MATERIAL DESCRIPTION: **Tank insulation**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:	500	MATERIAL UNITS:	SF
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	10	DAMAGE UNITS:	SF
------------------	-----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/28/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Lisa Laney		
SCHOOL NAME:	Joplin School	INSPECTION DATE:	8/29/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	H		
MATERIAL DESCRIPTION:	Aircell Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	1		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON:	Physical Damage		
DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Basement Boiler Room Crawlspace		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	100	DAMAGE UNITS:	LF
COMMENTS:	Basement Storage & Bathroom		

Inspector's Signature: _____ Date: 08/29/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Joplin School	REVIEW DATE:	9/28/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

HOMOGENEOUS AREA:	H				
MATERIAL DESCRIPTION:	Aircell Pipe Insulation				
MATERIAL LOCATION:	Basement Boiler Room Crawlspace				
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	LF		
DAMAGE QUANTITY:	100	DAMAGE UNITS:	LF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/28/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Lisa Laney		
SCHOOL NAME:	Joplin School	INSPECTION DATE:	8/29/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	I		
MATERIAL DESCRIPTION:	Fittings		
HISTORICAL AHERA DAMAGE CATEGORY	6		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Boiler Room Crawlspace		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 08/29/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Joplin School	REVIEW DATE:	9/28/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

HOMOGENEOUS AREA:	I				
MATERIAL DESCRIPTION:	Fittings				
MATERIAL LOCATION:	Boiler Room Crawlspace				
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/28/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Lisa Laney		
SCHOOL NAME:	Joplin School	INSPECTION DATE:	8/29/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	J	
MATERIAL DESCRIPTION:	Cardboard Insulation-NOT OBSERVED	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Boiler Room Crawlspace

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Not Observed Multiple Years

Inspector's Signature: _____ Date: 08/29/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Joplin School	REVIEW DATE:	9/28/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

HOMOGENEOUS AREA: **J**

MATERIAL DESCRIPTION: **Cardboard Insulation-NOT OBSERVED**

MATERIAL LOCATION: **Boiler Room Crawlspace**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/28/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Lisa Laney		
SCHOOL NAME:	Joplin School	INSPECTION DATE:	8/29/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	K	
MATERIAL DESCRIPTION:	Fittings Cementious - NOT OBSERVED	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Boiler Room Crawlspace

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Not Observed Multiple Years

Inspector's Signature: _____ Date: 08/29/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Joplin School	REVIEW DATE:	9/28/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

HOMOGENEOUS AREA: **K**

MATERIAL DESCRIPTION: **Fittings Cementious - NOT OBSERVED**

MATERIAL LOCATION: **Boiler Room Crawlspace**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/28/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Lisa Laney		
SCHOOL NAME:	Joplin School	INSPECTION DATE:	8/29/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	N		
MATERIAL DESCRIPTION:	Boiler Gaskets		
HISTORICAL AHERA DAMAGE CATEGORY	1 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON:	Deterioration		
DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Boiler Room		
MATERIAL QUANTITY:	125	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	10	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 08/29/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Joplin School	REVIEW DATE:	9/28/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

HOMOGENEOUS AREA:	N				
MATERIAL DESCRIPTION:	Boiler Gaskets				
MATERIAL LOCATION:	Boiler Room				
MATERIAL QUANTITY:	125	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	10	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/28/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Lisa Laney		
SCHOOL NAME:	Joplin School	INSPECTION DATE:	8/29/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	O		
MATERIAL DESCRIPTION:	Radiator Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout Building		
MATERIAL QUANTITY:	20	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 08/29/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Joplin School	REVIEW DATE:	9/28/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

HOMOGENEOUS AREA: **O**

MATERIAL DESCRIPTION: **Radiator Insulation**

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY: **20**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/28/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Lisa Laney		
SCHOOL NAME:	Joplin School	INSPECTION DATE:	8/29/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	P		
MATERIAL DESCRIPTION:	Blue Carpet Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 101, 105 & 213		
MATERIAL QUANTITY:	1200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 08/29/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Joplin School	REVIEW DATE:	9/28/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

HOMOGENEOUS AREA:	P				
MATERIAL DESCRIPTION:	Blue Carpet Mastic				
MATERIAL LOCATION:	Rooms 101, 105 & 213				
MATERIAL QUANTITY:	1200	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 09/28/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Lisa Laney		
SCHOOL NAME:	Joplin School	INSPECTION DATE:	8/29/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	TS-1		
MATERIAL DESCRIPTION:	Transite Table Tops		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 311		
MATERIAL QUANTITY:	15	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 08/29/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Joplin School	REVIEW DATE:	9/28/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

HOMOGENEOUS AREA: **TS-1**

MATERIAL DESCRIPTION: **Transite Table Tops**

MATERIAL LOCATION: **Room 311**

MATERIAL QUANTITY: **15**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/28/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Lisa Laney		
SCHOOL NAME:	Joplin School	INSPECTION DATE:	8/29/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	WC		
MATERIAL DESCRIPTION:	Window Caulk		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout School		
MATERIAL QUANTITY:	400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 08/29/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Joplin School	REVIEW DATE:	9/28/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

HOMOGENEOUS AREA:	WC				
MATERIAL DESCRIPTION:	Window Caulk				
MATERIAL LOCATION:	Throughout School				
MATERIAL QUANTITY:	400	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/28/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Lisa Laney		
SCHOOL NAME:	Joplin School	INSPECTION DATE:	8/29/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	S				
MATERIAL DESCRIPTION:	Transite Fume Hoods				
MATERIAL LOCATION:	Science Room				
MATERIAL QUANTITY:	50	MATERIAL UNITS:	SF		
MATERIAL CATEGORY:	MISC	FRIABLE:			
ASBESTOS TYPE:	Assumed				
DISTURBANCE POTENTIAL:	LOW	CONDITION:			
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage				
ACCESSIBILITY:	Within Reach	DAMAGE REASON:			
		DAMAGE REASON:			
		DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		
COMMENTS:					

Inspector's Signature: _____ Date: 08/29/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22281** BUILDING ID: **2330**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Joplin School** REVIEW DATE: **9/28/2019**
ADDRESS: **7931 S. Honore** IDPH LICENSE NO: **100-07839**

HOMOGENEOUS AREA: **S**
MATERIAL DESCRIPTION: **Transite Fume Hoods**
MATERIAL LOCATION: **Science Room**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **09/28/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Lisa Laney		
SCHOOL NAME:	Joplin School	INSPECTION DATE:	8/29/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	Q				
MATERIAL DESCRIPTION:	Plaster				
MATERIAL LOCATION:	Throughout Building				
MATERIAL QUANTITY:	10000	MATERIAL UNITS:	SF		
MATERIAL CATEGORY:	MISC	FRIABLE:			
ASBESTOS TYPE:	Assumed				
DISTURBANCE POTENTIAL:	MODERATE	CONDITION:			
AHERA DAMAGE CATEGORY:	4 Damaged or significantly damaged friable misc. ACBM				
ACCESSIBILITY:	Within Reach	DAMAGE REASON:			
		DAMAGE REASON:			
		DAMAGE REASON:			
DAMAGE QUANTITY:	100	DAMAGE UNITS:	SF		

COMMENTS:
Basement Stairwell Damage-Remove Damaged Friable material

Inspector's Signature: _____ Date: 08/29/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Joplin School	REVIEW DATE:	9/28/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

HOMOGENEOUS AREA:	Q				
MATERIAL DESCRIPTION:	Plaster				
MATERIAL LOCATION:	Throughout Building				
MATERIAL QUANTITY:	10000	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	100	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **09/28/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Lisa Laney		
SCHOOL NAME:	Joplin School	INSPECTION DATE:	8/29/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	R				
MATERIAL DESCRIPTION:	Window Glazing				
MATERIAL LOCATION:	Basement				
MATERIAL QUANTITY:	250	MATERIAL UNITS:	LF		
MATERIAL CATEGORY:	MISC	FRIABLE:			
ASBESTOS TYPE:	Assumed				
DISTURBANCE POTENTIAL:	LOW	CONDITION:			
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage				
ACCESSIBILITY:	Within Reach	DAMAGE REASON:			
		DAMAGE REASON:			
		DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF		
COMMENTS:					

Inspector's Signature: _____ Date: 08/29/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22281** BUILDING ID: **2330**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Joplin School** REVIEW DATE: **9/28/2019**
ADDRESS: **7931 S. Honore** IDPH LICENSE NO: **100-07839**

HOMOGENEOUS AREA: **R**
MATERIAL DESCRIPTION: **Window Glazing**
MATERIAL LOCATION: **Basement**
MATERIAL QUANTITY: **250** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **09/28/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Lisa Laney		
SCHOOL NAME:	Joplin School	INSPECTION DATE:	8/29/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	22M				
MATERIAL DESCRIPTION:	12x12 Tan Mottled Vinyl Floor Tile Mastic				
MATERIAL LOCATION:	Rooms 107, 108, 204, 207, 209, 215				
MATERIAL QUANTITY:	3900	MATERIAL UNITS:	SF		
MATERIAL CATEGORY:	MISC	FRIABLE:			
ASBESTOS TYPE:	Assumed				
DISTURBANCE POTENTIAL:	LOW	CONDITION:			
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage				
ACCESSIBILITY:	Not Reachable	DAMAGE REASON:			
		DAMAGE REASON:			
		DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		
COMMENTS:					

Inspector's Signature: _____ Date: 08/29/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Joplin School	REVIEW DATE:	9/28/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

HOMOGENEOUS AREA:	22M				
MATERIAL DESCRIPTION:	12x12 Tan Mottled Vinyl Floor Tile Mastic				
MATERIAL LOCATION:	Rooms 107, 108, 204, 207, 209, 215				
MATERIAL QUANTITY:	3900	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **09/28/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Lisa Laney		
SCHOOL NAME:	Joplin School	INSPECTION DATE:	8/29/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	22		
MATERIAL DESCRIPTION:	12x12 Tan Mottled Vinyl Floor Tile		
MATERIAL LOCATION:	Rooms 107, 108, 204, 207, 209, 215		
MATERIAL QUANTITY:	3900	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE REASON:	
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 08/29/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22281	BUILDING ID:	2330
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Joplin School	REVIEW DATE:	9/28/2019		
ADDRESS:	7931 S. Honore	IDPH LICENSE NO:	100-07839		

HOMOGENEOUS AREA:	22				
MATERIAL DESCRIPTION:	12x12 Tan Mottled Vinyl Floor Tile				
MATERIAL LOCATION:	Rooms 107, 108, 204, 207, 209, 215				
MATERIAL QUANTITY:	3900	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **09/28/2019**

APPENDIX B

Inspector and Management Planner Licenses

2019



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900 ♦ www.otssafety.com

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Lisa Laney


has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 4/5/2019

Exam Date: 4/5/2019

Expiration Date: 4/5/2020

Certificate Number: BIR1904051198



Kathy DeSalvo, Director

Wm. H. Lacey

Reliable
Environmental
Solutions, Inc. **RES**

This is to certify that **Amy J. Williams**

*has on 04/03/19, in Springfield, Illinois,
completed the requirements for asbestos accreditation under Section 206 of TSCA Title II*

Asbestos Building Inspector Refresher Training

*as accredited by the State of Illinois and approved by the U.S.E.P.A. under 40 CFR 763 (AHERA)
and passed the associated examination with a score of 70% or higher*

Course Date: April 03, 2019

COURSE LENGTH: 4 HOURS

Examination Date: April 03, 2019

Expiration Date: April 03, 2020

Certificate Number: BIR/0808

William S. Williams

Training Program Manager, William S. Williams

4211 Westgate Drive, Springfield, Illinois ☐ 217.787.9800 ☐ 217.787.9801 FAX ☐ www.ReliableEnv.com



2539 Vandalia Street, Collinsville, IL 62234 * Phone: 618-855-8764

Environmental and Occupational Safety & Health Training

Does hereby certify

William Williams

4211 Westgate Drive, Springfield, IL 62711

*Has successfully completed and passed the course examination with at least
70% for re-accreditation under AHERA (Title II)*

Asbestos Management Planner Refresher


Class Date: 02/15/2019
Examination Date: 02/15/2019
STC Certificate Number: STC-20190215-000527AMPR
Certification Expiration: 02/15/2020

David M. Mendoza – President/Training Director
Certified Environmental Specialist
OSHA Authorized Instructor

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License



ASBESTOS PROFESSIONAL LICENSE

ENDORSEMENTS

TC EXPIRES

INSPECTOR

4/21/2019

ID NUMBER

ISSUED

EXPIRES

100 - 00746

4/11/2019

05/15/2020

MANAGEMENT PLANNER

4/21/2019

PROJECT MANAGER

4/2/2020


AIR SAMPLING PROFESSIONAL

AMY J WILLIAMS

1408 S CLAY

JACKSONVILLE, IL 62650

Environmental Health



Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois
Department of Public Health
This license is valid only when accompanied by a valid
training course certificate.

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL		
	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE		
	Loc	Localized
	Dist	Distributed