

ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-2091
SCHOOL NAME: Haley, Alex Modular
ADDRESS OF SCHOOL: 11413 S Eggelston
CITY: Chicago, IL, 60628

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **4/15/2016**

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II (Please type or print)

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 10/1/2019 ENROLLMENT 524
IDPH INSPECTOR LICENSE NUMBER: 100-00440
IDPH LICENSED INSPECTOR NAME(Please Print): Shawn Brown
IDPH MP LICENSE NUMBER: 100-00746
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Amy Williams

DESIGNATED PERSON (Please Print): Robert Christlieb PHONE: (773) 553-3197



10/1/2019

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Haley, Alex Modular

11413 S Egelston
Chicago, IL, 60628

Unit: 22301
Building ID: 8712

IDPH ID Number: 14-016-2990-2091

REPORT DATE:

Tuesday, October 01, 2019

Prepared for:

**Chicago Public Schools
42 West Madison Street
Chicago, IL 60602**

Prepared by:

TEM Environmental, Inc.

174 N. Brandon Drive

Glendale Heights, IL, 60139

Phone 630-790-0880

Fax 630-790-0882

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

October 7, 2019

Mr. Glen E. Garner
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2019 Three-Year Reinspections

Dear Mr. Glen:

TEM Environmental, Inc. , Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 5, 6 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 70204 Region: 00 IDPH ID:14-016-2990-2091

School: Haley, Alex Modular Building ID: 8712

Address: 11413 S Egelston
Chicago, IL, 60628

Building Contact: Contact Phone:

Current Building Owners: Chicago Public Schools

Review Date: 10/29/2019

Inspector: Shawn Brown Inspector IDPH License: 100-00440
Management Planner: Amy Williams Management Planner IDPH License: 100-00746

If you have any questions or comments, please contact us at 630-790-0880

Sincerely,
TEM Environmental, Inc.

Amy Williams
100-00746

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: October 07, 2019

RE: Haley, Alex Modular, Unit 22301
11413 S Egelston
Chicago, IL, 60628

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2019 asbestos three year re-inspection has been completed at Haley, Alex Modular, following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at Haley, Alex Modular, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Robert Christlieb, the designated Local Education Authority's Designated Person at (773) 553-3197 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Haley, Alex Modular Unit: 70204 Region: 00
Address: 11413 S Eggelston Chicago, IL, 60628
IDPH ID: 14-016-2990-2091 Building ID: 8712
Contact: Phone:

2. Description of Facility

Original Construction: Additional Construction:
Total Square Footage: No of Floors:
Current Occupancy: 524

3. LEA Designated Person

Contact: Robert Christlieb Phone: (773) 553-3197
Address: 42 West Madison Street
Chicago, IL 60602

4. Managing Environmental Consultant

MEC: TEM Environmental, Inc.
Contact: Steven Geneser
Address 174 N. Brandon Drive
Glendale Heights, IL, 60139
Phone: 630-790-0880 Fax: 630-790-0882

5. Inspector

Inspector Name: Shawn Brown

Inspector IDPH license # 100-00440

Signature:
Date: 10/7/2019

6. Management Planner

Management Planner Name: Amy Williams

Management Planner IDPH license # 100-00746

Signature:
Date: 10/29/2019

7. Review Date: 10/29/2019

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature:



Date: 10/1/2019

Name: Robert Christlieb

II. EXECUTIVE SUMMARY

TEM Environmental, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Haley, Alex Modular. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.85 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas(HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 8712:

B. The following new homogenous areas have been identified for Building 8712:

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

05M	12 x 12 Dark Green Floor Tile Mastic
06AM	12 x 12 Light Brown Floor Tile Mastic
06M	12 x 12 Light Brown Floor Tile
07AM	12 x 12 Cream Floor Tile Mastic
07M	12 X 12 Cream Floor Tile
08AM	12 x 12 Tan Floor Tile Mastic
08M	12 x 12 Tan Floor Tile
09AM	Black Mopboard Mastic
09M	Black Mopboard
11M	Ceramic Tile Grout
12M	Green Carpet Mastic
13M	Brown Carpet Mastic
14	12 x 12 Pink Floor Tile
14M	12 x 12 Pink Floor Tile Mastic
15	12 x 12 Orange Floor Tile
15M	12 x 12 Orange Floor Tile Mastic
16	12x12 Light Green Speckled Vinyl Floor Tile
16AM	12x12 Light Green Speckled Vinyl Floor Tile Mastic
17	2'x4' Smooth White Ceiling Tile
18	Brown Carpet Mastic
1M	12 x 12 Dark Green Floor Tile
BM	MJP E/F/V on Fiberglass Pipe Insulation

The following areas were deemed to be inaccessible:

05M	12 x 12 Dark Green Floor Tile Mastic
06AM	12 x 12 Light Brown Floor Tile Mastic
07AM	12 x 12 Cream Floor Tile Mastic
08AM	12 x 12 Tan Floor Tile Mastic
09AM	Black Mopboard Mastic
12M	Green Carpet Mastic
13M	Brown Carpet Mastic
14M	12 x 12 Pink Floor Tile Mastic
15M	12 x 12 Orange Floor Tile Mastic
16AM	12x12 Light Green Speckled Vinyl Floor Tile Mastic
18	Brown Carpet Mastic

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Shawn Brown, IDPH License # 100-00440. The Management Plan was updated by Amy Williams, IDPH License # 100-00746. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates: 7/10/2017
 7/10/2017
 7/10/2017

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Haley, Alex Modular Building 8712 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. Atimely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Haley, Alex Modular Unit 70204 Building ID 8712

Address 11413 S Egelston Region 00

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
05M	12 x 12 Dark Green Floor Tile Mastic	4,827	SF	Kitchen, Kitchen Storage Room, North and South Stairwells, Landings, Multi Purpose, 3rd Floor South Storage, 505B, 2nd Floor Closet, Electrical, 1st Floor Closet	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
06AM	12 x 12 Light Brown Floor Tile Mastic	1,706	SF	1st Floor Stairway, North and South Entrys, Room 301	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
06M	12 x 12 Light Brown Floor Tile	1,706	SF	1st Floor Stairway, North and South Entrys, Room 301	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
07AM	12 x 12 Cream Floor Tile Mastic	6,400	SF	Main Offices, Teacher's Lounge, Rooms 302, 304, 309, Lounge, Library, Rooms 400 - 407, 409, 501, 502, Lab, 504, 506 - 510	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
07M	12 X 12 Cream Floor Tile	6,400	SF	Main Offices, Teachers' Lounge, Rooms 302, 304, 309, Lounge, Library, Rooms 400 - 407, 409, 501, 502, Lab, 504, 506 - 510	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
08AM	12 x 12 Tan Floor Tile Mastic	9,426	SF	Room 302-304, 306, 401, 402, 404-409, 501-510, 1st, 2nd & 3rd Floor Corridors	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
08M	12 x 12 Tan Floor Tile	9,426	SF	Rooms 302-304, 306, 401, 402, 404-409, 501-510, 1st, 2nd & 3rd Floor Corridors	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
09AM	Black Mopboard Mastic	253	LF	Multi Purpose Room, Room 301, and Hallway (Partial)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
09M	Black Mopboard	253	LF	Room 301, Multipurpose Room,	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Haley, Alex Modular Unit 70204 Building ID 8712

Address 11413 S Eggleston Region 00

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Gym, and Hallways (Partial)										
10M	2 x 4 Ceiling Tile	25,880	SF	Throughout 1972 Building	CHR	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
11M	Ceramic Tile Grout	1,500	SF	All Washrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
12M	Green Carpet Mastic	220	SF	Room 309	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
13M	Brown Carpet Mastic	860	SF	Main Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
14	12 x 12 Pink Floor Tile	1,160	SF	Rooms 301 and 303	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
14M	12 x 12 Pink Floor Tile Mastic	1,160	SF	Rooms 301 and 303	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
15	12 x 12 Orange Floor Tile	1,160	SF	Rooms 301 and 303	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
15M	12 x 12 Orange Floor Tile Mastic	1,160	SF	Rooms 301 and 303	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
16	12x12 Light Green Speckled Vinyl Floor Tile	500	SF	Kitchen	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
16AM	12x12 Light Green Speckled Vinyl Floor Tile Mastic	500	SF	Kitchen	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
17	2'x4' Smooth White Ceiling Tile	1,300	SF	Lunchroom and Kitchen	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
18	Brown Carpet Mastic	550	SF	Main Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
1M	12 x 12 Dark Green Floor Tile	4,827	SF	Kitchen, Kitchen Storage Room, North and South Stairwells, Landings, Multi Purpose, 3rd Floor South Storage, 505B, 2nd Floor Closet, Electrical, 1st Floor Closet	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
BM	MJP E/F/V on Fiberglass Pipe Insulation	20	LF	Kitchen, Janitor's Closet, 1st Storage Room	ASSUMED	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW

Chicago Public Schools

School Haley, Alex Modular Unit 70204 Building ID 8712

Address 11413 S Egelston Region 00

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

Reinspection Date 10/7/2019
Inspector Name Shawn Brown
100-00440 5/15/2020
Inspector's IDPH License Number / Expiration Date

Inspector's Comments

HA Number:	Inspector Comments:
05M	
06AM	
06M	
07AM	
07M	
08AM	
08M	
09AM	
09M	
10M	Abated (2017) in Rms 402 (202), 404, 408 (Library), 2nd Fl Hall & Stairs; 500B, 507, 509 508 (308), 507, Storage, 3rd Fl. Hall
11M	
12M	
13M	
14	
14M	
15	
15M	
16	
16AM	
17	
18	
1M	
BM	

Chicago Public Schools

School Haley, Alex Modular **Unit** 70204 **Building ID** 8712

Address 11413 S Eggeston **Region** 00

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

Table II

Management Planner's Review

Chicago Public Schools

School Haley, Alex Modular
Address 11413 S Egelston

Unit 70204
 Chicago, IL, 60628

Building ID 8712
Region 00

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
05M	12 x 12 Dark Green Floor Tile Mastic	4,827	SF	Kitchen, Kitchen Storage Room, North and South Stairwells, Landings, Multi Purpose, 3rd Floor South Storage, 505B, 2nd Floor Closet, Electrical, 1st Floor Closet	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
06AM	12 x 12 Light Brown Floor Tile Mastic	1,706	SF	1st Floor Stairway, North and South Entrys, Room 301	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
06M	12 x 12 Light Brown Floor Tile	1,706	SF	1st Floor Stairway, North and South Entrys, Room 301	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
07AM	12 x 12 Cream Floor Tile Mastic	6,400	SF	Main Offices, Teacher's Lounge, Rooms 302, 304, 309, Lounge, Library, Rooms 400 - 407, 409, 501, 502, Lab, 504, 506 - 510	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
07M	12 X 12 Cream Floor Tile	6,400	SF	Main Offices, Teachers' Lounge, Rooms 302, 304, 309, Lounge, Library, Rooms 400 - 407, 409, 501, 502, Lab, 504, 506 - 510	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
08AM	12 x 12 Tan Floor Tile Mastic	9,426	SF	Room 302-304, 306, 401, 402, 404-409, 501-510, 1st, 2nd & 3rd Floor Corridors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
08M	12 x 12 Tan Floor Tile	9,426	SF	Rooms 302-304, 306, 401, 402, 404-409, 501-510, 1st, 2nd & 3rd Floor Corridors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
09AM	Black Mopboard Mastic	253	LF	Multi Purpose Room, Room 301, and Hallway (Partial)	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
09M	Black Mopboard	253	LF	Room 301, Multipurpose Room, Gym, and Hallways (Partial)	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
10M	2 x 4 Ceiling Tile	25,880	SF	Throughout 1972 Building	Chrysotile	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
11M	Ceramic Tile Grout	1,500	SF	All Washrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
12M	Green Carpet Mastic	220	SF	Room 309	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
13M	Brown Carpet Mastic	860	SF	Main Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
14	12 x 12 Pink Floor Tile	1,160	SF	Rooms 301 and 303	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
14M	12 x 12 Pink Floor Tile Mastic	1,160	SF	Rooms 301 and 303	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
15	12 x 12 Orange Floor Tile	1,160	SF	Rooms 301 and 303	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Haley, Alex Modular
Address 11413 S Eggelston

Unit 70204
 Chicago, IL, 60628

Building ID 8712
Region 00

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
15M	12 x 12 Orange Floor Tile Mastic	1,160	SF	Rooms 301 and 303	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
16	12x12 Light Green Speckled Vinyl Floor Tile	500	SF	Kitchen	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
16AM	12x12 Light Green Speckled Vinyl Floor Tile Mastic	500	SF	Kitchen	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
17	2'x4' Smooth White Ceiling Tile	1,300	SF	Lunchroom and Kitchen	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
18	Brown Carpet Mastic	550	SF	Main Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
1M	12 x 12 Dark Green Floor Tile	4,827	SF	Kitchen, Kitchen Storage Room, North and South Stairwells, Landings, Multi Purpose, 3rd Floor South Storage, 505B, 2nd Floor Closet, Electrical, 1st Floor Closet	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
BM	MJP E/F/V on Fiberglass Pipe Insulation	20	LF	Kitchen, Janitor's Closet, 1st Storage Room	Assumed	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan

Chicago Public Schools

School Haley, Alex Modular
Address 11413 S Egelston

Unit 70204
 Chicago, IL, 60628

Building ID 8712
Region 00

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

Review Date	10/29/2019
Manager Planner Name	Amy Williams
100-00746	5/15/2020
Manager IDPH License No/Expiration	

HA Number	Management Comments
05M	
06AM	
06M	
07AM	
07M	
08AM	
08M	
09AM	
09M	
10M	
11M	
12M	
13M	
14	
14M	
15	
15M	
16	
16AM	
17	
18	

Chicago Public Schools

School Haley, Alex Modular

Unit 70204

Building ID 8712

Address 11413 S Egelston

Chicago, IL, 60628

Region 00

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
1M	
BM	

Chicago Public Schools

TEM Environmental, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **70204** BUIDLING ID: **8712**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shawn Brown**
SCHOOL NAME: **Haley, Alex Modular** INSPECTION DATE: **10/7/2019**
ADDRESS: **11413 S Eggelston** IDPH LICENSE NO: **100-00440**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **05M**
MATERIAL DESCRIPTION: **12 x 12 Dark Green Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Kitchen, Kitchen Storage Room, North and South Stairwells, Landings, Multi Purpose, 3rd Floor South Storage, 505B, 2nd Floor Closet, Electrical, 1st Floor Closet**

MATERIAL QUANTITY: **4827** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/07/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **70204** BUIDLING ID: **8712**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Haley, Alex Modular** REVIEW DATE: **10/29/2019**
ADDRESS: **11413 S Eggeston** IDPH LICENSE NO: **100-00440**

HOMOGENEOUS AREA: **05M**
MATERIAL DESCRIPTION: **12 x 12 Dark Green Floor Tile Mastic**
MATERIAL LOCATION: **Kitchen, Kitchen Storage Room, North and South Stairwells, Landings, Multi Purpose, 3rd Floor South Storage, 505B, 2nd Floor Closet, Electrical, 1st Floor Closet**
MATERIAL QUANTITY: **4827** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/29/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **70204** BUIDLING ID: **8712**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shawn Brown**
SCHOOL NAME: **Haley, Alex Modular** INSPECTION DATE: **10/7/2019**
ADDRESS: **11413 S Eggelston** IDPH LICENSE NO: **100-00440**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **06AM**
MATERIAL DESCRIPTION: **12 x 12 Light Brown Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st Floor Stairway, North and South Entrys, Room 301**
MATERIAL QUANTITY: **1706** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/07/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **70204** BUIDLING ID: **8712**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Haley, Alex Modular** REVIEW DATE: **10/29/2019**
ADDRESS: **11413 S Egelston** IDPH LICENSE NO: **100-00440**

HOMOGENEOUS AREA: **06AM**
MATERIAL DESCRIPTION: **12 x 12 Light Brown Floor Tile Mastic**
MATERIAL LOCATION: **1st Floor Stairway, North and South Entrys, Room 301**
MATERIAL QUANTITY: **1706** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/29/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **70204** BUILDING ID: **8712**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shawn Brown**
SCHOOL NAME: **Haley, Alex Modular** INSPECTION DATE: **10/7/2019**
ADDRESS: **11413 S Egelston** IDPH LICENSE NO: **100-00440**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **06M**
MATERIAL DESCRIPTION: **12 x 12 Light Brown Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **1st Floor Stairway, North and South Entrys, Room 301**
MATERIAL QUANTITY: **1706** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/07/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **70204** BUIDLING ID: **8712**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Haley, Alex Modular** REVIEW DATE: **10/29/2019**
ADDRESS: **11413 S Eggeston** IDPH LICENSE NO: **100-00440**

HOMOGENEOUS AREA: **06M**
MATERIAL DESCRIPTION: **12 x 12 Light Brown Floor Tile**
MATERIAL LOCATION: **1st Floor Stairway, North and South Entrys, Room 301**
MATERIAL QUANTITY: **1706** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/29/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **70204** BUIDLING ID: **8712**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shawn Brown**
SCHOOL NAME: **Haley, Alex Modular** INSPECTION DATE: **10/7/2019**
ADDRESS: **11413 S Egelston** IDPH LICENSE NO: **100-00440**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **07AM**
MATERIAL DESCRIPTION: **12 x 12 Cream Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Main Offices, Teacher's Lounge, Rooms 302, 304, 309, Lounge, Library, Rooms 400 - 407, 409, 501, 502, Lab, 504, 506 - 510**

MATERIAL QUANTITY: **6400**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/07/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **70204** BUIDLING ID: **8712**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Haley, Alex Modular** REVIEW DATE: **10/29/2019**
ADDRESS: **11413 S Eggeston** IDPH LICENSE NO: **100-00440**

HOMOGENEOUS AREA: **07AM**
MATERIAL DESCRIPTION: **12 x 12 Cream Floor Tile Mastic**
MATERIAL LOCATION: **Main Offices, Teacher's Lounge, Rooms 302, 304, 309, Lounge, Library, Rooms 400 - 407, 409, 501, 502, Lab, 504, 506 - 510**
MATERIAL QUANTITY: **6400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/29/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **70204** BUILDING ID: **8712**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shawn Brown**
SCHOOL NAME: **Haley, Alex Modular** INSPECTION DATE: **10/7/2019**
ADDRESS: **11413 S Egelston** IDPH LICENSE NO: **100-00440**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **07M**
MATERIAL DESCRIPTION: **12 X 12 Cream Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Main Offices, Teachers' Lounge, Rooms 302, 304, 309, Lounge, Library, Rooms 400 - 407, 409, 501, 502, Lab, 504, 506 - 510**

MATERIAL QUANTITY: **6400**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 10/07/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **70204** BUIDLING ID: **8712**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Haley, Alex Modular** REVIEW DATE: **10/29/2019**
ADDRESS: **11413 S Eggeston** IDPH LICENSE NO: **100-00440**

HOMOGENEOUS AREA: **07M**
MATERIAL DESCRIPTION: **12 X 12 Cream Floor Tile**
MATERIAL LOCATION: **Main Offices, Teachers' Lounge, Rooms 302, 304, 309, Lounge, Library, Rooms 400 - 407, 409, 501, 502, Lab, 504, 506 - 510**
MATERIAL QUANTITY: **6400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/29/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **70204** BUIDLING ID: **8712**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shawn Brown**
SCHOOL NAME: **Haley, Alex Modular** INSPECTION DATE: **10/7/2019**
ADDRESS: **11413 S Egelston** IDPH LICENSE NO: **100-00440**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **08AM**
MATERIAL DESCRIPTION: **12 x 12 Tan Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 302-304, 306, 401, 402, 404-409, 501-510, 1st, 2nd & 3rd Floor Corridors**
MATERIAL QUANTITY: **9426** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/07/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **70204** BUIDLING ID: **8712**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Haley, Alex Modular** REVIEW DATE: **10/29/2019**
ADDRESS: **11413 S Egelston** IDPH LICENSE NO: **100-00440**

HOMOGENEOUS AREA: **08AM**
MATERIAL DESCRIPTION: **12 x 12 Tan Floor Tile Mastic**
MATERIAL LOCATION: **Room 302-304, 306, 401, 402, 404-409, 501-510, 1st, 2nd & 3rd Floor Corridors**
MATERIAL QUANTITY: **9426** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/29/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **70204** BUIDLING ID: **8712**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shawn Brown**
SCHOOL NAME: **Haley, Alex Modular** INSPECTION DATE: **10/7/2019**
ADDRESS: **11413 S Eggelston** IDPH LICENSE NO: **100-00440**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **08M**
MATERIAL DESCRIPTION: **12 x 12 Tan Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 302-304, 306, 401, 402, 404-409, 501-510, 1st, 2nd & 3rd Floor Corridors**
MATERIAL QUANTITY: **9426** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/07/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **70204** BUIDLING ID: **8712**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Haley, Alex Modular** REVIEW DATE: **10/29/2019**
ADDRESS: **11413 S Egelston** IDPH LICENSE NO: **100-00440**

HOMOGENEOUS AREA: **08M**
MATERIAL DESCRIPTION: **12 x 12 Tan Floor Tile**
MATERIAL LOCATION: **Rooms 302-304, 306, 401, 402, 404-409, 501-510, 1st, 2nd & 3rd Floor Corridors**
MATERIAL QUANTITY: **9426** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/29/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **70204** BUIDLING ID: **8712**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shawn Brown**
SCHOOL NAME: **Haley, Alex Modular** INSPECTION DATE: **10/7/2019**
ADDRESS: **11413 S Eggelston** IDPH LICENSE NO: **100-00440**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **09AM**
MATERIAL DESCRIPTION: **Black Mopboard Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Multi Purpose Room, Room 301, and Hallway (Partial)**
MATERIAL QUANTITY: **253** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 10/07/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **70204** BUIDLING ID: **8712**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Haley, Alex Modular** REVIEW DATE: **10/29/2019**
ADDRESS: **11413 S Egelston** IDPH LICENSE NO: **100-00440**

HOMOGENEOUS AREA: **09AM**
MATERIAL DESCRIPTION: **Black Mopboard Mastic**
MATERIAL LOCATION: **Multi Purpose Room, Room 301, and Hallway (Partial)**
MATERIAL QUANTITY: **253** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/29/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **70204** BUIDLING ID: **8712**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shawn Brown**
SCHOOL NAME: **Haley, Alex Modular** INSPECTION DATE: **10/7/2019**
ADDRESS: **11413 S Eggelston** IDPH LICENSE NO: **100-00440**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **09M**
MATERIAL DESCRIPTION: **Black Mopboard**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 301, Multipurpose Room, Gym, and Hallways (Partial)**
MATERIAL QUANTITY: **253** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 10/07/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **70204** BUIDLING ID: **8712**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Haley, Alex Modular** REVIEW DATE: **10/29/2019**
ADDRESS: **11413 S Egelston** IDPH LICENSE NO: **100-00440**

HOMOGENEOUS AREA: **09M**
MATERIAL DESCRIPTION: **Black Mopboard**
MATERIAL LOCATION: **Room 301, Multipurpose Room, Gym, and Hallways (Partial)**
MATERIAL QUANTITY: **253** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/29/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **70204** BUIDLING ID: **8712**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shawn Brown**
SCHOOL NAME: **Haley, Alex Modular** INSPECTION DATE: **10/7/2019**
ADDRESS: **11413 S Egelston** IDPH LICENSE NO: **100-00440**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10M**
MATERIAL DESCRIPTION: **2 x 4 Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout 1972 Building**
MATERIAL QUANTITY: **25880** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS: **Abated (2017) in Rms 402 (202), 404, 408 (Library), 2nd Fl Hall & Stairs; 500B, 507, 509 508 (308), 507, Storage, 3rd Fl. Hall**

Inspector's Signature: _____ Date: 10/07/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **70204** BUIDLING ID: **8712**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Haley, Alex Modular** REVIEW DATE: **10/29/2019**
ADDRESS: **11413 S Egelston** IDPH LICENSE NO: **100-00440**

HOMOGENEOUS AREA: **10M**
MATERIAL DESCRIPTION: **2 x 4 Ceiling Tile**
MATERIAL LOCATION: **Throughout 1972 Building**
MATERIAL QUANTITY: **25880** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/29/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **70204** BUILDING ID: **8712**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shawn Brown**
SCHOOL NAME: **Haley, Alex Modular** INSPECTION DATE: **10/7/2019**
ADDRESS: **11413 S Egelston** IDPH LICENSE NO: **100-00440**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11M**
MATERIAL DESCRIPTION: **Ceramic Tile Grout**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **All Washrooms**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/07/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **70204** BUIDLING ID: **8712**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Haley, Alex Modular** REVIEW DATE: **10/29/2019**
ADDRESS: **11413 S Eggeston** IDPH LICENSE NO: **100-00440**

HOMOGENEOUS AREA: **11M**
MATERIAL DESCRIPTION: **Ceramic Tile Grout**
MATERIAL LOCATION: **All Washrooms**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/29/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **70204** BUILDING ID: **8712**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shawn Brown**
SCHOOL NAME: **Haley, Alex Modular** INSPECTION DATE: **10/7/2019**
ADDRESS: **11413 S Egelston** IDPH LICENSE NO: **100-00440**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12M**
MATERIAL DESCRIPTION: **Green Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 309**
MATERIAL QUANTITY: **220** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/07/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **70204** BUILDING ID: **8712**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Haley, Alex Modular** REVIEW DATE: **10/29/2019**
ADDRESS: **11413 S Eggeston** IDPH LICENSE NO: **100-00440**

HOMOGENEOUS AREA: **12M**
MATERIAL DESCRIPTION: **Green Carpet Mastic**
MATERIAL LOCATION: **Room 309**
MATERIAL QUANTITY: **220** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/29/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **70204** BUIDLING ID: **8712**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shawn Brown**
SCHOOL NAME: **Haley, Alex Modular** INSPECTION DATE: **10/7/2019**
ADDRESS: **11413 S Eggelston** IDPH LICENSE NO: **100-00440**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13M**
MATERIAL DESCRIPTION: **Brown Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Main Office**
MATERIAL QUANTITY: **860** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/07/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **70204** BUIDLING ID: **8712**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Haley, Alex Modular** REVIEW DATE: **10/29/2019**
ADDRESS: **11413 S Eggeston** IDPH LICENSE NO: **100-00440**

HOMOGENEOUS AREA: **13M**
MATERIAL DESCRIPTION: **Brown Carpet Mastic**
MATERIAL LOCATION: **Main Office**
MATERIAL QUANTITY: **860** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/29/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **70204** BUILDING ID: **8712**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shawn Brown**
SCHOOL NAME: **Haley, Alex Modular** INSPECTION DATE: **10/7/2019**
ADDRESS: **11413 S Egelston** IDPH LICENSE NO: **100-00440**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14**
MATERIAL DESCRIPTION: **12 x 12 Pink Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 301 and 303**
MATERIAL QUANTITY: **1160** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/07/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **70204** BUIDLING ID: **8712**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Haley, Alex Modular** REVIEW DATE: **10/29/2019**
ADDRESS: **11413 S Egelston** IDPH LICENSE NO: **100-00440**

HOMOGENEOUS AREA: **14**
MATERIAL DESCRIPTION: **12 x 12 Pink Floor Tile**
MATERIAL LOCATION: **Rooms 301 and 303**
MATERIAL QUANTITY: **1160** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/29/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **70204** BUIDLING ID: **8712**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shawn Brown**
SCHOOL NAME: **Haley, Alex Modular** INSPECTION DATE: **10/7/2019**
ADDRESS: **11413 S Eggelston** IDPH LICENSE NO: **100-00440**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14M**
MATERIAL DESCRIPTION: **12 x 12 Pink Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 301 and 303**
MATERIAL QUANTITY: **1160** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/07/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **70204** BUIDLING ID: **8712**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Haley, Alex Modular** REVIEW DATE: **10/29/2019**
ADDRESS: **11413 S Egelston** IDPH LICENSE NO: **100-00440**

HOMOGENEOUS AREA: **14M**
MATERIAL DESCRIPTION: **12 x 12 Pink Floor Tile Mastic**
MATERIAL LOCATION: **Rooms 301 and 303**
MATERIAL QUANTITY: **1160** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/29/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **70204** BUILDING ID: **8712**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shawn Brown**
SCHOOL NAME: **Haley, Alex Modular** INSPECTION DATE: **10/7/2019**
ADDRESS: **11413 S Egelston** IDPH LICENSE NO: **100-00440**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15**
MATERIAL DESCRIPTION: **12 x 12 Orange Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Rooms 301 and 303**
MATERIAL QUANTITY: **1160** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/07/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **70204** BUIDLING ID: **8712**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Haley, Alex Modular** REVIEW DATE: **10/29/2019**
ADDRESS: **11413 S Egelston** IDPH LICENSE NO: **100-00440**

HOMOGENEOUS AREA: **15**
MATERIAL DESCRIPTION: **12 x 12 Orange Floor Tile**
MATERIAL LOCATION: **Rooms 301 and 303**
MATERIAL QUANTITY: **1160** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/29/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **70204** BUIDLING ID: **8712**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shawn Brown**
SCHOOL NAME: **Haley, Alex Modular** INSPECTION DATE: **10/7/2019**
ADDRESS: **11413 S Egelston** IDPH LICENSE NO: **100-00440**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15M**
MATERIAL DESCRIPTION: **12 x 12 Orange Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 301 and 303**
MATERIAL QUANTITY: **1160** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/07/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **70204** BUIDLING ID: **8712**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Haley, Alex Modular** REVIEW DATE: **10/29/2019**
ADDRESS: **11413 S Egelston** IDPH LICENSE NO: **100-00440**

HOMOGENEOUS AREA: **15M**
MATERIAL DESCRIPTION: **12 x 12 Orange Floor Tile Mastic**
MATERIAL LOCATION: **Rooms 301 and 303**
MATERIAL QUANTITY: **1160** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/29/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **70204** BUILDING ID: **8712**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shawn Brown**
SCHOOL NAME: **Haley, Alex Modular** INSPECTION DATE: **10/7/2019**
ADDRESS: **11413 S Egelston** IDPH LICENSE NO: **100-00440**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16**
MATERIAL DESCRIPTION: **12x12 Light Green Speckled Vinyl Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Kitchen**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/07/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **70204** BUIDLING ID: **8712**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Haley, Alex Modular** REVIEW DATE: **10/29/2019**
ADDRESS: **11413 S Eggeston** IDPH LICENSE NO: **100-00440**

HOMOGENEOUS AREA: **16**
MATERIAL DESCRIPTION: **12x12 Light Green Speckled Vinyl Floor Tile**
MATERIAL LOCATION: **Kitchen**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/29/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **70204** BUILDING ID: **8712**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shawn Brown**
SCHOOL NAME: **Haley, Alex Modular** INSPECTION DATE: **10/7/2019**
ADDRESS: **11413 S Egelston** IDPH LICENSE NO: **100-00440**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16AM**
MATERIAL DESCRIPTION: **12x12 Light Green Speckled Vinyl Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Kitchen**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/07/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **70204** BUIDLING ID: **8712**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Haley, Alex Modular** REVIEW DATE: **10/29/2019**
ADDRESS: **11413 S Egelston** IDPH LICENSE NO: **100-00440**

HOMOGENEOUS AREA: **16AM**
MATERIAL DESCRIPTION: **12x12 Light Green Speckled Vinyl Floor Tile Mastic**
MATERIAL LOCATION: **Kitchen**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/29/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **70204** BUIDLING ID: **8712**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shawn Brown**
SCHOOL NAME: **Haley, Alex Modular** INSPECTION DATE: **10/7/2019**
ADDRESS: **11413 S Eggelston** IDPH LICENSE NO: **100-00440**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17**
MATERIAL DESCRIPTION: **2'x4' Smooth White Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Lunchroom and Kitchen**
MATERIAL QUANTITY: **1300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/07/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **70204** BUIDLING ID: **8712**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Haley, Alex Modular** REVIEW DATE: **10/29/2019**
ADDRESS: **11413 S Eggeston** IDPH LICENSE NO: **100-00440**

HOMOGENEOUS AREA: **17**
MATERIAL DESCRIPTION: **2'x4' Smooth White Ceiling Tile**
MATERIAL LOCATION: **Lunchroom and Kitchen**
MATERIAL QUANTITY: **1300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/29/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **70204** BUIDLING ID: **8712**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shawn Brown**
SCHOOL NAME: **Haley, Alex Modular** INSPECTION DATE: **10/7/2019**
ADDRESS: **11413 S Eggelston** IDPH LICENSE NO: **100-00440**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18**
MATERIAL DESCRIPTION: **Brown Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Main Office**
MATERIAL QUANTITY: **550** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/07/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **70204** BUIDLING ID: **8712**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Haley, Alex Modular** REVIEW DATE: **10/29/2019**
ADDRESS: **11413 S Eggeston** IDPH LICENSE NO: **100-00440**

HOMOGENEOUS AREA: **18**
MATERIAL DESCRIPTION: **Brown Carpet Mastic**
MATERIAL LOCATION: **Main Office**
MATERIAL QUANTITY: **550** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/29/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **70204** BUIDLING ID: **8712**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shawn Brown**
SCHOOL NAME: **Haley, Alex Modular** INSPECTION DATE: **10/7/2019**
ADDRESS: **11413 S Eggelston** IDPH LICENSE NO: **100-00440**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **1M**
MATERIAL DESCRIPTION: **12 x 12 Dark Green Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Kitchen, Kitchen Storage Room, North and South Stairwells, Landings, Multi Purpose, 3rd Floor South Storage, 505B, 2nd Floor Closet, Electrical, 1st Floor Closet**

MATERIAL QUANTITY: **4827** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/07/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **70204** BUILDING ID: **8712**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Haley, Alex Modular** REVIEW DATE: **10/29/2019**
ADDRESS: **11413 S Eggeston** IDPH LICENSE NO: **100-00440**

HOMOGENEOUS AREA: **1M**
MATERIAL DESCRIPTION: **12 x 12 Dark Green Floor Tile**
MATERIAL LOCATION: **Kitchen, Kitchen Storage Room, North and South Stairwells, Landings, Multi Purpose, 3rd Floor South Storage, 505B, 2nd Floor Closet, Electrical, 1st Floor Closet**
MATERIAL QUANTITY: **4827** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/29/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **70204** BUIDLING ID: **8712**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shawn Brown**
SCHOOL NAME: **Haley, Alex Modular** INSPECTION DATE: **10/7/2019**
ADDRESS: **11413 S Eggelston** IDPH LICENSE NO: **100-00440**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **BM**
MATERIAL DESCRIPTION: **MJP E/F/V on Fiberglass Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Kitchen, Janitor's Closet, 1st Storage Room**
MATERIAL QUANTITY: **20** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 10/07/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **70204** BUIDLING ID: **8712**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Haley, Alex Modular** REVIEW DATE: **10/29/2019**
ADDRESS: **11413 S Eggeston** IDPH LICENSE NO: **100-00440**

HOMOGENEOUS AREA: **BM**
MATERIAL DESCRIPTION: **MJP E/F/V on Fiberglass Pipe Insulation**
MATERIAL LOCATION: **Kitchen, Janitor's Closet, 1st Storage Room**
MATERIAL QUANTITY: **20** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/29/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

APPENDIX B

Inspector and Management Planner Licenses

CERTIFICATE OF ACHIEVEMENT ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that SHAWN L. BROWN
has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the
examination on 03/18/2019 with a minimum score of 70% or better. Training was in accordance
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:
Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.

03/18/2019

Course Dates:

03/18/2020

Expires:

1903BIR03

Certificate Number:



PUBLIC HEALTH & SAFETY inc.

Environmental and Occupational Services
375 Ashland Ave., Chicago, IL 60607

www.public-health-safety.com

Office: 312-491-0081
Fax: 312-421-2801

Director of Training

Nicholas J. Peneff

Doctor of Public Health

Phone: 312-491-0081

FORM # A-010B

CERTIFICATE OF ACHIEVEMENT ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that SHAWN L. BROWN
has completed the Asbestos Management Planner Refresher course and passed the examination
on 03/18/2019 with a minimum score of 70% or better. Training was in accordance with U.S.
E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools: Model
Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.

03/18/2019

Course Dates:

03/18/2020

Expires:

1903MPR01

Certificate Number:



PUBLIC HEALTH & SAFETY Inc.
Environmental and Occupational Services
311 S. Ashland Ave., Chicago, IL 60607

Office: 312-491-0081
Fax: 312-421-2901
www.public-health-safety.com

Director of Training
Nicholas J. Peneff
Doctor of Public Health




Phone: 312-491-0081

FORM # A-011

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

		ASBESTOS PROFESSIONAL LICENSE		ENDORSEMENTS	TC EXPIRES
ID NUMBER	ISSUED	EXPIRES		INSPECTOR	3/19/2019
100 - 02950	3/6/2019	05/15/2020		PROJECT MANAGER	4/9/2019
KEITH CLOUGH				AIR SAMPLING PROFESSIONAL	
524 HOMELAND RD MATTESON, IL 60443	Environmental Health			Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	

Reliable
Environmental
Solutions, Inc. **RES**

This is to certify that **Amy J. Williams**

*has on 04/03/19, in Springfield, Illinois,
completed the requirements for asbestos accreditation under Section 206 of TSCA Title II*

Asbestos Building Inspector Refresher Training

*as accredited by the State of Illinois and approved by the U.S.E.P.A. under 40 CFR 763 (AHERA)
and passed the associated examination with a score of 70% or higher*

Course Date: April 03, 2019

COURSE LENGTH: 4 HOURS

Examination Date: April 03, 2019

Expiration Date: April 03, 2020

William S. Williams

Certificate Number: BIR/0808

Training Program Manager, William S. Williams

4211 Westgate Drive, Springfield, Illinois ☐ 217.787.9800 ☐ 217.787.9801 FAX ☐ www.ReliableEnv.com



2539 Vandalia Street, Collinsville, IL 62234 * Phone: 618-855-8764

Environmental and Occupational Safety & Health Training

Does hereby certify

William Williams

4211 Westgate Drive, Springfield, IL 62711

*Has successfully completed and passed the course examination with at least
70% for re-accreditation under AHERA (Title II)*

Asbestos Management Planner Refresher

Class Date: 02/15/2019
Examination Date: 02/15/2019
STC Certificate Number: STC-20190215-000527AMPR
Certification Expiration: 02/15/2020

David M. Mendoza – President/Training Director
Certified Environmental Specialist
OSHA Authorized Instructor

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License



ASBESTOS PROFESSIONAL LICENSE

ENDORSEMENTS

TC EXPIRES

INSPECTOR

4/21/2019

ID NUMBER

ISSUED

EXPIRES

100 - 00746

4/11/2019

05/15/2020

MANAGEMENT PLANNER

4/21/2019

PROJECT MANAGER

4/2/2020


AIR SAMPLING PROFESSIONAL

AMY J WILLIAMS

1408 S CLAY

JACKSONVILLE, IL 62650

Environmental Health



Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois
Department of Public Health
This license is valid only when accompanied by a valid
training course certificate.

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL		
	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE		
	Loc	Localized
	Dist	Distributed