

ILLINOIS DEPARTMENT OF PUBLIC HEALTH  
AHERA THREE YEAR REINSPECTION  
ASBESTOS ABATEMENT PROGRAM  
SCHOOL INFORMATION FORM

**SECTION I**

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299  
SCHOOL ID NUMBER: 14-016-2990-2092  
SCHOOL NAME: Haley, Alex School  
ADDRESS OF SCHOOL: 11411 S Eggleston  
CITY: Chicago, IL, 60628

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **4/15/2016**

**If the address on this form is different than the address of the building, submit a written explanation.**

**SECTION II** (Please type or print)

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 10/1/2019 ENROLLMENT 524  
IDPH INSPECTOR LICENSE NUMBER: 100-00440  
IDPH LICENSED INSPECTOR NAME(Please Print): Shawn Brown  
IDPH MP LICENSE NUMBER: 100-09786  
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): John Fenn

DESIGNATED PERSON (Please Print): Robert Christlieb PHONE: (773) 553-3197



10/1/2019

Signature of Designated Person

Date

**SECTION III**

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: \_\_\_\_\_

School has been closed. Date closed: \_\_\_\_\_

School building has been demolished. Date: \_\_\_\_\_

School building is asbestos free since last reinspection: \_\_\_\_\_

**Please explain in writing why the school building is now asbestos free and include the supporting documentation.**

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

**Explain in writing if the address of the building is different than the address on this form:**

**THREE-YEAR REINSPECTION**

**CHICAGO SCHOOL DIST 299**

**Haley, Alex School**

11411 S Eggleston  
Chicago, IL, 60628

Unit: 22301  
Building ID: 2360

IDPH ID Number: 14-016-2990-2092

**REPORT DATE:**

Tuesday, October 01, 2019

**Prepared for:**

**Chicago Public Schools  
42 West Madison Street  
Chicago, IL 60602**

**Prepared by:**

**TEM Environmental, Inc.**

174 N. Brandon Drive

Glendale Heights, IL, 60139

Phone 630-790-0880

Fax 630-790-0882

**DO NOT REMOVE FROM SCHOOL  
REQUIRED BY FEDERAL LAW**

September 2, 2019

Mr. Glen E. Garner  
Asbestos Program  
Illinois Department of Public Health  
525 West Jefferson Street  
Springfield, Illinois 62761

Re: Chicago Public Schools - 2019 Three-Year Reinspections

Dear Mr. Glen:

TEM Environmental, Inc. , Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 5, 6 Elementary Schools. Please update your records with the following information.

School District: 299          Unit: 22301          Region: 06          IDPH ID:14-016-2990-2092

School: Haley, Alex School          Building ID: 2360

Address: 11411 S Eggleston

Chicago, IL, 60628

Building Contact: Wassong, Joseph

Contact Phone:708 770 2446

Current Building Owners: Chicago Public Schools

Review Date: 10/01/2019

Inspector: Shawn Brown

Inspector IDPH License: 100-00440

Management Planner: John Fenn

Management Planner IDPH License: 100-09786

If you have any questions or comments, please contact us at 630-790-0880

Sincerely,  
TEM Environmental, Inc.

John Fenn  
100-09786

## **Environmental Notification to Occupants**

To: Faculty, Staff and Parents  
From: Chicago Public Schools  
Date: September 02, 2019

RE: Haley, Alex School, Unit 22301  
11411 S Eggleston  
Chicago, IL, 60628

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2019 asbestos three year re-inspection has been completed at Haley, Alex School, following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at Haley, Alex School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Robert Christlieb, the designated Local Education Authority's Designated Person at (773) 553-3197 .

## **Table of Contents**

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

### **APPENDICES:**

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

## SCHOOL AND INSPECTION INFORMATION

### 1. School Information

School: Haley, Alex School  
Address: 11411 S Eggleston  
IDPH ID: 14-016-2990-2092  
Contact: Wassong, Joseph

Unit: 22301  
Chicago, IL, 60628  
Building ID: 2360  
Phone: 708 770 2446

Region: 06

### 2. Description of Facility

Original Construction: 1925  
Total Square Footage: 64306  
Current Occupancy: 524

Additional Construction:  
No of Floors: 2

### 3. LEA Designated Person

Contact: Robert Christlieb  
Address: 42 West Madison Street  
Chicago, IL 60602

Phone: (773) 553-3197

### 4. Managing Environmental Consultant

MEC: TEM Environmental, Inc.  
Contact: Steven Geneser  
Address 174 N. Brandon Drive  
Glendale Heights, IL, 60139  
Phone: 630-790-0880

Fax: 630-790-0882

### 5. Inspector

Inspector Name: Shawn Brown

Inspector IDPH license # 100-00440

Signature:  
Date: 9/2/2019

### 6. Management Planner

Management Planner Name: John Fenn

Management Planner IDPH license # 100-09786

Signature:  
Date: 10/01/2019

### 7. Review Date:10/01/2019

### 8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature:



Date: 10/1/2019

Name: Robert Christlieb

## II. EXECUTIVE SUMMARY

TEM Environmental, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Haley, Alex School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.85 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 2360:

B. The following new homogenous areas have been identified for Building 2360:



C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

13	Heating Pipe
15	Fire Brick in Incinerator
16	Terrazzo
17A	12x12 Sand Colored Floor Tile Mastic
18	12x12 Cream Colored Floor Tile
19	12x12 Tan Floor Tile
19A	12x12 Tan Floor Tile Mastic
20A	12x12 Light Brown Floor Tile Mastic
21	12x12 White w/Black Streaks Floor Tile
21A	12x12 White w/Black Streaks Floor Tile Mastic
23	Grey Carpet Mastic
24	Hardcoat Plaster
25	1 x 1 White Fissured Ceiling Tile
25M	1 x 1 White Fissured Ceiling Tile Mastic
26	2 x 4 White Fissured Ceiling Tile
27	12 x 12 White with Beige Specs Floor Tile
27M	12 x 12 White with Beige Specs Floor Tile Mastic
28	12 x 12 Off White with Beige Specs Floor Tile
28M	12 x 12 Off White with Beige Specs Floor Tile Mastic
29	12x12 Light Gray w/White Specks Vinyl Floor Tile
29M	12 x 12 Light Gray w/White Specks Vinyl Floor Tile Mastic
30	12 x 12 Blue Speckled Vinyl Floor Tile
30M	12 x 12 Blue Speckled Vinyl Floor Tile Mastic
31	12x12 Maroon w/Dark Brown Specks Vinyl Floor Tile
31M	12x12 Maroon w/Dark Brown Specks Vinyl Floor Tile Mastic

The following areas were deemed to be inaccessible:

09	12x12 Brown Speckled Floor Tile Mastic
17A	12x12 Sand Colored Floor Tile Mastic
18A	12x12 Cream Colored Floor Tile Mastic
19A	12x12 Tan Floor Tile Mastic
20A	12x12 Light Brown Floor Tile Mastic
21A	12x12 White w/Black Streaks Floor Tile Mastic
23	Grey Carpet Mastic
25M	1 x 1 White Fissured Ceiling Tile Mastic

27M	12 x 12 White with Beige Specs Floor Tile Mastic
28M	12 x 12 Off White with Beige Specs Floor Tile Mastic
29M	12 x 12 Light Gray w/White Specks Vinyl Floor Tile Mastic
30M	12 x 12 Blue Speckled Vinyl Floor Tile Mastic
H	MJP E/F/V on Heating and Water Pipe Insulation

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Shawn Brown, IDPH License # 100-00440. The Management Plan was updated by John Fenn, IDPH License # 100-09786. Inspector and Management Planner Licenses are included in Appendix B.

### **III. METHODOLOGY**

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

### **IV. ABATEMENT HISTORY**

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

### **V. REASSESSMENTS AND RECOMMENDATIONS**

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

### **VI. CONCLUSIONS**

The Haley, Alex School Building 2360 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. Atimely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

**Table I**  
**Inspector's Reinspection Findings**

---

# Chicago Public Schools

School Haley, Alex School Unit 22301 Building ID 2360

Address 11411 S Eggleston Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
01	Linoleum-NOT OBSERVED			Kitchen		MISC								
02	12x12 Brown Speckled Floor Tile	7,116	SF	All Corridors - 1st and 2nd Floors	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
08	Linoleum Mastic-NOT OBSERVED			Kitchen		MISC								
09	12x12 Brown Speckled Floor Tile Mastic	7,116	SF	All Corridors - 1st and 2nd Floors	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
11	Black Mopboard			Teachers' Lounge and Cafeteria	NO_ACBM	MISC								
12	Black Mopboard Mastic			Teachers' Lounge and Cafeteria	NO_ACBM	MISC								
13	Heating Pipe	80	LF	Boiler Room	ASSUMED	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
14	Transite Partitions			All Washrooms Throughout The Facility	NO_ACBM	MISC								
15	Fire Brick in Incinerator	50	SF	Boiler Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
16	Terrazzo	5,100	SF	Throughout School	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
17	12x12 Sand Colored Floor Tile	384	SF	Main Office	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
17A	12x12 Sand Colored Floor Tile Mastic	384	SF	Main Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
18	12x12 Cream Colored Floor Tile	470	SF	Rooms 124 (Teachers' Lounge) and Kitchen Closet	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
18A	12x12 Cream Colored Floor Tile Mastic	470	SF	Rooms 124 (Teachers' Lounge) and Kitchen Closet	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
19	12x12 Tan Floor Tile	370	SF	Rooms 124 (Teachers' Lounge)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
19A	12x12 Tan Floor Tile Mastic	370	SF	Rooms 124 (Teachers' Lounge)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
20	12x12 Light Brown Floor Tile	1,680	SF	Room 117 (Library) and 1st & 2nd Floor Storage Rooms	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
20A	12x12 Light Brown Floor Tile Mastic	1,680	SF	Room 117 (Library) and 1st & 2nd Floor Storage Rooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
21	12x12 White w/Black Streaks Floor Tile	1,264	SF	Room 116 (Lunchroom)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
21A	12x12 White w/Black Streaks Floor Tile Mastic	1,264	SF	Room 116 (Lunchroom)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

# Chicago Public Schools

School Haley, Alex School Unit 22301 Building ID 2360

Address 11411 S Eggleston Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
22	Ceramic Tile Grout			All Washrooms at the Facility	NO_ACBM	MISC								
23	Grey Carpet Mastic	384	SF	Main Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
24	Hardcoat Plaster	200,000	SF	1st and 2nd Floors-Throughout	ASSUMED	SURFACE	N	NONE	0		No	ACBM with the potential for damage		LOW
25	1 x 1 White Fissured Ceiling Tile	1,400	SF	Room 121 (Library)	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
25M	1 x 1 White Fissured Ceiling Tile Mastic	1,400	SF	Room 121 (Library)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
26	2 x 4 White Fissured Ceiling Tile	720	SF	Room 122 (Kindergarden)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
27	12 x 12 White with Beige Specs Floor Tile	210	SF	Kitchen	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
27M	12 x 12 White with Beige Specs Floor Tile Mastic	210	SF	Kitchen	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
28	12 x 12 Off White with Beige Specs Floor Tile	210	SF	Kitchen	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
28M	12 x 12 Off White with Beige Specs Floor Tile Mastic	210	SF	Kitchen	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
29	12x12 Light Gray w/White Specks Vinyl Floor Tile	1,100	SF	Cafeteria and Kitchen	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
29M	12 x 12 Light Gray w/White Specks Vinyl Floor Tile Mastic	1,100	SF	Cafeteria and Kitchen	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
30	12 x 12 Blue Speckled Vinyl Floor Tile	600	SF	Main Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
30M	12 x 12 Blue Speckled Vinyl Floor Tile Mastic	600	SF	Main Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
31	12x12 Maroon w/Dark Brown Specks Vinyl Floor Tile	50	SF	Elevator Vestibule	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
31M	12x12 Maroon w/Dark Brown Specks Vinyl Floor Tile Mastic	50	SF	Elevator Vestibule	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
A	Boiler Insulation	2,200	SF	Boiler Room	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
B	Insulation on Water Return Tanks	80	SF	Boiler Room	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
C	Heating and Water Pipe Insulation	889	LF	Boiler Room, Mechanical Room, Air Tunnels, Pipe Chases	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
D	MJP E/F/V on Heating and Water Pipe	78	LF	Boiler Room,	CHR	TSI	Y	NONE	0		No	Any remaining friable		LOW

# Chicago Public Schools

School Haley, Alex School Unit 22301 Building ID 2360

Address 11411 S Eggleston Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
	Insulation			Mechanical Room, Air Tunnels, Pipe Chases								ACBM or friable suspect ACBM		
E	Insulation on Heating Pipes	180	LF	Boiler Room, Boiler Room Tunnel, Mechanical Room	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
F	Magblock Pipe Joint Insulation	15	LF	Boiler Room and Throughout Basement Pipe Chases	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
G	Heating and Water Pipe Insulation	1,465	LF	Boiler Room, Pipe Chases, Mechanical Room, Air Tunnels, Unexcavated Crawl Spaces	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
H	MJP E/F/V on Heating and Water Pipe Insulation	386	LF	Boiler Room, Pipe Chases, Mechanical Room, Air Tunnels, Unexcavated Crawl Spaces	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
I	Aircell Duct Insulation	390	SF	East & West Crawl Space (under Assembly Hall)	CHR	TSI	Y	DIST	60		No	Damaged or significantly damaged friable thermal system insulating ACBM	3	HIGH

# Chicago Public Schools

School Haley, Alex School Unit 22301 Building ID 2360  
Address 11411 S Eggleston Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

Reinspection Date <b>9/2/2019</b>
Inspector Name <b>Shawn Brown</b>
<b>100-00440</b> <b>5/15/2020</b>
Inspector's IDPH License Number / Expiration Date

### Inspector's Comments

HA Number:	Inspector Comments:
01	NOT OBSERVED-Multiple Years
02	
08	NOT OBSERVED Multiple Years
09	
11	
12	
13	
14	
15	
16	
17	NOT OBSERVED
17A	VFT NOT OBSERVED
18	Room 108 Abated
18A	Room 108 Abated
19	Room 108 Abated
19A	Room 108 Abated
20	
20A	
21	
21A	
22	
23	NOT OBSERVED
24	



# Chicago Public Schools

**School** Haley, Alex School **Unit** 22301 **Building ID** 2360  
**Address** 11411 S Eggleston **Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
25	
25M	
26	
27	NOT OBSERVED
27M	NOT OBSERVED
28	NOT OBSERVED
28M	NOT OBSERVED
29	
29M	
30	
30M	
31	
31M	
A	
B	
C	
D	
E	
F	
G	
H	
I	

**Table II**

**Management Planner's Review**

---

# Chicago Public Schools

**School** Haley, Alex School  
**Address** 11411 S Eggleston

**Unit** 22301  
Chicago, IL, 60628

**Building ID** 2360  
**Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

### Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
01	Linoleum-NOT OBSERVED			Kitchen		MISC					
02	12x12 Brown Speckled Floor Tile	7,116	SF	All Corridors - 1st and 2nd Floors	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
08	Linoleum Mastic-NOT OBSERVED			Kitchen		MISC					
09	12x12 Brown Speckled Floor Tile Mastic	7,116	SF	All Corridors - 1st and 2nd Floors	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
11	Black Mopboard			Teachers' Lounge and Cafeteria	No ACBM	MISC					
12	Black Mopboard Mastic			Teachers' Lounge and Cafeteria	No ACBM	MISC					
13	Heating Pipe	80	LF	Boiler Room	Assumed	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
14	Transite Partitions			All Washrooms Throughout The Facility	No ACBM	MISC					
15	Fire Brick in Incinerator	50	SF	Boiler Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
16	Terrazzo	5,100	SF	Throughout School	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
17	12x12 Sand Colored Floor Tile	384	SF	Main Office	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
17A	12x12 Sand Colored Floor Tile Mastic	384	SF	Main Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
18	12x12 Cream Colored Floor Tile	470	SF	Rooms 124 (Teachers' Lounge) and Kitchen Closet	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
18A	12x12 Cream Colored Floor Tile Mastic	470	SF	Rooms 124 (Teachers' Lounge) and Kitchen Closet	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
19	12x12 Tan Floor Tile	370	SF	Rooms 124 (Teachers' Lounge)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
19A	12x12 Tan Floor Tile Mastic	370	SF	Rooms 124 (Teachers' Lounge)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
20	12x12 Light Brown Floor Tile	1,680	SF	Room 117 (Library) and 1st & 2nd Floor Storage Rooms	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
20A	12x12 Light Brown Floor Tile Mastic	1,680	SF	Room 117 (Library) and 1st & 2nd Floor Storage Rooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
21	12x12 White w/Black Streaks Floor Tile	1,264	SF	Room 116 (Lunchroom)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
21A	12x12 White w/Black Streaks Floor Tile Mastic	1,264	SF	Room 116 (Lunchroom)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
22	Ceramic Tile Grout			All Washrooms at the Facility	No ACBM	MISC					
23	Grey Carpet Mastic	384	SF	Main Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
24	Hardcoat Plaster	200,000	SF	1st and 2nd Floors- Throughout	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
25	1 x 1 White Fissured Ceiling Tile	1,400	SF	Room 121 (Library)	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
25M	1 x 1 White Fissured Ceiling Tile Mastic	1,400	SF	Room 121 (Library)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
26	2 x 4 White Fissured Ceiling Tile	720	SF	Room 122 (Kindergarden)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
27	12 x 12 White with Beige Specs Floor Tile	210	SF	Kitchen	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
27M	12 x 12 White with Beige Specs Floor Tile Mastic	210	SF	Kitchen	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

School Haley, Alex School

Unit 22301

Building ID 2360

Address 11411 S Eggleston

Chicago, IL, 60628

Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

### Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
28	12 x 12 Off White with Beige Specs Floor Tile	210	SF	Kitchen	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
28M	12 x 12 Off White with Beige Specs Floor Tile Mastic	210	SF	Kitchen	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
29	12x12 Light Gray w/White Specks Vinyl Floor Tile	1,100	SF	Cafeteria and Kitchen	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
29M	12 x 12 Light Gray w/White Specks Vinyl Floor Tile Mastic	1,100	SF	Cafeteria and Kitchen	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
30	12 x 12 Blue Speckled Vinyl Floor Tile	600	SF	Main Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
30M	12 x 12 Blue Speckled Vinyl Floor Tile Mastic	600	SF	Main Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
31	12x12 Maroon w/Dark Brown Specks Vinyl Floor Tile	50	SF	Elevator Vestibule	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
31M	12x12 Maroon w/Dark Brown Specks Vinyl Floor Tile Mastic	50	SF	Elevator Vestibule	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
A	Boiler Insulation	2,200	SF	Boiler Room	Chrysotile	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
B	Insulation on Water Return Tanks	80	SF	Boiler Room	Chrysotile	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
C	Heating and Water Pipe Insulation	889	LF	Boiler Room, Mechanical Room, Air Tunnels, Pipe Chases	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
D	MJP E/F/V on Heating and Water Pipe Insulation	78	LF	Boiler Room, Mechanical Room, Air Tunnels, Pipe Chases	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
E	Insulation on Heating Pipes	180	LF	Boiler Room, Boiler Room Tunnel, Mechanical Room	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
F	Magblock Pipe Joint Insulation	15	LF	Boiler Room and Throughout Basement Pipe Chases	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
G	Heating and Water Pipe Insulation	1,465	LF	Boiler Room, Pipe Chases, Mechanical Room, Air Tunnels, Unexcavated Crawl Spaces	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
H	MJP E/F/V on Heating and Water Pipe Insulation	386	LF	Boiler Room, Pipe Chases, Mechanical Room, Air Tunnels, Unexcavated Crawl Spaces	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
I	Aircell Duct Insulation	390	SF	East & West Crawl Space (under Assembly Hall)	Chrysotile	TSI	Yes	60	SF	1 Damaged or significantly damaged friable thermal system insulating ACBM	Repair

# Chicago Public Schools

**School** Haley, Alex School  
**Address** 11411 S Eggleston

**Unit** 22301  
 Chicago, IL, 60628

**Building ID** 2360  
**Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

*Management Planner's Comments Summarized at the End of the Report*

Review Date	10/01/2019
Manager Planner Name	John Fenn
100-09786	5/15/2020
Manager IDPH License No/Expiration	

HA Number	Management Comments
01	No response action based on previous MPs
02	
08	No response action based on previous MPs
09	
11	
12	
13	
14	

# Chicago Public Schools

**School** Haley, Alex School  
**Address** 11411 S Eggleston

**Unit** 22301  
 Chicago, IL, 60628

**Building ID** 2360  
**Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
15	
16	
17	
17A	
18	
18A	
19	
19A	
20	
20A	
21	
21A	
22	
23	
24	
25	
25M	
26	
27	
27M	
28	
28M	
29	
29M	
30	
30M	

# Chicago Public Schools

**School** Haley, Alex School  
**Address** 11411 S Eggleston

**Unit** 22301  
Chicago, IL, 60628

**Building ID** 2360  
**Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
31	
31M	
A	
B	
C	
D	
E	
F	
G	
H	
I	

# Chicago Public Schools

TEM Environmental, Inc.

## 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22301** BUIDLING ID: **2360**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shawn Brown**  
SCHOOL NAME: **Haley, Alex School** INSPECTION DATE: **9/2/2019**  
ADDRESS: **11411 S Eggleston** IDPH LICENSE NO: **100-00440**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **01**  
MATERIAL DESCRIPTION: **Linoleum-NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Kitchen**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **NOT OBSERVED-Multiple Years**

Inspector's Signature: \_\_\_\_\_ Date: **09/02/2019**



# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22301** BUIDLING ID: **2360**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Haley, Alex School** REVIEW DATE: **10/1/2019**  
ADDRESS: **11411 S Eggleston** IDPH LICENSE NO: **100-00440**

---

HOMOGENEOUS AREA: **01**

MATERIAL DESCRIPTION: **Linoleum-NOT OBSERVED**

MATERIAL LOCATION: **Kitchen**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

No response action based on previous MPs

Management Planner's Signature: \_\_\_\_\_ Date: **10/01/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **22301**    BUILDING ID: **2360**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Shawn Brown**  
SCHOOL NAME: **Haley, Alex School**    INSPECTION DATE: **9/2/2019**  
ADDRESS: **11411 S Eggleston**    IDPH LICENSE NO: **100-00440**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **02**  
MATERIAL DESCRIPTION: **12x12 Brown Speckled Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile**    FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **All Corridors - 1st and 2nd Floors**  
MATERIAL QUANTITY: **7116**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/02/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22301** BUIDLING ID: **2360**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Haley, Alex School** REVIEW DATE: **10/1/2019**  
ADDRESS: **11411 S Eggleston** IDPH LICENSE NO: **100-00440**

---

HOMOGENEOUS AREA: **02**  
MATERIAL DESCRIPTION: **12x12 Brown Speckled Floor Tile**  
MATERIAL LOCATION: **All Corridors - 1st and 2nd Floors**  
MATERIAL QUANTITY: **7116** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/01/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22301** BUIDLING ID: **2360**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shawn Brown**  
SCHOOL NAME: **Haley, Alex School** INSPECTION DATE: **9/2/2019**  
ADDRESS: **11411 S Eggleston** IDPH LICENSE NO: **100-00440**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **08**  
MATERIAL DESCRIPTION: **Linoleum Mastic-NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Kitchen**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **NOT OBSERVED Multiple Years**

Inspector's Signature: \_\_\_\_\_ Date: **09/02/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22301** BUIDLING ID: **2360**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Haley, Alex School** REVIEW DATE: **10/1/2019**  
ADDRESS: **11411 S Eggleston** IDPH LICENSE NO: **100-00440**

---

HOMOGENEOUS AREA: **08**

MATERIAL DESCRIPTION: **Linoleum Mastic-NOT OBSERVED**

MATERIAL LOCATION: **Kitchen**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

No response action based on previous MPs

Management Planner's Signature: \_\_\_\_\_ Date: **10/01/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22301** BUIDLING ID: **2360**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shawn Brown**  
SCHOOL NAME: **Haley, Alex School** INSPECTION DATE: **9/2/2019**  
ADDRESS: **11411 S Eggleston** IDPH LICENSE NO: **100-00440**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **09**  
MATERIAL DESCRIPTION: **12x12 Brown Speckled Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **All Corridors - 1st and 2nd Floors**  
MATERIAL QUANTITY: **7116** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/02/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22301** BUIDLING ID: **2360**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Haley, Alex School** REVIEW DATE: **10/1/2019**  
ADDRESS: **11411 S Eggleston** IDPH LICENSE NO: **100-00440**

---

HOMOGENEOUS AREA: **09**  
MATERIAL DESCRIPTION: **12x12 Brown Speckled Floor Tile Mastic**  
MATERIAL LOCATION: **All Corridors - 1st and 2nd Floors**  
MATERIAL QUANTITY: **7116** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/01/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22301** BUIDLING ID: **2360**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shawn Brown**  
SCHOOL NAME: **Haley, Alex School** INSPECTION DATE: **9/2/2019**  
ADDRESS: **11411 S Eggleston** IDPH LICENSE NO: **100-00440**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11**  
MATERIAL DESCRIPTION: **Black Mopboard**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Teachers' Lounge and Cafeteria**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/02/2019**



# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22301** BUIDLING ID: **2360**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Haley, Alex School** REVIEW DATE: **10/1/2019**  
ADDRESS: **11411 S Eggleston** IDPH LICENSE NO: **100-00440**

---

HOMOGENEOUS AREA: **11**

MATERIAL DESCRIPTION: **Black Mopboard**

MATERIAL LOCATION: **Teachers' Lounge and Cafeteria**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/01/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22301** BUILDING ID: **2360**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shawn Brown**  
SCHOOL NAME: **Haley, Alex School** INSPECTION DATE: **9/2/2019**  
ADDRESS: **11411 S Eggleston** IDPH LICENSE NO: **100-00440**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12**  
MATERIAL DESCRIPTION: **Black Mopboard Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Teachers' Lounge and Cafeteria**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/02/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22301** BUIDLING ID: **2360**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Haley, Alex School** REVIEW DATE: **10/1/2019**  
ADDRESS: **11411 S Eggleston** IDPH LICENSE NO: **100-00440**

---

HOMOGENEOUS AREA: **12**

MATERIAL DESCRIPTION: **Black Mopboard Mastic**

MATERIAL LOCATION: **Teachers' Lounge and Cafeteria**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/01/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22301** BUIDLING ID: **2360**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shawn Brown**  
SCHOOL NAME: **Haley, Alex School** INSPECTION DATE: **9/2/2019**  
ADDRESS: **11411 S Eggleston** IDPH LICENSE NO: **100-00440**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13**  
MATERIAL DESCRIPTION: **Heating Pipe**  
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Boiler Room**  
MATERIAL QUANTITY: **80** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/02/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22301** BUIDLING ID: **2360**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Haley, Alex School** REVIEW DATE: **10/1/2019**  
ADDRESS: **11411 S Eggleston** IDPH LICENSE NO: **100-00440**

---

HOMOGENEOUS AREA: **13**  
MATERIAL DESCRIPTION: **Heating Pipe**  
MATERIAL LOCATION: **Boiler Room**  
MATERIAL QUANTITY: **80** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/01/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22301** BUILDING ID: **2360**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shawn Brown**  
SCHOOL NAME: **Haley, Alex School** INSPECTION DATE: **9/2/2019**  
ADDRESS: **11411 S Eggleston** IDPH LICENSE NO: **100-00440**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14**  
MATERIAL DESCRIPTION: **Transite Partitiions**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **All Washrooms Throughout The Facility**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/02/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22301** BUIDLING ID: **2360**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Haley, Alex School** REVIEW DATE: **10/1/2019**  
ADDRESS: **11411 S Eggleston** IDPH LICENSE NO: **100-00440**

---

HOMOGENEOUS AREA: **14**

MATERIAL DESCRIPTION: **Transite Partitiions**

MATERIAL LOCATION: **All Washrooms Throughout The Facility**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/01/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22301** BUIDLING ID: **2360**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shawn Brown**  
SCHOOL NAME: **Haley, Alex School** INSPECTION DATE: **9/2/2019**  
ADDRESS: **11411 S Eggleston** IDPH LICENSE NO: **100-00440**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15**  
MATERIAL DESCRIPTION: **Fire Brick in Incinerator**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Boiler Room**  
MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/02/2019



# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22301** BUIDLING ID: **2360**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Haley, Alex School** REVIEW DATE: **10/1/2019**  
ADDRESS: **11411 S Eggleston** IDPH LICENSE NO: **100-00440**

---

HOMOGENEOUS AREA: **15**  
MATERIAL DESCRIPTION: **Fire Brick in Incinerator**  
MATERIAL LOCATION: **Boiler Room**  
MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/01/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22301** BUIDLING ID: **2360**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shawn Brown**  
SCHOOL NAME: **Haley, Alex School** INSPECTION DATE: **9/2/2019**  
ADDRESS: **11411 S Eggleston** IDPH LICENSE NO: **100-00440**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16**  
MATERIAL DESCRIPTION: **Terrazzo**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout School**  
MATERIAL QUANTITY: **5100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/02/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22301** BUIDLING ID: **2360**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Haley, Alex School** REVIEW DATE: **10/1/2019**  
ADDRESS: **11411 S Eggleston** IDPH LICENSE NO: **100-00440**

---

HOMOGENEOUS AREA: **16**  
MATERIAL DESCRIPTION: **Terrazzo**  
MATERIAL LOCATION: **Throughout School**  
MATERIAL QUANTITY: **5100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/01/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22301** BUIDLING ID: **2360**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shawn Brown**  
SCHOOL NAME: **Haley, Alex School** INSPECTION DATE: **9/2/2019**  
ADDRESS: **11411 S Eggleston** IDPH LICENSE NO: **100-00440**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17**  
MATERIAL DESCRIPTION: **12x12 Sand Colored Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Main Office**  
MATERIAL QUANTITY: **384** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**  
COMMENTS: **NOT OBSERVED**

Inspector's Signature: \_\_\_\_\_ Date: 09/02/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22301** BUIDLING ID: **2360**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Haley, Alex School** REVIEW DATE: **10/1/2019**  
ADDRESS: **11411 S Eggleston** IDPH LICENSE NO: **100-00440**

---

HOMOGENEOUS AREA: **17**  
MATERIAL DESCRIPTION: **12x12 Sand Colored Floor Tile**  
MATERIAL LOCATION: **Main Office**  
MATERIAL QUANTITY: **384** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/01/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22301** BUIDLING ID: **2360**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shawn Brown**  
SCHOOL NAME: **Haley, Alex School** INSPECTION DATE: **9/2/2019**  
ADDRESS: **11411 S Eggleston** IDPH LICENSE NO: **100-00440**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17A**  
MATERIAL DESCRIPTION: **12x12 Sand Colored Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Main Office**  
MATERIAL QUANTITY: **384** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**  
COMMENTS: **VFT NOT OBSERVED**

Inspector's Signature: \_\_\_\_\_ Date: 09/02/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22301** BUIDLING ID: **2360**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Haley, Alex School** REVIEW DATE: **10/1/2019**  
ADDRESS: **11411 S Eggleston** IDPH LICENSE NO: **100-00440**

---

HOMOGENEOUS AREA: **17A**  
MATERIAL DESCRIPTION: **12x12 Sand Colored Floor Tile Mastic**  
MATERIAL LOCATION: **Main Office**  
MATERIAL QUANTITY: **384** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/01/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **22301**    BUILDING ID: **2360**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Shawn Brown**  
SCHOOL NAME: **Haley, Alex School**    INSPECTION DATE: **9/2/2019**  
ADDRESS: **11411 S Eggleston**    IDPH LICENSE NO: **100-00440**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18**  
MATERIAL DESCRIPTION: **12x12 Cream Colored Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 124 (Teachers' Lounge) and Kitchen Closet**  
MATERIAL QUANTITY: **470**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**  
COMMENTS: **Room 108 Abated**

Inspector's Signature: \_\_\_\_\_ Date: 09/02/2019



# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22301** BUIDLING ID: **2360**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Haley, Alex School** REVIEW DATE: **10/1/2019**  
ADDRESS: **11411 S Eggleston** IDPH LICENSE NO: **100-00440**

---

HOMOGENEOUS AREA: **18**  
MATERIAL DESCRIPTION: **12x12 Cream Colored Floor Tile**  
MATERIAL LOCATION: **Rooms 124 (Teachers' Lounge) and Kitchen Closet**  
MATERIAL QUANTITY: **470** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/01/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **22301**    BUILDING ID: **2360**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Shawn Brown**  
SCHOOL NAME: **Haley, Alex School**    INSPECTION DATE: **9/2/2019**  
ADDRESS: **11411 S Eggleston**    IDPH LICENSE NO: **100-00440**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18A**  
MATERIAL DESCRIPTION: **12x12 Cream Colored Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile**    FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 124 (Teachers' Lounge) and Kitchen Closet**  
MATERIAL QUANTITY: **470**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**  
COMMENTS: **Room 108 Abated**

Inspector's Signature: \_\_\_\_\_ Date: 09/02/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22301** BUIDLING ID: **2360**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Haley, Alex School** REVIEW DATE: **10/1/2019**  
ADDRESS: **11411 S Eggleston** IDPH LICENSE NO: **100-00440**

---

HOMOGENEOUS AREA: **18A**  
MATERIAL DESCRIPTION: **12x12 Cream Colored Floor Tile Mastic**  
MATERIAL LOCATION: **Rooms 124 (Teachers' Lounge) and Kitchen Closet**  
MATERIAL QUANTITY: **470** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/01/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22301** BUIDLING ID: **2360**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shawn Brown**  
SCHOOL NAME: **Haley, Alex School** INSPECTION DATE: **9/2/2019**  
ADDRESS: **11411 S Eggleston** IDPH LICENSE NO: **100-00440**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19**  
MATERIAL DESCRIPTION: **12x12 Tan Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 124 (Teachers' Lounge)**  
MATERIAL QUANTITY: **370** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**  
COMMENTS: **Room 108 Abated**

Inspector's Signature: \_\_\_\_\_ Date: 09/02/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22301** BUIDLING ID: **2360**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Haley, Alex School** REVIEW DATE: **10/1/2019**  
ADDRESS: **11411 S Eggleston** IDPH LICENSE NO: **100-00440**

---

HOMOGENEOUS AREA: **19**  
MATERIAL DESCRIPTION: **12x12 Tan Floor Tile**  
MATERIAL LOCATION: **Rooms 124 (Teachers' Lounge)**  
MATERIAL QUANTITY: **370** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/01/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22301** BUIDLING ID: **2360**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shawn Brown**  
SCHOOL NAME: **Haley, Alex School** INSPECTION DATE: **9/2/2019**  
ADDRESS: **11411 S Eggleston** IDPH LICENSE NO: **100-00440**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19A**  
MATERIAL DESCRIPTION: **12x12 Tan Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 124 (Teachers' Lounge)**  
MATERIAL QUANTITY: **370** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**  
COMMENTS: **Room 108 Abated**

Inspector's Signature: \_\_\_\_\_ Date: 09/02/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22301** BUIDLING ID: **2360**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Haley, Alex School** REVIEW DATE: **10/1/2019**  
ADDRESS: **11411 S Eggleston** IDPH LICENSE NO: **100-00440**

---

HOMOGENEOUS AREA: **19A**  
MATERIAL DESCRIPTION: **12x12 Tan Floor Tile Mastic**  
MATERIAL LOCATION: **Rooms 124 (Teachers' Lounge)**  
MATERIAL QUANTITY: **370** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/01/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22301** BUIDLING ID: **2360**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shawn Brown**  
SCHOOL NAME: **Haley, Alex School** INSPECTION DATE: **9/2/2019**  
ADDRESS: **11411 S Eggleston** IDPH LICENSE NO: **100-00440**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**  
MATERIAL DESCRIPTION: **12x12 Light Brown Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 117 (Library) and 1st & 2nd Floor Storage Rooms**  
MATERIAL QUANTITY: **1680** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/02/2019



# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22301** BUIDLING ID: **2360**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Haley, Alex School** REVIEW DATE: **10/1/2019**  
ADDRESS: **11411 S Eggleston** IDPH LICENSE NO: **100-00440**

---

HOMOGENEOUS AREA: **20**  
MATERIAL DESCRIPTION: **12x12 Light Brown Floor Tile**  
MATERIAL LOCATION: **Room 117 (Library) and 1st & 2nd Floor Storage Rooms**  
MATERIAL QUANTITY: **1680** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/01/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22301** BUIDLING ID: **2360**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shawn Brown**  
SCHOOL NAME: **Haley, Alex School** INSPECTION DATE: **9/2/2019**  
ADDRESS: **11411 S Eggleston** IDPH LICENSE NO: **100-00440**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20A**  
MATERIAL DESCRIPTION: **12x12 Light Brown Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 117 (Library) and 1st & 2nd Floor Storage Rooms**  
MATERIAL QUANTITY: **1680** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/02/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22301** BUIDLING ID: **2360**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Haley, Alex School** REVIEW DATE: **10/1/2019**  
ADDRESS: **11411 S Eggleston** IDPH LICENSE NO: **100-00440**

---

HOMOGENEOUS AREA: **20A**  
MATERIAL DESCRIPTION: **12x12 Light Brown Floor Tile Mastic**  
MATERIAL LOCATION: **Room 117 (Library) and 1st & 2nd Floor Storage Rooms**  
MATERIAL QUANTITY: **1680** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/01/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22301** BUIDLING ID: **2360**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shawn Brown**  
SCHOOL NAME: **Haley, Alex School** INSPECTION DATE: **9/2/2019**  
ADDRESS: **11411 S Eggleston** IDPH LICENSE NO: **100-00440**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21**  
MATERIAL DESCRIPTION: **12x12 White w/Black Streaks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 116 (Lunchroom)**  
MATERIAL QUANTITY: **1264** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/02/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22301** BUIDLING ID: **2360**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Haley, Alex School** REVIEW DATE: **10/1/2019**  
ADDRESS: **11411 S Eggleston** IDPH LICENSE NO: **100-00440**

---

HOMOGENEOUS AREA: **21**  
MATERIAL DESCRIPTION: **12x12 White w/Black Streaks Floor Tile**  
MATERIAL LOCATION: **Room 116 (Lunchroom)**  
MATERIAL QUANTITY: **1264** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/01/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22301** BUIDLING ID: **2360**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shawn Brown**  
SCHOOL NAME: **Haley, Alex School** INSPECTION DATE: **9/2/2019**  
ADDRESS: **11411 S Eggleston** IDPH LICENSE NO: **100-00440**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21A**  
MATERIAL DESCRIPTION: **12x12 White w/Black Streaks Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 116 (Lunchroom)**  
MATERIAL QUANTITY: **1264** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/02/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22301** BUIDLING ID: **2360**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Haley, Alex School** REVIEW DATE: **10/1/2019**  
ADDRESS: **11411 S Eggleston** IDPH LICENSE NO: **100-00440**

---

HOMOGENEOUS AREA: **21A**  
MATERIAL DESCRIPTION: **12x12 White w/Black Streaks Floor Tile Mastic**  
MATERIAL LOCATION: **Room 116 (Lunchroom)**  
MATERIAL QUANTITY: **1264** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/01/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22301** BUIDLING ID: **2360**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shawn Brown**  
SCHOOL NAME: **Haley, Alex School** INSPECTION DATE: **9/2/2019**  
ADDRESS: **11411 S Eggleston** IDPH LICENSE NO: **100-00440**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22**  
MATERIAL DESCRIPTION: **Ceramic Tile Grout**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **All Washrooms at the Facility**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/02/2019**



# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22301** BUIDLING ID: **2360**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Haley, Alex School** REVIEW DATE: **10/1/2019**  
ADDRESS: **11411 S Eggleston** IDPH LICENSE NO: **100-00440**

---

HOMOGENEOUS AREA: **22**

MATERIAL DESCRIPTION: **Ceramic Tile Grout**

MATERIAL LOCATION: **All Washrooms at the Facility**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/01/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22301** BUIDLING ID: **2360**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shawn Brown**  
SCHOOL NAME: **Haley, Alex School** INSPECTION DATE: **9/2/2019**  
ADDRESS: **11411 S Eggleston** IDPH LICENSE NO: **100-00440**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23**  
MATERIAL DESCRIPTION: **Grey Carpet Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Main Office**  
MATERIAL QUANTITY: **384** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**  
COMMENTS: **NOT OBSERVED**

Inspector's Signature: \_\_\_\_\_ Date: **09/02/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22301** BUIDLING ID: **2360**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Haley, Alex School** REVIEW DATE: **10/1/2019**  
ADDRESS: **11411 S Eggleston** IDPH LICENSE NO: **100-00440**

---

HOMOGENEOUS AREA: **23**  
MATERIAL DESCRIPTION: **Grey Carpet Mastic**  
MATERIAL LOCATION: **Main Office**  
MATERIAL QUANTITY: **384** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/01/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **22301**    BUILDING ID: **2360**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Shawn Brown**  
SCHOOL NAME: **Haley, Alex School**    INSPECTION DATE: **9/2/2019**  
ADDRESS: **11411 S Eggleston**    IDPH LICENSE NO: **100-00440**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **24**  
MATERIAL DESCRIPTION: **Hardcoat Plaster**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st and 2nd Floors- Throughout**  
MATERIAL QUANTITY: **200000**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/02/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22301** BUIDLING ID: **2360**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Haley, Alex School** REVIEW DATE: **10/1/2019**  
ADDRESS: **11411 S Eggleston** IDPH LICENSE NO: **100-00440**

---

HOMOGENEOUS AREA: **24**  
MATERIAL DESCRIPTION: **Hardcoat Plaster**  
MATERIAL LOCATION: **1st and 2nd Floors- Throughout**  
MATERIAL QUANTITY: **200000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/01/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22301** BUIDLING ID: **2360**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shawn Brown**  
SCHOOL NAME: **Haley, Alex School** INSPECTION DATE: **9/2/2019**  
ADDRESS: **11411 S Eggleston** IDPH LICENSE NO: **100-00440**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25**  
MATERIAL DESCRIPTION: **1 x 1 White Fissured Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 121 (Library)**  
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/02/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22301** BUIDLING ID: **2360**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Haley, Alex School** REVIEW DATE: **10/1/2019**  
ADDRESS: **11411 S Eggleston** IDPH LICENSE NO: **100-00440**

---

HOMOGENEOUS AREA: **25**  
MATERIAL DESCRIPTION: **1 x 1 White Fissured Ceiling Tile**  
MATERIAL LOCATION: **Room 121 (Library)**  
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/01/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **22301**    BUILDING ID: **2360**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Shawn Brown**  
SCHOOL NAME: **Haley, Alex School**    INSPECTION DATE: **9/2/2019**  
ADDRESS: **11411 S Eggleston**    IDPH LICENSE NO: **100-00440**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25M**  
MATERIAL DESCRIPTION: **1 x 1 White Fissured Ceiling Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 121 (Library)**  
MATERIAL QUANTITY: **1400**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/02/2019**



# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22301** BUIDLING ID: **2360**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Haley, Alex School** REVIEW DATE: **10/1/2019**  
ADDRESS: **11411 S Eggleston** IDPH LICENSE NO: **100-00440**

---

HOMOGENEOUS AREA: **25M**  
MATERIAL DESCRIPTION: **1 x 1 White Fissured Ceiling Tile Mastic**  
MATERIAL LOCATION: **Room 121 (Library)**  
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/01/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22301** BUIDLING ID: **2360**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shawn Brown**  
SCHOOL NAME: **Haley, Alex School** INSPECTION DATE: **9/2/2019**  
ADDRESS: **11411 S Eggleston** IDPH LICENSE NO: **100-00440**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26**  
MATERIAL DESCRIPTION: **2 x 4 White Fissured Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 122 (Kindergarden)**  
MATERIAL QUANTITY: **720** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/02/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22301** BUIDLING ID: **2360**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Haley, Alex School** REVIEW DATE: **10/1/2019**  
ADDRESS: **11411 S Eggleston** IDPH LICENSE NO: **100-00440**

---

HOMOGENEOUS AREA: **26**  
MATERIAL DESCRIPTION: **2 x 4 White Fissured Ceiling Tile**  
MATERIAL LOCATION: **Room 122 (Kindergarden)**  
MATERIAL QUANTITY: **720** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/01/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **22301**    BUILDING ID: **2360**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Shawn Brown**  
SCHOOL NAME: **Haley, Alex School**    INSPECTION DATE: **9/2/2019**  
ADDRESS: **11411 S Eggleston**    IDPH LICENSE NO: **100-00440**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27**  
MATERIAL DESCRIPTION: **12 x 12 White with Beige Specs Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Kitchen**  
MATERIAL QUANTITY: **210**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**  
COMMENTS: **NOT OBSERVED**

Inspector's Signature: \_\_\_\_\_ Date: 09/02/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22301** BUIDLING ID: **2360**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Haley, Alex School** REVIEW DATE: **10/1/2019**  
ADDRESS: **11411 S Eggleston** IDPH LICENSE NO: **100-00440**

---

HOMOGENEOUS AREA: **27**  
MATERIAL DESCRIPTION: **12 x 12 White with Beige Specs Floor Tile**  
MATERIAL LOCATION: **Kitchen**  
MATERIAL QUANTITY: **210** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/01/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22301** BUIDLING ID: **2360**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shawn Brown**  
SCHOOL NAME: **Haley, Alex School** INSPECTION DATE: **9/2/2019**  
ADDRESS: **11411 S Eggleston** IDPH LICENSE NO: **100-00440**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27M**  
MATERIAL DESCRIPTION: **12 x 12 White with Beige Specs Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Kitchen**  
MATERIAL QUANTITY: **210** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**  
COMMENTS: **NOT OBSERVED**

Inspector's Signature: \_\_\_\_\_ Date: 09/02/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22301** BUIDLING ID: **2360**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Haley, Alex School** REVIEW DATE: **10/1/2019**  
ADDRESS: **11411 S Eggleston** IDPH LICENSE NO: **100-00440**

---

HOMOGENEOUS AREA: **27M**  
MATERIAL DESCRIPTION: **12 x 12 White with Beige Specs Floor Tile Mastic**  
MATERIAL LOCATION: **Kitchen**  
MATERIAL QUANTITY: **210** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/01/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **22301**    BUILDING ID: **2360**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Shawn Brown**  
SCHOOL NAME: **Haley, Alex School**    INSPECTION DATE: **9/2/2019**  
ADDRESS: **11411 S Eggleston**    IDPH LICENSE NO: **100-00440**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28**  
MATERIAL DESCRIPTION: **12 x 12 Off White with Beige Specs Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Kitchen**  
MATERIAL QUANTITY: **210**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**  
COMMENTS: **NOT OBSERVED**

Inspector's Signature: \_\_\_\_\_ Date: **09/02/2019**



# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22301** BUIDLING ID: **2360**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Haley, Alex School** REVIEW DATE: **10/1/2019**  
ADDRESS: **11411 S Eggleston** IDPH LICENSE NO: **100-00440**

---

HOMOGENEOUS AREA: **28**  
MATERIAL DESCRIPTION: **12 x 12 Off White with Beige Specs Floor Tile**  
MATERIAL LOCATION: **Kitchen**  
MATERIAL QUANTITY: **210** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/01/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22301** BUIDLING ID: **2360**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shawn Brown**  
SCHOOL NAME: **Haley, Alex School** INSPECTION DATE: **9/2/2019**  
ADDRESS: **11411 S Eggleston** IDPH LICENSE NO: **100-00440**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28M**  
MATERIAL DESCRIPTION: **12 x 12 Off White with Beige Specs Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Kitchen**  
MATERIAL QUANTITY: **210** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**  
COMMENTS: **NOT OBSERVED**

Inspector's Signature: \_\_\_\_\_ Date: **09/02/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22301** BUIDLING ID: **2360**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Haley, Alex School** REVIEW DATE: **10/1/2019**  
ADDRESS: **11411 S Eggleston** IDPH LICENSE NO: **100-00440**

---

HOMOGENEOUS AREA: **28M**  
MATERIAL DESCRIPTION: **12 x 12 Off White with Beige Specs Floor Tile Mastic**  
MATERIAL LOCATION: **Kitchen**  
MATERIAL QUANTITY: **210** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/01/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22301** BUIDLING ID: **2360**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shawn Brown**  
SCHOOL NAME: **Haley, Alex School** INSPECTION DATE: **9/2/2019**  
ADDRESS: **11411 S Eggleston** IDPH LICENSE NO: **100-00440**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **29**  
MATERIAL DESCRIPTION: **12x12 Light Gray w/White Specks Vinyl Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Cafeteria and Kitchen**  
MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/02/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22301** BUIDLING ID: **2360**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Haley, Alex School** REVIEW DATE: **10/1/2019**  
ADDRESS: **11411 S Eggleston** IDPH LICENSE NO: **100-00440**

---

HOMOGENEOUS AREA: **29**  
MATERIAL DESCRIPTION: **12x12 Light Gray w/White Specks Vinyl Floor Tile**  
MATERIAL LOCATION: **Cafeteria and Kitchen**  
MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/01/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **22301**    BUILDING ID: **2360**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Shawn Brown**  
SCHOOL NAME: **Haley, Alex School**    INSPECTION DATE: **9/2/2019**  
ADDRESS: **11411 S Eggleston**    IDPH LICENSE NO: **100-00440**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **29M**  
MATERIAL DESCRIPTION: **12 x 12 Light Gray w/White Specks Vinyl Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Cafeteria and Kitchen**  
MATERIAL QUANTITY: **1100**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/02/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22301** BUIDLING ID: **2360**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Haley, Alex School** REVIEW DATE: **10/1/2019**  
ADDRESS: **11411 S Eggleston** IDPH LICENSE NO: **100-00440**

---

HOMOGENEOUS AREA: **29M**  
MATERIAL DESCRIPTION: **12 x 12 Light Gray w/White Specks Vinyl Floor Tile Mastic**  
MATERIAL LOCATION: **Cafeteria and Kitchen**  
MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/01/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22301** BUIDLING ID: **2360**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shawn Brown**  
SCHOOL NAME: **Haley, Alex School** INSPECTION DATE: **9/2/2019**  
ADDRESS: **11411 S Eggleston** IDPH LICENSE NO: **100-00440**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **30**  
MATERIAL DESCRIPTION: **12 x 12 Blue Speckled Vinyl Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Main Office**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/02/2019



# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22301** BUIDLING ID: **2360**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Haley, Alex School** REVIEW DATE: **10/1/2019**  
ADDRESS: **11411 S Eggleston** IDPH LICENSE NO: **100-00440**

---

HOMOGENEOUS AREA: **30**  
MATERIAL DESCRIPTION: **12 x 12 Blue Speckled Vinyl Floor Tile**  
MATERIAL LOCATION: **Main Office**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/01/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22301** BUIDLING ID: **2360**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shawn Brown**  
SCHOOL NAME: **Haley, Alex School** INSPECTION DATE: **9/2/2019**  
ADDRESS: **11411 S Eggleston** IDPH LICENSE NO: **100-00440**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **30M**  
MATERIAL DESCRIPTION: **12 x 12 Blue Speckled Vinyl Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Main Office**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/02/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22301** BUIDLING ID: **2360**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Haley, Alex School** REVIEW DATE: **10/1/2019**  
ADDRESS: **11411 S Eggleston** IDPH LICENSE NO: **100-00440**

---

HOMOGENEOUS AREA: **30M**  
MATERIAL DESCRIPTION: **12 x 12 Blue Speckled Vinyl Floor Tile Mastic**  
MATERIAL LOCATION: **Main Office**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/01/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **22301**    BUILDING ID: **2360**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Shawn Brown**  
SCHOOL NAME: **Haley, Alex School**    INSPECTION DATE: **9/2/2019**  
ADDRESS: **11411 S Eggleston**    IDPH LICENSE NO: **100-00440**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **31**  
MATERIAL DESCRIPTION: **12x12 Maroon w/Dark Brown Specks Vinyl Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Elevator Vestibule**  
MATERIAL QUANTITY: **50**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/02/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22301** BUIDLING ID: **2360**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Haley, Alex School** REVIEW DATE: **10/1/2019**  
ADDRESS: **11411 S Eggleston** IDPH LICENSE NO: **100-00440**

---

HOMOGENEOUS AREA: **31**  
MATERIAL DESCRIPTION: **12x12 Maroon w/Dark Brown Specks Vinyl Floor Tile**  
MATERIAL LOCATION: **Elevator Vestibule**  
MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/01/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22301** BUIDLING ID: **2360**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shawn Brown**  
SCHOOL NAME: **Haley, Alex School** INSPECTION DATE: **9/2/2019**  
ADDRESS: **11411 S Eggleston** IDPH LICENSE NO: **100-00440**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **31M**  
MATERIAL DESCRIPTION: **12x12 Maroon w/Dark Brown Specks Vinyl Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Elevator Vestibule**  
MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/02/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22301** BUIDLING ID: **2360**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Haley, Alex School** REVIEW DATE: **10/1/2019**  
ADDRESS: **11411 S Eggleston** IDPH LICENSE NO: **100-00440**

---

HOMOGENEOUS AREA: **31M**  
MATERIAL DESCRIPTION: **12x12 Maroon w/Dark Brown Specks Vinyl Floor Tile Mastic**  
MATERIAL LOCATION: **Elevator Vestibule**  
MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/01/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22301** BUIDLING ID: **2360**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shawn Brown**  
SCHOOL NAME: **Haley, Alex School** INSPECTION DATE: **9/2/2019**  
ADDRESS: **11411 S Eggleston** IDPH LICENSE NO: **100-00440**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **A**  
MATERIAL DESCRIPTION: **Boiler Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Boiler Room**  
MATERIAL QUANTITY: **2200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/02/2019**



# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22301** BUIDLING ID: **2360**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Haley, Alex School** REVIEW DATE: **10/1/2019**  
ADDRESS: **11411 S Eggleston** IDPH LICENSE NO: **100-00440**

---

HOMOGENEOUS AREA: **A**  
MATERIAL DESCRIPTION: **Boiler Insulation**  
MATERIAL LOCATION: **Boiler Room**  
MATERIAL QUANTITY: **2200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/01/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22301** BUIDLING ID: **2360**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shawn Brown**  
SCHOOL NAME: **Haley, Alex School** INSPECTION DATE: **9/2/2019**  
ADDRESS: **11411 S Eggleston** IDPH LICENSE NO: **100-00440**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **B**  
MATERIAL DESCRIPTION: **Insulation on Water Return Tanks**  
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Boiler Room**  
MATERIAL QUANTITY: **80** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/02/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22301** BUIDLING ID: **2360**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Haley, Alex School** REVIEW DATE: **10/1/2019**  
ADDRESS: **11411 S Eggleston** IDPH LICENSE NO: **100-00440**

---

HOMOGENEOUS AREA: **B**  
MATERIAL DESCRIPTION: **Insulation on Water Return Tanks**  
MATERIAL LOCATION: **Boiler Room**  
MATERIAL QUANTITY: **80** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/01/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22301** BUIDLING ID: **2360**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shawn Brown**  
SCHOOL NAME: **Haley, Alex School** INSPECTION DATE: **9/2/2019**  
ADDRESS: **11411 S Eggleston** IDPH LICENSE NO: **100-00440**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **C**  
MATERIAL DESCRIPTION: **Heating and Water Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Boiler Room, Mechanical Room, Air Tunnels, Pipe Chases**  
MATERIAL QUANTITY: **889** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/02/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22301** BUIDLING ID: **2360**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Haley, Alex School** REVIEW DATE: **10/1/2019**  
ADDRESS: **11411 S Eggleston** IDPH LICENSE NO: **100-00440**

---

HOMOGENEOUS AREA: **C**  
MATERIAL DESCRIPTION: **Heating and Water Pipe Insulation**  
MATERIAL LOCATION: **Boiler Room, Mechanical Room, Air Tunnels, Pipe Chases**  
MATERIAL QUANTITY: **889** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/01/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22301** BUIDLING ID: **2360**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shawn Brown**  
SCHOOL NAME: **Haley, Alex School** INSPECTION DATE: **9/2/2019**  
ADDRESS: **11411 S Eggleston** IDPH LICENSE NO: **100-00440**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **D**  
MATERIAL DESCRIPTION: **MJP E/F/V on Heating and Water Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Boiler Room, Mechanical Room, Air Tunnels, Pipe Chases**  
MATERIAL QUANTITY: **78** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/02/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22301** BUIDLING ID: **2360**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Haley, Alex School** REVIEW DATE: **10/1/2019**  
ADDRESS: **11411 S Eggleston** IDPH LICENSE NO: **100-00440**

---

HOMOGENEOUS AREA: **D**  
MATERIAL DESCRIPTION: **MJP E/F/V on Heating and Water Pipe Insulation**  
MATERIAL LOCATION: **Boiler Room, Mechanical Room, Air Tunnels, Pipe Chases**  
MATERIAL QUANTITY: **78** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/01/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22301** BUIDLING ID: **2360**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shawn Brown**  
SCHOOL NAME: **Haley, Alex School** INSPECTION DATE: **9/2/2019**  
ADDRESS: **11411 S Eggleston** IDPH LICENSE NO: **100-00440**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **E**  
MATERIAL DESCRIPTION: **Insulation on Heating Pipes**  
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Boiler Room, Boiler Room Tunnel, Mechanical Room**  
MATERIAL QUANTITY: **180** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/02/2019**



# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22301** BUIDLING ID: **2360**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Haley, Alex School** REVIEW DATE: **10/1/2019**  
ADDRESS: **11411 S Eggleston** IDPH LICENSE NO: **100-00440**

---

HOMOGENEOUS AREA: **E**  
MATERIAL DESCRIPTION: **Insulation on Heating Pipes**  
MATERIAL LOCATION: **Boiler Room, Boiler Room Tunnel, Mechanical Room**  
MATERIAL QUANTITY: **180** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/01/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22301** BUIDLING ID: **2360**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shawn Brown**  
SCHOOL NAME: **Haley, Alex School** INSPECTION DATE: **9/2/2019**  
ADDRESS: **11411 S Eggleston** IDPH LICENSE NO: **100-00440**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **F**  
MATERIAL DESCRIPTION: **Magblock Pipe Joint Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Boiler Room and Throughout Basement Pipe Chases**  
MATERIAL QUANTITY: **15** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/02/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22301** BUIDLING ID: **2360**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Haley, Alex School** REVIEW DATE: **10/1/2019**  
ADDRESS: **11411 S Eggleston** IDPH LICENSE NO: **100-00440**

---

HOMOGENEOUS AREA: **F**  
MATERIAL DESCRIPTION: **Magblock Pipe Joint Insulation**  
MATERIAL LOCATION: **Boiler Room and Throughout Basement Pipe Chases**  
MATERIAL QUANTITY: **15** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/01/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22301** BUIDLING ID: **2360**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shawn Brown**  
SCHOOL NAME: **Haley, Alex School** INSPECTION DATE: **9/2/2019**  
ADDRESS: **11411 S Eggleston** IDPH LICENSE NO: **100-00440**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **G**  
MATERIAL DESCRIPTION: **Heating and Water Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Boiler Room, Pipe Chases, Mechanical Room, Air Tunnels, Unexcavated Crawl Spaces**  
MATERIAL QUANTITY: **1465** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/02/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22301** BUIDLING ID: **2360**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Haley, Alex School** REVIEW DATE: **10/1/2019**  
ADDRESS: **11411 S Eggleston** IDPH LICENSE NO: **100-00440**

---

HOMOGENEOUS AREA: **G**  
MATERIAL DESCRIPTION: **Heating and Water Pipe Insulation**  
MATERIAL LOCATION: **Boiler Room, Pipe Chases, Mechanical Room, Air Tunnels, Unexcavated Crawl Spaces**  
MATERIAL QUANTITY: **1465** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/01/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22301** BUIDLING ID: **2360**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shawn Brown**  
SCHOOL NAME: **Haley, Alex School** INSPECTION DATE: **9/2/2019**  
ADDRESS: **11411 S Eggleston** IDPH LICENSE NO: **100-00440**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **H**  
MATERIAL DESCRIPTION: **MJP E/F/V on Heating and Water Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Boiler Room, Pipe Chases, Mechanical Room, Air Tunnels, Unexcavated Crawl Spaces**  
MATERIAL QUANTITY: **386** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/02/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22301** BUIDLING ID: **2360**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Haley, Alex School** REVIEW DATE: **10/1/2019**  
ADDRESS: **11411 S Eggleston** IDPH LICENSE NO: **100-00440**

---

HOMOGENEOUS AREA: **H**  
MATERIAL DESCRIPTION: **MJP E/F/V on Heating and Water Pipe Insulation**  
MATERIAL LOCATION: **Boiler Room, Pipe Chases, Mechanical Room, Air Tunnels, Unexcavated Crawl Spaces**  
MATERIAL QUANTITY: **386** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/01/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22301** BUIDLING ID: **2360**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shawn Brown**  
SCHOOL NAME: **Haley, Alex School** INSPECTION DATE: **9/2/2019**  
ADDRESS: **11411 S Eggleston** IDPH LICENSE NO: **100-00440**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **I**  
MATERIAL DESCRIPTION: **Aircell Duct Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **1 Damaged or significantly damaged friable thermal system insulating ACBM**  
HISTORICAL DAMAGE REASON: **Deterioration**  
HISTORICAL RESPONSE ACTION: **Repair**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON: **Deterioration**  
DISTURBANCE POTENTIAL: **HIGH**  
MATERIAL LOCATION: **East & West Crawl Space (under Assembly Hall)**  
MATERIAL QUANTITY: **390** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **60** DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/02/2019



# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22301** BUIDLING ID: **2360**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Haley, Alex School** REVIEW DATE: **10/1/2019**  
ADDRESS: **11411 S Eggleston** IDPH LICENSE NO: **100-00440**

---

HOMOGENEOUS AREA: **I**  
MATERIAL DESCRIPTION: **Aircell Duct Insulation**  
MATERIAL LOCATION: **East & West Crawl Space (under Assembly Hall)**  
MATERIAL QUANTITY: **390** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **60** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/01/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
*2019 AHERA REINSPECTION*

# APPENDIX B

## Inspector and Management Planner Licenses

---

# CERTIFICATE OF ACHIEVEMENT ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that SHAWN L. BROWN  
has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the  
examination on 03/18/2019 with a minimum score of 70% or better. Training was in accordance  
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:  
Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.

03/18/2019

Course Dates:

03/18/2020

Expires:

1903BIR03

Certificate Number:



**PUBLIC HEALTH & SAFETY** inc.

Environmental and Occupational Services  
375 Ashland Ave., Chicago, IL 60607

[www.public-health-safety.com](http://www.public-health-safety.com)

Office: 312-491-0081  
Fax: 312-421-2801

Director of Training

Nicholas J. Peneff

Doctor of Public Health

Phone: 312-491-0081

FORM # A-010B

# CERTIFICATE OF ACHIEVEMENT ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that SHAWN L. BROWN  
has completed the Asbestos Management Planner Refresher course and passed the examination  
on 03/18/2019 with a minimum score of 70% or better. Training was in accordance with U.S.  
E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools: Model  
Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.

03/18/2019

Course Dates:

03/18/2020

Expires:

1903MPR01

Certificate Number:



**PUBLIC HEALTH & SAFETY** Inc.  
Environmental and Occupational Services  
311 S. Ashland Ave., Chicago, IL 60607  
[www.public-health-safety.com](http://www.public-health-safety.com)

Office: 312-491-0081  
Fax: 312-421-2901

Director of Training  
Nicholas J. Peneff  
Doctor of Public Health



Phone: 312-491-0081

FORM # A-011

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

	<b>ASBESTOS PROFESSIONAL LICENSE</b>	<b>ENDORSEMENTS</b>	<b>TC EXPIRES</b>
<b>ID NUMBER</b> 100 - 02950	<b>ISSUED</b> 3/6/2019	INSPECTOR	3/19/2019
<b>EXPIRES</b> 05/15/2020		PROJECT MANAGER	4/9/2019
<b>KEITH CLOUGH</b> 524 HOMELAND RD MATTESON, IL 60443 Environmental Health		AIR SAMPLING PROFESSIONAL	
		Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	

2019



**OCCUPATIONAL TRAINING & SUPPLY, INC.**

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900 ♦ [www.otssafety.com](http://www.otssafety.com)

# Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

**John Fenn**

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 3/19/2019

Exam Date: 3/19/2019

Expiration Date: 3/19/2020

Certificate Number: BIR1903191011

A handwritten signature in black ink that reads 'Kathy DeSalvo'.

---

Kathy DeSalvo, Director

2019



**OCCUPATIONAL TRAINING & SUPPLY, INC.**

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900 ♦ [www.otssafety.com](http://www.otssafety.com)

# Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

**John Fenn**


has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 3/19/2019

Exam Date: 3/19/2019

Expiration Date: 3/19/2020

Certificate Number: MPR1903191035



---

Kathy DeSalvo, Director



# COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License



## ASBESTOS PROFESSIONAL LICENSE

### ENDORSEMENTS

### TC EXPIRES

INSPECTOR

3/19/2020

ID NUMBER

ISSUED

EXPIRES

MANAGEMENT PLANNER

3/19/2020

100 - 09786

4/11/2019

05/15/2020

PROJECT MANAGER

3/18/2020

**JOHN H FENN**

2829 N TROY ST

CHICAGO, IL 60618

Environmental Health



AIR SAMPLING PROFESSIONAL

**Alteration of this license shall result in legal action**  
This license issued under authority of the State of Illinois  
Department of Public Health

This license is valid only when accompanied by a valid  
training course certificate.

# APPENDIX C

## Laboratory Accreditations

---

# APPENDIX D

## Laboratory Results

---

# APPENDIX E

## Chain of Custody Forms

---

## Three-Year Reinspection Key to Terms

	<b>CODE</b>	<b>KEY</b>
<b>MATERIAL</b>		
	ACBM	Asbestos Containing Building Materials
<b>MATERIAL CATEGORY</b>		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
<b>MATERIAL UNITS</b>		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
<b>DAMAGE TYPE</b>		
	Loc	Localized
	Dist	Distributed