

ILLINOIS DEPARTMENT OF PUBLIC HEALTH  
AHERA THREE YEAR REINSPECTION  
ASBESTOS ABATEMENT PROGRAM  
SCHOOL INFORMATION FORM

**SECTION I**

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299  
SCHOOL ID NUMBER: 14-016-2990-2096  
SCHOOL NAME: Bright School  
ADDRESS OF SCHOOL: 10740 S. Calhoun  
CITY: Chicago, IL, 60617

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **3/11/2016**

**If the address on this form is different than the address of the building, submit a written explanation.**

**SECTION II** (Please type or print)

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 10/1/2019 ENROLLMENT 280  
IDPH INSPECTOR LICENSE NUMBER: 100-19716  
IDPH LICENSED INSPECTOR NAME(Please Print): Imani Robinson  
IDPH MP LICENSE NUMBER: 100-09786  
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): John Fenn

DESIGNATED PERSON (Please Print): Robert Christlieb PHONE: (773) 553-3197



10/1/2019

Signature of Designated Person

Date

**SECTION III**

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: \_\_\_\_\_

School has been closed. Date closed: \_\_\_\_\_

School building has been demolished. Date: \_\_\_\_\_

School building is asbestos free since last reinspection: \_\_\_\_\_

**Please explain in writing why the school building is now asbestos free and include the supporting documentation.**

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

**Explain in writing if the address of the building is different than the address on this form:**

**THREE-YEAR REINSPECTION**

**CHICAGO SCHOOL DIST 299**

**Bright School**

10740 S. Calhoun  
Chicago, IL, 60617

Unit: 22331  
Building ID: 2390

IDPH ID Number: 14-016-2990-2096

**REPORT DATE:**

Tuesday, October 01, 2019

**Prepared for:**

**Chicago Public Schools  
42 West Madison Street  
Chicago, IL 60602**

**Prepared by:**

**TEM Environmental, Inc.**

174 N. Brandon Drive

Glendale Heights, IL, 60139

Phone 630-790-0880

Fax 630-790-0882

**DO NOT REMOVE FROM SCHOOL  
REQUIRED BY FEDERAL LAW**

August 16, 2019

Mr. Glen E. Garner  
Asbestos Program  
Illinois Department of Public Health  
525 West Jefferson Street  
Springfield, Illinois 62761

Re: Chicago Public Schools - 2019 Three-Year Reinspections

Dear Mr. Glen:

TEM Environmental, Inc. , Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 5, 6 Elementary Schools. Please update your records with the following information.

School District: 299            Unit: 22331            Region: 06            IDPH ID:14-016-2990-2096

School: Bright School            Building ID: 2390

Address: 10740 S. Calhoun  
Chicago, IL, 60617

Building Contact:            Contact Phone:

Current Building Owners: Chicago Public Schools

Review Date: 09/15/2019

Inspector: Imani Robinson  
Management Planner: John Fenn

Inspector IDPH License: 100-19716  
Management Planner IDPH License: 100-09786

If you have any questions or comments, please contact us at 630-790-0880

Sincerely,  
TEM Environmental, Inc.

John Fenn  
100-09786

## **Environmental Notification to Occupants**

To: Faculty, Staff and Parents  
From: Chicago Public Schools  
Date: August 16, 2019

RE: Bright School, Unit 22331  
10740 S. Calhoun  
Chicago, IL, 60617

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2019 asbestos three year re-inspection has been completed at Bright School, following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at Bright School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Robert Christlieb, the designated Local Education Authority's Designated Person at (773) 553-3197 .

## **Table of Contents**

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

### **APPENDICES:**

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

## SCHOOL AND INSPECTION INFORMATION

### 1. School Information

School: Bright School  
Address: 10740 S. Calhoun  
IDPH ID: 14-016-2990-2096  
Contact:

Unit: 22331  
Chicago, IL, 60617  
Building ID: 2390  
Phone:

Region: 06

### 2. Description of Facility

Original Construction:  
Total Square Footage:  
Current Occupancy: 280

Additional Construction:  
No of Floors:

### 3. LEA Designated Person

Contact: Robert Christlieb  
Address: 42 West Madison Street  
Chicago, IL 60602

Phone: (773) 553-3197

### 4. Managing Environmental Consultant

MEC: TEM Environmental, Inc.  
Contact: Steven Geneser  
Address 174 N. Brandon Drive  
Glendale Heights, IL, 60139  
Phone: 630-790-0880

Fax: 630-790-0882

### 5. Inspector

Inspector Name: Imani Robinson

Inspector IDPH license # 100-19716

Signature:  
Date: 8/16/2019

### 6. Management Planner

Management Planner Name: John Fenn

Management Planner IDPH license # 100-09786

Signature:  
Date: 09/15/2019

### 7. Review Date:09/15/2019

### 8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature:



Date: 10/1/2019

Name: Robert Christlieb

## II. EXECUTIVE SUMMARY

TEM Environmental, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Bright School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.85 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas(HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 2390:

23	White Ceiling Tile
CM-1	Baseboard Carpet Mastic
FT-1	12x12 Beige Specks Floor Tile
FTM-1	12x12 Floor Tile Mastic

B. The following new homogenous areas have been identified for Building 2390:



C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

01	Hard Coat Plaster
03	Canvas Wall Covering
04B	12x12 Cream Floor Tile
05	2'x4' Lay In Ceiling Panels
10	Black Vinyl Strip Border
12	Black Vinyl Strip Border
14	12x12 Cream w/Tan Specks Floor Tile
15	12x12 White w/Black Specks Floor Tile
15A	12x12 White w/Black Specks Floor Tile Mastic
16	Grey Baseboard and Mastic
17	2'x2' Ceiling Tile
18	Black w/Tan Speckles Terrazzo
19	Emerald w/Black Speckles Terrazzo Floor
20	Ivory w/Black Speckles Terrazzo Floor
21	Smooth Plaster Walls and Ceilings
22	Plaster Walls (Lower Wall, Block Pattern)
23	White Ceiling Tile
24	Green Mosaic Ceramic Tile Grout
25	Green Carpet Mastic
26	Yellow Ceramic Tile Grout
27	Blue Ceramic Tile Grout
28	Gray Carpet Mastic
BB-1	Baseboard
BBM-1	Baseboard Mastic
C	Cardboard Pipe Insulation
CM-1	Baseboard Carpet Mastic
CM-2	Blue Carpet Mastic
CM-3	Gray Carpet Mastic
FT-1	12x12 Beige Specks Floor Tile
I	Aircell Pipe Insulation
J	Preform Pipe Insulation
L	MJP E/F/V on Preformed Pipe Insulation
O	MJP E/F/V on Fiberglass Pipe Insulation

The following areas were deemed to be inaccessible:

06	12x12 White w/Black Streaks Floor Tile Mastic
09	12x12 White w/Black Streaks Floor Tile Mastic
09A	12x12 Floor Tile Mastic
09B	12x12 Cream Floor Tile Mastic

11	Black Vinyl Strip Border Mastic
13	Black Vinyl Strip Border Mastic
15A	12x12 White w/Black Specks Floor Tile Mastic
25	Green Carpet Mastic
28	Gray Carpet Mastic
BBM-1	Baseboard Mastic
C	Cardboard Pipe Insulation
CM-1	Baseboard Carpet Mastic
CM-2	Blue Carpet Mastic
CM-3	Gray Carpet Mastic
FTM-1	12x12 Floor Tile Mastic
FTM-2	12x12 Tan Floor Tile Mastic

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Imani Robinson, IDPH License # 100-19716. The Management Plan was updated by John Fenn, IDPH License # 100-09786. Inspector and Management Planner Licenses are included in Appendix B.

### **III. METHODOLOGY**

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

### **IV. ABATEMENT HISTORY**

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

### **V. REASSESSMENTS AND RECOMMENDATIONS**

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

### **VI. CONCLUSIONS**

The Bright School Building 2390 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

**Table I**  
**Inspector's Reinspection Findings**

---

# Chicago Public Schools

School Bright School Unit 22331 Building ID 2390

Address 10740 S. Calhoun Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
01	Hard Coat Plaster	50,000	SF	Throughout Facility	ASSUMED	SURFACE	N	NONE	0		No	ACBM with the potential for damage		MODERATE
02	9x9 Floor Tile Beige Specks	0	SF	Not Observed	CHR	MISC								
03	Canvas Wall Covering	15,000	SF	Throughout Facility	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
04	12x12 White w/Black Streaks Floor Tile	8,000	SF	1921 Building- 2nd & 3rd Floor Corridors & Room 105	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
04A	12 x12 Brown Floor Tile	610	SF	Teachers' Lounge, Room 204	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
04B	12x12 Cream Floor Tile	1,176	SF	Room 204 and Dress Room 109B	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
05	2'x4' Lay In Ceiling Panels	900	SF	Room 105, Janitor's Closet 107A	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		MODERATE
06	12x12 White w/Black Streaks Floor Tile Mastic	2,406	SF	1938 Addition- 2nd & 3rd Floor Corridors & Stair Landings	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
07	9x9 Beige Speck Floor Tile Mastic	0		Not Observed	CHR	MISC								
08	12x12 White w/Black Streaks Floor Tile	2,406	SF	1938 Addition- 2nd & 3rd Floor Corridors & Stair Landings	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
09	12x12 White w/Black Streaks Floor Tile Mastic	8,000	SF	1921 Building- 2nd & 3rd Floor Corridors & Room 105	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
09A	12x12 Floor Tile Mastic	610	SF	Teachers' Lounge, Room 204	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
09B	12x12 Cream Floor Tile Mastic	1,176	SF	Room 204 and Dress Room 109B	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
10	Black Vinyl Strip Border	900	LF	1921 Building- 2nd & 3rd Floor Corridors	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
11	Black Vinyl Strip Border Mastic	900	LF	1921 Building- 2nd & 3rd Floor Corridors	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
12	Black Vinyl Strip Border	210	LF	1938 Addition- 2nd & 3rd Floor Corridors	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
13	Black Vinyl Strip Border Mastic	210	LF	1938 Addition- 2nd & 3rd Floor Corridors	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

# Chicago Public Schools

School Bright School Unit 22331 Building ID 2390

Address 10740 S. Calhoun Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
14	12x12 Cream w/Tan Specks Floor Tile	700	SF	Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
15	12x12 White w/Black Specks Floor Tile	5,500	SF	1998 Mobile Unit Classrooms and Corridors	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
15A	12x12 White w/Black Specks Floor Tile Mastic	5,500	SF	1998 Mobile Unit Classrooms and Corridors	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
16	Grey Baseboard and Mastic	2,000	LF	1998 Mobile Unit Classrooms and Corridors	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
17	2'x2' Ceiling Tile	5,500	SF	1998 Mobile Unit Classrooms and Corridors	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
18	Black w/Tan Speckles Terrazzo	7,500	SF	1st Floor Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
19	Emerald w/Black Speckles Terrazzo Floor	9,500	SF	1st, 2nd & 3rd Floor Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
20	Ivory w/Black Speckles Terrazzo Floor	7,500	SF	1st Floor Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
21	Smooth Plaster Walls and Ceilings	35,000	SF	Throughout	ASSUMED	SURFACE	N	NONE	0		No	ACBM with the potential for damage		LOW
22	Plaster Walls (Lower Wall, Block Pattern)	15,000	SF	Throughout	ASSUMED	SURFACE	N	NONE	0		No	ACBM with the potential for damage		LOW
23	White Ceiling Tile	200	SF	1st Floor Elevator Vestibule	ASSUMED	MISC	Y	NONE	0		Yes	Any remaining friable ACBM or friable suspect ACBM		MODERATE
24	Green Mosaic Ceramic Tile Grout	800	SF	2nd & 3rd Floor Boys' Toilet	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
25	Green Carpet Mastic	450	SF	Room 306	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
26	Yellow Ceramic Tile Grout	450	SF	3rd Floor Girls' Toilet	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
27	Blue Ceramic Tile Grout	450	SF	2nd Floor Girls' Toilet	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
28	Gray Carpet Mastic	800	SF	Counselor's Office Room 106A, Speech Therapy Room 106B and Counselor's Office Room 106C	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
A	Mag Block Tank Insulation	300	SF	1921 Building Basement	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
A - Annex	Aircell Pipe Cover	700	LF	Annex C- Boiler Room & Attic	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW

# Chicago Public Schools

School Bright School Unit 22331 Building ID 2390

Address 10740 S. Calhoun Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
"C"														
B	Aircell Pipe Insulation	600	LF	1921 Building- Restrooms and Classrooms & Basement	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
BB-1	Baseboard	170	LF	Room 104 and Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
BBM-1	Baseboard Mastic	170	LF	Room 104 and Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
C	Cardboard Pipe Insulation	25	LF	1921 Building- Basement and Toilet	ASSUMED	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
CM-1	Baseboard Carpet Mastic	0	SF	Room 104	ASSUMED	MISC		NONE	0		Yes			
CM-2	Blue Carpet Mastic	200	SF	Room 206	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
CM-3	Gray Carpet Mastic	1,230	SF	South Sky Box, North Sky Box and MDF Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
D	Preformed Pipe Insulation	156	LF	1921 Building Basement	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
E	MJP E/F/V on Aircell Pipe Insulation	25	LF	Throughout 1921 Building	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
FT-1	12x12 Beige Specks Floor Tile	1,900	SF	Lunchroom Room 108 and Dress Room 109B	ASSUMED	MISC	N	NONE	50		Yes	ACBM with potential for significant damage	5	MODERATE
FT-2	12x12 Tan Floor Tile	520	SF	Room 308	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
FTM-1	12x12 Floor Tile Mastic	1,900	SF	Lunchroom and Dress Room 109B	CHR	MISC	N	NONE	50		Yes	ACBM with potential for significant damage	5	LOW
FTM-2	12x12 Tan Floor Tile Mastic	520	SF	Room 308	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
G	MJP E/F/V on Cardboard Pipe Insulation	6	LF	Throughout 1921 Building	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		MODERATE
H	MJP E/F/V on Preformed Pipe Insulation	20	LF	Throughout 1921 Building	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		MODERATE
I	Aircell Pipe Insulation	0	SF	1938 Addition- Washrooms and Classrooms	ASSUMED	TSI	Y	NONE	0		No	ACBM with the potential for damage		MODERATE
I-1	Aircell Pipe Insulation	800	LF	1938 Addition- Air Tunnel	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
J	Preform Pipe Insulation	100	LF	1938 Addition- Tunnel	ASSUMED	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
K	MJP E/F/V on Aircell Pipe Insulation	20	LF	1938 Addition- Mechanical	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		MODERATE

# Chicago Public Schools

School Bright School Unit 22331 Building ID 2390

Address 10740 S. Calhoun Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
L	MJP E/F/V on Preformed Pipe Insulation	50	LF	1938 Addition-Basement	ASSUMED	TSI	Y	NONE	0		No	ACBM with the potential for damage		MODERATE
M	Cardboard Pipe Insulation	40	LF	Air Tunnel	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
N	MJP E/F/V on Cardboard Pipe Insulation	8	LF	Air Tunnel	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
O	MJP E/F/V on Fiberglass Pipe Insulation	700	LF	Engine Room, Janitor's Closets, Restrooms, Doctor's Office, Room 104, Storage Room and Main Office	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		MODERATE



# Chicago Public Schools

School Bright School Unit 22331 Building ID 2390

Address 10740 S. Calhoun Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

Reinspection Date <b>8/16/2019</b>
Inspector Name <b><u>Imani Robinson</u></b>
<b>100-19716</b> <b>5/15/2020</b>
Inspector's IDPH License Number / Expiration Date

### Inspector's Comments

HA Number:	Inspector Comments:
01	
02	Not Observed 2019
03	
04	
04A	
04B	
05	
06	
07	Not Observed 2019
08	
09	
09A	
09B	
10	
11	
12	
13	
14	
15	
15A	
16	
17	
18	

# Chicago Public Schools

School Bright School Unit 22331 Building ID 2390

Address 10740 S. Calhoun Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
19	
20	
21	
22	
23	
24	
25	
26	
27	
28	
A	
A - Annex "C"	
B	
BB-1	
BBM-1	
C	
CM-1	Not Observed - Wood Floor 2019
CM-2	
CM-3	
D	
E	
FT-1	Damage in Lunchroom
FT-2	
FTM-1	Damage in Lunchroom
FTM-2	
G	
H	
I	
I-1	

# Chicago Public Schools

School Bright School Unit 22331 Building ID 2390

Address 10740 S. Calhoun Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
J	
K	
L	
M	
N	
O	

**Table II**

**Management Planner's Review**

---

# Chicago Public Schools

**School** Bright School  
**Address** 10740 S. Calhoun

**Unit** 22331  
Chicago, IL, 60617

**Building ID** 2390  
**Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

### Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
01	Hard Coat Plaster	50,000	SF	Throughout Facility	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
02	9x9 Floor Tile Beige Specks	0	SF	Not Observed	Chrysotile	MISC			SF		
03	Canvas Wall Covering	15,000	SF	Throughout Facility	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
04	12x12 White w/Black Streaks Floor Tile	8,000	SF	1921 Building- 2nd & 3rd Floor Corridors & Room 105	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
04A	12 x12 Brown Floor Tile	610	SF	Teachers' Lounge, Room 204	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
04B	12x12 Cream Floor Tile	1,176	SF	Room 204 and Dress Room 109B	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
05	2'x4' Lay In Ceiling Panels	900	SF	Room 105, Janitor's Closet 107A	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
06	12x12 White w/Black Streaks Floor Tile Mastic	2,406	SF	1938 Addition- 2nd & 3rd Floor Corridors & Stair Landings	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
07	9x9 Beige Speck Floor Tile Mastic	0		Not Observed	Chrysotile	MISC					
08	12x12 White w/Black Streaks Floor Tile	2,406	SF	1938 Addition- 2nd & 3rd Floor Corridors & Stair Landings	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
09	12x12 White w/Black Streaks Floor Tile Mastic	8,000	SF	1921 Building- 2nd & 3rd Floor Corridors & Room 105	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
09A	12x12 Floor Tile Mastic	610	SF	Teachers' Lounge, Room 204	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
09B	12x12 Cream Floor Tile Mastic	1,176	SF	Room 204 and Dress Room 109B	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
10	Black Vinyl Strip Border	900	LF	1921 Building- 2nd & 3rd Floor Corridors	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
11	Black Vinyl Strip Border Mastic	900	LF	1921 Building- 2nd & 3rd Floor Corridors	Chrysotile	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
12	Black Vinyl Strip Border	210	LF	1938 Addition- 2nd & 3rd Floor Corridors	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
13	Black Vinyl Strip Border Mastic	210	LF	1938 Addition- 2nd & 3rd Floor Corridors	Chrysotile	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
14	12x12 Cream w/Tan Specks Floor Tile	700	SF	Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
15	12x12 White w/Black Specks Floor Tile	5,500	SF	1998 Mobile Unit Classrooms and Corridors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
15A	12x12 White w/Black Specks Floor Tile Mastic	5,500	SF	1998 Mobile Unit Classrooms and Corridors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
16	Grey Baseboard and Mastic	2,000	LF	1998 Mobile Unit Classrooms and Corridors	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
17	2'x2' Ceiling Tile	5,500	SF	1998 Mobile Unit Classrooms and Corridors	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

School Bright School  
Address 10740 S. Calhoun

Unit 22331  
Chicago, IL, 60617

Building ID 2390  
Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

### Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
18	Black w/Tan Speckles Terrazzo	7,500	SF	1st Floor Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
19	Emerald w/Black Speckles Terrazzo Floor	9,500	SF	1st, 2nd & 3rd Floor Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
20	Ivory w/Black Speckles Terrazzo Floor	7,500	SF	1st Floor Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
21	Smooth Plaster Walls and Ceilings	35,000	SF	Throughout	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
22	Plaster Walls (Lower Wall, Block Pattern)	15,000	SF	Throughout	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
23	White Ceiling Tile	200	SF	1st Floor Elevator Vestibule	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
24	Green Mosaic Ceramic Tile Grout	800	SF	2nd & 3rd Floor Boys' Toilet	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
25	Green Carpet Mastic	450	SF	Room 306	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
26	Yellow Ceramic Tile Grout	450	SF	3rd Floor Girls' Toilet	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
27	Blue Ceramic Tile Grout	450	SF	2nd Floor Girls' Toilet	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
28	Gray Carpet Mastic	800	SF	Counselor's Office Room 106A, Speech Therapy Room 106B and Counselor's Office Room 106C	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
A	Mag Block Tank Insulation	300	SF	1921 Building Basement	Chrysotile	TSI	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
A - Annex "C"	Aircell Pipe Cover	700	LF	Annex C- Boiler Room & Attic	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
B	Aircell Pipe Insulation	600	LF	1921 Building- Restrooms and Classrooms & Basement	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
BB-1	Baseboard	170	LF	Room 104 and Office	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
BBM-1	Baseboard Mastic	170	LF	Room 104 and Office	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
C	Cardboard Pipe Insulation	25	LF	1921 Building- Basement and Toilet	Assumed	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
CM-1	Baseboard Carpet Mastic	0	SF	Room 104 -	Assumed	MISC		0	SF		
CM-2	Blue Carpet Mastic	200	SF	Room 206	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
CM-3	Gray Carpet Mastic	1,230	SF	South Sky Box, North Sky Box and MDF Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
D	Preformed Pipe Insulation	156	LF	1921 Building Basement	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
E	MJP E/F/V on Aircell Pipe Insulation	25	LF	Throughout 1921 Building	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
FT-1	12x12 Beige Specks Floor Tile	1,900	SF	Lunchroom Room 108 and Dress Room 109B	Assumed	MISC	No	50	SF	5 ACBM with potential for significant damage	Follow O&M Plan
FT-2	12x12 Tan Floor Tile	520	SF	Room 308	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FTM-1	12x12 Floor Tile Mastic	1,900	SF	Lunchroom and Dress Room 109B	Chrysotile	MISC	No	50	SF	5 ACBM with potential for significant damage	Follow O&M Plan
FTM-2	12x12 Tan Floor Tile Mastic	520	SF	Room 308	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Bright School  
**Address** 10740 S. Calhoun

**Unit** 22331  
Chicago, IL, 60617

**Building ID** 2390  
**Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
G	MJP E/F/V on Cardboard Pipe Insulation	6	LF	Throughout 1921 Building	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
H	MJP E/F/V on Preformed Pipe Insulation	20	LF	Throughout 1921 Building	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
I	Aircell Pipe Insulation	0	SF	1938 Addition- Washrooms and Classrooms	Assumed	TSI	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
I-1	Aircell Pipe Insulation	800	LF	1938 Addition- Air Tunnel	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
J	Preform Pipe Insulation	100	LF	1938 Addition- Tunnel	Assumed	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
K	MJP E/F/V on Aircell Pipe Insulation	20	LF	1938 Addition- Mechanical	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
L	MJP E/F/V on Preformed Pipe Insulation	50	LF	1938 Addition- Basement	Assumed	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
M	Cardboard Pipe Insulation	40	LF	Air Tunnel	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
N	MJP E/F/V on Cardboard Pipe Insulation	8	LF	Air Tunnel	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
O	MJP E/F/V on Fiberglass Pipe Insulation	700	LF	Engine Room, Janitor's Closets, Restrooms, Doctor's Office, Room 104, Storage Room and Main Office	Assumed	MISC	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Bright School  
**Address** 10740 S. Calhoun

**Unit** 22331  
 Chicago, IL, 60617

**Building ID** 2390  
**Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

*Management Planner's Comments Summarized at the End of the Report*

Review Date	09/15/2019
Manager Planner Name	John Fenn
100-09786	5/15/2020
Manager IDPH License No/Expiration	

HA Number	Management Comments
01	
02	
03	
04	
04A	
04B	
05	
06	
07	
08	
09	
09A	
09B	
10	
11	
12	
13	
14	
15	
15A	
16	



# Chicago Public Schools

**School** Bright School  
**Address** 10740 S. Calhoun

**Unit** 22331  
 Chicago, IL, 60617

**Building ID** 2390  
**Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
17	
18	
19	
20	
21	
22	
23	
24	
25	
26	
27	
28	
A	
A - Annex "C"	
B	
BB-1	
BBM-1	
C	
CM-1	
CM-2	
CM-3	
D	
E	
FT-1	
FT-2	
FTM-1	

# Chicago Public Schools

**School** Bright School  
**Address** 10740 S. Calhoun

**Unit** 22331  
Chicago, IL, 60617

**Building ID** 2390  
**Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
FTM-2	
G	
H	
I	
I-1	
J	
K	
L	
M	
N	
O	

# Chicago Public Schools

TEM Environmental, Inc.

## 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22331** BUIDLING ID: **2390**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Imani Robinson**  
SCHOOL NAME: **Bright School** INSPECTION DATE: **8/16/2019**  
ADDRESS: **10740 S. Calhoun** IDPH LICENSE NO: **100-19716**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **01**  
MATERIAL DESCRIPTION: **Hard Coat Plaster**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY: **50000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **08/16/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22331** BUIDLING ID: **2390**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Bright School** REVIEW DATE: **9/15/2019**  
ADDRESS: **10740 S. Calhoun** IDPH LICENSE NO: **100-19716**

---

HOMOGENEOUS AREA: **01**  
MATERIAL DESCRIPTION: **Hard Coat Plaster**  
MATERIAL LOCATION: **Throughout Facility**  
MATERIAL QUANTITY: **50000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/15/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22331** BUIDLING ID: **2390**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Imani Robinson**  
SCHOOL NAME: **Bright School** INSPECTION DATE: **8/16/2019**  
ADDRESS: **10740 S. Calhoun** IDPH LICENSE NO: **100-19716**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **02**  
MATERIAL DESCRIPTION: **9x9 Floor Tile Beige Specks**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Not Observed**

MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not Observed 2019**

Inspector's Signature: \_\_\_\_\_ Date: **08/16/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22331** BUIDLING ID: **2390**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Bright School** REVIEW DATE: **9/15/2019**  
ADDRESS: **10740 S. Calhoun** IDPH LICENSE NO: **100-19716**

---

HOMOGENEOUS AREA: **02**  
MATERIAL DESCRIPTION: **9x9 Floor Tile Beige Specks**  
MATERIAL LOCATION: **Not Observed**  
MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/15/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22331** BUIDLING ID: **2390**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Imani Robinson**  
SCHOOL NAME: **Bright School** INSPECTION DATE: **8/16/2019**  
ADDRESS: **10740 S. Calhoun** IDPH LICENSE NO: **100-19716**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **03**  
MATERIAL DESCRIPTION: **Canvas Wall Covering**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Throughout Facility**  
MATERIAL QUANTITY: **15000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/16/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22331** BUIDLING ID: **2390**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Bright School** REVIEW DATE: **9/15/2019**  
ADDRESS: **10740 S. Calhoun** IDPH LICENSE NO: **100-19716**

---

HOMOGENEOUS AREA: **03**  
MATERIAL DESCRIPTION: **Canvas Wall Covering**  
MATERIAL LOCATION: **Throughout Facility**  
MATERIAL QUANTITY: **15000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/15/2019**



# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22331** BUIDLING ID: **2390**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Imani Robinson**  
SCHOOL NAME: **Bright School** INSPECTION DATE: **8/16/2019**  
ADDRESS: **10740 S. Calhoun** IDPH LICENSE NO: **100-19716**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **04**  
MATERIAL DESCRIPTION: **12x12 White w/Black Streaks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **1921 Building- 2nd & 3rd Floor Corridors & Room 105**  
MATERIAL QUANTITY: **8000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/16/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22331** BUIDLING ID: **2390**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Bright School** REVIEW DATE: **9/15/2019**  
ADDRESS: **10740 S. Calhoun** IDPH LICENSE NO: **100-19716**

---

HOMOGENEOUS AREA: **04**  
MATERIAL DESCRIPTION: **12x12 White w/Black Streaks Floor Tile**  
MATERIAL LOCATION: **1921 Building- 2nd & 3rd Floor Corridors & Room 105**  
MATERIAL QUANTITY: **8000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/15/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22331** BUIDLING ID: **2390**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Imani Robinson**  
SCHOOL NAME: **Bright School** INSPECTION DATE: **8/16/2019**  
ADDRESS: **10740 S. Calhoun** IDPH LICENSE NO: **100-19716**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **04A**  
MATERIAL DESCRIPTION: **12 x12 Brown Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Teachers' Lounge, Room 204**  
MATERIAL QUANTITY: **610** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/16/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22331** BUIDLING ID: **2390**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Bright School** REVIEW DATE: **9/15/2019**  
ADDRESS: **10740 S. Calhoun** IDPH LICENSE NO: **100-19716**

---

HOMOGENEOUS AREA: **04A**  
MATERIAL DESCRIPTION: **12 x12 Brown Floor Tile**  
MATERIAL LOCATION: **Teachers' Lounge, Room 204**  
MATERIAL QUANTITY: **610** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/15/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **22331**    BUILDING ID: **2390**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Imani Robinson**  
SCHOOL NAME: **Bright School**    INSPECTION DATE: **8/16/2019**  
ADDRESS: **10740 S. Calhoun**    IDPH LICENSE NO: **100-19716**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **04B**  
MATERIAL DESCRIPTION: **12x12 Cream Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Room 204 and Dress Room 109B**  
MATERIAL QUANTITY: **1176**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/16/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22331** BUIDLING ID: **2390**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Bright School** REVIEW DATE: **9/15/2019**  
ADDRESS: **10740 S. Calhoun** IDPH LICENSE NO: **100-19716**

---

HOMOGENEOUS AREA: **04B**  
MATERIAL DESCRIPTION: **12x12 Cream Floor Tile**  
MATERIAL LOCATION: **Room 204 and Dress Room 109B**  
MATERIAL QUANTITY: **1176** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/15/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22331** BUIDLING ID: **2390**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Imani Robinson**  
SCHOOL NAME: **Bright School** INSPECTION DATE: **8/16/2019**  
ADDRESS: **10740 S. Calhoun** IDPH LICENSE NO: **100-19716**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **05**  
MATERIAL DESCRIPTION: **2'x4' Lay In Ceiling Panels**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Room 105, Janitor's Closet 107A**  
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/16/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22331** BUIDLING ID: **2390**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Bright School** REVIEW DATE: **9/15/2019**  
ADDRESS: **10740 S. Calhoun** IDPH LICENSE NO: **100-19716**

---

HOMOGENEOUS AREA: **05**  
MATERIAL DESCRIPTION: **2'x4' Lay In Ceiling Panels**  
MATERIAL LOCATION: **Room 105, Janitor's Closet 107A**  
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/15/2019**



# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22331** BUIDLING ID: **2390**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Imani Robinson**  
SCHOOL NAME: **Bright School** INSPECTION DATE: **8/16/2019**  
ADDRESS: **10740 S. Calhoun** IDPH LICENSE NO: **100-19716**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **06**  
MATERIAL DESCRIPTION: **12x12 White w/Black Streaks Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1938 Addition- 2nd & 3rd Floor Corridors & Stair Landings**  
MATERIAL QUANTITY: **2406** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/16/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22331** BUIDLING ID: **2390**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Bright School** REVIEW DATE: **9/15/2019**  
ADDRESS: **10740 S. Calhoun** IDPH LICENSE NO: **100-19716**

---

HOMOGENEOUS AREA: **06**  
MATERIAL DESCRIPTION: **12x12 White w/Black Streaks Floor Tile Mastic**  
MATERIAL LOCATION: **1938 Addition- 2nd & 3rd Floor Corridors & Stair Landings**  
MATERIAL QUANTITY: **2406** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/15/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22331** BUIDLING ID: **2390**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Imani Robinson**  
SCHOOL NAME: **Bright School** INSPECTION DATE: **8/16/2019**  
ADDRESS: **10740 S. Calhoun** IDPH LICENSE NO: **100-19716**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **07**  
MATERIAL DESCRIPTION: **9x9 Beige Speck Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Not Observed**

MATERIAL QUANTITY: **0** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not Observed 2019**

Inspector's Signature: \_\_\_\_\_ Date: **08/16/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22331** BUIDLING ID: **2390**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Bright School** REVIEW DATE: **9/15/2019**  
ADDRESS: **10740 S. Calhoun** IDPH LICENSE NO: **100-19716**

---

HOMOGENEOUS AREA: **07**

MATERIAL DESCRIPTION: **9x9 Beige Speck Floor Tile Mastic**

MATERIAL LOCATION: **Not Observed**

MATERIAL QUANTITY: **0**

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/15/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22331** BUIDLING ID: **2390**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Imani Robinson**  
SCHOOL NAME: **Bright School** INSPECTION DATE: **8/16/2019**  
ADDRESS: **10740 S. Calhoun** IDPH LICENSE NO: **100-19716**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **08**  
MATERIAL DESCRIPTION: **12x12 White w/Black Streaks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **1938 Addition- 2nd & 3rd Floor Corridors & Stair Landings**  
MATERIAL QUANTITY: **2406** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/16/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22331** BUIDLING ID: **2390**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Bright School** REVIEW DATE: **9/15/2019**  
ADDRESS: **10740 S. Calhoun** IDPH LICENSE NO: **100-19716**

---

HOMOGENEOUS AREA: **08**  
MATERIAL DESCRIPTION: **12x12 White w/Black Streaks Floor Tile**  
MATERIAL LOCATION: **1938 Addition- 2nd & 3rd Floor Corridors & Stair Landings**  
MATERIAL QUANTITY: **2406** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/15/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22331** BUIDLING ID: **2390**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Imani Robinson**  
SCHOOL NAME: **Bright School** INSPECTION DATE: **8/16/2019**  
ADDRESS: **10740 S. Calhoun** IDPH LICENSE NO: **100-19716**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **09**  
MATERIAL DESCRIPTION: **12x12 White w/Black Streaks Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1921 Building- 2nd & 3rd Floor Corridors & Room 105**  
MATERIAL QUANTITY: **8000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/16/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22331** BUIDLING ID: **2390**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Bright School** REVIEW DATE: **9/15/2019**  
ADDRESS: **10740 S. Calhoun** IDPH LICENSE NO: **100-19716**

---

HOMOGENEOUS AREA: **09**  
MATERIAL DESCRIPTION: **12x12 White w/Black Streaks Floor Tile Mastic**  
MATERIAL LOCATION: **1921 Building- 2nd & 3rd Floor Corridors & Room 105**  
MATERIAL QUANTITY: **8000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/15/2019**



# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22331** BUIDLING ID: **2390**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Imani Robinson**  
SCHOOL NAME: **Bright School** INSPECTION DATE: **8/16/2019**  
ADDRESS: **10740 S. Calhoun** IDPH LICENSE NO: **100-19716**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **09A**  
MATERIAL DESCRIPTION: **12x12 Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Teachers' Lounge, Room 204**  
MATERIAL QUANTITY: **610** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/16/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22331** BUIDLING ID: **2390**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Bright School** REVIEW DATE: **9/15/2019**  
ADDRESS: **10740 S. Calhoun** IDPH LICENSE NO: **100-19716**

---

HOMOGENEOUS AREA: **09A**  
MATERIAL DESCRIPTION: **12x12 Floor Tile Mastic**  
MATERIAL LOCATION: **Teachers' Lounge, Room 204**  
MATERIAL QUANTITY: **610** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/15/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22331** BUIDLING ID: **2390**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Imani Robinson**  
SCHOOL NAME: **Bright School** INSPECTION DATE: **8/16/2019**  
ADDRESS: **10740 S. Calhoun** IDPH LICENSE NO: **100-19716**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **09B**  
MATERIAL DESCRIPTION: **12x12 Cream Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 204 and Dress Room 109B**  
MATERIAL QUANTITY: **1176** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/16/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22331** BUIDLING ID: **2390**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Bright School** REVIEW DATE: **9/15/2019**  
ADDRESS: **10740 S. Calhoun** IDPH LICENSE NO: **100-19716**

---

HOMOGENEOUS AREA: **09B**  
MATERIAL DESCRIPTION: **12x12 Cream Floor Tile Mastic**  
MATERIAL LOCATION: **Room 204 and Dress Room 109B**  
MATERIAL QUANTITY: **1176** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/15/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22331** BUIDLING ID: **2390**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Imani Robinson**  
SCHOOL NAME: **Bright School** INSPECTION DATE: **8/16/2019**  
ADDRESS: **10740 S. Calhoun** IDPH LICENSE NO: **100-19716**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10**  
MATERIAL DESCRIPTION: **Black Vinyl Strip Border**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1921 Building- 2nd & 3rd Floor Corridors**  
MATERIAL QUANTITY: **900** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/16/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22331** BUIDLING ID: **2390**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Bright School** REVIEW DATE: **9/15/2019**  
ADDRESS: **10740 S. Calhoun** IDPH LICENSE NO: **100-19716**

---

HOMOGENEOUS AREA: **10**  
MATERIAL DESCRIPTION: **Black Vinyl Strip Border**  
MATERIAL LOCATION: **1921 Building- 2nd & 3rd Floor Corridors**  
MATERIAL QUANTITY: **900** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/15/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22331** BUIDLING ID: **2390**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Imani Robinson**  
SCHOOL NAME: **Bright School** INSPECTION DATE: **8/16/2019**  
ADDRESS: **10740 S. Calhoun** IDPH LICENSE NO: **100-19716**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11**  
MATERIAL DESCRIPTION: **Black Vinyl Strip Border Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1921 Building- 2nd & 3rd Floor Corridors**  
MATERIAL QUANTITY: **900** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/16/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22331** BUIDLING ID: **2390**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Bright School** REVIEW DATE: **9/15/2019**  
ADDRESS: **10740 S. Calhoun** IDPH LICENSE NO: **100-19716**

---

HOMOGENEOUS AREA: **11**  
MATERIAL DESCRIPTION: **Black Vinyl Strip Border Mastic**  
MATERIAL LOCATION: **1921 Building- 2nd & 3rd Floor Corridors**  
MATERIAL QUANTITY: **900** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/15/2019**



# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **22331**    BUILDING ID: **2390**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Imani Robinson**  
SCHOOL NAME: **Bright School**    INSPECTION DATE: **8/16/2019**  
ADDRESS: **10740 S. Calhoun**    IDPH LICENSE NO: **100-19716**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12**  
MATERIAL DESCRIPTION: **Black Vinyl Strip Border**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1938 Addition- 2nd & 3rd Floor Corridors**  
MATERIAL QUANTITY: **210**    MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **08/16/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22331** BUIDLING ID: **2390**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Bright School** REVIEW DATE: **9/15/2019**  
ADDRESS: **10740 S. Calhoun** IDPH LICENSE NO: **100-19716**

---

HOMOGENEOUS AREA: **12**  
MATERIAL DESCRIPTION: **Black Vinyl Strip Border**  
MATERIAL LOCATION: **1938 Addition- 2nd & 3rd Floor Corridors**  
MATERIAL QUANTITY: **210** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/15/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22331** BUIDLING ID: **2390**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Imani Robinson**  
SCHOOL NAME: **Bright School** INSPECTION DATE: **8/16/2019**  
ADDRESS: **10740 S. Calhoun** IDPH LICENSE NO: **100-19716**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13**  
MATERIAL DESCRIPTION: **Black Vinyl Strip Border Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1938 Addition- 2nd & 3rd Floor Corridors**  
MATERIAL QUANTITY: **210** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/16/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22331** BUIDLING ID: **2390**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Bright School** REVIEW DATE: **9/15/2019**  
ADDRESS: **10740 S. Calhoun** IDPH LICENSE NO: **100-19716**

---

HOMOGENEOUS AREA: **13**  
MATERIAL DESCRIPTION: **Black Vinyl Strip Border Mastic**  
MATERIAL LOCATION: **1938 Addition- 2nd & 3rd Floor Corridors**  
MATERIAL QUANTITY: **210** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/15/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22331** BUIDLING ID: **2390**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Imani Robinson**  
SCHOOL NAME: **Bright School** INSPECTION DATE: **8/16/2019**  
ADDRESS: **10740 S. Calhoun** IDPH LICENSE NO: **100-19716**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14**  
MATERIAL DESCRIPTION: **12x12 Cream w/Tan Specks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Office**  
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/16/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22331** BUIDLING ID: **2390**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Bright School** REVIEW DATE: **9/15/2019**  
ADDRESS: **10740 S. Calhoun** IDPH LICENSE NO: **100-19716**

---

HOMOGENEOUS AREA: **14**  
MATERIAL DESCRIPTION: **12x12 Cream w/Tan Specks Floor Tile**  
MATERIAL LOCATION: **Office**  
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/15/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22331** BUIDLING ID: **2390**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Imani Robinson**  
SCHOOL NAME: **Bright School** INSPECTION DATE: **8/16/2019**  
ADDRESS: **10740 S. Calhoun** IDPH LICENSE NO: **100-19716**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15**  
MATERIAL DESCRIPTION: **12x12 White w/Black Specks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **1998 Mobile Unit Classrooms and Corridors**  
MATERIAL QUANTITY: **5500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/16/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22331** BUIDLING ID: **2390**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Bright School** REVIEW DATE: **9/15/2019**  
ADDRESS: **10740 S. Calhoun** IDPH LICENSE NO: **100-19716**

---

HOMOGENEOUS AREA: **15**  
MATERIAL DESCRIPTION: **12x12 White w/Black Specks Floor Tile**  
MATERIAL LOCATION: **1998 Mobile Unit Classrooms and Corridors**  
MATERIAL QUANTITY: **5500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/15/2019**



# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22331** BUIDLING ID: **2390**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Imani Robinson**  
SCHOOL NAME: **Bright School** INSPECTION DATE: **8/16/2019**  
ADDRESS: **10740 S. Calhoun** IDPH LICENSE NO: **100-19716**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15A**  
MATERIAL DESCRIPTION: **12x12 White w/Black Specks Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1998 Mobile Unit Classrooms and Corridors**  
MATERIAL QUANTITY: **5500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/16/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22331** BUIDLING ID: **2390**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Bright School** REVIEW DATE: **9/15/2019**  
ADDRESS: **10740 S. Calhoun** IDPH LICENSE NO: **100-19716**

---

HOMOGENEOUS AREA: **15A**  
MATERIAL DESCRIPTION: **12x12 White w/Black Specks Floor Tile Mastic**  
MATERIAL LOCATION: **1998 Mobile Unit Classrooms and Corridors**  
MATERIAL QUANTITY: **5500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/15/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22331** BUIDLING ID: **2390**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Imani Robinson**  
SCHOOL NAME: **Bright School** INSPECTION DATE: **8/16/2019**  
ADDRESS: **10740 S. Calhoun** IDPH LICENSE NO: **100-19716**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16**  
MATERIAL DESCRIPTION: **Grey Baseboard and Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1998 Mobile Unit Classrooms and Corridors**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/16/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22331** BUIDLING ID: **2390**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Bright School** REVIEW DATE: **9/15/2019**  
ADDRESS: **10740 S. Calhoun** IDPH LICENSE NO: **100-19716**

---

HOMOGENEOUS AREA: **16**  
MATERIAL DESCRIPTION: **Grey Baseboard and Mastic**  
MATERIAL LOCATION: **1998 Mobile Unit Classrooms and Corridors**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/15/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22331** BUIDLING ID: **2390**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Imani Robinson**  
SCHOOL NAME: **Bright School** INSPECTION DATE: **8/16/2019**  
ADDRESS: **10740 S. Calhoun** IDPH LICENSE NO: **100-19716**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17**  
MATERIAL DESCRIPTION: **2'x2' Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1998 Mobile Unit Classrooms and Corridors**  
MATERIAL QUANTITY: **5500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/16/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22331** BUIDLING ID: **2390**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Bright School** REVIEW DATE: **9/15/2019**  
ADDRESS: **10740 S. Calhoun** IDPH LICENSE NO: **100-19716**

---

HOMOGENEOUS AREA: **17**  
MATERIAL DESCRIPTION: **2'x2' Ceiling Tile**  
MATERIAL LOCATION: **1998 Mobile Unit Classrooms and Corridors**  
MATERIAL QUANTITY: **5500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/15/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22331** BUIDLING ID: **2390**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Imani Robinson**  
SCHOOL NAME: **Bright School** INSPECTION DATE: **8/16/2019**  
ADDRESS: **10740 S. Calhoun** IDPH LICENSE NO: **100-19716**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18**  
MATERIAL DESCRIPTION: **Black w/Tan SpecklesTerrazzo**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st Floor Corridor**  
MATERIAL QUANTITY: **7500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/16/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22331** BUIDLING ID: **2390**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Bright School** REVIEW DATE: **9/15/2019**  
ADDRESS: **10740 S. Calhoun** IDPH LICENSE NO: **100-19716**

---

HOMOGENEOUS AREA: **18**  
MATERIAL DESCRIPTION: **Black w/Tan SpecklesTerrazzo**  
MATERIAL LOCATION: **1st Floor Corridor**  
MATERIAL QUANTITY: **7500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/15/2019**



# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **22331**    BUILDING ID: **2390**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Imani Robinson**  
SCHOOL NAME: **Bright School**    INSPECTION DATE: **8/16/2019**  
ADDRESS: **10740 S. Calhoun**    IDPH LICENSE NO: **100-19716**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19**  
MATERIAL DESCRIPTION: **Emerald w/Black Speckles Terrazzo Floor**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st, 2nd & 3rd Floor Corridor**  
MATERIAL QUANTITY: **9500**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **08/16/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22331** BUIDLING ID: **2390**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Bright School** REVIEW DATE: **9/15/2019**  
ADDRESS: **10740 S. Calhoun** IDPH LICENSE NO: **100-19716**

---

HOMOGENEOUS AREA: **19**  
MATERIAL DESCRIPTION: **Emerald w/Black Speckles Terrazzo Floor**  
MATERIAL LOCATION: **1st, 2nd & 3rd Floor Corridor**  
MATERIAL QUANTITY: **9500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/15/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22331** BUIDLING ID: **2390**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Imani Robinson**  
SCHOOL NAME: **Bright School** INSPECTION DATE: **8/16/2019**  
ADDRESS: **10740 S. Calhoun** IDPH LICENSE NO: **100-19716**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**  
MATERIAL DESCRIPTION: **Ivory w/Black Speckles Terrazzo Floor**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st Floor Corridor**  
MATERIAL QUANTITY: **7500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/16/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22331** BUIDLING ID: **2390**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Bright School** REVIEW DATE: **9/15/2019**  
ADDRESS: **10740 S. Calhoun** IDPH LICENSE NO: **100-19716**

---

HOMOGENEOUS AREA: **20**  
MATERIAL DESCRIPTION: **Ivory w/Black Speckles Terrazzo Floor**  
MATERIAL LOCATION: **1st Floor Corridor**  
MATERIAL QUANTITY: **7500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/15/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22331** BUIDLING ID: **2390**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Imani Robinson**  
SCHOOL NAME: **Bright School** INSPECTION DATE: **8/16/2019**  
ADDRESS: **10740 S. Calhoun** IDPH LICENSE NO: **100-19716**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21**  
MATERIAL DESCRIPTION: **Smooth Plaster Walls and Ceilings**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout**  
MATERIAL QUANTITY: **35000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/16/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22331** BUIDLING ID: **2390**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Bright School** REVIEW DATE: **9/15/2019**  
ADDRESS: **10740 S. Calhoun** IDPH LICENSE NO: **100-19716**

---

HOMOGENEOUS AREA: **21**  
MATERIAL DESCRIPTION: **Smooth Plaster Walls and Ceilings**  
MATERIAL LOCATION: **Throughout**  
MATERIAL QUANTITY: **35000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/15/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **22331**    BUILDING ID: **2390**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Imani Robinson**  
SCHOOL NAME: **Bright School**    INSPECTION DATE: **8/16/2019**  
ADDRESS: **10740 S. Calhoun**    IDPH LICENSE NO: **100-19716**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22**  
MATERIAL DESCRIPTION: **Plaster Walls (Lower Wall, Block Pattern)**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout**  
MATERIAL QUANTITY: **15000**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/16/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22331** BUIDLING ID: **2390**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Bright School** REVIEW DATE: **9/15/2019**  
ADDRESS: **10740 S. Calhoun** IDPH LICENSE NO: **100-19716**

---

HOMOGENEOUS AREA: **22**  
MATERIAL DESCRIPTION: **Plaster Walls (Lower Wall, Block Pattern)**  
MATERIAL LOCATION: **Throughout**  
MATERIAL QUANTITY: **15000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/15/2019**



# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22331** BUIDLING ID: **2390**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Imani Robinson**  
SCHOOL NAME: **Bright School** INSPECTION DATE: **8/16/2019**  
ADDRESS: **10740 S. Calhoun** IDPH LICENSE NO: **100-19716**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23**  
MATERIAL DESCRIPTION: **White Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **1st Floor Elevator Vestibule**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/16/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22331** BUILDING ID: **2390**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Bright School** REVIEW DATE: **9/15/2019**  
ADDRESS: **10740 S. Calhoun** IDPH LICENSE NO: **100-19716**

---

HOMOGENEOUS AREA: **23**  
MATERIAL DESCRIPTION: **White Ceiling Tile**  
MATERIAL LOCATION: **1st Floor Elevator Vestibule**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/15/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22331** BUIDLING ID: **2390**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Imani Robinson**  
SCHOOL NAME: **Bright School** INSPECTION DATE: **8/16/2019**  
ADDRESS: **10740 S. Calhoun** IDPH LICENSE NO: **100-19716**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **24**  
MATERIAL DESCRIPTION: **Green Mosaic Ceramic Tile Grout**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **2nd & 3rd Floor Boys' Toilet**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/16/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22331** BUIDLING ID: **2390**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Bright School** REVIEW DATE: **9/15/2019**  
ADDRESS: **10740 S. Calhoun** IDPH LICENSE NO: **100-19716**

---

HOMOGENEOUS AREA: **24**  
MATERIAL DESCRIPTION: **Green Mosaic Ceramic Tile Grout**  
MATERIAL LOCATION: **2nd & 3rd Floor Boys' Toilet**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/15/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22331** BUIDLING ID: **2390**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Imani Robinson**  
SCHOOL NAME: **Bright School** INSPECTION DATE: **8/16/2019**  
ADDRESS: **10740 S. Calhoun** IDPH LICENSE NO: **100-19716**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25**  
MATERIAL DESCRIPTION: **Green Carpet Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 306**  
MATERIAL QUANTITY: **450** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/16/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22331** BUIDLING ID: **2390**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Bright School** REVIEW DATE: **9/15/2019**  
ADDRESS: **10740 S. Calhoun** IDPH LICENSE NO: **100-19716**

---

HOMOGENEOUS AREA: **25**  
MATERIAL DESCRIPTION: **Green Carpet Mastic**  
MATERIAL LOCATION: **Room 306**  
MATERIAL QUANTITY: **450** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/15/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22331** BUIDLING ID: **2390**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Imani Robinson**  
SCHOOL NAME: **Bright School** INSPECTION DATE: **8/16/2019**  
ADDRESS: **10740 S. Calhoun** IDPH LICENSE NO: **100-19716**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26**  
MATERIAL DESCRIPTION: **Yellow Ceramic Tile Grout**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **3rd Floor Girls' Toilet**  
MATERIAL QUANTITY: **450** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/16/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22331** BUIDLING ID: **2390**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Bright School** REVIEW DATE: **9/15/2019**  
ADDRESS: **10740 S. Calhoun** IDPH LICENSE NO: **100-19716**

---

HOMOGENEOUS AREA: **26**  
MATERIAL DESCRIPTION: **Yellow Ceramic Tile Grout**  
MATERIAL LOCATION: **3rd Floor Girls' Toilet**  
MATERIAL QUANTITY: **450** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/15/2019**



# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22331** BUIDLING ID: **2390**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Imani Robinson**  
SCHOOL NAME: **Bright School** INSPECTION DATE: **8/16/2019**  
ADDRESS: **10740 S. Calhoun** IDPH LICENSE NO: **100-19716**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27**  
MATERIAL DESCRIPTION: **Blue Ceramic Tile Grout**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **2nd Floor Girls' Toilet**  
MATERIAL QUANTITY: **450** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/16/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22331** BUIDLING ID: **2390**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Bright School** REVIEW DATE: **9/15/2019**  
ADDRESS: **10740 S. Calhoun** IDPH LICENSE NO: **100-19716**

---

HOMOGENEOUS AREA: **27**  
MATERIAL DESCRIPTION: **Blue Ceramic Tile Grout**  
MATERIAL LOCATION: **2nd Floor Girls' Toilet**  
MATERIAL QUANTITY: **450** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/15/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22331** BUIDLING ID: **2390**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Imani Robinson**  
SCHOOL NAME: **Bright School** INSPECTION DATE: **8/16/2019**  
ADDRESS: **10740 S. Calhoun** IDPH LICENSE NO: **100-19716**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28**  
MATERIAL DESCRIPTION: **Gray Carpet Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Counselor's Office Room 106A, Speech Therapy Room 106B and Counselor's Office Room 106C**

MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/16/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22331** BUIDLING ID: **2390**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Bright School** REVIEW DATE: **9/15/2019**  
ADDRESS: **10740 S. Calhoun** IDPH LICENSE NO: **100-19716**

---

HOMOGENEOUS AREA: **28**  
MATERIAL DESCRIPTION: **Gray Carpet Mastic**  
MATERIAL LOCATION: **Counselor's Office Room 106A, Speech Therapy Room 106B and Counselor's Office Room 106C**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/15/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **22331**    BUIDLING ID: **2390**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Imani Robinson**  
SCHOOL NAME: **Bright School**    INSPECTION DATE: **8/16/2019**  
ADDRESS: **10740 S. Calhoun**    IDPH LICENSE NO: **100-19716**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **A**  
MATERIAL DESCRIPTION: **Mag Block Tank Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile**    FRIABLE: **Yes**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1921 Building Basement**  
MATERIAL QUANTITY: **300**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/16/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22331** BUIDLING ID: **2390**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Bright School** REVIEW DATE: **9/15/2019**  
ADDRESS: **10740 S. Calhoun** IDPH LICENSE NO: **100-19716**

---

HOMOGENEOUS AREA: **A**  
MATERIAL DESCRIPTION: **Mag Block Tank Insulation**  
MATERIAL LOCATION: **1921 Building Basement**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/15/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **22331**    BUIDLING ID: **2390**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Imani Robinson**  
SCHOOL NAME: **Bright School**    INSPECTION DATE: **8/16/2019**  
ADDRESS: **10740 S. Calhoun**    IDPH LICENSE NO: **100-19716**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **A - Annex "C"**  
MATERIAL DESCRIPTION: **Aircell Pipe Cover**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile**    FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Annex C- Boiler Room & Attic**  
MATERIAL QUANTITY: **700**    MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **08/16/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22331** BUIDLING ID: **2390**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Bright School** REVIEW DATE: **9/15/2019**  
ADDRESS: **10740 S. Calhoun** IDPH LICENSE NO: **100-19716**

---

HOMOGENEOUS AREA: **A - Annex "C"**  
MATERIAL DESCRIPTION: **Aircell Pipe Cover**  
MATERIAL LOCATION: **Annex C- Boiler Room & Attic**  
MATERIAL QUANTITY: **700** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/15/2019**



# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22331** BUIDLING ID: **2390**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Imani Robinson**  
SCHOOL NAME: **Bright School** INSPECTION DATE: **8/16/2019**  
ADDRESS: **10740 S. Calhoun** IDPH LICENSE NO: **100-19716**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **B**  
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1921 Building- Restrooms and Classrooms & Basement**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/16/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22331** BUIDLING ID: **2390**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Bright School** REVIEW DATE: **9/15/2019**  
ADDRESS: **10740 S. Calhoun** IDPH LICENSE NO: **100-19716**

---

HOMOGENEOUS AREA: **B**  
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**  
MATERIAL LOCATION: **1921 Building- Restrooms and Classrooms & Basement**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/15/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22331** BUIDLING ID: **2390**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Imani Robinson**  
SCHOOL NAME: **Bright School** INSPECTION DATE: **8/16/2019**  
ADDRESS: **10740 S. Calhoun** IDPH LICENSE NO: **100-19716**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **BB-1**  
MATERIAL DESCRIPTION: **Baseboard**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 104 and Office**  
MATERIAL QUANTITY: **170** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/16/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22331** BUIDLING ID: **2390**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Bright School** REVIEW DATE: **9/15/2019**  
ADDRESS: **10740 S. Calhoun** IDPH LICENSE NO: **100-19716**

---

HOMOGENEOUS AREA: **BB-1**  
MATERIAL DESCRIPTION: **Baseboard**  
MATERIAL LOCATION: **Room 104 and Office**  
MATERIAL QUANTITY: **170** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/15/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22331** BUIDLING ID: **2390**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Imani Robinson**  
SCHOOL NAME: **Bright School** INSPECTION DATE: **8/16/2019**  
ADDRESS: **10740 S. Calhoun** IDPH LICENSE NO: **100-19716**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **BBM-1**  
MATERIAL DESCRIPTION: **Baseboard Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 104 and Office**  
MATERIAL QUANTITY: **170** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/16/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22331** BUIDLING ID: **2390**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Bright School** REVIEW DATE: **9/15/2019**  
ADDRESS: **10740 S. Calhoun** IDPH LICENSE NO: **100-19716**

---

HOMOGENEOUS AREA: **BBM-1**  
MATERIAL DESCRIPTION: **Baseboard Mastic**  
MATERIAL LOCATION: **Room 104 and Office**  
MATERIAL QUANTITY: **170** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/15/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22331** BUIDLING ID: **2390**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Imani Robinson**  
SCHOOL NAME: **Bright School** INSPECTION DATE: **8/16/2019**  
ADDRESS: **10740 S. Calhoun** IDPH LICENSE NO: **100-19716**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **C**  
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1921 Building- Basement and Toilet**  
MATERIAL QUANTITY: **25** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/16/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22331** BUIDLING ID: **2390**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Bright School** REVIEW DATE: **9/15/2019**  
ADDRESS: **10740 S. Calhoun** IDPH LICENSE NO: **100-19716**

---

HOMOGENEOUS AREA: **C**  
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**  
MATERIAL LOCATION: **1921 Building- Basement and Toilet**  
MATERIAL QUANTITY: **25** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/15/2019**



# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22331** BUIDLING ID: **2390**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Imani Robinson**  
SCHOOL NAME: **Bright School** INSPECTION DATE: **8/16/2019**  
ADDRESS: **10740 S. Calhoun** IDPH LICENSE NO: **100-19716**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **CM-1**  
MATERIAL DESCRIPTION: **Baseboard Carpet Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 104 -**

MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS: **Not Observed - Wood Floor 2019**

Inspector's Signature: \_\_\_\_\_ Date: **08/16/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22331** BUIDLING ID: **2390**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Bright School** REVIEW DATE: **9/15/2019**  
ADDRESS: **10740 S. Calhoun** IDPH LICENSE NO: **100-19716**

---

HOMOGENEOUS AREA: **CM-1**  
MATERIAL DESCRIPTION: **Baseboard Carpet Mastic**  
MATERIAL LOCATION: **Room 104 -**  
MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/15/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22331** BUIDLING ID: **2390**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Imani Robinson**  
SCHOOL NAME: **Bright School** INSPECTION DATE: **8/16/2019**  
ADDRESS: **10740 S. Calhoun** IDPH LICENSE NO: **100-19716**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **CM-2**  
MATERIAL DESCRIPTION: **Blue Carpet Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 206**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/16/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22331** BUIDLING ID: **2390**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Bright School** REVIEW DATE: **9/15/2019**  
ADDRESS: **10740 S. Calhoun** IDPH LICENSE NO: **100-19716**

---

HOMOGENEOUS AREA: **CM-2**  
MATERIAL DESCRIPTION: **Blue Carpet Mastic**  
MATERIAL LOCATION: **Room 206**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/15/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22331** BUIDLING ID: **2390**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Imani Robinson**  
SCHOOL NAME: **Bright School** INSPECTION DATE: **8/16/2019**  
ADDRESS: **10740 S. Calhoun** IDPH LICENSE NO: **100-19716**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **CM-3**  
MATERIAL DESCRIPTION: **Gray Carpet Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **South Sky Box, North Sky Box and MDF Room**  
MATERIAL QUANTITY: **1230** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/16/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22331** BUIDLING ID: **2390**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Bright School** REVIEW DATE: **9/15/2019**  
ADDRESS: **10740 S. Calhoun** IDPH LICENSE NO: **100-19716**

---

HOMOGENEOUS AREA: **CM-3**  
MATERIAL DESCRIPTION: **Gray Carpet Mastic**  
MATERIAL LOCATION: **South Sky Box, North Sky Box and MDF Room**  
MATERIAL QUANTITY: **1230** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/15/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22331** BUILDING ID: **2390**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Imani Robinson**  
SCHOOL NAME: **Bright School** INSPECTION DATE: **8/16/2019**  
ADDRESS: **10740 S. Calhoun** IDPH LICENSE NO: **100-19716**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **D**  
MATERIAL DESCRIPTION: **Preformed Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1921 Building Basement**  
MATERIAL QUANTITY: **156** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/16/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22331** BUIDLING ID: **2390**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Bright School** REVIEW DATE: **9/15/2019**  
ADDRESS: **10740 S. Calhoun** IDPH LICENSE NO: **100-19716**

---

HOMOGENEOUS AREA: **D**  
MATERIAL DESCRIPTION: **Preformed Pipe Insulation**  
MATERIAL LOCATION: **1921 Building Basement**  
MATERIAL QUANTITY: **156** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/15/2019**



# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22331** BUIDLING ID: **2390**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Imani Robinson**  
SCHOOL NAME: **Bright School** INSPECTION DATE: **8/16/2019**  
ADDRESS: **10740 S. Calhoun** IDPH LICENSE NO: **100-19716**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **E**  
MATERIAL DESCRIPTION: **MJP E/F/V on Aircell Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout 1921 Building**  
MATERIAL QUANTITY: **25** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/16/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22331** BUIDLING ID: **2390**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Bright School** REVIEW DATE: **9/15/2019**  
ADDRESS: **10740 S. Calhoun** IDPH LICENSE NO: **100-19716**

---

HOMOGENEOUS AREA: **E**  
MATERIAL DESCRIPTION: **MJP E/F/V on Aircell Pipe Insulation**  
MATERIAL LOCATION: **Throughout 1921 Building**  
MATERIAL QUANTITY: **25** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/15/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **22331**    BUILDING ID: **2390**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Imani Robinson**  
SCHOOL NAME: **Bright School**    INSPECTION DATE: **8/16/2019**  
ADDRESS: **10740 S. Calhoun**    IDPH LICENSE NO: **100-19716**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FT-1**  
MATERIAL DESCRIPTION: **12x12 Beige Specks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY: **5 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON: **Physical Damage**  
DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Lunchroom Room 108 and Dress Room 109B**  
MATERIAL QUANTITY: **1900**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **50**    DAMAGE UNITS: **SF**  
COMMENTS: **Damage in Lunchroom**

Inspector's Signature: \_\_\_\_\_ Date: **08/16/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22331** BUIDLING ID: **2390**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Bright School** REVIEW DATE: **9/15/2019**  
ADDRESS: **10740 S. Calhoun** IDPH LICENSE NO: **100-19716**

---

HOMOGENEOUS AREA: **FT-1**  
MATERIAL DESCRIPTION: **12x12 Beige Specks Floor Tile**  
MATERIAL LOCATION: **Lunchroom Room 108 and Dress Room 109B**  
MATERIAL QUANTITY: **1900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **50** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/15/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **22331**    BUIDLING ID: **2390**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Imani Robinson**  
SCHOOL NAME: **Bright School**    INSPECTION DATE: **8/16/2019**  
ADDRESS: **10740 S. Calhoun**    IDPH LICENSE NO: **100-19716**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FT-2**  
MATERIAL DESCRIPTION: **12x12 Tan Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile**    FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Room 308**  
MATERIAL QUANTITY: **520**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/16/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22331** BUIDLING ID: **2390**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Bright School** REVIEW DATE: **9/15/2019**  
ADDRESS: **10740 S. Calhoun** IDPH LICENSE NO: **100-19716**

---

HOMOGENEOUS AREA: **FT-2**  
MATERIAL DESCRIPTION: **12x12 Tan Floor Tile**  
MATERIAL LOCATION: **Room 308**  
MATERIAL QUANTITY: **520** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/15/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22331** BUIDLING ID: **2390**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Imani Robinson**  
SCHOOL NAME: **Bright School** INSPECTION DATE: **8/16/2019**  
ADDRESS: **10740 S. Calhoun** IDPH LICENSE NO: **100-19716**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FTM-1**  
MATERIAL DESCRIPTION: **12x12 Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **5 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON: **Physical Damage**  
DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Lunchroom and Dress Room 109B**  
MATERIAL QUANTITY: **1900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **50** DAMAGE UNITS: **SF**  
COMMENTS: **Damage in Lunchroom**

Inspector's Signature: \_\_\_\_\_ Date: **08/16/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22331** BUIDLING ID: **2390**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Bright School** REVIEW DATE: **9/15/2019**  
ADDRESS: **10740 S. Calhoun** IDPH LICENSE NO: **100-19716**

---

HOMOGENEOUS AREA: **FTM-1**  
MATERIAL DESCRIPTION: **12x12 Floor Tile Mastic**  
MATERIAL LOCATION: **Lunchroom and Dress Room 109B**  
MATERIAL QUANTITY: **1900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **50** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/15/2019**



# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22331** BUIDLING ID: **2390**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Imani Robinson**  
SCHOOL NAME: **Bright School** INSPECTION DATE: **8/16/2019**  
ADDRESS: **10740 S. Calhoun** IDPH LICENSE NO: **100-19716**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FTM-2**  
MATERIAL DESCRIPTION: **12x12 Tan Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 308**  
MATERIAL QUANTITY: **520** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/16/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22331** BUIDLING ID: **2390**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Bright School** REVIEW DATE: **9/15/2019**  
ADDRESS: **10740 S. Calhoun** IDPH LICENSE NO: **100-19716**

---

HOMOGENEOUS AREA: **FTM-2**  
MATERIAL DESCRIPTION: **12x12 Tan Floor Tile Mastic**  
MATERIAL LOCATION: **Room 308**  
MATERIAL QUANTITY: **520** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/15/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22331** BUIDLING ID: **2390**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Imani Robinson**  
SCHOOL NAME: **Bright School** INSPECTION DATE: **8/16/2019**  
ADDRESS: **10740 S. Calhoun** IDPH LICENSE NO: **100-19716**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **G**  
MATERIAL DESCRIPTION: **MJP E/F/V on Cardboard Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Throughout 1921 Building**  
MATERIAL QUANTITY: **6** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/16/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22331** BUIDLING ID: **2390**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Bright School** REVIEW DATE: **9/15/2019**  
ADDRESS: **10740 S. Calhoun** IDPH LICENSE NO: **100-19716**

---

HOMOGENEOUS AREA: **G**  
MATERIAL DESCRIPTION: **MJP E/F/V on Cardboard Pipe Insulation**  
MATERIAL LOCATION: **Throughout 1921 Building**  
MATERIAL QUANTITY: **6** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/15/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22331** BUIDLING ID: **2390**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Imani Robinson**  
SCHOOL NAME: **Bright School** INSPECTION DATE: **8/16/2019**  
ADDRESS: **10740 S. Calhoun** IDPH LICENSE NO: **100-19716**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **H**  
MATERIAL DESCRIPTION: **MJP E/F/V on Preformed Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Throughout 1921 Building**  
MATERIAL QUANTITY: **20** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/16/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22331** BUILDING ID: **2390**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Bright School** REVIEW DATE: **9/15/2019**  
ADDRESS: **10740 S. Calhoun** IDPH LICENSE NO: **100-19716**

---

HOMOGENEOUS AREA: **H**  
MATERIAL DESCRIPTION: **MJP E/F/V on Preformed Pipe Insulation**  
MATERIAL LOCATION: **Throughout 1921 Building**  
MATERIAL QUANTITY: **20** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/15/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **22331**    BUIDLING ID: **2390**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Imani Robinson**  
SCHOOL NAME: **Bright School**    INSPECTION DATE: **8/16/2019**  
ADDRESS: **10740 S. Calhoun**    IDPH LICENSE NO: **100-19716**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **I**  
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **1938 Addition- Washrooms and Classrooms**  
MATERIAL QUANTITY: **0**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **08/16/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22331** BUIDLING ID: **2390**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Bright School** REVIEW DATE: **9/15/2019**  
ADDRESS: **10740 S. Calhoun** IDPH LICENSE NO: **100-19716**

---

HOMOGENEOUS AREA: **I**  
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**  
MATERIAL LOCATION: **1938 Addition- Washrooms and Classrooms**  
MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/15/2019**



# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **22331**    BUILDING ID: **2390**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Imani Robinson**  
SCHOOL NAME: **Bright School**    INSPECTION DATE: **8/16/2019**  
ADDRESS: **10740 S. Calhoun**    IDPH LICENSE NO: **100-19716**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **I-1**  
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY: **7 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile**    FRIABLE: **Yes**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1938 Addition- Air Tunnel**  
MATERIAL QUANTITY: **800**    MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **08/16/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22331** BUIDLING ID: **2390**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Bright School** REVIEW DATE: **9/15/2019**  
ADDRESS: **10740 S. Calhoun** IDPH LICENSE NO: **100-19716**

---

HOMOGENEOUS AREA: **I-1**  
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**  
MATERIAL LOCATION: **1938 Addition- Air Tunnel**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/15/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **22331**    BUILDING ID: **2390**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Imani Robinson**  
SCHOOL NAME: **Bright School**    INSPECTION DATE: **8/16/2019**  
ADDRESS: **10740 S. Calhoun**    IDPH LICENSE NO: **100-19716**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **J**  
MATERIAL DESCRIPTION: **Preform Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1938 Addition- Tunnel**  
MATERIAL QUANTITY: **100**    MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/16/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22331** BUIDLING ID: **2390**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Bright School** REVIEW DATE: **9/15/2019**  
ADDRESS: **10740 S. Calhoun** IDPH LICENSE NO: **100-19716**

---

HOMOGENEOUS AREA: **J**  
MATERIAL DESCRIPTION: **Preform Pipe Insulation**  
MATERIAL LOCATION: **1938 Addition- Tunnel**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/15/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22331** BUIDLING ID: **2390**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Imani Robinson**  
SCHOOL NAME: **Bright School** INSPECTION DATE: **8/16/2019**  
ADDRESS: **10740 S. Calhoun** IDPH LICENSE NO: **100-19716**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **K**  
MATERIAL DESCRIPTION: **MJP E/F/V on Aircell Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **1938 Addition- Mechanical**  
MATERIAL QUANTITY: **20** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/16/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22331** BUIDLING ID: **2390**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Bright School** REVIEW DATE: **9/15/2019**  
ADDRESS: **10740 S. Calhoun** IDPH LICENSE NO: **100-19716**

---

HOMOGENEOUS AREA: **K**  
MATERIAL DESCRIPTION: **MJP E/F/V on Aircell Pipe Insulation**  
MATERIAL LOCATION: **1938 Addition- Mechanical**  
MATERIAL QUANTITY: **20** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/15/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22331** BUIDLING ID: **2390**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Imani Robinson**  
SCHOOL NAME: **Bright School** INSPECTION DATE: **8/16/2019**  
ADDRESS: **10740 S. Calhoun** IDPH LICENSE NO: **100-19716**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **L**  
MATERIAL DESCRIPTION: **MJP E/F/V on Preformed Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **1938 Addition- Basement**  
MATERIAL QUANTITY: **50** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/16/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22331** BUIDLING ID: **2390**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Bright School** REVIEW DATE: **9/15/2019**  
ADDRESS: **10740 S. Calhoun** IDPH LICENSE NO: **100-19716**

---

HOMOGENEOUS AREA: **L**  
MATERIAL DESCRIPTION: **MJP E/F/V on Preformed Pipe Insulation**  
MATERIAL LOCATION: **1938 Addition- Basement**  
MATERIAL QUANTITY: **50** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/15/2019**



# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22331** BUIDLING ID: **2390**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Imani Robinson**  
SCHOOL NAME: **Bright School** INSPECTION DATE: **8/16/2019**  
ADDRESS: **10740 S. Calhoun** IDPH LICENSE NO: **100-19716**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **M**  
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Air Tunnel**  
MATERIAL QUANTITY: **40** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/16/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22331** BUIDLING ID: **2390**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Bright School** REVIEW DATE: **9/15/2019**  
ADDRESS: **10740 S. Calhoun** IDPH LICENSE NO: **100-19716**

---

HOMOGENEOUS AREA: **M**  
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**  
MATERIAL LOCATION: **Air Tunnel**  
MATERIAL QUANTITY: **40** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/15/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22331** BUIDLING ID: **2390**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Imani Robinson**  
SCHOOL NAME: **Bright School** INSPECTION DATE: **8/16/2019**  
ADDRESS: **10740 S. Calhoun** IDPH LICENSE NO: **100-19716**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **N**  
MATERIAL DESCRIPTION: **MJP E/F/V on Cardboard Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Air Tunnel**  
MATERIAL QUANTITY: **8** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/16/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22331** BUIDLING ID: **2390**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Bright School** REVIEW DATE: **9/15/2019**  
ADDRESS: **10740 S. Calhoun** IDPH LICENSE NO: **100-19716**

---

HOMOGENEOUS AREA: **N**

MATERIAL DESCRIPTION: **MJP E/F/V on Cardboard Pipe Insulation**

MATERIAL LOCATION: **Air Tunnel**

MATERIAL QUANTITY: **8**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/15/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22331** BUIDLING ID: **2390**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Imani Robinson**  
SCHOOL NAME: **Bright School** INSPECTION DATE: **8/16/2019**  
ADDRESS: **10740 S. Calhoun** IDPH LICENSE NO: **100-19716**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **0**  
MATERIAL DESCRIPTION: **MJP E/F/V on Fiberglass Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Engine Room, Janitor's Closets, Restrooms, Doctor's Office, Room 104, Storage Room and Main Office**

MATERIAL QUANTITY: **700** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/16/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22331** BUIDLING ID: **2390**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Bright School** REVIEW DATE: **9/15/2019**  
ADDRESS: **10740 S. Calhoun** IDPH LICENSE NO: **100-19716**

---

HOMOGENEOUS AREA: **0**  
MATERIAL DESCRIPTION: **MJP E/F/V on Fiberglass Pipe Insulation**  
MATERIAL LOCATION: **Engine Room, Janitor's Closets, Restrooms, Doctor's Office, Room 104, Storage Room and Main Office**  
MATERIAL QUANTITY: **700** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/15/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
*2019 AHERA REINSPECTION*

# APPENDIX B

## Inspector and Management Planner Licenses

---



# CERTIFICATE OF ACHIEVEMENT ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that IMANI ROBINSON  
has completed the ASBESTOS INSPECTOR'S INITIAL course and successfully passed the  
examination on 01/30/2019 with a minimum score of 70% or better. Training was in accordance  
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:  
Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.

01/28/2019-01/30/2019

Course Dates:

01/30/2020

Expires:

1901BI05

Certificate Number:



**PUBLIC HEALTH & SAFETY** inc.

Environmental and Occupational Services  
375 Ashland Ave., Chicago, IL 60607

[www.public-health-safety.com](http://www.public-health-safety.com)

Office: 312-491-0081  
Fax: 312-421-2901

Director of Training

Nicholas J. Peneff

Doctor of Public Health


Phone: 312-491-0081

FORM # A-010

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License



**ASBESTOS  
PROFESSIONAL  
LICENSE**

**ENDORSEMENTS**

**TC EXPIRES**

INSPECTOR

3/29/2020

ID NUMBER

100 - 19716

ISSUED

5/22/2019

EXPIRES

05/15/2020

PROJECT MANAGER

3/30/2020

AIR SAMPLING PROFESSIONAL

**IMANI ROBINSON**

12823 S. GREEN

CHICAGO, IL 60643

Environmental Health



**Alteration of this license shall result in legal action**  
This license issued under authority of the State of Illinois  
Department of Public Health  
This license is valid only when accompanied by a valid  
training course certificate.

2019



**OCCUPATIONAL TRAINING & SUPPLY, INC.**

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900 ♦ [www.otssafety.com](http://www.otssafety.com)

# Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

**John Fenn**

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 3/19/2019

Exam Date: 3/19/2019

Expiration Date: 3/19/2020

Certificate Number: BIR1903191011

A handwritten signature in black ink that reads 'Kathy DeSalvo'.

---

Kathy DeSalvo, Director



2019



**OCCUPATIONAL TRAINING & SUPPLY, INC.**

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900 ♦ [www.otssafety.com](http://www.otssafety.com)

# Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

**John Fenn**


has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 3/19/2019

Exam Date: 3/19/2019

Expiration Date: 3/19/2020

Certificate Number: MPR1903191035




---

Kathy DeSalvo, Director

# COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License



## ASBESTOS PROFESSIONAL LICENSE

### ENDORSEMENTS

### TC EXPIRES

INSPECTOR

3/19/2020

ID NUMBER

ISSUED

EXPIRES

MANAGEMENT PLANNER

3/19/2020

100 - 09786

4/11/2019

05/15/2020

PROJECT MANAGER

3/18/2020

**JOHN H FENN**

2829 N TROY ST

CHICAGO, IL 60618

Environmental Health



AIR SAMPLING PROFESSIONAL

**Alteration of this license shall result in legal action**  
This license issued under authority of the State of Illinois  
Department of Public Health

This license is valid only when accompanied by a valid  
training course certificate.

# APPENDIX C

## Laboratory Accreditations

---

# APPENDIX D

## Laboratory Results

---

# APPENDIX E

## Chain of Custody Forms

---



## Three-Year Reinspection Key to Terms

	<b>CODE</b>	<b>KEY</b>
<b>MATERIAL</b>		
	ACBM	Asbestos Containing Building Materials
<b>MATERIAL CATEGORY</b>		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
<b>MATERIAL UNITS</b>		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
<b>DAMAGE TYPE</b>		
	Loc	Localized
	Dist	Distributed