

ILLINOIS DEPARTMENT OF PUBLIC HEALTH  
AHERA THREE YEAR REINSPECTION  
ASBESTOS ABATEMENT PROGRAM  
SCHOOL INFORMATION FORM

**SECTION I**

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299  
SCHOOL ID NUMBER: 14-016-2990-2100  
SCHOOL NAME: Bouchet Academy  
ADDRESS OF SCHOOL: 7355 S. Jeffrey Blvd.  
CITY: Chicago, IL, 60649

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **3/15/2016**

**If the address on this form is different than the address of the building, submit a written explanation.**

**SECTION II** (Please type or print)

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 10/1/2019 ENROLLMENT 668  
IDPH INSPECTOR LICENSE NUMBER: 100-11167  
IDPH LICENSED INSPECTOR NAME(Please Print): Brian Barry  
IDPH MP LICENSE NUMBER: 100-09786  
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): John Fenn

DESIGNATED PERSON (Please Print): Robert Christlieb PHONE: (773) 553-3197



10/1/2019

Signature of Designated Person

Date

**SECTION III**

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: \_\_\_\_\_

School has been closed. Date closed: \_\_\_\_\_

School building has been demolished. Date: \_\_\_\_\_

School building is asbestos free since last reinspection: \_\_\_\_\_

**Please explain in writing why the school building is now asbestos free and include the supporting documentation.**

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

**Explain in writing if the address of the building is different than the address on this form:**

**THREE-YEAR REINSPECTION**

**CHICAGO SCHOOL DIST 299**

**Bouchet Academy**

7355 S. Jeffrey Blvd.  
Chicago, IL, 60649

Unit: 22371  
Building ID: 2430

IDPH ID Number: 14-016-2990-2100

**REPORT DATE:**

Tuesday, October 01, 2019

**Prepared for:**

**Chicago Public Schools  
42 West Madison Street  
Chicago, IL 60602**

**Prepared by:**

**TEM Environmental, Inc.**

174 N. Brandon Drive

Glendale Heights, IL, 60139

Phone 630-790-0880

Fax 630-790-0882

**DO NOT REMOVE FROM SCHOOL  
REQUIRED BY FEDERAL LAW**

October 20, 2019

Mr. Glen E. Garner  
Asbestos Program  
Illinois Department of Public Health  
525 West Jefferson Street  
Springfield, Illinois 62761

Re: Chicago Public Schools - 2019 Three-Year Reinspections

Dear Mr. Glen:

TEM Environmental, Inc. , Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 5, 6 Elementary Schools. Please update your records with the following information.

School District: 299          Unit: 22371          Region: 05          IDPH ID:14-016-2990-2100

School: Bouchet Academy          Building ID: 2430

Address: 7355 S. Jeffrey Blvd.

Chicago, IL, 60649

Building Contact: Kennedy, David

Contact Phone:

Current Building Owners: Chicago Public Schools

Review Date: 11/04/2019

Inspector: Brian Barry

Inspector IDPH License: 100-11167

Management Planner: John Fenn

Management Planner IDPH License: 100-09786

If you have any questions or comments, please contact us at 630-790-0880

Sincerely,  
TEM Environmental, Inc.

John Fenn  
100-09786

## **Environmental Notification to Occupants**

To: Faculty, Staff and Parents  
From: Chicago Public Schools  
Date: October 20, 2019

RE: Bouchet Academy, Unit 22371  
7355 S. Jeffrey Blvd.  
Chicago, IL, 60649

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2019 asbestos three year re-inspection has been completed at Bouchet Academy, following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at Bouchet Academy, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Robert Christlieb, the designated Local Education Authority's Designated Person at (773) 553-3197 .

## **Table of Contents**

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

### **APPENDICES:**

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

## SCHOOL AND INSPECTION INFORMATION

### 1. School Information

School: Bouchet Academy  
Address: 7355 S. Jeffrey Blvd.  
IDPH ID: 14-016-2990-2100  
Contact: Kennedy, David

Unit: 22371  
Chicago, IL, 60649  
Building ID: 2430  
Phone:

Region: 05

### 2. Description of Facility

Original Construction: 1914  
Total Square Footage: 55927  
Current Occupancy: 668

Additional Construction: 1903,1922  
No of Floors: 3

### 3. LEA Designated Person

Contact: Robert Christlieb  
Address: 42 West Madison Street  
Chicago, IL 60602

Phone: (773) 553-3197

### 4. Managing Environmental Consultant

MEC: TEM Environmental, Inc.  
Contact: Steven Geneser  
Address 174 N. Brandon Drive  
Glendale Heights, IL, 60139  
Phone: 630-790-0880

Fax: 630-790-0882

### 5. Inspector

Inspector Name: Brian Barry

Inspector IDPH license # 100-11167

Signature:  
Date: 10/20/2019

### 6. Management Planner

Management Planner Name: John Fenn

Management Planner IDPH license # 100-09786

Signature:  
Date: 11/04/2019

### 7. Review Date:11/04/2019

### 8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature:



Date: 10/1/2019

Name: Robert Christlieb

## II. EXECUTIVE SUMMARY

TEM Environmental, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Bouchet Academy. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.85 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas(HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 2430:

10	Aircell Pipe Insulation
A	Aircell Pipe Insulation

B. The following new homogenous areas have been identified for Building 2430:



C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

03B	12"x12" Mottled Beige Floor Tile
03F	Purple 12"x12" Carpet Mastic
05	Green Linoleum
06	Vinyl Mopboard
07	Vinyl Mopboard Mastic
08	Fire Doors
09	Incinerator Door
11E	Mastic for HA 03E
13	12x12 Cream w/Beige & Grey Floor Tile
14	12x12 Brown Vinyl Floor Tile
14M	12 x 12 Brown Floor Tile Mastic
15	12x12 Gray Speckled Vinyl Floor Tile
15M	12 x 12 Gray Speckled Floor Tile Mastic

The following areas were deemed to be inaccessible:

07	Vinyl Mopboard Mastic
11	Mastic for HA #03
11B	Mastic for HA 03B
11C	Mastic for HA # 03C
11E	Mastic for HA 03E
14M	12 x 12 Brown Floor Tile Mastic
15M	12 x 12 Gray Speckled Floor Tile Mastic
A	Aircell Pipe Insulation

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Brian Barry, IDPH License # 100-11167. The Management Plan was updated by John Fenn, IDPH License # 100-09786. Inspector and Management Planner Licenses are included in Appendix B.

### III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

### IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:	7/27/2018
	7/27/2018
	7/27/2018
	7/27/2018
	7/27/2018
	7/27/2018
	7/27/2018
	7/27/2018
	7/27/2018
	7/27/2018
	7/27/2018
	7/27/2018
	7/27/2018
	7/27/2018

### V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

### VI. CONCLUSIONS

The Bouchet Academy Building 2430 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. Atimely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.



**Table I**  
**Inspector's Reinspection Findings**

---





# Chicago Public Schools

School Bouchet Academy Unit 22371 Building ID 2430  
Address 7355 S. Jeffrey Blvd. Region 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

Reinspection Date <b>10/20/2019</b>
Inspector Name <b>Brian Barry</b>
<b>100-11167</b> <b>5/15/2020</b>
Inspector's IDPH License Number / Expiration Date

#### Inspector's Comments

HA Number:	Inspector Comments:
03A	
03	2018 Abatement-design drawings are blank so areas/quantities questionable
03A	Not Observed 2019; 2018 Abatement
03B	Multiple areas abated 2018
03C	
03D	Abated 2018
03E	
03F	Not Observed 2019
04	
05	
06	
07	
08	
09	Not Observed 2019
10	Not Observed 2019
11	2018 Abatement-design drawings are blank so areas/quantities questionable
11A	Not Observed 2019; 2018 Abatement
11B	Multiple areas abated 2018
11C	
11D	
11E	
12	
13	

# Chicago Public Schools

**School** Bouchet Academy **Unit** 22371 **Building ID** 2430

**Address** 7355 S. Jeffrey Blvd. **Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
14	
14M	
15	
15M	
16	Rms. were abated in 2018
16M	Rms. were abated in 2018
A	
B	
G	
H	



**Table II**

**Management Planner's Review**

---

# Chicago Public Schools

School Bouchet Academy

Unit 22371

Building ID 2430

Address 7355 S. Jeffrey Blvd.

Chicago, IL, 60649

Region 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

### Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
03A	9"x 9" Red Floor Tile ABATED			2nd & 3rd Floor Corridors	Abated	MISC					
03	12"x12" Brown w/White Streaks Floor Tile	15,000	SF	1st, 2nd, 3rd & Basement Corridors North Girls' Restroom 1, 2, 3, Basement, Teachers' Restroom 1, 2, 3	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
03A	12"X12" Tan w/Brown Specks Floor Tile - ABATED			Rooms 1, 2, 4, Dining Room, 311, 109, 210, 110, Pass Office, 100	Abated	MISC					
03B	12"x12" Mottled Beige Floor Tile	1,800	SF	Room 205, 101	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
03C	12"x12" Off White w/Tan Floor Tile	6,900	SF	Rooms 100, 200, 204, 105, Corridor	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
03D	12"x12" Tan w/White & Brown Floor Tile-ABATED			Room 104	Abated	MISC					
03E	12"x12" Mottled Green Floor Tile	250	SF	Engineer's Office	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
03F	Purple 12"x12" Carpet Mastic			Room 108	Assumed	MISC					
04	Linoleum ABATED			Room 200	Abated	MISC					
05	Green Linoleum	2,300	SF	Gym	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
06	Vinyl Mopboard	500	LF	Restrooms throughout, 2nd Floor Corridor, Room 109	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
07	Vinyl Mopboard Mastic	500	LF	Restrooms Throughout	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
08	Fire Doors	6	EA	Gym	Assumed	MISC	No	0	EA	6 ACBM with the potential for damage	Follow O&M Plan
09	Incinerator Door			Boiler Room	Assumed	MISC					
10	Aircell Pipe Insulation			Unexcavated Areas, N & S Heat Plenum, Pump Room	Chrysotile	TSI					
11	Mastic for HA #03	15,000	SF	1st, 2nd, 3rd & Basement Corridors, North Girls' Restroom 1, 2, 3, Basement, Teachers' Restroom 1, 2, 3	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
11A	Mastic for HA #03A-ABATED			Rooms 1, 2, 4, Dining Room, 311, 109, 210, 110, Pass Office, 100	Abated	MISC					
11B	Mastic for HA 03B	1,800	SF	Room 205, 101	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
11C	Mastic for HA # 03C	6,900	SF	Rooms 100, 200, 204, 105, Corridor	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
11D	Mastic for HA #03D-ABATED			Room 104	Abated	MISC					
11E	Mastic for HA 03E	250	SF	Engineer's Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
12	Linoleum Mastic ABATED			Room 200	Abated	MISC					
13	12x12 Cream w/Beige & Grey Floor Tile	900	SF	Room 200	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
14	12x12 Brown Vinyl Floor Tile	2,000	SF	2nd & 3rd Floor Corridors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
14M	12 x 12 Brown Floor Tile Mastic	2,000	SF	2nd & 3rd Floor Corridors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
15	12x12 Gray Speckled Vinyl Floor Tile	600	SF	Room 108	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Bouchet Academy  
**Address** 7355 S. Jeffrey Blvd.

**Unit** 22371  
 Chicago, IL, 60649

**Building ID** 2430  
**Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
15M	12 x 12 Gray Speckled Floor Tile Mastic	600	SF	Room 108	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
16	12" x 12" White w/Gray Speckles-Abated			Rooms 001, 002, 004 & 005	Abated	MISC					
16M	12" x 12" White w/ Gray Speckles Mastic-Abated			Rooms 001, 002, 004 & 005	Abated	MISC		0			
A	Aircell Pipe Insulation	150	LF	Kitchen, Basement Corridor, Room 100, 200	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
B	Magblock ABATED			Boiler Room	Abated	TSI					
G	Preform ABATED			Boiler Room	Abated	TSI					
H	Boiler Gaskets ABATED			Boiler Rom	Abated	MISC					

# Chicago Public Schools

**School** Bouchet Academy  
**Address** 7355 S. Jeffrey Blvd.

**Unit** 22371  
 Chicago, IL, 60649

**Building ID** 2430  
**Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

### *Management Planner's Comments Summarized at the End of the Report*

Review Date	11/04/2019
Manager Planner Name	John Fenn
100-09786	5/15/2020
Manager IDPH License No/Expiration	

HA Number	Management Comments
03A	
03	
03A	
03B	
03C	
03D	
03E	
03F	
04	
05	
06	
07	
08	
09	No response based on previous MP
10	
11	
11A	
11B	
11C	
11D	
11E	
12	
13	
14	
14M	

# Chicago Public Schools

**School** Bouchet Academy  
**Address** 7355 S. Jeffrey Blvd.

**Unit** 22371  
Chicago, IL, 60649

**Building ID** 2430  
**Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
15	
15M	
16	
16M	
A	
B	
G	
H	

# Chicago Public Schools

TEM Environmental, Inc.

## 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **22371**    BUILDING ID: **2430**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Brian Barry**  
SCHOOL NAME: **Bouchet Academy**    INSPECTION DATE: **10/20/2019**  
ADDRESS: **7355 S. Jeffrey Blvd.**    IDPH LICENSE NO: **100-11167**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **03A**  
MATERIAL DESCRIPTION: **9"x 9" Red Floor Tile ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated**    FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **2nd & 3rd Floor Corridors**

MATERIAL QUANTITY:    MATERIAL UNITS:

DAMAGE QUANTITY:    DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **10/20/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22371** BUILDING ID: **2430**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Bouchet Academy** REVIEW DATE: **11/4/2019**  
ADDRESS: **7355 S. Jeffrey Blvd.** IDPH LICENSE NO: **100-11167**

---

HOMOGENEOUS AREA: **03A**  
MATERIAL DESCRIPTION: **9"x 9" Red Floor Tile ABATED**  
MATERIAL LOCATION: **2nd & 3rd Floor Corridors**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/04/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22371** BUIDLING ID: **2430**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Brian Barry**  
SCHOOL NAME: **Bouchet Academy** INSPECTION DATE: **10/20/2019**  
ADDRESS: **7355 S. Jeffrey Blvd.** IDPH LICENSE NO: **100-11167**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **03**  
MATERIAL DESCRIPTION: **12"x12" Brown w/White Streaks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON: **Physical Damage**  
HISTORICAL RESPONSE ACTION: **Repair**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st, 2nd, 3rd & Basement Corridors North Girls' Restroom 1, 2, 3, Basement, Teachers' Restroom 1, 2, 3**

MATERIAL QUANTITY: **15000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS: **2018 Abatement-design drawings are blank so areas/quantities questionable**

Inspector's Signature: \_\_\_\_\_ Date: 10/20/2019



# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22371** BUIDLING ID: **2430**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Bouchet Academy** REVIEW DATE: **11/4/2019**  
ADDRESS: **7355 S. Jeffrey Blvd.** IDPH LICENSE NO: **100-11167**

---

HOMOGENEOUS AREA: **03**  
MATERIAL DESCRIPTION: **12"x12" Brown w/White Streaks Floor Tile**  
MATERIAL LOCATION: **1st, 2nd, 3rd & Basement Corridors North Girls' Restroom 1, 2, 3, Basement, Teachers' Restroom 1, 2, 3**  
MATERIAL QUANTITY: **15000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/04/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22371** BUIDLING ID: **2430**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Brian Barry**  
SCHOOL NAME: **Bouchet Academy** INSPECTION DATE: **10/20/2019**  
ADDRESS: **7355 S. Jeffrey Blvd.** IDPH LICENSE NO: **100-11167**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **03A**  
MATERIAL DESCRIPTION: **12"X12" Tan w/Brown Specks Floor Tile - ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 1, 2, 4, Dining Room, 311, 109, 210, 110, Pass Office, 100**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not Observed 2019; 2018 Abatement**

Inspector's Signature: \_\_\_\_\_ Date: 10/20/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22371** BUIDLING ID: **2430**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Bouchet Academy** REVIEW DATE: **11/4/2019**  
ADDRESS: **7355 S. Jeffrey Blvd.** IDPH LICENSE NO: **100-11167**

---

HOMOGENEOUS AREA: **03A**  
MATERIAL DESCRIPTION: **12"X12" Tan w/Brown Specks Floor Tile - ABATED**  
MATERIAL LOCATION: **Rooms 1, 2, 4, Dining Room, 311, 109, 210, 110, Pass Office, 100**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/04/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22371** BUIDLING ID: **2430**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Brian Barry**  
SCHOOL NAME: **Bouchet Academy** INSPECTION DATE: **10/20/2019**  
ADDRESS: **7355 S. Jeffrey Blvd.** IDPH LICENSE NO: **100-11167**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **03B**  
MATERIAL DESCRIPTION: **12"x12" Mottled Beige Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 205, 101**  
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**  
COMMENTS: **Multiple areas abated 2018**

Inspector's Signature: \_\_\_\_\_ Date: 10/20/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22371** BUIDLING ID: **2430**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Bouchet Academy** REVIEW DATE: **11/4/2019**  
ADDRESS: **7355 S. Jeffrey Blvd.** IDPH LICENSE NO: **100-11167**

---

HOMOGENEOUS AREA: **03B**  
MATERIAL DESCRIPTION: **12"x12" Mottled Beige Floor Tile**  
MATERIAL LOCATION: **Room 205, 101**  
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/04/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22371** BUIDLING ID: **2430**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Brian Barry**  
SCHOOL NAME: **Bouchet Academy** INSPECTION DATE: **10/20/2019**  
ADDRESS: **7355 S. Jeffrey Blvd.** IDPH LICENSE NO: **100-11167**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **03C**  
MATERIAL DESCRIPTION: **12"x12" Off White w/Tan Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 100, 200, 204, 105, Corridor**  
MATERIAL QUANTITY: **6900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/20/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22371** BUIDLING ID: **2430**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Bouchet Academy** REVIEW DATE: **11/4/2019**  
ADDRESS: **7355 S. Jeffrey Blvd.** IDPH LICENSE NO: **100-11167**

---

HOMOGENEOUS AREA: **03C**  
MATERIAL DESCRIPTION: **12"x12" Off White w/Tan Floor Tile**  
MATERIAL LOCATION: **Rooms 100, 200, 204, 105, Corridor**  
MATERIAL QUANTITY: **6900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/04/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22371** BUIDLING ID: **2430**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Brian Barry**  
SCHOOL NAME: **Bouchet Academy** INSPECTION DATE: **10/20/2019**  
ADDRESS: **7355 S. Jeffrey Blvd.** IDPH LICENSE NO: **100-11167**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **03D**  
MATERIAL DESCRIPTION: **12"x12" Tan w/White & Brown Floor Tile-ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Abated** FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 104**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Abated 2018**

Inspector's Signature: \_\_\_\_\_ Date: 10/20/2019



# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22371** BUIDLING ID: **2430**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Bouchet Academy** REVIEW DATE: **11/4/2019**  
ADDRESS: **7355 S. Jeffrey Blvd.** IDPH LICENSE NO: **100-11167**

---

HOMOGENEOUS AREA: **03D**

MATERIAL DESCRIPTION: **12"x12" Tan w/White & Brown Floor Tile-ABATED**

MATERIAL LOCATION: **Room 104**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/04/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22371** BUIDLING ID: **2430**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Brian Barry**  
SCHOOL NAME: **Bouchet Academy** INSPECTION DATE: **10/20/2019**  
ADDRESS: **7355 S. Jeffrey Blvd.** IDPH LICENSE NO: **100-11167**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **03E**  
MATERIAL DESCRIPTION: **12"x12" Mottled Green Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Engineer's Office**  
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/20/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22371** BUIDLING ID: **2430**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Bouchet Academy** REVIEW DATE: **11/4/2019**  
ADDRESS: **7355 S. Jeffrey Blvd.** IDPH LICENSE NO: **100-11167**

---

HOMOGENEOUS AREA: **03E**  
MATERIAL DESCRIPTION: **12"x12" Mottled Green Floor Tile**  
MATERIAL LOCATION: **Engineer's Office**  
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/04/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22371** BUIDLING ID: **2430**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Brian Barry**  
SCHOOL NAME: **Bouchet Academy** INSPECTION DATE: **10/20/2019**  
ADDRESS: **7355 S. Jeffrey Blvd.** IDPH LICENSE NO: **100-11167**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **03F**  
MATERIAL DESCRIPTION: **Purple 12"x12" Carpet Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 108**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed 2019**

Inspector's Signature: \_\_\_\_\_ Date: **10/20/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22371** BUILDING ID: **2430**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Bouchet Academy** REVIEW DATE: **11/4/2019**  
ADDRESS: **7355 S. Jeffrey Blvd.** IDPH LICENSE NO: **100-11167**

---

HOMOGENEOUS AREA: **03F**  
MATERIAL DESCRIPTION: **Purple 12"x12" Carpet Mastic**  
MATERIAL LOCATION: **Room 108**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/04/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22371** BUIDLING ID: **2430**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Brian Barry**  
SCHOOL NAME: **Bouchet Academy** INSPECTION DATE: **10/20/2019**  
ADDRESS: **7355 S. Jeffrey Blvd.** IDPH LICENSE NO: **100-11167**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **04**  
MATERIAL DESCRIPTION: **Linoleum ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 200**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **10/20/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22371** BUIDLING ID: **2430**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Bouchet Academy** REVIEW DATE: **11/4/2019**  
ADDRESS: **7355 S. Jeffrey Blvd.** IDPH LICENSE NO: **100-11167**

---

HOMOGENEOUS AREA: **04**

MATERIAL DESCRIPTION: **Linoleum ABATED**

MATERIAL LOCATION: **Room 200**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/04/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22371** BUIDLING ID: **2430**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Brian Barry**  
SCHOOL NAME: **Bouchet Academy** INSPECTION DATE: **10/20/2019**  
ADDRESS: **7355 S. Jeffrey Blvd.** IDPH LICENSE NO: **100-11167**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **05**  
MATERIAL DESCRIPTION: **Green Linoleum**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Gym**  
MATERIAL QUANTITY: **2300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/20/2019



# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22371** BUIDLING ID: **2430**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Bouchet Academy** REVIEW DATE: **11/4/2019**  
ADDRESS: **7355 S. Jeffrey Blvd.** IDPH LICENSE NO: **100-11167**

---

HOMOGENEOUS AREA: **05**  
MATERIAL DESCRIPTION: **Green Linoleum**  
MATERIAL LOCATION: **Gym**  
MATERIAL QUANTITY: **2300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/04/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22371** BUIDLING ID: **2430**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Brian Barry**  
SCHOOL NAME: **Bouchet Academy** INSPECTION DATE: **10/20/2019**  
ADDRESS: **7355 S. Jeffrey Blvd.** IDPH LICENSE NO: **100-11167**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **06**  
MATERIAL DESCRIPTION: **Vinyl Mopboard**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Restrooms throughout, 2nd Floor Corridor, Room 109**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/20/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22371** BUIDLING ID: **2430**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Bouchet Academy** REVIEW DATE: **11/4/2019**  
ADDRESS: **7355 S. Jeffrey Blvd.** IDPH LICENSE NO: **100-11167**

---

HOMOGENEOUS AREA: **06**  
MATERIAL DESCRIPTION: **Vinyl Mopboard**  
MATERIAL LOCATION: **Restrooms throughout, 2nd Floor Corridor, Room 109**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/04/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22371** BUIDLING ID: **2430**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Brian Barry**  
SCHOOL NAME: **Bouchet Academy** INSPECTION DATE: **10/20/2019**  
ADDRESS: **7355 S. Jeffrey Blvd.** IDPH LICENSE NO: **100-11167**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **07**  
MATERIAL DESCRIPTION: **Vinyl Mopboard Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Restrooms Throughout**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/20/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22371** BUIDLING ID: **2430**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Bouchet Academy** REVIEW DATE: **11/4/2019**  
ADDRESS: **7355 S. Jeffrey Blvd.** IDPH LICENSE NO: **100-11167**

---

HOMOGENEOUS AREA: **07**  
MATERIAL DESCRIPTION: **Vinyl Mopboard Mastic**  
MATERIAL LOCATION: **Restrooms Throughout**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/04/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22371** BUIDLING ID: **2430**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Brian Barry**  
SCHOOL NAME: **Bouchet Academy** INSPECTION DATE: **10/20/2019**  
ADDRESS: **7355 S. Jeffrey Blvd.** IDPH LICENSE NO: **100-11167**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **08**  
MATERIAL DESCRIPTION: **Fire Doors**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Gym**  
MATERIAL QUANTITY: **6** MATERIAL UNITS: **EA**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/20/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22371** BUIDLING ID: **2430**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Bouchet Academy** REVIEW DATE: **11/4/2019**  
ADDRESS: **7355 S. Jeffrey Blvd.** IDPH LICENSE NO: **100-11167**

---

HOMOGENEOUS AREA: **08**  
MATERIAL DESCRIPTION: **Fire Doors**  
MATERIAL LOCATION: **Gym**  
MATERIAL QUANTITY: **6** MATERIAL UNITS: **EA**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/04/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22371** BUIDLING ID: **2430**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Brian Barry**  
SCHOOL NAME: **Bouchet Academy** INSPECTION DATE: **10/20/2019**  
ADDRESS: **7355 S. Jeffrey Blvd.** IDPH LICENSE NO: **100-11167**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **09**  
MATERIAL DESCRIPTION: **Incinerator Door**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed 2019**

Inspector's Signature: \_\_\_\_\_ Date: **10/20/2019**



# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22371** BUIDLING ID: **2430**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Bouchet Academy** REVIEW DATE: **11/4/2019**  
ADDRESS: **7355 S. Jeffrey Blvd.** IDPH LICENSE NO: **100-11167**

---

HOMOGENEOUS AREA: **09**

MATERIAL DESCRIPTION: **Incinerator Door**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

No response based on previous MP

Management Planner's Signature: \_\_\_\_\_ Date: **11/04/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22371** BUIDLING ID: **2430**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Brian Barry**  
SCHOOL NAME: **Bouchet Academy** INSPECTION DATE: **10/20/2019**  
ADDRESS: **7355 S. Jeffrey Blvd.** IDPH LICENSE NO: **100-11167**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10**  
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Unexcavated Areas, N & S Heat Plenum, Pump Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not Observed 2019**

Inspector's Signature: \_\_\_\_\_ Date: **10/20/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22371** BUILDING ID: **2430**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Bouchet Academy** REVIEW DATE: **11/4/2019**  
ADDRESS: **7355 S. Jeffrey Blvd.** IDPH LICENSE NO: **100-11167**

---

HOMOGENEOUS AREA: **10**  
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**  
MATERIAL LOCATION: **Unexcavated Areas, N & S Heat Plenum, Pump Room**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/04/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22371** BUIDLING ID: **2430**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Brian Barry**  
SCHOOL NAME: **Bouchet Academy** INSPECTION DATE: **10/20/2019**  
ADDRESS: **7355 S. Jeffrey Blvd.** IDPH LICENSE NO: **100-11167**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11**  
MATERIAL DESCRIPTION: **Mastic for HA #03**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st, 2nd, 3rd & Basement Corridors, North Girls' Restroom 1, 2, 3, Basement, Teachers' Restroom 1, 2, 3**

MATERIAL QUANTITY: **15000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS: **2018 Abatement-design drawings are blank so areas/quantities questionable**

Inspector's Signature: \_\_\_\_\_ Date: 10/20/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22371** BUILDING ID: **2430**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Bouchet Academy** REVIEW DATE: **11/4/2019**  
ADDRESS: **7355 S. Jeffrey Blvd.** IDPH LICENSE NO: **100-11167**

---

HOMOGENEOUS AREA: **11**  
MATERIAL DESCRIPTION: **Mastic for HA #03**  
MATERIAL LOCATION: **1st, 2nd, 3rd & Basement Corridors, North Girls' Restroom 1, 2, 3, Basement, Teachers' Restroom 1, 2, 3**  
MATERIAL QUANTITY: **15000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/04/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22371** BUIDLING ID: **2430**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Brian Barry**  
SCHOOL NAME: **Bouchet Academy** INSPECTION DATE: **10/20/2019**  
ADDRESS: **7355 S. Jeffrey Blvd.** IDPH LICENSE NO: **100-11167**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11A**  
MATERIAL DESCRIPTION: **Mastic for HA #03A-ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 1, 2, 4, Dining Room, 311, 109, 210, 110, Pass Office, 100**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not Observed 2019; 2018 Abatement**

Inspector's Signature: \_\_\_\_\_ Date: 10/20/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22371** BUILDING ID: **2430**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Bouchet Academy** REVIEW DATE: **11/4/2019**  
ADDRESS: **7355 S. Jeffrey Blvd.** IDPH LICENSE NO: **100-11167**

---

HOMOGENEOUS AREA: **11A**  
MATERIAL DESCRIPTION: **Mastic for HA #03A-ABATED**  
MATERIAL LOCATION: **Rooms 1, 2, 4, Dining Room, 311, 109, 210, 110, Pass Office, 100**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/04/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22371** BUIDLING ID: **2430**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Brian Barry**  
SCHOOL NAME: **Bouchet Academy** INSPECTION DATE: **10/20/2019**  
ADDRESS: **7355 S. Jeffrey Blvd.** IDPH LICENSE NO: **100-11167**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11B**  
MATERIAL DESCRIPTION: **Mastic for HA 03B**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 205, 101**  
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**  
COMMENTS: **Multiple areas abated 2018**

Inspector's Signature: \_\_\_\_\_ Date: 10/20/2019



# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22371** BUIDLING ID: **2430**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Bouchet Academy** REVIEW DATE: **11/4/2019**  
ADDRESS: **7355 S. Jeffrey Blvd.** IDPH LICENSE NO: **100-11167**

---

HOMOGENEOUS AREA: **11B**  
MATERIAL DESCRIPTION: **Mastic for HA 03B**  
MATERIAL LOCATION: **Room 205, 101**  
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/04/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22371** BUIDLING ID: **2430**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Brian Barry**  
SCHOOL NAME: **Bouchet Academy** INSPECTION DATE: **10/20/2019**  
ADDRESS: **7355 S. Jeffrey Blvd.** IDPH LICENSE NO: **100-11167**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11C**  
MATERIAL DESCRIPTION: **Mastic for HA # 03C**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 100, 200, 204, 105, Corridor**  
MATERIAL QUANTITY: **6900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/20/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22371** BUIDLING ID: **2430**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Bouchet Academy** REVIEW DATE: **11/4/2019**  
ADDRESS: **7355 S. Jeffrey Blvd.** IDPH LICENSE NO: **100-11167**

---

HOMOGENEOUS AREA: **11C**  
MATERIAL DESCRIPTION: **Mastic for HA # 03C**  
MATERIAL LOCATION: **Rooms 100, 200, 204, 105, Corridor**  
MATERIAL QUANTITY: **6900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/04/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22371** BUIDLING ID: **2430**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Brian Barry**  
SCHOOL NAME: **Bouchet Academy** INSPECTION DATE: **10/20/2019**  
ADDRESS: **7355 S. Jeffrey Blvd.** IDPH LICENSE NO: **100-11167**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11D**  
MATERIAL DESCRIPTION: **Mastic for HA #03D-ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 104**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/20/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22371** BUIDLING ID: **2430**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Bouchet Academy** REVIEW DATE: **11/4/2019**  
ADDRESS: **7355 S. Jeffrey Blvd.** IDPH LICENSE NO: **100-11167**

---

HOMOGENEOUS AREA: **11D**  
MATERIAL DESCRIPTION: **Mastic for HA #03D-ABATED**  
MATERIAL LOCATION: **Room 104**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/04/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **22371**    BUIDLING ID: **2430**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Brian Barry**  
SCHOOL NAME: **Bouchet Academy**    INSPECTION DATE: **10/20/2019**  
ADDRESS: **7355 S. Jeffrey Blvd.**    IDPH LICENSE NO: **100-11167**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11E**  
MATERIAL DESCRIPTION: **Mastic for HA 03E**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Engineer's Office**  
MATERIAL QUANTITY: **250**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/20/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22371** BUIDLING ID: **2430**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Bouchet Academy** REVIEW DATE: **11/4/2019**  
ADDRESS: **7355 S. Jeffrey Blvd.** IDPH LICENSE NO: **100-11167**

---

HOMOGENEOUS AREA: **11E**  
MATERIAL DESCRIPTION: **Mastic for HA 03E**  
MATERIAL LOCATION: **Engineer's Office**  
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/04/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22371** BUIDLING ID: **2430**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Brian Barry**  
SCHOOL NAME: **Bouchet Academy** INSPECTION DATE: **10/20/2019**  
ADDRESS: **7355 S. Jeffrey Blvd.** IDPH LICENSE NO: **100-11167**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12**  
MATERIAL DESCRIPTION: **Linoleum Mastic ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 200**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **10/20/2019**



# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22371** BUIDLING ID: **2430**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Bouchet Academy** REVIEW DATE: **11/4/2019**  
ADDRESS: **7355 S. Jeffrey Blvd.** IDPH LICENSE NO: **100-11167**

---

HOMOGENEOUS AREA: **12**

MATERIAL DESCRIPTION: **Linoleum Mastic ABATED**

MATERIAL LOCATION: **Room 200**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/04/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **22371**    BUILDING ID: **2430**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Brian Barry**  
SCHOOL NAME: **Bouchet Academy**    INSPECTION DATE: **10/20/2019**  
ADDRESS: **7355 S. Jeffrey Blvd.**    IDPH LICENSE NO: **100-11167**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13**  
MATERIAL DESCRIPTION: **12x12 Cream w/Beige & Grey Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 200**  
MATERIAL QUANTITY: **900**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/20/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22371** BUIDLING ID: **2430**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Bouchet Academy** REVIEW DATE: **11/4/2019**  
ADDRESS: **7355 S. Jeffrey Blvd.** IDPH LICENSE NO: **100-11167**

---

HOMOGENEOUS AREA: **13**  
MATERIAL DESCRIPTION: **12x12 Cream w/Beige & Grey Floor Tile**  
MATERIAL LOCATION: **Room 200**  
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/04/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **22371**    BUILDING ID: **2430**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Brian Barry**  
SCHOOL NAME: **Bouchet Academy**    INSPECTION DATE: **10/20/2019**  
ADDRESS: **7355 S. Jeffrey Blvd.**    IDPH LICENSE NO: **100-11167**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14**  
MATERIAL DESCRIPTION: **12x12 Brown Vinyl Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **2nd & 3rd Floor Corridors**  
MATERIAL QUANTITY: **2000**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/20/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22371** BUIDLING ID: **2430**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Bouchet Academy** REVIEW DATE: **11/4/2019**  
ADDRESS: **7355 S. Jeffrey Blvd.** IDPH LICENSE NO: **100-11167**

---

HOMOGENEOUS AREA: **14**  
MATERIAL DESCRIPTION: **12x12 Brown Vinyl Floor Tile**  
MATERIAL LOCATION: **2nd & 3rd Floor Corridors**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/04/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22371** BUIDLING ID: **2430**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Brian Barry**  
SCHOOL NAME: **Bouchet Academy** INSPECTION DATE: **10/20/2019**  
ADDRESS: **7355 S. Jeffrey Blvd.** IDPH LICENSE NO: **100-11167**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14M**  
MATERIAL DESCRIPTION: **12 x 12 Brown Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **2nd & 3rd Floor Corridors**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/20/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22371** BUIDLING ID: **2430**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Bouchet Academy** REVIEW DATE: **11/4/2019**  
ADDRESS: **7355 S. Jeffrey Blvd.** IDPH LICENSE NO: **100-11167**

---

HOMOGENEOUS AREA: **14M**  
MATERIAL DESCRIPTION: **12 x 12 Brown Floor Tile Mastic**  
MATERIAL LOCATION: **2nd & 3rd Floor Corridors**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/04/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22371** BUIDLING ID: **2430**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Brian Barry**  
SCHOOL NAME: **Bouchet Academy** INSPECTION DATE: **10/20/2019**  
ADDRESS: **7355 S. Jeffrey Blvd.** IDPH LICENSE NO: **100-11167**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15**  
MATERIAL DESCRIPTION: **12x12 Gray Speckled Vinyl Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 108**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/20/2019



# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22371** BUIDLING ID: **2430**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Bouchet Academy** REVIEW DATE: **11/4/2019**  
ADDRESS: **7355 S. Jeffrey Blvd.** IDPH LICENSE NO: **100-11167**

---

HOMOGENEOUS AREA: **15**  
MATERIAL DESCRIPTION: **12x12 Gray Speckled Vinyl Floor Tile**  
MATERIAL LOCATION: **Room 108**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/04/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22371** BUILDING ID: **2430**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Brian Barry**  
SCHOOL NAME: **Bouchet Academy** INSPECTION DATE: **10/20/2019**  
ADDRESS: **7355 S. Jeffrey Blvd.** IDPH LICENSE NO: **100-11167**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15M**  
MATERIAL DESCRIPTION: **12 x 12 Gray Speckled Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 108**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/20/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22371** BUIDLING ID: **2430**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Bouchet Academy** REVIEW DATE: **11/4/2019**  
ADDRESS: **7355 S. Jeffrey Blvd.** IDPH LICENSE NO: **100-11167**

---

HOMOGENEOUS AREA: **15M**  
MATERIAL DESCRIPTION: **12 x 12 Gray Speckled Floor Tile Mastic**  
MATERIAL LOCATION: **Room 108**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/04/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22371** BUIDLING ID: **2430**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Brian Barry**  
SCHOOL NAME: **Bouchet Academy** INSPECTION DATE: **10/20/2019**  
ADDRESS: **7355 S. Jeffrey Blvd.** IDPH LICENSE NO: **100-11167**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16**  
MATERIAL DESCRIPTION: **12" x 12" White w/Gray Speckles-Abated**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON: **Physical Damage**  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 001, 002, 004 & 005**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Rms. were abated in 2018**

Inspector's Signature: \_\_\_\_\_

Date: 10/20/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22371** BUIDLING ID: **2430**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Bouchet Academy** REVIEW DATE: **11/4/2019**  
ADDRESS: **7355 S. Jeffrey Blvd.** IDPH LICENSE NO: **100-11167**

---

HOMOGENEOUS AREA: **16**

MATERIAL DESCRIPTION: **12" x 12" White w/Gray Speckles-Abated**

MATERIAL LOCATION: **Rooms 001, 002, 004 & 005**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/04/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22371** BUIDLING ID: **2430**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Brian Barry**  
SCHOOL NAME: **Bouchet Academy** INSPECTION DATE: **10/20/2019**  
ADDRESS: **7355 S. Jeffrey Blvd.** IDPH LICENSE NO: **100-11167**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16M**  
MATERIAL DESCRIPTION: **12" x 12" White w/ Gray Speckles Mastic-Abated**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with potential for significant damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 001, 002, 004 & 005**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY: **0**

DAMAGE UNITS:

COMMENTS: **Rms. were abated in 2018**

Inspector's Signature: \_\_\_\_\_

Date: 10/20/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22371** BUILDING ID: **2430**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Bouchet Academy** REVIEW DATE: **11/4/2019**  
ADDRESS: **7355 S. Jeffrey Blvd.** IDPH LICENSE NO: **100-11167**

---

HOMOGENEOUS AREA: **16M**  
MATERIAL DESCRIPTION: **12" x 12" White w/ Gray Speckles Mastic-Abated**  
MATERIAL LOCATION: **Rooms 001, 002, 004 & 005**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: **0** DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/04/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22371** BUIDLING ID: **2430**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Brian Barry**  
SCHOOL NAME: **Bouchet Academy** INSPECTION DATE: **10/20/2019**  
ADDRESS: **7355 S. Jeffrey Blvd.** IDPH LICENSE NO: **100-11167**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **A**  
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 Damaged or significantly damaged friable thermal system insulating ACM**  
HISTORICAL DAMAGE REASON: **Air Erosion/Flow Deterioration Physical Damage**  
HISTORICAL RESPONSE ACTION: **Repair**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **HIGH**  
MATERIAL LOCATION: **Kitchen, Basement Corridor, Room 100, 200**  
MATERIAL QUANTITY: **150** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/20/2019



# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22371** BUIDLING ID: **2430**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Bouchet Academy** REVIEW DATE: **11/4/2019**  
ADDRESS: **7355 S. Jeffrey Blvd.** IDPH LICENSE NO: **100-11167**

---

HOMOGENEOUS AREA: **A**  
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**  
MATERIAL LOCATION: **Kitchen, Basement Corridor, Room 100, 200**  
MATERIAL QUANTITY: **150** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/04/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22371** BUIDLING ID: **2430**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Brian Barry**  
SCHOOL NAME: **Bouchet Academy** INSPECTION DATE: **10/20/2019**  
ADDRESS: **7355 S. Jeffrey Blvd.** IDPH LICENSE NO: **100-11167**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **B**  
MATERIAL DESCRIPTION: **Magblock ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **10/20/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22371** BUILDING ID: **2430**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Bouchet Academy** REVIEW DATE: **11/4/2019**  
ADDRESS: **7355 S. Jeffrey Blvd.** IDPH LICENSE NO: **100-11167**

---

HOMOGENEOUS AREA: **B**

MATERIAL DESCRIPTION: **Magblock ABATED**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/04/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22371** BUIDLING ID: **2430**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Brian Barry**  
SCHOOL NAME: **Bouchet Academy** INSPECTION DATE: **10/20/2019**  
ADDRESS: **7355 S. Jeffrey Blvd.** IDPH LICENSE NO: **100-11167**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **G**  
MATERIAL DESCRIPTION: **Preform ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **10/20/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22371** BUIDLING ID: **2430**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Bouchet Academy** REVIEW DATE: **11/4/2019**  
ADDRESS: **7355 S. Jeffrey Blvd.** IDPH LICENSE NO: **100-11167**

---

HOMOGENEOUS AREA: **G**

MATERIAL DESCRIPTION: **Preform ABATED**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/04/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22371** BUIDLING ID: **2430**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Brian Barry**  
SCHOOL NAME: **Bouchet Academy** INSPECTION DATE: **10/20/2019**  
ADDRESS: **7355 S. Jeffrey Blvd.** IDPH LICENSE NO: **100-11167**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **H**  
MATERIAL DESCRIPTION: **Boiler Gaskets ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Rom**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **10/20/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22371** BUIDLING ID: **2430**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Bouchet Academy** REVIEW DATE: **11/4/2019**  
ADDRESS: **7355 S. Jeffrey Blvd.** IDPH LICENSE NO: **100-11167**

---

HOMOGENEOUS AREA: **H**

MATERIAL DESCRIPTION: **Boiler Gaskets ABATED**

MATERIAL LOCATION: **Boiler Rom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/04/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
*2019 AHERA REINSPECTION*



# APPENDIX B

## Inspector and Management Planner Licenses

---



**OCCUPATIONAL TRAINING & SUPPLY, INC.**

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900 ♦ [www.otssafety.com](http://www.otssafety.com)

# Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

**Brian Barry**


has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/28/2018

Exam Date: 11/28/2018

Expiration Date: 11/28/2019

Certificate Number: BIR1811283255



---


Kathy DeSalvo, Director

**IDPH** ASBESTOS PROFESSIONAL LICENSE

ID NUMBER	ISSUED	EXPIRES
100 - 11167	4/10/2019	05/15/2020

**BRIAN J BARRY**  
 174 N BRANDON DR  
 GLENDALE HEIGHTS, IL 60139

Environmental Health



**ENDORSEMENTS**

**TC EXPIRES**

INSPECTOR	11/28/2019
PROJECT MANAGER AIR SAMPLING PROFESSIONAL	12/5/2019

**Alteration of this license shall result in legal action**  
 This license issued under authority of the State of Illinois  
 Department of Public Health  
 This license is valid only when accompanied by a valid  
 training course certificate.

2019



**OCCUPATIONAL TRAINING & SUPPLY, INC.**

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900 ♦ [www.otssafety.com](http://www.otssafety.com)

# Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

**John Fenn**

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 3/19/2019

Exam Date: 3/19/2019

Expiration Date: 3/19/2020

Certificate Number: BIR1903191011

A handwritten signature in black ink that reads 'Kathy DeSalvo'.

---

Kathy DeSalvo, Director

2019



**OCCUPATIONAL TRAINING & SUPPLY, INC.**

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900 ♦ [www.otssafety.com](http://www.otssafety.com)

# Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

**John Fenn**


has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 3/19/2019

Exam Date: 3/19/2019

Expiration Date: 3/19/2020

Certificate Number: MPR1903191035



---

Kathy DeSalvo, Director

# COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License



## ASBESTOS PROFESSIONAL LICENSE

### ENDORSEMENTS

### TC EXPIRES

INSPECTOR

3/19/2020

ID NUMBER

ISSUED

EXPIRES

MANAGEMENT PLANNER

3/19/2020

100 - 09786

4/11/2019

05/15/2020

PROJECT MANAGER

3/18/2020

**JOHN H FENN**

2829 N TROY ST

CHICAGO, IL 60618

Environmental Health



AIR SAMPLING PROFESSIONAL

**Alteration of this license shall result in legal action**  
This license issued under authority of the State of Illinois  
Department of Public Health

This license is valid only when accompanied by a valid  
training course certificate.

# APPENDIX C

## Laboratory Accreditations

---

# APPENDIX D

## Laboratory Results

---



# APPENDIX E

## Chain of Custody Forms

---

## Three-Year Reinspection Key to Terms

	<b>CODE</b>	<b>KEY</b>
<b>MATERIAL</b>		
	ACBM	Asbestos Containing Building Materials
<b>MATERIAL CATEGORY</b>		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
<b>MATERIAL UNITS</b>		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
<b>DAMAGE TYPE</b>		
	Loc	Localized
	Dist	Distributed