

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM**

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-2286
SCHOOL NAME: Jefferson School
ADDRESS OF SCHOOL: 1522 W. Fillmore
CITY: Chicago, IL, 60607

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **3/22/2016**

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II *(Please type or print)*

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 10/1/2019 ENROLLMENT 443
IDPH INSPECTOR LICENSE NUMBER: 100-03175
IDPH LICENSED INSPECTOR NAME(Please Print): Marcos Iwankiw
IDPH MP LICENSE NUMBER: 100-19466
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Evan Christian

DESIGNATED PERSON (Please Print): Robert Christlieb PHONE: (773) 553-3197



10/1/2019

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Jefferson School

1522 W. Fillmore
Chicago, IL, 60607

Unit: 22711
Building ID: 4190

IDPH ID Number: 14-016-2990-2286

REPORT DATE:

Tuesday, October 01, 2019

Prepared for:

**Chicago Public Schools
42 West Madison Street
Chicago, IL 60602**

Prepared by:

Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Chicago, IL, 60607

Phone (312) 762-2900

Fax (312) 782-5145

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

May 29, 2019

Mr. Glen E. Garner
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2019 Three-Year Reinspections

Dear Mr. Glen:

Carnow, Conibear and Associates, Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 3, 4 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 23941 Region: 03 IDPH ID:14-016-2990-2286

School: Jefferson School Building ID: 4190

Address: 1522 W. Fillmore
Chicago, IL, 60607

Building Contact: Contact Phone:

Current Building Owners: Chicago Public Schools

Review Date: 06/21/2019

Inspector: Marcos Iwankiw Inspector IDPH License: 100-03175
Management Planner: Evan Christian Management Planner IDPH License: 100-19466

If you have any questions or comments, please contact us at (312) 762-2900

Sincerely,
Carnow, Conibear and Associates

Evan Christian
100-19466

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: May 29, 2019

RE: Jefferson School, Unit 22711
1522 W. Fillmore
Chicago, IL, 60607

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2019 asbestos three year re-inspection has been completed at Jefferson School, following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at Jefferson School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Robert Christlieb, the designated Local Education Authority's Designated Person at (773) 553-3197 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Jefferson School
Address: 1522 W. Fillmore
IDPH ID: 14-016-2990-2286
Contact:

Unit: 23941
Chicago, IL, 60607
Building ID: 4190
Phone:

Region: 03

2. Description of Facility

Original Construction:
Total Square Footage:
Current Occupancy: 443

Additional Construction:
No of Floors:

3. LEA Designated Person

Contact: Robert Christlieb
Address: 42 West Madison Street
Chicago, IL 60602

Phone: (773) 553-3197

4. Managing Environmental Consultant

MEC: Carnow, Conibear and Associates
Contact: Doug McCormick
Address 600 West Van Buren St., Ste 500
Chicago, IL, 60607
Phone: (312) 762-2900

Fax: (312) 782-5145

5. Inspector

Inspector Name: Marcos Iwankiw

Inspector IDPH license # 100-03175

Signature:
Date: 5/29/2019

6. Management Planner

Management Planner Name: Evan Christian

Management Planner IDPH license # 100-19466

Signature:
Date: 06/21/2019

7. Review Date: 06/21/2019

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature:



Date: 10/1/2019

Name: Robert Christlieb

II. EXECUTIVE SUMMARY

Carnow, Conibear and Associates was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Jefferson School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.85 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas(HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 4190:

13	12" x 12" Blue Floor Tile
21	12" x 12" Brown Floor Tile
33	Fire Door Insulation
49	12" x 12" Blue Floor Tile Mastic
60	12"x12" Gray Speckle Floor Tile
61	12"x12" Gray Speckle Floor Tile - Mastic
80	Pink/Tan Sheet Flooring
81	Mastic Associated w/ Pink/Tan Sheet Flooring
82	6" Gray Vinyl Baseboard

- 83 Adhesive on 6" Gray Vinyl Baseboard
- 84 White Sink Undercoat

B. The following new homogenous areas have been identified for Building 4190:

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

11	Roof Material & Flashing - Non-AHERA
13	12" x 12" Blue Floor Tile
16A	12" x 12" Beige (& Gray) Floor Tile Mastic
16C	12" x 12" Gray (w/White & Gray) Floor Tile Mastic
21	12" x 12" Brown Floor Tile
22	12" x 12" Beige Floor Tile w/Gray Streaks
26	12" x 12" Beige Floor Tile w/White & Gray Streaks
27	Carpet Mastic
28	Blue Floor Tile Mastic
33	Fire Door Insulation
34	Ceramic Tile Grout - Floor
43	Tank Insulation
47	Blue Floor Tile
48	Terrazzo Flooring
49	12" x 12" Blue Floor Tile Mastic
53	12"x12" Beige Floor Tile w/Gray & White Streaks
54	Purple Carpet Mastic
60	12"x12" Gray Speckle Floor Tile
61	12"x12" Gray Speckle Floor Tile - Mastic
62	2" Brown Vinyl Baseboard
63	2" Brown Vinyl Baseboard - Adhesive
64	12"x12" Brown Speckled Floor Tile
65	12"x12" Tan Speckled Floor Tile - Mastic
66	Ceramic Baseboard Grout
67	Ceramic Baseboard Grout - Adhesive
70	Dark Blotted Beige VFT
71	Dark Blotted Beige VFT Mastic
72	12" X 12" Tan Texture VFT
73	12" X 12" Tan Texture VFT Mastic
74	Brown Rubber Floor Adhesive
75	2' X 2' Green Carpet Adhesive
76	2' X 2' Blue Carpet Adhesive
77	Lab Counter tops
78	12" X 12" lite Beige VFT
79	12" X 12" lite Beige VFT Mastic
80	Pink/Tan Sheet Flooring
81	Mastic Associated w/ Pink/Tan Sheet Flooring
82	6" Gray Vinyl Baseboard
83	Adhesive on 6" Gray Vinyl Baseboard
84	White Sink Undercoat
9	12" x 12" Brown Floor Tile - Not Observed
A	Air Cell Pipe Insulation

B	Cementitious Joints on Aircell Pipe Insulation
C	Cardboard Pipe Insulation
D	Cementitious Joint Insulation off Cardboard
E	Powder Pipe Insulation
F	Powder Elbows
G	Boiler Gasket
H	Boiler Packing
J	Kiln
K	Aircell Pipe Insulation
L	Cementitious Joint Insulation on Aircell
M	Cardboard Pipe Insulation
N	Cementitious Pipe Joint Insulation off Cardboard
O	Powder Pipe Insulation
P	Powder Elbows

The following areas were deemed to be inaccessible:

14	Red Linoleum Mastic
16A	12" x 12" Beige (& Gray) Floor Tile Mastic
16C	12" x 12" Gray (w/White & Gray) Floor Tile Mastic
49	12" x 12" Blue Floor Tile Mastic
61	12"x12" Gray Speckle Floor Tile - Mastic
67	Ceramic Baseboard Grout - Adhesive
71	Dark Blotted Beige VFT Mastic
73	12" X 12" Tan Texture VFT Mastic
74	Brown Rubber Floor Adhesive
75	2' X 2' Green Carpet Adhesive
76	2' X 2' Blue Carpet Adhesive
79	12" X 12" lite Beige VFT Mastic
81	Mastic Associated w/ Pink/Tan Sheet Flooring
83	Adhesive on 6" Gray Vinyl Baseboard
A	Air Cell Pipe Insulation
B	Cementitious Joints on Aircell Pipe Insulation
C	Cardboard Pipe Insulation
D	Cementitious Joint Insulation off Cardboard
E	Powder Pipe Insulation
F	Powder Elbows
G	Boiler Gasket
H	Boiler Packing
L	Cementitious Joint Insulation on Aircell
M	Cardboard Pipe Insulation
N	Cementitious Pipe Joint Insulation off Cardboard
O	Powder Pipe Insulation
P	Powder Elbows

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Marcos Iwankiw, IDPH License # 100-03175. The Management Plan was updated by Evan Christian, IDPH License # 100-19466. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Jefferson School Building 4190 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. Atimely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Jefferson School Unit 23941 Building ID 4190

Address 1522 W. Fillmore Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
1	9" x 9" Dark Green Floor Tile			Room 314 - 1884 Building	ABATED	MISC		None						
10	Fireproofing - ABATED			Boiler Room	ABATED	MISC								
11	Roof Material & Flashing - Non-AHERA			Roof	ASSUMED	MISC								
12	9" x 9" Dark Green Floor Tile Mastic			Room 314 - 1884 Building	ABATED	MISC								
13	12" x 12" Blue Floor Tile	1,500	SF	Main Office, Principal's Office - 1911 Building and Room 411 - 1884 Building	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
14	Red Linoleum Mastic	800	SF	Engineer's Office - 1884 Building	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
15	9" x 9" Brown Floor Tile Mastic			Room 314 - 1884 Building	ABATED	MISC								Low
16A	12" x 12" Beige (& Gray) Floor Tile Mastic	5,000	SF	Rooms 302 & 308, corridors, and the Stage in the Auditorium	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
16B	12" x 12" Brown Floor Tile Mastic	1,400	SF	Rooms 312 & 113 - 1884 Building	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
16C	12" x 12" Gray (w/White & Gray) Floor Tile Mastic	3,000	SF	Landings by Rooms 310 & 209 & Room 102	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
17	Brown Linoleum			1884 Building - Basement-Engineer's Office, Hall & Storage Room.	NO_ACBM	MISC								
19	9" x 9" Tan Floor Tile Mastic (Under Carpet)			Principal's Office & Throughout Basement	ABATED	MISC		None						Low
2	9" x 9" Tan Floor Tile (Under Carpet)			Principal's Office & Throughout Basement	ABATED	MISC		None						Low
20	9" x 9" Brown Floor Tile			Room 314 - 1884 Building	ABATED	MISC		None						Low
21	12" x 12" Brown Floor Tile	200	SF	Rooms 113 - 1884 Building	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
22	12" x 12" Beige Floor Tile w/Gray Streaks	4,300	SF	Rooms 202, 302, 308, 312, corridors, & Auditorium Stage	ASSUMED	MISC	N	LOC	6		No	ACBM with the potential for damage	5	LOW
23	12" x 12" Beige Floor Tile Mastic			Room 201	ABATED	MISC								
24	Pink Linoleum			Room 310	NO_ACBM	MISC								

Chicago Public Schools

School Jefferson School Unit 23941 Building ID 4190

Address 1522 W. Fillmore Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
25	2' x 4' Lay In Ceiling Panels	2,000	SF	Women's Teacher's Washrooms on the 2nd & 3rd Floors	CHR	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
26	12" x 12" Beige Floor Tile w/White & Gray Streaks			Hall Landings by Room 102	ASSUMED	MISC								
27	Carpet Mastic			Room 208	ASSUMED	MISC		None						Low
28	Blue Floor Tile Mastic			Hall at Exit by Office	ASSUMED	MISC								
29	Interior Window Grout			Interior Windows	NO_ACBM	SURFACE								
3	12" x 12" Tan Floor Tile - ABATED			Basement, 3rd Floor Corridor and Gym - ROOM 212 NOT ABATED	ABATED	MISC								
30	Interior Bricks			Throughout 1884 Building	NO_ACBM	MISC								
31	Interior Brick Mortar			Throughout 1884 Building	NO_ACBM	MISC								
32	Cinder Block Mortar			Throughout 1884 Basement	NO_ACBM	MISC								
33	Fire Door Insulation	40	SF	Throughout 1911 & 1884 Buildings	ASSUMED	TSI	Y	NONE	0		Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
34	Ceramic Tile Grout - Floor	1,000	SF	Throughout Boy's & Girl's Washrooms - 1911 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
35	Baseboards			Room 113 of the 1884 Building & Room 308 of the 1911 Building	NO_ACBM	MISC								
36	Baseboard Mastic			Room 113 of the 1884 Building & Room 308 of the 1911 Building	NO_ACBM	MISC								
37	Exterior Brick			Exterior of the 1911 Building	NO_ACBM	MISC								
38	Exterior Brick Mortar			Exterior of the 1911 Building	NO_ACBM	MISC								
39	Exterior Window Grout			Exterior Windows of the 1911 Building	NO_ACBM	MISC								
4	Red Linoleum	800	SF	Engineer's Office - 1884 Building	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
40	Exterior Brick - NON AHERA			Exterior of the 1884 Building	NO_ACBM	MISC								
41	Exterior Mortar - NON AHERA			Exterior of the 1814	NO_ACBM	MISC								

Chicago Public Schools

School Jefferson School Unit 23941 Building ID 4190

Address 1522 W. Fillmore Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Building										
42	Exterior Window Grout - NON AHERA			Exterior of the 1884 Building	NO_ACBM	MISC								
43	Tank Insulation	1,000	SF	Boiler Room	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
44	Exterior Brick Used to Block Windows - NON AHERA			Exterior of the 1884 Building	NO_ACBM	MISC								
45	Brick Mortar Used to Block Windows			Exterior of the 1884 Building	NO_ACBM	MISC								
46	Spray-on Insulation			Electric Room on the 1st Floor of the 1911 Building, Boiler Room Ceiling by Back Door- 1911 Bldg.	NO_ACBM	TSI								
47	Blue Floor Tile			Hall at Exit by Office	ASSUMED	MISC								
48	Terrazzo Flooring	1,000	SF	Throughout the 1911 Building Stairs	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
49	12" x 12" Blue Floor Tile Mastic	2,700	SF	Main Office & Principal's Office of the 1911 Building & Room 411 of the 1884 Building	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
53	12"x12" Beige Floor Tile w/Gray & White Streaks			The Stair Landings of the 1884 Building & Room 102 of the 1911 Building	ASSUMED	MISC								
54	Purple Carpet Mastic			Room 206/208	ASSUMED	MISC		None						Low
55	Linoleum Flooring			Gymnasium - 1911 Building	ABATED	MISC		None						Low
56	Linoleum Flooring Mastic			Gymnasium	ABATED	MISC		None						
57	Blue Carpet Mastic			Main Office, Principal's Office, Room 202 - 1911 Building	NO_ACBM	MISC		None						Low
58	4" Brown Vinyl Baseboard			1911 Building Gym/Assembly Hall	NO_ACBM	MISC								Low
59	4" Brown Vinyl Baseboard - Adhesive			1911 Building - Gym/Assembly Hall	NO_ACBM	MISC		None						Low
5A	9" x 9" Tan Floor Tile (Under Carpet)			Room 202 - 1911 Building	ABATED	MISC								Low
5B	9" x 9" Tan Floor Tile Mastic (Under			Room 202 - 1911	ABATED	MISC								Low

Chicago Public Schools

School Jefferson School Unit 23941 Building ID 4190

Address 1522 W. Fillmore Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
	Carpet)			Building										
6	Gray Linoleum			Room 210	NO_ACBM	MISC								
60	12"x12" Gray Speckle Floor Tile	840	SF	1911 Building - Old Lunchroom, Room 102	ASSUMED	MISC	N	LOC	12		Yes	ACBM with the potential for damage	5	LOW
61	12"x12" Gray Speckle Floor Tile - Mastic	840	SF	1191 Building - Old Lunchroom/Room 102	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
62	2" Brown Vinyl Baseboard	100	LF	1911 Building - Old Lunchroom/Room 102	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
63	2" Brown Vinyl Baseboard - Adhesive	100	LF	1911 Building - Old Lunchroom/Room 102	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
64	12"x12" Brown Speckled Floor Tile			1884 Building - Room 103	ASSUMED	MISC		None						
65	12"x12" Tan Speckled Floor Tile - Mastic			1884 Building - Room 103	ASSUMED	MISC								
66	Ceramic Baseboard Grout	120	LF	1911 Building - 2nd and 3rd Floor Girls' and Teacher's Washrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
67	Ceramic Baseboard Grout - Adhesive	120	LF	1911 Building - 2nd and 3rd Floor Girls' and Teacher's Washrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
68	12"x12" Patched Floor Tile			1884 Building - Room 314	ABATED	MISC		None						Low
69	12"x12" Patched Floor Tile - Mastic			1884 Building - Room 314	ABATED	MISC		None						Low
7	Plaster			Throughout the 1911 Building	NO_ACBM	MISC								
70	Dark Blotted Beige VFT	1,000	SF	Lunchroom, Exit 3 entrance	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
71	Dark Blotted Beige VFT Mastic	1,000	SF	Lunchroom, Exit 3 entrance	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
72	12" X 12" Tan Texture VFT	100	SF	West Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
73	12" X 12" Tan Texture VFT Mastic	100	SF	West Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
74	Brown Rubber Floor Adhesive	1,000	SF	Stairwells	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
75	2' X 2' Green Carpet Adhesive	1,000	SF	Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Jefferson School Unit 23941 Building ID 4190

Address 1522 W. Fillmore Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
76	2' X 2' Blue Carpet Adhesive	1,800	SF	Room 206, 208	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
77	Lab Counter tops	3	EA	Room 314, 214, 114	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
78	12" X 12" lite Beige VFT	16,000	SF	Classroom 104 and Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
79	12" X 12" lite Beige VFT Mastic	1,600	SF	Classroom 104 and Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
8	Plaster			Throughout the 1884 Building	NO_ACBM	SURFACE								
80	Pink/Tan Sheet Flooring	2,400	SF	Rooms 214, 312, 313, 314, 413, 414	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
81	Mastic Associated w/ Pink/Tan Sheet Flooring	2,400	SF	Rooms 214, 312, 313, 314, 413, 414	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
82	6" Gray Vinyl Baseboard	240	LF	Rooms 214, 312, 313, 314, 413, 414	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
83	Adhesive on 6" Gray Vinyl Baseboard	240	LF	Rooms 214, 312, 313, 314, 413, 414	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
84	White Sink Undercoat	1	EA	Room 113	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
9	12" x 12" Brown Floor Tile - Not Observed			Teacher's Washroom by Room 309	ASSUMED	MISC								
A	Air Cell Pipe Insulation	100	SF	Pipe Chases and Within Walls	ASSUMED	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
B	Cementitious Joints on Aircell Pipe Insulation	100	SF	Pipe Chases and Within Walls	ASSUMED	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
C	Cardboard Pipe Insulation	100	SF	Pipe Chases and Within Walls	ASSUMED	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
D	Cementitious Joint Insulation off Cardboard	100	SF	Pipe Chases and Within Walls	ASSUMED	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
E	Powder Pipe Insulation	100	SF	Pipe Chases and Within Walls	ASSUMED	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
F	Powder Elbows	100	SF	Pipe Chases and Within Walls	ASSUMED	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
G	Boiler Gasket	10	LF	Boiler Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
H	Boiler Packing	100	SF	Boiler Room	ASSUMED	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable		LOW

Chicago Public Schools

School Jefferson School **Unit** 23941 **Building ID** 4190

Address 1522 W. Fillmore **Region** 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
												suspect ACBM		
I	Tank Insulation - Abated 1994			Boiler Room	ABATED	MISC								
J	Kiln				ASSUMED	MISC		None						
K	Aircell Pipe Insulation	100	SF	Pipe Chases and Within Walls	ASSUMED	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
L	Cementitious Joint Insulation on Aircell	100	SF	Pipe Chases and Within Walls	ASSUMED	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
M	Cardboard Pipe Insulation	100	LF	Pipe Chases and Within Walls	ASSUMED	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
N	Cementitious Pipe Joint Insulation off Cardboard	100	SF	Pipe Chases and Within Walls	ASSUMED	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
O	Powder Pipe Insulation	100	LF	Pipe Chases and Within Walls	ASSUMED	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
P	Powder Elbows	100	SF	Pipe Chases and Within Walls	ASSUMED	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW

Chicago Public Schools

School Jefferson School **Unit** 23941 **Building ID** 4190
Address 1522 W. Fillmore **Region** 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

Reinspection Date <u>5/29/2019</u>
Inspector Name <u>Marcos Iwankiw</u>
<u>100-03175</u> <u>5/15/2020</u>
Inspector's IDPH License Number / Expiration Date

Inspector's Comments

HA Number:	Inspector Comments:
1	Abated
10	Abated
11	
12	Abated
13	No Access to Principal's Office, not in Room 411
14	
15	Abated
16A	
16B	
16C	
17	
19	Not Observed - Abated
2	Not Observed - Abated
20	Abated
21	
22	Not Observed on Auditorium Stage
23	Abated
24	Not Observed
25	
26	Not Observed
27	Not Observed
28	Not Observed
29	

Chicago Public Schools

School Jefferson School **Unit** 23941 **Building ID** 4190
Address 1522 W. Fillmore **Region** 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
3	Abated, Room 212 is now wood
30	
31	
32	
33	
34	
35	
36	
37	
38	
39	
4	
40	
41	
42	
43	
44	
45	
46	
47	Not Observed
48	
49	No Access to Principal's Office
53	Not Observed
54	Not Observed
55	Abated
56	Abated
57	
58	
59	

Chicago Public Schools

School Jefferson School **Unit** 23941 **Building ID** 4190
Address 1522 W. Fillmore **Region** 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
5A	Abated
5B	Abated
6	
60	
61	
62	
63	
64	Not Observed
65	Not Observed
66	
67	
68	Abated
69	Abated
7	
70	
71	
72	
73	
74	
75	
76	
77	
78	
79	
8	
80	Not Observed in Room 312, 314
81	
82	
83	

Chicago Public Schools

School Jefferson School **Unit** 23941 **Building ID** 4190
Address 1522 W. Fillmore **Region** 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
84	
9	Not Observed
A	
B	
C	
D	
E	
F	
G	
H	
I	Abated
J	Not Observed
K	
L	
M	
N	
O	
P	

Table II

Management Planner's Review

Chicago Public Schools

School Jefferson School

Unit 23941

Building ID 4190

Address 1522 W. Fillmore

Chicago, IL, 60607

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, Il, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
1	9" x 9" Dark Green Floor Tile			Room 314 - 1884 Building	Abated	MISC					
10	Fireproofing - ABATED			Boiler Room	Abated	MISC					
11	Roof Material & Flashing - Non-AHERA			Roof	Assumed	MISC					
12	9" x 9" Dark Green Floor Tile Mastic			Room 314 - 1884 Building	Abated	MISC					
13	12" x 12" Blue Floor Tile	1,500	SF	Main Office, Principal's Office - 1911 Building and Room 411 - 1884 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
14	Red Linoleum Mastic	800	SF	Engineer's Office - 1884 Building	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
15	9" x 9" Brown Floor Tile Mastic			Room 314 - 1884 Building	Abated	MISC					
16A	12" x 12" Beige (& Gray) Floor Tile Mastic	5,000	SF	Rooms 302 & 308, corridors, and the Stage in the Auditorium	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
16B	12" x 12" Brown Floor Tile Mastic	1,400	SF	Rooms 312 & 113 - 1884 Building	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
16C	12" x 12" Gray (w/White & Gray) Floor Tile Mastic	3,000	SF	Landings by Rooms 310 & 209 & Room 102	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
17	Brown Linoleum			1884 Building - Basement- Engineer's Office, Hall & Storage Room.	No ACBM	MISC					
19	9" x 9" Tan Floor Tile Mastic (Under Carpet)			Principal's Office & Throughout Basement	Abated	MISC					
2	9" x 9" Tan Floor Tile (Under Carpet)			Principal's Office & Throughout Basement	Abated	MISC					
20	9" x 9" Brown Floor Tile			Room 314 - 1884 Building	Abated	MISC					
21	12" x 12" Brown Floor Tile	200	SF	Rooms 113 - 1884 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
22	12" x 12" Beige Floor Tile w/Gray Streaks	4,300	SF	Rooms 202, 302, 308, 312, corridors, & Auditorium Stage	Assumed	MISC	No	6	SF	6 ACBM with the potential for damage	Follow O&M Plan
23	12" x 12" Beige Floor Tile Mastic			Room 201	Abated	MISC					
24	Pink Linoleum			Room 310	No ACBM	MISC					
25	2' x 4' Lay In Ceiling Panels	2,000	SF	Women's Teacher's Washrooms on the 2nd & 3rd Floors	Chrysotile	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
26	12" x 12" Beige Floor Tile w/White & Gray Streaks			Hall Landings by Room 102	Assumed	MISC					
27	Carpet Mastic			Room 208	Assumed	MISC					
28	Blue Floor Tile Mastic			Hall at Exit by Office	Assumed	MISC					
29	Interior Window Grout			Interior Windows	No ACBM	SURFACE					
3	12" x 12" Tan Floor Tile - ABATED			Basement, 3rd Floor Corridor and Gym - ROOM 212 NOT ABATED	Abated	MISC					

Chicago Public Schools

School Jefferson School

Unit 23941

Building ID 4190

Address 1522 W. Fillmore

Chicago, IL, 60607

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, Il, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
30	Interior Bricks			Throughout 1884 Building	No ACBM	MISC					
31	Interior Brick Mortar			Throughout 1884 Building	No ACBM	MISC					
32	Cinder Block Mortar			Throughout 1884 Basement	No ACBM	MISC					
33	Fire Door Insulation	40	SF	Throughout 1911 & 1884 Buildings	Assumed	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
34	Ceramic Tile Grout - Floor	1,000	SF	Throughout Boy's & Girl's Washrooms - 1911 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
35	Baseboards			Room 113 of the 1884 Building & Room 308 of the1911 Building	No ACBM	MISC					
36	Baseboard Mastic			Room 113 of the 1884 Building & Room 308 of the1911 Building	No ACBM	MISC					
37	Exterior Brick			Exterior of the 1911 Building	No ACBM	MISC					
38	Exterior Brick Mortar			Exterior of the 1911 Building	No ACBM	MISC					
39	Exterior Window Grout			Exterior Windows of the 1911 Building	No ACBM	MISC					
4	Red Linoleum	800	SF	Engineer's Office - 1884 Building	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
40	Exterior Brick - NON AHERA			Exterior of the 1884 Building	No ACBM	MISC					
41	Exterior Mortar - NON AHERA			Exterior of the 1814 Building	No ACBM	MISC					
42	Exterior Window Grout - NON AHERA			Exterior of the 1884 Building	No ACBM	MISC					
43	Tank Insulation	1,000	SF	Boiler Room	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
44	Exterior Brick Used to Block Windows - NON AHERA			Exterior of the 1884 Building	No ACBM	MISC					
45	Brick Mortar Used to Block Windows			Exterior of the 1884 Building	No ACBM	MISC					
46	Spray-on Insulation			Electric Room on the 1st Floor of the 1911 Building, Boiler Room Ceiling by Back Door- 1911 Bldg.	No ACBM	TSI					
47	Blue Floor Tile			Hall at Exit by Office	Assumed	MISC					
48	Terrazzo Flooring	1,000	SF	Throughout the 1911 Building Stairs	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
49	12" x 12" Blue Floor Tile Mastic	2,700	SF	Main Office & Principal's Office of the 1911 Building & Room 411 of the 1884 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
53	12"x12" Beige Floor Tile w/Gray & White Streaks			The Stair Landings of the 1884 Building & Room 102 of the 1911 Building	Assumed	MISC					
54	Purple Carpet Mastic			Room 206/208	Assumed	MISC					

Chicago Public Schools

School Jefferson School

Unit 23941

Building ID 4190

Address 1522 W. Fillmore

Chicago, IL, 60607

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, Il, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
55	Linoleum Flooring			Gymnasium - 1911 Building	Abated	MISC					
56	Linoleum Flooring Mastic			Gymnasium	Abated	MISC					
57	Blue Carpet Masric			Main Office, Principal's Office, Room 202 - 1911 Building	No ACBM	MISC					
58	4" Brown Vinyl Baseboard			1911 Building Gym/Assembly Hall	No ACBM	MISC					
59	4" Brown Vinyl Baseboard - Adhesive			1911 Building - Gym/Assembly Hall	No ACBM	MISC					
5A	9" x 9" Tan Floor Tile (Under Carpet)			Room 202 - 1911 Building	Abated	MISC					
5B	9" x 9" Tan Floor Tile Mastic (Under Carpet)			Room 202 - 1911 Building	Abated	MISC					
6	Gray Linoleum			Room 210	No ACBM	MISC					
60	12"x12" Gray Speckle Floor Tile	840	SF	1911 Building - Old Lunchroom, Room 102	Assumed	MISC	No	12	SF	6 ACBM with the potential for damage	Follow O&M Plan
61	12"x12" Gray Speckle Floor Tile - Mastic	840	SF	1191 Building - Old Lunchroom/Room 102	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
62	2" Brown Vinyl Baseboard	100	LF	1911 Building - Old Lunchroom/Room 102	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
63	2" Brown Vinyl Baseboard - Adhesive	100	LF	1911 Building - Old Lunchroom/Room 102	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
64	12"x12" Brown Speckled Floor Tile			1884 Building - Room 103	Assumed	MISC					
65	12"x12" Tan Speckled Floor Tile - Mastic			1884 Building - Room 103	Assumed	MISC					
66	Ceramic Baseboard Grout	120	LF	1911 Building - 2nd and 3rd Floor Girls' and Teacher's Washrooms	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
67	Ceramic Baseboard Grout - Adhesive	120	LF	1911 Building - 2nd and 3rd Floor Girls' and Teacher's Washrooms	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
68	12"x12" Patched Floor Tile			1884 Building - Room 314	Abated	MISC					
69	12"x12" Patched Floor Tile - Mastic			1884 Building - Room 314	Abated	MISC					
7	Plaster			Throughout the 1911 Building	No ACBM	MISC					
70	Dark Blotted Beige VFT	1,000	SF	Lunchroom, Exit 3 entrance	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
71	Dark Blotted Beige VFT Mastic	1,000	SF	Lunchroom, Exit 3 entrance	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
72	12" X 12" Tan Texture VFT	100	SF	West Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
73	12" X 12" Tan Texture VFT Mastic	100	SF	West Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
74	Brown Rubber Floor Adhesive	1,000	SF	Stairwells	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
75	2' X 2' Green Carpet Adhesive	1,000	SF	Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
76	2' X 2' Blue Carpet Adhesive	1,800	SF	Room 206, 208	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
77	Lab Counter tops	3	EA	Room 314, 214, 114	Assumed	MISC	No	0	EA	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Jefferson School

Unit 23941

Building ID 4190

Address 1522 W. Fillmore

Chicago, IL, 60607

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, Il, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
78	12" X 12" lite Beige VFT	16,000	SF	Classroom 104 and Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
79	12" X 12" lite Beige VFT Mastic	1,600	SF	Classroom 104 and Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
8	Plaster			Throughout the 1884 Building	No ACBM	SURFACE					
80	Pink/Tan Sheet Flooring	2,400	SF	Rooms 214, 312, 313, 314, 413, 414	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
81	Mastic Associated w/ Pink/Tan Sheet Flooring	2,400	SF	Rooms 214, 312, 313, 314, 413, 414	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
82	6" Gray Vinyl Baseboard	240	LF	Rooms 214, 312, 313, 314, 413, 414	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
83	Adhesive on 6" Gray Vinyl Baseboard	240	LF	Rooms 214, 312, 313, 314, 413, 414	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
84	White Sink Undercoat	1	EA	Room 113	Assumed	MISC	No	0	EA	6 ACBM with the potential for damage	Follow O&M Plan
9	12" x 12" Brown Floor Tile - Not Observed			Teacher's Washroom by Room 309	Assumed	MISC					
A	Air Cell Pipe Insulation	100	SF	Pipe Chases and Within Walls	Assumed	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
B	Cementitious Joints on Aircell Pipe Insulation	100	SF	Pipe Chases and Within Walls	Assumed	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
C	Cardboard Pipe Insulation	100	SF	Pipe Chases and Within Walls	Assumed	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
D	Cementitious Joint Insulation off Cardboard	100	SF	Pipe Chases and Within Walls	Assumed	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
E	Powder Pipe Insulation	100	SF	Pipe Chases and Within Walls	Assumed	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
F	Powder Elbows	100	SF	Pipe Chases and Within Walls	Assumed	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
G	Boiler Gasket	10	LF	Boiler Room	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
H	Boiler Packing	100	SF	Boiler Room	Assumed	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
I	Tank Insulation - Abated 1994			Boiler Room	Abated	MISC					
J	Kiln				Assumed	MISC					
K	Aircell Pipe Insulation	100	SF	Pipe Chases and Within Walls	Assumed	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
L	Cementitious Joint Insulation on Aircell	100	SF	Pipe Chases and Within Walls	Assumed	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
M	Cardboard Pipe Insulation	100	LF	Pipe Chases and Within Walls	Assumed	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
N	Cementitious Pipe Joint Insulation off Cardboard	100	SF	Pipe Chases and Within Walls	Assumed	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan

Chicago Public Schools

School Jefferson School

Unit 23941

Building ID 4190

Address 1522 W. Fillmore

Chicago, IL, 60607

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
O	Powder Pipe Insulation	100	LF	Pipe Chases and Within Walls	Assumed	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
P	Powder Elbows	100	SF	Pipe Chases and Within Walls	Assumed	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan

HA Number	Management Comments
-----------	---------------------

Chicago Public Schools

School Jefferson School

Unit 23941

Building ID 4190

Address 1522 W. Fillmore

Chicago, IL, 60607

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, Il, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

Review Date	06/21/2019
Manager Planner Name	Evan Christian
100-19466	5/15/2020
Manager IDPH License No/Expiration	

HA Number	Management Comments
1	
10	
11	
12	
13	
14	
15	
16A	
16B	
16C	
17	
19	
2	
20	
21	
22	
23	
24	
25	
26	
27	
28	
29	
3	
30	
31	

Chicago Public Schools

School Jefferson School

Unit 23941

Building ID 4190

Address 1522 W. Fillmore

Chicago, IL, 60607

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
32	
33	
34	
35	
36	
37	
38	
39	
4	
40	
41	
42	
43	
44	
45	
46	
47	
48	
49	
53	
54	
55	
56	
57	
58	
59	

Chicago Public Schools

School Jefferson School

Unit 23941

Building ID 4190

Address 1522 W. Fillmore

Chicago, IL, 60607

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, Il, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
5A	
5B	
6	
60	
61	
62	
63	
64	
65	
66	
67	
68	
69	
7	
70	
71	
72	
73	
74	
75	
76	
77	
78	
79	
8	
80	

Chicago Public Schools

School Jefferson School

Unit 23941

Building ID 4190

Address 1522 W. Fillmore

Chicago, IL, 60607

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
81	
82	
83	
84	
9	
A	
B	
C	
D	
E	
F	
G	
H	
I	
J	
K	
L	
M	
N	
O	
P	

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	5/29/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	1		
MATERIAL DESCRIPTION:	9" x 9" Dark Green Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Abated	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 314 - 1884 Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Abated

Inspector's Signature: _____ Date: 05/29/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	6/21/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **1**

MATERIAL DESCRIPTION: **9" x 9" Dark Green Floor Tile**

MATERIAL LOCATION: **Room 314 - 1884 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **06/21/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	5/29/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	10	
MATERIAL DESCRIPTION:	Fireproofing - ABATED	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Abated	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Boiler Room

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Abated

Inspector's Signature: _____ Date: 05/29/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	6/21/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **10**

MATERIAL DESCRIPTION: **Fireproofing - ABATED**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **06/21/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	5/29/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	11	
MATERIAL DESCRIPTION:	Roof Material & Flashing - Non-AHERA	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Roof

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 05/29/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	6/21/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **11**

MATERIAL DESCRIPTION: **Roof Material & Flashing - Non-AHERA**

MATERIAL LOCATION: **Roof**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **06/21/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	5/29/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	12	
MATERIAL DESCRIPTION:	9" x 9" Dark Green Floor Tile Mastic	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Abated	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 314 - 1884 Building

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Abated

Inspector's Signature: _____ Date: 05/29/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	6/21/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **12**

MATERIAL DESCRIPTION: **9" x 9" Dark Green Floor Tile Mastic**

MATERIAL LOCATION: **Room 314 - 1884 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **06/21/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	5/29/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	13		
MATERIAL DESCRIPTION:	12" x 12" Blue Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Main Office, Principal's Office - 1911 Building and Room 411 - 1884 Building		
MATERIAL QUANTITY:	1500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

COMMENTS: No Access to Principal's Office, not in Room 411

Inspector's Signature: _____ Date: 05/29/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	6/21/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA:	13		
MATERIAL DESCRIPTION:	12" x 12" Blue Floor Tile		
MATERIAL LOCATION:	Main Office, Principal's Office - 1911 Building and Room 411 - 1884 Building		
MATERIAL QUANTITY:	1500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/21/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	5/29/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	14		
MATERIAL DESCRIPTION:	Red Linoleum Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Engineer's Office - 1884 Building		
MATERIAL QUANTITY:	800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/29/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	6/21/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **14**

MATERIAL DESCRIPTION: **Red Linoleum Mastic**

MATERIAL LOCATION: **Engineer's Office - 1884 Building**

MATERIAL QUANTITY:	800	MATERIAL UNITS:	SF
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/21/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	5/29/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	15	
MATERIAL DESCRIPTION:	9" x 9" Brown Floor Tile Mastic	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Abated	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: Low

MATERIAL LOCATION: Room 314 - 1884 Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Abated

Inspector's Signature: _____ Date: 05/29/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	6/21/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **15**

MATERIAL DESCRIPTION: **9" x 9" Brown Floor Tile Mastic**

MATERIAL LOCATION: **Room 314 - 1884 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **06/21/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	5/29/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	16A		
MATERIAL DESCRIPTION:	12" x 12" Beige (& Gray) Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 302 & 308, corridors, and the Stage in the Auditorium		
MATERIAL QUANTITY:	5000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/29/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	6/21/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA:	16A		
MATERIAL DESCRIPTION:	12" x 12" Beige (& Gray) Floor Tile Mastic		
MATERIAL LOCATION:	Rooms 302 & 308, corridors, and the Stage in the Auditorium		
MATERIAL QUANTITY:	5000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/21/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	5/29/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	16B		
MATERIAL DESCRIPTION:	12" x 12" Brown Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 312 & 113 - 1884 Building		
MATERIAL QUANTITY:	1400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/29/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	6/21/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA:	16B				
MATERIAL DESCRIPTION:	12" x 12" Brown Floor Tile Mastic				
MATERIAL LOCATION:	Rooms 312 & 113 - 1884 Building				
MATERIAL QUANTITY:	1400	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/21/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	5/29/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	16C		
MATERIAL DESCRIPTION:	12" x 12" Gray (w/White & Gray) Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Landings by Rooms 310 & 209 & Room 102		
MATERIAL QUANTITY:	3000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/29/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	6/21/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA:	16C		
MATERIAL DESCRIPTION:	12" x 12" Gray (w/White & Gray) Floor Tile Mastic		
MATERIAL LOCATION:	Landings by Rooms 310 & 209 & Room 102		
MATERIAL QUANTITY:	3000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/21/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	5/29/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	17	
MATERIAL DESCRIPTION:	Brown Linoleum	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1884 Building - Basement- Engineer's Office, Hall & Storage Room.

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 05/29/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	6/21/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **17**

MATERIAL DESCRIPTION: **Brown Linoleum**

MATERIAL LOCATION: **1884 Building - Basement- Engineer's Office, Hall & Storage Room.**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **06/21/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	5/29/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	19	
MATERIAL DESCRIPTION:	9" x 9" Tan Floor Tile Mastic (Under Carpet)	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Abated	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: Low

MATERIAL LOCATION: Principal's Office & Throughout Basement

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Not Observed - Abated

Inspector's Signature: _____ Date: 05/29/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	6/21/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **19**

MATERIAL DESCRIPTION: **9" x 9" Tan Floor Tile Mastic (Under Carpet)**

MATERIAL LOCATION: **Principal's Office & Throughout Basement**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **06/21/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	5/29/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	2	
MATERIAL DESCRIPTION:	9" x 9" Tan Floor Tile (Under Carpet)	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Abated	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: Low

MATERIAL LOCATION: Principal's Office & Throughout Basement

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Not Observed - Abated

Inspector's Signature: _____ Date: 05/29/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	6/21/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **2**

MATERIAL DESCRIPTION: **9" x 9" Tan Floor Tile (Under Carpet)**

MATERIAL LOCATION: **Principal's Office & Throughout Basement**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **06/21/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	5/29/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	20	
MATERIAL DESCRIPTION:	9" x 9" Brown Floor Tile	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Abated	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: Low

MATERIAL LOCATION: Room 314 - 1884 Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Abated

Inspector's Signature: _____ Date: 05/29/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	6/21/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **20**

MATERIAL DESCRIPTION: **9" x 9" Brown Floor Tile**

MATERIAL LOCATION: **Room 314 - 1884 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **06/21/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	5/29/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	21		
MATERIAL DESCRIPTION:	12" x 12" Brown Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 113 - 1884 Building		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/29/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	6/21/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **21**

MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile**

MATERIAL LOCATION: **Rooms 113 - 1884 Building**

MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/21/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	5/29/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	22		
MATERIAL DESCRIPTION:	12" x 12" Beige Floor Tile w/Gray Streaks		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:	Physical Damage		
DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 202, 302, 308, 312, corridors, & Auditorium Stage		
MATERIAL QUANTITY:	4300	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	6	DAMAGE UNITS:	SF
COMMENTS:	Not Observed on Auditorium Stage		

Inspector's Signature: _____ Date: 05/29/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	6/21/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **22**

MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile w/Gray Streaks**

MATERIAL LOCATION: **Rooms 202, 302, 308, 312, corridors, & Auditorium Stage**

MATERIAL QUANTITY:	4300	MATERIAL UNITS:	SF
--------------------	-------------	-----------------	-----------

DAMAGE QUANTITY:	6	DAMAGE UNITS:	SF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/21/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23941** BUILDING ID: **4190**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Jefferson School** INSPECTION DATE: **5/29/2019**
ADDRESS: **1522 W. Fillmore** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23**
MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 201**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Abated**

Inspector's Signature: _____ Date: **05/29/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	6/21/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **23**

MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile Mastic**

MATERIAL LOCATION: **Room 201**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **06/21/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	5/29/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	24	
MATERIAL DESCRIPTION:	Pink Linoleum	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 310

MATERIAL QUANTITY:

DAMAGE QUANTITY:

COMMENTS: Not Observed

MATERIAL UNITS:

DAMAGE UNITS:

Inspector's Signature: _____ Date: 05/29/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	6/21/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **24**

MATERIAL DESCRIPTION: **Pink Linoleum**

MATERIAL LOCATION: **Room 310**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **06/21/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	5/29/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	25		
MATERIAL DESCRIPTION:	2' x 4' Lay In Ceiling Panels		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Women's Teacher's Washrooms on the 2nd & 3rd Floors		
MATERIAL QUANTITY:	2000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/29/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	6/21/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **25**

MATERIAL DESCRIPTION: **2' x 4' Lay In Ceiling Panels**

MATERIAL LOCATION: **Women's Teacher's Washrooms on the 2nd & 3rd Floors**

MATERIAL QUANTITY:	2000	MATERIAL UNITS:	SF
--------------------	-------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/21/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	5/29/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	26	
MATERIAL DESCRIPTION:	12" x 12" Beige Floor Tile w/White & Gray Streaks	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Hall Landings by Room 102

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Not Observed

Inspector's Signature: _____ Date: 05/29/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	6/21/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **26**

MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile w/White & Gray Streaks**

MATERIAL LOCATION: **Hall Landings by Room 102**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **06/21/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	5/29/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	27	
MATERIAL DESCRIPTION:	Carpet Mastic	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: Low

MATERIAL LOCATION: Room 208

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Not Observed

Inspector's Signature: _____ Date: 05/29/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	6/21/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **27**

MATERIAL DESCRIPTION: **Carpet Mastic**

MATERIAL LOCATION: **Room 208**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **06/21/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	5/29/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	28	
MATERIAL DESCRIPTION:	Blue Floor Tile Mastic	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Hall at Exit by Office

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Not Observed

Inspector's Signature: _____ Date: 05/29/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	6/21/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **28**

MATERIAL DESCRIPTION: **Blue Floor Tile Mastic**

MATERIAL LOCATION: **Hall at Exit by Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **06/21/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	5/29/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	29	
MATERIAL DESCRIPTION:	Interior Window Grout	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Interior Windows

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 05/29/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	6/21/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **29**

MATERIAL DESCRIPTION: **Interior Window Grout**

MATERIAL LOCATION: **Interior Windows**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **06/21/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	5/29/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	3	
MATERIAL DESCRIPTION:	12" x 12" Tan Floor Tile - ABATED	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Abated	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Basement, 3rd Floor Corridor and Gym - ROOM 212 NOT ABATED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Abated, Room 212 is now wood

Inspector's Signature: _____ Date: 05/29/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	6/21/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **3**

MATERIAL DESCRIPTION: **12" x 12" Tan Floor Tile - ABATED**

MATERIAL LOCATION: **Basement, 3rd Floor Corridor and Gym - ROOM 212 NOT ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **06/21/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	5/29/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	30	
MATERIAL DESCRIPTION:	Interior Bricks	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throughout 1884 Building

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 05/29/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	6/21/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **30**

MATERIAL DESCRIPTION: **Interior Bricks**

MATERIAL LOCATION: **Throughout 1884 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **06/21/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	5/29/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	31	
MATERIAL DESCRIPTION:	Interior Brick Mortar	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throughout 1884 Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 05/29/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	6/21/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **31**

MATERIAL DESCRIPTION: **Interior Brick Mortar**

MATERIAL LOCATION: **Throughout 1884 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **06/21/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	5/29/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	32	
MATERIAL DESCRIPTION:	Cinder Block Mortar	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throughout 1884 Basement

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 05/29/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	6/21/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **32**

MATERIAL DESCRIPTION: **Cinder Block Mortar**

MATERIAL LOCATION: **Throughout 1884 Basement**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **06/21/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	5/29/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	33		
MATERIAL DESCRIPTION:	Fire Door Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout 1911 & 1884 Buildings		
MATERIAL QUANTITY:	40	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/29/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	6/21/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **33**

MATERIAL DESCRIPTION: **Fire Door Insulation**

MATERIAL LOCATION: **Throughout 1911 & 1884 Buildings**

MATERIAL QUANTITY: **40**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/21/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	5/29/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	34		
MATERIAL DESCRIPTION:	Ceramic Tile Grout - Floor		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout Boy's & Girl's Washrooms - 1911 Building		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/29/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	6/21/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA:	34		
MATERIAL DESCRIPTION:	Ceramic Tile Grout - Floor		
MATERIAL LOCATION:	Throughout Boy's & Girl's Washrooms - 1911 Building		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/21/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	5/29/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	35	
MATERIAL DESCRIPTION:	Baseboards	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 113 of the 1884 Building & Room 308 of the 1911 Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 05/29/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	6/21/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **35**

MATERIAL DESCRIPTION: **Baseboards**

MATERIAL LOCATION: **Room 113 of the 1884 Building & Room 308 of the 1911 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **06/21/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	5/29/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	36	
MATERIAL DESCRIPTION:	Baseboard Mastic	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 113 of the 1884 Building & Room 308 of the 1911 Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 05/29/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	6/21/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **36**

MATERIAL DESCRIPTION: **Baseboard Mastic**

MATERIAL LOCATION: **Room 113 of the 1884 Building & Room 308 of the 1911 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **06/21/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	5/29/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	37	
MATERIAL DESCRIPTION:	Exterior Brick	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Exterior of the 1911 Building

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 05/29/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	6/21/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **37**

MATERIAL DESCRIPTION: **Exterior Brick**

MATERIAL LOCATION: **Exterior of the 1911 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **06/21/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	5/29/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	38	
MATERIAL DESCRIPTION:	Exterior Brick Mortar	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Exterior of the 1911 Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 05/29/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	6/21/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **38**

MATERIAL DESCRIPTION: **Exterior Brick Mortar**

MATERIAL LOCATION: **Exterior of the 1911 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **06/21/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	5/29/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	39	
MATERIAL DESCRIPTION:	Exterior Window Grout	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Exterior Windows of the 1911 Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 05/29/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	6/21/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **39**

MATERIAL DESCRIPTION: **Exterior Window Grout**

MATERIAL LOCATION: **Exterior Windows of the 1911 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **06/21/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	5/29/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	4		
MATERIAL DESCRIPTION:	Red Linoleum		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Engineer's Office - 1884 Building		
MATERIAL QUANTITY:	800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/29/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	6/21/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **4**

MATERIAL DESCRIPTION: **Red Linoleum**

MATERIAL LOCATION: **Engineer's Office - 1884 Building**

MATERIAL QUANTITY:	800	MATERIAL UNITS:	SF
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/21/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	5/29/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	40	
MATERIAL DESCRIPTION:	Exterior Brick - NON AHERA	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Exterior of the 1884 Building

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 05/29/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	6/21/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **40**

MATERIAL DESCRIPTION: **Exterior Brick - NON AHERA**

MATERIAL LOCATION: **Exterior of the 1884 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **06/21/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	5/29/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	41	
MATERIAL DESCRIPTION:	Exterior Mortar - NON AHERA	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Exterior of the 1814 Building

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 05/29/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	6/21/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **41**

MATERIAL DESCRIPTION: **Exterior Mortar - NON AHERA**

MATERIAL LOCATION: **Exterior of the 1814 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **06/21/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	5/29/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	42	
MATERIAL DESCRIPTION:	Exterior Window Grout - NON AHERA	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Exterior of the 1884 Building

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 05/29/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	6/21/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **42**

MATERIAL DESCRIPTION: **Exterior Window Grout - NON AHERA**

MATERIAL LOCATION: **Exterior of the 1884 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **06/21/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	5/29/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	43		
MATERIAL DESCRIPTION:	Tank Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Boiler Room		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

COMMENTS:

Inspector's Signature: _____ Date: 05/29/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	6/21/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **43**

MATERIAL DESCRIPTION: **Tank Insulation**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: **1000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/21/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	5/29/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	44	
MATERIAL DESCRIPTION:	Exterior Brick Used to Block Windows - NON AHERA	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Exterior of the 1884 Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 05/29/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	6/21/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **44**

MATERIAL DESCRIPTION: **Exterior Brick Used to Block Windows - NON AHERA**

MATERIAL LOCATION: **Exterior of the 1884 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **06/21/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	5/29/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	45	
MATERIAL DESCRIPTION:	Brick Mortar Used to Block Windows	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Exterior of the 1884 Building

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 05/29/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	6/21/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **45**

MATERIAL DESCRIPTION: **Brick Mortar Used to Block Windows**

MATERIAL LOCATION: **Exterior of the 1884 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **06/21/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	5/29/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	46	
MATERIAL DESCRIPTION:	Spray-on Insulation	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Electric Room on the 1st Floor of the 1911 Building, Boiler Room Ceiling by Back Door- 1911 Bldg.

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 05/29/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	6/21/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **46**

MATERIAL DESCRIPTION: **Spray-on Insulation**

MATERIAL LOCATION: **Electric Room on the 1st Floor of the 1911 Building, Boiler Room Ceiling by Back Door- 1911 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **06/21/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	5/29/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	47	
MATERIAL DESCRIPTION:	Blue Floor Tile	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Hall at Exit by Office

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Not Observed

Inspector's Signature: _____ Date: 05/29/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	6/21/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **47**

MATERIAL DESCRIPTION: **Blue Floor Tile**

MATERIAL LOCATION: **Hall at Exit by Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **06/21/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	5/29/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	48		
MATERIAL DESCRIPTION:	Terrazzo Flooring		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout the 1911 Building Stairs		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/29/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	6/21/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **48**

MATERIAL DESCRIPTION: **Terrazzo Flooring**

MATERIAL LOCATION: **Throughout the 1911 Building Stairs**

MATERIAL QUANTITY: **1000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/21/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	5/29/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	49		
MATERIAL DESCRIPTION:	12" x 12" Blue Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Main Office & Principal's Office of the 1911 Building & Room 411 of the 1884 Building		
MATERIAL QUANTITY:	2700	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:	No Access to Principal's Office		

Inspector's Signature: _____ Date: 05/29/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	6/21/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA:	49				
MATERIAL DESCRIPTION:	12" x 12" Blue Floor Tile Mastic				
MATERIAL LOCATION:	Main Office & Principal's Office of the 1911 Building & Room 411 of the 1884 Building				
MATERIAL QUANTITY:	2700	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/21/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	5/29/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	53	
MATERIAL DESCRIPTION:	12"x12" Beige Floor Tile w/Gray & White Streaks	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: The Stair Landings of the 1884 Building & Room 102 of the 1911 Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Not Observed

Inspector's Signature: _____ Date: 05/29/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	6/21/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **53**

MATERIAL DESCRIPTION: **12"x12" Beige Floor Tile w/Gray & White Streaks**

MATERIAL LOCATION: **The Stair Landings of the 1884 Building & Room 102 of the 1911 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **06/21/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	5/29/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	54	
MATERIAL DESCRIPTION:	Purple Carpet Mastic	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: Low

MATERIAL LOCATION: Room 206/208

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Not Observed

Inspector's Signature: _____ Date: 05/29/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	6/21/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **54**

MATERIAL DESCRIPTION: **Purple Carpet Mastic**

MATERIAL LOCATION: **Room 206/208**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **06/21/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	5/29/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	55	
MATERIAL DESCRIPTION:	Linoleum Flooring	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Abated	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: Low

MATERIAL LOCATION: Gymnasium - 1911 Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Abated

Inspector's Signature: _____ Date: 05/29/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	6/21/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **55**

MATERIAL DESCRIPTION: **Linoleum Flooring**

MATERIAL LOCATION: **Gymnasium - 1911 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **06/21/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	5/29/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	56		
MATERIAL DESCRIPTION:	Linoleum Flooring Mastic		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Abated	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Gymnasium

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Abated

Inspector's Signature: _____ Date: 05/29/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	6/21/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **56**

MATERIAL DESCRIPTION: **Linoleum Flooring Mastic**

MATERIAL LOCATION: **Gymnasium**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **06/21/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	5/29/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	57	
MATERIAL DESCRIPTION:	Blue Carpet Masric	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: Low

MATERIAL LOCATION: Main Office, Principal's Office, Room 202 - 1911 Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 05/29/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	6/21/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **57**

MATERIAL DESCRIPTION: **Blue Carpet Masric**

MATERIAL LOCATION: **Main Office, Principal's Office, Room 202 - 1911 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **06/21/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	5/29/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	58	
MATERIAL DESCRIPTION:	4" Brown Vinyl Baseboard	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: Low

MATERIAL LOCATION: 1911 Building Gym/Assembly Hall

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 05/29/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	6/21/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **58**

MATERIAL DESCRIPTION: **4" Brown Vinyl Baseboard**

MATERIAL LOCATION: **1911 Building Gym/Assembly Hall**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **06/21/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	5/29/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	59	
MATERIAL DESCRIPTION:	4" Brown Vinyl Baseboard - Adhesive	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: Low

MATERIAL LOCATION: 1911 Building - Gym/Assembly Hall

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 05/29/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	6/21/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **59**

MATERIAL DESCRIPTION: **4" Brown Vinyl Baseboard - Adhesive**

MATERIAL LOCATION: **1911 Building - Gym/Assembly Hall**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **06/21/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	5/29/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	5A	
MATERIAL DESCRIPTION:	9" x 9" Tan Floor Tile (Under Carpet)	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Abated	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: Low

MATERIAL LOCATION: Room 202 - 1911 Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Abated

Inspector's Signature: _____ Date: 05/29/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	6/21/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **5A**

MATERIAL DESCRIPTION: **9" x 9" Tan Floor Tile (Under Carpet)**

MATERIAL LOCATION: **Room 202 - 1911 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **06/21/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	5/29/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	5B		
MATERIAL DESCRIPTION:	9" x 9" Tan Floor Tile Mastic (Under Carpet)		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Abated	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: Low

MATERIAL LOCATION: Room 202 - 1911 Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Abated

Inspector's Signature: _____ Date: 05/29/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	6/21/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **5B**

MATERIAL DESCRIPTION: **9" x 9" Tan Floor Tile Mastic (Under Carpet)**

MATERIAL LOCATION: **Room 202 - 1911 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **06/21/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	5/29/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	6	
MATERIAL DESCRIPTION:	Gray Linoleum	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 210

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 05/29/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	6/21/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **6**

MATERIAL DESCRIPTION: **Gray Linoleum**

MATERIAL LOCATION: **Room 210**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **06/21/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	5/29/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	60		
MATERIAL DESCRIPTION:	12"x12" Gray Speckle Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:	Physical Damage		
DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1911 Building - Old Lunchroom, Room 102		
MATERIAL QUANTITY:	840	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	12	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/29/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	6/21/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **60**

MATERIAL DESCRIPTION: **12"x12" Gray Speckle Floor Tile**

MATERIAL LOCATION: **1911 Building - Old Lunchroom, Room 102**

MATERIAL QUANTITY:	840	MATERIAL UNITS:	SF
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	12	DAMAGE UNITS:	SF
------------------	-----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/21/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	5/29/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	61		
MATERIAL DESCRIPTION:	12"x12" Gray Speckle Floor Tile - Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1191 Building - Old Lunchroom/Room 102		
MATERIAL QUANTITY:	840	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/29/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	6/21/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA:	61		
MATERIAL DESCRIPTION:	12"x12" Gray Speckle Floor Tile - Mastic		
MATERIAL LOCATION:	1191 Building - Old Lunchroom/Room 102		
MATERIAL QUANTITY:	840	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/21/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	5/29/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	62		
MATERIAL DESCRIPTION:	2" Brown Vinyl Baseboard		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1911 Building - Old Lunchroom/Room 102		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature: _____ Date: 05/29/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	6/21/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **62**

MATERIAL DESCRIPTION: **2" Brown Vinyl Baseboard**

MATERIAL LOCATION: **1911 Building - Old Lunchroom/Room 102**

MATERIAL QUANTITY:	100	MATERIAL UNITS:	LF
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/21/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	5/29/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	63		
MATERIAL DESCRIPTION:	2" Brown Vinyl Baseboard - Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1911 Building - Old Lunchroom/Room 102		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature: _____ Date: 05/29/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	6/21/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **63**

MATERIAL DESCRIPTION: **2" Brown Vinyl Baseboard - Adhesive**

MATERIAL LOCATION: **1911 Building - Old Lunchroom/Room 102**

MATERIAL QUANTITY:	100	MATERIAL UNITS:	LF
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/21/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	5/29/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	64	
MATERIAL DESCRIPTION:	12"x12" Brown Speckled Floor Tile	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1884 Building - Room 103

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Not Observed

Inspector's Signature: _____ Date: 05/29/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	6/21/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **64**

MATERIAL DESCRIPTION: **12"x12" Brown Speckled Floor Tile**

MATERIAL LOCATION: **1884 Building - Room 103**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **06/21/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	5/29/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	65	
MATERIAL DESCRIPTION:	12"x12" Tan Speckled Floor Tile - Mastic	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1884 Building - Room 103

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Not Observed

Inspector's Signature: _____ Date: 05/29/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	6/21/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **65**

MATERIAL DESCRIPTION: **12"x12" Tan Speckled Floor Tile - Mastic**

MATERIAL LOCATION: **1884 Building - Room 103**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **06/21/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	5/29/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	66		
MATERIAL DESCRIPTION:	Ceramic Baseboard Grout		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1911 Building - 2nd and 3rd Floor Girls' and Teacher's Washrooms		
MATERIAL QUANTITY:	120	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature: _____ Date: 05/29/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	6/21/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **66**

MATERIAL DESCRIPTION: **Ceramic Baseboard Grout**

MATERIAL LOCATION: **1911 Building - 2nd and 3rd Floor Girls' and Teacher's Washrooms**

MATERIAL QUANTITY:	120	MATERIAL UNITS:	LF
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/21/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	5/29/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	67		
MATERIAL DESCRIPTION:	Ceramic Baseboard Grout - Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1911 Building - 2nd and 3rd Floor Girls' and Teacher's Washrooms		
MATERIAL QUANTITY:	120	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature: _____ Date: 05/29/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	6/21/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **67**

MATERIAL DESCRIPTION: **Ceramic Baseboard Grout - Adhesive**

MATERIAL LOCATION: **1911 Building - 2nd and 3rd Floor Girls' and Teacher's Washrooms**

MATERIAL QUANTITY:	120	MATERIAL UNITS:	LF
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/21/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	5/29/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	68	
MATERIAL DESCRIPTION:	12"x12" Patched Floor Tile	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Abated	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: Low

MATERIAL LOCATION: 1884 Building - Room 314

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Abated

Inspector's Signature: _____ Date: 05/29/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	6/21/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **68**

MATERIAL DESCRIPTION: **12"x12" Patched Floor Tile**

MATERIAL LOCATION: **1884 Building - Room 314**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **06/21/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	5/29/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	69	
MATERIAL DESCRIPTION:	12"x12" Patched Floor Tile - Mastic	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Abated	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: Low

MATERIAL LOCATION: 1884 Building - Room 314

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Abated

Inspector's Signature: _____ Date: 05/29/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	6/21/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **69**

MATERIAL DESCRIPTION: **12"x12" Patched Floor Tile - Mastic**

MATERIAL LOCATION: **1884 Building - Room 314**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **06/21/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	5/29/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	7	
MATERIAL DESCRIPTION:	Plaster	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throughout the 1911 Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 05/29/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	6/21/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **7**

MATERIAL DESCRIPTION: **Plaster**

MATERIAL LOCATION: **Throughout the 1911 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **06/21/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	5/29/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	70		
MATERIAL DESCRIPTION:	Dark Blotted Beige VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Lunchroom, Exit 3 entrance		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/29/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	6/21/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA:	70		
MATERIAL DESCRIPTION:	Dark Blotted Beige VFT		
MATERIAL LOCATION:	Lunchroom, Exit 3 entrance		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/21/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	5/29/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	71		
MATERIAL DESCRIPTION:	Dark Blotted Beige VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Lunchroom, Exit 3 entrance		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/29/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	6/21/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **71**

MATERIAL DESCRIPTION: **Dark Blotted Beige VFT Mastic**

MATERIAL LOCATION: **Lunchroom, Exit 3 entrance**

MATERIAL QUANTITY: **1000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/21/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	5/29/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	72		
MATERIAL DESCRIPTION:	12" X 12" Tan Texture VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	West Corridor		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/29/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	6/21/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **72**

MATERIAL DESCRIPTION: **12" X 12" Tan Texture VFT**

MATERIAL LOCATION: **West Corridor**

MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/21/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	5/29/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	73		
MATERIAL DESCRIPTION:	12" X 12" Tan Texture VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	West Corridor		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/29/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	6/21/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **73**

MATERIAL DESCRIPTION: **12" X 12" Tan Texture VFT Mastic**

MATERIAL LOCATION: **West Corridor**

MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/21/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	5/29/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	74		
MATERIAL DESCRIPTION:	Brown Rubber Floor Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Stairwells		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/29/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	6/21/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **74**

MATERIAL DESCRIPTION: **Brown Rubber Floor Adhesive**

MATERIAL LOCATION: **Stairwells**

MATERIAL QUANTITY: **1000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/21/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	5/29/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	75		
MATERIAL DESCRIPTION:	2' X 2' Green Carpet Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Office		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

COMMENTS:

Inspector's Signature: _____ Date: 05/29/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	6/21/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **75**

MATERIAL DESCRIPTION: **2' X 2' Green Carpet Adhesive**

MATERIAL LOCATION: **Office**

MATERIAL QUANTITY: **1000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/21/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	5/29/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	76		
MATERIAL DESCRIPTION:	2' X 2' Blue Carpet Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 206, 208		
MATERIAL QUANTITY:	1800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/29/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	6/21/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **76**

MATERIAL DESCRIPTION: **2' X 2' Blue Carpet Adhesive**

MATERIAL LOCATION: **Room 206, 208**

MATERIAL QUANTITY: **1800**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/21/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	5/29/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	77		
MATERIAL DESCRIPTION:	Lab Counter tops		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 314, 214, 114		
MATERIAL QUANTITY:	3	MATERIAL UNITS:	EA
DAMAGE QUANTITY:	0	DAMAGE UNITS:	EA
COMMENTS:			

Inspector's Signature: _____ Date: 05/29/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	6/21/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **77**

MATERIAL DESCRIPTION: **Lab Counter tops**

MATERIAL LOCATION: **Room 314, 214, 114**

MATERIAL QUANTITY: **3**

MATERIAL UNITS: **EA**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **EA**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/21/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	5/29/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	78		
MATERIAL DESCRIPTION:	12" X 12" lite Beige VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Classroom 104 and Corridor		
MATERIAL QUANTITY:	16000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/29/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	6/21/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA:	78		
MATERIAL DESCRIPTION:	12" X 12" lite Beige VFT		
MATERIAL LOCATION:	Classroom 104 and Corridor		
MATERIAL QUANTITY:	16000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/21/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	5/29/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	79		
MATERIAL DESCRIPTION:	12" X 12" lite Beige VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Classroom 104 and Corridor		
MATERIAL QUANTITY:	1600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/29/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	6/21/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **79**

MATERIAL DESCRIPTION: **12" X 12" lite Beige VFT Mastic**

MATERIAL LOCATION: **Classroom 104 and Corridor**

MATERIAL QUANTITY: **1600**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/21/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	5/29/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	8	
MATERIAL DESCRIPTION:	Plaster	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throughout the 1884 Building

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 05/29/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	6/21/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **8**

MATERIAL DESCRIPTION: **Plaster**

MATERIAL LOCATION: **Throughout the 1884 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **06/21/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	5/29/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	80		
MATERIAL DESCRIPTION:	Pink/Tan Sheet Flooring		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 214, 312, 313, 314, 413, 414		
MATERIAL QUANTITY:	2400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:	Not Observed in Room 312, 314		

Inspector's Signature: _____ Date: 05/29/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	6/21/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **80**

MATERIAL DESCRIPTION: **Pink/Tan Sheet Flooring**

MATERIAL LOCATION: **Rooms 214, 312, 313, 314, 413, 414**

MATERIAL QUANTITY: **2400**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/21/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	5/29/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	81		
MATERIAL DESCRIPTION:	Mastic Associated w/ Pink/Tan Sheet Flooring		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 214, 312, 313, 314, 413, 414		
MATERIAL QUANTITY:	2400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/29/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	6/21/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **81**

MATERIAL DESCRIPTION: **Mastic Associated w/ Pink/Tan Sheet Flooring**

MATERIAL LOCATION: **Rooms 214, 312, 313, 314, 413, 414**

MATERIAL QUANTITY: **2400**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/21/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	5/29/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	82		
MATERIAL DESCRIPTION:	6" Gray Vinyl Baseboard		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 214, 312, 313, 314, 413, 414		
MATERIAL QUANTITY:	240	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature: _____ Date: 05/29/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	6/21/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **82**

MATERIAL DESCRIPTION: **6" Gray Vinyl Baseboard**

MATERIAL LOCATION: **Rooms 214, 312, 313, 314, 413, 414**

MATERIAL QUANTITY:	240	MATERIAL UNITS:	LF
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/21/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	5/29/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	83		
MATERIAL DESCRIPTION:	Adhesive on 6" Gray Vinyl Baseboard		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 214, 312, 313, 314, 413, 414		
MATERIAL QUANTITY:	240	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature: _____ Date: 05/29/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	6/21/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **83**

MATERIAL DESCRIPTION: **Adhesive on 6" Gray Vinyl Baseboard**

MATERIAL LOCATION: **Rooms 214, 312, 313, 314, 413, 414**

MATERIAL QUANTITY:	240	MATERIAL UNITS:	LF
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/21/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	5/29/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	84		
MATERIAL DESCRIPTION:	White Sink Undercoat		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 113		
MATERIAL QUANTITY:	1	MATERIAL UNITS:	EA
DAMAGE QUANTITY:	0	DAMAGE UNITS:	EA

COMMENTS:

Inspector's Signature: _____ Date: 05/29/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	6/21/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **84**

MATERIAL DESCRIPTION: **White Sink Undercoat**

MATERIAL LOCATION: **Room 113**

MATERIAL QUANTITY: **1**

MATERIAL UNITS: **EA**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **EA**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/21/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	5/29/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	9	
MATERIAL DESCRIPTION:	12" x 12" Brown Floor Tile - Not Observed	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Teacher's Washroom by Room 309

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Not Observed

Inspector's Signature: _____ Date: 05/29/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	6/21/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **9**

MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile - Not Observed**

MATERIAL LOCATION: **Teacher's Washroom by Room 309**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **06/21/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	5/29/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	A		
MATERIAL DESCRIPTION:	Air Cell Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Pipe Chases and Within Walls		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/29/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	6/21/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **A**

MATERIAL DESCRIPTION: **Air Cell Pipe Insulation**

MATERIAL LOCATION: **Pipe Chases and Within Walls**

MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/21/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	5/29/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	B		
MATERIAL DESCRIPTION:	Cementitious Joints on Aircell Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Pipe Chases and Within Walls		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/29/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	6/21/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **B**

MATERIAL DESCRIPTION: **Cementitious Joints on Aircell Pipe Insulation**

MATERIAL LOCATION: **Pipe Chases and Within Walls**

MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/21/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	5/29/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	C		
MATERIAL DESCRIPTION:	Cardboard Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Pipe Chases and Within Walls		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/29/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	6/21/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **C**

MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**

MATERIAL LOCATION: **Pipe Chases and Within Walls**

MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/21/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	5/29/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	D		
MATERIAL DESCRIPTION:	Cementitious Joint Insulation off Cardboard		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Pipe Chases and Within Walls		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

COMMENTS:

Inspector's Signature: _____ Date: 05/29/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	6/21/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **D**

MATERIAL DESCRIPTION: **Cementitious Joint Insulation off Cardboard**

MATERIAL LOCATION: **Pipe Chases and Within Walls**

MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/21/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	5/29/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	E		
MATERIAL DESCRIPTION:	Powder Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Pipe Chases and Within Walls		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/29/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	6/21/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **E**

MATERIAL DESCRIPTION: **Powder Pipe Insulation**

MATERIAL LOCATION: **Pipe Chases and Within Walls**

MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/21/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	5/29/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	F		
MATERIAL DESCRIPTION:	Powder Elbows		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Pipe Chases and Within Walls		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/29/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	6/21/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **F**

MATERIAL DESCRIPTION: **Powder Elbows**

MATERIAL LOCATION: **Pipe Chases and Within Walls**

MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/21/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	5/29/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	G		
MATERIAL DESCRIPTION:	Boiler Gasket		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Boiler Room		
MATERIAL QUANTITY:	10	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature: _____ Date: 05/29/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	6/21/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **G**

MATERIAL DESCRIPTION: **Boiler Gasket**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: **10**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/21/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	5/29/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	H		
MATERIAL DESCRIPTION:	Boiler Packing		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Boiler Room		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

COMMENTS:

Inspector's Signature: _____ Date: 05/29/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	6/21/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **H**

MATERIAL DESCRIPTION: **Boiler Packing**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/21/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	5/29/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	I	
MATERIAL DESCRIPTION:	Tank Insulation - Abated 1994	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Abated	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Boiler Room

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Abated

Inspector's Signature: _____ Date: 05/29/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	6/21/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **I**

MATERIAL DESCRIPTION: **Tank Insulation - Abated 1994**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **06/21/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	5/29/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	J	
MATERIAL DESCRIPTION:	Kiln	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION:

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed**

Inspector's Signature: _____ Date: 05/29/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	6/21/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **J**

MATERIAL DESCRIPTION: **Kiln**

MATERIAL LOCATION:

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **06/21/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	5/29/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	K		
MATERIAL DESCRIPTION:	Aircell Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Pipe Chases and Within Walls		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/29/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	6/21/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **K**

MATERIAL DESCRIPTION: **Aircell Pipe Insulation**

MATERIAL LOCATION: **Pipe Chases and Within Walls**

MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/21/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	5/29/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	L		
MATERIAL DESCRIPTION:	Cementitious Joint Insulation on Aircell		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Pipe Chases and Within Walls		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/29/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	6/21/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **L**

MATERIAL DESCRIPTION: **Cementitious Joint Insulation on Aircell**

MATERIAL LOCATION: **Pipe Chases and Within Walls**

MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/21/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	5/29/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	M		
MATERIAL DESCRIPTION:	Cardboard Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Pipe Chases and Within Walls		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature: _____ Date: 05/29/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	6/21/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **M**

MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**

MATERIAL LOCATION: **Pipe Chases and Within Walls**

MATERIAL QUANTITY:	100	MATERIAL UNITS:	LF
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/21/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	5/29/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	N		
MATERIAL DESCRIPTION:	Cementitious Pipe Joint Insulation off Cardboard		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Pipe Chases and Within Walls		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/29/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	6/21/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **N**

MATERIAL DESCRIPTION: **Cementitious Pipe Joint Insulation off Cardboard**

MATERIAL LOCATION: **Pipe Chases and Within Walls**

MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/21/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	5/29/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	O		
MATERIAL DESCRIPTION:	Powder Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Pipe Chases and Within Walls		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature: _____ Date: 05/29/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	6/21/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **O**

MATERIAL DESCRIPTION: **Powder Pipe Insulation**

MATERIAL LOCATION: **Pipe Chases and Within Walls**

MATERIAL QUANTITY:	100	MATERIAL UNITS:	LF
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/21/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	5/29/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	P		
MATERIAL DESCRIPTION:	Powder Elbows		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Pipe Chases and Within Walls		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/29/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Evan Christian		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	6/21/2019		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **P**

MATERIAL DESCRIPTION: **Powder Elbows**

MATERIAL LOCATION: **Pipe Chases and Within Walls**

MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/21/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

APPENDIX B

Inspector and Management Planner Licenses

2015



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Evan Christian

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 12/2/2015

Exam Date: 12/2/2015

Expiration Date: 12/2/2016

Certificate Number: BIR1512024159

Kathy DeSalvo, Director

Reliable
Environmental
Solutions, Inc. **RES**

This is to certify that **Evan Christian**

*has on January 28 & 29, 2016, in Springfield, Illinois,
completed the requirements for asbestos accreditation under Section 206 of TSCA Title II*

Asbestos Management Planner Initial Training

*as accredited by the State of Illinois and approved by the U.S.E.P.A. under 40 CFR 763 (AHERA)
and passed the associated examination with a score of 70% or higher*

Course Date: January 28 & 29, 2016

Examination Date: January 29, 2016

Expiration Date: January 29, 2017

Certificate Number: MP/0103

William S. Williams

Training Program Manager, William S. Williams

4211 Westgate Drive, Springfield, Illinois ☐ 217.787.9800 ☐ 217.787.9801 FAX ☐ www.ReliableEnv.com

2019



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900 ♦ www.otssafety.com

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Evan Christian

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Course Date: 11/19/2019

Exam Date: 11/19/2019

Expiration Date: 11/19/2020

Certificate Number: BIR1911192384


Kathy DeSalvo, Director



**ASBESTOS
PROFESSIONAL
LICENSE**

ID NUMBER
100 - 19466

ISSUED
4/12/2019

EXPIRES
05/15/2020

EVAN I CHRISTIAN
3024 N RACINE AVE, APT 2
CHICAGO, IL 60657

Environmental Health



ENDORSEMENTS

TC EXPIRES

INSPECTOR

11/28/2019

MANAGEMENT PLANNER

1/5/2019

PROJECT MANAGER

2/5/2020

AIR SAMPLING PROFESSIONAL

Alteration of this license shall result in legal action

This license issued under authority of the State of Illinois
Department of Public Health

This license is valid only when accompanied by a valid
training course certificate.

2019



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900 ♦ www.otssafety.com

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Evan Christian

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Course Date: 1/7/2019

Exam Date: 1/7/2019



Expiration Date: 1/7/2020

Certificate Number: MPR1901070063

Kathy DeSalvo, Director

Evan Christian

Illinois Licensed Project Manager, and Air Sampling Professional



**CARNOW
CONIBEAR**

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL		
	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE		
	Loc	Localized
	Dist	Distributed