

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH  
AHERA THREE YEAR REINSPECTION  
ASBESTOS ABATEMENT PROGRAM  
SCHOOL INFORMATION FORM**

**SECTION I**

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299  
SCHOOL ID NUMBER: 14-016-2990-2139  
SCHOOL NAME: Cook School  
ADDRESS OF SCHOOL: 8150 S. Bishop  
CITY: Chicago, IL, 60620

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **3/10/2016**

**If the address on this form is different than the address of the building, submit a written explanation.**

**SECTION II** *(Please type or print)*

**PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:**

DATE REINSPECTION COMPLETED: 10/1/2019 ENROLLMENT 341  
IDPH INSPECTOR LICENSE NUMBER: 100-07839  
IDPH LICENSED INSPECTOR NAME(Please Print): Lisa Laney  
IDPH MP LICENSE NUMBER: 100-00746  
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Amy Williams

DESIGNATED PERSON (Please Print): Robert Christlieb PHONE: (773) 553-3197



10/1/2019

*Signature of Designated Person*

*Date*

**SECTION III**

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: \_\_\_\_\_

School has been closed. Date closed: \_\_\_\_\_

School building has been demolished. Date: \_\_\_\_\_

School building is asbestos free since last reinspection: \_\_\_\_\_

**Please explain in writing why the school building is now asbestos free and include the supporting documentation.**

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

**Explain in writing if the address of the building is different than the address on this form:**

**THREE-YEAR REINSPECTION**

**CHICAGO SCHOOL DIST 299**

**Cook School**

8150 S. Bishop  
Chicago, IL, 60620

Unit: 22801  
Building ID: 2860

IDPH ID Number: 14-016-2990-2139

**REPORT DATE:**

Tuesday, October 01, 2019

**Prepared for:**

**Chicago Public Schools  
42 West Madison Street  
Chicago, IL 60602**

**Prepared by:**

**TEM Environmental, Inc.**

174 N. Brandon Drive

Glendale Heights, IL, 60139

Phone 630-790-0880

Fax 630-790-0882

**DO NOT REMOVE FROM SCHOOL  
REQUIRED BY FEDERAL LAW**

August 16, 2019

Mr. Glen E. Garner  
Asbestos Program  
Illinois Department of Public Health  
525 West Jefferson Street  
Springfield, Illinois 62761

Re: Chicago Public Schools - 2019 Three-Year Reinspections

Dear Mr. Glen:

TEM Environmental, Inc. , Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 5, 6 Elementary Schools. Please update your records with the following information.

School District: 299            Unit: 22801            Region: 05            IDPH ID:14-016-2990-2139

School: Cook School            Building ID: 2860

Address: 8150 S. Bishop  
Chicago, IL, 60620

Building Contact:            Contact Phone:

Current Building Owners: Chicago Public Schools

Review Date: 09/12/2019

Inspector: Lisa Laney            Inspector IDPH License: 100-07839  
Management Planner: Amy Williams            Management Planner IDPH License: 100-00746

If you have any questions or comments, please contact us at 630-790-0880

Sincerely,  
TEM Environmental, Inc.

Amy Williams  
100-00746

## **Environmental Notification to Occupants**

To: Faculty, Staff and Parents  
From: Chicago Public Schools  
Date: August 16, 2019

RE: Cook School, Unit 22801  
8150 S. Bishop  
Chicago, IL, 60620

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2019 asbestos three year re-inspection has been completed at Cook School, following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at Cook School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Robert Christlieb, the designated Local Education Authority's Designated Person at (773) 553-3197 .

## **Table of Contents**

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

### **APPENDICES:**

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

## SCHOOL AND INSPECTION INFORMATION

### 1. School Information

School: Cook School  
Address: 8150 S. Bishop  
IDPH ID: 14-016-2990-2139  
Contact:

Unit: 22801  
Chicago, IL, 60620  
Building ID: 2860  
Phone:

Region: 05

### 2. Description of Facility

Original Construction:  
Total Square Footage:  
Current Occupancy: 341

Additional Construction:  
No of Floors:

### 3. LEA Designated Person

Contact: Robert Christlieb  
Address: 42 West Madison Street  
Chicago, IL 60602

Phone: (773) 553-3197

### 4. Managing Environmental Consultant

MEC: TEM Environmental, Inc.  
Contact: Steven Geneser  
Address 174 N. Brandon Drive  
Glendale Heights, IL, 60139  
Phone: 630-790-0880

Fax: 630-790-0882

### 5. Inspector

Inspector Name: Lisa Laney

Inspector IDPH license # 100-07839

Signature:  
Date: 8/16/2019

### 6. Management Planner

Management Planner Name: Amy Williams

Management Planner IDPH license # 100-00746

Signature:  
Date: 09/12/2019

### 7. Review Date:09/12/2019

### 8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature:



Date: 10/1/2019

Name: Robert Christlieb

## II. EXECUTIVE SUMMARY

TEM Environmental, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Cook School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.85 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas(HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 2860:

48	Hard Coat Plaster
A	Aircell Pipe Insulation
I	Fittings on Aircell
K	Whiteboard Mastic
L	Old Chalkboards

B. The following new homogenous areas have been identified for Building 2860:

K	Whiteboard Mastic
L	Old Chalkboards



C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

03	12" White Floor Tile
07	12" Brown Floor Tile
12	12" Beige Floor Tile
14	12" White Floor Tile
16	Fire Doors
18	Transite Lab Tables
19	Baseboard Mastic
20	Fire Doors
21	Baseboard Mastic
22	Baseboard
24	9" Beige Floor Tile Mastic
30	12" Tan Floor Tile Mastic
32	12" Beige Floor Tile Mastic
33	12" Purple Floor Tile
34	12" Purple Floor Tile Mastic
35	12" Tan Floor Tile
37	Brown Linoleum
38	Brown Linoleum Mastic
39	Purple Carpet Mastic
40	Orange Carpet Mastic
41	Brown Carpet Mastic
42	Orange Carpet Mastic
43	12x12 White Floor Tile
44	Multicolor Carpet Adhesive
45	12x12 Tan w/Specks Floor Tile
46	Purple Carpet
47	2'x4' Ceiling Tile w/Chicken Scratch
48	Hard Coat Plaster
49	Hard Coat Plaster
50	12x12 Dark Brown Floor Tile
51	12x12 Dark Brown Floor Tile Mastic
52	1'x1' Acoustical Ceiling Tile
53	1'x1' Acoustical Ceiling Tile Glue Dots
54	12x12 Light Beige w/Tan Specks Floor Tile
55	12x12 Light Beige w/Tan Specks Floor Tile Mastic
B	Paper Wrap Pipe Insulation
E	Tank Insulation
I	Fittings on Aircell
J	Incinerator Insulation (Gone c1990)
K	Whiteboard Mastic
L	Old Chalkboards

The following areas were deemed to be inaccessible:

19	Baseboard Mastic
21	Baseboard Mastic
24	9" Beige Floor Tile Mastic
25	12" Orange Floor Tile Mastic
26	12" Brown Floor Tile Mastic
27	12" White Floor Tile Mastic
28	12" Brown Floor Tile Mastic
29	12" White Floor Tile Mastic
30	12" Tan Floor Tile Mastic
31	12" Medium Brown Floor Tile Mastic
32	12" Beige Floor Tile Mastic
34	12" Purple Floor Tile Mastic
36	12" Tan Floor Tile Mastic
39	Purple Carpet Mastic
40	Orange Carpet Mastic
41	Brown Carpet Mastic
42	Orange Carpet Mastic
44	Multicolor Carpet Adhesive
51	12x12 Dark Brown Floor Tile Mastic
52	1'x1' Acoustical Ceiling Tile
53	1'x1' Acoustical Ceiling Tile Glue Dots
55	12x12 Light Beige w/Tan Specks Floor Tile Mastic
A	Aircell Pipe Insulation
I	Fittings on Aircell
K	Whiteboard Mastic

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Lisa Laney, IDPH License # 100-07839. The Management Plan was updated by Amy Williams, IDPH License # 100-00746. Inspector and Management Planner Licenses are included in Appendix B.

### **III. METHODOLOGY**

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

### **IV. ABATEMENT HISTORY**

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

### **V. REASSESSMENTS AND RECOMMENDATIONS**

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

### **VI. CONCLUSIONS**

The Cook School Building 2860 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

**Table I**  
**Inspector's Reinspection Findings**

---

# Chicago Public Schools

School Cook School Unit 22801 Building ID 2860

Address 8150 S. Bishop Region 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
03	12" White Floor Tile	2,250	SF	1925 Building-Room 102 & 112	ASSUMED	MISC	N	LOC	5		No	ACBM with the potential for damage	5	LOW
04	9x9 Beige Floor Tile	750	SF	1925 Building-Room 104	CHR	MISC	N	LOC	2		No	ACBM with the potential for damage	5	LOW
05	12" Tan Floor Tile	1,150	SF	1925 Building-Room 113	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
07	12" Brown Floor Tile	1,950	SF	Room 110 & 112	ASSUMED	MISC	N	LOC	10		No	ACBM with the potential for damage	5	LOW
08	12x12 White Floor Tile	750	SF	1925 Building-Room 111	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
09	12" Brown Floor Tile	3,520	SF	1974 Building- Store Rooms, Eng. Office, 1st & 2nd Floor Corridors	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
12	12" Beige Floor Tile	1,950	SF	1974 Building-Room 224 & 228	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
14	12" White Floor Tile	5,600	SF	1974 Building-Room 119, 121, Lunchroom, Teachers' Lunchroom & Corridor	ASSUMED	MISC	N	LOC	25		No	ACBM with the potential for damage	5	LOW
16	Fire Doors	2	EA	1925 Building-Boiler Room, Boiler Room Tunnel	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
17	Boiler Room Gasket ABATED			1925 Building-Boiler Room	ABATED	TSI								
18	Transite Lab Tables	30	SF	1925 Building-Room 207	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
19	Baseboard Mastic	70	LF	1925 Building-Rooms 115A, 216A, 1st Floor Boys' Toilet & Adjacent Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
20	Fire Doors	2	EA	1974 Building-Kitchen	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
21	Baseboard Mastic	2,940	LF	Throughout 1974 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
22	Baseboard	70	LF	1925 Building-Rooms 115A & 216A	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
23	Baseboard	2,940	LF	Throughout 1974 Building	ANT	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
24	9" Beige Floor Tile Mastic	750	SF	Room 104	ASSUMED	MISC	N	LOC	2		No	ACBM with the	5	LOW

# Chicago Public Schools

School Cook School Unit 22801 Building ID 2860

Address 8150 S. Bishop Region 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
												potential for damage		
25	12" Orange Floor Tile Mastic	8,650	SF	1st & 2nd Floor Corridors	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
26	12" Brown Floor Tile Mastic	1,950	SF	1925 Building-Room 110 & 112	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
27	12" White Floor Tile Mastic	5,600	SF	1974 Building-Room 119, 121, Teachers' Lunchroom, Lunchroom & Corridor	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
28	12" Brown Floor Tile Mastic	3,520	SF	1974 Building-Storerooms, Electrical Room, Engineer's Office, 1st & 2nd Floor Corridors	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
29	12" White Floor Tile Mastic	2,250	SF	1925 Building-Rooms 102 & 112	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
30	12" Tan Floor Tile Mastic	1,150	SF	1925 Building-Room 113	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
31	12" Medium Brown Floor Tile Mastic	750	SF	1925 Building-Room 111,115A	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
32	12" Beige Floor Tile Mastic	1,950	SF	1974 Building-Rooms 224 & 228	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
33	12" Purple Floor Tile	420	SF	1925 Building- Main Office, Principal's Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
34	12" Purple Floor Tile Mastic	420	SF	1925 Building- Main Office, Principal's Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
35	12" Tan Floor Tile	625	SF	1974 Annex Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
36	12" Tan Floor Tile Mastic	625	SF	1974 Annex Office	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
37	Brown Linoleum			1925 Building-Storeroom	ASSUMED	MISC								
38	Brown Linoleum Mastic			1925 Building-Storeroom	ASSUMED	MISC								
39	Purple Carpet Mastic	80	SF	1925 Building- Main Office Storeroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
40	Orange Carpet Mastic	1,125	SF	1925 Building-Teachers' Restroom & Room 218	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

# Chicago Public Schools

School Cook School Unit 22801 Building ID 2860

Address 8150 S. Bishop Region 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
41	Brown Carpet Mastic	1,500	SF	Principal's Office, Annex Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
42	Orange Carpet Mastic	6,000	SF	1974 Building-Rooms 120, 122, 124, 126, Storeroom & Library; Rooms 217, 219-223, 226, Teachers' Lounge, Library Office & AV Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
43	12x12 White Floor Tile	375	SF	1925 Building-Room 111	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
44	Multicolor Carpet Adhesive	1,125	SF	Room 218	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
45	12x12 Tan w/Specks Floor Tile	9,000	SF	Rooms 124, 126, 219 & 226	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
46	Purple Carpet	2,000	SF	Library	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
47	2'x4' Ceiling Tile w/Chicken Scratch	25,000	SF	1925 Building-Throughout 1st & 2nd Corridors, and All Classrooms	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
48	Hard Coat Plaster	37,500	SF	Throughout 1925 Building	ASSUMED	SURFACE	N	NONE	0		Yes	ACBM with the potential for damage		LOW
49	Hard Coat Plaster	37,500	SF	Throughout 1974 Building	ASSUMED	SURFACE	N	NONE	0		No	ACBM with the potential for damage		LOW
50	12x12 Dark Brown Floor Tile	474	SF	1st Floor Restroom and Rooms 115B and 215B	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
51	12x12 Dark Brown Floor Tile Mastic	474	SF	1st Floor Restroom and Rooms 115B and 215B	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
52	1'x1' Acoustical Ceiling Tile	38	SF	Room 213 Chalk Board	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
53	1'x1' Acoustical Ceiling Tile Glue Dots	38	SF	Room 213 Chalk Board	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
54	12x12 Light Beige w/Tan Specks Floor Tile	725	SF	Room 208	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
55	12x12 Light Beige w/Tan Specks Floor Tile Mastic	725	SF	Room 208	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
A	Aircell Pipe Insulation		LF	1925 Building-Basement, Open Crawlspace	CHR	TSI	Y	DIST	100		Yes	Damaged or significantly damaged friable thermal system insulating ACBM	3	LOW

# Chicago Public Schools

School Cook School Unit 22801 Building ID 2860

Address 8150 S. Bishop Region 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
B	Paper Wrap Pipe Insulation	60	LF	1925 Building-Basement Crawlspace, Boys' & Girls Bathroom, Pipe Chases Throughout	ASSUMED	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
D	Aircell Duct Insulation			Wall, Crawlspace	CHR	TSI								
E	Tank Insulation	100	SF	Boiler Room	ASSUMED	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
F	Fittings on Fiberglass	1	FITTING	1974 Building- Compactor Room	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
H	Fittings on Paper Wrap	20	LF	1925 Building-Basement Crawlspace, Boys' & Girls' Bathrooms, Pipe Chases Throughout Building	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
I	Fittings on Aircell		LF	1925 Building-Crawlspace	ASSUMED	TSI	Y	DIST	25		Yes	Damaged or significantly damaged friable thermal system insulating ACBM	5	LOW
J	Incinerator Insulation (Gone c1990)			1925 Building-Boiler Room	ASSUMED	TSI								
K	Whiteboard Mastic	750	SF	Throughout	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
L	Old Chalkboards	4,000	SF	Throughout School	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW



# Chicago Public Schools

School Cook School Unit 22801 Building ID 2860

Address 8150 S. Bishop Region 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

Reinspection Date <b>8/16/2019</b>
Inspector Name <b><u>Lisa Laney</u></b>
<b>100-07839</b> <b>5/15/2020</b>
Inspector's IDPH License Number / Expiration Date

### Inspector's Comments

HA Number:	Inspector Comments:
03	Damage Rm. 112
04	Damage is located in Room 104
05	
07	Damage located in Room 110/112
08	
09	
12	
14	Lunchroom Damage
16	
17	
18	No Transite Table Tops Observed
19	
20	
21	
22	
23	
24	Damage is located in Room 104
25	
26	
27	
28	
29	
30	

# Chicago Public Schools

School Cook School Unit 22801 Building ID 2860

Address 8150 S. Bishop Region 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
31	
32	
33	
34	
35	
36	
37	Not Observed 2019. Concrete Floors
38	Not Observed 2019. Concrete Floors
39	
40	
41	
42	
43	
44	
45	
46	
47	
48	
49	
50	
51	
52	
53	
54	
55	
A	Crawl Spaces;exposed ends, delaminated canvas wrap
B	
D	Not Observed 2019
E	

# Chicago Public Schools

School Cook School Unit 22801 Building ID 2860

Address 8150 S. Bishop Region 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
F	
H	
I	Crawlspaces
J	Not Observed 2019. Gone Since 1990
K	
L	

**Table II**

**Management Planner's Review**

---

# Chicago Public Schools

School Cook School

Unit 22801

Building ID 2860

Address 8150 S. Bishop

Chicago, IL, 60620

Region 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

### Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
03	12" White Floor Tile	2,250	SF	1925 Building- Room 102 & 112	Assumed	MISC	No	5	SF	6 ACBM with the potential for damage	Follow O&M Plan
04	9x9 Beige Floor Tile	750	SF	1925 Building- Room 104	Chrysotile	MISC	No	2	SF	6 ACBM with the potential for damage	Follow O&M Plan
05	12" Tan Floor Tile	1,150	SF	1925 Building- Room 113	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
07	12" Brown Floor Tile	1,950	SF	Room 110 & 112	Assumed	MISC	No	10	SF	6 ACBM with the potential for damage	Follow O&M Plan
08	12x12 White Floor Tile	750	SF	1925 Building- Room 111	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
09	12" Brown Floor Tile	3,520	SF	1974 Building- Store Rooms, Eng. Office, 1st & 2nd Floor Corridors	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
12	12" Beige Floor Tile	1,950	SF	1974 Building- Room 224 & 228	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
14	12" White Floor Tile	5,600	SF	1974 Building- Room 119, 121, Lunchroom, Teachers' Lunchroom & Corridor	Assumed	MISC	No	25	SF	6 ACBM with the potential for damage	Follow O&M Plan
16	Fire Doors	2	EA	1925 Building- Boiler Room, Boiler Room Tunnel	Assumed	MISC	No	0	EA	6 ACBM with the potential for damage	Follow O&M Plan
17	Boiler Room Gasket ABATED			1925 Building- Boiler Room	Abated	TSI					
18	Transite Lab Tables	30	SF	1925 Building- Room 207	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
19	Baseboard Mastic	70	LF	1925 Building- Rooms 115A, 216A, 1st Floor Boys' Toilet & Adjacent Corridor	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
20	Fire Doors	2	EA	1974 Building- Kitchen	Assumed	MISC	No	0	EA	6 ACBM with the potential for damage	Follow O&M Plan
21	Baseboard Mastic	2,940	LF	Throughout 1974 Building	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
22	Baseboard	70	LF	1925 Building- Rooms 115A & 216A	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
23	Baseboard	2,940	LF	Throughout 1974 Building	Anthophyllite	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
24	9" Beige Floor Tile Mastic	750	SF	Room 104	Assumed	MISC	No	2	SF	6 ACBM with the potential for damage	Follow O&M Plan
25	12" Orange Floor Tile Mastic	8,650	SF	1st & 2nd Floor Corridors	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
26	12" Brown Floor Tile Mastic	1,950	SF	1925 Building- Room 110 & 112	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
27	12" White Floor Tile Mastic	5,600	SF	1974 Building- Room 119, 121, Teachers' Lunchroom, Lunchroom & Corridor	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
28	12" Brown Floor Tile Mastic	3,520	SF	1974 Building- Storerooms, Electrical Room, Engineer's Office, 1st & 2nd Floor Corridors	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
29	12" White Floor Tile Mastic	2,250	SF	1925 Building- Rooms 102 & 112	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
30	12" Tan Floor Tile Mastic	1,150	SF	1925 Building- Room 113	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
31	12" Medium Brown Floor Tile Mastic	750	SF	1925 Building- Room 111, 115A	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

School Cook School

Unit 22801

Building ID 2860

Address 8150 S. Bishop

Chicago, IL, 60620

Region 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

### Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
32	12" Beige Floor Tile Mastic	1,950	SF	1974 Building- Rooms 224 & 228	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
33	12" Purple Floor Tile	420	SF	1925 Building- Main Office, Principal's Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
34	12" Purple Floor Tile Mastic	420	SF	1925 Building- Main Office, Principal's Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
35	12" Tan Floor Tile	625	SF	1974 Annex Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
36	12" Tan Floor Tile Mastic	625	SF	1974 Annex Office	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
37	Brown Linoleum			1925 Building- Storeroom	Assumed	MISC					
38	Brown Linoleum Mastic			1925 Building- Storeroom	Assumed	MISC					
39	Purple Carpet Mastic	80	SF	1925 Building- Main Office Storeroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
40	Orange Carpet Mastic	1,125	SF	1925 Building- Teachers' Restroom & Room 218	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
41	Brown Carpet Mastic	1,500	SF	Principal's Office, Annex Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
42	Orange Carpet Mastic	6,000	SF	1974 Building- Rooms 120, 122, 124, 126, Storeroom & Library; Rooms 217, 219-223, 226, Teachers' Lounge, Library Office & AV Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
43	12x12 White Floor Tile	375	SF	1925 Building- Room 111	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
44	Multicolor Carpet Adhesive	1,125	SF	Room 218	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
45	12x12 Tan w/Specks Floor Tile	9,000	SF	Rooms 124, 126, 219 & 226	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
46	Purple Carpet	2,000	SF	Library	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
47	2'x4' Ceiling Tile w/Chicken Scratch	25,000	SF	1925 Building- Throughout 1st & 2nd Corridors, and All Classrooms	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
48	Hard Coat Plaster	37,500	SF	Throughout 1925 Building	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
49	Hard Coat Plaster	37,500	SF	Throughout 1974 Building	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
50	12x12 Dark Brown Floor Tile	474	SF	1st Floor Restroom and Rooms 115B and 215B	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
51	12x12 Dark Brown Floor Tile Mastic	474	SF	1st Floor Restroom and Rooms 115B and 215B	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
52	1'x1' Acoustical Ceiling Tile	38	SF	Room 213 Chalk Board	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
53	1'x1' Acoustical Ceiling Tile Glue Dots	38	SF	Room 213 Chalk Board	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
54	12x12 Light Beige w/Tan Specks Floor Tile	725	SF	Room 208	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
55	12x12 Light Beige w/Tan Specks Floor Tile Mastic	725	SF	Room 208	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

School Cook School

Unit 22801

Building ID 2860

Address 8150 S. Bishop

Chicago, IL, 60620

Region 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

### Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
A	Aircell Pipe Insulation		LF	1925 Building- Basement, Open Crawlspace	Chrysotile	TSI	Yes	100	LF	1 Damaged or significantly damaged friable thermal system insulating ACBM	Repair
B	Paper Wrap Pipe Insulation	60	LF	1925 Building- Basement Crawlspace, Boys' & Girls Bathroom, Pipe Chases Throughout	Assumed	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
D	Aircell Duct Insulation			Wall, Crawlspace	Chrysotile	TSI					
E	Tank Insulation	100	SF	Boiler Room	Assumed	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
F	Fittings on Fiberglass	1	FITTING	1974 Building- Compactor Room	Chrysotile	TSI	Yes	0	FITTING	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
H	Fittings on Paper Wrap	20	LF	1925 Building- Basement Crawlspace, Boys' & Girls' Bathrooms, Pipe Chases Throughout Building	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
I	Fittings on Aircell		LF	1925 Building- Crawlspace	Assumed	TSI	Yes	25	LF	1 Damaged or significantly damaged friable thermal system insulating ACBM	Repair
J	Incinerator Insulation (Gone c1990)			1925 Building- Boiler Room	Assumed	TSI					
K	Whiteboard Mastic	750	SF	Throughout	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
L	Old Chalkboards	4,000	SF	Throughout School	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Cook School  
**Address** 8150 S. Bishop

**Unit** 22801  
 Chicago, IL, 60620

**Building ID** 2860  
**Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.  
 174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

*Management Planner's Comments Summarized at the End of the Report*

Review Date	09/12/2019
Manager Planner Name	Amy Williams
100-00746	5/15/2020
Manager IDPH License No/Expiration	

HA Number	Management Comments
03	
04	
05	
07	
08	
09	
12	
14	
16	
17	
18	
19	
20	
21	
22	
23	
24	
25	
26	



# Chicago Public Schools

**School** Cook School  
**Address** 8150 S. Bishop

**Unit** 22801  
Chicago, IL, 60620

**Building ID** 2860  
**Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
27	
28	
29	
30	
31	
32	
33	
34	
35	
36	
37	
38	
39	
40	
41	
42	
43	
44	
45	
46	
47	
48	
49	
50	
51	
52	

# Chicago Public Schools

**School** Cook School  
**Address** 8150 S. Bishop

**Unit** 22801  
Chicago, IL, 60620

**Building ID** 2860  
**Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
53	
54	
55	
A	
B	
D	
E	
F	
H	
I	
J	
K	
L	

# Chicago Public Schools

TEM Environmental, Inc.

## 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22801** BUIDLING ID: **2860**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Cook School** INSPECTION DATE: **8/16/2019**  
ADDRESS: **8150 S. Bishop** IDPH LICENSE NO: **100-07839**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **03**  
MATERIAL DESCRIPTION: **12" White Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Physical Damage**  
DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1925 Building- Room 102 & 112**  
MATERIAL QUANTITY: **2250** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **5** DAMAGE UNITS: **SF**  
COMMENTS: **Damage Rm. 112**

Inspector's Signature: \_\_\_\_\_ Date: **08/16/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22801** BUIDLING ID: **2860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Cook School** REVIEW DATE: **9/12/2019**  
ADDRESS: **8150 S. Bishop** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **03**  
MATERIAL DESCRIPTION: **12" White Floor Tile**  
MATERIAL LOCATION: **1925 Building- Room 102 & 112**  
MATERIAL QUANTITY: **2250** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **5** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/12/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **22801**    BUILDING ID: **2860**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Cook School**    INSPECTION DATE: **8/16/2019**  
ADDRESS: **8150 S. Bishop**    IDPH LICENSE NO: **100-07839**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **04**  
MATERIAL DESCRIPTION: **9x9 Beige Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON: **Physical Damage**  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile**    FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Physical Damage**  
DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1925 Building- Room 104**  
MATERIAL QUANTITY: **750**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **2**    DAMAGE UNITS: **SF**  
COMMENTS: **Damage is located in Room 104**

Inspector's Signature: \_\_\_\_\_ Date: **08/16/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22801** BUIDLING ID: **2860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Cook School** REVIEW DATE: **9/12/2019**  
ADDRESS: **8150 S. Bishop** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **04**  
MATERIAL DESCRIPTION: **9x9 Beige Floor Tile**  
MATERIAL LOCATION: **1925 Building- Room 104**  
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **2** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/12/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **22801**    BUILDING ID: **2860**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Cook School**    INSPECTION DATE: **8/16/2019**  
ADDRESS: **8150 S. Bishop**    IDPH LICENSE NO: **100-07839**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **05**  
MATERIAL DESCRIPTION: **12" Tan Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile**    FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1925 Building- Room 113**  
MATERIAL QUANTITY: **1150**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/16/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22801** BUIDLING ID: **2860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Cook School** REVIEW DATE: **9/12/2019**  
ADDRESS: **8150 S. Bishop** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **05**  
MATERIAL DESCRIPTION: **12" Tan Floor Tile**  
MATERIAL LOCATION: **1925 Building- Room 113**  
MATERIAL QUANTITY: **1150** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/12/2019**



# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22801** BUIDLING ID: **2860**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Cook School** INSPECTION DATE: **8/16/2019**  
ADDRESS: **8150 S. Bishop** IDPH LICENSE NO: **100-07839**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **07**  
MATERIAL DESCRIPTION: **12" Brown Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Physical Damage**  
DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 110 & 112**  
MATERIAL QUANTITY: **1950** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **10** DAMAGE UNITS: **SF**  
COMMENTS: **Damage located in Room 110/112**

Inspector's Signature: \_\_\_\_\_ Date: 08/16/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22801** BUIDLING ID: **2860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Cook School** REVIEW DATE: **9/12/2019**  
ADDRESS: **8150 S. Bishop** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **07**  
MATERIAL DESCRIPTION: **12" Brown Floor Tile**  
MATERIAL LOCATION: **Room 110 & 112**  
MATERIAL QUANTITY: **1950** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **10** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/12/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22801** BUIDLING ID: **2860**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Cook School** INSPECTION DATE: **8/16/2019**  
ADDRESS: **8150 S. Bishop** IDPH LICENSE NO: **100-07839**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **08**  
MATERIAL DESCRIPTION: **12x12 White Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1925 Building- Room 111**  
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/16/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22801** BUIDLING ID: **2860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Cook School** REVIEW DATE: **9/12/2019**  
ADDRESS: **8150 S. Bishop** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **08**  
MATERIAL DESCRIPTION: **12x12 White Floor Tile**  
MATERIAL LOCATION: **1925 Building- Room 111**  
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/12/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22801** BUIDLING ID: **2860**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Cook School** INSPECTION DATE: **8/16/2019**  
ADDRESS: **8150 S. Bishop** IDPH LICENSE NO: **100-07839**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **09**  
MATERIAL DESCRIPTION: **12" Brown Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1974 Building- Store Rooms, Eng. Office, 1st & 2nd Floor Corridors**  
MATERIAL QUANTITY: **3520** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/16/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22801** BUIDLING ID: **2860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Cook School** REVIEW DATE: **9/12/2019**  
ADDRESS: **8150 S. Bishop** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **09**  
MATERIAL DESCRIPTION: **12" Brown Floor Tile**  
MATERIAL LOCATION: **1974 Building- Store Rooms, Eng. Office, 1st & 2nd Floor Corridors**  
MATERIAL QUANTITY: **3520** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/12/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22801** BUIDLING ID: **2860**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Cook School** INSPECTION DATE: **8/16/2019**  
ADDRESS: **8150 S. Bishop** IDPH LICENSE NO: **100-07839**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12**  
MATERIAL DESCRIPTION: **12" Beige Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1974 Building- Room 224 & 228**  
MATERIAL QUANTITY: **1950** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/16/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22801** BUIDLING ID: **2860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Cook School** REVIEW DATE: **9/12/2019**  
ADDRESS: **8150 S. Bishop** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **12**  
MATERIAL DESCRIPTION: **12" Beige Floor Tile**  
MATERIAL LOCATION: **1974 Building- Room 224 & 228**  
MATERIAL QUANTITY: **1950** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/12/2019**



# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22801** BUIDLING ID: **2860**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Cook School** INSPECTION DATE: **8/16/2019**  
ADDRESS: **8150 S. Bishop** IDPH LICENSE NO: **100-07839**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14**  
MATERIAL DESCRIPTION: **12" White Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Physical Damage**  
DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1974 Building- Room 119, 121, Lunchroom, Teachers' Lunchroom & Corridor**  
MATERIAL QUANTITY: **5600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **25** DAMAGE UNITS: **SF**  
COMMENTS: **Lunchroom Damage**

Inspector's Signature: \_\_\_\_\_ Date: 08/16/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22801** BUIDLING ID: **2860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Cook School** REVIEW DATE: **9/12/2019**  
ADDRESS: **8150 S. Bishop** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **14**  
MATERIAL DESCRIPTION: **12" White Floor Tile**  
MATERIAL LOCATION: **1974 Building- Room 119, 121, Lunchroom, Teachers' Lunchroom & Corridor**  
MATERIAL QUANTITY: **5600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **25** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/12/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22801** BUIDLING ID: **2860**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Cook School** INSPECTION DATE: **8/16/2019**  
ADDRESS: **8150 S. Bishop** IDPH LICENSE NO: **100-07839**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16**  
MATERIAL DESCRIPTION: **Fire Doors**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1925 Building- Boiler Room, Boiler Room Tunnel**  
MATERIAL QUANTITY: **2** MATERIAL UNITS: **EA**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/16/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22801** BUIDLING ID: **2860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Cook School** REVIEW DATE: **9/12/2019**  
ADDRESS: **8150 S. Bishop** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **16**  
MATERIAL DESCRIPTION: **Fire Doors**  
MATERIAL LOCATION: **1925 Building- Boiler Room, Boiler Room Tunnel**  
MATERIAL QUANTITY: **2** MATERIAL UNITS: **EA**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/12/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22801** BUIDLING ID: **2860**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Cook School** INSPECTION DATE: **8/16/2019**  
ADDRESS: **8150 S. Bishop** IDPH LICENSE NO: **100-07839**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17**  
MATERIAL DESCRIPTION: **Boiler Room Gasket ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1925 Building- Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **08/16/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22801** BUILDING ID: **2860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Cook School** REVIEW DATE: **9/12/2019**  
ADDRESS: **8150 S. Bishop** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **17**

MATERIAL DESCRIPTION: **Boiler Room Gasket ABATED**

MATERIAL LOCATION: **1925 Building- Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/12/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22801** BUIDLING ID: **2860**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Cook School** INSPECTION DATE: **8/16/2019**  
ADDRESS: **8150 S. Bishop** IDPH LICENSE NO: **100-07839**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18**  
MATERIAL DESCRIPTION: **Transite Lab Tables**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1925 Building- Room 207**  
MATERIAL QUANTITY: **30** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS: **No Transite Table Tops Observed**

Inspector's Signature: \_\_\_\_\_ Date: 08/16/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22801** BUIDLING ID: **2860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Cook School** REVIEW DATE: **9/12/2019**  
ADDRESS: **8150 S. Bishop** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **18**  
MATERIAL DESCRIPTION: **Transite Lab Tables**  
MATERIAL LOCATION: **1925 Building- Room 207**  
MATERIAL QUANTITY: **30** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/12/2019**



# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **22801**    BUILDING ID: **2860**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Cook School**    INSPECTION DATE: **8/16/2019**  
ADDRESS: **8150 S. Bishop**    IDPH LICENSE NO: **100-07839**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19**  
MATERIAL DESCRIPTION: **Baseboard Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1925 Building- Rooms 115A, 216A, 1st Floor Boys' Toilet & Adjacent Corridor**  
MATERIAL QUANTITY: **70**    MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/16/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22801** BUIDLING ID: **2860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Cook School** REVIEW DATE: **9/12/2019**  
ADDRESS: **8150 S. Bishop** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **19**  
MATERIAL DESCRIPTION: **Baseboard Mastic**  
MATERIAL LOCATION: **1925 Building- Rooms 115A, 216A, 1st Floor Boys' Toilet & Adjacent Corridor**  
MATERIAL QUANTITY: **70** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/12/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22801** BUIDLING ID: **2860**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Cook School** INSPECTION DATE: **8/16/2019**  
ADDRESS: **8150 S. Bishop** IDPH LICENSE NO: **100-07839**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**  
MATERIAL DESCRIPTION: **Fire Doors**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1974 Building- Kitchen**  
MATERIAL QUANTITY: **2** MATERIAL UNITS: **EA**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/16/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22801** BUIDLING ID: **2860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Cook School** REVIEW DATE: **9/12/2019**  
ADDRESS: **8150 S. Bishop** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **20**  
MATERIAL DESCRIPTION: **Fire Doors**  
MATERIAL LOCATION: **1974 Building- Kitchen**  
MATERIAL QUANTITY: **2** MATERIAL UNITS: **EA**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/12/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22801** BUIDLING ID: **2860**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Cook School** INSPECTION DATE: **8/16/2019**  
ADDRESS: **8150 S. Bishop** IDPH LICENSE NO: **100-07839**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21**  
MATERIAL DESCRIPTION: **Baseboard Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout 1974 Building**  
MATERIAL QUANTITY: **2940** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/16/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22801** BUIDLING ID: **2860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Cook School** REVIEW DATE: **9/12/2019**  
ADDRESS: **8150 S. Bishop** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **21**  
MATERIAL DESCRIPTION: **Baseboard Mastic**  
MATERIAL LOCATION: **Throughout 1974 Building**  
MATERIAL QUANTITY: **2940** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/12/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22801** BUIDLING ID: **2860**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Cook School** INSPECTION DATE: **8/16/2019**  
ADDRESS: **8150 S. Bishop** IDPH LICENSE NO: **100-07839**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22**  
MATERIAL DESCRIPTION: **Baseboard**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1925 Building- Rooms 115A & 216A**  
MATERIAL QUANTITY: **70** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/16/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22801** BUIDLING ID: **2860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Cook School** REVIEW DATE: **9/12/2019**  
ADDRESS: **8150 S. Bishop** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **22**  
MATERIAL DESCRIPTION: **Baseboard**  
MATERIAL LOCATION: **1925 Building- Rooms 115A & 216A**  
MATERIAL QUANTITY: **70** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/12/2019**



# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22801** BUIDLING ID: **2860**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Cook School** INSPECTION DATE: **8/16/2019**  
ADDRESS: **8150 S. Bishop** IDPH LICENSE NO: **100-07839**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23**  
MATERIAL DESCRIPTION: **Baseboard**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Anthophyllite** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout 1974 Building**  
MATERIAL QUANTITY: **2940** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **08/16/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22801** BUIDLING ID: **2860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Cook School** REVIEW DATE: **9/12/2019**  
ADDRESS: **8150 S. Bishop** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **23**  
MATERIAL DESCRIPTION: **Baseboard**  
MATERIAL LOCATION: **Throughout 1974 Building**  
MATERIAL QUANTITY: **2940** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/12/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22801** BUIDLING ID: **2860**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Cook School** INSPECTION DATE: **8/16/2019**  
ADDRESS: **8150 S. Bishop** IDPH LICENSE NO: **100-07839**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **24**  
MATERIAL DESCRIPTION: **9" Beige Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON: **Physical Damage**  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Physical Damage**  
DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 104**  
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **2** DAMAGE UNITS: **SF**  
COMMENTS: **Damage is located in Room 104**

Inspector's Signature: \_\_\_\_\_ Date: **08/16/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22801** BUIDLING ID: **2860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Cook School** REVIEW DATE: **9/12/2019**  
ADDRESS: **8150 S. Bishop** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **24**  
MATERIAL DESCRIPTION: **9" Beige Floor Tile Mastic**  
MATERIAL LOCATION: **Room 104**  
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **2** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/12/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22801** BUIDLING ID: **2860**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Cook School** INSPECTION DATE: **8/16/2019**  
ADDRESS: **8150 S. Bishop** IDPH LICENSE NO: **100-07839**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25**  
MATERIAL DESCRIPTION: **12" Orange Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st & 2nd Floor Corridors**  
MATERIAL QUANTITY: **8650** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/16/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22801** BUIDLING ID: **2860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Cook School** REVIEW DATE: **9/12/2019**  
ADDRESS: **8150 S. Bishop** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **25**  
MATERIAL DESCRIPTION: **12" Orange Floor Tile Mastic**  
MATERIAL LOCATION: **1st & 2nd Floor Corridors**  
MATERIAL QUANTITY: **8650** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/12/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **22801**    BUILDING ID: **2860**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Cook School**    INSPECTION DATE: **8/16/2019**  
ADDRESS: **8150 S. Bishop**    IDPH LICENSE NO: **100-07839**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26**  
MATERIAL DESCRIPTION: **12" Brown Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile**    FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1925 Building- Room 110 & 112**  
MATERIAL QUANTITY: **1950**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/16/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22801** BUILDING ID: **2860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Cook School** REVIEW DATE: **9/12/2019**  
ADDRESS: **8150 S. Bishop** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **26**  
MATERIAL DESCRIPTION: **12" Brown Floor Tile Mastic**  
MATERIAL LOCATION: **1925 Building- Room 110 & 112**  
MATERIAL QUANTITY: **1950** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/12/2019**



# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **22801**    BUILDING ID: **2860**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Cook School**    INSPECTION DATE: **8/16/2019**  
ADDRESS: **8150 S. Bishop**    IDPH LICENSE NO: **100-07839**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27**  
MATERIAL DESCRIPTION: **12" White Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile**    FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1974 Building- Room 119, 121, Teachers' Lunchroom, Lunchroom & Corridor**  
MATERIAL QUANTITY: **5600**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/16/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22801** BUIDLING ID: **2860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Cook School** REVIEW DATE: **9/12/2019**  
ADDRESS: **8150 S. Bishop** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **27**  
MATERIAL DESCRIPTION: **12" White Floor Tile Mastic**  
MATERIAL LOCATION: **1974 Building- Room 119, 121, Teachers' Lunchroom, Lunchroom & Corridor**  
MATERIAL QUANTITY: **5600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/12/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22801** BUIDLING ID: **2860**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Cook School** INSPECTION DATE: **8/16/2019**  
ADDRESS: **8150 S. Bishop** IDPH LICENSE NO: **100-07839**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28**  
MATERIAL DESCRIPTION: **12" Brown Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1974 Building- Storerooms, Electrical Room, Engineer's Office, 1st & 2nd Floor Corridors**

MATERIAL QUANTITY: **3520** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/16/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22801** BUILDING ID: **2860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Cook School** REVIEW DATE: **9/12/2019**  
ADDRESS: **8150 S. Bishop** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **28**  
MATERIAL DESCRIPTION: **12" Brown Floor Tile Mastic**  
MATERIAL LOCATION: **1974 Building- Storerooms, Electrical Room, Engineer's Office, 1st & 2nd Floor Corridors**  
MATERIAL QUANTITY: **3520** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/12/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22801** BUIDLING ID: **2860**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Cook School** INSPECTION DATE: **8/16/2019**  
ADDRESS: **8150 S. Bishop** IDPH LICENSE NO: **100-07839**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **29**  
MATERIAL DESCRIPTION: **12" White Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1925 Building- Rooms 102 & 112**  
MATERIAL QUANTITY: **2250** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/16/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22801** BUIDLING ID: **2860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Cook School** REVIEW DATE: **9/12/2019**  
ADDRESS: **8150 S. Bishop** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **29**  
MATERIAL DESCRIPTION: **12" White Floor Tile Mastic**  
MATERIAL LOCATION: **1925 Building- Rooms 102 & 112**  
MATERIAL QUANTITY: **2250** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/12/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22801** BUIDLING ID: **2860**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Cook School** INSPECTION DATE: **8/16/2019**  
ADDRESS: **8150 S. Bishop** IDPH LICENSE NO: **100-07839**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **30**  
MATERIAL DESCRIPTION: **12" Tan Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1925 Building- Room 113**  
MATERIAL QUANTITY: **1150** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/16/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22801** BUIDLING ID: **2860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Cook School** REVIEW DATE: **9/12/2019**  
ADDRESS: **8150 S. Bishop** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **30**  
MATERIAL DESCRIPTION: **12" Tan Floor Tile Mastic**  
MATERIAL LOCATION: **1925 Building- Room 113**  
MATERIAL QUANTITY: **1150** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/12/2019**



# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22801** BUIDLING ID: **2860**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Cook School** INSPECTION DATE: **8/16/2019**  
ADDRESS: **8150 S. Bishop** IDPH LICENSE NO: **100-07839**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **31**  
MATERIAL DESCRIPTION: **12" Medium Brown Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1925 Building- Room 111,115A**  
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/16/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22801** BUIDLING ID: **2860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Cook School** REVIEW DATE: **9/12/2019**  
ADDRESS: **8150 S. Bishop** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **31**  
MATERIAL DESCRIPTION: **12" Medium Brown Floor Tile Mastic**  
MATERIAL LOCATION: **1925 Building- Room 111,115A**  
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/12/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22801** BUIDLING ID: **2860**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Cook School** INSPECTION DATE: **8/16/2019**  
ADDRESS: **8150 S. Bishop** IDPH LICENSE NO: **100-07839**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **32**  
MATERIAL DESCRIPTION: **12" Beige Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1974 Building- Rooms 224 & 228**  
MATERIAL QUANTITY: **1950** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/16/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22801** BUIDLING ID: **2860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Cook School** REVIEW DATE: **9/12/2019**  
ADDRESS: **8150 S. Bishop** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **32**  
MATERIAL DESCRIPTION: **12" Beige Floor Tile Mastic**  
MATERIAL LOCATION: **1974 Building- Rooms 224 & 228**  
MATERIAL QUANTITY: **1950** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/12/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **22801**    BUILDING ID: **2860**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Cook School**    INSPECTION DATE: **8/16/2019**  
ADDRESS: **8150 S. Bishop**    IDPH LICENSE NO: **100-07839**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **33**  
MATERIAL DESCRIPTION: **12" Purple Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1925 Building- Main Office, Principal's Office**  
MATERIAL QUANTITY: **420**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/16/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22801** BUILDING ID: **2860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Cook School** REVIEW DATE: **9/12/2019**  
ADDRESS: **8150 S. Bishop** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **33**  
MATERIAL DESCRIPTION: **12" Purple Floor Tile**  
MATERIAL LOCATION: **1925 Building- Main Office, Principal's Office**  
MATERIAL QUANTITY: **420** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/12/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22801** BUIDLING ID: **2860**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Cook School** INSPECTION DATE: **8/16/2019**  
ADDRESS: **8150 S. Bishop** IDPH LICENSE NO: **100-07839**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **34**  
MATERIAL DESCRIPTION: **12" Purple Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1925 Building- Main Office, Principal's Office**  
MATERIAL QUANTITY: **420** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/16/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22801** BUIDLING ID: **2860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Cook School** REVIEW DATE: **9/12/2019**  
ADDRESS: **8150 S. Bishop** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **34**  
MATERIAL DESCRIPTION: **12" Purple Floor Tile Mastic**  
MATERIAL LOCATION: **1925 Building- Main Office, Principal's Office**  
MATERIAL QUANTITY: **420** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/12/2019**



# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22801** BUIDLING ID: **2860**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Cook School** INSPECTION DATE: **8/16/2019**  
ADDRESS: **8150 S. Bishop** IDPH LICENSE NO: **100-07839**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **35**  
MATERIAL DESCRIPTION: **12" Tan Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1974 Annex Office**  
MATERIAL QUANTITY: **625** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/16/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22801** BUIDLING ID: **2860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Cook School** REVIEW DATE: **9/12/2019**  
ADDRESS: **8150 S. Bishop** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **35**  
MATERIAL DESCRIPTION: **12" Tan Floor Tile**  
MATERIAL LOCATION: **1974 Annex Office**  
MATERIAL QUANTITY: **625** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/12/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22801** BUIDLING ID: **2860**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Cook School** INSPECTION DATE: **8/16/2019**  
ADDRESS: **8150 S. Bishop** IDPH LICENSE NO: **100-07839**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **36**  
MATERIAL DESCRIPTION: **12" Tan Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1974 Annex Office**  
MATERIAL QUANTITY: **625** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/16/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22801** BUIDLING ID: **2860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Cook School** REVIEW DATE: **9/12/2019**  
ADDRESS: **8150 S. Bishop** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **36**  
MATERIAL DESCRIPTION: **12" Tan Floor Tile Mastic**  
MATERIAL LOCATION: **1974 Annex Office**  
MATERIAL QUANTITY: **625** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/12/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22801** BUIDLING ID: **2860**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Cook School** INSPECTION DATE: **8/16/2019**  
ADDRESS: **8150 S. Bishop** IDPH LICENSE NO: **100-07839**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37**  
MATERIAL DESCRIPTION: **Brown Linoleum**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1925 Building- Storeroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed 2019. Concrete Floors**

Inspector's Signature: \_\_\_\_\_ Date: **08/16/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22801** BUIDLING ID: **2860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Cook School** REVIEW DATE: **9/12/2019**  
ADDRESS: **8150 S. Bishop** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **37**

MATERIAL DESCRIPTION: **Brown Linoleum**

MATERIAL LOCATION: **1925 Building- Storeroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/12/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22801** BUILDING ID: **2860**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Cook School** INSPECTION DATE: **8/16/2019**  
ADDRESS: **8150 S. Bishop** IDPH LICENSE NO: **100-07839**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **38**  
MATERIAL DESCRIPTION: **Brown Linoleum Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1925 Building- Storeroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed 2019. Concrete Floors**

Inspector's Signature: \_\_\_\_\_ Date: **08/16/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22801** BUIDLING ID: **2860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Cook School** REVIEW DATE: **9/12/2019**  
ADDRESS: **8150 S. Bishop** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **38**

MATERIAL DESCRIPTION: **Brown Linoleum Mastic**

MATERIAL LOCATION: **1925 Building- Storeroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/12/2019**



# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22801** BUIDLING ID: **2860**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Cook School** INSPECTION DATE: **8/16/2019**  
ADDRESS: **8150 S. Bishop** IDPH LICENSE NO: **100-07839**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **39**  
MATERIAL DESCRIPTION: **Purple Carpet Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1925 Building- Main Office Storeroom**  
MATERIAL QUANTITY: **80** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/16/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22801** BUIDLING ID: **2860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Cook School** REVIEW DATE: **9/12/2019**  
ADDRESS: **8150 S. Bishop** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **39**  
MATERIAL DESCRIPTION: **Purple Carpet Mastic**  
MATERIAL LOCATION: **1925 Building- Main Office Storeroom**  
MATERIAL QUANTITY: **80** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/12/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22801** BUIDLING ID: **2860**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Cook School** INSPECTION DATE: **8/16/2019**  
ADDRESS: **8150 S. Bishop** IDPH LICENSE NO: **100-07839**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **40**  
MATERIAL DESCRIPTION: **Orange Carpet Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1925 Building- Teachers' Restroom & Room 218**  
MATERIAL QUANTITY: **1125** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/16/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22801** BUIDLING ID: **2860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Cook School** REVIEW DATE: **9/12/2019**  
ADDRESS: **8150 S. Bishop** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **40**  
MATERIAL DESCRIPTION: **Orange Carpet Mastic**  
MATERIAL LOCATION: **1925 Building- Teachers' Restroom & Room 218**  
MATERIAL QUANTITY: **1125** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/12/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22801** BUIDLING ID: **2860**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Cook School** INSPECTION DATE: **8/16/2019**  
ADDRESS: **8150 S. Bishop** IDPH LICENSE NO: **100-07839**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **41**  
MATERIAL DESCRIPTION: **Brown Carpet Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Principal's Office, Annex Office**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/16/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22801** BUIDLING ID: **2860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Cook School** REVIEW DATE: **9/12/2019**  
ADDRESS: **8150 S. Bishop** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **41**  
MATERIAL DESCRIPTION: **Brown Carpet Mastic**  
MATERIAL LOCATION: **Principal's Office, Annex Office**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/12/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22801** BUIDLING ID: **2860**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Cook School** INSPECTION DATE: **8/16/2019**  
ADDRESS: **8150 S. Bishop** IDPH LICENSE NO: **100-07839**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **42**  
MATERIAL DESCRIPTION: **Orange Carpet Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1974 Building- Rooms 120, 122, 124, 126, Storeroom & Library; Rooms 217, 219-223, 226, Teachers' Lounge, Library Office & AV Room**

MATERIAL QUANTITY: **6000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/16/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22801** BUIDLING ID: **2860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Cook School** REVIEW DATE: **9/12/2019**  
ADDRESS: **8150 S. Bishop** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **42**

MATERIAL DESCRIPTION: **Orange Carpet Mastic**

MATERIAL LOCATION: **1974 Building- Rooms 120, 122, 124, 126, Storeroom & Library; Rooms 217, 219-223, 226, Teachers' Lounge, Library Office & AV Room**

MATERIAL QUANTITY: **6000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/12/2019**



# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22801** BUIDLING ID: **2860**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Cook School** INSPECTION DATE: **8/16/2019**  
ADDRESS: **8150 S. Bishop** IDPH LICENSE NO: **100-07839**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **43**  
MATERIAL DESCRIPTION: **12x12 White Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1925 Building- Room 111**  
MATERIAL QUANTITY: **375** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/16/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22801** BUILDING ID: **2860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Cook School** REVIEW DATE: **9/12/2019**  
ADDRESS: **8150 S. Bishop** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **43**  
MATERIAL DESCRIPTION: **12x12 White Floor Tile**  
MATERIAL LOCATION: **1925 Building- Room 111**  
MATERIAL QUANTITY: **375** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/12/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22801** BUIDLING ID: **2860**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Cook School** INSPECTION DATE: **8/16/2019**  
ADDRESS: **8150 S. Bishop** IDPH LICENSE NO: **100-07839**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **44**  
MATERIAL DESCRIPTION: **Multicolor Carpet Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 218**  
MATERIAL QUANTITY: **1125** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/16/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22801** BUIDLING ID: **2860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Cook School** REVIEW DATE: **9/12/2019**  
ADDRESS: **8150 S. Bishop** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **44**  
MATERIAL DESCRIPTION: **Multicolor Carpet Adhesive**  
MATERIAL LOCATION: **Room 218**  
MATERIAL QUANTITY: **1125** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/12/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22801** BUIDLING ID: **2860**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Cook School** INSPECTION DATE: **8/16/2019**  
ADDRESS: **8150 S. Bishop** IDPH LICENSE NO: **100-07839**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **45**  
MATERIAL DESCRIPTION: **12x12 Tan w/Specks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 124, 126, 219 & 226**  
MATERIAL QUANTITY: **9000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/16/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22801** BUIDLING ID: **2860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Cook School** REVIEW DATE: **9/12/2019**  
ADDRESS: **8150 S. Bishop** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **45**  
MATERIAL DESCRIPTION: **12x12 Tan w/Specks Floor Tile**  
MATERIAL LOCATION: **Rooms 124, 126, 219 & 226**  
MATERIAL QUANTITY: **9000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/12/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **22801**    BUIDLING ID: **2860**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Cook School**    INSPECTION DATE: **8/16/2019**  
ADDRESS: **8150 S. Bishop**    IDPH LICENSE NO: **100-07839**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **46**  
MATERIAL DESCRIPTION: **Purple Carpet**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Library**  
MATERIAL QUANTITY: **2000**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/16/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22801** BUIDLING ID: **2860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Cook School** REVIEW DATE: **9/12/2019**  
ADDRESS: **8150 S. Bishop** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **46**  
MATERIAL DESCRIPTION: **Purple Carpet**  
MATERIAL LOCATION: **Library**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/12/2019**



# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22801** BUIDLING ID: **2860**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Cook School** INSPECTION DATE: **8/16/2019**  
ADDRESS: **8150 S. Bishop** IDPH LICENSE NO: **100-07839**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **47**  
MATERIAL DESCRIPTION: **2'x4' Ceiling Tile w/Chicken Scratch**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1925 Building- Throughout 1st & 2nd Corridors, and All Classrooms**  
MATERIAL QUANTITY: **25000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/16/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22801** BUIDLING ID: **2860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Cook School** REVIEW DATE: **9/12/2019**  
ADDRESS: **8150 S. Bishop** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **47**  
MATERIAL DESCRIPTION: **2'x4' Ceiling Tile w/Chicken Scratch**  
MATERIAL LOCATION: **1925 Building- Throughout 1st & 2nd Corridors, and All Classrooms**  
MATERIAL QUANTITY: **25000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/12/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **22801**    BUIDLING ID: **2860**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Cook School**    INSPECTION DATE: **8/16/2019**  
ADDRESS: **8150 S. Bishop**    IDPH LICENSE NO: **100-07839**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **48**  
MATERIAL DESCRIPTION: **Hard Coat Plaster**  
HISTORICAL AHERA DAMAGE CATEGORY **6 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout 1925 Building**  
MATERIAL QUANTITY: **37500**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/16/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22801** BUILDING ID: **2860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Cook School** REVIEW DATE: **9/12/2019**  
ADDRESS: **8150 S. Bishop** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **48**  
MATERIAL DESCRIPTION: **Hard Coat Plaster**  
MATERIAL LOCATION: **Throughout 1925 Building**  
MATERIAL QUANTITY: **37500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/12/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22801** BUIDLING ID: **2860**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Cook School** INSPECTION DATE: **8/16/2019**  
ADDRESS: **8150 S. Bishop** IDPH LICENSE NO: **100-07839**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **49**  
MATERIAL DESCRIPTION: **Hard Coat Plaster**  
HISTORICAL AHERA DAMAGE CATEGORY **6 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout 1974 Building**  
MATERIAL QUANTITY: **37500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/16/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22801** BUILDING ID: **2860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Cook School** REVIEW DATE: **9/12/2019**  
ADDRESS: **8150 S. Bishop** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **49**  
MATERIAL DESCRIPTION: **Hard Coat Plaster**  
MATERIAL LOCATION: **Throughout 1974 Building**  
MATERIAL QUANTITY: **37500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/12/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22801** BUIDLING ID: **2860**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Cook School** INSPECTION DATE: **8/16/2019**  
ADDRESS: **8150 S. Bishop** IDPH LICENSE NO: **100-07839**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **50**  
MATERIAL DESCRIPTION: **12x12 Dark Brown Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st Floor Restroom and Rooms 115B and 215B**  
MATERIAL QUANTITY: **474** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **08/16/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22801** BUIDLING ID: **2860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Cook School** REVIEW DATE: **9/12/2019**  
ADDRESS: **8150 S. Bishop** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **50**  
MATERIAL DESCRIPTION: **12x12 Dark Brown Floor Tile**  
MATERIAL LOCATION: **1st Floor Restroom and Rooms 115B and 215B**  
MATERIAL QUANTITY: **474** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/12/2019**



# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22801** BUIDLING ID: **2860**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Cook School** INSPECTION DATE: **8/16/2019**  
ADDRESS: **8150 S. Bishop** IDPH LICENSE NO: **100-07839**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **51**  
MATERIAL DESCRIPTION: **12x12 Dark Brown Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st Floor Restroom and Rooms 115B and 215B**  
MATERIAL QUANTITY: **474** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/16/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22801** BUIDLING ID: **2860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Cook School** REVIEW DATE: **9/12/2019**  
ADDRESS: **8150 S. Bishop** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **51**  
MATERIAL DESCRIPTION: **12x12 Dark Brown Floor Tile Mastic**  
MATERIAL LOCATION: **1st Floor Restroom and Rooms 115B and 215B**  
MATERIAL QUANTITY: **474** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/12/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22801** BUIDLING ID: **2860**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Cook School** INSPECTION DATE: **8/16/2019**  
ADDRESS: **8150 S. Bishop** IDPH LICENSE NO: **100-07839**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **52**  
MATERIAL DESCRIPTION: **1'x1' Acoustical Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 213 Chalk Board**  
MATERIAL QUANTITY: **38** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/16/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22801** BUIDLING ID: **2860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Cook School** REVIEW DATE: **9/12/2019**  
ADDRESS: **8150 S. Bishop** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **52**  
MATERIAL DESCRIPTION: **1'x1' Acoustical Ceiling Tile**  
MATERIAL LOCATION: **Room 213 Chalk Board**  
MATERIAL QUANTITY: **38** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/12/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22801** BUIDLING ID: **2860**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Cook School** INSPECTION DATE: **8/16/2019**  
ADDRESS: **8150 S. Bishop** IDPH LICENSE NO: **100-07839**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **53**  
MATERIAL DESCRIPTION: **1'x1' Acoustical Ceiling Tile Glue Dots**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 213 Chalk Board**  
MATERIAL QUANTITY: **38** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/16/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22801** BUIDLING ID: **2860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Cook School** REVIEW DATE: **9/12/2019**  
ADDRESS: **8150 S. Bishop** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **53**  
MATERIAL DESCRIPTION: **1'x1' Acoustical Ceiling Tile Glue Dots**  
MATERIAL LOCATION: **Room 213 Chalk Board**  
MATERIAL QUANTITY: **38** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/12/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22801** BUIDLING ID: **2860**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Cook School** INSPECTION DATE: **8/16/2019**  
ADDRESS: **8150 S. Bishop** IDPH LICENSE NO: **100-07839**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **54**  
MATERIAL DESCRIPTION: **12x12 Light Beige w/Tan Specks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 208**  
MATERIAL QUANTITY: **725** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/16/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22801** BUIDLING ID: **2860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Cook School** REVIEW DATE: **9/12/2019**  
ADDRESS: **8150 S. Bishop** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **54**  
MATERIAL DESCRIPTION: **12x12 Light Beige w/Tan Specks Floor Tile**  
MATERIAL LOCATION: **Room 208**  
MATERIAL QUANTITY: **725** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/12/2019**



# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **22801**    BUILDING ID: **2860**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Cook School**    INSPECTION DATE: **8/16/2019**  
ADDRESS: **8150 S. Bishop**    IDPH LICENSE NO: **100-07839**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **55**  
MATERIAL DESCRIPTION: **12x12 Light Beige w/Tan Specks Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 208**  
MATERIAL QUANTITY: **725**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/16/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22801** BUIDLING ID: **2860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Cook School** REVIEW DATE: **9/12/2019**  
ADDRESS: **8150 S. Bishop** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **55**  
MATERIAL DESCRIPTION: **12x12 Light Beige w/Tan Specks Floor Tile Mastic**  
MATERIAL LOCATION: **Room 208**  
MATERIAL QUANTITY: **725** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/12/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22801** BUILDING ID: **2860**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Cook School** INSPECTION DATE: **8/16/2019**  
ADDRESS: **8150 S. Bishop** IDPH LICENSE NO: **100-07839**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **A**  
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **1**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON: **Deterioration  
Delamination**  
DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1925 Building- Basement, Open Crawlspace**  
MATERIAL QUANTITY: MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **100** DAMAGE UNITS: **LF**  
COMMENTS: **Crawl Spaces;exposed ends, delaminated canvas wrap**

Inspector's Signature: \_\_\_\_\_ Date: 08/16/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22801** BUIDLING ID: **2860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Cook School** REVIEW DATE: **9/12/2019**  
ADDRESS: **8150 S. Bishop** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **A**  
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**  
MATERIAL LOCATION: **1925 Building- Basement, Open Crawlspace**  
MATERIAL QUANTITY: MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **100** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/12/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22801** BUIDLING ID: **2860**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Cook School** INSPECTION DATE: **8/16/2019**  
ADDRESS: **8150 S. Bishop** IDPH LICENSE NO: **100-07839**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **B**  
MATERIAL DESCRIPTION: **Paper Wrap Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1925 Building- Basement Crawlspace, Boys' & Girls Bathroom, Pipe Chases Throughout**

MATERIAL QUANTITY: **60** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/16/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22801** BUIDLING ID: **2860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Cook School** REVIEW DATE: **9/12/2019**  
ADDRESS: **8150 S. Bishop** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **B**  
MATERIAL DESCRIPTION: **Paper Wrap Pipe Insulation**  
MATERIAL LOCATION: **1925 Building- Basement Crawlspace, Boys' & Girls Bathroom, Pipe Chases Throughout**  
MATERIAL QUANTITY: **60** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/12/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22801** BUIDLING ID: **2860**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Cook School** INSPECTION DATE: **8/16/2019**  
ADDRESS: **8150 S. Bishop** IDPH LICENSE NO: **100-07839**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **D**  
MATERIAL DESCRIPTION: **Aircell Duct Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Wall, Crawlspace**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not Observed 2019**

Inspector's Signature: \_\_\_\_\_ Date: **08/16/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22801** BUIDLING ID: **2860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Cook School** REVIEW DATE: **9/12/2019**  
ADDRESS: **8150 S. Bishop** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **D**

MATERIAL DESCRIPTION: **Aircell Duct Insulation**

MATERIAL LOCATION: **Wall, Crawlspace**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/12/2019**



# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22801** BUIDLING ID: **2860**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Cook School** INSPECTION DATE: **8/16/2019**  
ADDRESS: **8150 S. Bishop** IDPH LICENSE NO: **100-07839**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **E**  
MATERIAL DESCRIPTION: **Tank Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Boiler Room**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/16/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22801** BUIDLING ID: **2860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Cook School** REVIEW DATE: **9/12/2019**  
ADDRESS: **8150 S. Bishop** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **E**  
MATERIAL DESCRIPTION: **Tank Insulation**  
MATERIAL LOCATION: **Boiler Room**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/12/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22801** BUIDLING ID: **2860**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Cook School** INSPECTION DATE: **8/16/2019**  
ADDRESS: **8150 S. Bishop** IDPH LICENSE NO: **100-07839**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **F**  
MATERIAL DESCRIPTION: **Fittings on Fiberglass**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1974 Building- Compactor Room**  
MATERIAL QUANTITY: **1** MATERIAL UNITS: **FITTING**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **FITTING**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/16/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22801** BUIDLING ID: **2860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Cook School** REVIEW DATE: **9/12/2019**  
ADDRESS: **8150 S. Bishop** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **F**  
MATERIAL DESCRIPTION: **Fittings on Fiberglass**  
MATERIAL LOCATION: **1974 Building- Compactor Room**  
MATERIAL QUANTITY: **1** MATERIAL UNITS: **FITTING**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **FITTING**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/12/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22801** BUIDLING ID: **2860**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Cook School** INSPECTION DATE: **8/16/2019**  
ADDRESS: **8150 S. Bishop** IDPH LICENSE NO: **100-07839**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **H**  
MATERIAL DESCRIPTION: **Fittings on Paper Wrap**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1925 Building- Basement Crawlspace, Boys' & Girls' Bathrooms, Pipe Chases Throughout Building**  
MATERIAL QUANTITY: **20** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/16/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22801** BUIDLING ID: **2860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Cook School** REVIEW DATE: **9/12/2019**  
ADDRESS: **8150 S. Bishop** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **H**  
MATERIAL DESCRIPTION: **Fittings on Paper Wrap**  
MATERIAL LOCATION: **1925 Building- Basement Crawlspace, Boys' & Girls' Bathrooms, Pipe Chases Throughout Building**  
MATERIAL QUANTITY: **20** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/12/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22801** BUIDLING ID: **2860**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Cook School** INSPECTION DATE: **8/16/2019**  
ADDRESS: **8150 S. Bishop** IDPH LICENSE NO: **100-07839**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **I**  
MATERIAL DESCRIPTION: **Fittings on Aircell**  
HISTORICAL AHERA DAMAGE CATEGORY **1**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON: **Physical Damage**  
DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1925 Building- Crawlspace**  
MATERIAL QUANTITY: MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **25** DAMAGE UNITS: **LF**  
COMMENTS: **Crawlspaces**

Inspector's Signature: \_\_\_\_\_ Date: 08/16/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22801** BUIDLING ID: **2860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Cook School** REVIEW DATE: **9/12/2019**  
ADDRESS: **8150 S. Bishop** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **I**  
MATERIAL DESCRIPTION: **Fittings on Aircell**  
MATERIAL LOCATION: **1925 Building- Crawlspace**  
MATERIAL QUANTITY: MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **25** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/12/2019**



# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22801** BUIDLING ID: **2860**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Cook School** INSPECTION DATE: **8/16/2019**  
ADDRESS: **8150 S. Bishop** IDPH LICENSE NO: **100-07839**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **J**  
MATERIAL DESCRIPTION: **Incinerator Insulation (Gone c1990)**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1925 Building- Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed 2019. Gone Since 1990**

Inspector's Signature: \_\_\_\_\_

Date: **08/16/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22801** BUIDLING ID: **2860**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Cook School** REVIEW DATE: **9/12/2019**  
ADDRESS: **8150 S. Bishop** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **J**  
MATERIAL DESCRIPTION: **Incinerator Insulation (Gone c1990)**  
MATERIAL LOCATION: **1925 Building- Boiler Room**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/12/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
*2019 AHERA REINSPECTION*

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **22801**      BUIDLING ID: **2860**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Cook School**      INSPECTION DATE: **8/16/2019**  
ADDRESS: **8150 S. Bishop**      IDPH LICENSE NO: **100-07839**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **K**

MATERIAL DESCRIPTION: **Whiteboard Mastic**

MATERIAL LOCATION: **Throughout**

MATERIAL QUANTITY: **750**      MATERIAL UNITS: **SF**

MATERIAL CATEGORY: **MISC**      FRIABLE:

ASBESTOS TYPE: **Assumed**

DISTURBANCE POTENTIAL: **LOW**      CONDITION:

AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**

ACCESSIBILITY: **Not Reachable**      DAMAGE REASON:

DAMAGE QUANTITY: **0**      DAMAGE REASON:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **08/16/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **22801**      BUILDING ID: **2860**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Cook School**      REVIEW DATE: **9/12/2019**  
ADDRESS: **8150 S. Bishop**      IDPH LICENSE NO: **100-07839**

HOMOGENEOUS AREA: **K**  
MATERIAL DESCRIPTION: **Whiteboard Mastic**  
MATERIAL LOCATION: **Throughout**  
MATERIAL QUANTITY: **750**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **09/12/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **22801**    BUILDING ID: **2860**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Cook School**    INSPECTION DATE: **8/16/2019**  
ADDRESS: **8150 S. Bishop**    IDPH LICENSE NO: **100-07839**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **L**  
MATERIAL DESCRIPTION: **Old Chalkboards**  
MATERIAL LOCATION: **Throughout School**  
MATERIAL QUANTITY: **4000**    MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**    FRIABLE:  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**    CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**    DAMAGE REASON:  
DAMAGE QUANTITY: **0**    DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **08/16/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **22801**      BUILDING ID: **2860**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Cook School**      REVIEW DATE: **9/12/2019**  
ADDRESS: **8150 S. Bishop**      IDPH LICENSE NO: **100-07839**

HOMOGENEOUS AREA: **L**  
MATERIAL DESCRIPTION: **Old Chalkboards**  
MATERIAL LOCATION: **Throughout School**  
MATERIAL QUANTITY: **4000**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **09/12/2019**

# APPENDIX B

## Inspector and Management Planner Licenses

---



2019



**OCCUPATIONAL TRAINING & SUPPLY, INC.**

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900 ♦ www.otssafety.com

# Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

**Lisa Laney**

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 4/5/2019

Exam Date: 4/5/2019

Expiration Date: 4/5/2020

Certificate Number: BIR1904051198

---

Kathy DeSalvo, Director

Miss Nancy

**Reliable**  
**Environmental**  
**Solutions, Inc.** **RES**

*This is to certify that* **Amy J. Williams**

*has on 04/03/19, in Springfield, Illinois,  
completed the requirements for asbestos accreditation under Section 206 of TSCA Title II*

**Asbestos Building Inspector Refresher Training**

*as accredited by the State of Illinois and approved by the U.S.E.P.A. under 40 CFR 763 (AHERA)  
and passed the associated examination with a score of 70% or higher*

Course Date: April 03, 2019

**COURSE LENGTH: 4 HOURS**

Examination Date: April 03, 2019

Expiration Date: April 03, 2020

*William S. Williams*

Certificate Number: BIR/0808

Training Program Manager, William S. Williams

4211 Westgate Drive, Springfield, Illinois ☐ 217.787.9800 ☐ 217.787.9801 FAX ☐ [www.ReliableEnv.com](http://www.ReliableEnv.com)



2539 Vandalia Street, Collinsville, IL 62234 \* Phone: 618-855-8764

Environmental and Occupational Safety & Health Training

*Does hereby certify*

**William Williams**

4211 Westgate Drive, Springfield, IL 62711

*Has successfully completed and passed the course examination with at least  
70% for re-accreditation under AHERA (Title II)*

**Asbestos Management Planner Refresher**


**Class Date:** 02/15/2019  
**Examination Date:** 02/15/2019  
**STC Certificate Number:** STC-20190215-000527AMPR  
**Certification Expiration:** 02/15/2020

David M. Mendoza – President/Training Director  
Certified Environmental Specialist  
OSHA Authorized Instructor

# COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License



## ASBESTOS PROFESSIONAL LICENSE

### ENDORSEMENTS

### TC EXPIRES

INSPECTOR

4/21/2019

ID NUMBER

ISSUED

EXPIRES

100 - 00746

4/11/2019

05/15/2020

MANAGEMENT PLANNER

4/21/2019

PROJECT MANAGER

4/2/2020


AIR SAMPLING PROFESSIONAL

**AMY J WILLIAMS**

1408 S CLAY

JACKSONVILLE, IL 62650

Environmental Health



**Alteration of this license shall result in legal action**  
This license issued under authority of the State of Illinois  
Department of Public Health  
This license is valid only when accompanied by a valid  
training course certificate.

# APPENDIX C

## Laboratory Accreditations

---

# APPENDIX D

## Laboratory Results

---

# APPENDIX E

## Chain of Custody Forms

---



## Three-Year Reinspection Key to Terms

	<b>CODE</b>	<b>KEY</b>
<b>MATERIAL</b>		
	ACBM	Asbestos Containing Building Materials
<b>MATERIAL CATEGORY</b>		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
<b>MATERIAL UNITS</b>		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
<b>DAMAGE TYPE</b>		
	Loc	Localized
	Dist	Distributed