

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM**

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-2153
SCHOOL NAME: Deneen School
ADDRESS OF SCHOOL: 7240 S. Wabash
CITY: Chicago, IL, 60619

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED 2/29/2016

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II (Please type or print)

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 10/1/2019 ENROLLMENT 491
IDPH INSPECTOR LICENSE NUMBER: 100-09106
IDPH LICENSED INSPECTOR NAME(Please Print): Michael Hasier
IDPH MP LICENSE NUMBER: 100-01784
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Steven Geneser

DESIGNATED PERSON (Please Print): Robert Christlieb PHONE: (773) 553-3197



10/1/2019

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Deneen School

7240 S. Wabash
Chicago, IL, 60619

Unit: 22931
Building ID: 3010

IDPH ID Number: 14-016-2990-2153

REPORT DATE:

Tuesday, October 01, 2019

Prepared for:

**Chicago Public Schools
42 West Madison Street
Chicago, IL 60602**

Prepared by:

TEM Environmental, Inc.

174 N. Brandon Drive

Glendale Heights, IL, 60139

Phone 630-790-0880

Fax 630-790-0882

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

Steven Geneser
100-01784

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: September 19, 2019

RE: Deneen School, Unit 22931
7240 S. Wabash
Chicago, IL, 60619

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2019 asbestos three year re-inspection has been completed at Deneen School, following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at Deneen School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Robert Christlieb, the designated Local Education Authority's Designated Person at (773) 553-3197 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Deneen School
Address: 7240 S. Wabash
IDPH ID: 14-016-2990-2153
Contact:

Unit: 22931
Chicago, IL, 60619
Building ID: 3010
Phone:

Region: 05

2. Description of Facility

Original Construction: 1955
Total Square Footage: 33076
Current Occupancy: 491

Additional Construction: 1958,1962,2005
No of Floors: 2

3. LEA Designated Person

Contact: Robert Christlieb
Address: 42 West Madison Street
Chicago, IL 60602

Phone: (773) 553-3197

4. Managing Environmental Consultant

MEC: TEM Environmental, Inc.
Contact: Steven Geneser
Address 174 N. Brandon Drive
Glendale Heights, IL, 60139
Phone: 630-790-0880

Fax: 630-790-0882

5. Inspector

Inspector Name: Michael Hasier

Inspector IDPH license # 100-09106

Signature:
Date: 9/19/2019

6. Management Planner

Management Planner Name: Steven Geneser

Management Planner IDPH license # 100-01784

Signature:
Date: 10/07/2019

7. Review Date:10/07/2019

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature:



Date: 10/1/2019

Name: Robert Christlieb

II. EXECUTIVE SUMMARY

TEM Environmental, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Deneen School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.85 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas(HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 3010:

B. The following new homogenous areas have been identified for Building 3010:

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

05	1 x 1 Acoustical Ceiling Tiles
06A	12 x 12 Blue Floor Tile
06B	12 x 12 White Floor Tile
14A	12x12 Blue Floor Tile
14B	12x12 White Floor Tile
15A	12x12 Blue Floor Tile Mastic
15B	12x12 White Floor Tile Mastic
18A	12x12 White Floor Tile
18B	12x12 Blue Floor Tile
19B	12x12 Blue Floor Tile Mastic
23	Wrap Around Duct Fiberglass
24	Wrap Around Breeching Fiberglass
33	Acoustic Plaster
36	Brown Coat Plaster
37	Acoustic Ceiling Plaster
38A	12 x 12 Blue Floor Tile Mastic
38B	12 x 12 White Floor Tile Mastic
39	Brown Coat Plaster
40	1 x 1 Acoustical Ceiling Tile Mastic
41	2'x4' Acoustical Ceiling Tiles
42A	12x12 Blue Floor Tile
42B	12x12 Blue Floor Tile Mastic
43A	12x12 Blue Floor Tile
43B	12x12 Blue Floor Tile Mastic
44	Blue/Gray Carpet Mastic
45	Brown Carpet Mastic
46	12" x 12" Light Green Vinyl Floor Tile
47	12" x 12" Light Green Vinyl Floor Tile Mastic
48	Tan Baseboard
49	Tan Baseboard Mastic
50	12" x 12" Yellow Vinyl Floor Tile
51	12" x 12" Light Beige Vinyl Floor Tile
52	Mastic Associated with HA 50 and HA 51
53	Green Baseboard
54	Green Baseboard Mastic
FT-1	12x12 Green Speckled Floor Tile
FT-2	12x12 Beige Floor Tile
FTM-1	12x12 Green Speckled Floor Tile Mastic
FTM-2	12x12 Beige Floor Tile Mastic

The following areas were deemed to be inaccessible:

15A	12x12 Blue Floor Tile Mastic
15B	12x12 White Floor Tile Mastic
19A	12x12 White Floor Tile Mastic
19B	12x12 Blue Floor Tile Mastic
40	1 x 1 Acoustical Ceiling Tile Mastic
44	Blue/Gray Carpet Mastic
45	Brown Carpet Mastic
47	12" x 12" Light Green Vinyl Floor Tile Mastic
49	Tan Baseboard Mastic
52	Mastic Associated with HA 50 and HA 51
54	Green Baseboard Mastic
FTM-1	12x12 Green Speckled Floor Tile Mastic
FTM-2	12x12 Beige Floor Tile Mastic

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Michael Hasier, IDPH License # 100-09106. The Management Plan was updated by Steven Geneser, IDPH License # 100-01784. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Deneen School Building 3010 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. Atimely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Deneen School **Unit** 22931 **Building ID** 3010

Address 7240 S. Wabash **Region** 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
03	2 x 2 Drop Ceiling Tile			1953 Building-Lobby and Gym	NO_ACBM									
04	1 x 1 Acoustical Ceiling Tiles			1953 Building-Lunchroom & Kitchen	NO_ACBM									
05	1 x 1 Acoustical Ceiling Tiles	600	SF	1953 Building-Lobby	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
06A	12 x 12 Blue Floor Tile	4,675	SF	1962 Addition-Rooms 116, 117, 118, 119, 120, Teachers Lounge (115)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
06B	12 x 12 White Floor Tile	2,640	SF	1962 Addition- 1st & 2nd Floor Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
09	Vinyl Mopboard			1953 Building-Classrooms & Lunchroom	NO_ACBM									
10	Vinyl Mopboard Mastic			1953 Building-Classrooms & Lunchroom	NO_ACBM									
12	9x9 Tan Floor Tile			1953 Building-Room 200	CHR	MISC	N				No	ACBM with the potential for damage		
13	9x9 Tan Floor Tile Mastic			1953 Building-Room 200	CHR	MISC	N	None			No	ACBM with the potential for damage		Low
14A	12x12 Blue Floor Tile	11,200	SF	1953 Building-School Offices, Rooms 104, 103, 105, 109, 202, 203, 204, 205, 206, 207, 208, 209	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
14B	12x12 White Floor Tile	5,400	SF	1953 Building- 1st & 2nd Floor Corridors, Rm. 200	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
15A	12x12 Blue Floor Tile Mastic	11,200	SF	1953 Building-School Offices, Rooms 104, 103, 105, 109, 202, 203, 204, 205, 206, 207, 208, 209	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
15B	12x12 White Floor Tile Mastic	8,825	SF	1953 Building- 1st & 2nd Floor Corridors and Rooms 106, 107, 108	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Deneen School **Unit** 22931 **Building ID** 3010

Address 7240 S. Wabash **Region** 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
18A	12x12 White Floor Tile	3,850	SF	1958 Building- 1st & 2nd Floor Corridors	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
18B	12x12 Blue Floor Tile	4,660	SF	1958 Building- Rooms 112, 114, 210, 212, 214	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
19A	12x12 White Floor Tile Mastic	3,850	SF	1958 Building- 1st & 2nd Floor Corridors	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
19B	12x12 Blue Floor Tile Mastic	4,660	SF	1958 Building- Rooms 112, 114, 210, 212, 214	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
22	Vibration Gasket			1953 Building- Fan Room	NO_ACBM									
23	Wrap Around Duct Fiberglass	275	LF	Boiler Room	ASSUMED	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
24	Wrap Around Breeching Fiberglass	150	LF	Boiler Room	ASSUMED	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
25	Boiler Gasket ABATED			Boiler Room	ABATED	MISC								
26	Baseboard			1958 Building- Rooms 210A, 210B, 212, 214, 110, 112, 114	NO_ACBM									
27	Baseboard Mastic			1958 Building- Rooms 210A, 210B, 212, 214, 110, 112, 114	NO_ACBM									
28	Baseboard			1962 Building- Rooms 116, 117, 118, 119, 120, 216, 218, 219, 220	NO_ACBM									
29	Baseboard Mastic			1962 Building- Rooms 116, 117, 118, 119, 120, 216, 218, 219, 220	NO_ACBM									
32	Acoustic Ceiling			1958 Building- Corridors	NO_ACBM	SURFACE								
33	Acoustic Plaster	5,300	SF	1962 Building- Rooms 116, 117, 118, 119, 120, teachers lounge, 218, 220	ASSUMED	SURFACE	N	NONE			No	ACBM with the potential for damage		MODERATE
34	Acoustic Plaster	1,390	SF	1958 Building- Room 110	CHR	SURFACE	Y	NONE	0		No	Any remaining friable ACBM or friable		LOW

Chicago Public Schools

School Deneen School **Unit** 22931 **Building ID** 3010

Address 7240 S. Wabash **Region** 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
												suspect ACBM		
36	Brown Coat Plaster	7,900	SF	1958 Building-Corridors/Ceiling	ASSUMED	SURFACE	N	NONE	0		No	ACBM with the potential for damage		LOW
37	Acoustic Ceiling Plaster	1,260	SF	1962 Building- 1st & 2nd Floor Corridors	ASSUMED	SURFACE	N	NONE	0		No	ACBM with potential for significant damage		LOW
38A	12 x 12 Blue Floor Tile Mastic	4,755	SF	1962 Addition-Rooms 116, 117, 118, 119, 120, Teachers Lounge (115), Engineer's Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
38B	12 x 12 White Floor Tile Mastic	2,640	SF	1962 Addition- 1st & 2nd Floor Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
39	Brown Coat Plaster	1,260	SF	1962 Addition- 1st & 2nd Floor Corridors	ASSUMED	SURFACE	Y				No	ACBM with the potential for damage		LOW
40	1 x 1 Acoustical Ceiling Tile Mastic	2,650	SF	1953 Building-Kitchen & Lunchroom	ASSUMED	MISC	N				No	ACBM with the potential for damage		LOW
41	2'x4' Acoustical Ceiling Tiles	2,400	SF	1953 Building-Lunchroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
42A	12x12 Blue Floor Tile	4,413	SF	1953 Building-Rooms 104, 106, 108	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
42B	12x12 Blue Floor Tile Mastic	4,413	SF	1953 Building - Rooms 104, 106, 108	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
43A	12x12 Blue Floor Tile	1,471	SF	1958 Building-Room 110	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
43B	12x12 Blue Floor Tile Mastic	1,471	SF	1958 Building-Room 110	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
44	Blue/Gray Carpet Mastic	384	SF	Old Building- Room 102	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
45	Brown Carpet Mastic	2,000	SF	2007 Building- Main Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
46	12" x 12" Light Green Vinyl Floor Tile	7,892	SF	2007 Building-Cafeteria, Rooms 160, 201, 263, 252, 256	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
47	12" x 12" Light Green Vinyl Floor Tile Mastic	7,892	SF	2007 Building-Cafeteria, Rooms 160, 201, 263, 252,	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Deneen School Unit 22931 Building ID 3010

Address 7240 S. Wabash Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
48	Tan Baseboard	312	LF	256 2007 Building- Cafeteria, Rooms 160, 201, 263, 252, 256	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
49	Tan Baseboard Mastic	312	LF	2007 Building- Cafeteria, Rooms 160, 201, 263, 252, 256	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
50	12" x 12" Yellow Vinyl Floot Tile	225	SF	2007 Building- Cafeteria, Rooms 160, 261, 263, 252	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
51	12" x 12" Light Beige Vinyl Floor Tile	225	SF	2007 Building- Cafeteria, Rooms 160, 261, 263, 252	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
52	Mastic Associated with HA 50 and HA 51	450	SF	2007 Building- Cafeteria, Rooms 160, 261, 263, 252	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
53	Green Baseboard	224	LF	2007 Building- Room 256 (Library)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
54	Green Baseboard Mastic	224	LF	2007 Building- Room 256 (Library)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
A	Aircell Pipe Insulation ABATED			1953 Building- Air Tunnel, Crawlspace (Abated)	ABATED	TSI								
B	MJP Fittings ABATED			1953 Building- Air Tunnels, Crawlspace (Abated)	ABATED	TSI		None						
C	Fittings on Fiberglass Runs ABATED		Fittings	1962 Building- Pipe Chases, Crawlspace (Abated)	ABATED	TSI		None						
E	Aircell Pipe Insulation ABATED			1958 Addition- Crawlspace (Abated)	ABATED	TSI		None						
F	Cardboard Pipe Insulation ABATED			1958 Addition- Crawlspace (Abated)	ABATED	TSI		None						
FT-1	12x12 Green Speckled Floor Tile	250	SF	Room 200 & 100	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FT-2	12x12 Beige Floor Tile	85	SF	Room 217	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FTM-1	12x12 Green Speckled Floor Tile Mastic	250	SF	Room 200 & 100	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FTM-2	12x12 Beige Floor Tile Mastic	85	SF	Room 217	ASSUMED	MISC	N	NONE	0		No	ACBM with the		LOW

Chicago Public Schools

School Deneen School **Unit** 22931 **Building ID** 3010

Address 7240 S. Wabash **Region** 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
												potential for damage		
G	Fittings on Fiberglass Runs ABATED			1958 Addition- (Abated)	ABATED	TSI		None						
H	Fittings on Fberglass Runs ABATED		Fittings	1962 Building- Crawlspace (Abated)	ABATED	TSI								
I	Aircell Pipe Fittings ABATED		Fittings	1953 Building- Air Tunnel, Crawlspace, Corridor (Abated)	ABATED	TSI								
J	Cardboard Pipe Fittings ABATED		Fittings	1953 Building- Air Tunnels (Abated)	ABATED	TSI								
K	Aircell Pipe Joint ABATED		Fittings	1958 Building- Crawlspace (Abated)	ABATED	TSI								
L	Cardboard Joint Fittings ABATED		Fittings	1958 Addition- Crawlspace (Abated)	ABATED	TSI								

Chicago Public Schools

School Deneen School Unit 22931 Building ID 3010

Address 7240 S. Wabash Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

Reinspection Date	<u>9/19/2019</u>
Inspector Name	<u>Michael Hasier</u>
<u>100-09106</u>	<u>5/15/2020</u>
Inspector's IDPH License Number / Expiration Date	

Inspector's Comments

HA Number:	Inspector Comments:
03	
04	
05	
06A	
06B	
09	
10	
12	Not Observed 2019
13	Not Observed 2019
14A	
14B	
15A	
15B	
18A	
18B	
19A	
19B	
22	
23	
24	
25	
26	
27	

Chicago Public Schools

School Deneen School **Unit** 22931 **Building ID** 3010

Address 7240 S. Wabash **Region** 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
28	
29	
32	
33	
34	
36	
37	
38A	
38B	
39	Not Observed 2019
40	Not Observed 2019
41	
42A	
42B	
43A	
43B	
44	
45	
46	
47	
48	
49	
50	
51	
52	
53	
54	
A	
B	

Chicago Public Schools

School Deneen School **Unit** 22931 **Building ID** 3010
Address 7240 S. Wabash **Region** 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
C	
E	
F	
FT-1	
FT-2	
FTM-1	
FTM-2	
G	
H	
I	
J	
K	
L	

Table II

Management Planner's Review

Chicago Public Schools

School Deneen School

Unit 22931

Building ID 3010

Address 7240 S. Wabash

Chicago, IL, 60619

Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
03	2 x 2 Drop Ceiling Tile			1953 Building- Lobby and Gym	No ACBM						
04	1 x 1 Acoustical Ceiling Tiles			1953 Building- Lunchroom & Kitchen	No ACBM						
05	1 x 1 Acoustical Ceiling Tiles	600	SF	1953 Building- Lobby	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
06A	12 x 12 Blue Floor Tile	4,675	SF	1962 Addition- Rooms 116, 117, 118, 119, 120, Teachers Lounge (115)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
06B	12 x 12 White Floor Tile	2,640	SF	1962 Addition- 1st & 2nd Floor Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
09	Vinyl Mopboard			1953 Building- Classrooms & Lunchroom	No ACBM						
10	Vinyl Mopboard Mastic			1953 Building- Classrooms & Lunchroom	No ACBM						
12	9x9 Tan Floor Tile			1953 Building- Room 200	Chrysotile	MISC	No			6 ACBM with the potential for damage	Follow O&M Plan
13	9x9 Tan Floor Tile Mastic			1953 Building- Room 200	Chrysotile	MISC	No			6 ACBM with the potential for damage	Follow O&M Plan
14A	12x12 Blue Floor Tile	11,200	SF	1953 Building- School Offices, Rooms 104, 103, 105, 109, 202, 203, 204, 205, 206, 207, 208, 209	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
14B	12x12 White Floor Tile	5,400	SF	1953 Building- 1st & 2nd Floor Corridors, Rm. 200	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
15A	12x12 Blue Floor Tile Mastic	11,200	SF	1953 Building- School Offices, Rooms 104, 103, 105, 109, 202, 203, 204, 205, 206, 207, 208, 209	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
15B	12x12 White Floor Tile Mastic	8,825	SF	1953 Building- 1st & 2nd Floor Corridors and Rooms 106, 107, 108	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
18A	12x12 White Floor Tile	3,850	SF	1958 Building- 1st & 2nd Floor Corridors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
18B	12x12 Blue Floor Tile	4,660	SF	1958 Building- Rooms 112, 114, 210, 212, 214	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
19A	12x12 White Floor Tile Mastic	3,850	SF	1958 Building- 1st & 2nd Floor Corridors	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
19B	12x12 Blue Floor Tile Mastic	4,660	SF	1958 Building- Rooms 112, 114, 210, 212, 214	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
22	Vibration Gasket			1953 Building- Fan Room	No ACBM						
23	Wrap Around Duct Fiberglass	275	LF	Boiler Room	Assumed	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
24	Wrap Around Breeching Fiberglass	150	LF	Boiler Room	Assumed	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
25	Boiler Gasket ABATED			Boiler Room	Abated	MISC					

Chicago Public Schools

School Deneen School

Unit 22931

Building ID 3010

Address 7240 S. Wabash

Chicago, IL, 60619

Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
26	Baseboard			1958 Building- Rooms 210A, 210B, 212, 214, 110, 112, 114	No ACBM						
27	Baseboard Mastic			1958 Building- Rooms 210A, 210B, 212, 214, 110, 112, 114	No ACBM						
28	Baseboard			1962 Building- Rooms 116, 117, 118, 119, 120, 216, 218, 219, 220	No ACBM						
29	Baseboard Mastic			1962 Building- Rooms 116, 117, 118, 119, 120, 216, 218, 219, 220	No ACBM						
32	Acoustic Ceiling			1958 Building- Corridors	No ACBM	SURFACE					
33	Acoustic Plaster	5,300	SF	1962 Building- Rooms 116, 117, 118, 119, 120, teachers lounge, 218, 220	Assumed	SURFACE	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
34	Acoustic Plaster	1,390	SF	1958 Building- Room 110	Chrysotile	SURFACE	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
36	Brown Coat Plaster	7,900	SF	1958 Building- Corridors/Ceiling	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
37	Acoustic Ceiling Plaster	1,260	SF	1962 Building- 1st & 2nd Floor Corridors	Assumed	SURFACE	No	0	SF	5 ACBM with potential for significant damage	Follow O&M Plan
38A	12 x 12 Blue Floor Tile Mastic	4,755	SF	1962 Addition- Rooms 116, 117, 118, 119, 120, Teachers Lounge (115), Engineer's Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
38B	12 x 12 White Floor Ttile Mastic	2,640	SF	1962 Addition- 1st & 2nd Floor Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
39	Brown Coat Plaster	1,260	SF	1962 Addition- 1st & 2nd Floor Corridors	Assumed	SURFACE	Yes		SF	6 ACBM with the potential for damage	Follow O&M Plan
40	1 x 1 Acoustical Ceiling Tile Mastic	2,650	SF	1953 Building- Kitchen & Lunchroom	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
41	2'x4' Acoustical Ceiling Tiles	2,400	SF	1953 Building- Lunchroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
42A	12x12 Blue Floor Tile	4,413	SF	1953 Building- Rooms 104, 106, 108	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
42B	12x12 Blue Floor Tile Mastic	4,413	SF	1953 Building - Rooms 104, 106, 108	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
43A	12x12 Blue Floor Tile	1,471	SF	1958 Building- Room 110	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
43B	12x12 Blue Floor Tile Mastic	1,471	SF	1958 Building- Room 110	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
44	Blue/Gray Carpet Mastic	384	SF	Old Building- Room 102	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
45	Brown Carpet Mastic	2,000	SF	2007 Building- Main Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
46	12" x 12" Light Green Vinyl Floor Tile	7,892	SF	2007 Building- Cafeteria, Rooms 160, 201, 263, 252, 256	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
47	12" x 12" Light Green Vinyl Floor Tile Mastic	7,892	SF	2007 Building- Cafeteria, Rooms 160, 201, 263, 252, 256	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Deneen School

Unit 22931

Building ID 3010

Address 7240 S. Wabash

Chicago, IL, 60619

Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
48	Tan Baseboard	312	LF	2007 Building- Cafeteria, Rooms 160, 201, 263, 252, 256	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
49	Tan Baseboard Mastic	312	LF	2007 Building- Cafeteria, Rooms 160, 201, 263, 252, 256	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
50	12" x 12" Yellow Vinyl Floot Tile	225	SF	2007 Building- Cafeteria, Rooms 160, 261, 263, 252	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
51	12" x 12" Light Beige Vinyl Floor Tile	225	SF	2007 Building- Cafeteria, Rooms 160, 261, 263, 252	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
52	Mastic Associated with HA 50 and HA 51	450	SF	2007 Building- Cafeteria, Rooms 160, 261, 263, 252	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
53	Green Baseboard	224	LF	2007 Building- Room 256 (Library)	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
54	Green Baseboard Mastic	224	LF	2007 Building- Room 256 (Library)	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
A	Aircell Pipe Insulation ABATED			1953 Building- Air Tunnel, Crawlspace (Abated)	Abated	TSI					
B	MJP Fittings ABATED			1953 Building- Air Tunnels, Crawlspace (Abated)	Abated	TSI					
C	Fittings on Fiberglass Runs ABATED		Fittings	1962 Building- Pipe Chases, Crawlspace (Abated)	Abated	TSI			Fittings		
E	Aircell Pipe Insulation ABATED			1958 Addition- Crawlspace (Abated)	Abated	TSI					
F	Cardboard Pipe Insulation ABATED			1958 Addition- Crawlspace (Abated)	Abated	TSI					
FT-1	12x12 Green Speckled Floor Tile	250	SF	Room 200 & 100	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FT-2	12x12 Beige Floor Tile	85	SF	Room 217	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FTM-1	12x12 Green Speckled Floor Tile Mastic	250	SF	Room 200 & 100	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FTM-2	12x12 Beige Floor Tile Mastic	85	SF	Room 217	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
G	Fittings on Fiberglass Runs ABATED			1958 Addition- (Abated)	Abated	TSI					
H	Fittings on Fberglass Runs ABATED		Fittings	1962 Building- Crawlspace (Abated)	Abated	TSI			Fittings		
I	Aircell Pipe Fittings ABATED		Fittings	1953 Building- Air Tunnel, Crawlspace, Corridor (Abated)	Abated	TSI			Fittings		
J	Cardboard Pipe Fittings ABATED		Fittings	1953 Building- Air Tunnels (Abated)	Abated	TSI			Fittings		
K	Aircell Pipe Joint ABATED		Fittings	1958 Building- Crawlspace (Abated)	Abated	TSI			Fittings		
L	Cardboard Joint Fittings ABATED		Fittings	1958 Addition- Crawlspace (Abated)	Abated	TSI			Fittings		

Chicago Public Schools

School Deneen School

Unit 22931

Building ID 3010

Address 7240 S. Wabash

Chicago, IL, 60619

Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.
174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

Review Date	10/07/2019
Manager Planner Name	Steven Geneser
100-01784	5/15/2020
Manager IDPH License No/Expiration	

HA Number	Management Comments
03	
04	
05	
06A	
06B	
09	
10	
12	

Chicago Public Schools

School Deneen School

Unit 22931

Building ID 3010

Address 7240 S. Wabash

Chicago, IL, 60619

Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.
174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
13	
14A	
14B	
15A	
15B	
18A	
18B	
19A	
19B	
22	
23	
24	
25	
26	
27	
28	
29	
32	
33	
34	
36	
37	
38A	
38B	
39	
40	

Chicago Public Schools

School Deneen School

Unit 22931

Building ID 3010

Address 7240 S. Wabash

Chicago, IL, 60619

Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.
174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
41	
42A	
42B	
43A	
43B	
44	
45	
46	
47	
48	
49	
50	
51	
52	
53	
54	
A	
B	
C	
E	
F	
FT-1	
FT-2	
FTM-1	
FTM-2	
G	

Chicago Public Schools

School Deneen School

Unit 22931

Building ID 3010

Address 7240 S. Wabash

Chicago, IL, 60619

Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.
174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
H	
I	
J	
K	
L	

Chicago Public Schools

TEM Environmental, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Deneen School	INSPECTION DATE:	9/19/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	03	
MATERIAL DESCRIPTION:	2 x 2 Drop Ceiling Tile	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1953 Building- Lobby and Gym

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 09/19/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Deneen School	REVIEW DATE:	10/7/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

HOMOGENEOUS AREA: **03**

MATERIAL DESCRIPTION: **2 x 2 Drop Ceiling Tile**

MATERIAL LOCATION: **1953 Building- Lobby and Gym**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/07/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Deneen School	INSPECTION DATE:	9/19/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	04	
MATERIAL DESCRIPTION:	1 x 1 Acoustical Ceiling Tiles	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1953 Building- Lunchroom & Kitchen

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 09/19/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Deneen School	REVIEW DATE:	10/7/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

HOMOGENEOUS AREA: **04**

MATERIAL DESCRIPTION: **1 x 1 Acoustical Ceiling Tiles**

MATERIAL LOCATION: **1953 Building- Lunchroom & Kitchen**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/07/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Deneen School	INSPECTION DATE:	9/19/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	05		
MATERIAL DESCRIPTION:	1 x 1 Acoustical Ceiling Tiles		
HISTORICAL AHERA DAMAGE CATEGORY	6 Any remaining friable ACM or friable suspect ACM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1953 Building- Lobby		
MATERIAL QUANTITY:	600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/19/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Deneen School	REVIEW DATE:	10/7/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

HOMOGENEOUS AREA:	05		
MATERIAL DESCRIPTION:	1 x 1 Acoustical Ceiling Tiles		
MATERIAL LOCATION:	1953 Building- Lobby		
MATERIAL QUANTITY:	600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/07/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Deneen School	INSPECTION DATE:	9/19/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	06A		
MATERIAL DESCRIPTION:	12 x 12 Blue Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1962 Addition- Rooms 116, 117, 118, 119, 120, Teachers Lounge (115)		
MATERIAL QUANTITY:	4675	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/19/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Deneen School	REVIEW DATE:	10/7/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

HOMOGENEOUS AREA:	06A		
MATERIAL DESCRIPTION:	12 x 12 Blue Floor Tile		
MATERIAL LOCATION:	1962 Addition- Rooms 116, 117, 118, 119, 120, Teachers Lounge (115)		
MATERIAL QUANTITY:	4675	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 10/07/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Deneen School	INSPECTION DATE:	9/19/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	06B		
MATERIAL DESCRIPTION:	12 x 12 White Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1962 Addition- 1st & 2nd Floor Corridor		
MATERIAL QUANTITY:	2640	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/19/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Deneen School	REVIEW DATE:	10/7/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

HOMOGENEOUS AREA:	06B				
MATERIAL DESCRIPTION:	12 x 12 White Floor Tile				
MATERIAL LOCATION:	1962 Addition- 1st & 2nd Floor Corridor				
MATERIAL QUANTITY:	2640	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 10/07/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Deneen School	INSPECTION DATE:	9/19/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	09	
MATERIAL DESCRIPTION:	Vinyl Mopboard	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1953 Building- Classrooms & Lunchroom

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 09/19/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Deneen School	REVIEW DATE:	10/7/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

HOMOGENEOUS AREA: **09**

MATERIAL DESCRIPTION: **Vinyl Mopboard**

MATERIAL LOCATION: **1953 Building- Classrooms & Lunchroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/07/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Deneen School	INSPECTION DATE:	9/19/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	10	
MATERIAL DESCRIPTION:	Vinyl Mopboard Mastic	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1953 Building- Classrooms & Lunchroom

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 09/19/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Deneen School	REVIEW DATE:	10/7/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

HOMOGENEOUS AREA: **10**

MATERIAL DESCRIPTION: **Vinyl Mopboard Mastic**

MATERIAL LOCATION: **1953 Building- Classrooms & Lunchroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/07/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Deneen School	INSPECTION DATE:	9/19/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	12		
MATERIAL DESCRIPTION:	9x9 Tan Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1953 Building- Room 200**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed 2019**

Inspector's Signature: _____ Date: **09/19/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Deneen School	REVIEW DATE:	10/7/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

HOMOGENEOUS AREA: **12**

MATERIAL DESCRIPTION: **9x9 Tan Floor Tile**

MATERIAL LOCATION: **1953 Building- Room 200**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/07/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Deneen School	INSPECTION DATE:	9/19/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	13		
MATERIAL DESCRIPTION:	9x9 Tan Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **1953 Building- Room 200**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed 2019**

Inspector's Signature: _____ Date: **09/19/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Deneen School	REVIEW DATE:	10/7/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

HOMOGENEOUS AREA: **13**

MATERIAL DESCRIPTION: **9x9 Tan Floor Tile Mastic**

MATERIAL LOCATION: **1953 Building- Room 200**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/07/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Deneen School	INSPECTION DATE:	9/19/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	14A		
MATERIAL DESCRIPTION:	12x12 Blue Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1953 Building- School Offices, Rooms 104, 103, 105, 109, 202, 203, 204, 205, 206, 207, 208, 209		
MATERIAL QUANTITY:	11200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/19/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Deneen School	REVIEW DATE:	10/7/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

HOMOGENEOUS AREA:	14A				
MATERIAL DESCRIPTION:	12x12 Blue Floor Tile				
MATERIAL LOCATION:	1953 Building- School Offices, Rooms 104, 103, 105, 109, 202, 203, 204, 205, 206, 207, 208, 209				
MATERIAL QUANTITY:	11200	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 10/07/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Deneen School	INSPECTION DATE:	9/19/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	14B		
MATERIAL DESCRIPTION:	12x12 White Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1953 Building- 1st & 2nd Floor Corridors, Rm. 200		
MATERIAL QUANTITY:	5400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/19/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Deneen School	REVIEW DATE:	10/7/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

HOMOGENEOUS AREA:	14B		
MATERIAL DESCRIPTION:	12x12 White Floor Tile		
MATERIAL LOCATION:	1953 Building- 1st & 2nd Floor Corridors, Rm. 200		
MATERIAL QUANTITY:	5400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/07/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Deneen School	INSPECTION DATE:	9/19/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	15A		
MATERIAL DESCRIPTION:	12x12 Blue Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1953 Building- School Offices, Rooms 104, 103, 105, 109, 202, 203, 204, 205, 206, 207, 208, 209		
MATERIAL QUANTITY:	11200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/19/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Deneen School	REVIEW DATE:	10/7/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

HOMOGENEOUS AREA:	15A				
MATERIAL DESCRIPTION:	12x12 Blue Floor Tile Mastic				
MATERIAL LOCATION:	1953 Building- School Offices, Rooms 104, 103, 105, 109, 202, 203, 204, 205, 206, 207, 208, 209				
MATERIAL QUANTITY:	11200	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 10/07/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Deneen School	INSPECTION DATE:	9/19/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	15B		
MATERIAL DESCRIPTION:	12x12 White Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1953 Building- 1st & 2nd Floor Corridors and Rooms 106, 107, 108		
MATERIAL QUANTITY:	8825	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/19/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Deneen School	REVIEW DATE:	10/7/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

HOMOGENEOUS AREA:	15B		
MATERIAL DESCRIPTION:	12x12 White Floor Tile Mastic		
MATERIAL LOCATION:	1953 Building- 1st & 2nd Floor Corridors and Rooms 106, 107, 108		
MATERIAL QUANTITY:	8825	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/07/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Deneen School	INSPECTION DATE:	9/19/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	18A		
MATERIAL DESCRIPTION:	12x12 White Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1958 Building- 1st & 2nd Floor Corridors		
MATERIAL QUANTITY:	3850	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/19/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Deneen School	REVIEW DATE:	10/7/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

HOMOGENEOUS AREA:	18A				
MATERIAL DESCRIPTION:	12x12 White Floor Tile				
MATERIAL LOCATION:	1958 Building- 1st & 2nd Floor Corridors				
MATERIAL QUANTITY:	3850	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 10/07/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Deneen School	INSPECTION DATE:	9/19/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	18B		
MATERIAL DESCRIPTION:	12x12 Blue Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1958 Building- Rooms 112, 114, 210, 212, 214		
MATERIAL QUANTITY:	4660	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/19/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Deneen School	REVIEW DATE:	10/7/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

HOMOGENEOUS AREA:	18B				
MATERIAL DESCRIPTION:	12x12 Blue Floor Tile				
MATERIAL LOCATION:	1958 Building- Rooms 112, 114, 210, 212, 214				
MATERIAL QUANTITY:	4660	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 10/07/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Deneen School	INSPECTION DATE:	9/19/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	19A		
MATERIAL DESCRIPTION:	12x12 White Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1958 Building- 1st & 2nd Floor Corridors		
MATERIAL QUANTITY:	3850	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/19/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Deneen School	REVIEW DATE:	10/7/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

HOMOGENEOUS AREA:	19A				
MATERIAL DESCRIPTION:	12x12 White Floor Tile Mastic				
MATERIAL LOCATION:	1958 Building- 1st & 2nd Floor Corridors				
MATERIAL QUANTITY:	3850	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 10/07/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Deneen School	INSPECTION DATE:	9/19/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	19B		
MATERIAL DESCRIPTION:	12x12 Blue Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1958 Building- Rooms 112, 114, 210, 212, 214		
MATERIAL QUANTITY:	4660	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/19/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Deneen School	REVIEW DATE:	10/7/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

HOMOGENEOUS AREA:	19B				
MATERIAL DESCRIPTION:	12x12 Blue Floor Tile Mastic				
MATERIAL LOCATION:	1958 Building- Rooms 112, 114, 210, 212, 214				
MATERIAL QUANTITY:	4660	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 10/07/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Deneen School	INSPECTION DATE:	9/19/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	22	
MATERIAL DESCRIPTION:	Vibration Gasket	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1953 Building- Fan Room

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 09/19/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Deneen School	REVIEW DATE:	10/7/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

HOMOGENEOUS AREA: **22**

MATERIAL DESCRIPTION: **Vibration Gasket**

MATERIAL LOCATION: **1953 Building- Fan Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/07/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Deneen School	INSPECTION DATE:	9/19/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	23		
MATERIAL DESCRIPTION:	Wrap Around Duct Fiberglass		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Boiler Room		
MATERIAL QUANTITY:	275	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature: _____ Date: 09/19/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Deneen School	REVIEW DATE:	10/7/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

HOMOGENEOUS AREA:	23		
MATERIAL DESCRIPTION:	Wrap Around Duct Fiberglass		
MATERIAL LOCATION:	Boiler Room		
MATERIAL QUANTITY:	275	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 10/07/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Deneen School	INSPECTION DATE:	9/19/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	24		
MATERIAL DESCRIPTION:	Wrap Around Breeching Fiberglass		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Boiler Room		
MATERIAL QUANTITY:	150	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature: _____ Date: 09/19/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Deneen School	REVIEW DATE:	10/7/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

HOMOGENEOUS AREA: **24**

MATERIAL DESCRIPTION: **Wrap Around Breeching Fiberglass**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:	150	MATERIAL UNITS:	LF
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/07/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Deneen School	INSPECTION DATE:	9/19/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	25	
MATERIAL DESCRIPTION:	Boiler Gasket ABATED	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Abated	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Boiler Room

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 09/19/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Deneen School	REVIEW DATE:	10/7/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

HOMOGENEOUS AREA: **25**

MATERIAL DESCRIPTION: **Boiler Gasket ABATED**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/07/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Deneen School	INSPECTION DATE:	9/19/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	26	
MATERIAL DESCRIPTION:	Baseboard	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1958 Building- Rooms 210A, 210B, 212, 214, 110, 112, 114

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 09/19/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Deneen School	REVIEW DATE:	10/7/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

HOMOGENEOUS AREA: **26**

MATERIAL DESCRIPTION: **Baseboard**

MATERIAL LOCATION: **1958 Building- Rooms 210A, 210B, 212, 214, 110, 112, 114**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/07/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Deneen School	INSPECTION DATE:	9/19/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	27	
MATERIAL DESCRIPTION:	Baseboard Mastic	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1958 Building- Rooms 210A, 210B, 212, 214, 110, 112, 114

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 09/19/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Deneen School	REVIEW DATE:	10/7/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

HOMOGENEOUS AREA: **27**

MATERIAL DESCRIPTION: **Baseboard Mastic**

MATERIAL LOCATION: **1958 Building- Rooms 210A, 210B, 212, 214, 110, 112, 114**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/07/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Deneen School	INSPECTION DATE:	9/19/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	28	
MATERIAL DESCRIPTION:	Baseboard	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1962 Building- Rooms 116, 117, 118, 119, 120, 216, 218, 219, 220

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 09/19/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Deneen School	REVIEW DATE:	10/7/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

HOMOGENEOUS AREA: **28**

MATERIAL DESCRIPTION: **Baseboard**

MATERIAL LOCATION: **1962 Building- Rooms 116, 117, 118, 119, 120, 216, 218, 219, 220**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/07/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Deneen School	INSPECTION DATE:	9/19/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	29	
MATERIAL DESCRIPTION:	Baseboard Mastic	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1962 Building- Rooms 116, 117, 118, 119, 120, 216, 218, 219, 220

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 09/19/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Deneen School	REVIEW DATE:	10/7/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

HOMOGENEOUS AREA: **29**

MATERIAL DESCRIPTION: **Baseboard Mastic**

MATERIAL LOCATION: **1962 Building- Rooms 116, 117, 118, 119, 120, 216, 218, 219, 220**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/07/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Deneen School	INSPECTION DATE:	9/19/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	32	
MATERIAL DESCRIPTION:	Acoustic Ceiling	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1958 Building- Corridors

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 09/19/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Deneen School	REVIEW DATE:	10/7/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

HOMOGENEOUS AREA: **32**

MATERIAL DESCRIPTION: **Acoustic Ceiling**

MATERIAL LOCATION: **1958 Building- Corridors**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/07/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Deneen School	INSPECTION DATE:	9/19/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	33		
MATERIAL DESCRIPTION:	Acoustic Plaster		
HISTORICAL AHERA DAMAGE CATEGORY	6		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	1962 Building- Rooms 116, 117, 118, 119, 120, teachers lounge, 218, 220		
MATERIAL QUANTITY:	5300	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/19/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Deneen School	REVIEW DATE:	10/7/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

HOMOGENEOUS AREA:	33		
MATERIAL DESCRIPTION:	Acoustic Plaster		
MATERIAL LOCATION:	1962 Building- Rooms 116, 117, 118, 119, 120, teachers lounge, 218, 220		
MATERIAL QUANTITY:	5300	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/07/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Deneen School	INSPECTION DATE:	9/19/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	34		
MATERIAL DESCRIPTION:	Acoustic Plaster		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1958 Building- Room 110		
MATERIAL QUANTITY:	1390	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/19/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Deneen School	REVIEW DATE:	10/7/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

HOMOGENEOUS AREA:	34		
MATERIAL DESCRIPTION:	Acoustic Plaster		
MATERIAL LOCATION:	1958 Building- Room 110		
MATERIAL QUANTITY:	1390	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 10/07/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Deneen School	INSPECTION DATE:	9/19/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	36		
MATERIAL DESCRIPTION:	Brown Coat Plaster		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1958 Building- Corridors/Ceiling		
MATERIAL QUANTITY:	7900	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/19/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Deneen School	REVIEW DATE:	10/7/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

HOMOGENEOUS AREA:	36		
MATERIAL DESCRIPTION:	Brown Coat Plaster		
MATERIAL LOCATION:	1958 Building- Corridors/Ceiling		
MATERIAL QUANTITY:	7900	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/07/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Deneen School	INSPECTION DATE:	9/19/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	37		
MATERIAL DESCRIPTION:	Acoustic Ceiling Plaster		
HISTORICAL AHERA DAMAGE CATEGORY	5 ACBM with potential for significant damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1962 Building- 1st & 2nd Floor Corridors		
MATERIAL QUANTITY:	1260	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/19/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Deneen School	REVIEW DATE:	10/7/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

HOMOGENEOUS AREA:	37		
MATERIAL DESCRIPTION:	Acoustic Ceiling Plaster		
MATERIAL LOCATION:	1962 Building- 1st & 2nd Floor Corridors		
MATERIAL QUANTITY:	1260	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 10/07/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Deneen School	INSPECTION DATE:	9/19/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	38A		
MATERIAL DESCRIPTION:	12 x 12 Blue Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1962 Addition- Rooms 116, 117, 118, 119, 120, Teachers Lounge (115), Engineer's Office		
MATERIAL QUANTITY:	4755	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/19/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Deneen School	REVIEW DATE:	10/7/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

HOMOGENEOUS AREA:	38A				
MATERIAL DESCRIPTION:	12 x 12 Blue Floor Tile Mastic				
MATERIAL LOCATION:	1962 Addition- Rooms 116, 117, 118, 119, 120, Teachers Lounge (115), Engineer's Office				
MATERIAL QUANTITY:	4755	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 10/07/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Deneen School	INSPECTION DATE:	9/19/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	38B		
MATERIAL DESCRIPTION:	12 x 12 White Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1962 Addition- 1st & 2nd Floor Corridor		
MATERIAL QUANTITY:	2640	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/19/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Deneen School	REVIEW DATE:	10/7/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

HOMOGENEOUS AREA:	38B				
MATERIAL DESCRIPTION:	12 x 12 White Floor Tile Mastic				
MATERIAL LOCATION:	1962 Addition- 1st & 2nd Floor Corridor				
MATERIAL QUANTITY:	2640	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 10/07/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Deneen School	INSPECTION DATE:	9/19/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	39		
MATERIAL DESCRIPTION:	Brown Coat Plaster		
HISTORICAL AHERA DAMAGE CATEGORY	6		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1962 Addition- 1st & 2nd Floor Corridors		
MATERIAL QUANTITY:	1260	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Not Observed 2019		

Inspector's Signature: _____ Date: 09/19/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Deneen School	REVIEW DATE:	10/7/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

HOMOGENEOUS AREA: **39**

MATERIAL DESCRIPTION: **Brown Coat Plaster**

MATERIAL LOCATION: **1962 Addition- 1st & 2nd Floor Corridors**

MATERIAL QUANTITY: **1260**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/07/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Deneen School	INSPECTION DATE:	9/19/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	40		
MATERIAL DESCRIPTION:	1 x 1 Acoustical Ceiling Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1953 Building- Kitchen & Lunchroom		
MATERIAL QUANTITY:	2650	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Not Observed 2019		

Inspector's Signature: _____ Date: 09/19/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Deneen School	REVIEW DATE:	10/7/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

HOMOGENEOUS AREA:	40		
MATERIAL DESCRIPTION:	1 x 1 Acoustical Ceiling Tile Mastic		
MATERIAL LOCATION:	1953 Building- Kitchen & Lunchroom		
MATERIAL QUANTITY:	2650	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 10/07/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Deneen School	INSPECTION DATE:	9/19/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	41		
MATERIAL DESCRIPTION:	2'x4' Acoustical Ceiling Tiles		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1953 Building- Lunchroom		
MATERIAL QUANTITY:	2400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/19/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Deneen School	REVIEW DATE:	10/7/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

HOMOGENEOUS AREA:	41		
MATERIAL DESCRIPTION:	2'x4' Acoustical Ceiling Tiles		
MATERIAL LOCATION:	1953 Building- Lunchroom		
MATERIAL QUANTITY:	2400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 10/07/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Deneen School	INSPECTION DATE:	9/19/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	42A		
MATERIAL DESCRIPTION:	12x12 Blue Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1953 Building- Rooms 104, 106, 108		
MATERIAL QUANTITY:	4413	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/19/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Deneen School	REVIEW DATE:	10/7/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

HOMOGENEOUS AREA:	42A		
MATERIAL DESCRIPTION:	12x12 Blue Floor Tile		
MATERIAL LOCATION:	1953 Building- Rooms 104, 106, 108		
MATERIAL QUANTITY:	4413	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 10/07/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Deneen School	INSPECTION DATE:	9/19/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	42B		
MATERIAL DESCRIPTION:	12x12 Blue Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1953 Building - Rooms 104, 106, 108		
MATERIAL QUANTITY:	4413	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/19/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Deneen School	REVIEW DATE:	10/7/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

HOMOGENEOUS AREA:	42B				
MATERIAL DESCRIPTION:	12x12 Blue Floor Tile Mastic				
MATERIAL LOCATION:	1953 Building - Rooms 104, 106, 108				
MATERIAL QUANTITY:	4413	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 10/07/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Deneen School	INSPECTION DATE:	9/19/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	43A		
MATERIAL DESCRIPTION:	12x12 Blue Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1958 Building- Room 110		
MATERIAL QUANTITY:	1471	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/19/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Deneen School	REVIEW DATE:	10/7/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

HOMOGENEOUS AREA:	43A				
MATERIAL DESCRIPTION:	12x12 Blue Floor Tile				
MATERIAL LOCATION:	1958 Building- Room 110				
MATERIAL QUANTITY:	1471	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 10/07/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Deneen School	INSPECTION DATE:	9/19/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	43B		
MATERIAL DESCRIPTION:	12x12 Blue Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1958 Building- Room 110		
MATERIAL QUANTITY:	1471	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/19/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Deneen School	REVIEW DATE:	10/7/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

HOMOGENEOUS AREA:	43B				
MATERIAL DESCRIPTION:	12x12 Blue Floor Tile Mastic				
MATERIAL LOCATION:	1958 Building- Room 110				
MATERIAL QUANTITY:	1471	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 10/07/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Deneen School	INSPECTION DATE:	9/19/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	44		
MATERIAL DESCRIPTION:	Blue/Gray Carpet Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Old Building- Room 102		
MATERIAL QUANTITY:	384	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/19/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Deneen School	REVIEW DATE:	10/7/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

HOMOGENEOUS AREA:	44		
MATERIAL DESCRIPTION:	Blue/Gray Carpet Mastic		
MATERIAL LOCATION:	Old Building- Room 102		
MATERIAL QUANTITY:	384	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 10/07/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Deneen School	INSPECTION DATE:	9/19/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	45		
MATERIAL DESCRIPTION:	Brown Carpet Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	2007 Building- Main Office		
MATERIAL QUANTITY:	2000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/19/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Deneen School	REVIEW DATE:	10/7/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

HOMOGENEOUS AREA:	45		
MATERIAL DESCRIPTION:	Brown Carpet Mastic		
MATERIAL LOCATION:	2007 Building- Main Office		
MATERIAL QUANTITY:	2000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/07/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Deneen School	INSPECTION DATE:	9/19/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	46		
MATERIAL DESCRIPTION:	12" x 12" Light Green Vinyl Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	2007 Building- Cafeteria, Rooms 160, 201, 263, 252, 256		
MATERIAL QUANTITY:	7892	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/19/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Deneen School	REVIEW DATE:	10/7/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

HOMOGENEOUS AREA:	46		
MATERIAL DESCRIPTION:	12" x 12" Light Green Vinyl Floor Tile		
MATERIAL LOCATION:	2007 Building- Cafeteria, Rooms 160, 201, 263, 252, 256		
MATERIAL QUANTITY:	7892	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 10/07/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Deneen School	INSPECTION DATE:	9/19/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	47		
MATERIAL DESCRIPTION:	12" x 12" Light Green Vinyl Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	2007 Building- Cafeteria, Rooms 160, 201, 263, 252, 256		
MATERIAL QUANTITY:	7892	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/19/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Deneen School	REVIEW DATE:	10/7/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

HOMOGENEOUS AREA:	47				
MATERIAL DESCRIPTION:	12" x 12" Light Green Vinyl Floor Tile Mastic				
MATERIAL LOCATION:	2007 Building- Cafeteria, Rooms 160, 201, 263, 252, 256				
MATERIAL QUANTITY:	7892	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 10/07/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Deneen School	INSPECTION DATE:	9/19/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	48		
MATERIAL DESCRIPTION:	Tan Baseboard		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	2007 Building- Cafeteria, Rooms 160, 201, 263, 252, 256		
MATERIAL QUANTITY:	312	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature: _____ Date: 09/19/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Deneen School	REVIEW DATE:	10/7/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

HOMOGENEOUS AREA:	48		
MATERIAL DESCRIPTION:	Tan Baseboard		
MATERIAL LOCATION:	2007 Building- Cafeteria, Rooms 160, 201, 263, 252, 256		
MATERIAL QUANTITY:	312	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 10/07/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Deneen School	INSPECTION DATE:	9/19/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	49		
MATERIAL DESCRIPTION:	Tan Baseboard Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	2007 Building- Cafeteria, Rooms 160, 201, 263, 252, 256		
MATERIAL QUANTITY:	312	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature: _____ Date: 09/19/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Deneen School	REVIEW DATE:	10/7/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

HOMOGENEOUS AREA: 49

MATERIAL DESCRIPTION: Tan Baseboard Mastic

MATERIAL LOCATION: 2007 Building- Cafeteria, Rooms 160, 201, 263, 252, 256

MATERIAL QUANTITY:	312	MATERIAL UNITS:	LF
--------------------	-----	-----------------	----

DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF
------------------	---	---------------	----

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 10/07/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Deneen School	INSPECTION DATE:	9/19/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	50		
MATERIAL DESCRIPTION:	12" x 12" Yellow Vinyl Floom Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	2007 Building- Cafeteria, Rooms 160, 261, 263, 252		
MATERIAL QUANTITY:	225	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/19/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Deneen School	REVIEW DATE:	10/7/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

HOMOGENEOUS AREA:	50		
MATERIAL DESCRIPTION:	12" x 12" Yellow Vinyl Floom Tile		
MATERIAL LOCATION:	2007 Building- Cafeteria, Rooms 160, 261, 263, 252		
MATERIAL QUANTITY:	225	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 10/07/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Deneen School	INSPECTION DATE:	9/19/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	51		
MATERIAL DESCRIPTION:	12" x 12" Light Beige Vinyl Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	2007 Building- Cafeteria, Rooms 160, 261, 263, 252		
MATERIAL QUANTITY:	225	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/19/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Deneen School	REVIEW DATE:	10/7/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

HOMOGENEOUS AREA:	51				
MATERIAL DESCRIPTION:	12" x 12" Light Beige Vinyl Floor Tile				
MATERIAL LOCATION:	2007 Building- Cafeteria, Rooms 160, 261, 263, 252				
MATERIAL QUANTITY:	225	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 10/07/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Deneen School	INSPECTION DATE:	9/19/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	52		
MATERIAL DESCRIPTION:	Mastic Associated with HA 50 and HA 51		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	2007 Building- Cafeteria, Rooms 160, 261, 263, 252		
MATERIAL QUANTITY:	450	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/19/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Deneen School	REVIEW DATE:	10/7/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

HOMOGENEOUS AREA:	52				
MATERIAL DESCRIPTION:	Mastic Associated with HA 50 and HA 51				
MATERIAL LOCATION:	2007 Building- Cafeteria, Rooms 160, 261, 263, 252				
MATERIAL QUANTITY:	450	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 10/07/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Deneen School	INSPECTION DATE:	9/19/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	53		
MATERIAL DESCRIPTION:	Green Baseboard		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	2007 Building- Room 256 (Library)		
MATERIAL QUANTITY:	224	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature: _____ Date: 09/19/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Deneen School	REVIEW DATE:	10/7/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

HOMOGENEOUS AREA: **53**

MATERIAL DESCRIPTION: **Green Baseboard**

MATERIAL LOCATION: **2007 Building- Room 256 (Library)**

MATERIAL QUANTITY:	224	MATERIAL UNITS:	LF
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/07/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Deneen School	INSPECTION DATE:	9/19/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	54		
MATERIAL DESCRIPTION:	Green Baseboard Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	2007 Building- Room 256 (Library)		
MATERIAL QUANTITY:	224	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature: _____ Date: 09/19/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Deneen School	REVIEW DATE:	10/7/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

HOMOGENEOUS AREA:	54		
MATERIAL DESCRIPTION:	Green Baseboard Mastic		
MATERIAL LOCATION:	2007 Building- Room 256 (Library)		
MATERIAL QUANTITY:	224	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 10/07/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Deneen School	INSPECTION DATE:	9/19/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	A	
MATERIAL DESCRIPTION:	Aircell Pipe Insulation ABATED	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Abated	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1953 Building- Air Tunnel, Crawlspace (Abated)

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 09/19/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Deneen School	REVIEW DATE:	10/7/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

HOMOGENEOUS AREA: **A**

MATERIAL DESCRIPTION: **Aircell Pipe Insulation ABATED**

MATERIAL LOCATION: **1953 Building- Air Tunnel, Crawlspace (Abated)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/07/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Deneen School	INSPECTION DATE:	9/19/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	B	
MATERIAL DESCRIPTION:	MJP Fittings ABATED	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Abated	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1953 Building- Air Tunnels, Crawlspace (Abated)

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 09/19/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Deneen School	REVIEW DATE:	10/7/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

HOMOGENEOUS AREA: **B**

MATERIAL DESCRIPTION: **MJP Fittings ABATED**

MATERIAL LOCATION: **1953 Building- Air Tunnels, Crawlspace (Abated)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/07/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Deneen School	INSPECTION DATE:	9/19/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	C	
MATERIAL DESCRIPTION:	Fittings on Fiberglass Runs ABATED	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Abated	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1962 Building- Pipe Chases, Crawlspace (Abated)

MATERIAL QUANTITY:		MATERIAL UNITS:	Fittings
--------------------	--	-----------------	----------

DAMAGE QUANTITY:		DAMAGE UNITS:	Fittings
------------------	--	---------------	----------

COMMENTS:

Inspector's Signature:	_____	Date:	09/19/2019
------------------------	-------	-------	------------

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Deneen School	REVIEW DATE:	10/7/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

HOMOGENEOUS AREA: **C**

MATERIAL DESCRIPTION: **Fittings on Fiberglass Runs ABATED**

MATERIAL LOCATION: **1962 Building- Pipe Chases, Crawlspace (Abated)**

MATERIAL QUANTITY:		MATERIAL UNITS:	Fittings
--------------------	--	-----------------	-----------------

DAMAGE QUANTITY:		DAMAGE UNITS:	Fittings
------------------	--	---------------	-----------------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/07/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Deneen School	INSPECTION DATE:	9/19/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	E	
MATERIAL DESCRIPTION:	Aircell Pipe Insulation ABATED	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Abated	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1958 Addition- Crawlspace (Abated)

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 09/19/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Deneen School	REVIEW DATE:	10/7/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

HOMOGENEOUS AREA: **E**

MATERIAL DESCRIPTION: **Aircell Pipe Insulation ABATED**

MATERIAL LOCATION: **1958 Addition- Crawlspace (Abated)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/07/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Deneen School	INSPECTION DATE:	9/19/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	F	
MATERIAL DESCRIPTION:	Cardboard Pipe Insulation ABATED	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Abated	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1958 Addition- Crawlspace (Abated)

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 09/19/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Deneen School	REVIEW DATE:	10/7/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

HOMOGENEOUS AREA: **F**

MATERIAL DESCRIPTION: **Cardboard Pipe Insulation ABATED**

MATERIAL LOCATION: **1958 Addition- Crawlspace (Abated)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/07/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Deneen School	INSPECTION DATE:	9/19/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	FT-1		
MATERIAL DESCRIPTION:	12x12 Green Speckled Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 200 & 100		
MATERIAL QUANTITY:	250	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/19/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Deneen School	REVIEW DATE:	10/7/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

HOMOGENEOUS AREA:	FT-1				
MATERIAL DESCRIPTION:	12x12 Green Speckled Floor Tile				
MATERIAL LOCATION:	Room 200 & 100				
MATERIAL QUANTITY:	250	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/07/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Deneen School	INSPECTION DATE:	9/19/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	FT-2		
MATERIAL DESCRIPTION:	12x12 Beige Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 217		
MATERIAL QUANTITY:	85	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/19/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Deneen School	REVIEW DATE:	10/7/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

HOMOGENEOUS AREA: **FT-2**

MATERIAL DESCRIPTION: **12x12 Beige Floor Tile**

MATERIAL LOCATION: **Room 217**

MATERIAL QUANTITY: **85**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/07/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Deneen School	INSPECTION DATE:	9/19/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	FTM-1		
MATERIAL DESCRIPTION:	12x12 Green Speckled Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 200 & 100		
MATERIAL QUANTITY:	250	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/19/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Deneen School	REVIEW DATE:	10/7/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

HOMOGENEOUS AREA: **FTM-1**

MATERIAL DESCRIPTION: **12x12 Green Speckled Floor Tile Mastic**

MATERIAL LOCATION: **Room 200 & 100**

MATERIAL QUANTITY:	250	MATERIAL UNITS:	SF
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/07/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Deneen School	INSPECTION DATE:	9/19/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	FTM-2		
MATERIAL DESCRIPTION:	12x12 Beige Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 217		
MATERIAL QUANTITY:	85	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/19/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Deneen School	REVIEW DATE:	10/7/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

HOMOGENEOUS AREA:	FTM-2				
MATERIAL DESCRIPTION:	12x12 Beige Floor Tile Mastic				
MATERIAL LOCATION:	Room 217				
MATERIAL QUANTITY:	85	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 10/07/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Deneen School	INSPECTION DATE:	9/19/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	G	
MATERIAL DESCRIPTION:	Fittings on Fiberglass Runs ABATED	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Abated	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1958 Addition- (Abated)

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 09/19/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Deneen School	REVIEW DATE:	10/7/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

HOMOGENEOUS AREA: **G**

MATERIAL DESCRIPTION: **Fittings on Fiberglass Runs ABATED**

MATERIAL LOCATION: **1958 Addition- (Abated)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/07/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Deneen School	INSPECTION DATE:	9/19/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	H	
MATERIAL DESCRIPTION:	Fittings on Fberglass Runs ABATED	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Abated	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1962 Building- Crawlspace (Abated)

MATERIAL QUANTITY:	MATERIAL UNITS:	Fittings
--------------------	-----------------	----------

DAMAGE QUANTITY:	DAMAGE UNITS:	Fittings
------------------	---------------	----------

COMMENTS:

Inspector's Signature:	_____	Date:	09/19/2019
------------------------	-------	-------	------------

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Deneen School	REVIEW DATE:	10/7/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

HOMOGENEOUS AREA: **H**

MATERIAL DESCRIPTION: **Fittings on Fberglass Runs ABATED**

MATERIAL LOCATION: **1962 Building- Crawlspace (Abated)**

MATERIAL QUANTITY:	MATERIAL UNITS:	Fittings
--------------------	-----------------	-----------------

DAMAGE QUANTITY:	DAMAGE UNITS:	Fittings
------------------	---------------	-----------------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/07/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Deneen School	INSPECTION DATE:	9/19/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	I	
MATERIAL DESCRIPTION:	Aircell Pipe Fittings ABATED	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Abated	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1953 Building- Air Tunnel, Crawlspace, Corridor (Abated)

MATERIAL QUANTITY:		MATERIAL UNITS:	Fittings
--------------------	--	-----------------	----------

DAMAGE QUANTITY:		DAMAGE UNITS:	Fittings
------------------	--	---------------	----------

COMMENTS:

Inspector's Signature:	_____	Date:	09/19/2019
------------------------	-------	-------	------------

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Deneen School	REVIEW DATE:	10/7/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

HOMOGENEOUS AREA: **I**

MATERIAL DESCRIPTION: **Aircell Pipe Fittings ABATED**

MATERIAL LOCATION: **1953 Building- Air Tunnel, Crawlspace, Corridor (Abated)**

MATERIAL QUANTITY:		MATERIAL UNITS:	Fittings
--------------------	--	-----------------	-----------------

DAMAGE QUANTITY:		DAMAGE UNITS:	Fittings
------------------	--	---------------	-----------------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/07/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Deneen School	INSPECTION DATE:	9/19/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	J	
MATERIAL DESCRIPTION:	Cardboard Pipe Fittings ABATED	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Abated	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1953 Building- Air Tunnels (Abated)

MATERIAL QUANTITY:	MATERIAL UNITS:	Fittings
--------------------	-----------------	----------

DAMAGE QUANTITY:	DAMAGE UNITS:	Fittings
------------------	---------------	----------

COMMENTS:

Inspector's Signature:	_____	Date:	09/19/2019
------------------------	-------	-------	------------

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Deneen School	REVIEW DATE:	10/7/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

HOMOGENEOUS AREA:	J		
MATERIAL DESCRIPTION:	Cardboard Pipe Fittings ABATED		
MATERIAL LOCATION:	1953 Building- Air Tunnels (Abated)		
MATERIAL QUANTITY:		MATERIAL UNITS:	Fittings
DAMAGE QUANTITY:		DAMAGE UNITS:	Fittings

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: 10/07/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Hasier		
SCHOOL NAME:	Deneen School	INSPECTION DATE:	9/19/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	K	
MATERIAL DESCRIPTION:	Aircell Pipe Joint ABATED	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Abated	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1958 Building- Crawlspace (Abated)

MATERIAL QUANTITY:	MATERIAL UNITS:	Fittings
--------------------	-----------------	----------

DAMAGE QUANTITY:	DAMAGE UNITS:	Fittings
------------------	---------------	----------

COMMENTS:

Inspector's Signature:	_____	Date:	09/19/2019
------------------------	-------	-------	------------

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Deneen School	REVIEW DATE:	10/7/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

HOMOGENEOUS AREA:	K		
MATERIAL DESCRIPTION:	Aircell Pipe Joint ABATED		
MATERIAL LOCATION:	1958 Building- Crawlspace (Abated)		
MATERIAL QUANTITY:		MATERIAL UNITS:	Fittings
DAMAGE QUANTITY:		DAMAGE UNITS:	Fittings

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/07/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22931** BUILDING ID: **3010**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**
SCHOOL NAME: **Deneen School** INSPECTION DATE: **9/19/2019**
ADDRESS: **7240 S. Wabash** IDPH LICENSE NO: **100-09106**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **L**
MATERIAL DESCRIPTION: **Cardboard Joint Fittings ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1958 Addition- Crawlspace (Abated)**

MATERIAL QUANTITY: MATERIAL UNITS: **Fittings**

DAMAGE QUANTITY: DAMAGE UNITS: **Fittings**

COMMENTS:

Inspector's Signature: _____ Date: **09/19/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22931	BUILDING ID:	3010
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Geneser		
SCHOOL NAME:	Deneen School	REVIEW DATE:	10/7/2019		
ADDRESS:	7240 S. Wabash	IDPH LICENSE NO:	100-09106		

HOMOGENEOUS AREA: L

MATERIAL DESCRIPTION: Cardboard Joint Fittings ABATED

MATERIAL LOCATION: 1958 Addition- Crawlspace (Abated)

MATERIAL QUANTITY:	MATERIAL UNITS:	Fittings
--------------------	-----------------	----------

DAMAGE QUANTITY:	DAMAGE UNITS:	Fittings
------------------	---------------	----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: 10/07/2019

Chicago Public Schools

TEM Environmental, Inc.

2019 AHERA REINSPECTION

APPENDIX B

Inspector and Management Planner Licenses

CERTIFICATE OF ACHIEVEMENT ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that MICHAEL HASIER
has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the
examination on 05/01/2019 with a minimum score of 70% or better. Training was in accordance
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:
Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.

05/01/2019

Course Dates:

05/01/2020

Expires:

1905BIR02

Certificate Number:



PUBLIC HEALTH & SAFETY inc.

Environmental and Occupational Services
375 S. Arland Ave., Chicago, IL 60607

www.public-health-safety.com

Office: 312-491-0081
Fax: 312-421-2901

Director of Training

Nicholas J. Peneff

Doctor of Public Health

Phone: 312-491-0081

FORM # A-010B

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License



ASBESTOS PROFESSIONAL LICENSE

ENDORSEMENTS

TO EXPIRES

SUPERVISOR/WORKER

3/1/2020

INSPECTOR

5/1/2020

ID NUMBER

ISSUED

EXPIRES

100 - 09106

5/8/2019

05/15/2020

PROJECT MANAGER

3/1/2020

AIR SAMPLING PROFESSIONAL

MICHAEL S HASIER

444 OLD BARN RD., APT. B
BARRINGTON, IL 60010

Environmental Health



Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois
Department of Public Health

This license is valid only when accompanied by a valid
training course certificate.

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL		
	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE		
	Loc	Localized
	Dist	Distributed