

ILLINOIS DEPARTMENT OF PUBLIC HEALTH  
AHERA THREE YEAR REINSPECTION  
ASBESTOS ABATEMENT PROGRAM  
SCHOOL INFORMATION FORM

**SECTION I**

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299  
SCHOOL ID NUMBER: 14-016-2990-2210  
SCHOOL NAME: Fulton School  
ADDRESS OF SCHOOL: 5300 S. Hermitage  
CITY: Chicago, IL, 60609

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **3/7/2016**

**If the address on this form is different than the address of the building, submit a written explanation.**

**SECTION II** (Please type or print)

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 10/1/2019 ENROLLMENT 373  
IDPH INSPECTOR LICENSE NUMBER: 100-05090  
IDPH LICENSED INSPECTOR NAME(Please Print): Michael Herman  
IDPH MP LICENSE NUMBER: 100-19466  
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Evan Christian

DESIGNATED PERSON (Please Print): Robert Christlieb PHONE: (773) 553-3197



10/1/2019

Signature of Designated Person

Date

**SECTION III**

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: \_\_\_\_\_

School has been closed. Date closed: \_\_\_\_\_

School building has been demolished. Date: \_\_\_\_\_

School building is asbestos free since last reinspection: \_\_\_\_\_

**Please explain in writing why the school building is now asbestos free and include the supporting documentation.**

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

**Explain in writing if the address of the building is different than the address on this form:**

**THREE-YEAR REINSPECTION**

**CHICAGO SCHOOL DIST 299**

**Fulton School**

5300 S. Hermitage  
Chicago, IL, 60609

Unit: 23281  
Building ID: 3450

IDPH ID Number: 14-016-2990-2210

**REPORT DATE:**

Tuesday, October 01, 2019

**Prepared for:**

**Chicago Public Schools  
42 West Madison Street  
Chicago, IL 60602**

**Prepared by:**

**Carnow, Conibear and Associates**

600 West Van Buren St., Ste 500

Chicago, Il, 60607

Phone (312) 762-2900

Fax (312) 782-5145

**DO NOT REMOVE FROM SCHOOL  
REQUIRED BY FEDERAL LAW**

May 7, 2019

Mr. Glen E. Garner  
Asbestos Program  
Illinois Department of Public Health  
525 West Jefferson Street  
Springfield, Illinois 62761

Re: Chicago Public Schools - 2019 Three-Year Reinspections

Dear Mr. Glen:

Carnow, Conibear and Associates, Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 3, 4 Elementary Schools. Please update your records with the following information.

School District: 299            Unit: 23281            Region: 04            IDPH ID:14-016-2990-2210

School: Fulton School            Building ID: 3450

Address: 5300 S. Hermitage  
Chicago, IL, 60609

Building Contact:            Contact Phone:

Current Building Owners: Chicago Public Schools

Review Date: 05/24/2019

Inspector: Michael Herman            Inspector IDPH License: 100-05090  
Management Planner: Evan Christian            Management Planner IDPH License: 100-19466

If you have any questions or comments, please contact us at (312) 762-2900

Sincerely,  
Carnow, Conibear and Associates

Evan Christian  
100-19466

## **Environmental Notification to Occupants**

To: Faculty, Staff and Parents  
From: Chicago Public Schools  
Date: May 07, 2019

RE: Fulton School, Unit 23281  
5300 S. Hermitage  
Chicago, IL, 60609

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2019 asbestos three year re-inspection has been completed at Fulton School, following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at Fulton School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Robert Christlieb, the designated Local Education Authority's Designated Person at (773) 553-3197 .

## **Table of Contents**

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

### **APPENDICES:**

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

## SCHOOL AND INSPECTION INFORMATION

### 1. School Information

School: Fulton School Unit: 23281 Region: 04  
Address: 5300 S. Hermitage Chicago, IL, 60609  
IDPH ID: 14-016-2990-2210 Building ID: 3450  
Contact: Phone:

### 2. Description of Facility

Original Construction: 1894 Additional Construction:  
Total Square Footage: 75628 No of Floors: 4  
Current Occupancy: 373

### 3. LEA Designated Person

Contact: Robert Christlieb Phone: (773) 553-3197  
Address: 42 West Madison Street  
Chicago, IL 60602

### 4. Managing Environmental Consultant

MEC: Carnow, Conibear and Associates  
Contact: Doug McCormick  
Address 600 West Van Buren St., Ste 500  
Chicago, IL, 60607  
Phone: (312) 762-2900 Fax: (312) 782-5145

### 5. Inspector

Inspector Name: Michael Herman

Inspector IDPH license # 100-05090

Signature:  
Date: 5/7/2019

### 6. Management Planner

Management Planner Name: Evan Christian

Management Planner IDPH license # 100-19466

Signature:  
Date: 05/24/2019

### 7. Review Date:05/24/2019

### 8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature:



Date: 10/1/2019

Name: Robert Christlieb

## II. EXECUTIVE SUMMARY

Carnow, Conibear and Associates was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Fulton School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.85 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas(HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 3450:

62	12" x 12" Dark Blue Floor Tile
63	Mastic Associated w/ 12" x 12" Dark Blue Floor Tile
64	Beige Linoleum
65	Yellow Glue Associated w/ Beige Linoleum

B. The following new homogenous areas have been identified for Building 3450:



C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

10.1	12" x 12" Off Wt. w/Wt. Brwn and Gry Specks FT
10.2	12x12 VFT, Off-White W/ Wt. Brn., and Gry Specks
10.3	12x12 VFT, White
11.2	12x12 Off-White FT W/Wt., Brn., Gry. Specks REMOVED
12.2	12x12 Off White FT W/White-Brown-Gray Speck Mastic
12.3	Mastic for 12x12 White FT
13.1	Mastic for 12x12 Brown FT W/White-Brown Specks
18	Light and Dark Brown Linoleums
19	Light and Dark Brown Linoleum Mastic
22	Drywall Joint Compound
29	Drywall Joint Compound
34	Gray/Black Carpet Adhesive
36	Gray/Red Carpet Adhesive
37	Pink Carpet Adhesive
38	Vault Door Core
39	Lab Table Tops
40	Brown Mix Carpet Adhesive
41	4" Black Vinyl Baseboard
42	4" Black Vinyl Baseboard Adhesive
43	4" Tan Vinyl Baseboard
44	4" Tan Vinyl Baseboard Adhesive
45	5" Brown Vinyl Baseboard
46	5" Brown Vinyl Baseboard Adhesive
47	12" x 12" Bright Blue Mix Floor Tile
48	12" x 12" Bright Blue Mix Floor Tile Mastic
49	Black Boards
50	Black Board Adhesive
51	Black Boards
52	Black Board Adhesive
59	Refractory Block
60	2 X 4 Pinhole Ceiling Tile
61	2 X 2 Solid Ceiling Tile
62	12" x 12" Dark Blue Floor Tile
63	Mastic Associated w/ 12" x 12" Dark Blue Floor Tile
64	Beige Linoleum
65	Yellow Glue Associated w/ Beige Linoleum
A	Aircell Pipe Insulation

D	Aircell Pipe Fitting
F	Aircell Pipe Insulation
G	Aircell Pipe Fitting
H	Cardboard Pipe Insulation

The following areas were deemed to be inaccessible:

10.2	12x12 VFT, Off-White W/ Wt. Brn., and Gry Specks
12.2	12x12 Off White FT W/White-Brown-Gray Speck Mastic
19	Light and Dark Brown Linoleum Mastic
38	Vault Door Core
42	4" Black Vinyl Baseboard Adhesive
44	4" Tan Vinyl Baseboard Adhesive
46	5" Brown Vinyl Baseboard Adhesive
63	Mastic Associated w/ 12" x 12" Dark Blue Floor Tile
A	Aircell Pipe Insulation
F	Aircell Pipe Insulation
G	Aircell Pipe Fitting
H	Cardboard Pipe Insulation
I	Cardboard Pipe Fitting
L	Preform Pipe Insulation
M	Preform Pipe Fitting

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Michael Herman, IDPH License # 100-05090. The Management Plan was updated by Evan Christian, IDPH License # 100-19466. Inspector and Management Planner Licenses are included in Appendix B.

### **III. METHODOLOGY**

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

### **IV. ABATEMENT HISTORY**

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

### **V. REASSESSMENTS AND RECOMMENDATIONS**

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

### **VI. CONCLUSIONS**

The Fulton School Building 3450 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

**Table I**  
**Inspector's Reinspection Findings**

---

# Chicago Public Schools

School **Fulton School** Unit **23281** Building ID **3450**

Address **5300 S. Hermitage** Region **04**

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) **Carnow, Conibear and Associates**

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
10.1	12" x 12" Off Wt. w/Wt. Brwn and Gry Specks FT	1,800	SF	1894- Office, Rooms 102, 302,	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
10.2	12x12 VFT, Off-White W/ Wt. Brn., and Gry Specks	1,800	SF	1894- kitchen	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
10.3	12x12 VFT, White	100	SF	1894- Engineer's Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
10.4	12x12 VFT, Brwn W/White and Brown Specks ABATED			1894- Rooms 206, 306 (2nd layer), 305A, 306A, 302, 104A, 102A, 106, 102, 104, 205, 305	ABATED	MISC								
11.1	12x12 VFT, Brown W/White and Brown Specks	5,000	SF	1910- Room 012	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
11.2	12x12 Off-White FT W/Wt., Brn., Gry. Specks REMOVED			1910- Room 208	ASSUMED	MISC								
12.1	12" x 12" Off Wt. w/Wt., Brwn&Gray Specks FT	4,000	SF	1894- Office, Rooms 102, 302, 306, 104, 106, 103, 205, 303, 305, 306, 310	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
12.2	12x12 Off White FT W/White-Brown-Gray Speck Mastic	200	SF	bldg. 1894--303, kitchen	ASSUMED	SURFACE	N	NONE	0		No	ACBM with the potential for damage		LOW
12.3	Mastic for 12x12 White FT	100	SF	Bldg. 1894-- Engineer Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
12.4	12x12 VFT, Brwn W/White and Brown Specks Mastic ABATED			1894- Rooms 206, 306 (2nd layer), 305A, 306A, 302, 104A, 102A, 106, 102, 104, 205, 305	ABATED	MISC								
13.1	Mastic for 12x12 Brown FT W/White-Brown Specks	5,700	SF	Bldg 1910 Room 012	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
13.2	12x12 Off-White FT W/Wt., Brn., Gry. Specks Mastic ABATED			1910- Room 208	ABATED	MISC								
15	9x9 VFT, Red - Abated			bldg. 1910-- Electrical Room - ABATED 1999	ABATED	MISC								
16	9x9 VFT, Mastic - Abated			1894- Electrical Room - ABATED 1994	ABATED	MISC								
17	9x9 Red VFT, Mastic - Abated			1910- Electrical Room - ABATED 1999	ABATED	MISC								
18	Light and Dark Brown Linoleums	1,000	SF	1910- Assembly Hall & Kitchen	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

# Chicago Public Schools

School **Fulton School** Unit **23281** Building ID **3450**

Address **5300 S. Hermitage** Region **04**

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) **Carnow, Conibear and Associates**

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Storage										
19	Light and Dark Brown Linoleum Mastic	550	SF	1910- Assembly Hall & Kitchen Storage	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
2	Plaster			1894- Throughout	NO_ACBM	SURFACE								
21	Drywall			1894- Washrooms	NO_ACBM	SURFACE								
22	Drywall Joint Compound	600	SF	1894- Washrooms	ASSUMED	SURFACE	N	NONE	0		No	ACBM with the potential for damage		LOW
23	Exterior Brick			1894- Exterior	NO_ACBM	SURFACE								
24	Exterior Brick Mortar			1894- Exterior	NO_ACBM	SURFACE								
25	Exterior Brick			1910- Exterior	NO_ACBM	SURFACE								
26	Exterior Brick Mortar			1910- Exterior	NO_ACBM	SURFACE								
27	Interior Window Transom Glaze			1894 Bldg	NO_ACBM	SURFACE								
28	Drywall			1910 Bldg.	NO_ACBM	SURFACE								
29	Drywall Joint Compound	1,000	SF	1910 Bldg	ASSUMED	SURFACE	N	NONE	0		No	ACBM with the potential for damage		LOW
30	12" x 12" Gray Mix Floor Tile ABATED			Office and Rooms 303 & 303A	ABATED	MISC								
31	12" x 12" Gray Mix Floor Tile Mastic ABATED			Office and Rooms 303 & 303A	ABATED	MISC								
32	12" x 12" Red Mix Floor Tile ABATED			Office	ABATED	MISC								
33	12" x 12" Red Mix Floor Tile Mastic ABATED			Office	ABATED	MISC								
34	Gray/Black Carpet Adhesive			Entrances by Engineers Office and Disciplinary Office	ASSUMED	MISC								
35	Purple Carpet Adhesive ABATED			Office	ABATED	MISC								
36	Gray/Red Carpet Adhesive			Rooms 102, 104, 206 & 306	ASSUMED	MISC								
37	Pink Carpet Adhesive			Room 205	ASSUMED	MISC								
38	Vault Door Core	28	SF	Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
39	Lab Table Tops	88	SF	Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
4	2x4 Ceiling Tile			1894- 1st Floor Corridor	NO_ACBM	MISC								
40	Brown Mix Carpet Adhesive	600	SF	Room 002 (Principal's Office)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
41	4" Black Vinyl Baseboard	100	LF	Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
42	4" Black Vinyl Baseboard Adhesive	100	LF	Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

# Chicago Public Schools

School **Fulton School** Unit **23281** Building ID **3450**

Address **5300 S. Hermitage** Region **04**

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
43	4" Tan Vinyl Baseboard	100	LF	Gym	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
44	4" Tan Vinyl Baseboard Adhesive	100	LF	Gym	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
45	5" Brown Vinyl Baseboard	100	LF	Staff Lounge & Adjacent Foyer to Women's Washroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
46	5" Brown Vinyl Baseboard Adhesive	100	LF	Staff Lounge & Adjacent Foyer to Women's Washroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
47	12" x 12" Bright Blue Mix Floor Tile	1,700	SF	Staff Lounge & Adjacent Foyer to Women's Washroom, 001	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
48	12" x 12" Bright Blue Mix Floor Tile Mastic	850	SF	Staff Lounge & Adjacent Foyer to Women's Washroom, 001	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
49	Black Boards			All Classrooms 1894 bldg	ASSUMED	MISC								
50	Black Board Adhesive			All Classrooms 1894 bldg	ASSUMED	MISC								
51	Black Boards			All Classrooms 1910 Bldg	ASSUMED	MISC								
52	Black Board Adhesive			All Classrooms 1910 Bldg	ASSUMED	MISC								
53	Cork Flooring ABATED			Gym/Assembly	ABATED	MISC								
54	Cork Flooring Adhesive ABATED			Gym/Assembly	ABATED	MISC								
55	12" X 12" White w/Brown Floor Tile ABATED			Main Office	ABATED	MISC								
56	12" X 12" White w/Brown Floor Tile Mastic ABATED			Main Office	ABATED	MISC								
57	12" X 12" Grey w/Dk Grey Floor Tile ABATED			Main Office	ABATED	MISC								
58	12" X 12" Grey w/Dk Grey Floor Tile Mastic ABATED			Main Office	ABATED	MISC								
59	Refractory Block			Kiln 012	ASSUMED	TSI								
60	2 X 4 Pinhole Ceiling Tile	400	SF	Electrical Room	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
61	2 X 2 Solid Ceiling Tile	2,000	SF	Kitchen	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
62	12" x 12" Dark Blue Floor Tile	500	SF	Closet Next to	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the		LOW

# Chicago Public Schools

School **Fulton School** Unit **23281** Building ID **3450**

Address **5300 S. Hermitage** Region **04**

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Room 005 in Basement								potential for damage		
63	Mastic Associated w/ 12" x 12" Dark Blue Floor Tile	500	SF	Closet Next to Room 005 in Basement	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
64	Beige Linoleum	600	SF	Rm. 312	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
65	Yellow Glue Associated w/ Beige Linoleum	600	SF	Rm. 312	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
9	Plaster			1910- Throughout	NO_ACBM	SURFACE								
A	Aircell Pipe Insulation	50	LF	1894- Boiler Room	ASSUMED	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
B	Cardboard Pipe Insulation			1894- Ground Floor	NO_ACBM	TSI		None						Low
C	Boiler Insulation			1894- Boiler Room - ABATED 1994	ABATED	TSI								
D	Aircell Pipe Fitting	50	LF	1894- Boiler Room, Tank Room	ASSUMED	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
E	Cardboard Pipe Fitting	50	LF	1894- Ground Floor	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
F	Aircell Pipe Insulation	230	LF	1910- Ground Floor	ASSUMED	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
G	Aircell Pipe Fitting	30	LF	1910- Ground Floor	ASSUMED	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
H	Cardboard Pipe Insulation	230	LF	1910- Addition	ASSUMED	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
I	Cardboard Pipe Fitting	30	LF	1910- Ground Floor, 2nd Floor, Teacher Toilet	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
J	Fiberglass Pipe Fitting			1910- Ground Floor	NOT_TESTED	TSI								
K	Fiberglass Pipe Fitting			1894- Ground Level	NOT_TESTED	TSI								
L	Preform Pipe Insulation	30	LF	1894- Tank Room	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
M	Preform Pipe Fitting	10	LF	1894- Tank Room	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW





# Chicago Public Schools

School **Fulton School** Unit **23281** Building ID **3450**

Address **5300 S. Hermitage** Region **04**

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) **Carnow, Conibear and Associates**

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

Reinspection Date <b><u>5/7/2019</u></b>
Inspector Name <b><u>Michael Herman</u></b>
<b><u>100-05090</u></b> <b><u>5/15/2020</u></b>
Inspector's IDPH License Number / Expiration Date

### Inspector's Comments

HA Number:	Inspector Comments:
10.1	
10.2	
10.3	
10.4	
11.1	
11.2	
12.1	
12.2	
12.3	
12.4	
13.1	
13.2	
15	
16	
17	
18	
19	
2	
21	
22	
23	
24	
25	

# Chicago Public Schools

School Fulton School Unit 23281 Building ID 3450

Address 5300 S. Hermitage Region 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
26	
27	
28	
29	
30	
31	
32	
33	
34	Not observed 2016
35	
36	Not observed 2016
37	Not observed 2016
38	
39	
4	
40	
41	
42	
43	
44	
45	
46	
47	
48	
49	Not observed 2016
50	Not observed 2016
51	Not observed 2016
52	Not observed 2016
53	

# Chicago Public Schools

School Fulton School Unit 23281 Building ID 3450

Address 5300 S. Hermitage Region 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
54	
55	
56	
57	
58	
59	Not observed 2016
60	
61	
62	
63	
64	
65	
9	
A	
B	
C	
D	
E	
F	
G	
H	
I	
J	Not a suspect material
K	Not a suspect material
L	
M	
N	

# Chicago Public Schools

School Fulton School Unit 23281 Building ID 3450

Address 5300 S. Hermitage Region 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

---

**Table II**

**Management Planner's Review**

---

# Chicago Public Schools

**School** Fulton School  
**Address** 5300 S. Hermitage

**Unit** 23281  
Chicago, IL, 60609

**Building ID** 3450  
**Region** 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
10.1	12" x 12" Off Wt. w/Wt. Brwn and Gry Specks FT	1,800	SF	1894- Office, Rooms 102, 302,	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
10.2	12x12 VFT, Off-White W/ Wt. Brn., and Gry Specks	1,800	SF	1894- kitchen	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
10.3	12x12 VFT, White	100	SF	1894- Engineer's Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
10.4	12x12 VFT, Brwn W/White and Brown Specks ABATED			1894- Rooms 206, 306 (2nd layer), 305A, 306A, 302, 104A, 102A, 106, 102, 104, 205 305	Abated	MISC					
11.1	12x12 VFT, Brown W/White and Brown Specks	5,000	SF	1910- Room 012	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
11.2	12x12 Off-White FT W/Wt., Brn., Gry. Specks REMOVED			1910- Room 208	Assumed	MISC					
12.1	12" x 12" Off Wt. w/Wt., Brwn&Gray Specks FT	4,000	SF	1894- Office, Rooms 102, 302, 306, 104, 106, 103, 205, 303, 305, 306, 310	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
12.2	12x12 Off White FT W/White-Brown-Gray Speck Mastic	200	SF	bldg. 1894--303, kitchen	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
12.3	Mastic for 12x12 White FT	100	SF	Bldg. 1894--Engineer Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
12.4	12x12 VFT, Brwn W/White and Brown Specks Mastic ABATED			1894- Rooms 206, 306 (2nd layer), 305A, 306A, 302, 104A, 102A, 106, 102, 104, 205, 305	Abated	MISC					
13.1	Mastic for 12x12 Brown FT W/White-Brown Specks	5,700	SF	Bldg 1910 Room 012	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
13.2	12x12 Off-White FT W/Wt., Brn., Gry. Specks Mastic ABATED			1910- Room 208	Abated	MISC					
15	9x9 VFT, Red - Abated			bldg. 1910--Electrical Room - ABATED 1999	Abated	MISC					
16	9x9 VFT, Mastic - Abated			1894- Electrical Room - ABATED 1994	Abated	MISC					
17	9x9 Red VFT, Mastic - Abated			1910- Electrical Room - ABATED 1999	Abated	MISC					
18	Light and Dark Brown Linoleums	1,000	SF	1910- Assembly Hall & Kitchen Storage	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
19	Light and Dark Brown Linoleum Mastic	550	SF	1910- Assembly Hall & Kitchen Storage	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
2	Plaster			1894- Throughout	No ACBM	SURFACE					
21	Drywall			1894- Washrooms	No ACBM	SURFACE					
22	Drywall Joint Compound	600	SF	1894- Washrooms	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
23	Exterior Brick			1894- Exterior	No ACBM	SURFACE					
24	Exterior Brick Mortar			1894- Exterior	No ACBM	SURFACE					
25	Exterior Brick			1910- Exterior	No ACBM	SURFACE					

# Chicago Public Schools

**School** Fulton School  
**Address** 5300 S. Hermitage

**Unit** 23281  
Chicago, IL, 60609

**Building ID** 3450  
**Region** 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
26	Exterior Brick Mortar			1910- Exterior	No ACBM	SURFACE					
27	Interior Window Transom Glaze			1894 Bldg	No ACBM	SURFACE					
28	Drywall			1910 Bldg.	No ACBM	SURFACE					
29	Drywall Joint Compound	1,000	SF	1910 Bldg	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
30	12" x 12" Gray Mix Floor Tile ABATED			Office and Rooms 303 & 303A	Abated	MISC					
31	12" x 12" Gray Mix Floor Tile Mastic ABATED			Office and Rooms 303 & 303A	Abated	MISC					
32	12" x 12" Red Mix Floor Tile ABATED			Office	Abated	MISC					
33	12" x 12" Red Mix Floor Tile Mastic ABATED			Office	Abated	MISC					
34	Gray/Black Carpet Adhesive			Entrances by Engineers Office and Disciplinary Office	Assumed	MISC					
35	Purple Carpet Adhesive ABATED			Office	Abated	MISC					
36	Gray/Red Carpet Adhesive			Rooms 102, 104, 206 & 306	Assumed	MISC					
37	Pink Carpet Adhesive			Room 205	Assumed	MISC					
38	Vault Door Core	28	SF	Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
39	Lab Table Tops	88	SF	Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
4	2x4 Ceiling Tile			1894- 1st Floor Corridor	No ACBM	MISC					
40	Brown Mix Carpet Adhesive	600	SF	Room 002 (Principal's Office)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
41	4" Black Vinyl Baseboard	100	LF	Office	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
42	4" Black Vinyl Baseboard Adhesive	100	LF	Office	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
43	4" Tan Vinyl Baseboard	100	LF	Gym	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
44	4" Tan Vinyl Baseboard Adhesive	100	LF	Gym	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
45	5" Brown Vinyl Baseboard	100	LF	Staff Lounge & Adjacent Foyer to Women's Washroom	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
46	5" Brown Vinyl Baseboard Adhesive	100	LF	Staff Lounge & Adjacent Foyer to Women's Washroom	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
47	12" x 12" Bright Blue Mix Floor Tile	1,700	SF	Staff Lounge & Adjacent Foyer to Women's Washroom, 001	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
48	12" x 12" Bright Blue Mix Floor Tile Mastic	850	SF	Staff Lounge & Adjacent Foyer to Women's Washroom, 001	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
49	Black Boards			All Classrooms 1894 bldg	Assumed	MISC					
50	Black Board Adhesive			All Classrooms 1894 bldg	Assumed	MISC					
51	Black Boards			All Classrooms 1910 Bldg	Assumed	MISC					
52	Black Board Adhesive			All Classrooms 1910 Bldg	Assumed	MISC					
53	Cork Flooring ABATED			Gym/Assembly	Abated	MISC					



# Chicago Public Schools

**School** Fulton School  
**Address** 5300 S. Hermitage

**Unit** 23281  
Chicago, IL, 60609

**Building ID** 3450  
**Region** 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, Il, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
54	Cork Flooring Adhesive ABATED			Gym/Assembly	Abated	MISC					
55	12" X 12" White w/Brown Floor Tile ABATED			Main Office	Abated	MISC					
56	12" X 12" White w/Brown Floor Tile Mastic ABATED			Main Office	Abated	MISC					
57	12" X 12" Grey w/Dk Grey Floor Tile ABATED			Main Office	Abated	MISC					
58	12" X 12" Grey w/Dk Grey Floor Tile Mastic ABATED			Main Office	Abated	MISC					
59	Refractory Block			Kiln 012	Assumed	TSI					
60	2 X 4 Pinhole Ceiling Tile	400	SF	Electrical Room	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
61	2 X 2 Solid Ceiling Tile	2,000	SF	Kitchen	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
62	12" x 12" Dark Blue Floor Tile	500	SF	Closet Next to Room 005 in Basement	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
63	Mastic Associated w/ 12" x 12" Dark Blue Floor Tile	500	SF	Closet Next to Room 005 in Basement	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
64	Beige Linoleum	600	SF	Rm. 312	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
65	Yellow Glue Associated w/ Beige Linoleum	600	SF	Rm. 312	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
9	Plaster			1910- Throughout	No ACBM	SURFACE					
A	Aircell Pipe Insulation	50	LF	1894- Boiler Room	Assumed	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
B	Cardboard Pipe Insulation			1894- Ground Floor	No ACBM	TSI					
C	Boiler Insulation			1894- Boiler Room - ABATED 1994	Abated	TSI					
D	Aircell Pipe Fitting	50	LF	1894- Boiler Room, Tank Room	Assumed	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
E	Cardboard Pipe Fitting	50	LF	1894- Ground Floor	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
F	Aircell Pipe Insulation	230	LF	1910- Ground Floor	Assumed	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
G	Aircell Pipe Fitting	30	LF	1910- Ground Floor	Assumed	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
H	Cardboard Pipe Insulation	230	LF	1910- Addition	Assumed	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
I	Cardboard Pipe Fitting	30	LF	1910- Ground Floor, 2nd Floor. Teacher Toilet	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan

# Chicago Public Schools

**School** Fulton School  
**Address** 5300 S. Hermitage

**Unit** 23281  
 Chicago, IL, 60609

**Building ID** 3450  
**Region** 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
J	Fiberglass Pipe Fitting			1910- Ground Floor	Not Tested	TSI					
K	Fiberglass Pipe Fitting			1894- Ground Level	Not Tested	TSI					
L	Preform Pipe Insulation	30	LF	1894- Tank Room	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
M	Preform Pipe Fitting	10	LF	1894- Tank Room	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
N	Boiler Refractory Cement			1894- Boiler Room	No ACBM	MISC					

# Chicago Public Schools

**School** Fulton School  
**Address** 5300 S. Hermitage

**Unit** 23281  
 Chicago, IL, 60609

**Building ID** 3450  
**Region** 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

Review Date	05/24/2019
Manager Planner Name	Evan Christian
100-19466	5/15/2020
Manager IDPH License No/Expiration	

HA Number	Management Comments
10.1	
10.2	
10.3	
10.4	
11.1	
11.2	
12.1	
12.2	
12.3	
12.4	
13.1	
13.2	
15	
16	
17	
18	
19	
2	
21	
22	
23	
24	
25	
26	
27	

# Chicago Public Schools

**School** Fulton School  
**Address** 5300 S. Hermitage

**Unit** 23281  
Chicago, IL, 60609

**Building ID** 3450  
**Region** 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
28	
29	
30	
31	
32	
33	
34	
35	
36	
37	
38	
39	
4	
40	
41	
42	
43	
44	
45	
46	
47	
48	
49	
50	
51	
52	

# Chicago Public Schools

**School** Fulton School  
**Address** 5300 S. Hermitage

**Unit** 23281  
Chicago, IL, 60609

**Building ID** 3450  
**Region** 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
53	
54	
55	
56	
57	
58	
59	
60	
61	
62	
63	
64	
65	
9	
A	
B	
C	
D	
E	
F	
G	
H	
I	
J	
K	
L	

# Chicago Public Schools

**School** Fulton School  
**Address** 5300 S. Hermitage

**Unit** 23281  
Chicago, IL, 60609

**Building ID** 3450  
**Region** 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
M	
N	

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Herman**  
SCHOOL NAME: **Fulton School** INSPECTION DATE: **5/7/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10.1**  
MATERIAL DESCRIPTION: **12" x 12" Off Wt. w/Wt. Brwn and Gry Specks FT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1894- Office, Rooms 102, 302,**  
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/07/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Fulton School** REVIEW DATE: **5/24/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

HOMOGENEOUS AREA: **10.1**  
MATERIAL DESCRIPTION: **12" x 12" Off Wt. w/Wt. Brwn and Gry Specks FT**  
MATERIAL LOCATION: **1894- Office, Rooms 102, 302,**  
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**



# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Herman**  
SCHOOL NAME: **Fulton School** INSPECTION DATE: **5/7/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10.2**  
MATERIAL DESCRIPTION: **12x12 VFT, Off-White W/ Wt. Brn., and Gry Specks**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1894- kitchen**  
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/07/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Fulton School** REVIEW DATE: **5/24/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

HOMOGENEOUS AREA: **10.2**  
MATERIAL DESCRIPTION: **12x12 VFT, Off-White W/ Wt. Brn., and Gry Specks**  
MATERIAL LOCATION: **1894- kitchen**  
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

## Carnow, Conibear and Associates 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Herman**  
SCHOOL NAME: **Fulton School** INSPECTION DATE: **5/7/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10.3**  
MATERIAL DESCRIPTION: **12x12 VFT, White**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1894- Engineer's Office**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/07/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Fulton School** REVIEW DATE: **5/24/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

HOMOGENEOUS AREA: **10.3**  
MATERIAL DESCRIPTION: **12x12 VFT, White**  
MATERIAL LOCATION: **1894- Engineer's Office**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Herman**  
SCHOOL NAME: **Fulton School** INSPECTION DATE: **5/7/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10.4**  
MATERIAL DESCRIPTION: **12x12 VFT, Brwn W/White and Brown Specks ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1894- Rooms 206, 306 (2nd layer), 305A, 306A, 302, 104A, 102A, 106, 102, 104, 205 305**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Fulton School** REVIEW DATE: **5/24/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

HOMOGENEOUS AREA: **10.4**

MATERIAL DESCRIPTION: **12x12 VFT, Brwn W/White and Brown Specks ABATED**

MATERIAL LOCATION: **1894- Rooms 206, 306 (2nd layer), 305A, 306A, 302, 104A, 102A, 106, 102, 104, 205 305**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Herman**  
SCHOOL NAME: **Fulton School** INSPECTION DATE: **5/7/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11.1**  
MATERIAL DESCRIPTION: **12x12 VFT, Brown W/White and Brown Specks**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1910- Room 012**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/07/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Fulton School** REVIEW DATE: **5/24/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

HOMOGENEOUS AREA: **11.1**

MATERIAL DESCRIPTION: **12x12 VFT, Brown W/White and Brown Specks**

MATERIAL LOCATION: **1910- Room 012**

MATERIAL QUANTITY: **5000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**



# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Herman**  
SCHOOL NAME: **Fulton School** INSPECTION DATE: **5/7/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11.2**  
MATERIAL DESCRIPTION: **12x12 Off-White FT W/Wt., Brn., Gry. Specks REMOVED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1910- Room 208**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Fulton School** REVIEW DATE: **5/24/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

HOMOGENEOUS AREA: **11.2**

MATERIAL DESCRIPTION: **12x12 Off-White FT W/Wt., Brn., Gry. Specks REMOVED**

MATERIAL LOCATION: **1910- Room 208**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Herman**  
SCHOOL NAME: **Fulton School** INSPECTION DATE: **5/7/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12.1**  
MATERIAL DESCRIPTION: **12" x 12" Off Wt. w/Wt., Brwn&Gray Specks FT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1894- Office, Rooms 102, 302, 306, 104, 106, 103, 205, 303, 305, 306, 310**  
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/07/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Fulton School** REVIEW DATE: **5/24/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

HOMOGENEOUS AREA: **12.1**  
MATERIAL DESCRIPTION: **12" x 12" Off Wt. w/Wt., Brwn&Gray Specks FT**  
MATERIAL LOCATION: **1894- Office, Rooms 102, 302, 306, 104, 106, 103, 205, 303, 305, 306, 310**  
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Herman**  
SCHOOL NAME: **Fulton School** INSPECTION DATE: **5/7/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12.2**  
MATERIAL DESCRIPTION: **12x12 Off White FT W/White-Brown-Gray Speck Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **bldg. 1894--303, kitchen**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/07/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Fulton School** REVIEW DATE: **5/24/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

HOMOGENEOUS AREA: **12.2**  
MATERIAL DESCRIPTION: **12x12 Off White FT W/White-Brown-Gray Speck Mastic**  
MATERIAL LOCATION: **bldg. 1894--303, kitchen**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Herman**  
SCHOOL NAME: **Fulton School** INSPECTION DATE: **5/7/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12.3**  
MATERIAL DESCRIPTION: **Mastic for 12x12 White FT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Bldg. 1894--Engineer Office**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/07/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Fulton School** REVIEW DATE: **5/24/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

HOMOGENEOUS AREA: **12.3**  
MATERIAL DESCRIPTION: **Mastic for 12x12 White FT**  
MATERIAL LOCATION: **Bldg. 1894--Engineer Office**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**



# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Herman**  
SCHOOL NAME: **Fulton School** INSPECTION DATE: **5/7/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12.4**  
MATERIAL DESCRIPTION: **12x12 VFT, Brwn W/White and Brown Specks Mastic ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1894- Rooms 206, 306 (2nd layer), 305A, 306A, 302, 104A, 102A, 106, 102, 104, 205, 305**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Fulton School** REVIEW DATE: **5/24/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

HOMOGENEOUS AREA: **12.4**  
MATERIAL DESCRIPTION: **12x12 VFT, Brwn W/White and Brown Specks Mastic ABATED**  
MATERIAL LOCATION: **1894- Rooms 206, 306 (2nd layer), 305A, 306A, 302, 104A, 102A, 106, 102, 104, 205, 305**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Herman**  
SCHOOL NAME: **Fulton School** INSPECTION DATE: **5/7/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13.1**  
MATERIAL DESCRIPTION: **Mastic for 12x12 Brown FT W/White-Brown Specks**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Bldg 1910 Room 012**  
MATERIAL QUANTITY: **5700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Fulton School** REVIEW DATE: **5/24/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

HOMOGENEOUS AREA: **13.1**  
MATERIAL DESCRIPTION: **Mastic for 12x12 Brown FT W/White-Brown Specks**  
MATERIAL LOCATION: **Bldg 1910 Room 012**  
MATERIAL QUANTITY: **5700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Herman**  
SCHOOL NAME: **Fulton School** INSPECTION DATE: **5/7/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13.2**  
MATERIAL DESCRIPTION: **12x12 Off-White FT W/Wt., Brn., Gry. Specks Mastic ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1910- Room 208**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Fulton School** REVIEW DATE: **5/24/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

HOMOGENEOUS AREA: **13.2**

MATERIAL DESCRIPTION: **12x12 Off-White FT W/Wt., Brn., Gry. Specks Mastic ABATED**

MATERIAL LOCATION: **1910- Room 208**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Herman**  
SCHOOL NAME: **Fulton School** INSPECTION DATE: **5/7/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15**  
MATERIAL DESCRIPTION: **9x9 VFT, Red - Abated**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **bldg. 1910--Electrical Room - ABATED 1999**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Fulton School** REVIEW DATE: **5/24/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

HOMOGENEOUS AREA: **15**

MATERIAL DESCRIPTION: **9x9 VFT, Red - Abated**

MATERIAL LOCATION: **bldg. 1910--Electrical Room - ABATED 1999**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**



# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **23281**    BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Michael Herman**  
SCHOOL NAME: **Fulton School**    INSPECTION DATE: **5/7/2019**  
ADDRESS: **5300 S. Hermitage**    IDPH LICENSE NO: **100-05090**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16**  
MATERIAL DESCRIPTION: **9x9 VFT, Mastic - Abated**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated**    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1894- Electrical Room - ABATED 1994**

MATERIAL QUANTITY:    MATERIAL UNITS:

DAMAGE QUANTITY:    DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Fulton School** REVIEW DATE: **5/24/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

HOMOGENEOUS AREA: **16**

MATERIAL DESCRIPTION: **9x9 VFT, Mastic - Abated**

MATERIAL LOCATION: **1894- Electrical Room - ABATED 1994**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Herman**  
SCHOOL NAME: **Fulton School** INSPECTION DATE: **5/7/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17**  
MATERIAL DESCRIPTION: **9x9 Red VFT, Mastic - Abated**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1910- Electrical Room - ABATED 1999**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Fulton School** REVIEW DATE: **5/24/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

HOMOGENEOUS AREA: **17**

MATERIAL DESCRIPTION: **9x9 Red VFT, Mastic - Abated**

MATERIAL LOCATION: **1910- Electrical Room - ABATED 1999**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Herman**  
SCHOOL NAME: **Fulton School** INSPECTION DATE: **5/7/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18**  
MATERIAL DESCRIPTION: **Light and Dark Brown Linoleums**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1910- Assembly Hall & Kitchen Storage**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/07/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Fulton School** REVIEW DATE: **5/24/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

HOMOGENEOUS AREA: **18**  
MATERIAL DESCRIPTION: **Light and Dark Brown Linoleums**  
MATERIAL LOCATION: **1910- Assembly Hall & Kitchen Storage**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Herman**  
SCHOOL NAME: **Fulton School** INSPECTION DATE: **5/7/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19**  
MATERIAL DESCRIPTION: **Light and Dark Brown Linoleum Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1910- Assembly Hall & Kitchen Storage**  
MATERIAL QUANTITY: **550** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/07/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Fulton School** REVIEW DATE: **5/24/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

HOMOGENEOUS AREA: **19**  
MATERIAL DESCRIPTION: **Light and Dark Brown Linoleum Mastic**  
MATERIAL LOCATION: **1910- Assembly Hall & Kitchen Storage**  
MATERIAL QUANTITY: **550** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**



# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Herman**  
SCHOOL NAME: **Fulton School** INSPECTION DATE: **5/7/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **2**  
MATERIAL DESCRIPTION: **Plaster**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1894- Throughout**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Fulton School** REVIEW DATE: **5/24/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

HOMOGENEOUS AREA: **2**

MATERIAL DESCRIPTION: **Plaster**

MATERIAL LOCATION: **1894- Throughout**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Herman**  
SCHOOL NAME: **Fulton School** INSPECTION DATE: **5/7/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21**  
MATERIAL DESCRIPTION: **Drywall**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1894- Washrooms**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Fulton School** REVIEW DATE: **5/24/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

HOMOGENEOUS AREA: **21**

MATERIAL DESCRIPTION: **Drywall**

MATERIAL LOCATION: **1894- Washrooms**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Herman**  
SCHOOL NAME: **Fulton School** INSPECTION DATE: **5/7/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22**  
MATERIAL DESCRIPTION: **Drywall Joint Compound**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1894- Washrooms**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/07/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Fulton School** REVIEW DATE: **5/24/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

HOMOGENEOUS AREA: **22**  
MATERIAL DESCRIPTION: **Drywall Joint Compound**  
MATERIAL LOCATION: **1894- Washrooms**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Herman**  
SCHOOL NAME: **Fulton School** INSPECTION DATE: **5/7/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23**  
MATERIAL DESCRIPTION: **Exterior Brick**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1894- Exterior**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Fulton School** REVIEW DATE: **5/24/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

HOMOGENEOUS AREA: **23**

MATERIAL DESCRIPTION: **Exterior Brick**

MATERIAL LOCATION: **1894- Exterior**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**



# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **23281**    BUILDING ID: **3450**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Michael Herman**  
SCHOOL NAME: **Fulton School**    INSPECTION DATE: **5/7/2019**  
ADDRESS: **5300 S. Hermitage**    IDPH LICENSE NO: **100-05090**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **24**  
MATERIAL DESCRIPTION: **Exterior Brick Mortar**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM**    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1894- Exterior**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Fulton School** REVIEW DATE: **5/24/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

HOMOGENEOUS AREA: **24**

MATERIAL DESCRIPTION: **Exterior Brick Mortar**

MATERIAL LOCATION: **1894- Exterior**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Herman**  
SCHOOL NAME: **Fulton School** INSPECTION DATE: **5/7/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25**  
MATERIAL DESCRIPTION: **Exterior Brick**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1910- Exterior**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 05/07/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Fulton School** REVIEW DATE: **5/24/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

HOMOGENEOUS AREA: **25**

MATERIAL DESCRIPTION: **Exterior Brick**

MATERIAL LOCATION: **1910- Exterior**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Herman**  
SCHOOL NAME: **Fulton School** INSPECTION DATE: **5/7/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26**  
MATERIAL DESCRIPTION: **Exterior Brick Mortar**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1910- Exterior**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 05/07/2019

# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Fulton School** REVIEW DATE: **5/24/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

HOMOGENEOUS AREA: **26**

MATERIAL DESCRIPTION: **Exterior Brick Mortar**

MATERIAL LOCATION: **1910- Exterior**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Herman**  
SCHOOL NAME: **Fulton School** INSPECTION DATE: **5/7/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27**  
MATERIAL DESCRIPTION: **Interior Window Transom Glaze**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1894 Bldg**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Fulton School** REVIEW DATE: **5/24/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

HOMOGENEOUS AREA: **27**

MATERIAL DESCRIPTION: **Interior Window Transom Glaze**

MATERIAL LOCATION: **1894 Bldg**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**



# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Herman**  
SCHOOL NAME: **Fulton School** INSPECTION DATE: **5/7/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28**  
MATERIAL DESCRIPTION: **Drywall**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1910 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Fulton School** REVIEW DATE: **5/24/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

HOMOGENEOUS AREA: **28**

MATERIAL DESCRIPTION: **Drywall**

MATERIAL LOCATION: **1910 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Herman**  
SCHOOL NAME: **Fulton School** INSPECTION DATE: **5/7/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **29**  
MATERIAL DESCRIPTION: **Drywall Joint Compound**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1910 Bldg**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/07/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Fulton School** REVIEW DATE: **5/24/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

HOMOGENEOUS AREA: **29**  
MATERIAL DESCRIPTION: **Drywall Joint Compound**  
MATERIAL LOCATION: **1910 Bldg**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **23281**    BUILDING ID: **3450**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Michael Herman**  
SCHOOL NAME: **Fulton School**    INSPECTION DATE: **5/7/2019**  
ADDRESS: **5300 S. Hermitage**    IDPH LICENSE NO: **100-05090**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **30**  
MATERIAL DESCRIPTION: **12" x 12" Gray Mix Floor Tile ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated**    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Office and Rooms 303 & 303A**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Fulton School** REVIEW DATE: **5/24/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

HOMOGENEOUS AREA: **30**

MATERIAL DESCRIPTION: **12" x 12" Gray Mix Floor Tile ABATED**

MATERIAL LOCATION: **Office and Rooms 303 & 303A**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Herman**  
SCHOOL NAME: **Fulton School** INSPECTION DATE: **5/7/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **31**  
MATERIAL DESCRIPTION: **12" x 12" Gray Mix Floor Tile Mastic ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Office and Rooms 303 & 303A**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Fulton School** REVIEW DATE: **5/24/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

HOMOGENEOUS AREA: **31**

MATERIAL DESCRIPTION: **12" x 12" Gray Mix Floor Tile Mastic ABATED**

MATERIAL LOCATION: **Office and Rooms 303 & 303A**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**



# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **23281**    BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Michael Herman**  
SCHOOL NAME: **Fulton School**    INSPECTION DATE: **5/7/2019**  
ADDRESS: **5300 S. Hermitage**    IDPH LICENSE NO: **100-05090**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **32**  
MATERIAL DESCRIPTION: **12" x 12" Red Mix Floor Tile ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated**    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Fulton School** REVIEW DATE: **5/24/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

HOMOGENEOUS AREA: **32**

MATERIAL DESCRIPTION: **12" x 12" Red Mix Floor Tile ABATED**

MATERIAL LOCATION: **Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Herman**  
SCHOOL NAME: **Fulton School** INSPECTION DATE: **5/7/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **33**  
MATERIAL DESCRIPTION: **12" x 12" Red Mix Floor Tile Mastic ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUILDING ID: **3450**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Fulton School** REVIEW DATE: **5/24/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

HOMOGENEOUS AREA: **33**

MATERIAL DESCRIPTION: **12" x 12" Red Mix Floor Tile Mastic ABATED**

MATERIAL LOCATION: **Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **23281**    BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Michael Herman**  
SCHOOL NAME: **Fulton School**    INSPECTION DATE: **5/7/2019**  
ADDRESS: **5300 S. Hermitage**    IDPH LICENSE NO: **100-05090**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **34**  
MATERIAL DESCRIPTION: **Gray/Black Carpet Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Entrances by Engineers Office and Disciplinary Office**

MATERIAL QUANTITY:    MATERIAL UNITS:

DAMAGE QUANTITY:    DAMAGE UNITS:

COMMENTS: **Not observed 2016**

Inspector's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Fulton School** REVIEW DATE: **5/24/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

HOMOGENEOUS AREA: **34**

MATERIAL DESCRIPTION: **Gray/Black Carpet Adhesive**

MATERIAL LOCATION: **Entrances by Engineers Office and Disciplinary Office**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Herman**  
SCHOOL NAME: **Fulton School** INSPECTION DATE: **5/7/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **35**  
MATERIAL DESCRIPTION: **Purple Carpet Adhesive ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/07/2019

# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Fulton School** REVIEW DATE: **5/24/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

HOMOGENEOUS AREA: **35**

MATERIAL DESCRIPTION: **Purple Carpet Adhesive ABATED**

MATERIAL LOCATION: **Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**



# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Herman**  
SCHOOL NAME: **Fulton School** INSPECTION DATE: **5/7/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **36**  
MATERIAL DESCRIPTION: **Gray/Red Carpet Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 102, 104, 206 & 306**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2016**

Inspector's Signature: \_\_\_\_\_

Date: 05/07/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Fulton School** REVIEW DATE: **5/24/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

HOMOGENEOUS AREA: **36**

MATERIAL DESCRIPTION: **Gray/Red Carpet Adhesive**

MATERIAL LOCATION: **Rooms 102, 104, 206 & 306**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Herman**  
SCHOOL NAME: **Fulton School** INSPECTION DATE: **5/7/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37**  
MATERIAL DESCRIPTION: **Pink Carpet Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 205**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2016**

Inspector's Signature: \_\_\_\_\_

Date: 05/07/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Fulton School** REVIEW DATE: **5/24/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

HOMOGENEOUS AREA: **37**

MATERIAL DESCRIPTION: **Pink Carpet Adhesive**

MATERIAL LOCATION: **Room 205**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Herman**  
SCHOOL NAME: **Fulton School** INSPECTION DATE: **5/7/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **38**  
MATERIAL DESCRIPTION: **Vault Door Core**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Office**  
MATERIAL QUANTITY: **28** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/07/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Fulton School** REVIEW DATE: **5/24/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

HOMOGENEOUS AREA: **38**

MATERIAL DESCRIPTION: **Vault Door Core**

MATERIAL LOCATION: **Office**

MATERIAL QUANTITY: **28**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **23281**    BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Michael Herman**  
SCHOOL NAME: **Fulton School**    INSPECTION DATE: **5/7/2019**  
ADDRESS: **5300 S. Hermitage**    IDPH LICENSE NO: **100-05090**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **39**  
MATERIAL DESCRIPTION: **Lab Table Tops**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Office**  
MATERIAL QUANTITY: **88**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/07/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Fulton School** REVIEW DATE: **5/24/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

HOMOGENEOUS AREA: **39**

MATERIAL DESCRIPTION: **Lab Table Tops**

MATERIAL LOCATION: **Office**

MATERIAL QUANTITY: **88**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**



# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Herman**  
SCHOOL NAME: **Fulton School** INSPECTION DATE: **5/7/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **4**  
MATERIAL DESCRIPTION: **2x4 Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1894- 1st Floor Corridor**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Fulton School** REVIEW DATE: **5/24/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

HOMOGENEOUS AREA: **4**

MATERIAL DESCRIPTION: **2x4 Ceiling Tile**

MATERIAL LOCATION: **1894- 1st Floor Corridor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Herman**  
SCHOOL NAME: **Fulton School** INSPECTION DATE: **5/7/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **40**  
MATERIAL DESCRIPTION: **Brown Mix Carpet Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 002 (Principal's Office)**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/07/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Fulton School** REVIEW DATE: **5/24/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

HOMOGENEOUS AREA: **40**

MATERIAL DESCRIPTION: **Brown Mix Carpet Adhesive**

MATERIAL LOCATION: **Room 002 (Principal's Office)**

MATERIAL QUANTITY: **600**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Herman**  
SCHOOL NAME: **Fulton School** INSPECTION DATE: **5/7/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **41**  
MATERIAL DESCRIPTION: **4" Black Vinyl Baseboard**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Office**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/07/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Fulton School** REVIEW DATE: **5/24/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

HOMOGENEOUS AREA: **41**

MATERIAL DESCRIPTION: **4" Black Vinyl Baseboard**

MATERIAL LOCATION: **Office**

MATERIAL QUANTITY: **100**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Herman**  
SCHOOL NAME: **Fulton School** INSPECTION DATE: **5/7/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **42**  
MATERIAL DESCRIPTION: **4" Black Vinyl Baseboard Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Office**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/07/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Fulton School** REVIEW DATE: **5/24/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

HOMOGENEOUS AREA: **42**

MATERIAL DESCRIPTION: **4" Black Vinyl Baseboard Adhesive**

MATERIAL LOCATION: **Office**

MATERIAL QUANTITY: **100**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**



# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **23281**    BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Michael Herman**  
SCHOOL NAME: **Fulton School**    INSPECTION DATE: **5/7/2019**  
ADDRESS: **5300 S. Hermitage**    IDPH LICENSE NO: **100-05090**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **43**  
MATERIAL DESCRIPTION: **4" Tan Vinyl Baseboard**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Gym**  
MATERIAL QUANTITY: **100**    MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/07/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Fulton School** REVIEW DATE: **5/24/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

HOMOGENEOUS AREA: **43**

MATERIAL DESCRIPTION: **4" Tan Vinyl Baseboard**

MATERIAL LOCATION: **Gym**

MATERIAL QUANTITY: **100**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Herman**  
SCHOOL NAME: **Fulton School** INSPECTION DATE: **5/7/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **44**  
MATERIAL DESCRIPTION: **4" Tan Vinyl Baseboard Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Gym**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/07/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Fulton School** REVIEW DATE: **5/24/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

HOMOGENEOUS AREA: **44**

MATERIAL DESCRIPTION: **4" Tan Vinyl Baseboard Adhesive**

MATERIAL LOCATION: **Gym**

MATERIAL QUANTITY: **100**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Herman**  
SCHOOL NAME: **Fulton School** INSPECTION DATE: **5/7/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **45**  
MATERIAL DESCRIPTION: **5" Brown Vinyl Baseboard**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Staff Lounge & Adjacent Foyer to Women's Washroom**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/07/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Fulton School** REVIEW DATE: **5/24/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

HOMOGENEOUS AREA: **45**

MATERIAL DESCRIPTION: **5" Brown Vinyl Baseboard**

MATERIAL LOCATION: **Staff Lounge & Adjacent Foyer to Women's Washroom**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Herman**  
SCHOOL NAME: **Fulton School** INSPECTION DATE: **5/7/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **46**  
MATERIAL DESCRIPTION: **5" Brown Vinyl Baseboard Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Staff Lounge & Adjacent Foyer to Women's Washroom**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/07/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Fulton School** REVIEW DATE: **5/24/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

HOMOGENEOUS AREA: **46**  
MATERIAL DESCRIPTION: **5" Brown Vinyl Baseboard Adhesive**  
MATERIAL LOCATION: **Staff Lounge & Adjacent Foyer to Women's Washroom**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**



# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Herman**  
SCHOOL NAME: **Fulton School** INSPECTION DATE: **5/7/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **47**  
MATERIAL DESCRIPTION: **12" x 12" Bright Blue Mix Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Staff Lounge & Adjacent Foyer to Women's Washroom, 001**  
MATERIAL QUANTITY: **1700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/07/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Fulton School** REVIEW DATE: **5/24/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

HOMOGENEOUS AREA: **47**  
MATERIAL DESCRIPTION: **12" x 12" Bright Blue Mix Floor Tile**  
MATERIAL LOCATION: **Staff Lounge & Adjacent Foyer to Women's Washroom, 001**  
MATERIAL QUANTITY: **1700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Herman**  
SCHOOL NAME: **Fulton School** INSPECTION DATE: **5/7/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **48**  
MATERIAL DESCRIPTION: **12" x 12" Bright Blue Mix Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Staff Lounge & Adjacent Foyer to Women's Washroom, 001**  
MATERIAL QUANTITY: **850** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/07/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Fulton School** REVIEW DATE: **5/24/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

HOMOGENEOUS AREA: **48**  
MATERIAL DESCRIPTION: **12" x 12" Bright Blue Mix Floor Tile Mastic**  
MATERIAL LOCATION: **Staff Lounge & Adjacent Foyer to Women's Washroom, 001**  
MATERIAL QUANTITY: **850** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Herman**  
SCHOOL NAME: **Fulton School** INSPECTION DATE: **5/7/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **49**  
MATERIAL DESCRIPTION: **Black Boards**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **All Classrooms 1894 bldg**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2016**

Inspector's Signature: \_\_\_\_\_

Date: 05/07/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Fulton School** REVIEW DATE: **5/24/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

HOMOGENEOUS AREA: **49**

MATERIAL DESCRIPTION: **Black Boards**

MATERIAL LOCATION: **All Classrooms 1894 bldg**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Herman**  
SCHOOL NAME: **Fulton School** INSPECTION DATE: **5/7/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **50**  
MATERIAL DESCRIPTION: **Black Board Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **All Classrooms 1894 bldg**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2016**

Inspector's Signature: \_\_\_\_\_ Date: 05/07/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Fulton School** REVIEW DATE: **5/24/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

HOMOGENEOUS AREA: **50**

MATERIAL DESCRIPTION: **Black Board Adhesive**

MATERIAL LOCATION: **All Classrooms 1894 bldg**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**



# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **23281**    BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Michael Herman**  
SCHOOL NAME: **Fulton School**    INSPECTION DATE: **5/7/2019**  
ADDRESS: **5300 S. Hermitage**    IDPH LICENSE NO: **100-05090**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **51**  
MATERIAL DESCRIPTION: **Black Boards**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **All Classrooms 1910 Bldg**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2016**

Inspector's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Fulton School** REVIEW DATE: **5/24/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

HOMOGENEOUS AREA: **51**

MATERIAL DESCRIPTION: **Black Boards**

MATERIAL LOCATION: **All Classrooms 1910 Bldg**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Herman**  
SCHOOL NAME: **Fulton School** INSPECTION DATE: **5/7/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **52**  
MATERIAL DESCRIPTION: **Black Board Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **All Classrooms 1910 Bldg**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2016**

Inspector's Signature: \_\_\_\_\_

Date: 05/07/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Fulton School** REVIEW DATE: **5/24/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

HOMOGENEOUS AREA: **52**

MATERIAL DESCRIPTION: **Black Board Adhesive**

MATERIAL LOCATION: **All Classrooms 1910 Bldg**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Herman**  
SCHOOL NAME: **Fulton School** INSPECTION DATE: **5/7/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **53**  
MATERIAL DESCRIPTION: **Cork Flooring ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Gym/Assembly**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Fulton School** REVIEW DATE: **5/24/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

HOMOGENEOUS AREA: **53**

MATERIAL DESCRIPTION: **Cork Flooring ABATED**

MATERIAL LOCATION: **Gym/Assembly**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Herman**  
SCHOOL NAME: **Fulton School** INSPECTION DATE: **5/7/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **54**  
MATERIAL DESCRIPTION: **Cork Flooring Adhesive ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Gym/Assembly**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 05/07/2019

# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Fulton School** REVIEW DATE: **5/24/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

HOMOGENEOUS AREA: **54**

MATERIAL DESCRIPTION: **Cork Flooring Adhesive ABATED**

MATERIAL LOCATION: **Gym/Assembly**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**



# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Herman**  
SCHOOL NAME: **Fulton School** INSPECTION DATE: **5/7/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **55**  
MATERIAL DESCRIPTION: **12" X 12" White w/Brown Floor Tile ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Main Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Fulton School** REVIEW DATE: **5/24/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

HOMOGENEOUS AREA: **55**

MATERIAL DESCRIPTION: **12" X 12" White w/Brown Floor Tile ABATED**

MATERIAL LOCATION: **Main Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Herman**  
SCHOOL NAME: **Fulton School** INSPECTION DATE: **5/7/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **56**  
MATERIAL DESCRIPTION: **12" X 12" White w/Brown Floor Tile Mastic ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Main Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Fulton School** REVIEW DATE: **5/24/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

HOMOGENEOUS AREA: **56**

MATERIAL DESCRIPTION: **12" X 12" White w/Brown Floor Tile Mastic ABATED**

MATERIAL LOCATION: **Main Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Herman**  
SCHOOL NAME: **Fulton School** INSPECTION DATE: **5/7/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **57**  
MATERIAL DESCRIPTION: **12" X 12" Grey w/Dk Grey Floor Tile ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Main Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Fulton School** REVIEW DATE: **5/24/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

HOMOGENEOUS AREA: **57**

MATERIAL DESCRIPTION: **12" X 12" Grey w/Dk Grey Floor Tile ABATED**

MATERIAL LOCATION: **Main Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Herman**  
SCHOOL NAME: **Fulton School** INSPECTION DATE: **5/7/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **58**  
MATERIAL DESCRIPTION: **12" X 12" Grey w/Dk Grey Floor Tile Mastic ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Main Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Fulton School** REVIEW DATE: **5/24/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

HOMOGENEOUS AREA: **58**

MATERIAL DESCRIPTION: **12" X 12" Grey w/Dk Grey Floor Tile Mastic ABATED**

MATERIAL LOCATION: **Main Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**



# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Herman**  
SCHOOL NAME: **Fulton School** INSPECTION DATE: **5/7/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **59**  
MATERIAL DESCRIPTION: **Refractory Block**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Kiln 012**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2016**

Inspector's Signature: \_\_\_\_\_

Date: 05/07/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Fulton School** REVIEW DATE: **5/24/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

HOMOGENEOUS AREA: **59**

MATERIAL DESCRIPTION: **Refractory Block**

MATERIAL LOCATION: **Kiln 012**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **23281**    BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Michael Herman**  
SCHOOL NAME: **Fulton School**    INSPECTION DATE: **5/7/2019**  
ADDRESS: **5300 S. Hermitage**    IDPH LICENSE NO: **100-05090**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **60**  
MATERIAL DESCRIPTION: **2 X 4 Pinhole Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY: **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Electrical Room**  
MATERIAL QUANTITY: **400**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/07/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Fulton School** REVIEW DATE: **5/24/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

HOMOGENEOUS AREA: **60**

MATERIAL DESCRIPTION: **2 X 4 Pinhole Ceiling Tile**

MATERIAL LOCATION: **Electrical Room**

MATERIAL QUANTITY: **400**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Herman**  
SCHOOL NAME: **Fulton School** INSPECTION DATE: **5/7/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **61**  
MATERIAL DESCRIPTION: **2 X 2 Solid Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Kitchen**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/07/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Fulton School** REVIEW DATE: **5/24/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

HOMOGENEOUS AREA: **61**  
MATERIAL DESCRIPTION: **2 X 2 Solid Ceiling Tile**  
MATERIAL LOCATION: **Kitchen**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Herman**  
SCHOOL NAME: **Fulton School** INSPECTION DATE: **5/7/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **62**  
MATERIAL DESCRIPTION: **12" x 12" Dark Blue Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Closet Next to Room 005 in Basement**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/07/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Fulton School** REVIEW DATE: **5/24/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

HOMOGENEOUS AREA: **62**  
MATERIAL DESCRIPTION: **12" x 12" Dark Blue Floor Tile**  
MATERIAL LOCATION: **Closet Next to Room 005 in Basement**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**



# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Herman**  
SCHOOL NAME: **Fulton School** INSPECTION DATE: **5/7/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **63**  
MATERIAL DESCRIPTION: **Mastic Associated w/ 12" x 12" Dark Blue Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Closet Next to Room 005 in Basement**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/07/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Fulton School** REVIEW DATE: **5/24/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

HOMOGENEOUS AREA: **63**

MATERIAL DESCRIPTION: **Mastic Associated w/ 12" x 12" Dark Blue Floor Tile**

MATERIAL LOCATION: **Closet Next to Room 005 in Basement**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Herman**  
SCHOOL NAME: **Fulton School** INSPECTION DATE: **5/7/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **64**  
MATERIAL DESCRIPTION: **Beige Linoleum**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rm. 312**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/07/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Fulton School** REVIEW DATE: **5/24/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

HOMOGENEOUS AREA: **64**

MATERIAL DESCRIPTION: **Beige Linoleum**

MATERIAL LOCATION: **Rm. 312**

MATERIAL QUANTITY: **600**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Herman**  
SCHOOL NAME: **Fulton School** INSPECTION DATE: **5/7/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **65**  
MATERIAL DESCRIPTION: **Yellow Glue Associated w/ Beige Linoleum**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rm. 312**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/07/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Fulton School** REVIEW DATE: **5/24/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

HOMOGENEOUS AREA: **65**

MATERIAL DESCRIPTION: **Yellow Glue Associated w/ Beige Linoleum**

MATERIAL LOCATION: **Rm. 312**

MATERIAL QUANTITY: **600**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Herman**  
SCHOOL NAME: **Fulton School** INSPECTION DATE: **5/7/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **9**  
MATERIAL DESCRIPTION: **Plaster**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1910- Throughout**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Fulton School** REVIEW DATE: **5/24/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

HOMOGENEOUS AREA: **9**

MATERIAL DESCRIPTION: **Plaster**

MATERIAL LOCATION: **1910- Throughout**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**



# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Herman**  
SCHOOL NAME: **Fulton School** INSPECTION DATE: **5/7/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **A**  
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1894- Boiler Room**  
MATERIAL QUANTITY: **50** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Fulton School** REVIEW DATE: **5/24/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

HOMOGENEOUS AREA: **A**  
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**  
MATERIAL LOCATION: **1894- Boiler Room**  
MATERIAL QUANTITY: **50** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **23281**    BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Michael Herman**  
SCHOOL NAME: **Fulton School**    INSPECTION DATE: **5/7/2019**  
ADDRESS: **5300 S. Hermitage**    IDPH LICENSE NO: **100-05090**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **B**  
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM**    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **1894- Ground Floor**

MATERIAL QUANTITY:    MATERIAL UNITS:

DAMAGE QUANTITY:    DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Fulton School** REVIEW DATE: **5/24/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

HOMOGENEOUS AREA: **B**

MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**

MATERIAL LOCATION: **1894- Ground Floor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Herman**  
SCHOOL NAME: **Fulton School** INSPECTION DATE: **5/7/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **C**  
MATERIAL DESCRIPTION: **Boiler Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1894- Boiler Room - ABATED 1994**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Fulton School** REVIEW DATE: **5/24/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

HOMOGENEOUS AREA: **C**

MATERIAL DESCRIPTION: **Boiler Insulation**

MATERIAL LOCATION: **1894- Boiler Room - ABATED 1994**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Herman**  
SCHOOL NAME: **Fulton School** INSPECTION DATE: **5/7/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **D**  
MATERIAL DESCRIPTION: **Aircell Pipe Fitting**  
HISTORICAL AHERA DAMAGE CATEGORY: **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1894- Boiler Room, Tank Room**  
MATERIAL QUANTITY: **50** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/07/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Fulton School** REVIEW DATE: **5/24/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

HOMOGENEOUS AREA: **D**  
MATERIAL DESCRIPTION: **Aircell Pipe Fitting**  
MATERIAL LOCATION: **1894- Boiler Room, Tank Room**  
MATERIAL QUANTITY: **50** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**



# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Herman**  
SCHOOL NAME: **Fulton School** INSPECTION DATE: **5/7/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **E**  
MATERIAL DESCRIPTION: **Cardboard Pipe Fitting**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1894- Ground Floor**  
MATERIAL QUANTITY: **50** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/07/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Fulton School** REVIEW DATE: **5/24/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

HOMOGENEOUS AREA: **E**  
MATERIAL DESCRIPTION: **Cardboard Pipe Fitting**  
MATERIAL LOCATION: **1894- Ground Floor**  
MATERIAL QUANTITY: **50** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **23281**    BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Michael Herman**  
SCHOOL NAME: **Fulton School**    INSPECTION DATE: **5/7/2019**  
ADDRESS: **5300 S. Hermitage**    IDPH LICENSE NO: **100-05090**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **F**  
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY: **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1910- Ground Floor**  
MATERIAL QUANTITY: **230**    MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/07/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Fulton School** REVIEW DATE: **5/24/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

HOMOGENEOUS AREA: **F**  
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**  
MATERIAL LOCATION: **1910- Ground Floor**  
MATERIAL QUANTITY: **230** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Herman**  
SCHOOL NAME: **Fulton School** INSPECTION DATE: **5/7/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **G**  
MATERIAL DESCRIPTION: **Aircell Pipe Fitting**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1910- Ground Floor**  
MATERIAL QUANTITY: **30** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Fulton School** REVIEW DATE: **5/24/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

HOMOGENEOUS AREA: **G**  
MATERIAL DESCRIPTION: **Aircell Pipe Fitting**  
MATERIAL LOCATION: **1910- Ground Floor**  
MATERIAL QUANTITY: **30** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Herman**  
SCHOOL NAME: **Fulton School** INSPECTION DATE: **5/7/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **H**  
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1910- Addition**  
MATERIAL QUANTITY: **230** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/07/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Fulton School** REVIEW DATE: **5/24/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

HOMOGENEOUS AREA: **H**  
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**  
MATERIAL LOCATION: **1910- Addition**  
MATERIAL QUANTITY: **230** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**



# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Herman**  
SCHOOL NAME: **Fulton School** INSPECTION DATE: **5/7/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **I**  
MATERIAL DESCRIPTION: **Cardboard Pipe Fitting**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1910- Ground Floor, 2nd Floor. Teacher Toilet**  
MATERIAL QUANTITY: **30** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/07/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Fulton School** REVIEW DATE: **5/24/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

HOMOGENEOUS AREA: **I**  
MATERIAL DESCRIPTION: **Cardboard Pipe Fitting**  
MATERIAL LOCATION: **1910- Ground Floor, 2nd Floor. Teacher Toilet**  
MATERIAL QUANTITY: **30** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Herman**  
SCHOOL NAME: **Fulton School** INSPECTION DATE: **5/7/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **J**  
MATERIAL DESCRIPTION: **Fiberglass Pipe Fitting**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Not Tested** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1910- Ground Floor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not a suspect material**

Inspector's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Fulton School** REVIEW DATE: **5/24/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

HOMOGENEOUS AREA: **J**

MATERIAL DESCRIPTION: **Fiberglass Pipe Fitting**

MATERIAL LOCATION: **1910- Ground Floor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Herman**  
SCHOOL NAME: **Fulton School** INSPECTION DATE: **5/7/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **K**  
MATERIAL DESCRIPTION: **Fiberglass Pipe Fitting**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Not Tested** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1894- Ground Level**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not a suspect material**

Inspector's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Fulton School** REVIEW DATE: **5/24/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

HOMOGENEOUS AREA: **K**

MATERIAL DESCRIPTION: **Fiberglass Pipe Fitting**

MATERIAL LOCATION: **1894- Ground Level**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **23281**    BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Michael Herman**  
SCHOOL NAME: **Fulton School**    INSPECTION DATE: **5/7/2019**  
ADDRESS: **5300 S. Hermitage**    IDPH LICENSE NO: **100-05090**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **L**  
MATERIAL DESCRIPTION: **Preform Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY: **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile**    FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1894- Tank Room**  
MATERIAL QUANTITY: **30**    MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Fulton School** REVIEW DATE: **5/24/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

HOMOGENEOUS AREA: **L**

MATERIAL DESCRIPTION: **Preform Pipe Insulation**

MATERIAL LOCATION: **1894- Tank Room**

MATERIAL QUANTITY: **30**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**



# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Herman**  
SCHOOL NAME: **Fulton School** INSPECTION DATE: **5/7/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **M**  
MATERIAL DESCRIPTION: **Preform Pipe Fitting**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1894- Tank Room**  
MATERIAL QUANTITY: **10** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/07/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Fulton School** REVIEW DATE: **5/24/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

HOMOGENEOUS AREA: **M**

MATERIAL DESCRIPTION: **Preform Pipe Fitting**

MATERIAL LOCATION: **1894- Tank Room**

MATERIAL QUANTITY: **10**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Herman**  
SCHOOL NAME: **Fulton School** INSPECTION DATE: **5/7/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **N**  
MATERIAL DESCRIPTION: **Boiler Refractory Cement**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1894- Boiler Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23281** BUIDLING ID: **3450**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Fulton School** REVIEW DATE: **5/24/2019**  
ADDRESS: **5300 S. Hermitage** IDPH LICENSE NO: **100-05090**

---

HOMOGENEOUS AREA: **N**

MATERIAL DESCRIPTION: **Boiler Refractory Cement**

MATERIAL LOCATION: **1894- Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# **Chicago Public Schools**

**Carnow, Conibear and Associates**

***2019 AHERA REINSPECTION***

# APPENDIX B

## Inspector and Management Planner Licenses

---



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • [www.dph.illinois.gov](http://www.dph.illinois.gov)

**MICHAEL D HERMAN**  
 5121 N MONITOR  
 CHICAGO, IL 60630

4/10/2019



ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 05090

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

**COPY OF THE ASBESTOS PROFESSIONAL LICENSE**

Front of License

Back of License

		<b>ASBESTOS          PROFESSIONAL          LICENSE</b>		<b>ENDORSEMENTS</b>	<b>TC EXPIRES</b>
<b>ID NUMBER</b> 100 - 05090	<b>ISSUED</b> 4/10/2019	<b>EXPIRES</b> 05/15/2020	INSPECTOR		1/17/2020
<b>MICHAEL D HERMAN</b> 5121 N MONITOR CHICAGO, IL 60630 Environmental Health				PROJECT MANAGER AIR SAMPLING PROFESSIONAL	1/16/2020
<p style="text-align: center;"><b>Alteration of this license shall result in legal action</b>          This license issued under authority of the State of Illinois          Department of Public Health          This license is valid only when accompanied by a valid          training course certificate.</p>					

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: [dph.illinois.gov/topics-services/environmental-health-protection/asbestos](http://dph.illinois.gov/topics-services/environmental-health-protection/asbestos)  
 EMAIL Address: [dph.asbestos@illinois.gov](mailto:dph.asbestos@illinois.gov)

**PROTECTING HEALTH, IMPROVING LIVES**  
*Nationally Accredited by PHAB*

2019



# OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900 ♦ [www.otssafety.com](http://www.otssafety.com)

## Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

**Michael Herman**

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 1/17/2019

Exam Date: 1/17/2019

Expiration Date: 1/17/2020

Certificate Number: BIR1901170228

Kathy DeSalvo, Director





525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • www.dph.illinois.gov

**MICHAEL D HERMAN**  
5121 N MONITOR  
CHICAGO, IL 60630

4/25/2018



ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 05090

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

**COPY OF THE ASBESTOS PROFESSIONAL LICENSE**

Front of License

Back of License

 <p><b>ASBESTOS PROFESSIONAL LICENSE</b></p>		<p><b>ENDORSEMENTS</b></p> <p>INSPECTOR</p> <p>PROJECT MANAGER AIR SAMPLING PROFESSIONAL</p>	<p><b>TC EXPIRES</b></p> <p>1/18/2019</p> <p>1/17/2019</p>
<p>ID NUMBER 100 - 05090</p> <p><b>MICHAEL D HERMAN</b> 5121 N MONITOR CHICAGO, IL 60630</p> <p>Environmental Health</p>	<p>ISSUED <b>4/25/2018</b></p> <p>EXPIRES 05/15/2019</p> 	<p><b>Alteration of this license shall result in legal action</b> This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.</p>	

*Michael D Herman*  
*[Signature]*

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: [dph.illinois.gov/topics-services/environmental-health-protection/asbestos](http://dph.illinois.gov/topics-services/environmental-health-protection/asbestos)  
EMAIL Address: [dph.asbestos@illinois.gov](mailto:dph.asbestos@illinois.gov)

**PROTECTING HEALTH. IMPROVING LIVES**  
Nationally Accredited by PHAB

2015



**OCCUPATIONAL TRAINING & SUPPLY, INC.**

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900

# Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

**Evan Christian**

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 12/2/2015

Exam Date: 12/2/2015

Expiration Date: 12/2/2016

Certificate Number: BIR1512024159

  
Katy DeSalvo, Director

**Reliable**  
**Environmental**  
**Solutions, Inc.** **RES**

*This is to certify that* **Evan Christian**

*has on January 28 & 29, 2016, in Springfield, Illinois,  
completed the requirements for asbestos accreditation under Section 206 of TSCA Title II*

**Asbestos Management Planner Initial Training**

*as accredited by the State of Illinois and approved by the U.S.E.P.A. under 40 CFR 763 (AHERA)  
and passed the associated examination with a score of 70% or higher*

Course Date: January 28 & 29, 2016

Examination Date: January 29, 2016

Expiration Date: January 29, 2017

Certificate Number: MP/0103

*William S. Williams*

Training Program Manager, William S. Williams

4211 Westgate Drive, Springfield, Illinois ☐ 217.787.9800 ☐ 217.787.9801 FAX ☐ [www.ReliableEnv.com](http://www.ReliableEnv.com)

2019



**OCCUPATIONAL TRAINING & SUPPLY, INC.**

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900 ♦ [www.otssafety.com](http://www.otssafety.com)

# Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that  
**Evan Christian**

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/19/2019

Exam Date: 11/19/2019

Expiration Date: 11/19/2020

Certificate Number: BIR1911192384

  
Kathy DeSalvo, Director



**ASBESTOS  
PROFESSIONAL  
LICENSE**

ID NUMBER  
**100 - 19466**

ISSUED  
**4/12/2019**

EXPIRES  
**05/15/2020**

**EVAN I CHRISTIAN**  
3024 N RACINE AVE, APT 2  
CHICAGO, IL 60657

Environmental Health



**ENDORSEMENTS**

**TC EXPIRES**

INSPECTOR

11/28/2019

MANAGEMENT PLANNER

1/5/2019

PROJECT MANAGER

2/5/2020

AIR SAMPLING PROFESSIONAL

**Alteration of this license shall result in legal action**  
This license issued under authority of the State of Illinois  
Department of Public Health

This license is valid only when accompanied by a valid  
training course certificate.

2019



**OCCUPATIONAL TRAINING & SUPPLY, INC.**

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900 ♦ [www.otssafety.com](http://www.otssafety.com)

# Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

**Evan Christian**

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Course Date: 1/7/2019

Exam Date: 1/7/2019


Expiration Date: 1/7/2020

Certificate Number: MPR1901070063

  
Kathy DeSalvo, Director

# Evan Christian

Illinois Licensed Project Manager, and Air Sampling Professional



ENDORSEMENTS	TC EXPIRES
PROJECT MANAGER AIR SAMPLING PROFESSIONAL	12/12/2015
<b>Alteration of this license shall result in legal action</b> This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	

**CARNOW  
CONIBEAR**

# APPENDIX C

## Laboratory Accreditations

---



# APPENDIX D

## Laboratory Results

---

# APPENDIX E

## Chain of Custody Forms

---

## Three-Year Reinspection Key to Terms

	<b>CODE</b>	<b>KEY</b>
<b>MATERIAL</b>		
	ACBM	Asbestos Containing Building Materials
<b>MATERIAL CATEGORY</b>		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
<b>MATERIAL UNITS</b>		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
<b>DAMAGE TYPE</b>		
	Loc	Localized
	Dist	Distributed