

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM**

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-2215
SCHOOL NAME: Gary School
ADDRESS OF SCHOOL: 3740 W. 31st St.
CITY: Chicago, IL, 60623

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **4/4/2016**

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II *(Please type or print)*

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 10/1/2019 ENROLLMENT 1020
IDPH INSPECTOR LICENSE NUMBER: 100-19554
IDPH LICENSED INSPECTOR NAME(Please Print): Carol Ashman
IDPH MP LICENSE NUMBER: 100-19466
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Evan Christian

DESIGNATED PERSON (Please Print): Robert Christlieb PHONE: (773) 553-3197



10/1/2019

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Gary School

3740 W. 31st St.
Chicago, IL, 60623

Unit: 23311
Building ID: 3520

IDPH ID Number: 14-016-2990-2215

REPORT DATE:

Tuesday, October 01, 2019

Prepared for:

**Chicago Public Schools
42 West Madison Street
Chicago, IL 60602**

Prepared by:

Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Chicago, Il, 60607

Phone (312) 762-2900

Fax (312) 782-5145

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

October 1, 2019

Mr. Glen E. Garner
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2019 Three-Year Reinspections

Dear Mr. Glen:

Carnow, Conibear and Associates, Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 3, 4 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 23311 Region: 04 IDPH ID:14-016-2990-2215

School: Gary School Building ID: 3520

Address: 3740 W. 31st St.
Chicago, IL, 60623

Building Contact: Contact Phone:

Current Building Owners: Chicago Public Schools

Review Date: 10/18/2019

Inspector: Carol Ashman Inspector IDPH License: 100-19554
Management Planner: Evan Christian Management Planner IDPH License: 100-19466

If you have any questions or comments, please contact us at (312) 762-2900

Sincerely,
Carnow, Conibear and Associates

Evan Christian
100-19466

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: October 01, 2019

RE: Gary School, Unit 23311
3740 W. 31st St.
Chicago, IL, 60623

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2019 asbestos three year re-inspection has been completed at Gary School, following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at Gary School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Robert Christlieb, the designated Local Education Authority's Designated Person at (773) 553-3197 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Gary School
Address: 3740 W. 31st St.
IDPH ID: 14-016-2990-2215
Contact:

Unit: 23311
Chicago, IL, 60623
Building ID: 3520
Phone:

Region: 04

2. Description of Facility

Original Construction:
Total Square Footage:
Current Occupancy: 1020

Additional Construction:
No of Floors:

3. LEA Designated Person

Contact: Robert Christlieb
Address: 42 West Madison Street
Chicago, IL 60602

Phone: (773) 553-3197

4. Managing Environmental Consultant

MEC: Carnow, Conibear and Associates
Contact: Doug McCormick
Address 600 West Van Buren St., Ste 500
Chicago, IL, 60607
Phone: (312) 762-2900

Fax: (312) 782-5145

5. Inspector

Inspector Name: Carol Ashman

Inspector IDPH license # 100-19554

Signature:
Date: 10/1/2019

6. Management Planner

Management Planner Name: Evan Christian

Management Planner IDPH license # 100-19466

Signature:
Date: 10/18/2019

7. Review Date: 10/18/2019

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature:



Date: 10/1/2019

Name: Robert Christlieb

II. EXECUTIVE SUMMARY

Carnow, Conibear and Associates was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Gary School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.85 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas(HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 3520:

1	Plaster
11	Tan Linoleum
15A	4" Black Vinyl Baseboards
26	2'x2' Ceiling Panels
2B	9"x9" Tan Floor Tile w/Brown and White
2C	9"x9" Brown Floor Tile w/White and Red
2G	9" x 9" Brown Floor Tile
2H	9"x9" Green Floor Tile w/White Streaks
32	Interior Brick

39	Blue/Green/Gray/White Ceramic Tile Grout
3D	12"x12" White Floor Tile
42	Black Border Tile
47	Boiler Wrap #1
48	Boiler Wrap #2
49	Insulation Over Fiberglass
51	Duct Insulation
52	Refractory Cement in Doors of #1 Boiler
53	Refractory Cement in Doors of #2 Boiler
54	Firebrick in Boiler #1
55	Firebrick in Boiler #2
5A	12"x12" Multi-Gray Floor Tile
79	12 x 12 Lt. Grey 2/ Dk. Grey & White Floor Tile
86	12" x 12" Beige Floor Tile
87	Mastic Associated w/ 12" x 12" Beige Floor Tile
88	Vinyl Sheeting Glued on Plywood
89	2' x 4' Ceiling Tile
B1	Cardboard Pipe Insulation

B. The following new homogenous areas have been identified for Building 3520:

90	9"x9" Brown with white streak floor tile
90A	9"x9" brown with white streak floor tile mastic
91	9"x9" dark brown floor tile patch
91A	9"x9" dark brown with white streak floor tile mastic
92	Brown carpet mastic
93	12"x12" gray floor tile with white spec
93A	12"x12" gray with white floor tile mastic
94	12"x12" Lt. Blue with white floor tile
94A	12"x12" Lt. Blue with white floor tile mastic
95	12"x12" white floor tile with beige streak
95A	12"x12" white with beige floor tile mastic
96	12"x12" Brown floor tile
96A	12"x12" Brown floor tile mastic
97	12"x12" Lt. Blue with dark blue speck floor tile
97A	12"x12" Lt. Blue with dark blue floor tile mastic
98	New building 12x12 white with gray and black speck floor tile
98A	12"x12" white with gray and black specks floor tile mastic

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

1	Plaster
11	Tan Linoleum
13	Beige Linoleum
15A	4" Black Vinyl Baseboards
15B	6" Black Vinyl Baseboard
16A	4" Black Vinyl Baseboard Mastic
16B	6" Black Vinyl Baseboard Mastic
19	Exterior Brick - Not AHERA
20	Exterior Brick Mortar
21	Exterior Door Caulk
22	Drywall
23	Black Cementitious Flooring
24	Green Terrazzo
25	Brown Terrazzo Wall Panels
26	2'x2' Ceiling Panels
27	Terrazzo Basin
28	Yellow Baseboard
29	Yellow Baseboard Mastic
30	Blue Baseboard
31	Blue Baseboard Mastic
32	Interior Brick
33	Interior Brick Mortar
34	Terrazzo Baseboard
35	Ceramic Tile Grout
36	Glazed Brick Mortar
37	Interior Door Caulk
38	Block Mortar
39	Blue/Green/Gray/White Ceramic Tile Grout
3A	12"x12" Beige Floor Tile w/Brown Streaks
3C	12"x12" Beige Floor Tile w/Brown and White Streaks
4	12"x12" Ceiling Tile
40	Gray Carpet Mastic (Brown)
41	Cinder Block Mortar
43	Black Border Tile Mastic
44	2'x4' Ceiling Panels
45	Terrazzo
46	12"x12" Terrazzo
49	Insulation Over Fiberglass
51	Duct Insulation
52	Refractory Cement in Doors of #1 Boiler
53	Refractory Cement in Doors of #2 Boiler

54	Firebrick in Boiler #1
55	Firebrick in Boiler #2
56	4" Black Vinyl Baseboard
57	4" Black Vinyl Baseboard Mastic
5A	12"x12" Multi-Gray Floor Tile
6	Brown Linoleum
60	Green Ceramic Tile Grout
61	Gray Carpet Mastic
65	Exterior Door Caulk
66	12"x12" Multi-Gray Floor Tile Mastic
68	Cementitious Pipe Joint Insulation
71	Vault Door Liner
72	12" x 12" Tan w/ Lt. Brown floor tile
73	Mastic w/ 12" x 12" tan w/ Lt. brown floor tile
74	12 x 12 Grey w/ Dk. Grey & White Floor Tile
75	mastic w/ 12 x 12 Grey w/ Dk. Grey & White floor tile
76	purple carpet adhesive
77	12 x 12 Tan Floor Tile
78	Mastic w/ 12 x 12 Tan Floor Tile
79	12 x 12 Lt. Grey 2/ Dk. Grey & White Floor Tile
80	Mastic w/ 12 x 12 Lt. Grey w/ Dk. Grey & White Floor Tile
81	12 x 12 Lt. Blue w/ Dk. Blue & White Floor Tile
82	Mastic w/ 12 x 12 Lt. Blue 2/ Dk. Blue & White Floor Tile
83	Tan Linoleum
84	Adhesive w/ Tan Linoleum
85	Brown Carpet Adhesive
86	12" x 12" Beige Floor Tile
87	Mastic Associated w/ 12" x 12" Beige Floor Tile
88	Vinyl Sheeting Glued on Plywood
89	2' x 4' Ceiling Tile
90	9"x9" Brown with white streak floor tile
90A	9"x9" brown with white streak floor tile mastic
91	9"x9" dark brown floor tile patch
91A	9"x9" dark brown with white streak floor tile mastic
92	Brown carpet mastic
93	12"x12" gray floor tile with white spec
93A	12"x12" gray with white floor tile mastic
94	12"x12" Lt. Blue with white floor tile
94A	12"x12" Lt. Blue with white floor tile mastic
95	12"x12" white floor tile with beige streak
95A	12"x12" white with beige floor tile mastic
96	12"x12" Brown floor tile
96A	12"x12" Brown floor tile mastic
97	12"x12" Lt. Blue with dark blue speck floor tile
97A	12"x12" Lt. Blue with dark blue floor tile mastic

98	New building 12x12 white with gray and black speck floor tile
98A	12"x12" white with gray and black specks floor tile mastic
9A	12" x 12" Beige Floor Tile w/ Brown Streaks Mastic
9C	12"x12" Beige Floor Tile w/ Brn & Wh Strks Mastic
A2	Cementitious Insulation on Joints off Fiberglass
B2	Cementitious Insulation off Paper Wrap Pipe Runs

The following areas were deemed to be inaccessible:

16A	4" Black Vinyl Baseboard Mastic
16B	6" Black Vinyl Baseboard Mastic
29	Yellow Baseboard Mastic
31	Blue Baseboard Mastic
40	Gray Carpet Mastic (Brown)
43	Black Border Tile Mastic
61	Gray Carpet Mastic
66	12"x12" Multi-Gray Floor Tile Mastic
67	12"x12" Gray Floor Tile w/White Streaks Mastic
87	Mastic Associated w/ 12" x 12" Beige Floor Tile
8A	9"x9" Tan w/Ye, Blue, and White Floor Tile Mastic
8B	9"x9" Tan Floor Tile w/Brown and White Mastic
8C	9"x9" Brown Floor Tile w/White and Red Mastic
8D	9" x 9" Beige Floor Tile Mastic
8E	9" x 9" Black Floor Tile Mastic
8F	9" x 9" Maroon Floor Tile Mastic
8G	9" x 9" Brown Floor Tile Mastic
8H	9" x 9" Green Floor Tile Mastic
8I	9" x 9" Aqua Floor Tile Mastic
8J	9" x 9" Aqua Floor Tile Mastic
8K	9" x 9" Yellow Floor Tile Mastic
9A	12" x 12" Beige Floor Tile w/ Brown Streaks Mastic
9B	12" x 12" Beige Floor Tile w/ Brn & Wh Spks Mastic
9C	12"x12" Beige Floor Tile w/ Brn & Wh Strks Mastic
9D	12" x 12" White Floor Tile Mastic

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Carol Ashman, IDPH License # 100-19554. The Management Plan was updated by Evan Christian, IDPH License # 100-19466. Inspector and

Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Gary School Building 3520 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Gary School Unit 23311 Building ID 3520

Address 3740 W. 31st St. Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
1	Plaster	60,000	SF	Throughout 1909 Building	ASSUMED	SURFACE	Y	NONE	0		Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
10	Number Skipped				UNDEFINE D									
11	Tan Linoleum	576	SF	Kitchen of 1909 Building	ASSUMED	MISC	N	DIST	25		Yes	ACBM with the potential for damage	3	LOW
13	Beige Linoleum	720	SF	Lunchroom, 008, and 009 of 1909 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
15A	4" Black Vinyl Baseboards	1,800	LF	Classrooms in 1972 Annex	ASSUMED	MISC	N	LOC	10		Yes	Damaged or significantly damaged friable misc. ACBM	5	LOW
15B	6" Black Vinyl Baseboard	480	LF	Hallways of 1972 Annex	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
16A	4" Black Vinyl Baseboard Mastic	1,800	LF	Classrooms of 1972 Annex	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
16B	6" Black Vinyl Baseboard Mastic	480	LF	Hallways of 1972 Annex	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
19	Exterior Brick - Not AHERA			1909 Building	ASSUMED	MISC								
2 D	9" x 9" Beige Floor Tile			104	CHR	MISC								
20	Exterior Brick Mortar	14,000	SF	1909 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
21	Exterior Door Caulk	120	LF	1909 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
22	Drywall	1,440	SF	Teacher's Room, Lunchroom, 008, 009 of 1909 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
23	Black Cementitious Flooring	1,760	SF	First Floor Corridor and Stair Landings of 1909 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
24	Green Terrazzo	40	SF	Women's Washroom of 1909 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
25	Brown Terrazzo Wall Panels	40	SF	Men's and Women's Washrooms of 1909 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
26	2'x2' Ceiling Panels	800	SF	Lunchroom of 1909 Building	ASSUMED	MISC	Y	NONE	0		Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
27	Terrazzo Basin	20	SF	Kitchen and Sink Closet of 1909 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
28	Yellow Baseboard	200	SF	Lunchroom of 1909	ASSUMED	MISC	N	NONE	0		No	ACBM with the		LOW

Chicago Public Schools

School Gary School Unit 23311 Building ID 3520

Address 3740 W. 31st St. Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Building								potential for damage		
29	Yellow Baseboard Mastic	200	SF	Lunchroom of 1909 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
2A	9"x9" Tan w/Yellow, Blue, and White Floor Tile	800	SF	100 of 1909 Building	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
2B	9"x9" Tan Floor Tile w/Brown and White	400	SF	100 and Room 208 of 1909 Building	CHR	MISC	N	LOC	20		Yes	Damaged or significantly damaged friable misc. ACBM	5	LOW
2C	9"x9" Brown Floor Tile w/White and Red	800	SF	208 and Faculty Washroom of 1909 Building	CHR	MISC	N	LOC	2		Yes	Damaged or significantly damaged friable misc. ACBM	5	LOW
2E	9" x 9" Black Floor Tile	50	SF	Faculty Washroom of 1909 Building	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
2F	9" x 9" Maroon Floor Tile	20	SF	Faculty Washroom of 1909 Building	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
2G	9" x 9" Brown Floor Tile	750	SF	208 of 1909 Building	CHR	MISC	N	LOC	20		Yes	Damaged or significantly damaged friable misc. ACBM	5	LOW
2H	9"x9" Green Floor Tile w/White Streaks	400	SF	204 of 1909 Building	CHR	MISC	N	LOC	15		Yes	Damaged or significantly damaged friable misc. ACBM	5	LOW
2I	9"x9" Aqua Floor Tiles w/White Streaks	415	SF	Room 204 of 1909 Building	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
2J	9"x9" Aqua Floor Tile w/Black and White Specks	40	SF	301 of 1909 Building	CHR	MISC	N	LOC	2		No	Damaged or significantly damaged friable misc. ACBM	3	LOW
2K	9"x9" Yellow Floor Tile w/White Streaks	50	SF	301 of 1909 Building	CHR	MISC	N	LOC	2		No	Damaged or significantly damaged friable misc. ACBM	5	LOW
2L	9"x9" Gray Floor Tile w/White Streaks			Gym of 1909 Building	CHR	MISC								
2M	9"x9" Light Brown Floor Tile w/White Swirls			Gym of 1909 Building	CHR	MISC								
30	Blue Baseboard	108	SF	1st Room West of E Entrance of 1909 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
31	Blue Baseboard Mastic	100	SF	1st Room West of E Entrance of 1909 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
32	Interior Brick	80,000	SF	Throughout 1909 Building	ASSUMED	MISC	N	LOC	4		Yes	Damaged or significantly damaged friable misc. ACBM	5	LOW
33	Interior Brick Mortar	80,000	SF	Throughout 1909 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Gary School Unit 23311 Building ID 3520

Address 3740 W. 31st St. Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
34	Terrazzo Baseboard	300	SF	Throughout 1909 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
35	Ceramic Tile Grout	70	SF	Throughout Entrances of 1909 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
36	Glazed Brick Mortar	400	SF	Throughout 1909 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
37	Interior Door Caulk	200	LF	Throughout 1909 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
38	Block Mortar	10	SF	Auditorium	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
39	Blue/Green/Gray/White Ceramic Tile Grout	500	SF	Throughout Boy's and Girl's Washrooms of 1909 Building	ASSUMED	MISC	N	NONE	8		Yes	Damaged or significantly damaged friable misc. ACBM	5	LOW
3A	12"x12" Beige Floor Tile w/Brown Streaks	700	SF	005 of 1909 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
3B	12"x12" Beige Floor Tile w/Brown and White Specks	750	SF	101 of 1909 Building	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
3C	12"x12" Beige Floor Tile w/Brown and White Streaks	750	SF	206 of 1909 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
3D	12"x12" White Floor Tile	700	SF	301 of 1909 Building	CHR	MISC	N	LOC	10		Yes	Damaged or significantly damaged friable misc. ACBM	3	LOW
4	12"x12" Ceiling Tile			Throughout Annex	ASSUMED	MISC								
40	Gray Carpet Mastic (Brown)	500	SF	Office, 105, and 106 of 1909 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
41	Cinder Block Mortar	1,300	SF	Throughout 1909 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
42	Black Border Tile	200	SF	204 of 1909 Building	CHR	MISC	N	LOC	3		Yes	Damaged or significantly damaged friable misc. ACBM	5	LOW
43	Black Border Tile Mastic	50	SF	204 of 1909 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
44	2'x4' Ceiling Panels	200	SF	Kitchen of 1909 Building	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
45	Terrazzo	150	SF	Washroom in Room D of 1909 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
46	12"x12" Terrazzo	150	SF	D Room of 1909 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
47	Boiler Wrap #1	500	SF	Boiler Room of 1909 Building	CHR	MISC	Y	LOC	50		Yes	Damaged or significantly damaged friable misc. ACBM	1	MODERATE

Chicago Public Schools

School Gary School Unit 23311 Building ID 3520

Address 3740 W. 31st St. Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
48	Boiler Wrap #2	500	SF	Boiler Room of 1909 Building	CHR	MISC	Y	LOC	50		Yes	Damaged or significantly damaged friable misc. ACBM	1	MODERATE
49	Insulation Over Fiberglass	140	LF	Maintenance Room of 1909 Building	ASSUMED	TSI	Y	NONE	0		Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
50	Mag Block Insulation	100	LF	Boiler Room of 1909 Building	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
51	Duct Insulation	300	SF	Boiler Room of 1909 Building	ASSUMED	TSI	Y	NONE	0		Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
52	Refractory Cement in Doors of #1 Boiler	20	SF	Boiler Room of 1909 Building	ASSUMED	TSI	Y	NONE	0		Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
53	Refractory Cement in Doors of #2 Boiler	20	SF	Boiler Room of 1909 Building	ASSUMED	TSI	Y	NONE	0		Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
54	Firebrick in Boiler #1	200	SF	Boiler Room of 1909 Building	ASSUMED	TSI	Y	NONE	0		Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
55	Firebrick in Boiler #2	200	SF	Boiler Room of 1909 Building	ASSUMED	TSI	Y	NONE	0		Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
56	4" Black Vinyl Baseboard			004 of 1909 Building	ASSUMED	MISC								
57	4" Black Vinyl Baseboard Mastic			004 of 1909 Building	ASSUMED	MISC								
5A	12"x12" Multi-Gray Floor Tile	1,900	SF	Hallways of 1972 Annex	ASSUMED	MISC	N	LOC	15		Yes	Damaged or significantly damaged friable misc. ACBM	5	LOW
5B	12"x12" Gray Floor Tile w/White Streaks	600	SF	Book Room and Storage in 1972 Annex	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
6	Brown Linoleum	400	SF	Basement Room D of 1909 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
60	Green Ceramic Tile Grout	10	SF	Entrances of 1972 Annex	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
61	Gray Carpet Mastic	600	SF	Classrooms, Teacher's Lounge and Office of 1972 Annex	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
65	Exterior Door Caulk	84	LF	Throughout 1972 Annex	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Gary School Unit 23311 Building ID 3520

Address 3740 W. 31st St. Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
66	12"x12" Multi-Gray Floor Tile Mastic	1,900	SF	Hallways of 1972 Annex	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
67	12"x12" Gray Floor Tile w/White Streaks Mastic	600	SF	Book Room and Storage in 1972 Annex	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
68	Cementitious Pipe Joint Insulation	4	LF	Electric Room (Behind Wall) in 1972 Annex	ASSUMED	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
7	Transite Panels			Basement (Abated)	ABATED			None						
70	Fiberglass Insulation			Electric Room of 1972 Annex	NOT_TESTED									
71	Vault Door Liner	15	SF	2nd Floor Landing N/E Stairwell	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
72	12" x 12" Tan w/ Lt. Brown floor tile			Engineer's Office	ASSUMED	MISC								
73	Mastic w/ 12" x 12" tan w/ Lt. brown floor tile			Engineer's Office	ASSUMED	MISC								
74	12 x 12 Grey w/ Dk. Grey & White Floor Tile	60	SF	Engineer's Washroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
75	mastic w/ 12 x 12 Grey w/ Dk. Grey & White floor tile	60	SF	Engineer's Washroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
76	purple carpet adhesive			Principal's Office	ASSUMED	MISC								
77	12 x 12 Tan Floor Tile	400	SF	Principal's Office Room 104	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
78	Mastic w/ 12 x 12 Tan Floor Tile	400	SF	Principal's Office Room 104	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
79	12 x 12 Lt. Grey 2/ Dk. Grey & White Floor Tile	2,300	SF	Café	ASSUMED	MISC	N	LOC	8		Yes	Damaged or significantly damaged friable misc. ACBM	5	LOW
80	Mastic w/ 12 x 12 Lt. Grey w/ Dk. Grey & White Floor Tile	2,300	SF	Café	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
81	12 x 12 Lt. Blue w/ Dk. Blue & White Floor Tile	100	SF	Café	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
82	Mastic w/ 12 x 12 Lt. Blue 2/ Dk. Blue & White Floor Tile	100	SF	Café	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
83	Tan Linoleum	600	SF	Basement Art Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
84	Adhesive w/ Tan Linoleum	600	SF	Basement Art Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
85	Brown Carpet Adhesive	3,000	SF	1972 Annex Classrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
86	12" x 12" Beige Floor Tile	700	SF	Room 104	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
87	Mastic Associated w/ 12" x 12" Beige Floor Tile	700	SF	Room 104	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW

Chicago Public Schools

School Gary School Unit 23311 Building ID 3520

Address 3740 W. 31st St. Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
88	Vinyl Sheeting Glued on Plywood	3,000	SF	Gym	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
89	2' x 4' Ceiling Tile	7,500	SF	N, S, E, W Corridor Entrances, Rooms 401-412	ASSUMED	MISC	Y	NONE	0		Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
8A	9"x9" Tan w/Ye. Blue, and White Floor Tile Mastic	800	SF	Room 100 in 1909 Building	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
8B	9"x9" Tan Floor Tile w/Brown and White Mastic	800	SF	Faculty Washroom by Room 100 and Room 208 of 1909 Building	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
8C	9"x9" Brown Floor Tile w/White and Red Mastic	800	SF	Faculty Washroom and Room 208 of 1909 Building	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
8D	9" x 9" Beige Floor Tile Mastic	250	SF	Room 104 of 1909 Building	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
8E	9" x 9" Black Floor Tile Mastic	50	SF	Faculty Washroom of 1909 Building	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
8F	9" x 9" Maroon Floor Tile Mastic	20	SF	Faculty Washroom of 1909 Building	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
8G	9" x 9" Brown Floor Tile Mastic	750	SF	Room 208 of 1909 Building	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
8H	9" x 9" Green Floor Tile Mastic	400	SF	Room 204 of 1909 Building	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
8I	9" x 9" Aqua Floor Tile Mastic	415	SF	Room 301 of 1909 Building	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
8J	9" x 9" Aqua Floor Tile Mastic	40	SF	Room 301 of 1909 Building	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
8K	9" x 9" Yellow Floor Tile Mastic	40	SF	Room 301 of 1909 Building	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
8L	9" x 9" Gray Floor Tile Mastic			Gym of 1909 Building	CHR	MISC								
8M	9" x 9" Light Brown Floor Tile Mastic			Gym of 1909 Building	CHR	MISC								
90	9"x9" Brown with white streak floor tile	20	SF	Room 301	ASSUMED	MISC	N	LOC	5		No	Damaged or significantly damaged friable misc. ACBM	5	LOW
90A	9"x9" brown with white streak floor tile mastic	20	SF	Room 301	ASSUMED	MISC	N	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
91	9"x9" dark brown floor tile patch	20	SF	Room 301	ASSUMED	MISC	N	LOC	5		No	Damaged or significantly damaged friable misc. ACBM	5	LOW
91A	9"x9" dark brown with white streak floor	20	SF	Room 301	ASSUMED	MISC	N	NONE	0		No	Any remaining friable		LOW

Chicago Public Schools

School Gary School Unit 23311 Building ID 3520

Address 3740 W. 31st St. Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
	tile mastic											ACBM or friable suspect ACBM		
92	Brown carpet mastic	1,000	SF	Room 105 and 106	ASSUMED	MISC	N	LOC	5		No	Damaged or significantly damaged friable misc. ACBM	5	LOW
93	12"x12" gray floor tile with white spec	400	SF	Room 402 and 409	ASSUMED	MISC	N	LOC	5		No	Damaged or significantly damaged friable misc. ACBM	5	LOW
93A	12"x12" gray with white floor tile mastic	400	SF	Room 409 and 402	ASSUMED	MISC	N	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
94	12"x12" Lt. Blue with white floor tile	200	SF	Room 408	ASSUMED	MISC	N	LOC	2		No	Damaged or significantly damaged friable misc. ACBM	5	LOW
94A	12"x12" Lt. Blue with white floor tile mastic	200	SF	Room 408	ASSUMED	MISC	N	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
95	12"x12" white floor tile with beige streak	1,000	SF	New building hallway by north entrance	ASSUMED	MISC	N	LOC	10		No	Damaged or significantly damaged friable misc. ACBM	5	LOW
95A	12"x12" white with beige floor tile mastic	1,000	SF	New building first floor hallway	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
96	12"x12" Brown floor tile	10,000	SF	1st and 2nd floor hallway	ASSUMED	MISC	N	LOC	30		No	Damaged or significantly damaged friable misc. ACBM	5	LOW
96A	12"x12" Brown floor tile mastic	10,000	SF	New building 1st and 2nd floor hallway	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
97	12"x12" Lt. Blue with dark blue speck floor tile	500	SF	Room 501, 502, and 505	ASSUMED	MISC	N	LOC	4		No	Damaged or significantly damaged friable misc. ACBM	5	LOW
97A	12" x 12" Lt. Blue with dark blue floor tile mastic	500	SF	Room 501, 502, and 505	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
98	New building 12x12 white with gray and black speck floor tile	5,000	SF	New building halls and classrooms	ASSUMED	MISC	N	LOC	13		No	Damaged or significantly damaged friable misc. ACBM	5	LOW
98A	12"x12" white with gray and black specks floor tile mastic	4,000	SF	New building halls and classrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
9A	12" x 12" Beige Floor Tile w/ Brown Streaks Mastic	750	SF	Room 005 of 1909 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
9B	12" x 12" Beige Floor Tile w/ Brn & Wh Spks Mastic	750	SF	101	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
9C	12"x12" Beige Floor Tile w/ Brn & Wh Strks Mastic	700	SF	206	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Gary School Unit 23311 Building ID 3520

Address 3740 W. 31st St. Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
9D	12" x 12" White Floor Tile Mastic	700	SF	301	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
A2	Cementitious Insulation on Joints off Fiberglass	350	LF	Throughout 1909 Building	ASSUMED	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
B1	Cardboard Pipe Insulation	1,300	LF	Throughout 1909 Building	CHR	TSI	N	LOC	5		Yes	Damaged or significantly damaged friable thermal system insulating ACBM	5	LOW
B2	Cementitious Insulation off Paper Wrap Pipe Runs	100	LF	Throughout 1909 Building	ASSUMED	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
D1	Aircell Pipe Insulation	300	LF	Boiler Room	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW

Chicago Public Schools

School Gary School Unit 23311 Building ID 3520

Address 3740 W. 31st St. Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

Reinspection Date 10/1/2019
Inspector Name Carol Ashman
100-19554 5/15/2020
Inspector's IDPH License Number / Expiration Date

Inspector's Comments

HA Number:	Inspector Comments:
1	
10	
11	Not observed
13	Not observed
15A	4 inch baseboard room 411 10 ft missing
15B	
16A	
16B	
19	
2 D	Not observed
20	
21	
22	Not observed
23	
24	
25	
26	
27	
28	
29	
2A	
2B	Not observed in Room 200, 9x9 tan floor tile with brown and white room 204 20ft crack
2C	9x9 brown floor tile with white and red men's restroom between 2nd and 3rd floor. 2

Chicago Public Schools

School Gary School Unit 23311 Building ID 3520

Address 3740 W. 31st St. Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
	ft cracked or missing
2E	
2F	
2G	9x9 brown floor tile Room 208 20 ft crack, Damage also in Room 204
2H	9x9 green floor tile Room 204 15 ft cracked
2I	
2J	9x9 aqua with black and white speck floor tile. 2 ft crack, Damage is located in Room 301
2K	9x9 yellow floor tile with white streaks Room 301 2 ft cracked
2L	Not observed
2M	Not observed
30	
31	
32	Interior brick 1st floor girls restroom 4 ft cracked/crumbling
33	
34	
35	
36	
37	
38	
39	Blue green gray white ceramic tile grout. 3rd floor boys bathroom 5 feet cracked. 1st floor boys bathroom 3 ft cracked
3A	
3B	
3C	
3D	Damage is located in Room 301
4	Not observed
40	Not observed in Room 105 and 106
41	

Chicago Public Schools

School Gary School Unit 23311 Building ID 3520

Address 3740 W. 31st St. Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
42	
43	
44	
45	
46	
47	
48	
49	
50	
51	
52	
53	
54	
55	
56	Not observed
57	Not observed
5A	12x12 multi grey floor tile - hallway by 410 5 ft cracked. Hallway by east side 10 ft cracked
5B	
6	
60	
61	
65	
66	
67	
68	Not observed may be behind wall
7	Not observed - abated
70	
71	

Chicago Public Schools

School Gary School Unit 23311 Building ID 3520

Address 3740 W. 31st St. Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
72	Not observed
73	Not observed
74	
75	
76	Not observed
77	
78	
79	12x12 lt gray, do, grey, white floor tile in cafe 8 ft (various areas) cracked
80	
81	
82	
83	Not observed
84	Not observed
85	
86	
87	
88	
89	
8A	
8B	
8C	
8D	
8E	
8F	
8G	
8H	
8I	
8J	
8K	

Chicago Public Schools

School Gary School Unit 23311 Building ID 3520

Address 3740 W. 31st St. Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
8L	Not observed
8M	Not observed
90	Room 301 - 5 ft cracked
90A	Room 301 9x9 brown w white streak mastic
91	9x9 dark brown floor tile patch room 301 5 ft cracked
91A	9x9 dark brown floor tile with white streak mastic Room 301
92	Light brown carpet mastic Room 105 5 ft worn carpet (mastic exposed)
93	12x12 gray with white spec floor tile Room 409 - 2 ft cracked Room 402 - 3 ft cracked
93A	12x12 gray with white floor tile mastic Room 409 and 402
94	12x12 lt. blue with white floor tile Room 408 - 2 ft cracked
94A	12x12 lt blue with white floor tile mastic Room 408
95	New building first floor hall 12x12 white floor with beige streak 10 ft cracked
95A	
96	New building 12x12 brown floor tile 1st and 2nd floor hallway
96A	12x12 brown floor tile mastic 1st and 2nd floor hallway
97	New building 12x12 light blue with dark blue speck room 503 - 4 ft cracked
97A	12x12 lt. blue floor tile with dark blue speck mastic
98	12x12 white with gray and black specks, hall by room 504 - 13 feet cracked
98A	12x12 white with gray and black floor tile mastic hallways and classrooms of new building
9A	
9B	
9C	
9D	
A2	
B1	Cardboard pipe insulation boiler room 5 ft worn
B2	
D1	

Chicago Public Schools

School Gary School **Unit** 23311 **Building ID** 3520

Address 3740 W. 31st St. **Region** 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

Table II

Management Planner's Review

Chicago Public Schools

School Gary School
Address 3740 W. 31st St.

Unit 23311
Chicago, IL, 60623

Building ID 3520
Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
1	Plaster	60,000	SF	Throughout 1909 Building	Assumed	SURFACE	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
10	Number Skipped				Undefined						
11	Tan Linoleum	576	SF	Kitchen of 1909 Building	Assumed	MISC	No	25	SF	6 ACBM with the potential for damage	Repair
13	Beige Linoleum	720	SF	Lunchroom, 008, and 009 of 1909 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
15A	4" Black Vinyl Baseboards	1,800	LF	Classrooms in 1972 Annex	Assumed	MISC	No	10	LF	4 Damaged or significantly damaged friable misc. ACBM	Repair
15B	6" Black Vinyl Baseboard	480	LF	Hallways of 1972 Annex	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
16A	4" Black Vinyl Baseboard Mastic	1,800	LF	Classrooms of 1972 Annex	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
16B	6" Black Vinyl Baseboard Mastic	480	LF	Hallways of 1972 Annex	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
19	Exterior Brick - Not AHERA			1909 Building	Assumed	MISC					
2 D	9" x 9" Beige Floor Tile			104	Chrysotile	MISC					
20	Exterior Brick Mortar	14,000	SF	1909 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
21	Exterior Door Caulk	120	LF	1909 Building	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
22	Drywall	1,440	SF	Teacher's Room, Lunchroom, 008, 009 of 1909 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
23	Black Cementitious Flooring	1,760	SF	First Floor Corridor and Stair Landings of 1909 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
24	Green Terrazzo	40	SF	Women's Washroom of 1909 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
25	Brown Terrazzo Wall Panels	40	SF	Men's and Women's Washrooms of 1909 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
26	2'x2' Ceiling Panels	800	SF	Lunchroom of 1909 Building	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
27	Terrazzo Basin	20	SF	Kitchen and Sink Closet of 1909 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
28	Yellow Baseboard	200	SF	Lunchroom of 1909 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
29	Yellow Baseboard Mastic	200	SF	Lunchroom of 1909 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
2A	9"x9" Tan w/Yellow, Blue, and White Floor Tile	800	SF	100 of 1909 Building	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
2B	9"x9" Tan Floor Tile w/Brown and White	400	SF	100 and Room 208 of 1909 Building	Chrysotile	MISC	No	20	SF	4 Damaged or significantly damaged friable misc. ACBM	Repair
2C	9"x9" Brown Floor Tile w/White and Red	800	SF	208 and Faculty Washroom of 1909 Building	Chrysotile	MISC	No	2	SF	4 Damaged or significantly damaged friable misc. ACBM	Repair
2E	9" x 9" Black Floor Tile	50	SF	Faculty Washroom of 1909 Building	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Gary School
Address 3740 W. 31st St.

Unit 23311
Chicago, IL, 60623

Building ID 3520
Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
2F	9" x 9" Maroon Floor Tile	20	SF	Faculty Washroom of 1909 Building	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
2G	9" x 9" Brown Floor Tile	750	SF	208 of 1909 Building	Chrysotile	MISC	No	20	SF	4 Damaged or significantly damaged friable misc. ACBM	Repair
2H	9"x9" Green Floor Tile w/White Streaks	400	SF	204 of 1909 Building	Chrysotile	MISC	No	15	SF	4 Damaged or significantly damaged friable misc. ACBM	Repair
2I	9"x9" Aqua Floor Tiles w/White Streaks	415	SF	Room 204 of 1909 Building	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
2J	9"x9" Aqua Floor Tile w/Black and White Specks	40	SF	301 of 1909 Building	Chrysotile	MISC	No	2	SF	4 Damaged or significantly damaged friable misc. ACBM	Follow O&M Plan
2K	9"x9" Yellow Floor Tile w/White Streaks	50	SF	301 of 1909 Building	Chrysotile	MISC	No	2	SF	4 Damaged or significantly damaged friable misc. ACBM	Follow O&M Plan
2L	9"x9" Gray Floor Tile w/White Streaks			Gym of 1909 Building	Chrysotile	MISC					
2M	9"x9" Light Brown Floor Tile w/White Swirls			Gym of 1909 Building	Chrysotile	MISC					
30	Blue Baseboard	108	SF	1st Room West of E Entrance of 1909 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
31	Blue Baseboard Mastic	100	SF	1st Room West of E Entrance of 1909 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
32	Interior Brick	80,000	SF	Throughout 1909 Building	Assumed	MISC	No	4	SF	4 Damaged or significantly damaged friable misc. ACBM	Follow O&M Plan
33	Interior Brick Mortar	80,000	SF	Throughout 1909 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
34	Terrazzo Baseboard	300	SF	Throughout 1909 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
35	Ceramic Tile Grout	70	SF	Throughout Entrances of 1909 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
36	Glazed Brick Mortar	400	SF	Throughout 1909 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
37	Interior Door Caulk	200	LF	Throughout 1909 Building	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
38	Block Mortar	10	SF	Auditorium	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
39	Blue/Green/Gray/White Ceramic Tile Grout	500	SF	Throughout Boy's and Girl's Washrooms of 1909 Building	Assumed	MISC	No	8	SF	4 Damaged or significantly damaged friable misc. ACBM	Repair
3A	12"x12" Beige Floor Tile w/Brown Streaks	700	SF	005 of 1909 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
3B	12"x12" Beige Floor Tile w/Brown and White Specks	750	SF	101 of 1909 Building	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
3C	12"x12" Beige Floor Tile w/Brown and White Streaks	750	SF	206 of 1909 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
3D	12"x12" White Floor Tile	700	SF	301 of 1909 Building	Chrysotile	MISC	No	10	SF	4 Damaged or significantly damaged friable misc. ACBM	Repair
4	12"x12" Ceiling Tile			Throughout Annex	Assumed	MISC					Follow O&M Plan

Chicago Public Schools

School Gary School
Address 3740 W. 31st St.

Unit 23311
Chicago, IL, 60623

Building ID 3520
Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
40	Gray Carpet Mastic (Brown)	500	SF	Office, 105, and 106 of 1909 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
41	Cinder Block Mortar	1,300	SF	Throughout 1909 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
42	Black Border Tile	200	SF	204 of 1909 Building	Chrysotile	MISC	No	3	SF	4 Damaged or significantly damaged friable misc. ACBM	Follow O&M Plan
43	Black Border Tile Mastic	50	SF	204 of 1909 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
44	2'x4' Ceiling Panels	200	SF	Kitchen of 1909 Building	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
45	Terrazzo	150	SF	Washroom in Room D of 1909 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
46	12"x12" Terrazzo	150	SF	D Room of 1909 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
47	Boiler Wrap #1	500	SF	Boiler Room of 1909 Building	Chrysotile	MISC	Yes	50	SF	4 Damaged or significantly damaged friable misc. ACBM	Repair
48	Boiler Wrap #2	500	SF	Boiler Room of 1909 Building	Chrysotile	MISC	Yes	50	SF	4 Damaged or significantly damaged friable misc. ACBM	Repair
49	Insulation Over Fiberglass	140	LF	Maintenance Room of 1909 Building	Assumed	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
50	Mag Block Insulation	100	LF	Boiler Room of 1909 Building	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
51	Duct Insulation	300	SF	Boiler Room of 1909 Building	Assumed	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
52	Refractory Cement in Doors of #1 Boiler	20	SF	Boiler Room of 1909 Building	Assumed	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
53	Refractory Cement in Doors of #2 Boiler	20	SF	Boiler Room of 1909 Building	Assumed	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
54	Firebrick in Boiler #1	200	SF	Boiler Room of 1909 Building	Assumed	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
55	Firebrick in Boiler #2	200	SF	Boiler Room of 1909 Building	Assumed	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
56	4" Black Vinyl Baseboard			004 of 1909 Building	Assumed	MISC					Follow O&M Plan
57	4" Black Vinyl Baseboard Mastic			004 of 1909 Building	Assumed	MISC					Follow O&M Plan
5A	12"x12" Multi-Gray Floor Tile	1,900	SF	Hallways of 1972 Annex	Assumed	MISC	No	15	SF	4 Damaged or significantly damaged friable misc. ACBM	Repair
5B	12"x12" Gray Floor Tile w/White Streaks	600	SF	Book Room and Storage in 1972 Annex	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
6	Brown Linoleum	400	SF	Basement Room D of 1909 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
60	Green Ceramic Tile Grout	10	SF	Entrances of 1972 Annex	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Gary School
Address 3740 W. 31st St.

Unit 23311
Chicago, IL, 60623

Building ID 3520
Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
61	Gray Carpet Mastic	600	SF	Classrooms, Teacher's Lounge and Office of 1972 Annex	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
65	Exterior Door Caulk	84	LF	Throughout 1972 Annex	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
66	12"x12" Multi-Gray Floor Tile Mastic	1,900	SF	Hallways of 1972 Annex	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
67	12"x12" Gray Floor Tile w/White Streaks Mastic	600	SF	Book Room and Storage in 1972 Annex	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
68	Cementitious Pipe Joint Insulation	4	LF	Electric Room (Behind Wall) in 1972 Annex	Assumed	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
7	Transite Panels			Basement (Abated)	Abated						
70	Fiberglass Insulation			Electric Room of 1972 Annex	Not Tested						
71	Vault Door Liner	15	SF	2nd Floor Landing N/E Stairwell	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
72	12" x 12" Tan w/ Lt. Brown floor tile			Engineer's Office	Assumed	MISC					Follow O&M Plan
73	Mastic w/ 12" x 12" tan w/ lt. brown floor tile			Engineer's Office	Assumed	MISC					Follow O&M Plan
74	12 x 12 Grey w/ Dk. Grey & White Floor Tile	60	SF	Engineer's Washroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
75	mastic w/ 12 x 12 Grey w/ Dk. Grey & White floor tile	60	SF	Engineer's Washroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
76	purple carpet adhesive			Principal's Office	Assumed	MISC					Follow O&M Plan
77	12 x 12 Tan Floor Tile	400	SF	Principal's Office Room 104	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
78	Mastic w/ 12 x 12 Tan Floor Tile	400	SF	Principal's Office Room 104	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
79	12 x 12 Lt. Grey 2/ Dk. Grey & White Floor Tile	2,300	SF	Café	Assumed	MISC	No	8	SF	4 Damaged or significantly damaged friable misc. ACBM	Repair
80	Mastic w/ 12 x 12 Lt. Grey w/ Dk. Grey & White Floor Tile	2,300	SF	Café	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
81	12 x 12 Lt. Blue w/ Dk. Blue & White Floor Tile	100	SF	Café	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
82	Mastic w/ 12 x 12 Lt. Blue 2/ Dk. Blue & White Floor Tile	100	SF	Café	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
83	Tan Linoleum	600	SF	Basement Art Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
84	Adhesive w/ Tan Linoleum	600	SF	Basement Art Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
85	Brown Carpet Adhesive	3,000	SF	1972 Annex Classrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
86	12" x 12" Beige Floor Tile	700	SF	Room 104	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
87	Mastic Associated w/ 12" x 12" Beige Floor Tile	700	SF	Room 104	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
88	Vinyl Sheeting Glued on Plywood	3,000	SF	Gym	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
89	2' x 4' Ceiling Tile	7,500	SF	N, S, E, W Corridor Entrances, Rooms 401-412	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
8A	9"x9" Tan w/Ye, Blue, and White Floor Tile	800	SF	Room 100 in 1909 Building	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Gary School
Address 3740 W. 31st St.

Unit 23311
Chicago, IL, 60623

Building ID 3520
Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
	Mastic										
8B	9"x9" Tan Floor Tile w/Brown and White Mastic	800	SF	Faculty Washroom by Room 100 and Room 208 of 1909 Building	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
8C	9"x9" Brown Floor Tile w/White and Red Mastic	800	SF	Faculty Washroom and Room 208 of 1909 Building	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
8D	9" x 9" Beige Floor Tile Mastic	250	SF	Room 104 of 1909 Building	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
8E	9" x 9" Black Floor Tile Mastic	50	SF	Faculty Washroom of 1909 Building	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
8F	9" x 9" Maroon Floor Tile Mastic	20	SF	Faculty Washroom of 1909 Building	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
8G	9" x 9" Brown Floor Tile Mastic	750	SF	Room 208 of 1909 Building	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
8H	9" x 9" Green Floor Tile Mastic	400	SF	Room 204 of 1909 Building	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
8I	9" x 9" Aqua Floor Tile Mastic	415	SF	Room 301 of 1909 Building	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
8J	9" x 9" Aqua Floor Tile Mastic	40	SF	Room 301 of 1909 Building	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
8K	9" x 9" Yellow Floor Tile Mastic	40	SF	Room 301 of 1909 Building	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
8L	9" x 9" Gray Floor Tile Mastic			Gym of 1909 Building	Chrysotile	MISC					Follow O&M Plan
8M	9" x 9" Light Brown Floor Tile Mastic			Gym of 1909 Building	Chrysotile	MISC					Follow O&M Plan
90	9"x9" Brown with white streak floor tile	20	SF	Room 301	Assumed	MISC	No	5	SF	4 Damaged or significantly damaged friable misc. ACBM	Repair
90A	9"x9" brown with white streak floor tile mastic	20	SF	Room 301	Assumed	MISC	No	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Repair
91	9"x9" dark brown floor tile patch	20	SF	Room 301	Assumed	MISC	No	5	SF	4 Damaged or significantly damaged friable misc. ACBM	Repair
91A	9"x9" dark brown with white streak floor tile mastic	20	SF	Room 301	Assumed	MISC	No	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Repair
92	Brown carpet mastic	1,000	SF	Room 105 and 106	Assumed	MISC	No	5	SF	4 Damaged or significantly damaged friable misc. ACBM	Repair
93	12"x12" gray floor tile with white spec	400	SF	Room 402 and 409	Assumed	MISC	No	5	SF	4 Damaged or significantly damaged friable misc. ACBM	Repair
93A	12"x12" gray with white floor tile mastic	400	SF	Room 409 and 402	Assumed	MISC	No	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
94	12"x12" Lt. Blue with white floor tile	200	SF	Room 408	Assumed	MISC	No	2	SF	4 Damaged or significantly damaged friable misc. ACBM	Follow O&M Plan
94A	12"x12" Lt. Blue with white floor tile mastic	200	SF	Room 408	Assumed	MISC	No	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
95	12"x12" white floor tile with beige streak	1,000	SF	New building hallway by north entrance	Assumed	MISC	No	10	SF	4 Damaged or significantly damaged	Repair

Chicago Public Schools

School Gary School
Address 3740 W. 31st St.

Unit 23311
Chicago, IL, 60623

Building ID 3520
Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
										friable misc. ACBM	
95A	12"x12" white with beige floor tile mastic	1,000	SF	New building first floor hallway	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Repair
96	12"x12" Brown floor tile	10,000	SF	1st and 2nd floor hallway	Assumed	MISC	No	30	SF	4 Damaged or significantly damaged friable misc. ACBM	Repair
96A	12"x12" Brown floor tile mastic	10,000	SF	New building 1st and 2nd floor hallway	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Repair
97	12"x12" Lt. Blue with dark blue speck floor tile	500	SF	Room 501, 502, and 505	Assumed	MISC	No	4	SF	4 Damaged or significantly damaged friable misc. ACBM	Follow O&M Plan
97A	12"x12" Lt. Blue with dark blue floor tile mastic	500	SF	Room 501, 502, and 505	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
98	New building 12x12 white with gray and black speck floor tile	5,000	SF	New building halls and classrooms	Assumed	MISC	No	13	SF	4 Damaged or significantly damaged friable misc. ACBM	Repair
98A	12"x12" white with gray and black specks floor tile mastic	4,000	SF	New building halls and classrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Repair
9A	12" x 12" Beige Floor Tile w/ Brown Streaks Mastic	750	SF	Room 005 of 1909 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
9B	12" x 12" Beige Floor Tile w/ Brn & Wh Spks Mastic	750	SF	101	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
9C	12"x12" Beige Floor Tile w/ Brn & Wh Strks Mastic	700	SF	206	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
9D	12" x 12" White Floor Tile Mastic	700	SF	301	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
A2	Cementitious Insulation on Joints off Fiberglass	350	LF	Throughout 1909 Building	Assumed	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
B1	Cardboard Pipe Insulation	1,300	LF	Throughout 1909 Building	Chrysotile	TSI	No	5	LF	1 Damaged or significantly damaged friable thermal system insulating ACBM	Follow O&M Plan
B2	Cementitious Insulation off Paper Wrap Pipe Runs	100	LF	Throughout 1909 Building	Assumed	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
D1	Aircell Pipe Insulation	300	LF	Boiler Room	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan

Chicago Public Schools

School Gary School
Address 3740 W. 31st St.

Unit 23311
 Chicago, IL, 60623

Building ID 3520
Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

Review Date	10/18/2019
Manager Planner Name	Evan Christian
100-19466	5/15/2020
Manager IDPH License No/Expiration	

HA Number	Management Comments
1	
10	
11	
13	
15A	
15B	
16A	
16B	
19	
2 D	

Chicago Public Schools

School Gary School
Address 3740 W. 31st St.

Unit 23311
 Chicago, IL, 60623

Building ID 3520
Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
20	
21	
22	
23	
24	
25	
26	
27	
28	
29	
2A	
2B	
2C	
2E	
2F	
2G	
2H	
2I	
2J	
2K	
2L	
2M	
30	
31	
32	
33	

Chicago Public Schools

School Gary School
Address 3740 W. 31st St.

Unit 23311
 Chicago, IL, 60623

Building ID 3520
Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
34	
35	
36	
37	
38	
39	Sample material to determine asbestos content. Repair and/or remove all damaged ACBM
3A	
3B	
3C	
3D	
4	
40	
41	
42	
43	
44	
45	
46	
47	Repair and/or remove damaged TSI Wrap
48	See HA 47
49	
50	
51	
52	
53	
54	

Chicago Public Schools

School Gary School
Address 3740 W. 31st St.

Unit 23311
 Chicago, IL, 60623

Building ID 3520
Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
55	
56	
57	
5A	Sample material to determine asbestos content. Repair and/or remove all damaged ACBM
5B	
6	
60	
61	
65	
66	
67	
68	
7	
70	
71	
72	
73	
74	
75	
76	
77	
78	
79	Sample material to determine asbestos content. Repair and/or remove all damaged ACBM
80	
81	
82	

Chicago Public Schools

School Gary School
Address 3740 W. 31st St.

Unit 23311
 Chicago, IL, 60623

Building ID 3520
Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
83	
84	
85	
86	
87	
88	
89	
8A	
8B	
8C	
8D	
8E	
8F	
8G	
8H	
8I	
8J	
8K	
8L	
8M	
90	Sample material to determine asbestos content. Repair and/or remove all damaged ACBM in room 301
90A	See HA 90
91	See HA 90
91A	See HA 90
92	See HA 90
93	See HA 90

Chicago Public Schools

School Gary School
Address 3740 W. 31st St.

Unit 23311
 Chicago, IL, 60623

Building ID 3520
Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
93A	See HA 90
94	
94A	
95	Sample material to determine asbestos content. Repair and/or remove all damaged ACBM
95A	See HA 95
96	Sample material to determine asbestos content. Repair and/or remove all damaged ACBM
96A	See HA 96
97	
97A	
98	Sample material to determine asbestos content. Repair and/or remove all damaged ACBM & Continue O&M
98A	See HA 98
9A	
9B	
9C	
9D	
A2	
B1	
B2	
D1	

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUILDING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **1**
MATERIAL DESCRIPTION: **Plaster**
HISTORICAL AHERA DAMAGE CATEGORY: **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout 1909 Building**
MATERIAL QUANTITY: **60000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/01/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **1**
MATERIAL DESCRIPTION: **Plaster**
MATERIAL LOCATION: **Throughout 1909 Building**
MATERIAL QUANTITY: **60000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10**
MATERIAL DESCRIPTION: **Number Skipped**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Undefined** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION:

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 10/01/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **10**

MATERIAL DESCRIPTION: **Number Skipped**

MATERIAL LOCATION:

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUILDING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11**
MATERIAL DESCRIPTION: **Tan Linoleum**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON: **Deterioration
Physical Damage**
HISTORICAL RESPONSE ACTION: **Repair**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Deterioration
Physical Damage**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Kitchen of 1909 Building**
MATERIAL QUANTITY: **576** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **25** DAMAGE UNITS: **SF**
COMMENTS: **Not observed**

Inspector's Signature: _____ Date: 10/01/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **11**

MATERIAL DESCRIPTION: **Tan Linoleum**

MATERIAL LOCATION: **Kitchen of 1909 Building**

MATERIAL QUANTITY: **576**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **25**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13**
MATERIAL DESCRIPTION: **Beige Linoleum**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Lunchroom, 008, and 009 of 1909 Building**
MATERIAL QUANTITY: **720** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**
COMMENTS: **Not observed**

Inspector's Signature: _____ Date: 10/01/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **13**

MATERIAL DESCRIPTION: **Beige Linoleum**

MATERIAL LOCATION: **Lunchroom, 008, and 009 of 1909 Building**

MATERIAL QUANTITY: **720** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15A**
MATERIAL DESCRIPTION: **4" Black Vinyl Baseboards**
HISTORICAL AHERA DAMAGE CATEGORY **4 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **4. Damaged or significantly damaged friable misc. ACBM**

DAMAGE REASON: **Physical Damage**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Classrooms in 1972 Annex**
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **10** DAMAGE UNITS: **LF**
COMMENTS: **4 inch baseboard room 411 10 ft missing**

Inspector's Signature: _____ Date: **10/01/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **15A**
MATERIAL DESCRIPTION: **4" Black Vinyl Baseboards**
MATERIAL LOCATION: **Classrooms in 1972 Annex**
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **10** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15B**
MATERIAL DESCRIPTION: **6" Black Vinyl Baseboard**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Hallways of 1972 Annex**
MATERIAL QUANTITY: **480** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 10/01/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **15B**
MATERIAL DESCRIPTION: **6" Black Vinyl Baseboard**
MATERIAL LOCATION: **Hallways of 1972 Annex**
MATERIAL QUANTITY: **480** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16A**
MATERIAL DESCRIPTION: **4" Black Vinyl Baseboard Mastic**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Classrooms of 1972 Annex**
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 10/01/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **16A**
MATERIAL DESCRIPTION: **4" Black Vinyl Baseboard Mastic**
MATERIAL LOCATION: **Classrooms of 1972 Annex**
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16B**
MATERIAL DESCRIPTION: **6" Black Vinyl Baseboard Mastic**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Hallways of 1972 Annex**
MATERIAL QUANTITY: **480** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 10/01/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **16B**
MATERIAL DESCRIPTION: **6" Black Vinyl Baseboard Mastic**
MATERIAL LOCATION: **Hallways of 1972 Annex**
MATERIAL QUANTITY: **480** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUILDING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19**
MATERIAL DESCRIPTION: **Exterior Brick - Not AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1909 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **10/01/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **19**

MATERIAL DESCRIPTION: **Exterior Brick - Not AHERA**

MATERIAL LOCATION: **1909 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUILDING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **2 D**
MATERIAL DESCRIPTION: **9" x 9" Beige Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **104**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed**

Inspector's Signature: _____ Date: **10/01/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **2 D**

MATERIAL DESCRIPTION: **9" x 9" Beige Floor Tile**

MATERIAL LOCATION: **104**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUILDING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**
MATERIAL DESCRIPTION: **Exterior Brick Mortar**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1909 Building**
MATERIAL QUANTITY: **14000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/01/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **20**
MATERIAL DESCRIPTION: **Exterior Brick Mortar**
MATERIAL LOCATION: **1909 Building**
MATERIAL QUANTITY: **14000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUILDING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21**
MATERIAL DESCRIPTION: **Exterior Door Caulk**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1909 Building**
MATERIAL QUANTITY: **120** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 10/01/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **21**

MATERIAL DESCRIPTION: **Exterior Door Caulk**

MATERIAL LOCATION: **1909 Building**

MATERIAL QUANTITY: **120**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22**
MATERIAL DESCRIPTION: **Drywall**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Teacher's Room, Lunchroom, 008, 009 of 1909 Building**
MATERIAL QUANTITY: **1440** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**
COMMENTS: **Not observed**

Inspector's Signature: _____ Date: 10/01/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **22**
MATERIAL DESCRIPTION: **Drywall**
MATERIAL LOCATION: **Teacher's Room, Lunchroom, 008, 009 of 1909 Building**
MATERIAL QUANTITY: **1440** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23**
MATERIAL DESCRIPTION: **Black Cementitious Flooring**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **First Floor Corridor and Stair Landings of 1909 Building**
MATERIAL QUANTITY: **1760** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/01/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **23**

MATERIAL DESCRIPTION: **Black Cementitious Flooring**

MATERIAL LOCATION: **First Floor Corridor and Stair Landings of 1909 Building**

MATERIAL QUANTITY: **1760**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **24**
MATERIAL DESCRIPTION: **Green Terrazzo**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Women's Washroom of 1909 Building**
MATERIAL QUANTITY: **40** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/01/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **24**

MATERIAL DESCRIPTION: **Green Terrazzo**

MATERIAL LOCATION: **Women's Washroom of 1909 Building**

MATERIAL QUANTITY: **40**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25**
MATERIAL DESCRIPTION: **Brown Terrazzo Wall Panels**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Men's and Women's Washrooms of 1909 Building**
MATERIAL QUANTITY: **40** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/01/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **25**

MATERIAL DESCRIPTION: **Brown Terrazzo Wall Panels**

MATERIAL LOCATION: **Men's and Women's Washrooms of 1909 Building**

MATERIAL QUANTITY: **40** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26**
MATERIAL DESCRIPTION: **2'x2' Ceiling Panels**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Lunchroom of 1909 Building**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **10/01/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **26**

MATERIAL DESCRIPTION: **2'x2' Ceiling Panels**

MATERIAL LOCATION: **Lunchroom of 1909 Building**

MATERIAL QUANTITY: **800**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27**
MATERIAL DESCRIPTION: **Terrazzo Basin**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Kitchen and Sink Closet of 1909 Building**
MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **10/01/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **27**

MATERIAL DESCRIPTION: **Terrazzo Basin**

MATERIAL LOCATION: **Kitchen and Sink Closet of 1909 Building**

MATERIAL QUANTITY: **20**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28**
MATERIAL DESCRIPTION: **Yellow Baseboard**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Lunchroom of 1909 Building**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/01/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **28**

MATERIAL DESCRIPTION: **Yellow Baseboard**

MATERIAL LOCATION: **Lunchroom of 1909 Building**

MATERIAL QUANTITY: **200**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **29**
MATERIAL DESCRIPTION: **Yellow Baseboard Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Lunchroom of 1909 Building**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/01/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **29**

MATERIAL DESCRIPTION: **Yellow Baseboard Mastic**

MATERIAL LOCATION: **Lunchroom of 1909 Building**

MATERIAL QUANTITY: **200**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUILDING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **2A**
MATERIAL DESCRIPTION: **9"x9" Tan w/Yellow, Blue, and White Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **100 of 1909 Building**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/01/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **2A**

MATERIAL DESCRIPTION: **9"x9" Tan w/Yellow, Blue, and White Floor Tile**

MATERIAL LOCATION: **100 of 1909 Building**

MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **2B**
MATERIAL DESCRIPTION: **9"x9" Tan Floor Tile w/Brown and White**
HISTORICAL AHERA DAMAGE CATEGORY **4 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **4. Damaged or significantly damaged friable misc. ACBM**

DAMAGE REASON: **Physical Damage**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **100 and Room 208 of 1909 Building**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **20** DAMAGE UNITS: **SF**
COMMENTS: **Not observed in Room 200, 9x9 tan floor tile with brown and white room 204 20ft crack**

Inspector's Signature: _____ Date: 10/01/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **2B**

MATERIAL DESCRIPTION: **9"x9" Tan Floor Tile w/Brown and White**

MATERIAL LOCATION: **100 and Room 208 of 1909 Building**

MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **20** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **2C**
MATERIAL DESCRIPTION: **9"x9" Brown Floor Tile w/White and Red**
HISTORICAL AHERA DAMAGE CATEGORY **4 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **4. Damaged or significantly damaged friable misc. ACBM**

DAMAGE REASON: **Physical Damage**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **208 and Faculty Washroom of 1909 Building**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **2** DAMAGE UNITS: **SF**
COMMENTS: **9x9 brown floor tile with white and red men's restroom between 2nd and 3rd floor. 2 ft cracked or missing**

Inspector's Signature: _____ Date: **10/01/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **2C**
MATERIAL DESCRIPTION: **9"x9" Brown Floor Tile w/White and Red**
MATERIAL LOCATION: **208 and Faculty Washroom of 1909 Building**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **2** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **2E**
MATERIAL DESCRIPTION: **9" x 9" Black Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Faculty Washroom of 1909 Building**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/01/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **2E**

MATERIAL DESCRIPTION: **9" x 9" Black Floor Tile**

MATERIAL LOCATION: **Faculty Washroom of 1909 Building**

MATERIAL QUANTITY: **50**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUILDING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **2F**
MATERIAL DESCRIPTION: **9" x 9" Maroon Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Faculty Washroom of 1909 Building**
MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/01/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **2F**

MATERIAL DESCRIPTION: **9" x 9" Maroon Floor Tile**

MATERIAL LOCATION: **Faculty Washroom of 1909 Building**

MATERIAL QUANTITY: **20**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **2G**
MATERIAL DESCRIPTION: **9" x 9" Brown Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **4 ACBM with potential for significant damage**
HISTORICAL DAMAGE REASON: **Physical Damage
Deterioration**
HISTORICAL RESPONSE ACTION: **Repair**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **4. Damaged or significantly damaged friable misc. ACBM**

DAMAGE REASON: **Physical Damage
Deterioration**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **208 of 1909 Building**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **20** DAMAGE UNITS: **SF**
COMMENTS: **9x9 brown floor tile Room 208 20 ft crack, Damage also in Room 204**

Inspector's Signature: _____ Date: 10/01/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **2G**
MATERIAL DESCRIPTION: **9" x 9" Brown Floor Tile**
MATERIAL LOCATION: **208 of 1909 Building**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **20** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **2H**
MATERIAL DESCRIPTION: **9"x9" Green Floor Tile w/White Streaks**
HISTORICAL AHERA DAMAGE CATEGORY **4 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **4. Damaged or significantly damaged friable misc. ACBM**

DAMAGE REASON: **Physical Damage**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **204 of 1909 Building**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **15** DAMAGE UNITS: **SF**
COMMENTS: **9x9 green floor tile Room 204 15 ft cracked**

Inspector's Signature: _____ Date: 10/01/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **2H**
MATERIAL DESCRIPTION: **9"x9" Green Floor Tile w/White Streaks**
MATERIAL LOCATION: **204 of 1909 Building**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **15** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **2I**
MATERIAL DESCRIPTION: **9"x9" Aqua Floor Tiles w/White Streaks**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 204 of 1909 Building**
MATERIAL QUANTITY: **415** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/01/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **2I**

MATERIAL DESCRIPTION: **9"x9" Aqua Floor Tiles w/White Streaks**

MATERIAL LOCATION: **Room 204 of 1909 Building**

MATERIAL QUANTITY: **415**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **2J**
MATERIAL DESCRIPTION: **9"x9" Aqua Floor Tile w/Black and White Specks**
HISTORICAL AHERA DAMAGE CATEGORY **4 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON: **Deterioration
Physical Damage**
HISTORICAL RESPONSE ACTION: **Repair**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **4. Damaged or significantly damaged friable misc. ACBM**

DAMAGE REASON: **Deterioration
Physical Damage**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **301 of 1909 Building**
MATERIAL QUANTITY: **40** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **2** DAMAGE UNITS: **SF**
COMMENTS: **9x9 aqua with black and white speck floor tile. 2 ft crack, Damage is located in Room 301**

Inspector's Signature: _____ Date: 10/01/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **2J**

MATERIAL DESCRIPTION: **9"x9" Aqua Floor Tile w/Black and White Specks**

MATERIAL LOCATION: **301 of 1909 Building**

MATERIAL QUANTITY: **40**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **2**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **2K**
MATERIAL DESCRIPTION: **9"x9" Yellow Floor Tile w/White Streaks**
HISTORICAL AHERA DAMAGE CATEGORY **4 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON: **Physical Damage**
HISTORICAL RESPONSE ACTION: **Repair**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **4. Damaged or significantly damaged friable misc. ACBM**

DAMAGE REASON: **Physical Damage**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **301 of 1909 Building**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **2** DAMAGE UNITS: **SF**
COMMENTS: **9x9 yellow floor tile with white streaks Room 301 2 ft cracked**

Inspector's Signature: _____ Date: **10/01/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **2K**
MATERIAL DESCRIPTION: **9"x9" Yellow Floor Tile w/White Streaks**
MATERIAL LOCATION: **301 of 1909 Building**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **2** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **2L**
MATERIAL DESCRIPTION: **9"x9" Gray Floor Tile w/White Streaks**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Gym of 1909 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed**

Inspector's Signature: _____ Date: **10/01/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **2L**

MATERIAL DESCRIPTION: **9"x9" Gray Floor Tile w/White Streaks**

MATERIAL LOCATION: **Gym of 1909 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **2M**
MATERIAL DESCRIPTION: **9"x9" Light Brown Floor Tile w/White Swirls**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Gym of 1909 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed**

Inspector's Signature: _____

Date: 10/01/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **2M**

MATERIAL DESCRIPTION: **9"x9" Light Brown Floor Tile w/White Swirls**

MATERIAL LOCATION: **Gym of 1909 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **30**
MATERIAL DESCRIPTION: **Blue Baseboard**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st Room West of E Entrance of 1909 Building**
MATERIAL QUANTITY: **108** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/01/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **30**
MATERIAL DESCRIPTION: **Blue Baseboard**
MATERIAL LOCATION: **1st Room West of E Entrance of 1909 Building**
MATERIAL QUANTITY: **108** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **31**
MATERIAL DESCRIPTION: **Blue Baseboard Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st Room West of E Entrance of 1909 Building**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/01/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **31**

MATERIAL DESCRIPTION: **Blue Baseboard Mastic**

MATERIAL LOCATION: **1st Room West of E Entrance of 1909 Building**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **32**
MATERIAL DESCRIPTION: **Interior Brick**
HISTORICAL AHERA DAMAGE CATEGORY **4 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **4. Damaged or significantly damaged friable misc. ACBM**

DAMAGE REASON: **Physical Damage**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout 1909 Building**
MATERIAL QUANTITY: **80000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **4** DAMAGE UNITS: **SF**
COMMENTS: **Interior brick 1st floor girls restroom 4 ft cracked/crumbling**

Inspector's Signature: _____ Date: **10/01/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUILDING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **32**

MATERIAL DESCRIPTION: **Interior Brick**

MATERIAL LOCATION: **Throughout 1909 Building**

MATERIAL QUANTITY: **80000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **4**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **33**
MATERIAL DESCRIPTION: **Interior Brick Mortar**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout 1909 Building**
MATERIAL QUANTITY: **80000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/01/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **33**
MATERIAL DESCRIPTION: **Interior Brick Mortar**
MATERIAL LOCATION: **Throughout 1909 Building**
MATERIAL QUANTITY: **80000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **34**
MATERIAL DESCRIPTION: **Terrazzo Baseboard**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout 1909 Building**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/01/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **34**

MATERIAL DESCRIPTION: **Terrazzo Baseboard**

MATERIAL LOCATION: **Throughout 1909 Building**

MATERIAL QUANTITY: **300**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUILDING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **35**
MATERIAL DESCRIPTION: **Ceramic Tile Grout**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout Entrances of 1909 Building**
MATERIAL QUANTITY: **70** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/01/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **35**
MATERIAL DESCRIPTION: **Ceramic Tile Grout**
MATERIAL LOCATION: **Throughout Entrances of 1909 Building**
MATERIAL QUANTITY: **70** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **36**
MATERIAL DESCRIPTION: **Glazed Brick Mortar**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout 1909 Building**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/01/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **36**

MATERIAL DESCRIPTION: **Glazed Brick Mortar**

MATERIAL LOCATION: **Throughout 1909 Building**

MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37**
MATERIAL DESCRIPTION: **Interior Door Caulk**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout 1909 Building**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 10/01/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **37**

MATERIAL DESCRIPTION: **Interior Door Caulk**

MATERIAL LOCATION: **Throughout 1909 Building**

MATERIAL QUANTITY: **200**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUILDING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **38**
MATERIAL DESCRIPTION: **Block Mortar**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Auditorium**
MATERIAL QUANTITY: **10** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/01/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **38**

MATERIAL DESCRIPTION: **Block Mortar**

MATERIAL LOCATION: **Auditorium**

MATERIAL QUANTITY: **10**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **39**
MATERIAL DESCRIPTION: **Blue/Green/Gray/White Ceramic Tile Grout**
HISTORICAL AHERA DAMAGE CATEGORY **4 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **4. Damaged or significantly damaged friable misc. ACBM**

DAMAGE REASON: **Physical Damage**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout Boy's and Girl's Washrooms of 1909 Building**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **8** DAMAGE UNITS: **SF**
COMMENTS: **Blue green gray white ceramic tile grout. 3rd floor boys bathroom 5 feet cracked. 1st floor boys bathroom 3 ft cracked**

Inspector's Signature: _____ Date: 10/01/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **39**
MATERIAL DESCRIPTION: **Blue/Green/Gray/White Ceramic Tile Grout**
MATERIAL LOCATION: **Throughout Boy's and Girl's Washrooms of 1909 Building**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **8** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample material to determine asbestos content. Repair and/or remove all damaged ACBM

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **3A**
MATERIAL DESCRIPTION: **12"x12" Beige Floor Tile w/Brown Streaks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **005 of 1909 Building**
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/01/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **3A**
MATERIAL DESCRIPTION: **12"x12" Beige Floor Tile w/Brown Streaks**
MATERIAL LOCATION: **005 of 1909 Building**
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **3B**
MATERIAL DESCRIPTION: **12"x12"Beige Floor Tile w/Brown and White Specks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **101 of 1909 Building**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/01/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **3B**
MATERIAL DESCRIPTION: **12"x12"Beige Floor Tile w/Brown and White Specks**
MATERIAL LOCATION: **101 of 1909 Building**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **3C**
MATERIAL DESCRIPTION: **12"x12" Beige Floor Tile w/Brown and White Streaks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **206 of 1909 Building**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/01/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **3C**
MATERIAL DESCRIPTION: **12"x12" Beige Floor Tile w/Brown and White Streaks**
MATERIAL LOCATION: **206 of 1909 Building**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **3D**
MATERIAL DESCRIPTION: **12"x12" White Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **4 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON: **Deterioration
Physical Damage**
HISTORICAL RESPONSE ACTION: **Repair**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **4. Damaged or significantly damaged friable misc. ACBM**

DAMAGE REASON: **Deterioration
Physical Damage**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **301of 1909 Building**
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **10** DAMAGE UNITS: **SF**
COMMENTS: **Damage is located in Room 301**

Inspector's Signature: _____ Date: 10/01/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **3D**

MATERIAL DESCRIPTION: **12"x12" White Floor Tile**

MATERIAL LOCATION: **301of 1909 Building**

MATERIAL QUANTITY: **700**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **10**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **4**
MATERIAL DESCRIPTION: **12"x12" Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Annex**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed**

Inspector's Signature: _____

Date: **10/01/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **4**

MATERIAL DESCRIPTION: **12"x12" Ceiling Tile**

MATERIAL LOCATION: **Throughout Annex**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUILDING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **40**
MATERIAL DESCRIPTION: **Gray Carpet Mastic (Brown)**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Office, 105, and 106 of 1909 Building**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS: **Not observed in Room 105 and 106**

Inspector's Signature: _____ Date: **10/01/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **40**
MATERIAL DESCRIPTION: **Gray Carpet Mastic (Brown)**
MATERIAL LOCATION: **Office, 105, and 106 of 1909 Building**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUILDING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **41**
MATERIAL DESCRIPTION: **Cinder Block Mortar**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout 1909 Building**
MATERIAL QUANTITY: **1300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/01/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **41**

MATERIAL DESCRIPTION: **Cinder Block Mortar**

MATERIAL LOCATION: **Throughout 1909 Building**

MATERIAL QUANTITY: **1300**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **42**
MATERIAL DESCRIPTION: **Black Border Tile**
HISTORICAL AHERA DAMAGE CATEGORY **4 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **4. Damaged or significantly damaged friable misc. ACBM**

DAMAGE REASON: **Physical Damage**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **204 of 1909 Building**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **3** DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: **10/01/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **42**

MATERIAL DESCRIPTION: **Black Border Tile**

MATERIAL LOCATION: **204 of 1909 Building**

MATERIAL QUANTITY: **200**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **3**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **43**
MATERIAL DESCRIPTION: **Black Border Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **204 of 1909 Building**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **10/01/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **43**

MATERIAL DESCRIPTION: **Black Border Tile Mastic**

MATERIAL LOCATION: **204 of 1909 Building**

MATERIAL QUANTITY: **50**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUILDING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **44**
MATERIAL DESCRIPTION: **2'x4' Ceiling Panels**
HISTORICAL AHERA DAMAGE CATEGORY: **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Kitchen of 1909 Building**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/01/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **44**
MATERIAL DESCRIPTION: **2'x4' Ceiling Panels**
MATERIAL LOCATION: **Kitchen of 1909 Building**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **45**
MATERIAL DESCRIPTION: **Terrazzo**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Washroom in Room D of 1909 Building**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/01/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **45**

MATERIAL DESCRIPTION: **Terrazzo**

MATERIAL LOCATION: **Washroom in Room D of 1909 Building**

MATERIAL QUANTITY: **150**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **46**
MATERIAL DESCRIPTION: **12"x12" Terrazzo**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **D Room of 1909 Building**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/01/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **46**
MATERIAL DESCRIPTION: **12"x12" Terrazzo**
MATERIAL LOCATION: **D Room of 1909 Building**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **47**
MATERIAL DESCRIPTION: **Boiler Wrap #1**
HISTORICAL AHERA DAMAGE CATEGORY **4 Damaged or significantly damaged friable misc. ACBM**
HISTORICAL DAMAGE REASON: **Air Erosion/Flow
Delamination
Deterioration**
HISTORICAL RESPONSE ACTION: **Repair**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **4. Damaged or significantly damaged friable misc. ACBM**

DAMAGE REASON: **Air Erosion/Flow
Delamination
Deterioration**
DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Boiler Room of 1909 Building**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **50** DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 10/01/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **47**
MATERIAL DESCRIPTION: **Boiler Wrap #1**
MATERIAL LOCATION: **Boiler Room of 1909 Building**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **50** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Repair and/or remove damaged TSI Wrap

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **48**
MATERIAL DESCRIPTION: **Boiler Wrap #2**
HISTORICAL AHERA DAMAGE CATEGORY **4 Damaged or significantly damaged friable misc. ACBM**
HISTORICAL DAMAGE REASON: **Air Erosion/Flow
Delamination
Deterioration**
HISTORICAL RESPONSE ACTION: **Repair**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **4. Damaged or significantly damaged friable misc. ACBM**

DAMAGE REASON: **Air Erosion/Flow
Delamination
Deterioration**
DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Boiler Room of 1909 Building**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **50** DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 10/01/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **48**

MATERIAL DESCRIPTION: **Boiler Wrap #2**

MATERIAL LOCATION: **Boiler Room of 1909 Building**

MATERIAL QUANTITY: **500**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **50**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

See HA 47

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **49**
MATERIAL DESCRIPTION: **Insulation Over Fiberglass**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Maintenance Room of 1909 Building**
MATERIAL QUANTITY: **140** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 10/01/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **49**

MATERIAL DESCRIPTION: **Insulation Over Fiberglass**

MATERIAL LOCATION: **Maintenance Room of 1909 Building**

MATERIAL QUANTITY: **140**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **50**
MATERIAL DESCRIPTION: **Mag Block Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Boiler Room of 1909 Building**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 10/01/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **50**

MATERIAL DESCRIPTION: **Mag Block Insulation**

MATERIAL LOCATION: **Boiler Room of 1909 Building**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **51**
MATERIAL DESCRIPTION: **Duct Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Boiler Room of 1909 Building**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/01/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **51**

MATERIAL DESCRIPTION: **Duct Insulation**

MATERIAL LOCATION: **Boiler Room of 1909 Building**

MATERIAL QUANTITY: **300**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **52**
MATERIAL DESCRIPTION: **Refractory Cement in Doors of #1 Boiler**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Boiler Room of 1909 Building**
MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/01/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **52**

MATERIAL DESCRIPTION: **Refractory Cement in Doors of #1 Boiler**

MATERIAL LOCATION: **Boiler Room of 1909 Building**

MATERIAL QUANTITY: **20**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **53**
MATERIAL DESCRIPTION: **Refractory Cement in Doors of #2 Boiler**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Boiler Room of 1909 Building**
MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/01/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **53**
MATERIAL DESCRIPTION: **Refractory Cement in Doors of #2 Boiler**
MATERIAL LOCATION: **Boiler Room of 1909 Building**
MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **54**
MATERIAL DESCRIPTION: **Firebrick in Boiler #1**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Boiler Room of 1909 Building**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/01/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **54**
MATERIAL DESCRIPTION: **Firebrick in Boiler #1**
MATERIAL LOCATION: **Boiler Room of 1909 Building**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **55**
MATERIAL DESCRIPTION: **Firebrick in Boiler #2**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Boiler Room of 1909 Building**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/01/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **55**

MATERIAL DESCRIPTION: **Firebrick in Boiler #2**

MATERIAL LOCATION: **Boiler Room of 1909 Building**

MATERIAL QUANTITY: **200**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **56**
MATERIAL DESCRIPTION: **4" Black Vinyl Baseboard**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **004 of 1909 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed**

Inspector's Signature: _____

Date: 10/01/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **56**

MATERIAL DESCRIPTION: **4" Black Vinyl Baseboard**

MATERIAL LOCATION: **004 of 1909 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUILDING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **57**
MATERIAL DESCRIPTION: **4" Black Vinyl Baseboard Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **004 of 1909 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed**

Inspector's Signature: _____ Date: **10/01/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **57**

MATERIAL DESCRIPTION: **4" Black Vinyl Baseboard Mastic**

MATERIAL LOCATION: **004 of 1909 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **5A**
MATERIAL DESCRIPTION: **12"x12" Multi-Gray Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **4 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **4. Damaged or significantly damaged friable misc. ACBM**

DAMAGE REASON: **Physical Damage**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Hallways of 1972 Annex**
MATERIAL QUANTITY: **1900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **15** DAMAGE UNITS: **SF**
COMMENTS: **12x12 multi grey floor tile - hallway by 410 5 ft cracked. Hallway by east side 10 ft cracked**

Inspector's Signature: _____ Date: 10/01/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **5A**
MATERIAL DESCRIPTION: **12"x12" Multi-Gray Floor Tile**
MATERIAL LOCATION: **Hallways of 1972 Annex**
MATERIAL QUANTITY: **1900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **15** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample material to determine asbestos content. Repair and/or remove all damaged ACBM

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **5B**
MATERIAL DESCRIPTION: **12"x12" Gray Floor Tile w/White Streaks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Book Room and Storage in 1972 Annex**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/01/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **5B**
MATERIAL DESCRIPTION: **12"x12" Gray Floor Tile w/White Streaks**
MATERIAL LOCATION: **Book Room and Storage in 1972 Annex**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **6**
MATERIAL DESCRIPTION: **Brown Linoleum**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Basement Room D of 1909 Building**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/01/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **6**
MATERIAL DESCRIPTION: **Brown Linoleum**
MATERIAL LOCATION: **Basement Room D of 1909 Building**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **60**
MATERIAL DESCRIPTION: **Green Ceramic Tile Grout**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Entrances of 1972 Annex**
MATERIAL QUANTITY: **10** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/01/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **60**

MATERIAL DESCRIPTION: **Green Ceramic Tile Grout**

MATERIAL LOCATION: **Entrances of 1972 Annex**

MATERIAL QUANTITY: **10**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **61**
MATERIAL DESCRIPTION: **Gray Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Classrooms, Teacher's Lounge and Office of 1972 Annex**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/01/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **61**
MATERIAL DESCRIPTION: **Gray Carpet Mastic**
MATERIAL LOCATION: **Classrooms, Teacher's Lounge and Office of 1972 Annex**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **65**
MATERIAL DESCRIPTION: **Exterior Door Caulk**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout 1972 Annex**
MATERIAL QUANTITY: **84** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 10/01/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **65**

MATERIAL DESCRIPTION: **Exterior Door Caulk**

MATERIAL LOCATION: **Throughout 1972 Annex**

MATERIAL QUANTITY: **84**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **66**
MATERIAL DESCRIPTION: **12"x12" Multi-Gray Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Hallways of 1972 Annex**

MATERIAL QUANTITY: **1900**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 10/01/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **66**
MATERIAL DESCRIPTION: **12"x12" Multi-Gray Floor Tile Mastic**
MATERIAL LOCATION: **Hallways of 1972 Annex**
MATERIAL QUANTITY: **1900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **67**
MATERIAL DESCRIPTION: **12"x12" Gray Floor Tile w/White Streaks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Book Room and Storage in 1972 Annex**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/01/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **67**

MATERIAL DESCRIPTION: **12"x12" Gray Floor Tile w/White Streaks Mastic**

MATERIAL LOCATION: **Book Room and Storage in 1972 Annex**

MATERIAL QUANTITY: **600**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **68**
MATERIAL DESCRIPTION: **Cementitious Pipe Joint Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Electric Room (Behind Wall) in 1972 Annex**
MATERIAL QUANTITY: **4** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS: **Not observed may be behind wall**

Inspector's Signature: _____ Date: **10/01/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **68**

MATERIAL DESCRIPTION: **Cementitious Pipe Joint Insulation**

MATERIAL LOCATION: **Electric Room (Behind Wall) in 1972 Annex**

MATERIAL QUANTITY: **4**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUILDING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **7**
MATERIAL DESCRIPTION: **Transite Panels**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Basement (Abated)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed - abated**

Inspector's Signature: _____ Date: **10/01/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **7**

MATERIAL DESCRIPTION: **Transite Panels**

MATERIAL LOCATION: **Basement (Abated)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **70**
MATERIAL DESCRIPTION: **Fiberglass Insulation**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Not Tested** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Electric Room of 1972 Annex**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **10/01/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **70**

MATERIAL DESCRIPTION: **Fiberglass Insulation**

MATERIAL LOCATION: **Electric Room of 1972 Annex**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **71**
MATERIAL DESCRIPTION: **Vault Door Liner**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **2nd Floor Landing N/E Stairwell**
MATERIAL QUANTITY: **15** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **10/01/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **71**
MATERIAL DESCRIPTION: **Vault Door Liner**
MATERIAL LOCATION: **2nd Floor Landing N/E Stairwell**
MATERIAL QUANTITY: **15** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **72**
MATERIAL DESCRIPTION: **12" x 12" Tan w/ lt. Brown floor tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Engineer's Office**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not observed**

Inspector's Signature: _____ Date: **10/01/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **72**

MATERIAL DESCRIPTION: **12" x 12" Tan w/ lt. Brown floor tile**

MATERIAL LOCATION: **Engineer's Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **73**
MATERIAL DESCRIPTION: **Mastic w/ 12" x 12" tan w/ lt. brown floor tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Engineer's Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed**

Inspector's Signature: _____

Date: 10/01/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **73**

MATERIAL DESCRIPTION: **Mastic w/ 12" x 12" tan w/ lt. brown floor tile**

MATERIAL LOCATION: **Engineer's Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **74**
MATERIAL DESCRIPTION: **12 x 12 Grey w/ Dk. Grey & White Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Engineer's Washroom**
MATERIAL QUANTITY: **60** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **10/01/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **74**

MATERIAL DESCRIPTION: **12 x 12 Grey w/ Dk. Grey & White Floor Tile**

MATERIAL LOCATION: **Engineer's Washroom**

MATERIAL QUANTITY: **60**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **75**
MATERIAL DESCRIPTION: **mastic w/ 12 x 12 Grey w/ Dk. Grey & White floor tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Engineer's Washroom**
MATERIAL QUANTITY: **60** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/01/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **75**

MATERIAL DESCRIPTION: **mastic w/ 12 x 12 Grey w/ Dk. Grey & White floor tile**

MATERIAL LOCATION: **Engineer's Washroom**

MATERIAL QUANTITY: **60**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **76**
MATERIAL DESCRIPTION: **purple carpet adhesive**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Principal's Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed**

Inspector's Signature: _____ Date: 10/01/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUILDING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **76**

MATERIAL DESCRIPTION: **purple carpet adhesive**

MATERIAL LOCATION: **Principal's Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **77**
MATERIAL DESCRIPTION: **12 x 12 Tan Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Principal's Office Room 104**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/01/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **77**

MATERIAL DESCRIPTION: **12 x 12 Tan Floor Tile**

MATERIAL LOCATION: **Principal's Office Room 104**

MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **78**
MATERIAL DESCRIPTION: **Mastic w/ 12 x 12 Tan Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Principal's Office Room 104**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/01/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **78**

MATERIAL DESCRIPTION: **Mastic w/ 12 x 12 Tan Floor Tile**

MATERIAL LOCATION: **Principal's Office Room 104**

MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **79**
MATERIAL DESCRIPTION: **12 x 12 Lt. Grey 2/ Dk. Grey & White Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **4 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **4. Damaged or significantly damaged friable misc. ACBM**

DAMAGE REASON: **Physical Damage**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Café**
MATERIAL QUANTITY: **2300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **8** DAMAGE UNITS: **SF**
COMMENTS: **12x12 lt gray, do, grey, white floor tile in cafe 8 ft (various areas) cracked**

Inspector's Signature: _____ Date: **10/01/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **79**
MATERIAL DESCRIPTION: **12 x 12 Lt. Grey 2/ Dk. Grey & White Floor Tile**
MATERIAL LOCATION: **Café**
MATERIAL QUANTITY: **2300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **8** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample material to determine asbestos content. Repair and/or remove all damaged ACBM

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **80**
MATERIAL DESCRIPTION: **Mastic w/ 12 x 12 Lt. Grey w/ Dk. Grey & White Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Café**
MATERIAL QUANTITY: **2300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/01/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **80**

MATERIAL DESCRIPTION: **Mastic w/ 12 x 12 Lt. Grey w/ Dk. Grey & White Floor Tile**

MATERIAL LOCATION: **Café**

MATERIAL QUANTITY: **2300**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **81**
MATERIAL DESCRIPTION: **12 x 12 Lt. Blue w/ Dk. Blue & White Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Café**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/01/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **81**

MATERIAL DESCRIPTION: **12 x 12 Lt. Blue w/ Dk. Blue & White Floor Tile**

MATERIAL LOCATION: **Café**

MATERIAL QUANTITY: **100**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **82**
MATERIAL DESCRIPTION: **Mastic w/ 12 x 12 Lt. Blue 2/ Dk. Blue & White Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Café**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/01/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **82**

MATERIAL DESCRIPTION: **Mastic w/ 12 x 12 Lt. Blue 2/ Dk. Blue & White Floor Tile**

MATERIAL LOCATION: **Café**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **83**
MATERIAL DESCRIPTION: **Tan Linoleum**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Basement Art Room**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**
COMMENTS: **Not observed**

Inspector's Signature: _____ Date: 10/01/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **83**

MATERIAL DESCRIPTION: **Tan Linoleum**

MATERIAL LOCATION: **Basement Art Room**

MATERIAL QUANTITY: **600**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **84**
MATERIAL DESCRIPTION: **Adhesive w/ Tan Linoleum**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Basement Art Room**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**
COMMENTS: **Not observed**

Inspector's Signature: _____ Date: 10/01/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **84**

MATERIAL DESCRIPTION: **Adhesive w/ Tan Linoleum**

MATERIAL LOCATION: **Basement Art Room**

MATERIAL QUANTITY: **600**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **85**
MATERIAL DESCRIPTION: **Brown Carpet Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1972 Annex Classrooms**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/01/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **85**
MATERIAL DESCRIPTION: **Brown Carpet Adhesive**
MATERIAL LOCATION: **1972 Annex Classrooms**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **86**
MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 104**
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/01/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **86**

MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile**

MATERIAL LOCATION: **Room 104**

MATERIAL QUANTITY: **700**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **87**
MATERIAL DESCRIPTION: **Mastic Associated w/ 12" x 12" Beige Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 104**
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/01/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **87**

MATERIAL DESCRIPTION: **Mastic Associated w/ 12" x 12" Beige Floor Tile**

MATERIAL LOCATION: **Room 104**

MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **88**
MATERIAL DESCRIPTION: **Vinyl Sheeting Glued on Plywood**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Gym**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/01/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **88**

MATERIAL DESCRIPTION: **Vinyl Sheeting Glued on Plywood**

MATERIAL LOCATION: **Gym**

MATERIAL QUANTITY: **3000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **89**
MATERIAL DESCRIPTION: **2' x 4' Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **N, S, E, W Corridor Entrances, Rooms 401-412**
MATERIAL QUANTITY: **7500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/01/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **89**

MATERIAL DESCRIPTION: **2' x 4' Ceiling Tile**

MATERIAL LOCATION: **N, S, E, W Corridor Entrances, Rooms 401-412**

MATERIAL QUANTITY: **7500**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **8A**
MATERIAL DESCRIPTION: **9"x9" Tan w/Ye, Blue, and White Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 100 in 1909 Building**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/01/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **8A**
MATERIAL DESCRIPTION: **9"x9" Tan w/Ye, Blue, and White Floor Tile Mastic**
MATERIAL LOCATION: **Room 100 in 1909 Building**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **8B**
MATERIAL DESCRIPTION: **9"x9" Tan Floor Tile w/Brown and White Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Faculty Washroom by Room 100 and Room 208 of 1909 Building**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/01/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **8B**
MATERIAL DESCRIPTION: **9"x9" Tan Floor Tile w/Brown and White Mastic**
MATERIAL LOCATION: **Faculty Washroom by Room 100 and Room 208 of 1909 Building**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **8C**
MATERIAL DESCRIPTION: **9"x9" Brown Floor Tile w/White and Red Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Faculty Washroom and Room 208 of 1909 Building**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/01/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **8C**
MATERIAL DESCRIPTION: **9"x9" Brown Floor Tile w/White and Red Mastic**
MATERIAL LOCATION: **Faculty Washroom and Room 208 of 1909 Building**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **8D**
MATERIAL DESCRIPTION: **9" x 9" Beige Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 104 of 1909 Building**
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/01/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **8D**
MATERIAL DESCRIPTION: **9" x 9" Beige Floor Tile Mastic**
MATERIAL LOCATION: **Room 104 of 1909 Building**
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUILDING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **8E**
MATERIAL DESCRIPTION: **9" x 9" Black Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Faculty Washroom of 1909 Building**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/01/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **8E**

MATERIAL DESCRIPTION: **9" x 9" Black Floor Tile Mastic**

MATERIAL LOCATION: **Faculty Washroom of 1909 Building**

MATERIAL QUANTITY: **50**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **8F**
MATERIAL DESCRIPTION: **9" x 9" Maroon Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Faculty Washroom of 1909 Building**
MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/01/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **8F**
MATERIAL DESCRIPTION: **9" x 9" Maroon Floor Tile Mastic**
MATERIAL LOCATION: **Faculty Washroom of 1909 Building**
MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **8G**
MATERIAL DESCRIPTION: **9" x 9" Brown Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 208 of 1909 Building**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/01/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **8G**
MATERIAL DESCRIPTION: **9" x 9" Brown Floor Tile Mastic**
MATERIAL LOCATION: **Room 208 of 1909 Building**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **8H**
MATERIAL DESCRIPTION: **9" x 9" Green Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 204 Of 1909 Building**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/01/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **8H**
MATERIAL DESCRIPTION: **9" x 9" Green Floor Tile Mastic**
MATERIAL LOCATION: **Room 204 Of 1909 Building**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **8I**
MATERIAL DESCRIPTION: **9" x 9" Aqua Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 301 of 1909 Building**
MATERIAL QUANTITY: **415** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/01/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **8I**
MATERIAL DESCRIPTION: **9" x 9" Aqua Floor Tile Mastic**
MATERIAL LOCATION: **Room 301 of 1909 Building**
MATERIAL QUANTITY: **415** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUILDING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **8J**
MATERIAL DESCRIPTION: **9" x 9" Aqua Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 301 of 1909 Building**
MATERIAL QUANTITY: **40** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/01/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **8J**
MATERIAL DESCRIPTION: **9" x 9" Aqua Floor Tile Mastic**
MATERIAL LOCATION: **Room 301 of 1909 Building**
MATERIAL QUANTITY: **40** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **8K**
MATERIAL DESCRIPTION: **9" x 9" Yellow Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 301 of 1909 Building**
MATERIAL QUANTITY: **40** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/01/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **8K**

MATERIAL DESCRIPTION: **9" x 9" Yellow Floor Tile Mastic**

MATERIAL LOCATION: **Room 301 of 1909 Building**

MATERIAL QUANTITY: **40**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUILDING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **8L**
MATERIAL DESCRIPTION: **9" x 9" Gray Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Gym of 1909 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not observed**

Inspector's Signature: _____ Date: 10/01/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **8L**

MATERIAL DESCRIPTION: **9" x 9" Gray Floor Tile Mastic**

MATERIAL LOCATION: **Gym of 1909 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUILDING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **8M**
MATERIAL DESCRIPTION: **9" x 9" Light Brown Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Gym of 1909 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed**

Inspector's Signature: _____ Date: **10/01/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **8M**

MATERIAL DESCRIPTION: **9" x 9" Light Brown Floor Tile Mastic**

MATERIAL LOCATION: **Gym of 1909 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **9A**
MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile w/ Brown Streaks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 005 of 1909 Building**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/01/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUILDING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **9A**
MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile w/ Brown Streaks Mastic**
MATERIAL LOCATION: **Room 005 of 1909 Building**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **9B**
MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile w/ Brn & Wh Spks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **101**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/01/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **9B**

MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile w/ Brn & Wh Spks Mastic**

MATERIAL LOCATION: **101**

MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **9C**
MATERIAL DESCRIPTION: **12"x12" Beige Floor Tile w/ Brn & Wh Strks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **206**
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/01/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **9C**

MATERIAL DESCRIPTION: **12"x12" Beige Floor Tile w/ Brn & Wh Strks Mastic**

MATERIAL LOCATION: **206**

MATERIAL QUANTITY: **700**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **9D**
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **301**
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/01/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **9D**

MATERIAL DESCRIPTION: **12" x 12" White Floor Tile Mastic**

MATERIAL LOCATION: **301**

MATERIAL QUANTITY: **700**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **A2**
MATERIAL DESCRIPTION: **Cementitious Insulation on Joints off Fiberglass**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout 1909 Building**
MATERIAL QUANTITY: **350** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: **10/01/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **A2**

MATERIAL DESCRIPTION: **Cementitious Insulation on Joints off Fiberglass**

MATERIAL LOCATION: **Throughout 1909 Building**

MATERIAL QUANTITY: **350** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **B1**
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **1 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON: **Physical Damage**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout 1909 Building**
MATERIAL QUANTITY: **1300** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **5** DAMAGE UNITS: **LF**
COMMENTS: **Cardboard pipe insulation boiler room 5 ft worn**

Inspector's Signature: _____ Date: 10/01/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **B1**
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**
MATERIAL LOCATION: **Throughout 1909 Building**
MATERIAL QUANTITY: **1300** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **5** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUILDING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **B2**
MATERIAL DESCRIPTION: **Cementitious Insulation off Paper Wrap Pipe Runs**
HISTORICAL AHERA DAMAGE CATEGORY: **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout 1909 Building**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 10/01/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **B2**

MATERIAL DESCRIPTION: **Cementitious Insulation off Paper Wrap Pipe Runs**

MATERIAL LOCATION: **Throughout 1909 Building**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **D1**
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Boiler Room**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: **10/01/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUIDLING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **D1**
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**
MATERIAL LOCATION: **Boiler Room**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUILDING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **90A**
MATERIAL DESCRIPTION: **9"x9" brown with white streak floor tile mastic**
MATERIAL LOCATION: **Room 301**
MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE:
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **7 Any remaining friable ACBM or friable suspect ACBM**
ACCESSIBILITY: **Barely Reachable** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**

COMMENTS:
Room 301 9x9 brown w white streak mastic

Inspector's Signature: _____ Date: 10/01/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUILDING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **90A**
MATERIAL DESCRIPTION: **9"x9" brown with white streak floor tile mastic**
MATERIAL LOCATION: **Room 301**
MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:
See HA 90

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23311	BUILDING ID:	3520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Gary School	INSPECTION DATE:	10/1/2019		
ADDRESS:	3740 W. 31st St.	IDPH LICENSE NO:	100-19554		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	98A		
MATERIAL DESCRIPTION:	12"x12" white with gray and black specks floor tile mastic		
MATERIAL LOCATION:	New building halls and classrooms		
MATERIAL QUANTITY:	4000	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Barely Reachable	DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE REASON:	
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

COMMENTS:

12x12 white with gray and black floor tile mastic hallways and classrooms of new building

Inspector's Signature: _____ Date: 10/01/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUILDING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **98A**
MATERIAL DESCRIPTION: **12"x12" white with gray and black specks floor tile mastic**
MATERIAL LOCATION: **New building halls and classrooms**
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:
See HA 98

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUILDING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **93A**

MATERIAL DESCRIPTION: **12"x12" gray with white floor tile mastic**

MATERIAL LOCATION: **Room 409 and 402**

MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**

MATERIAL CATEGORY: **MISC** FRIABLE:

ASBESTOS TYPE: **Assumed**

DISTURBANCE POTENTIAL: **LOW** CONDITION:

AHERA DAMAGE CATEGORY: **7 Any remaining friable ACBM or friable suspect ACBM**

ACCESSIBILITY: **Barely Reachable** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**

COMMENTS:
12x12 gray with white floor tile mastic Room 409 and 402

Inspector's Signature: _____

Date: **10/01/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUILDING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **93A**

MATERIAL DESCRIPTION: **12"x12" gray with white floor tile mastic**

MATERIAL LOCATION: **Room 409 and 402**

MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

See HA 90

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUILDING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **95A**
MATERIAL DESCRIPTION: **12"x12" white with beige floor tile mastic**
MATERIAL LOCATION: **New building first floor hallway**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE:
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Barely Reachable** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: **10/01/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUILDING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **95A**
MATERIAL DESCRIPTION: **12"x12" white with beige floor tile mastic**
MATERIAL LOCATION: **New building first floor hallway**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:
See HA 95

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUILDING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **96A**
MATERIAL DESCRIPTION: **12"x12" Brown floor tile mastic**
MATERIAL LOCATION: **New building 1st and 2nd floor hallway**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE:
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Barely Reachable** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**

COMMENTS:
12x12 brown floor tile mastic 1st and 2nd floor hallway

Inspector's Signature: _____ Date: 10/01/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUILDING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **96A**
MATERIAL DESCRIPTION: **12"x12" Brown floor tile mastic**
MATERIAL LOCATION: **New building 1st and 2nd floor hallway**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

See HA 96

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUILDING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **93**
MATERIAL DESCRIPTION: **12"x12" gray floor tile with white spec**
MATERIAL LOCATION: **Room 402 and 409**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE:
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **4 Damaged or significantly damaged friable misc. ACBM**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **5** DAMAGE REASON:
DAMAGE UNITS: **SF**

COMMENTS:
12x12 gray with white spec floor tile Room 409 - 2 ft cracked Room 402 - 3 ft cracked

Inspector's Signature: _____ Date: 10/01/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUILDING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **93**
MATERIAL DESCRIPTION: **12"x12" gray floor tile with white spec**
MATERIAL LOCATION: **Room 402 and 409**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **5** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

See HA 90

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUILDING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **95**
MATERIAL DESCRIPTION: **12"x12" white floor tile with beige streak**
MATERIAL LOCATION: **New building hallway by north entrance**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE:
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **4 Damaged or significantly damaged friable misc. ACBM**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **10** DAMAGE REASON:
DAMAGE UNITS: **SF**

COMMENTS:
New building first floor hall 12x12 white floor with beige streak 10 ft cracked

Inspector's Signature: _____ Date: 10/01/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUILDING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **95**
MATERIAL DESCRIPTION: **12"x12" white floor tile with beige streak**
MATERIAL LOCATION: **New building hallway by north entrance**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **10** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Sample material to determine asbestos content. Repair and/or remove all damaged ACBM

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUILDING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **97**
MATERIAL DESCRIPTION: **12"x12" Lt. Blue with dark blue speck floor tile**
MATERIAL LOCATION: **Room 501, 502, and 505**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE:
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **4 Damaged or significantly damaged friable misc. ACBM**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **4** DAMAGE REASON:
DAMAGE UNITS: **SF**

COMMENTS:
New building 12x12 light blue with dark blue speck room 503 - 4 ft cracked

Inspector's Signature: _____ Date: 10/01/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUILDING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **97**
MATERIAL DESCRIPTION: **12"x12" Lt. Blue with dark blue speck floor tile**
MATERIAL LOCATION: **Room 501, 502, and 505**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **4** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUILDING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **91**
MATERIAL DESCRIPTION: **9"x9" dark brown floor tile patch**
MATERIAL LOCATION: **Room 301**
MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE:
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **4 Damaged or significantly damaged friable misc. ACBM**

ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **5** DAMAGE REASON:
DAMAGE UNITS: **SF**

COMMENTS:
9x9 dark brown floor tile patch room 301 5 ft cracked

Inspector's Signature: _____ Date: **10/01/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUILDING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **91**

MATERIAL DESCRIPTION: **9"x9" dark brown floor tile patch**

MATERIAL LOCATION: **Room 301**

MATERIAL QUANTITY: **20**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **5**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

See HA 90

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23311	BUILDING ID:	3520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Gary School	INSPECTION DATE:	10/1/2019		
ADDRESS:	3740 W. 31st St.	IDPH LICENSE NO:	100-19554		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	91A				
MATERIAL DESCRIPTION:	9"x9" dark brown with white streak floor tile mastic				
MATERIAL LOCATION:	Room 301				
MATERIAL QUANTITY:	20	MATERIAL UNITS:	SF		
MATERIAL CATEGORY:	MISC	FRIABLE:			
ASBESTOS TYPE:	Assumed				
DISTURBANCE POTENTIAL:	LOW	CONDITION:			
AHERA DAMAGE CATEGORY:	7 Any remaining friable ACBM or friable suspect ACBM				
ACCESSIBILITY:	Barely Reachable	DAMAGE REASON:			
		DAMAGE REASON:			
		DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

COMMENTS:
9x9 dark brown floor tile with white streak mastic Room 301

Inspector's Signature: _____ Date: 10/01/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUILDING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **91A**

MATERIAL DESCRIPTION: **9"x9" dark brown with white streak floor tile mastic**

MATERIAL LOCATION: **Room 301**

MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

See HA 90

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUILDING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **97A**
MATERIAL DESCRIPTION: **12"x12" Lt. Blue with dark blue floor tile mastic**
MATERIAL LOCATION: **Room 501, 502, and 505**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE:
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Barely Reachable** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:
12x12 lt. blue floor tile with dark blue speck mastic

Inspector's Signature: _____ Date: 10/01/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUILDING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **97A**
MATERIAL DESCRIPTION: **12"x12" Lt. Blue with dark blue floor tile mastic**
MATERIAL LOCATION: **Room 501, 502, and 505**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUILDING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **96**
MATERIAL DESCRIPTION: **12"x12" Brown floor tile**
MATERIAL LOCATION: **1st and 2nd floor hallway**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE:
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **4 Damaged or significantly damaged friable misc. ACBM**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **30** DAMAGE REASON:
DAMAGE UNITS: **SF**

COMMENTS:
New building 12x12 brown floor tile 1st and 2nd floor hallway

Inspector's Signature: _____ Date: 10/01/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUILDING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **96**
MATERIAL DESCRIPTION: **12"x12" Brown floor tile**
MATERIAL LOCATION: **1st and 2nd floor hallway**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **30** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Sample material to determine asbestos content. Repair and/or remove all damaged ACBM

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUILDING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **90**
MATERIAL DESCRIPTION: **9"x9" Brown with white streak floor tile**
MATERIAL LOCATION: **Room 301**
MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE:
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **4 Damaged or significantly damaged friable misc. ACBM**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **5** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:
Room 301 - 5 ft cracked

Inspector's Signature: _____ Date: 10/01/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUILDING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **90**

MATERIAL DESCRIPTION: **9"x9" Brown with white streak floor tile**

MATERIAL LOCATION: **Room 301**

MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **5** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Sample material to determine asbestos content. Repair and/or remove all damaged ACBM in room 301

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUILDING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **92**
MATERIAL DESCRIPTION: **Brown carpet mastic**
MATERIAL LOCATION: **Room 105 and 106**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE:
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **4 Damaged or significantly damaged friable misc. ACBM**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **5** DAMAGE REASON:
DAMAGE UNITS: **SF**

COMMENTS:
Light brown carpet mastic Room 105 5 ft worn carpet (mastic exposed)

Inspector's Signature: _____ Date: 10/01/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUILDING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **92**
MATERIAL DESCRIPTION: **Brown carpet mastic**
MATERIAL LOCATION: **Room 105 and 106**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **5** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:
See HA 90

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUILDING ID: **3520**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Gary School** INSPECTION DATE: **10/1/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **98**
MATERIAL DESCRIPTION: **New building 12x12 white with gray and black speck floor tile**
MATERIAL LOCATION: **New building halls and classrooms**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE:
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **4 Damaged or significantly damaged friable misc. ACBM**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **13** DAMAGE REASON:
DAMAGE UNITS: **SF**

COMMENTS:
12x12 white with gray and black specks, hall by room 504 - 13 feet cracked

Inspector's Signature: _____ Date: 10/01/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUILDING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **98**
MATERIAL DESCRIPTION: **New building 12x12 white with gray and black speck floor tile**
MATERIAL LOCATION: **New building halls and classrooms**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **13** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:
Sample material to determine asbestos content. Repair and/or remove all damaged ACBM & Continue O&M

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23311	BUILDING ID:	3520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Gary School	INSPECTION DATE:	10/1/2019		
ADDRESS:	3740 W. 31st St.	IDPH LICENSE NO:	100-19554		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	94		
MATERIAL DESCRIPTION:	12"x12" Lt. Blue with white floor tile		
MATERIAL LOCATION:	Room 408		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	
AHERA DAMAGE CATEGORY:	4 Damaged or significantly damaged friable misc. ACBM		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
		DAMAGE REASON:	
DAMAGE QUANTITY:	2	DAMAGE REASON:	
		DAMAGE UNITS:	SF

COMMENTS:
12x12 lt. blue with white floor tile Room 408 - 2 ft cracked

Inspector's Signature: _____ Date: 10/01/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUILDING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **94**
MATERIAL DESCRIPTION: **12"x12" Lt. Blue with white floor tile**
MATERIAL LOCATION: **Room 408**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **2** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23311	BUILDING ID:	3520
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Gary School	INSPECTION DATE:	10/1/2019		
ADDRESS:	3740 W. 31st St.	IDPH LICENSE NO:	100-19554		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	94A		
MATERIAL DESCRIPTION:	12"x12" Lt. Blue with white floor tile mastic		
MATERIAL LOCATION:	Room 408		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	
AHERA DAMAGE CATEGORY:	7 Any remaining friable ACBM or friable suspect ACBM		
ACCESSIBILITY:	Barely Reachable	DAMAGE REASON:	
		DAMAGE REASON:	
DAMAGE QUANTITY:	0	DAMAGE REASON:	
		DAMAGE UNITS:	SF
COMMENTS:	12x12 Lt blue with white floor tile mastic Room 408		

Inspector's Signature: _____ Date: 10/01/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23311** BUILDING ID: **3520**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Gary School** REVIEW DATE: **10/18/2019**
ADDRESS: **3740 W. 31st St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **94A**

MATERIAL DESCRIPTION: **12"x12" Lt. Blue with white floor tile mastic**

MATERIAL LOCATION: **Room 408**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **10/18/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

APPENDIX B

Inspector and Management Planner Licenses

2019



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900 ♦ www.otssafety.com

Asbestos Building Inspector Initial

Occupational Training & Supply, Inc. certifies that

Carol Ashman


has successfully completed the Asbestos Building Inspector Initial course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 1/22/2019 - 1/24/2019

Exam Date: 1/24/2019

Expiration Date: 1/24/2020

Certificate Number: ABI1901240283


Kathy DeSalvo, Director



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • www.dph.illinois.gov

CAROL L ASHMAN
1633 Mc KAY ST.
WAUKEGAN, IL 60087

3/8/2019



ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 19554

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

 ASBESTOS PROFESSIONAL LICENSE		ENDORSEMENTS	TC EXPIRES
ID NUMBER 100 - 19554	ISSUED 3/8/2019	INSPECTOR	1/24/2020
EXPIRES 05/15/2020		PROJECT MANAGER	2/22/2020
CAROL L ASHMAN 1633 Mc KAY ST. WAUKEGAN, IL 60087 Environmental Health		AIR SAMPLING PROFESSIONAL	
		Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH, IMPROVING LIVES
Nationally Accredited by PHAB

2015



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Evan Christian

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 12/2/2015

Exam Date: 12/2/2015

Expiration Date: 12/2/2016

Certificate Number: BIR1512024159


Katy DeSalvo, Director

Reliable
Environmental
Solutions, Inc. **RES**

This is to certify that **Evan Christian**

*has on January 28 & 29, 2016, in Springfield, Illinois,
completed the requirements for asbestos accreditation under Section 206 of TSCA Title II*

Asbestos Management Planner Initial Training

*as accredited by the State of Illinois and approved by the U.S.E.P.A. under 40 CFR 763 (AHERA)
and passed the associated examination with a score of 70% or higher*

Course Date: January 28 & 29, 2016

Examination Date: January 29, 2016

Expiration Date: January 29, 2017

Certificate Number: MP/0103

William S. Williams

Training Program Manager, William S. Williams

4211 Westgate Drive, Springfield, Illinois ☐ 217.787.9800 ☐ 217.787.9801 FAX ☐ www.ReliableEnv.com

2019



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900 ♦ www.otssafety.com

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that
Evan Christian

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/19/2019

Exam Date: 11/19/2019

Expiration Date: 11/19/2020

Certificate Number: BIR1911192384


Kathy DeSalvo, Director



**ASBESTOS
PROFESSIONAL
LICENSE**

ID NUMBER
100 - 19466

ISSUED
4/12/2019

EXPIRES
05/15/2020

EVAN I CHRISTIAN
3024 N RACINE AVE, APT 2
CHICAGO, IL 60657



Environmental Health

ENDORSEMENTS

TC EXPIRES

INSPECTOR

11/28/2019

MANAGEMENT PLANNER

1/5/2019

PROJECT MANAGER

2/5/2020

AIR SAMPLING PROFESSIONAL

Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois
Department of Public Health

This license is valid only when accompanied by a valid
training course certificate.

2019



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900 ♦ www.otssafety.com

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Evan Christian

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Course Date: 1/7/2019

Exam Date: 1/7/2019

Expiration Date: 1/7/2020


Certificate Number: MPR1901070063



Kathy DeSalvo, Director

Evan Christian

Illinois Licensed Project Manager, and Air Sampling Professional



ENDORSEMENTS	TC EXPIRES
PROJECT MANAGER AIR SAMPLING PROFESSIONAL	12/12/2015
Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	

**CARNOW
CONIBEAR**

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL		
	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE		
	Loc	Localized
	Dist	Distributed