

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH  
AHERA THREE YEAR REINSPECTION  
ASBESTOS ABATEMENT PROGRAM  
SCHOOL INFORMATION FORM**

**SECTION I**

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299  
SCHOOL ID NUMBER: 14-016-2990-2223  
SCHOOL NAME: Goudy School  
ADDRESS OF SCHOOL: 5120 N Winthrop Avenue  
CITY: Chicago, IL, 60640

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **3/29/2016**

**If the address on this form is different than the address of the building, submit a written explanation.**

---

**SECTION II** *(Please type or print)*

**PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:**

DATE REINSPECTION COMPLETED: 10/1/2019 ENROLLMENT 657  
IDPH INSPECTOR LICENSE NUMBER: 100-18350  
IDPH LICENSED INSPECTOR NAME(Please Print): Joseph Hennigan  
IDPH MP LICENSE NUMBER: 100-07342  
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Jigar Shah

DESIGNATED PERSON (Please Print): Robert Christlieb PHONE: (773) 553-3197



10/1/2019

*Signature of Designated Person*

*Date*

**SECTION III**

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: \_\_\_\_\_

School has been closed. Date closed: \_\_\_\_\_

School building has been demolished. Date: \_\_\_\_\_

School building is asbestos free since last reinspection: \_\_\_\_\_

**Please explain in writing why the school building is now asbestos free and include the supporting documentation.**

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

**Explain in writing if the address of the building is different than the address on this form:**

---

---

---

**THREE-YEAR REINSPECTION**

**CHICAGO SCHOOL DIST 299**

**Goudy School**

5120 N Winthrop Avenue  
Chicago, IL, 60640

Unit: 23371  
Building ID: 3590

IDPH ID Number: 14-016-2990-2223

**REPORT DATE:**

Tuesday, October 01, 2019

**Prepared for:**

**Chicago Public Schools  
42 West Madison Street  
Chicago, IL 60602**

**Prepared by:**

**GSG-Probe Consulting, Inc.**

2942 W. Van Buren

Chicago, IL, 60612

Phone 3123197575

Fax

**DO NOT REMOVE FROM SCHOOL  
REQUIRED BY FEDERAL LAW**

September 19, 2019

Mr. Glen E. Garner  
Asbestos Program  
Illinois Department of Public Health  
525 West Jefferson Street  
Springfield, Illinois 62761

Re: Chicago Public Schools - 2019 Three-Year Reinspections

Dear Mr. Glen:

GSG-Probe Consulting, Inc., Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 1, 2 Elementary Schools. Please update your records with the following information.

School District: 299            Unit: 23371            Region: 01            IDPH ID:14-016-2990-2223

School: Goudy School            Building ID: 3590

Address: 5120 N Winthrop Avenue

Chicago, IL, 60640

Building Contact:

Contact Phone:

Current Building Owners: Chicago Public Schools

Review Date: 10/14/2019

Inspector: Joseph Hennigan

Inspector IDPH License: 100-18350

Management Planner: Jigar Shah

Management Planner IDPH License: 100-07342

If you have any questions or comments, please contact us at 3123197575

Sincerely,  
GSG-Probe Consulting, Inc.

Jigar Shah  
100-07342

## **Environmental Notification to Occupants**

To: Faculty, Staff and Parents  
From: Chicago Public Schools  
Date: September 19, 2019

RE: Goudy School, Unit 23371  
5120 N Winthrop Avenue  
Chicago, IL, 60640

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2019 asbestos three year re-inspection has been completed at Goudy School, following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at Goudy School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Robert Christlieb, the designated Local Education Authority's Designated Person at (773) 553-3197 .

## **Table of Contents**

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

### **APPENDICES:**

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

## SCHOOL AND INSPECTION INFORMATION

### 1. School Information

School: Goudy School Unit: 23371 Region: 01  
Address: 5120 N Winthrop Avenue Chicago, IL, 60640  
IDPH ID: 14-016-2990-2223 Building ID: 3590  
Contact: Phone:

### 2. Description of Facility

Original Construction: 1937 Additional Construction: 1953,2003  
Total Square Footage: 48127 No of Floors: 3  
Current Occupancy: 657

### 3. LEA Designated Person

Contact: Robert Christlieb Phone: (773) 553-3197  
Address: 42 West Madison Street  
Chicago, IL 60602

### 4. Managing Environmental Consultant

MEC: GSG-Probe Consulting, Inc.  
Contact: Jigar Shah  
Address 2942 W. Van Buren  
Chicago, IL, 60612  
Phone: 3123197575 Fax:

### 5. Inspector

Inspector Name: Joseph Hennigan

Inspector IDPH license # 100-18350

Signature:  
Date: 9/19/2019

### 6. Management Planner

Management Planner Name: Jigar Shah

Management Planner IDPH license # 100-07342

Signature:  
Date: 10/14/2019

### 7. Review Date:10/14/2019

### 8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature:



Date: 10/1/2019

Name: Robert Christlieb

## II. EXECUTIVE SUMMARY

GSG-Probe Consulting, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Goudy School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.85 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 3590:

B. The following new homogenous areas have been identified for Building 3590:

53	Cloth Wire Insulation
54	Sink Undercoating
55	Sink Undercoating



C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

36	Terrazzo
37	Carpet Mastic
38	Terrazzo
39	Drywall System
40	2' x 4' Ceiling Tile
41	12" X 12" Off-white with tan streaks VFT
41A	12" X 12" Off-white with tan streaks VFT mastic
42	12" X 12" Beige with white-and-tan streaks VFT
42A	12" X 12" Beige with white-and-tan streaks VFT Mastic
43	12" x 12" Blue/green- streaked VFT
43A	12" X 12" Blue/green-streaked VFT Mastic
44	12" X 12" Yellow streaked VFT
44A	12" X 12" Yellow streaked VFT mastic
45	12" x 12" White with blue-and-black specks VFT
45A	12" x 12" White with blue-and-black specks VFT mastic
46	2' X 4' Smooth ceiling tile
47	Spray-on fire proofing
48	9" X 9" Tan VFT
48A	9" X 9" Tan VFT Mastic
49	1' X 1' Ceiling tile
49A	1' X 1' Ceiling tile mastic
50	Decorative plaster
51	Tectum wall panels
52	Carpet Mastic
53	Cloth Wire Insulation
54	Sink Undercoating
55	Sink Undercoating
A	12"x12" White w/ Tan Vinyl Floor Tile
H	12"x12" Tan Vinyl Floor Tile
N	9"x9" Red Vinyl Floor Tile Mastic
W	12"x12" Tan VFT
Y	12" x 12" White w/beige streaks VFT
Y1	12" x 12" White w/beige streaks VFT Mastic
Z	Carpet Mastic
Z1	2' x 4' Ceiling Tiles
Z2	2' x 4' Ceiling Tiles

The following areas were deemed to be inaccessible:

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Joseph Hennigan, IDPH License # 100-18350. The Management Plan was updated by Jigar Shah, IDPH License # 100-07342. Inspector and Management Planner Licenses are included in Appendix B.

### **III. METHODOLOGY**

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

### **IV. ABATEMENT HISTORY**

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

### **V. REASSESSMENTS AND RECOMMENDATIONS**

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

### **VI. CONCLUSIONS**

The Goudy School Building 3590 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

**Table I**  
**Inspector's Reinspection Findings**

---

# Chicago Public Schools

School Goudy School Unit 23371 Building ID 3590

Address 5120 N Winthrop Avenue Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
07	Mudded Joint Packing (MJP) on Fiber Glass Pipe Insulation	75	EA	Boiler Room, & Switch Room Storage - 1936 Bldg.	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
08	Mudded Joint Compound on Cardboard Pipe Insulation	55	EA	Boiler Room, Air Tunnel #4, & Unexcavated Areas - 1936 Bldg.	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
10	Aircell Pipe Insulation	950	LF	Air Tunnel, Boiler, Pump, & Fan Rooms, Unex. Areas, NW Fan Rooms, Boiler Closet - 1936 Bldg.	CHR	TSI	Y	DIST	10		No	Damaged or significantly damaged friable thermal system insulating ACBM	3	MODERATE
11	Cardboard Pipe Insulation	1,000	LF	Boiler Room, Air Tunnel #4, & Unexcavated Areas - 1936 Bldg.	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
20	Mag Block Pipe Insulation	50	LF	Boiler Room, Pump Room, Air Tunnel - 1936 Bldg.	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
22	Aircell Duct Insulation	2,000	SF	Unexcavated Crawl Area - 1936 Bldg.	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
24	Mudded Joint Packing on Aircell Pipe Insulation	200	LF	Air Tunnel, Boiler, Pump, & Fan Rooms, Unex. Areas, SE & NW Fan Rooms, Boiler Closet - 1936 Bldg.	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
25	Aircell Pipe Insulation	1,500	LF	Basement - 1954 Bldg.	CHR	TSI	Y	LOC	10		No	Damaged or significantly damaged friable thermal system insulating ACBM	1	MODERATE
26	Cardboard Pipe Insulation	1,000	LF	Unexcavated Areas - 1954 Bldg.	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
31	Mudded Joint Packing on Aircell Pipe Insulation	300	EA	Corridor and unexcavated crawl space - 1954	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
32	MJP E/F/V on Mag Block Pipe Insulation	50	EA	Boiler Room, Pump Room & Tunnel - 1936 Bldg.	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
33	Mag Block Pipe Insulation	250	LF	Unexcavated Areas - 1954 Bldg.	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
34	MJP E/F/V on Mag Block Pipe Insulation	25	EA	Unexcavated Areas - 1954 Bldg.	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW

# Chicago Public Schools

School Goudy School Unit 23371 Building ID 3590

Address 5120 N Winthrop Avenue Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
35	MJP E/F/V on Cardboard Pipe Insulation	20	EA	Unexcavated Areas - 1954 Bldg.	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
36	Terrazzo	2,500	SF	Stairwells - 1936 Bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
37	Carpet Mastic	3,000	SF	Library (321) - 2003 Addition	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
38	Terrazzo	5,800	SF	Stairwells; 1st, 2nd, and 3rd floor corridors; boys, girls, and faculty toilets all floors - 2003 Addition	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
39	Drywall System	2,500	SF	1st, 2nd, and 3rd floor boys and girls toilets; Rms 314, 316, 214 and 218 - 2003 Addition	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
40	2' x 4' Ceiling Tile	10,000	SF	Throughout 2003 Addition	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
41	12" X 12" Off-white with tan streaks VFT	3,600	SF	Rooms 314, 316, 214, 216, 218, 225, 116, 114, and 125 - 2003 Addition	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
41A	12" X 12" Off-white with tan streaks VFT mastic	3,600	SF	Rooms 314, 316, 214, 216, 218, 225, 116, 114, and 125 - 2003 Addition	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
42	12" X 12" Beige with white-and-tan streaks VFT	4,500	SF	Rooms 323, 314, 316, 214, 216, 218, 225, 223, 116, 114, and 125 - 2003 Addition	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
42A	12" X 12" Beige with white-and-tan streaks VFT Mastic	4,500	SF	Rooms 323, 314, 316, 214, 216, 218, 225, 223, 116, 114, and 125 - 2003 Addition	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
43	12" x 12" Blue/green- streaked VFT	2,000	SF	Rooms 318, 314, 316, Storage 315, 214, 216, 218, 225, 116, 114, 125, 121F, 121E (Women), 121D (Men), and 121B	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
43A	12" X 12" Blue/green-streaked VFT Mastic	2,000	SF	Rooms 318, 314,	ASSUMED	MISC	N	NONE	0		No	ACBM with the		LOW

# Chicago Public Schools

School Goudy School Unit 23371 Building ID 3590

Address 5120 N Winthrop Avenue Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				316, Storage 315, 214, 216, 218, 225, 116, 114, 125, 121F, 121E (Women), 121D (Men), and 121B								potential for damage		
44	12" X 12" Yellow streaked VFT	100	SF	Multipurpose - 2003 Addition	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
44A	12" X 12" Yellow streaked VFT mastic	100	SF	Multipurpose - 2003 Addition	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
45	12" x 12" White with blue-and-black specks VFT	5,800	SF	Multipurpose, Serving Room 217A, Elevator	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
45A	12" x 12" White with blue-and-black specks VFT mastic	5,800	SF	Multipurpose, Serving Room 217A, Elevator	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
46	2' X 4' Smooth ceiling tile	2,600	SF	Kitchen, Serving Room, Women's Toilet 121 E, Men's Toilet 121 D, Dishwasher Room 127	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
47	Spray-on fire proofing	10,000	SF	Throughout 2003 Addition	ASSUMED	SURFACE	Y	NONE	0		No	ACBM with the potential for damage		LOW
48	9" X 9" Tan VFT	100	SF	Room 110 Storage Closet & Wardrobe - 1936 Bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
48A	9" X 9" Tan VFT Mastic	100	SF	Room 110 Storage Closet & Wardrobe - 1936 Bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
49	1' X 1' Ceiling tile	3,000	SF	Assembly Hall - 1936 bldg	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
49A	1' X 1' Ceiling tile mastic	3,000	SF	Assembly Hall - 1936 bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
50	Decorative plaster	1,500	SF	Assembly Hall - 1936 Bldg	ASSUMED	SURFACE	N	NONE	0		No	ACBM with the potential for damage		LOW
51	Tectum wall panels	2,000	SF	Gym - 1936 Bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
52	Carpet Mastic	800	SF	Room 212 - 1954 Addition	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
53	Cloth Wire Insulation	1	LF	2nd Floor Women's Restroom - 1936 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
54	Sink Undercoating	5	SF	Room 111 - 1936	ASSUMED	MISC	N	NONE	0		No	ACBM with the		





# Chicago Public Schools

School Goudy School Unit 23371 Building ID 3590

Address 5120 N Winthrop Avenue Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
P	Brown Linoleum Mastic			1st Floor Storage (closet next to Auditorium) - 1936 Bldg.	NO_ACBM									
Q	9"x9" Grey w/ White & Pink Streaks VFT	250	SF	Office Supply Store Room - 1936 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
R	9"x9" Grey w/ White & Pink Streaks VFT Mastic	250	SF	Office Supply Store Room - 1936 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
S	9"x9" Pink Vinyl Floor Tile ABATED			1st Floor Vault - 1954 (New Connection Corridor to 2003-2004 Annex)	ABATED	MISC		None				Any remaining friable ACBM or friable suspect ACBM		
T	9"x9" Pink Vinyl Floor Tile Mastic - ABATED			1st Floor Vault - 1954 (New Connection Corridor to 2003-2004 Annex)	ABATED	MISC		None				Any remaining friable ACBM or friable suspect ACBM		
U	12"x12" White Textured Vinyl Floor Tile NOT OBSERVED			1st Floor Vault - 1954 Addition NOT OBSERVED	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
V	12"x12" White Textured Vinyl Floor Tile Mastic NOT OBSERVED			1st Floor Vault - 1954 Addition NOT OBSERVED	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
W	12"x12" Tan VFT	3,500	SF	2nd, & 3rd Floor Corridors & Room 13; Room 212; 312, 313 - 1954 Addition	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
X	12"x12" Tan VFT Mastic	3,500	SF	2nd, & 3rd Floor Corridors & Rooms 212 & 213, 312, 313 - 1954 Addition	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
Y	12" x 12" White w/beige streaks VFT	575	SF	1st, 2nd, 3rd Floor former vaulted area (corridors) - 1954 addition	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
Y1	12" x 12" White w/beige streaks VFT Mastic	575	SF	1st, 2nd, 3rd Floor former vaulted area (corridors) - 1954 addition	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
Z	Carpet Mastic	200	SF	Main Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
Z1	2' x 4' Ceiling Tiles	40,000	SF	Throughout 1936 Building	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW

# Chicago Public Schools

School Goudy School Unit 23371 Building ID 3590

Address 5120 N Winthrop Avenue Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

*Inspector's Comments are Summarized at the End of the Report*

---

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
Z2	2' x 4' Ceiling Tiles	5,000	SF	1st, 2nd, 3rd Floor Corridors; Rooms 313, 312, 213, 212, 113, and 112 - 1954 Addition	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW

# Chicago Public Schools

School Goudy School Unit 23371 Building ID 3590

Address 5120 N Winthrop Avenue Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

*Inspector's Comments are Summarized at the End of the Report*

Reinspection Date <b>9/19/2019</b>
Inspector Name <b>Joseph Hennigan</b>
<b>100-18350</b> <b>5/15/2020</b>
Inspector's IDPH License Number / Expiration Date

### Inspector's Comments

HA Number:	Inspector Comments:
07	
08	
10	
11	
20	
22	
24	
25	
26	
31	
32	
33	
34	
35	
36	
37	
38	
39	
40	
41	
41A	
42	
42A	

# Chicago Public Schools

School Goudy School Unit 23371 Building ID 3590

Address 5120 N Winthrop Avenue Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
43	
43A	
44	
44A	
45	
45A	
46	
47	
48	
48A	
49	
49A	
50	
51	
52	
53	
54	
55	
A	
B	
C	
D	
E	
F	
G	
H	
I	
J	
M	

# Chicago Public Schools

School Goudy School Unit 23371 Building ID 3590

Address 5120 N Winthrop Avenue Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
N	
O	
P	
Q	
R	
S	
T	
U	
V	
W	
X	
Y	
Y1	
Z	
Z1	
Z2	

**Table II**

**Management Planner's Review**

---

# Chicago Public Schools

**School** Goudy School  
**Address** 5120 N Winthrop Avenue

**Unit** 23371  
Chicago, IL, 60640

**Building ID** 3590  
**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575

Fax:

### Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
07	Mudded Joint Packing (MJP) on Fiber Glass Pipe Insulation	75	EA	Boiler Room, & Switch Room Storage - 1936 Bldg.	Chrysotile	TSI	Yes	0	EA	6 ACBM with the potential for damage	Follow O&M Plan
08	Mudded Joint Compound on Cardboard Pipe Insulation	55	EA	Boiler Room, Air Tunnel #4, & Unexcavated Areas - 1936 Bldg.	Chrysotile	TSI	Yes	0	EA	6 ACBM with the potential for damage	Follow O&M Plan
10	Aircell Pipe Insulation	950	LF	Air Tunnel, Boiler, Pump, & Fan Rooms, Unex. Areas, NW Fan Rooms, Boiler Closet - 1936 Bldg.	Chrysotile	TSI	Yes	10	LF	1 Damaged or significantly damaged friable thermal system insulating ACBM	Repair
11	Cardboard Pipe Insulation	1,000	LF	Boiler Room, Air Tunnel #4, & Unexcavated Areas - 1936 Bldg.	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
20	Mag Block Pipe Insulation	50	LF	Boiler Room, Pump Room, Air Tunnel - 1936 Bldg.	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
22	Aircell Duct Insulation	2,000	SF	Unexcavated Crawl Area - 1936 Bldg.	Chrysotile	TSI	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
24	Mudded Joint Packing on Aircell Pipe Insulation	200	LF	Air Tunnel, Boiler, Pump, & Fan Rooms, Unex. Areas, SE & NW Fan Rooms, Boiler Closet - 1936 Bldg.	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
25	Aircell Pipe Insulation	1,500	LF	Basement - 1954 Bldg.	Chrysotile	TSI	Yes	10	LF	1 Damaged or significantly damaged friable thermal system insulating ACBM	Repair
26	Cardboard Pipe Insulation	1,000	LF	Unexcavated Areas - 1954 Bldg.	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
31	Mudded Joint Packing on Aircell Pipe Insulation	300	EA	Corridor and unexcavated crawl space - 1954	Chrysotile	TSI	Yes	0	EA	6 ACBM with the potential for damage	Follow O&M Plan
32	MJP E/F/V on Mag Block Pipe Insulation	50	EA	Boiler Room, Pump Room & Tunnel - 1936 Bldg.	Chrysotile	TSI	Yes	0	EA	6 ACBM with the potential for damage	Follow O&M Plan
33	Mag Block Pipe Insulation	250	LF	Unexcavated Areas - 1954 Bldg.	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
34	MJP E/F/V on Mag Block Pipe Insulation	25	EA	Unexcavated Areas - 1954 Bldg.	Chrysotile	TSI	Yes	0	EA	6 ACBM with the potential for damage	Follow O&M Plan
35	MJP E/F/V on Cardboard Pipe Insulation	20	EA	Unexcavated Areas - 1954 Bldg.	Chrysotile	TSI	Yes	0	EA	6 ACBM with the potential for damage	Follow O&M Plan
36	Terrazzo	2,500	SF	Stairwells - 1936 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
37	Carpet Mastic	3,000	SF	Library (321) - 2003 Addition	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
38	Terrazzo	5,800	SF	Stairwells; 1st, 2nd, and 3rd floor corridors; boys, girls, and faculty toilets all floors - 2003 Addition	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
39	Drywall System	2,500	SF	1st, 2nd, and 3rd floor boys and girls toilets; Rms 314, 316, 214 and 218 - 2003 Addition	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
40	2' x 4' Ceiling Tile	10,000	SF	Throughout 2003 Addition	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
41	12" X 12" Off-white with tan streaks VFT	3,600	SF	Rooms 314, 316, 214, 216, 218, 225,	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

School Goudy School  
Address 5120 N Winthrop Avenue

Unit 23371  
Chicago, IL, 60640

Building ID 3590  
Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575

Fax:

### Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				116, 114, and 125 - 2003 Addition							
41A	12" X 12" Off-white with tan streaks VFT mastic	3,600	SF	Rooms 314, 316, 214, 216, 218, 225, 116, 114, and 125 - 2003 Addition	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
42	12" X 12" Beige with white-and-tan streaks VFT	4,500	SF	Rooms 323, 314, 316, 214, 216, 218, 225, 223, 116, 114, and 125 - 2003 Addition	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
42A	12" X 12" Beige with white-and-tan streaks VFT Mastic	4,500	SF	Rooms 323, 314, 316, 214, 216, 218, 225, 223, 116, 114, and 125 - 2003 Addition	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
43	12" x 12" Blue/green- streaked VFT	2,000	SF	Rooms 318, 314, 316, Storage 315, 214, 216, 218, 225, 116, 114, 125, 121F, 121E (Women), 121D (Men), and 121B	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
43A	12" X 12" Blue/green-streaked VFT Mastic	2,000	SF	Rooms 318, 314, 316, Storage 315, 214, 216, 218, 225, 116, 114, 125, 121F, 121E (Women), 121D (Men), and 121B	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
44	12" X 12" Yellow streaked VFT	100	SF	Multipurpose - 2003 Addition	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
44A	12" X 12" Yellow streaked VFT mastic	100	SF	Multipurpose - 2003 Addition	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
45	12" x 12" White with blue-and-black specks VFT	5,800	SF	Multipurpose, Serving Room 217A, Elevator	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
45A	12" x 12" White with blue-and-black specks VFT mastic	5,800	SF	Multipurpose, Serving Room 217A, Elevator	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
46	2' X 4' Smooth ceiling tile	2,600	SF	Kitchen, Serving Room, Women's Toilet 121 E, Men's Toilet 121 D, Dishwasher Room 127	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
47	Spray-on fire proofing	10,000	SF	Throughout 2003 Addition	Assumed	SURFACE	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
48	9" X 9" Tan VFT	100	SF	Room 110 Storage Closet & Wardrobe - 1936 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
48A	9" X 9" Tan VFT Mastic	100	SF	Room 110 Storage Closet & Wardrobe - 1936 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
49	1' X 1' Ceiling tile	3,000	SF	Assembly Hall - 1936 bldg	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
49A	1' X 1' Ceiling tile mastic	3,000	SF	Assembly Hall - 1936 bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
50	Decorative plaster	1,500	SF	Assembly Hall - 1936 Bldg	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
51	Tectum wall panels	2,000	SF	Gym - 1936 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan



# Chicago Public Schools

**School** Goudy School  
**Address** 5120 N Winthrop Avenue

**Unit** 23371  
Chicago, IL, 60640

**Building ID** 3590  
**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575

Fax:

### Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
52	Carpet Mastic	800	SF	Room 212 - 1954 Addition	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
53	Cloth Wire Insulation	1	LF	2nd Floor Women's Restroom - 1936 Bldg.	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
54	Sink Undercoating	5	SF	Room 111 - 1936 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
55	Sink Undercoating	45	SF	Rooms 114, 125, 223, 316, 321B - 2003 Annex	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
A	12"x12" White w/ Tan Vinyl Floor Tile	2,295	SF	Rooms 112, 113, 213 - 1954 Addition	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
B	9"x9" Brown Vinyl Floor Tile	100	SF	Room 110 Storage Closet and Wardrobe - 1936 Bldg	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
C	Tan Linoleum - REMOVED			Room 111 (Kitchen) - 1936 Bldg	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
D	12"x12" White w/ Tan Vinyl Floor Tile Mastic	2,295	SF	Rooms 112, 113, 213 - 1954 Addition	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
E	12"x12" Tan Vinyl Floor Tile Mastic	5,950	SF	1st, 2nd, & 3rd Floor Corridors and Main Office - 1936 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
F	9"x9" Brown Vinyl Floor Tile Mastic	100	SF	Room 110 Storage Closet and Wardrobe - 1936 Bldg	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
G	Tan Linoleum Mastic - REMOVED			Room 111 - 1936 Bldg.	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
H	12"x12" Tan Vinyl Floor Tile	5,950	SF	1st, 2nd, & 3rd Floor Corridors and Main Office - 1936 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
I	Green Linoleum			Assembly Hall - 1936 Bldg.	No ACBM						
J	Green Linoleum Mastic			Assembly Hall - 1936 Bldg.	No ACBM						
M	9"x9" Red Vinyl Floor Tile	150	SF	Engineer's Office, Basement Janitors Closet(Boiler Room Closet) - 1936 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
N	9"x9" Red Vinyl Floor Tile Mastic	150	SF	Engineer's Office, Basement Janitors Closet(Boiler Room Closet) - 1936 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
O	Brown Linoleum			1st Floor Storage (closet next to Auditorium) - 1936 Bldg.	No ACBM						
P	Brown Linoleum Mastic			1st Floor Storage (closet next to Auditorium) - 1936 Bldg.	No ACBM						
Q	9"x9" Grey w/ White & Pink Streaks VFT	250	SF	Office Supply Store Room - 1936 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
R	9"x9" Grey w/ White & Pink Streaks VFT Mastic	250	SF	Office Supply Store Room - 1936 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
S	9"x9" Pink Vinyl Floor Tile ABATED			1st Floor Vault - 1954 (New Connection	Abated	MISC				7 Any remaining friable ACBM or friable	Follow O&M Plan

# Chicago Public Schools

**School** Goudy School  
**Address** 5120 N Winthrop Avenue

**Unit** 23371  
 Chicago, IL, 60640

**Building ID** 3590  
**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575

Fax:

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				Corridor to 2003-2004 Annex)						suspect ACBM	
T	9"x9" Pink Vinyl Floor Tile Mastic - ABATED			1st Floor Vault - 1954 (New Connection Corridor to 2003-2004 Annex)	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
U	12"x12" White Textured Vinyl Floor Tile NOT OBSERVED			1st Floor Vault - 1954 Addition NOT OBSERVED	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
V	12"x12" White Textured Vinyl Floor Tile Mastic NOT OBSERVED			1st Floor Vault - 1954 Addition NOT OBSERVED	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
W	12"x12" Tan VFT	3,500	SF	2nd, & 3rd Floor Corridors & Room 13; Room 212; 312, 313 - 1954 Addition	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
X	12"x12" Tan VFT Mastic	3,500	SF	2nd, & 3rd Floor Corridors & Rooms 212 & 213, 312, 313 - 1954 Addition	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
Y	12" x 12" White w/beige streaks VFT	575	SF	1st, 2nd, 3rd Floor former vaulted area (corridors) - 1954 addition	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
Y1	12" x 12" White w/beige streaks VFT Mastic	575	SF	1st, 2nd, 3rd Floor former vaulted area (corridors) - 1954 addition	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
Z	Carpet Mastic	200	SF	Main Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
Z1	2' x 4' Ceiling Tiles	40,000	SF	Throughout 1936 Building	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
Z2	2' x 4' Ceiling Tiles	5,000	SF	1st, 2nd, 3rd Floor Corridors; Rooms 313, 312, 213, 212, 113, and 112 - 1954 Addition	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Goudy School  
**Address** 5120 N Winthrop Avenue

**Unit** 23371  
 Chicago, IL, 60640

**Building ID** 3590  
**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG-Probe Consulting, Inc.  
 2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

*Management Planner's Comments Summarized at the End of the Report*

Review Date	10/14/2019
Manager Planner Name	Jigar Shah
100-07342	5/15/2020
Manager IDPH License No/Expiration	

HA Number	Management Comments
07	
08	
10	Repair Damaged ACM ASAP
11	
20	
22	
24	
25	Repair
26	
31	
32	
33	
34	
35	
36	
37	
38	

# Chicago Public Schools

**School** Goudy School  
**Address** 5120 N Winthrop Avenue

**Unit** 23371  
Chicago, IL, 60640

**Building ID** 3590  
**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG-Probe Consulting, Inc.  
2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
39	
40	
41	
41A	
42	
42A	
43	
43A	
44	
44A	
45	
45A	
46	
47	
48	
48A	
49	
49A	
50	
51	
52	
53	
54	
55	
A	
B	

# Chicago Public Schools

**School** Goudy School  
**Address** 5120 N Winthrop Avenue

**Unit** 23371  
Chicago, IL, 60640

**Building ID** 3590  
**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG-Probe Consulting, Inc.  
2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
C	
D	
E	
F	
G	
H	
I	
J	
M	
N	
O	
P	
Q	
R	
S	
T	
U	
V	
W	
X	
Y	
Y1	
Z	
Z1	
Z2	

# Chicago Public Schools

**School** Goudy School  
**Address** 5120 N Winthrop Avenue

**Unit** 23371  
Chicago, IL, 60640

**Building ID** 3590  
**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG-Probe Consulting, Inc.  
2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575

Fax:

*Management Planner's Comments Summarized at the End of the Report*

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Goudy School** INSPECTION DATE: **9/19/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **07**  
MATERIAL DESCRIPTION: **Mudded Joint Packing (MJP) on Fiber Glass Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Boiler Room, & Switch Room Storage - 1936 Bldg.**

MATERIAL QUANTITY: **75** MATERIAL UNITS: **EA**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/19/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Goudy School** REVIEW DATE: **10/14/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **07**  
MATERIAL DESCRIPTION: **Mudded Joint Packing (MJP) on Fiber Glass Pipe Insulation**  
MATERIAL LOCATION: **Boiler Room, & Switch Room Storage - 1936 Bldg.**  
MATERIAL QUANTITY: **75** MATERIAL UNITS: **EA**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Goudy School** INSPECTION DATE: **9/19/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **08**  
MATERIAL DESCRIPTION: **Mudded Joint Compound on Cardboard Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Boiler Room, Air Tunnel #4, & Unexcavated Areas - 1936 Bldg.**  
MATERIAL QUANTITY: **55** MATERIAL UNITS: **EA**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/19/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Goudy School** REVIEW DATE: **10/14/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **08**  
MATERIAL DESCRIPTION: **Mudded Joint Compound on Cardboard Pipe Insulation**  
MATERIAL LOCATION: **Boiler Room, Air Tunnel #4, & Unexcavated Areas - 1936 Bldg.**  
MATERIAL QUANTITY: **55** MATERIAL UNITS: **EA**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Goudy School** INSPECTION DATE: **9/19/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10**  
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **1 Damaged or significantly damaged friable thermal system insulating ACBM**  
HISTORICAL DAMAGE REASON: **Deterioration**  
HISTORICAL RESPONSE ACTION: **Repair**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON: **Deterioration**  
DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Air Tunnel, Boiler, Pump, & Fan Rooms, Unex. Areas, NW Fan Rooms, Boiler Closet - 1936 Bldg.**  
MATERIAL QUANTITY: **950** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **10** DAMAGE UNITS: **LF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/19/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Goudy School** REVIEW DATE: **10/14/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **10**  
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**  
MATERIAL LOCATION: **Air Tunnel, Boiler, Pump, & Fan Rooms, Unex. Areas, NW Fan Rooms, Boiler Closet - 1936 Bldg.**  
MATERIAL QUANTITY: **950** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **10** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair**

Comments:

Repair Damaged ACM ASAP

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Goudy School** INSPECTION DATE: **9/19/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11**  
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Boiler Room, Air Tunnel #4, & Unexcavated Areas - 1936 Bldg.**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/19/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Goudy School** REVIEW DATE: **10/14/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **11**  
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**  
MATERIAL LOCATION: **Boiler Room, Air Tunnel #4, & Unexcavated Areas - 1936 Bldg.**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Goudy School** INSPECTION DATE: **9/19/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**  
MATERIAL DESCRIPTION: **Mag Block Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Boiler Room, Pump Room, Air Tunnel - 1936 Bldg.**  
MATERIAL QUANTITY: **50** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/19/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Goudy School** REVIEW DATE: **10/14/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **20**  
MATERIAL DESCRIPTION: **Mag Block Pipe Insulation**  
MATERIAL LOCATION: **Boiler Room, Pump Room, Air Tunnel - 1936 Bldg.**  
MATERIAL QUANTITY: **50** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Goudy School** INSPECTION DATE: **9/19/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22**  
MATERIAL DESCRIPTION: **Aircell Duct Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Unexcavated Crawl Area - 1936 Bldg.**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/19/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Goudy School** REVIEW DATE: **10/14/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **22**  
MATERIAL DESCRIPTION: **Aircell Duct Insulation**  
MATERIAL LOCATION: **Unexcavated Crawl Area - 1936 Bldg.**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Goudy School** INSPECTION DATE: **9/19/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **24**  
MATERIAL DESCRIPTION: **Mudded Joint Packing on Aircell Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Air Tunnel, Boiler, Pump , & Fan Rooms, Unex. Areas, SE & NW Fan Rooms, Boiler Closet - 1936 Bldg.**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/19/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Goudy School** REVIEW DATE: **10/14/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **24**

MATERIAL DESCRIPTION: **Mudded Joint Packing on Aircell Pipe Insulation**

MATERIAL LOCATION: **Air Tunnel, Boiler, Pump , & Fan Rooms, Unex. Areas, SE & NW Fan Rooms, Boiler Closet - 1936 Bldg.**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Goudy School** INSPECTION DATE: **9/19/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25**  
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **1 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON: **Air Erosion/Flow**  
DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Basement - 1954 Bldg.**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **10** DAMAGE UNITS: **LF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/19/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Goudy School** REVIEW DATE: **10/14/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **25**  
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**  
MATERIAL LOCATION: **Basement - 1954 Bldg.**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **10** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Repair

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Goudy School** INSPECTION DATE: **9/19/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26**  
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Unexcavated Areas - 1954 Bldg.**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/19/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Goudy School** REVIEW DATE: **10/14/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **26**  
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**  
MATERIAL LOCATION: **Unexcavated Areas - 1954 Bldg.**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Goudy School** INSPECTION DATE: **9/19/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **31**  
MATERIAL DESCRIPTION: **Mudded Joint Packing on Aircell Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Corridor and unexcavated crawl space - 1954**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **EA**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/19/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Goudy School** REVIEW DATE: **10/14/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **31**  
MATERIAL DESCRIPTION: **Mudded Joint Packing on Aircell Pipe Insulation**  
MATERIAL LOCATION: **Corridor and unexcavated crawl space - 1954**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **EA**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Goudy School** INSPECTION DATE: **9/19/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **32**  
MATERIAL DESCRIPTION: **MJP E/F/V on Mag Block Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Boiler Room, Pump Room & Tunnel - 1936 Bldg.**  
MATERIAL QUANTITY: **50** MATERIAL UNITS: **EA**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/19/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Goudy School** REVIEW DATE: **10/14/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **32**  
MATERIAL DESCRIPTION: **MJP E/F/V on Mag Block Pipe Insulation**  
MATERIAL LOCATION: **Boiler Room, Pump Room & Tunnel - 1936 Bldg.**  
MATERIAL QUANTITY: **50** MATERIAL UNITS: **EA**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Goudy School** INSPECTION DATE: **9/19/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **33**  
MATERIAL DESCRIPTION: **Mag Block Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Unexcavated Areas - 1954 Bldg.**  
MATERIAL QUANTITY: **250** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/19/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Goudy School** REVIEW DATE: **10/14/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **33**  
MATERIAL DESCRIPTION: **Mag Block Pipe Insulation**  
MATERIAL LOCATION: **Unexcavated Areas - 1954 Bldg.**  
MATERIAL QUANTITY: **250** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Goudy School** INSPECTION DATE: **9/19/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **34**  
MATERIAL DESCRIPTION: **MJP E/F/V on Mag Block Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Unexcavated Areas - 1954 Bldg.**  
MATERIAL QUANTITY: **25** MATERIAL UNITS: **EA**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/19/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Goudy School** REVIEW DATE: **10/14/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **34**  
MATERIAL DESCRIPTION: **MJP E/F/V on Mag Block Pipe Insulation**  
MATERIAL LOCATION: **Unexcavated Areas - 1954 Bldg.**  
MATERIAL QUANTITY: **25** MATERIAL UNITS: **EA**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Goudy School** INSPECTION DATE: **9/19/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **35**  
MATERIAL DESCRIPTION: **MJP E/F/V on Cardboard Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Unexcavated Areas - 1954 Bldg.**  
MATERIAL QUANTITY: **20** MATERIAL UNITS: **EA**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/19/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Goudy School** REVIEW DATE: **10/14/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **35**  
MATERIAL DESCRIPTION: **MJP E/F/V on Cardboard Pipe Insulation**  
MATERIAL LOCATION: **Unexcavated Areas - 1954 Bldg.**  
MATERIAL QUANTITY: **20** MATERIAL UNITS: **EA**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Goudy School** INSPECTION DATE: **9/19/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **36**  
MATERIAL DESCRIPTION: **Terrazzo**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Stairwells - 1936 Bldg**  
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/19/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Goudy School** REVIEW DATE: **10/14/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **36**  
MATERIAL DESCRIPTION: **Terrazzo**  
MATERIAL LOCATION: **Stairwells - 1936 Bldg**  
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Goudy School** INSPECTION DATE: **9/19/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37**  
MATERIAL DESCRIPTION: **Carpet Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Library (321) - 2003 Addition**  
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/19/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Goudy School** REVIEW DATE: **10/14/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **37**  
MATERIAL DESCRIPTION: **Carpet Mastic**  
MATERIAL LOCATION: **Library (321) - 2003 Addition**  
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Goudy School** INSPECTION DATE: **9/19/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **38**  
MATERIAL DESCRIPTION: **Terrazzo**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Stairwells; 1st, 2nd, and 3rd floor corridors; boys, girls, and faculty toilets all floors - 2003 Addition**

MATERIAL QUANTITY: **5800**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/19/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUILDING ID: **3590**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Goudy School** REVIEW DATE: **10/14/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **38**  
MATERIAL DESCRIPTION: **Terrazzo**  
MATERIAL LOCATION: **Stairwells; 1st, 2nd, and 3rd floor corridors; boys, girls, and faculty toilets all floors - 2003 Addition**  
MATERIAL QUANTITY: **5800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: 10/14/2019



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Goudy School** INSPECTION DATE: **9/19/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **39**  
MATERIAL DESCRIPTION: **Drywall System**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st, 2nd, and 3rd floor boys and girls toilets; Rms 314, 316, 214 and 218 - 2003 Addition**  
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/19/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Goudy School** REVIEW DATE: **10/14/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **39**  
MATERIAL DESCRIPTION: **Drywall System**  
MATERIAL LOCATION: **1st, 2nd, and 3rd floor boys and girls toilets; Rms 314, 316, 214 and 218 - 2003 Addition**  
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Goudy School** INSPECTION DATE: **9/19/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **40**  
MATERIAL DESCRIPTION: **2' x 4' Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout 2003 Addition**  
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/19/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Goudy School** REVIEW DATE: **10/14/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **40**  
MATERIAL DESCRIPTION: **2' x 4' Ceiling Tile**  
MATERIAL LOCATION: **Throughout 2003 Addition**  
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Goudy School** INSPECTION DATE: **9/19/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **41**  
MATERIAL DESCRIPTION: **12" X 12" Off-white with tan streaks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 314, 316, 214, 216, 218, 225, 116, 114, and 125 - 2003 Addition**  
MATERIAL QUANTITY: **3600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/19/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Goudy School** REVIEW DATE: **10/14/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **41**  
MATERIAL DESCRIPTION: **12" X 12" Off-white with tan streaks VFT**  
MATERIAL LOCATION: **Rooms 314, 316, 214, 216, 218, 225, 116, 114, and 125 - 2003 Addition**  
MATERIAL QUANTITY: **3600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Goudy School** INSPECTION DATE: **9/19/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **41A**  
MATERIAL DESCRIPTION: **12" X 12" Off-white with tan streaks VFT mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 314, 316, 214, 216, 218, 225, 116, 114, and 125 - 2003 Addition**  
MATERIAL QUANTITY: **3600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/19/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Goudy School** REVIEW DATE: **10/14/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **41A**  
MATERIAL DESCRIPTION: **12" X 12" Off-white with tan streaks VFT mastic**  
MATERIAL LOCATION: **Rooms 314, 316, 214, 216, 218, 225, 116, 114, and 125 - 2003 Addition**  
MATERIAL QUANTITY: **3600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Goudy School** INSPECTION DATE: **9/19/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **42**  
MATERIAL DESCRIPTION: **12" X 12" Beige with white-and-tan streaks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 323, 314, 316, 214, 216, 218, 225, 223, 116, 114, and 125 - 2003 Addition**  
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/19/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Goudy School** REVIEW DATE: **10/14/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **42**  
MATERIAL DESCRIPTION: **12" X 12" Beige with white-and-tan streaks VFT**  
MATERIAL LOCATION: **Rooms 323, 314, 316, 214, 216, 218, 225, 223, 116, 114, and 125 - 2003 Addition**  
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Goudy School** INSPECTION DATE: **9/19/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **42A**  
MATERIAL DESCRIPTION: **12" X 12" Beige with white-and-tan streaks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 323, 314, 316, 214, 216, 218, 225, 223, 116, 114, and 125 - 2003 Addition**  
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/19/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Goudy School** REVIEW DATE: **10/14/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **42A**  
MATERIAL DESCRIPTION: **12" X 12" Beige with white-and-tan streaks VFT Mastic**  
MATERIAL LOCATION: **Rooms 323, 314, 316, 214, 216, 218, 225, 223, 116, 114, and 125 - 2003 Addition**  
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Goudy School** INSPECTION DATE: **9/19/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **43**  
MATERIAL DESCRIPTION: **12" x 12" Blue/green- streaked VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 318, 314, 316, Storage 315, 214, 216, 218, 225, 116, 114, 125, 121F, 121E (Women), 121D (Men), and 121B**

MATERIAL QUANTITY: **2000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 09/19/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Goudy School** REVIEW DATE: **10/14/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **43**  
MATERIAL DESCRIPTION: **12" x 12" Blue/green- streaked VFT**  
MATERIAL LOCATION: **Rooms 318, 314, 316, Storage 315, 214, 216, 218, 225, 116, 114, 125, 121F, 121E (Women), 121D (Men), and 121B**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Goudy School** INSPECTION DATE: **9/19/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **43A**  
MATERIAL DESCRIPTION: **12" X 12" Blue/green-streaked VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 318, 314, 316, Storage 315, 214, 216, 218, 225, 116, 114, 125, 121F, 121E (Women), 121D (Men), and 121B**

MATERIAL QUANTITY: **2000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 09/19/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUILDING ID: **3590**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Goudy School** REVIEW DATE: **10/14/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **43A**  
MATERIAL DESCRIPTION: **12" X 12" Blue/green-streaked VFT Mastic**  
MATERIAL LOCATION: **Rooms 318, 314, 316, Storage 315, 214, 216, 218, 225, 116, 114, 125, 121F, 121E (Women), 121D (Men), and 121B**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: 10/14/2019



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Goudy School** INSPECTION DATE: **9/19/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **44**  
MATERIAL DESCRIPTION: **12" X 12" Yellow streaked VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Multipurpose - 2003 Addition**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/19/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Goudy School** REVIEW DATE: **10/14/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **44**  
MATERIAL DESCRIPTION: **12" X 12" Yellow streaked VFT**  
MATERIAL LOCATION: **Multipurpose - 2003 Addition**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Goudy School** INSPECTION DATE: **9/19/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **44A**  
MATERIAL DESCRIPTION: **12" X 12" Yellow streaked VFT mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Multipurpose - 2003 Addition**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/19/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Goudy School** REVIEW DATE: **10/14/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **44A**  
MATERIAL DESCRIPTION: **12" X 12" Yellow streaked VFT mastic**  
MATERIAL LOCATION: **Multipurpose - 2003 Addition**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Goudy School** INSPECTION DATE: **9/19/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **45**  
MATERIAL DESCRIPTION: **12" x 12" White with blue-and-black specks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Multipurpose, Serving Room 217A, Elevator**  
MATERIAL QUANTITY: **5800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/19/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Goudy School** REVIEW DATE: **10/14/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **45**  
MATERIAL DESCRIPTION: **12" x 12" White with blue-and-black specks VFT**  
MATERIAL LOCATION: **Multipurpose, Serving Room 217A, Elevator**  
MATERIAL QUANTITY: **5800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Goudy School** INSPECTION DATE: **9/19/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **45A**  
MATERIAL DESCRIPTION: **12" x 12" White with blue-and-black specks VFT mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Multipurpose, Serving Room 217A, Elevator**  
MATERIAL QUANTITY: **5800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/19/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Goudy School** REVIEW DATE: **10/14/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **45A**  
MATERIAL DESCRIPTION: **12" x 12" White with blue-and-black specks VFT mastic**  
MATERIAL LOCATION: **Multipurpose, Serving Room 217A, Elevator**  
MATERIAL QUANTITY: **5800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Goudy School** INSPECTION DATE: **9/19/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **46**  
MATERIAL DESCRIPTION: **2' X 4' Smooth ceiling tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Kitchen, Serving Room, Women's Toilet 121 E, Men's Toilet 121 D, Dishwasher Room 127**

MATERIAL QUANTITY: **2600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/19/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Goudy School** REVIEW DATE: **10/14/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **46**

MATERIAL DESCRIPTION: **2' X 4' Smooth ceiling tile**

MATERIAL LOCATION: **Kitchen, Serving Room, Women's Toilet 121 E, Men's Toilet 121 D, Dishwasher Room 127**

MATERIAL QUANTITY: **2600**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Goudy School** INSPECTION DATE: **9/19/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **47**  
MATERIAL DESCRIPTION: **Spray-on fire proofing**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout 2003 Addition**  
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/19/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Goudy School** REVIEW DATE: **10/14/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **47**  
MATERIAL DESCRIPTION: **Spray-on fire proofing**  
MATERIAL LOCATION: **Throughout 2003 Addition**  
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Goudy School** INSPECTION DATE: **9/19/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **48**  
MATERIAL DESCRIPTION: **9" X 9" Tan VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 110 Storage Closet & Wardrobe - 1936 Bldg**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/19/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Goudy School** REVIEW DATE: **10/14/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **48**  
MATERIAL DESCRIPTION: **9" X 9" Tan VFT**  
MATERIAL LOCATION: **Room 110 Storage Closet & Wardrobe - 1936 Bldg**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Goudy School** INSPECTION DATE: **9/19/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **48A**  
MATERIAL DESCRIPTION: **9" X 9" Tan VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 110 Storage Closet & Wardrobe - 1936 Bldg**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/19/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Goudy School** REVIEW DATE: **10/14/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **48A**  
MATERIAL DESCRIPTION: **9" X 9" Tan VFT Mastic**  
MATERIAL LOCATION: **Room 110 Storage Closet & Wardrobe - 1936 Bldg**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Goudy School** INSPECTION DATE: **9/19/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **49**  
MATERIAL DESCRIPTION: **1' X 1' Ceiling tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Assembly Hall - 1936 bldg**  
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/19/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Goudy School** REVIEW DATE: **10/14/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **49**  
MATERIAL DESCRIPTION: **1' X 1' Ceiling tile**  
MATERIAL LOCATION: **Assembly Hall - 1936 bldg**  
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Goudy School** INSPECTION DATE: **9/19/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **49A**  
MATERIAL DESCRIPTION: **1' X 1' Ceiling tile mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Assembly Hall - 1936 bldg**  
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/19/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Goudy School** REVIEW DATE: **10/14/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **49A**  
MATERIAL DESCRIPTION: **1' X 1' Ceiling tile mastic**  
MATERIAL LOCATION: **Assembly Hall - 1936 bldg**  
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Goudy School** INSPECTION DATE: **9/19/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **50**  
MATERIAL DESCRIPTION: **Decorative plaster**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Assembly Hall - 1936 Bldg**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/19/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Goudy School** REVIEW DATE: **10/14/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **50**  
MATERIAL DESCRIPTION: **Decorative plaster**  
MATERIAL LOCATION: **Assembly Hall - 1936 Bldg**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Goudy School** INSPECTION DATE: **9/19/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **51**  
MATERIAL DESCRIPTION: **Tectum wall panels**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Gym - 1936 Bldg**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/19/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Goudy School** REVIEW DATE: **10/14/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **51**  
MATERIAL DESCRIPTION: **Tectum wall panels**  
MATERIAL LOCATION: **Gym - 1936 Bldg**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Goudy School** INSPECTION DATE: **9/19/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **52**  
MATERIAL DESCRIPTION: **Carpet Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 212 - 1954 Addition**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/19/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Goudy School** REVIEW DATE: **10/14/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **52**  
MATERIAL DESCRIPTION: **Carpet Mastic**  
MATERIAL LOCATION: **Room 212 - 1954 Addition**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Goudy School** INSPECTION DATE: **9/19/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **A**  
MATERIAL DESCRIPTION: **12"x12" White w/ Tan Vinyl Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 112, 113, 213 - 1954 Addition**  
MATERIAL QUANTITY: **2295** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/19/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Goudy School** REVIEW DATE: **10/14/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **A**  
MATERIAL DESCRIPTION: **12"x12" White w/ Tan Vinyl Floor Tile**  
MATERIAL LOCATION: **Rooms 112, 113, 213 - 1954 Addition**  
MATERIAL QUANTITY: **2295** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Goudy School** INSPECTION DATE: **9/19/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **B**  
MATERIAL DESCRIPTION: **9"x9" Brown Vinyl Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 110 Storage Closet and Wardrobe - 1936 Bldg**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/19/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Goudy School** REVIEW DATE: **10/14/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **B**  
MATERIAL DESCRIPTION: **9"x9" Brown Vinyl Floor Tile**  
MATERIAL LOCATION: **Room 110 Storage Closet and Wardrobe - 1936 Bldg**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Goudy School** INSPECTION DATE: **9/19/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **C**  
MATERIAL DESCRIPTION: **Tan Linoleum - REMOVED**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7**. **Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 111 (Kitchen) - 1936 Bldg**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/19/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Goudy School** REVIEW DATE: **10/14/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **C**

MATERIAL DESCRIPTION: **Tan Linoleum - REMOVED**

MATERIAL LOCATION: **Room 111 (Kitchen) - 1936 Bldg**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: 10/14/2019



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Goudy School** INSPECTION DATE: **9/19/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **D**  
MATERIAL DESCRIPTION: **12"x12" White w/ Tan Vinyl Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 112, 113, 213 - 1954 Addition**  
MATERIAL QUANTITY: **2295** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/19/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Goudy School** REVIEW DATE: **10/14/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **D**  
MATERIAL DESCRIPTION: **12"x12" White w/ Tan Vinyl Floor Tile Mastic**  
MATERIAL LOCATION: **Rooms 112, 113, 213 - 1954 Addition**  
MATERIAL QUANTITY: **2295** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Goudy School** INSPECTION DATE: **9/19/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **E**  
MATERIAL DESCRIPTION: **12"x12" Tan Vinyl Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st, 2nd, & 3rd Floor Corridors and Main Office - 1936 Bldg.**  
MATERIAL QUANTITY: **5950** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/19/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Goudy School** REVIEW DATE: **10/14/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **E**  
MATERIAL DESCRIPTION: **12"x12" Tan Vinyl Floor Tile Mastic**  
MATERIAL LOCATION: **1st, 2nd, & 3rd Floor Corridors and Main Office - 1936 Bldg.**  
MATERIAL QUANTITY: **5950** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Goudy School** INSPECTION DATE: **9/19/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **F**  
MATERIAL DESCRIPTION: **9"x9" Brown Vinyl Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 110 Storage Closet and Wardrobe - 1936 Bldg**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/19/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Goudy School** REVIEW DATE: **10/14/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **F**  
MATERIAL DESCRIPTION: **9"x9" Brown Vinyl Floor Tile Mastic**  
MATERIAL LOCATION: **Room 110 Storage Closet and Wardrobe - 1936 Bldg**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Goudy School** INSPECTION DATE: **9/19/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **G**  
MATERIAL DESCRIPTION: **Tan Linoleum Mastic - REMOVED**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 111 - 1936 Bldg.**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/19/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Goudy School** REVIEW DATE: **10/14/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **G**

MATERIAL DESCRIPTION: **Tan Linoleum Mastic - REMOVED**

MATERIAL LOCATION: **Room 111 - 1936 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Goudy School** INSPECTION DATE: **9/19/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **H**  
MATERIAL DESCRIPTION: **12"x12" Tan Vinyl Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st, 2nd, & 3rd Floor Corridors and Main Office - 1936 Bldg.**  
MATERIAL QUANTITY: **5950** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/19/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Goudy School** REVIEW DATE: **10/14/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **H**  
MATERIAL DESCRIPTION: **12"x12" Tan Vinyl Floor Tile**  
MATERIAL LOCATION: **1st, 2nd, & 3rd Floor Corridors and Main Office - 1936 Bldg.**  
MATERIAL QUANTITY: **5950** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Goudy School** INSPECTION DATE: **9/19/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **I**  
MATERIAL DESCRIPTION: **Green Linoleum**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Assembly Hall - 1936 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: **09/19/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Goudy School** REVIEW DATE: **10/14/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **I**

MATERIAL DESCRIPTION: **Green Linoleum**

MATERIAL LOCATION: **Assembly Hall - 1936 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Goudy School** INSPECTION DATE: **9/19/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **J**  
MATERIAL DESCRIPTION: **Green Linoleum Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Assembly Hall - 1936 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/19/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Goudy School** REVIEW DATE: **10/14/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **J**

MATERIAL DESCRIPTION: **Green Linoleum Mastic**

MATERIAL LOCATION: **Assembly Hall - 1936 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Goudy School** INSPECTION DATE: **9/19/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **M**  
MATERIAL DESCRIPTION: **9"x9" Red Vinyl Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Engineer's Office, Basement Janitors Closet(Boiler Room Closet) - 1936 Bldg.**  
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/19/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Goudy School** REVIEW DATE: **10/14/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **M**  
MATERIAL DESCRIPTION: **9"x9" Red Vinyl Floor Tile**  
MATERIAL LOCATION: **Engineer's Office, Basement Janitors Closet(Boiler Room Closet) - 1936 Bldg.**  
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Goudy School** INSPECTION DATE: **9/19/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **N**  
MATERIAL DESCRIPTION: **9"x9" Red Vinyl Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Engineer's Office, Basement Janitors Closet(Boiler Room Closet) - 1936 Bldg.**  
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/19/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Goudy School** REVIEW DATE: **10/14/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **N**  
MATERIAL DESCRIPTION: **9"x9" Red Vinyl Floor Tile Mastic**  
MATERIAL LOCATION: **Engineer's Office, Basement Janitors Closet(Boiler Room Closet) - 1936 Bldg.**  
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Goudy School** INSPECTION DATE: **9/19/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **0**  
MATERIAL DESCRIPTION: **Brown Linoleum**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st Floor Storage (closet next to Auditorium) - 1936 Bldg.**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/19/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Goudy School** REVIEW DATE: **10/14/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **O**  
MATERIAL DESCRIPTION: **Brown Linoleum**  
MATERIAL LOCATION: **1st Floor Storage (closet next to Auditorium) - 1936 Bldg.**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Goudy School** INSPECTION DATE: **9/19/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **P**  
MATERIAL DESCRIPTION: **Brown Linoleum Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st Floor Storage (closet next to Auditorium) - 1936 Bldg.**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/19/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Goudy School** REVIEW DATE: **10/14/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **P**

MATERIAL DESCRIPTION: **Brown Linoleum Mastic**

MATERIAL LOCATION: **1st Floor Storage (closet next to Auditorium) - 1936 Bldg.**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Goudy School** INSPECTION DATE: **9/19/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **Q**  
MATERIAL DESCRIPTION: **9"x9" Grey w/ White & Pink Streaks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Office Supply Store Room - 1936 Bldg.**

MATERIAL QUANTITY: **250**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 09/19/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Goudy School** REVIEW DATE: **10/14/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **Q**  
MATERIAL DESCRIPTION: **9"x9" Grey w/ White & Pink Streaks VFT**  
MATERIAL LOCATION: **Office Supply Store Room - 1936 Bldg.**  
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Goudy School** INSPECTION DATE: **9/19/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **R**  
MATERIAL DESCRIPTION: **9"x9" Grey w/ White & Pink Streaks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Office Supply Store Room - 1936 Bldg.**  
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/19/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Goudy School** REVIEW DATE: **10/14/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **R**  
MATERIAL DESCRIPTION: **9"x9" Grey w/ White & Pink Streaks VFT Mastic**  
MATERIAL LOCATION: **Office Supply Store Room - 1936 Bldg.**  
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Goudy School** INSPECTION DATE: **9/19/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **S**  
MATERIAL DESCRIPTION: **9"x9" Pink Vinyl Floor Tile ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st Floor Vault - 1954 (New Connection Corridor to 2003-2004 Annex)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/19/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Goudy School** REVIEW DATE: **10/14/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **S**  
MATERIAL DESCRIPTION: **9"x9" Pink Vinyl Floor Tile ABATED**  
MATERIAL LOCATION: **1st Floor Vault - 1954 (New Connection Corridor to 2003-2004 Annex)**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Goudy School** INSPECTION DATE: **9/19/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **T**  
MATERIAL DESCRIPTION: **9"x9" Pink Vinyl Floor Tile Mastic - ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st Floor Vault - 1954 (New Connection Corridor to 2003-2004 Annex)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/19/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Goudy School** REVIEW DATE: **10/14/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **T**  
MATERIAL DESCRIPTION: **9"x9" Pink Vinyl Floor Tile Mastic - ABATED**  
MATERIAL LOCATION: **1st Floor Vault - 1954 (New Connection Corridor to 2003-2004 Annex)**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Goudy School** INSPECTION DATE: **9/19/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **U**  
MATERIAL DESCRIPTION: **12"x12" White Textured Vinyl Floor Tile NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st Floor Vault - 1954 Addition NOT OBSERVED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/19/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Goudy School** REVIEW DATE: **10/14/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **U**  
MATERIAL DESCRIPTION: **12"x12" White Textured Vinyl Floor Tile NOT OBSERVED**  
MATERIAL LOCATION: **1st Floor Vault - 1954 Addition NOT OBSERVED**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **23371**    BUILDING ID: **3590**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Goudy School**    INSPECTION DATE: **9/19/2019**  
ADDRESS: **5120 N Winthrop Avenue**    IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **V**  
MATERIAL DESCRIPTION: **12"x12" White Textured Vinyl Floor Tile Mastic NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Abated**    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st Floor Vault - 1954 Addition NOT OBSERVED**

MATERIAL QUANTITY:    MATERIAL UNITS:

DAMAGE QUANTITY:    DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/19/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Goudy School** REVIEW DATE: **10/14/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **V**  
MATERIAL DESCRIPTION: **12"x12" White Textured Vinyl Floor Tile Mastic NOT OBSERVED**  
MATERIAL LOCATION: **1st Floor Vault - 1954 Addition NOT OBSERVED**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Goudy School** INSPECTION DATE: **9/19/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **W**  
MATERIAL DESCRIPTION: **12"x12" Tan VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **2nd, & 3rd Floor Corridors & Room 13; Room 212; 312, 313 - 1954 Addition**  
MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/19/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Goudy School** REVIEW DATE: **10/14/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **W**  
MATERIAL DESCRIPTION: **12"x12" Tan VFT**  
MATERIAL LOCATION: **2nd, & 3rd Floor Corridors & Room 13; Room 212; 312, 313 - 1954 Addition**  
MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Goudy School** INSPECTION DATE: **9/19/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **X**  
MATERIAL DESCRIPTION: **12"x12" Tan VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **2nd, & 3rd Floor Corridors & Rooms 212 & 213, 312, 313 - 1954 Addition**  
MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/19/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Goudy School** REVIEW DATE: **10/14/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **X**  
MATERIAL DESCRIPTION: **12"x12" Tan VFT Mastic**  
MATERIAL LOCATION: **2nd, & 3rd Floor Corridors & Rooms 212 & 213, 312, 313 - 1954 Addition**  
MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Goudy School** INSPECTION DATE: **9/19/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **Y**  
MATERIAL DESCRIPTION: **12" x 12" White w/beige streaks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st, 2nd, 3rd Floor former vaulted area (corridors) - 1954 addition**  
MATERIAL QUANTITY: **575** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/19/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Goudy School** REVIEW DATE: **10/14/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **Y**  
MATERIAL DESCRIPTION: **12" x 12" White w/beige streaks VFT**  
MATERIAL LOCATION: **1st, 2nd, 3rd Floor former vaulted area (corridors) - 1954 addition**  
MATERIAL QUANTITY: **575** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Goudy School** INSPECTION DATE: **9/19/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **Y1**  
MATERIAL DESCRIPTION: **12" x 12" White w/beige streaks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st, 2nd, 3rd Floor former vaulted area (corridors) - 1954 addition**  
MATERIAL QUANTITY: **575** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/19/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Goudy School** REVIEW DATE: **10/14/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **Y1**  
MATERIAL DESCRIPTION: **12" x 12" White w/beige streaks VFT Mastic**  
MATERIAL LOCATION: **1st, 2nd, 3rd Floor former vaulted area (corridors) - 1954 addition**  
MATERIAL QUANTITY: **575** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **23371**    BUILDING ID: **3590**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Goudy School**    INSPECTION DATE: **9/19/2019**  
ADDRESS: **5120 N Winthrop Avenue**    IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **Z**  
MATERIAL DESCRIPTION: **Carpet Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Main Office**  
MATERIAL QUANTITY: **200**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/19/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Goudy School** REVIEW DATE: **10/14/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **Z**  
MATERIAL DESCRIPTION: **Carpet Mastic**  
MATERIAL LOCATION: **Main Office**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Goudy School** INSPECTION DATE: **9/19/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **Z1**  
MATERIAL DESCRIPTION: **2' x 4' Ceiling Tiles**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout 1936 Building**  
MATERIAL QUANTITY: **40000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/19/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Goudy School** REVIEW DATE: **10/14/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **Z1**  
MATERIAL DESCRIPTION: **2' x 4' Ceiling Tiles**  
MATERIAL LOCATION: **Throughout 1936 Building**  
MATERIAL QUANTITY: **40000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Goudy School** INSPECTION DATE: **9/19/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **Z2**  
MATERIAL DESCRIPTION: **2' x 4' Ceiling Tiles**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st, 2nd, 3rd Floor Corridors; Rooms 313, 312, 213, 212, 113, and 112 - 1954 Addition**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/19/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUIDLING ID: **3590**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Goudy School** REVIEW DATE: **10/14/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **Z2**  
MATERIAL DESCRIPTION: **2' x 4' Ceiling Tiles**  
MATERIAL LOCATION: **1st, 2nd, 3rd Floor Corridors; Rooms 313, 312, 213, 212, 113, and 112 - 1954 Addition**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.

*2019 AHERA REINSPECTION*

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **23371**    BUILDING ID: **3590**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Goudy School**    INSPECTION DATE: **9/19/2019**  
ADDRESS: **5120 N Winthrop Avenue**    IDPH LICENSE NO: **100-18350**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **53**  
MATERIAL DESCRIPTION: **Cloth Wire Insulation**  
MATERIAL LOCATION: **2nd Floor Women's Restroom - 1936 Bldg.**  
MATERIAL QUANTITY: **1**    MATERIAL UNITS: **LF**  
MATERIAL CATEGORY: **MISC**    FRIABLE:  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**    CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**    DAMAGE REASON:  
DAMAGE QUANTITY: **0**    DAMAGE REASON:  
DAMAGE UNITS: **LF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/19/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **23371**      BUILDING ID: **3590**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Goudy School**      REVIEW DATE: **10/14/2019**  
ADDRESS: **5120 N Winthrop Avenue**      IDPH LICENSE NO: **100-18350**

HOMOGENEOUS AREA: **53**

MATERIAL DESCRIPTION: **Cloth Wire Insulation**

MATERIAL LOCATION: **2nd Floor Women's Restroom - 1936 Bldg.**

MATERIAL QUANTITY: **1**      MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**      DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **23371**    BUILDING ID: **3590**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Goudy School**    INSPECTION DATE: **9/19/2019**  
ADDRESS: **5120 N Winthrop Avenue**    IDPH LICENSE NO: **100-18350**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **54**  
MATERIAL DESCRIPTION: **Sink Undercoating**  
MATERIAL LOCATION: **Room 111 - 1936 Bldg.**  
MATERIAL QUANTITY: **5**    MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**    FRIABLE:  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL:    CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**    DAMAGE REASON:  
DAMAGE QUANTITY: **0**    DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/19/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **23371**      BUILDING ID: **3590**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Goudy School**      REVIEW DATE: **10/14/2019**  
ADDRESS: **5120 N Winthrop Avenue**      IDPH LICENSE NO: **100-18350**

HOMOGENEOUS AREA: **54**  
MATERIAL DESCRIPTION: **Sink Undercoating**  
MATERIAL LOCATION: **Room 111 - 1936 Bldg.**  
MATERIAL QUANTITY: **5**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **23371**    BUILDING ID: **3590**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Goudy School**    INSPECTION DATE: **9/19/2019**  
ADDRESS: **5120 N Winthrop Avenue**    IDPH LICENSE NO: **100-18350**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **55**  
MATERIAL DESCRIPTION: **Sink Undercoating**  
MATERIAL LOCATION: **Rooms 114, 125, 223, 316, 321B - 2003 Annex**  
MATERIAL QUANTITY: **45**    MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**    FRIABLE:  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**    CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**    DAMAGE REASON:  
DAMAGE QUANTITY: **0**    DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/19/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23371** BUILDING ID: **3590**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Goudy School** REVIEW DATE: **10/14/2019**  
ADDRESS: **5120 N Winthrop Avenue** IDPH LICENSE NO: **100-18350**

HOMOGENEOUS AREA: **55**  
MATERIAL DESCRIPTION: **Sink Undercoating**  
MATERIAL LOCATION: **Rooms 114, 125, 223, 316, 321B - 2003 Annex**  
MATERIAL QUANTITY: **45** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# APPENDIX B

## Inspector and Management Planner Licenses

---





525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • www.idph.illinois.gov

4/18/2016

**JOSEPH L HENNIGAN**  
855 W ADAMS, SUITE 200  
CHICAGO, IL 60607



ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 18350

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

**COPY OF THE ASBESTOS PROFESSIONAL LICENSE**

Front of License

Back of License

ASBESTOS PROFESSIONAL LICENSE			ENDORSEMENTS	TC EXPIRES
			INSPECTOR	2/13/2017
ID NUMBER	ISSUED	EXPIRES	PROJECT MANAGER	2/6/2017
100 - 10350	4/18/2016	05/15/2017	AIR SAMPLING PROFESSIONAL	
JOSEPH L HENNIGAN			<b>Alteration of this license shall result in legal action</b>	
855 W ADAMS, SUITE 200 CHICAGO, IL 60607			This license issued under authority of the State of Illinois Department of Public Health	
Environmental Health			This license is valid only when accompanied by a valid training course certificate.	

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: [dph.illinois.gov/topics-services/environmental-health-protection/asbestos](http://dph.illinois.gov/topics-services/environmental-health-protection/asbestos)  
EMAIL Address: [dph.asbestos@illinois.gov](mailto:dph.asbestos@illinois.gov)

**PROTECTING HEALTH, IMPROVING LIVES**  
*Nationally Accredited by PHAB*



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • [www.dph.illinois.gov](http://www.dph.illinois.gov)

**JOSEPH L HENNIGAN**  
2942 W VAN BUREN ST  
CHICAGO, IL 60612

5/9/2018

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 18350

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

**COPY OF THE ASBESTOS PROFESSIONAL LICENSE**

Front of License

Back of License

FRONT OF LICENSE			BACK OF LICENSE	
	<b>ASBESTOS PROFESSIONAL LICENSE</b>		<b>ENDORSEMENTS</b>	<b>TC EXPIRES</b>
<b>ID NUMBER</b> 100 - 18350	<b>ISSUED</b> 5/9/2018	<b>EXPIRES</b> 05/15/2019	INSPECTOR	2/10/2019
<b>JOSEPH L HENNIGAN</b> 2942 W VAN BUREN ST CHICAGO, IL 60612 Environmental Health			PROJECT MANAGER AIR SAMPLING PROFESSIONAL	2/3/2019
			<b>Alteration of this license shall result in legal action</b> This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: [dph.illinois.gov/topics-services/environmental-health-protection/asbestos](http://dph.illinois.gov/topics-services/environmental-health-protection/asbestos)  
EMAIL Address: [dph.asbestos@illinois.gov](mailto:dph.asbestos@illinois.gov)

**PROTECTING HEALTH, IMPROVING LIVES**  
*Nationally Accredited by PHAB*

# CERTIFICATE OF ACHIEVEMENT ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that JOSEPH L. HENNIGAN  
has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the  
examination on 02/09/2019 with a minimum score of 70% or better. Training was in accordance  
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:  
Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.



02/09/2019

Course Dates:

02/09/2020

Expires:

1902BIR15

Certificate Number:

*Nicholas J. Peneff*

Director of Training  
Nicholas J. Peneff  
Doctor of Public Health

Phone: 312-491-0081

FORM # A-010B

# CERTIFICATE OF ACHIEVEMENT ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that JOSEPH L. HENNIGAN  
has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the  
examination on 02/13/2016 with a minimum score of 70% or better. Training was in accordance  
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:  
Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.

02/13/2016

Course Dates:

02/13/2017

Expires:

1602BIR15

Certificate Number:



*N. Penoff*

Director of Training  
Nicholas J. Penoff  
Doctor of Public Health

Phone: 312-491-0081

FORM # A-010B



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • [www.dph.illinois.gov](http://www.dph.illinois.gov)

**JOSEPH L HENNIGAN**  
2942 W VAN BUREN ST  
CHICAGO, IL 60612

4/19/2019



ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 18350

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

**COPY OF THE ASBESTOS PROFESSIONAL LICENSE**

Front of License

Back of License

FRONT OF LICENSE			BACK OF LICENSE	
	<b>ASBESTOS PROFESSIONAL LICENSE</b>		<b>ENDORSEMENTS</b>	<b>TC EXPIRES</b>
ID NUMBER 100 - 18350	ISSUED 4/19/2019	EXPIRES 05/15/2020	INSPECTOR	2/9/2020
<b>JOSEPH L HENNIGAN</b> 2942 W VAN BUREN ST CHICAGO, IL 60612 Environmental Health			PROJECT MANAGER AIR SAMPLING PROFESSIONAL	2/2/2020
			<b>Alteration of this license shall result in legal action</b> This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: [dph.illinois.gov/topics-services/environmental-health-protection/asbestos](http://dph.illinois.gov/topics-services/environmental-health-protection/asbestos)  
EMAIL Address: [dph.asbestos@illinois.gov](mailto:dph.asbestos@illinois.gov)

**PROTECTING HEALTH, IMPROVING LIVES**  
*Nationally Accredited by PHAB*



# CERTIFICATE OF ACHIEVEMENT ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that JOSEPH L. HENNIGAN  
has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the  
examination on 02/09/2019 with a minimum score of 70% or better. Training was in accordance  
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:  
Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.



02/09/2019

Course Dates:

02/09/2020

Expires:

1902BIR15

Certificate Number:

Director of Training  
Nicholas J. Peneff  
Doctor of Public Health

Phone: 312-491-0081

FORM # A-010B

2019



**OCCUPATIONAL TRAINING & SUPPLY, INC.**

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900 ♦ [www.otssafety.com](http://www.otssafety.com)

# Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

**Jigar Shah**

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 2/28/2019

Exam Date: 2/28/2019

Expiration Date: 2/28/2020

Certificate Number: MPR1902280695

  
Kathy DeSalvo, Director



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • [www.dph.illinois.gov](http://www.dph.illinois.gov)

**JIGAR M SHAH**  
2942 W VAN BUREN ST  
CHICAGO, IL 60612

4/19/2019



ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 07342

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

**COPY OF THE ASBESTOS PROFESSIONAL LICENSE**

Front of License

Back of License

		<b>ASBESTOS PROFESSIONAL LICENSE</b>		<b>ENDORSEMENTS</b>	<b>TC EXPIRES</b>
<b>ID NUMBER</b> 100 - 07342	<b>ISSUED</b> 4/19/2019	<b>EXPIRES</b> 05/15/2020		INSPECTOR PROJECT DESIGNER MANAGEMENT PLANNER PROJECT MANAGER AIR SAMPLING PROFESSIONAL	2/28/2020 3/15/2020 2/28/2020 2/22/2020
<b>JIGAR M SHAH</b> 2942 W VAN BUREN ST CHICAGO, IL 60612 Environmental Health		<b>Alteration of this license shall result in legal action</b> This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.			

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: [dph.illinois.gov/topics-services/environmental-health-protection/asbestos](http://dph.illinois.gov/topics-services/environmental-health-protection/asbestos)  
EMAIL Address: [dph.asbestos@illinois.gov](mailto:dph.asbestos@illinois.gov)

**PROTECTING HEALTH, IMPROVING LIVES**  
*Nationally Accredited by PHAB*



# APPENDIX C

## Laboratory Accreditations

---

# APPENDIX D

## Laboratory Results

---

# APPENDIX E

## Chain of Custody Forms

---

## Three-Year Reinspection Key to Terms

	<b>CODE</b>	<b>KEY</b>
<b>MATERIAL</b>		
	ACBM	Asbestos Containing Building Materials
<b>MATERIAL CATEGORY</b>		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
<b>MATERIAL UNITS</b>		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
<b>DAMAGE TYPE</b>		
	Loc	Localized
	Dist	Distributed