

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH  
AHERA THREE YEAR REINSPECTION  
ASBESTOS ABATEMENT PROGRAM  
SCHOOL INFORMATION FORM**

**SECTION I**

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299  
SCHOOL ID NUMBER: 14-016-2990-2246  
SCHOOL NAME: Harvard School  
ADDRESS OF SCHOOL: 7525 S. Harvard  
CITY: Chicago, IL, 60620

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **3/22/2016**

**If the address on this form is different than the address of the building, submit a written explanation.**

---

**SECTION II** *(Please type or print)*

**PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:**

DATE REINSPECTION COMPLETED: 10/1/2019 ENROLLMENT 381  
IDPH INSPECTOR LICENSE NUMBER: 100-07839  
IDPH LICENSED INSPECTOR NAME(Please Print): Lisa Laney  
IDPH MP LICENSE NUMBER: 100-00440  
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Shawn Brown

DESIGNATED PERSON (Please Print): Robert Christlieb PHONE: (773) 553-3197



10/1/2019

*Signature of Designated Person*

*Date*

**SECTION III**

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: \_\_\_\_\_

School has been closed. Date closed: \_\_\_\_\_

School building has been demolished. Date: \_\_\_\_\_

School building is asbestos free since last reinspection: \_\_\_\_\_

**Please explain in writing why the school building is now asbestos free and include the supporting documentation.**

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

**Explain in writing if the address of the building is different than the address on this form:**

---

---

---

**THREE-YEAR REINSPECTION**

**CHICAGO SCHOOL DIST 299**

**Harvard School**

7525 S. Harvard  
Chicago, IL, 60620

Unit: 23581  
Building ID: 3800

IDPH ID Number: 14-016-2990-2246

**REPORT DATE:**

Tuesday, October 01, 2019

**Prepared for:**

**Chicago Public Schools  
42 West Madison Street  
Chicago, IL 60602**

**Prepared by:**

**TEM Environmental, Inc.**

174 N. Brandon Drive

Glendale Heights, IL, 60139

Phone 630-790-0880

Fax 630-790-0882

**DO NOT REMOVE FROM SCHOOL  
REQUIRED BY FEDERAL LAW**

August 29, 2019

Mr. Glen E. Garner  
Asbestos Program  
Illinois Department of Public Health  
525 West Jefferson Street  
Springfield, Illinois 62761

Re: Chicago Public Schools - 2019 Three-Year Reinspections

Dear Mr. Glen:

TEM Environmental, Inc. , Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 5, 6 Elementary Schools. Please update your records with the following information.

School District: 299          Unit: 23581          Region: 05          IDPH ID:14-016-2990-2246

School: Harvard School          Building ID: 3800

Address: 7525 S. Harvard  
Chicago, IL, 60620

Building Contact:

Contact Phone:

Current Building Owners: Chicago Public Schools

Review Date: 09/28/2019

Inspector: Lisa Laney

Inspector IDPH License: 100-07839

Management Planner: Shawn Brown

Management Planner IDPH License: 100-00440

If you have any questions or comments, please contact us at 630-790-0880

Sincerely,  
TEM Environmental, Inc.

Shawn Brown  
100-00440

## **Environmental Notification to Occupants**

To: Faculty, Staff and Parents  
From: Chicago Public Schools  
Date: August 29, 2019

RE: Harvard School, Unit 23581  
7525 S. Harvard  
Chicago, IL, 60620

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2019 asbestos three year re-inspection has been completed at Harvard School, following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at Harvard School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Robert Christlieb, the designated Local Education Authority's Designated Person at (773) 553-3197 .

## **Table of Contents**

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

### **APPENDICES:**

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

## SCHOOL AND INSPECTION INFORMATION

### 1. School Information

School: Harvard School  
Address: 7525 S. Harvard  
IDPH ID: 14-016-2990-2246  
Contact:

Unit: 23581  
Chicago, IL, 60620  
Building ID: 3800  
Phone:

Region: 05

### 2. Description of Facility

Original Construction: 1905  
Total Square Footage: 54868  
Current Occupancy: 381

Additional Construction:  
No of Floors: 3

### 3. LEA Designated Person

Contact: Robert Christlieb  
Address: 42 West Madison Street  
Chicago, IL 60602

Phone: (773) 553-3197

### 4. Managing Environmental Consultant

MEC: TEM Environmental, Inc.  
Contact: Steven Geneser  
Address 174 N. Brandon Drive  
Glendale Heights, IL, 60139  
Phone: 630-790-0880

Fax: 630-790-0882

### 5. Inspector

Inspector Name: Lisa Laney

Inspector IDPH license # 100-07839

Signature:  
Date: 8/29/2019

### 6. Management Planner

Management Planner Name: Shawn Brown

Management Planner IDPH license # 100-00440

Signature:  
Date: 09/28/2019

### 7. Review Date:09/28/2019

### 8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature:



Date: 10/1/2019

Name: Robert Christlieb

## II. EXECUTIVE SUMMARY

TEM Environmental, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Harvard School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.85 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas(HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 3800:

- |   |                            |
|---|----------------------------|
| B | Cementitious Pipe Fittings |
| D | Aircell Fittings           |
| E | Cardboard Pipe Insulation  |

B. The following new homogenous areas have been identified for Building 3800:

- 30                    12" X 12" Gray Floor Tile
- 30A                  12" X 12" Grey Floor Tile Mastic



C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

16	Baseboard
17	Baseboard Mastic
18	Baseboard-NOT OBSERVED
19	Baseboard Mastic-NOT OBSERVED
20	Firebrick
22	Fire Door
23	Plaster
24	12x12 White Floor Tile-NOT OBSERVED
25	12"x12" Yellow w/White Specks Vinyl Floor Tile
25A	12"x12" Yellow w/White Specks Vinyl Floor Tile Mastic
26	12"x12" Orange w/Streaks Vinyl Floor Tile
26A	12"x12" Orange w/Streaks Vinyl Floor Tile Mastic
27	Wood Mastic
28	Grey Roll Tile Mastic
29	9"x9" Tan w/Brown Streaks VFT
29A	9"x9" Tan w/Brown Streaks VFT Mastic
30	12" X 12" Gray Floor Tile
30A	12" X 12" Grey Floor Tile Mastic
CM-1	Carpet Mastic-NOT OBSERVED
FT-2	12x12 Orange Floor Tile
FT-5	12x12 Checkerboard Tan Floor Tile-NOT OBSERVED
FT-7	12x12 Maroon Floor Tile
FT-8	12x12 Beige w/Cream Specks Floor Tile
FT-9	12x12 White w/Tan Specks Floor Tile
FTM-5	12x12 Checkerboard Tan Floor Tile Mastic-NOT OBSERVED
FTM-7	12x12 Maroon Floor Tile Mastic
FTM-8	12x12 Beige w/Cream Specks Floor Tile Mastic
FU-1	12x12 Yellow VFT
FU-10	12x12 OrangeVFT Mastic
FU-11	12x12 Grey Tile
FU-12	12x12 Grey VFT Mastic
FU-13	12x12 Brown Tile
FU-14	12x12 Brown VFT Mastic
FU-2	12x12 Yellow VFT Mastic
FU-3	12x12 Orange Tile
FU-4	12x12 Orange Mastic
FU-5	12x12 Blue Tile
FU-6	12x12 Blue Mastic
FU-7	12x12 Yellow Tile

FU-8	12x12 Yellow VFT Mastic
FU-9	12x12 Orange Tile
R	Cardboard Fittings

The following areas were deemed to be inaccessible:

17	Baseboard Mastic
20	Firebrick
22	Fire Door
25A	12"x12" Yellow w/White Specks Vinyl Floor Tile Mastic
26A	12"x12" Orange w/Streaks Vinyl Floor Tile Mastic
28	Grey Roll Tile Mastic
29A	9"x9" Tan w/Brown Streaks VFT Mastic
B	Cementitious Pipe Fittings
C	Aircell Pipe Insulation
D	Aircell Fittings
E	Cardboard Pipe Insulation
FTM-2	12x12 Orange Floor Tile Mastic
FTM-7	12x12 Maroon Floor Tile Mastic
FTM-8	12x12 Beige w/Cream Specks Floor Tile Mastic
FU-10	12x12 Orange VFT Mastic
FU-12	12x12 Grey VFT Mastic
FU-14	12x12 Brown VFT Mastic
FU-2	12x12 Yellow VFT Mastic
FU-4	12x12 Orange Mastic
FU-6	12x12 Blue Mastic
FU-8	12x12 Yellow VFT Mastic
J	Mag Tank Insulation
N	Cementitious Fittings
O	Aircell Pipe Insulation
Q	Cardboard Pipe Insulation
R	Cardboard Fittings

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Lisa Laney, IDPH License # 100-07839. The Management Plan was updated by Shawn Brown, IDPH License # 100-00440. Inspector and Management Planner Licenses are included in Appendix B.

### **III. METHODOLOGY**

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

### **IV. ABATEMENT HISTORY**

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:       6/27/2019  
                                  6/27/2019

### **V. REASSESSMENTS AND RECOMMENDATIONS**

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

### **VI. CONCLUSIONS**

The Harvard School Building 3800 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

**Table I**  
**Inspector's Reinspection Findings**

---

# Chicago Public Schools

School Harvard School Unit 23581 Building ID 3800

Address 7525 S. Harvard Region 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
08	9x9 Green w/White & Dark Green Streaks Floor Tile ABATED			Original Building- Basement Classrooms	ABATED	MISC		None						
09	9x9 Green Floor Tile Mastic ABATED			Original Building- Basement Classrooms	ABATED	MISC								
10	9x9 Tan w/Cream & Brown Streaks Floor Tile ABATED			1959 Addition- All Classrooms	ABATED	MISC		None						Low
11	9x9 Tan w/Crème & Brown Streaks Floor Tile Mastic ABATED			Safe Room	ABATED	MISC								
12	12x12 Crème w/Tan & Brown Flakes Floor Tile ABATED			Original Building- 2nd & 3rd Floor Classrooms	ABATED	MISC		None						Low
13	12x12 Crème w/Tan & Brown Flakes Floor Tile Mastic ABATED			Original Building- 2nd & 3rd Floor Classrooms	ABATED	MISC		None						Low
14	12x12 Tan w/Crème Brown Flakes ABATED			1959 Addition- 1st & 2nd Floor Hall (Patch)	ABATED	MISC		None						Low
15	12x12 Tan w/Crème Brown Flakes Mastic ABATED			1959 Addition- 1st & 2nd Floor Hall (Patch)	ABATED	MISC								
16	Baseboard	100	LF	Original Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
17	Baseboard Mastic	100	LF	Original Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
18	Baseboard-NOT OBSERVED			1959 Addition	ASSUMED	MISC		None						Low
19	Baseboard Mastic-NOT OBSERVED			1959 Addition	ASSUMED	MISC		None						Low
20	Firebrick	100	SF	Boiler Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
22	Fire Door	8	EA	Original Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
23	Plaster	1,539,800	SF	Old Building- 201, 203 Coat Room, 304, N. Stairwell, Outside 201, 203; New Building- Stairwell Entrance	ASSUMED	SURFACE	N	NONE	0		No	ACBM with the potential for damage		LOW
24	12x12 White Floor Tile-NOT OBSERVED			1959 Building- 1st & 2nd Floor Corridors	ASSUMED	MISC								
25	12"x12" Yellow w/White Specks Vinyl Floor Tile	6,800	SF	2nd & 3rd Floor Classrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
25A	12"x12" Yellow w/White Specks Vinyl	6,800	SF	2nd & 3rd Floor	ASSUMED	MISC	N	NONE	0		No	ACBM with the		LOW



# Chicago Public Schools

School Harvard School Unit 23581 Building ID 3800

Address 7525 S. Harvard Region 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
	ABATED			Patches in 112, 110, 108, Assistant Principal's Office										
FT-4	12x12 Checkerboard White & Tan ABATED			1959 Building-Teachers' Bathroom and Hallway Patch	ABATED	MISC								
FT-5	12x12 Checkerboard Tan Floor Tile-NOT OBSERVED			1959 Main building - Engineer's Office	ASSUMED	MISC								
FT-6	12x12 Taupe Floor Tile ABATED			Annex- Corridors; Main Building-Classrooms A & B	ABATED	MISC		None						
FT-7	12x12 Maroon Floor Tile	600	SF	Main Building-Kitchen	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FT-8	12x12 Beige w/Cream Specks Floor Tile	800	SF	Annex- 108 Patch; Main Building-Lunchroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FT-9	12x12 White w/Tan Specks Floor Tile	1,500	SF	Annex- 1/2 of Room 105	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FTM-1	12x12 Mastic Crème w/White Flakes Floor Tile	80	SF	Original Building-Staircase Landing	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FTM-2	12x12 Orange Floor Tile Mastic	200	SF	Original Building-Auditorium Balcony	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FTM-3	9x9 Checkerboard Tan & Brown Floor Tile Mastic ABATED			1959 Building-Patches in 112, 110, 108	ABATED	MISC		None						
FTM-4	12x12 Checkerboard White & Tan-ABATED			1959 Building-Teachers' Bathroom and Hallway Patch	ABATED	MISC		None						
FTM-5	12x12 Checkerboard Tan Floor Tile Mastic-NOT OBSERVED			1959 Building-Room 105, Teachers' Lounge Washroom; Main Building- Engineer's Office	ASSUMED	MISC								
FTM-6	12x12 Taupe Floor Tile Mastic ABATED			Annex- Corridors; Main Building-Classrooms A & B	ABATED	MISC		None						
FTM-7	12x12 Maroon Floor Tile Mastic	600	SF	Main Building-Kitchen	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FTM-8	12x12 Beige w/Cream Specks Floor Tile Mastic	800	SF	Annex- 108 Patch; Main Building-Lunchroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FU-1	12x12 Yellow VFT	3,000	SF	Lunchroom A & B, Annex Corridors	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

# Chicago Public Schools

School Harvard School Unit 23581 Building ID 3800

Address 7525 S. Harvard Region 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
FU-10	12x12 Orange VFT Mastic	360	SF	Principal's Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FU-11	12x12 Grey Tile	240	SF	Original Building- Staircase Landing	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FU-12	12x12 Grey VFT Mastic	240	SF	Original Building- Staircase Landing	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FU-13	12x12 Brown Tile	350	SF	1959 Building- Teacher's Lounge Washroom, Engineer's Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FU-14	12x12 Brown VFT Mastic	350	SF	1959 Building- Teacher's Lounge Washroom, Engineer's Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FU-2	12x12 Yellow VFT Mastic	3,000	SF	Lunchroom A & B, Annex Corridors	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FU-3	12x12 Orange Tile	1,500	SF	Lunchroom A & B, Annex Corridors	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FU-4	12x12 Orange Mastic	1,500	SF	Lunchroom A & B, Annex Corridors	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FU-5	12x12 Blue Tile	3,985	SF	1959 Building- All Rooms and Corridors on 1st & 2nd Floors	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FU-6	12x12 Blue Mastic	3,985	SF	1959 Building- All Rooms and Corridors on 1st & 2nd Floors	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FU-7	12x12 Yellow Tile	1,700	SF	1959 Building- All Rooms and Corridors on 1st & 2nd Floors	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FU-8	12x12 Yellow VFT Mastic	1,700	SF	1959 Building- 1st & 2nd Floor, All Rooms & Corridors	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FU-9	12x12 Orange Tile	360	SF	Principal's Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
G	Mag Pipe Insulation ABATED			Basement- Fan Houses Piping	ABATED	TSI		None						
H	Mag Fittings	100	LF	Basement - Fan Houses Piping	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
J	Mag Tank Insulation	200	SF	Tankroom	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable		LOW



# Chicago Public Schools

School Harvard School Unit 23581 Building ID 3800

Address 7525 S. Harvard Region 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
												suspect ACBM		
N	Cementious Fittings	95	LF	1959 Addition	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
O	Aircell Pipe Insulation	95	LF	1959 Addition	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
Q	Cardboard Pipe Insulation	150	LF	1959 Addition	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
R	Cardboard Fittings	25	LF	1959 Building	ASSUMED	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
WC-1	Window Caulking ABATED			1959 Building	ABATED	MISC								
WG-1	Window Glazing ABATED			1959 Building	ABATED	MISC		None						Low

# Chicago Public Schools

School Harvard School Unit 23581 Building ID 3800

Address 7525 S. Harvard Region 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

Reinspection Date <b>8/29/2019</b>
Inspector Name <b><u>Lisa Laney</u></b>
<b>100-07839</b> <b>5/15/2020</b>
Inspector's IDPH License Number / Expiration Date

### Inspector's Comments

HA Number:	Inspector Comments:
08	
09	
10	
11	
12	
13	
14	
15	
16	
17	
18	Not Observed Multiple Years
19	Not Observed Multiple Years
20	
22	
23	
24	
25	
25A	
26	
26A	
27	
28	
29	

# Chicago Public Schools

School Harvard School Unit 23581 Building ID 3800

Address 7525 S. Harvard Region 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
29A	
30	
30A	Damaged VFT in Boiler Room
B	Damage in Basement Switch Gear Rm., Pump Rm., Boiler Rm., Boiler Rm. Bathroom
C	Damage in Basement Switch Gear Rm., Pump Rm., Boiler Rm., Boiler Rm. Bathroom
CM-1	Not Observed Multiple Years
D	Damage in Basement Switch Gear Rm., Pump Rm., Boiler Rm., Boiler Rm. Bathroom
E	Damage in Basement Switch Gear Rm., Pump Rm.
FT-1	
FT-2	
FT-3	
FT-4	
FT-5	Not Observed Multiple Years - New HA is 30
FT-6	
FT-7	
FT-8	
FT-9	
FTM-1	
FTM-2	
FTM-3	
FTM-4	
FTM-5	Not Observed Multiple Years
FTM-6	
FTM-7	
FTM-8	
FU-1	
FU-10	
FU-11	
FU-12	

# Chicago Public Schools

School Harvard School Unit 23581 Building ID 3800

Address 7525 S. Harvard Region 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
FU-13	
FU-14	
FU-2	
FU-3	
FU-4	
FU-5	15 SF Abated in Rm. 108 for cabinet replacement June 2019
FU-6	15 SF Abated in Rm. 108 for cabinet replacement 2019
FU-7	
FU-8	
FU-9	
G	
H	Tank Room
J	
N	
O	
Q	
R	
WC-1	
WG-1	

**Table II**

**Management Planner's Review**

---

# Chicago Public Schools

**School** Harvard School  
**Address** 7525 S. Harvard

**Unit** 23581  
Chicago, IL, 60620

**Building ID** 3800  
**Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

### Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
08	9x9 Green w/White & Dark Green Streaks Floor Tile ABATED			Original Building- Basement Classrooms	Abated	MISC					
09	9x9 Green Floor Tile Mastic ABATED			Original Building- Basement Classrooms	Abated	MISC					
10	9x9 Tan w/Cream & Brown Streaks Floor Tile ABATED			1959 Addition- All Classrooms	Abated	MISC					
11	9x9 Tan w/Crème & Brown Streaks Floor Tile Mastic ABATED			Safe Room	Abated	MISC					
12	12x12 Crème w/Tan & Brown Flakes Floor Tile ABATED			Original Building- 2nd & 3rd Floor Classrooms	Abated	MISC					
13	12x12 Crème w/Tan & Brown Flakes Floor Tile Mastic ABATED			Original Building- 2nd & 3rd Floor Classrooms	Abated	MISC					
14	12x12 Tan w/Crème Brown Flakes ABATED			1959 Addition- 1st & 2nd Floor Hall (Patch)	Abated	MISC					
15	12x12 Tan w/Crème Brown Flakes Mastic ABATED			1959 Addition- 1st & 2nd Floor Hall (Patch)	Abated	MISC					
16	Baseboard	100	LF	Original Building	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
17	Baseboard Mastic	100	LF	Original Building	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
18	Baseboard-NOT OBSERVED			1959 Addition	Assumed	MISC					
19	Baseboard Mastic-NOT OBSERVED			1959 Addition	Assumed	MISC					
20	Firebrick	100	SF	Boiler Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
22	Fire Door	8	EA	Original Building	Assumed	MISC	No	0	EA	6 ACBM with the potential for damage	Follow O&M Plan
23	Plaster	1,539,800	SF	Old Building- 201, 203 Coat Room, 304, N. Stairwell, Outside 201, 203; New Building- Stairwell Entrance	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
24	12x12 White Floor Tile-NOT OBSERVED			1959 Building- 1st & 2nd Floor Corridors	Assumed	MISC					
25	12"x12" Yellow w/White Specks Vinyl Floor Tile	6,800	SF	2nd & 3rd Floor Classrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
25A	12"x12" Yellow w/White Specks Vinyl Floor Tile Mastic	6,800	SF	2nd & 3rd Floor Classrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
26	12"x12" Orange w/Streaks Vinyl Floor Tile	2,000	SF	2nd & 3rd Floor Classrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
26A	12"x12" Orange w/Streaks Vinyl Floor Tile Mastic	2,000	SF	2nd & 3rd Floor Classrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
27	Wood Mastic	2,000	SF	Rooms 101-104	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
28	Grey Roll Tile Mastic	240	SF	Staircase Landing 2nd & 3rd Floor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Harvard School  
**Address** 7525 S. Harvard

**Unit** 23581  
Chicago, IL, 60620

**Building ID** 3800  
**Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

### Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
29	9"x9" Tan w/Brown Streaks VFT	100	SF	107B Storage Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
29A	9"x9" Tan w/Brown Streaks VFT Mastic	100	SF	107B Storage Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
30	12" X 12" Gray Floor Tile	200	SF	Boiler Room Bathroom	Assumed	MISC	No	30	SF	6 ACBM with the potential for damage	Follow O&M Plan
30A	12" X 12" Grey Floor Tile Mastic	200	SF	Boiler Room Bathroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
B	Cementitious Pipe Fittings	140	FITTING	Original Building	Chrysotile	TSI	Yes	20	FITTING	1 Damaged or significantly damaged friable thermal system insulating ACBM	Repair
C	Aircell Pipe Insulation	710	LF	Original Building	Chrysotile	TSI	Yes	25	LF	1 Damaged or significantly damaged friable thermal system insulating ACBM	Repair
CM-1	Carpet Mastic-NOT OBSERVED			1959 Building- Office, Teachers Lounge; Main Building- Room 205	Assumed	MISC					
D	Aircell Fittings	132	FITTING	Original Building	Chrysotile	TSI	Yes	15	FITTING	1 Damaged or significantly damaged friable thermal system insulating ACBM	Repair
E	Cardboard Pipe Insulation	850	LF	Original Building	Chrysotile	TSI	Yes	20	LF	1 Damaged or significantly damaged friable thermal system insulating ACBM	Repair
FT-1	12x12 Crème w/White Flakes Floor Tile ABATED			Original Building- Staircase Landing and Assistant Principal's Office	Abated	MISC					
FT-2	12x12 Orange Floor Tile	200	SF	Original Building- Auditorium Balcony	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FT-3	9x9 Checkboard Tan & Brown Floor Tile ABATED			1959 Building- Patches in 112, 110, 108, Assistant Principal's Office	Abated	MISC					
FT-4	12x12 Checkerboard White & Tan ABATED			1959 Building- Teachers' Bathroom and Hallway Patch	Abated	MISC					
FT-5	12x12 Checkerboard Tan Floor Tile-NOT OBSERVED			1959 Main building - Engineer's Office	Assumed	MISC					
FT-6	12x12 Taupe Floor Tile ABATED			Annex- Corridors; Main Building- Classrooms A & B	Abated	MISC					
FT-7	12x12 Maroon Floor Tile	600	SF	Main Building- Kitchen	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FT-8	12x12 Beige w/Cream Specks Floor Tile	800	SF	Annex- 108 Patch; Main Building- Lunchroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FT-9	12x12 White w/Tan Specks Floor Tile	1,500	SF	Annex- 1/2 of Room 105	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FTM-1	12x12 Mastic Crème w/White Flakes Floor Tile	80	SF	Original Building- Staircase Landing	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FTM-2	12x12 Orange Floor Tile Mastic	200	SF	Original Building- Auditorium Balcony	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FTM-3	9x9 Checkboard Tan & Brown Floor Tile Mastic ABATED			1959 Building- Patches in 112, 110, 108	Abated	MISC					
FTM-4	12x12 Checkerboard White & Tan-ABATED			1959 Building- Teachers' Bathroom and	Abated	MISC					

# Chicago Public Schools

School Harvard School

Unit 23581

Building ID 3800

Address 7525 S. Harvard

Chicago, IL, 60620

Region 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

### Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				Hallway Patch							
FTM-5	12x12 Checkerboard Tan Floor Tile Mastic-NOT OBSERVED			1959 Building- Room 105, Teachers' Lounge Washroom; Main Building- Engineer's Office	Assumed	MISC					
FTM-6	12x12 Taupe Floor Tile Mastic ABATED			Annex- Corridors; Main Building- Classrooms A & B	Abated	MISC					
FTM-7	12x12 Maroon Floor Tile Mastic	600	SF	Main Building- Kitchen	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FTM-8	12x12 Beige w/Cream Specks Floor Tile Mastic	800	SF	Annex- 108 Patch; Main Building- Lunchroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FU-1	12x12 Yellow VFT	3,000	SF	Lunchroom A & B, Annex Corridors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FU-10	12x12 Orange VFT Mastic	360	SF	Principal's Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FU-11	12x12 Grey Tile	240	SF	Original Building- Staircase Landing	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FU-12	12x12 Grey VFT Mastic	240	SF	Original Building- Staircase Landing	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FU-13	12x12 Brown Tile	350	SF	1959 Building- Teacher's Lounge Washroom, Engineer's Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FU-14	12x12 Brown VFT Mastic	350	SF	1959 Building- Teacher's Lounge Washroom, Engineer's Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FU-2	12x12 Yellow VFT Mastic	3,000	SF	Lunchroom A & B, Annex Corridors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FU-3	12x12 Orange Tile	1,500	SF	Lunchroom A & B, Annex Corridors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FU-4	12x12 Orange Mastic	1,500	SF	Lunchroom A & B, Annex Corridors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FU-5	12x12 Blue Tile	3,985	SF	1959 Building- All Rooms and Corridors on 1st & 2nd Floors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FU-6	12x12 Blue Mastic	3,985	SF	1959 Building- All Rooms and Corridors on 1st & 2nd Floors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FU-7	12x12 Yellow Tile	1,700	SF	1959 Building- All Rooms and Corridors on 1st & 2nd Floors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FU-8	12x12 Yellow VFT Mastic	1,700	SF	1959 Building- 1st & 2nd Floor, All Rooms & Corridors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FU-9	12x12 Orange Tile	360	SF	Principal's Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
G	Mag Pipe Insulation ABATED			Basement- Fan Houses Piping	Abated	TSI					
H	Mag Fittings	100	LF	Basement - Fan Houses Piping	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
J	Mag Tank Insulation	200	SF	Tankroom	Chrysotile	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan



# Chicago Public Schools

**School** Harvard School  
**Address** 7525 S. Harvard

**Unit** 23581  
 Chicago, IL, 60620

**Building ID** 3800  
**Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
N	Cementious Fittings	95	LF	1959 Addition	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
O	Aircell Pipe Insulation	95	LF	1959 Addition	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
Q	Cardboard Pipe Insulation	150	LF	1959 Addition	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
R	Cardboard Fittings	25	LF	1959 Building	Assumed	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
WC-1	Window Caulking ABATED			1959 Building	Abated	MISC					
WG-1	Window Glazing ABATED			1959 Building	Abated	MISC					

# Chicago Public Schools

**School** Harvard School  
**Address** 7525 S. Harvard

**Unit** 23581  
 Chicago, IL, 60620

**Building ID** 3800  
**Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

*Management Planner's Comments Summarized at the End of the Report*

Review Date	09/28/2019
Manager Planner Name	Shawn Brown
100-00440	5/15/2020
Manager IDPH License No/Expiration	

HA Number	Management Comments
08	
09	
10	
11	
12	
13	
14	
15	
16	
17	
18	
19	
20	
22	
23	
24	
25	
25A	
26	
26A	
27	
28	
29	

# Chicago Public Schools

**School** Harvard School  
**Address** 7525 S. Harvard

**Unit** 23581  
 Chicago, IL, 60620

**Building ID** 3800  
**Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
29A	
30	
30A	
B	
C	
CM-1	
D	
E	
FT-1	
FT-2	
FT-3	
FT-4	
FT-5	
FT-6	
FT-7	
FT-8	
FT-9	
FTM-1	
FTM-2	
FTM-3	
FTM-4	
FTM-5	
FTM-6	
FTM-7	
FTM-8	
FU-1	

# Chicago Public Schools

**School** Harvard School  
**Address** 7525 S. Harvard

**Unit** 23581  
 Chicago, IL, 60620

**Building ID** 3800  
**Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
FU-10	
FU-11	
FU-12	
FU-13	
FU-14	
FU-2	
FU-3	
FU-4	
FU-5	
FU-6	
FU-7	
FU-8	
FU-9	
G	
H	
J	
N	
O	
Q	
R	
WC-1	
WG-1	

# Chicago Public Schools

TEM Environmental, Inc.

## 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **23581**    BUILDING ID: **3800**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Harvard School**    INSPECTION DATE: **8/29/2019**  
ADDRESS: **7525 S. Harvard**    IDPH LICENSE NO: **100-07839**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **08**  
MATERIAL DESCRIPTION: **9x9 Green w/White & Dark Green Streaks Floor Tile ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated**    FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Original Building- Basement Classrooms**

MATERIAL QUANTITY:    MATERIAL UNITS:

DAMAGE QUANTITY:    DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **08/29/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUIDLING ID: **3800**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Harvard School** REVIEW DATE: **9/28/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **08**

MATERIAL DESCRIPTION: **9x9 Green w/White & Dark Green Streaks Floor Tile ABATED**

MATERIAL LOCATION: **Original Building- Basement Classrooms**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/28/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUILDING ID: **3800**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Harvard School** INSPECTION DATE: **8/29/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **09**  
MATERIAL DESCRIPTION: **9x9 Green Floor Tile Mastic ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Original Building- Basement Classrooms**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **08/29/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUIDLING ID: **3800**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Harvard School** REVIEW DATE: **9/28/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **09**

MATERIAL DESCRIPTION: **9x9 Green Floor Tile Mastic ABATED**

MATERIAL LOCATION: **Original Building- Basement Classrooms**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/28/2019**



# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUIDLING ID: **3800**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Harvard School** INSPECTION DATE: **8/29/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10**  
MATERIAL DESCRIPTION: **9x9 Tan w/Cream & Brown Streaks Floor Tile ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **1959 Addition- All Classrooms**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **08/29/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUIDLING ID: **3800**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Harvard School** REVIEW DATE: **9/28/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **10**

MATERIAL DESCRIPTION: **9x9 Tan w/Cream & Brown Streaks Floor Tile ABATED**

MATERIAL LOCATION: **1959 Addition- All Classrooms**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/28/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUIDLING ID: **3800**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Harvard School** INSPECTION DATE: **8/29/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11**  
MATERIAL DESCRIPTION: **9x9 Tan w/Crème & Brown Streaks Floor Tile Mastic ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Safe Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: **08/29/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUIDLING ID: **3800**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Harvard School** REVIEW DATE: **9/28/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **11**

MATERIAL DESCRIPTION: **9x9 Tan w/Crème & Brown Streaks Floor Tile Mastic ABATED**

MATERIAL LOCATION: **Safe Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/28/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUIDLING ID: **3800**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Harvard School** INSPECTION DATE: **8/29/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12**  
MATERIAL DESCRIPTION: **12x12 Crème w/Tan & Brown Flakes Floor Tile ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **Original Building- 2nd & 3rd Floor Classrooms**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **08/29/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUIDLING ID: **3800**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Harvard School** REVIEW DATE: **9/28/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **12**

MATERIAL DESCRIPTION: **12x12 Crème w/Tan & Brown Flakes Floor Tile ABATED**

MATERIAL LOCATION: **Original Building- 2nd & 3rd Floor Classrooms**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/28/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUILDING ID: **3800**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Harvard School** INSPECTION DATE: **8/29/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13**  
MATERIAL DESCRIPTION: **12x12 Crème w/Tan & Brown Flakes Floor Tile Mastic ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **Original Building- 2nd & 3rd Floor Classrooms**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **08/29/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUIDLING ID: **3800**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Harvard School** REVIEW DATE: **9/28/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **13**

MATERIAL DESCRIPTION: **12x12 Crème w/Tan & Brown Flakes Floor Tile Mastic ABATED**

MATERIAL LOCATION: **Original Building- 2nd & 3rd Floor Classrooms**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/28/2019**



# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUIDLING ID: **3800**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Harvard School** INSPECTION DATE: **8/29/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14**  
MATERIAL DESCRIPTION: **12x12 Tan w/Crème Brown Flakes ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **1959 Addition- 1st & 2nd Floor Hall (Patch)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **08/29/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUIDLING ID: **3800**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Harvard School** REVIEW DATE: **9/28/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **14**

MATERIAL DESCRIPTION: **12x12 Tan w/Crème Brown Flakes ABATED**

MATERIAL LOCATION: **1959 Addition- 1st & 2nd Floor Hall (Patch)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/28/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **23581**    BUIDLING ID: **3800**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Harvard School**    INSPECTION DATE: **8/29/2019**  
ADDRESS: **7525 S. Harvard**    IDPH LICENSE NO: **100-07839**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15**  
MATERIAL DESCRIPTION: **12x12 Tan w/Crème Brown Flakes Mastic ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated**    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1959 Addition- 1st & 2nd Floor Hall (Patch)**

MATERIAL QUANTITY:    MATERIAL UNITS:

DAMAGE QUANTITY:    DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **08/29/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUIDLING ID: **3800**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Harvard School** REVIEW DATE: **9/28/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **15**  
MATERIAL DESCRIPTION: **12x12 Tan w/Crème Brown Flakes Mastic ABATED**  
MATERIAL LOCATION: **1959 Addition- 1st & 2nd Floor Hall (Patch)**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/28/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUIDLING ID: **3800**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Harvard School** INSPECTION DATE: **8/29/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16**  
MATERIAL DESCRIPTION: **Baseboard**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Original Building**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/29/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUIDLING ID: **3800**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Harvard School** REVIEW DATE: **9/28/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **16**  
MATERIAL DESCRIPTION: **Baseboard**  
MATERIAL LOCATION: **Original Building**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/28/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUIDLING ID: **3800**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Harvard School** INSPECTION DATE: **8/29/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17**  
MATERIAL DESCRIPTION: **Baseboard Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Original Building**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/29/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUIDLING ID: **3800**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Harvard School** REVIEW DATE: **9/28/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **17**  
MATERIAL DESCRIPTION: **Baseboard Mastic**  
MATERIAL LOCATION: **Original Building**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/28/2019**



# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUIDLING ID: **3800**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Harvard School** INSPECTION DATE: **8/29/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18**  
MATERIAL DESCRIPTION: **Baseboard-NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **1959 Addition**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed Multiple Years**

Inspector's Signature: \_\_\_\_\_ Date: 08/29/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUIDLING ID: **3800**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Harvard School** REVIEW DATE: **9/28/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **18**

MATERIAL DESCRIPTION: **Baseboard-NOT OBSERVED**

MATERIAL LOCATION: **1959 Addition**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/28/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUIDLING ID: **3800**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Harvard School** INSPECTION DATE: **8/29/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19**  
MATERIAL DESCRIPTION: **Baseboard Mastic-NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **1959 Addition**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed Multiple Years**

Inspector's Signature: \_\_\_\_\_ Date: 08/29/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUIDLING ID: **3800**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Harvard School** REVIEW DATE: **9/28/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **19**

MATERIAL DESCRIPTION: **Baseboard Mastic-NOT OBSERVED**

MATERIAL LOCATION: **1959 Addition**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/28/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUIDLING ID: **3800**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Harvard School** INSPECTION DATE: **8/29/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**  
MATERIAL DESCRIPTION: **Firebrick**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Boiler Room**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/29/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUIDLING ID: **3800**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Harvard School** REVIEW DATE: **9/28/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **20**  
MATERIAL DESCRIPTION: **Firebrick**  
MATERIAL LOCATION: **Boiler Room**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/28/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUIDLING ID: **3800**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Harvard School** INSPECTION DATE: **8/29/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22**  
MATERIAL DESCRIPTION: **Fire Door**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Original Building**  
MATERIAL QUANTITY: **8** MATERIAL UNITS: **EA**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/29/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUILDING ID: **3800**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Harvard School** REVIEW DATE: **9/28/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **22**  
MATERIAL DESCRIPTION: **Fire Door**  
MATERIAL LOCATION: **Original Building**  
MATERIAL QUANTITY: **8** MATERIAL UNITS: **EA**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/28/2019**



# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUIDLING ID: **3800**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Harvard School** INSPECTION DATE: **8/29/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23**  
MATERIAL DESCRIPTION: **Plaster**  
HISTORICAL AHERA DAMAGE CATEGORY **6 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Old Building- 201, 203 Coat Room, 304, N. Stairwell, Outside 201, 203; New Building- Stairwell Entrance**

MATERIAL QUANTITY: **1539800**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 08/29/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUIDLING ID: **3800**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Harvard School** REVIEW DATE: **9/28/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **23**  
MATERIAL DESCRIPTION: **Plaster**  
MATERIAL LOCATION: **Old Building- 201, 203 Coat Room, 304, N. Stairwell, Outside 201, 203; New Building- Stairwell Entrance**  
MATERIAL QUANTITY: **1539800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/28/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUILDING ID: **3800**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Harvard School** INSPECTION DATE: **8/29/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **24**  
MATERIAL DESCRIPTION: **12x12 White Floor Tile-NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1959 Building- 1st & 2nd Floor Corridors**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/29/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUIDLING ID: **3800**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Harvard School** REVIEW DATE: **9/28/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **24**

MATERIAL DESCRIPTION: **12x12 White Floor Tile-NOT OBSERVED**

MATERIAL LOCATION: **1959 Building- 1st & 2nd Floor Corridors**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/28/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUIDLING ID: **3800**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Harvard School** INSPECTION DATE: **8/29/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25**  
MATERIAL DESCRIPTION: **12"x12" Yellow w/White Specks Vinyl Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **2nd & 3rd Floor Classrooms**  
MATERIAL QUANTITY: **6800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/29/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUIDLING ID: **3800**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Harvard School** REVIEW DATE: **9/28/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **25**  
MATERIAL DESCRIPTION: **12"x12" Yellow w/White Specks Vinyl Floor Tile**  
MATERIAL LOCATION: **2nd & 3rd Floor Classrooms**  
MATERIAL QUANTITY: **6800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/28/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUIDLING ID: **3800**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Harvard School** INSPECTION DATE: **8/29/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25A**  
MATERIAL DESCRIPTION: **12"x12" Yellow w/White Specks Vinyl Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **2nd & 3rd Floor Classrooms**  
MATERIAL QUANTITY: **6800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/29/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUILDING ID: **3800**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Harvard School** REVIEW DATE: **9/28/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **25A**  
MATERIAL DESCRIPTION: **12"x12" Yellow w/White Specks Vinyl Floor Tile Mastic**  
MATERIAL LOCATION: **2nd & 3rd Floor Classrooms**  
MATERIAL QUANTITY: **6800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/28/2019**



# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUIDLING ID: **3800**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Harvard School** INSPECTION DATE: **8/29/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26**  
MATERIAL DESCRIPTION: **12"x12" Orange w/Streaks Vinyl Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **2nd & 3rd Floor Classrooms**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/29/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUIDLING ID: **3800**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Harvard School** REVIEW DATE: **9/28/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **26**  
MATERIAL DESCRIPTION: **12"x12" Orange w/Streaks Vinyl Floor Tile**  
MATERIAL LOCATION: **2nd & 3rd Floor Classrooms**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/28/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUIDLING ID: **3800**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Harvard School** INSPECTION DATE: **8/29/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26A**  
MATERIAL DESCRIPTION: **12"x12" Orange w/Streaks Vinyl Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **2nd & 3rd Floor Classrooms**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/29/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUIDLING ID: **3800**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Harvard School** REVIEW DATE: **9/28/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **26A**  
MATERIAL DESCRIPTION: **12"x12" Orange w/Streaks Vinyl Floor Tile Mastic**  
MATERIAL LOCATION: **2nd & 3rd Floor Classrooms**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/28/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUIDLING ID: **3800**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Harvard School** INSPECTION DATE: **8/29/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27**  
MATERIAL DESCRIPTION: **Wood Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 101-104**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/29/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUILDING ID: **3800**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Harvard School** REVIEW DATE: **9/28/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **27**  
MATERIAL DESCRIPTION: **Wood Mastic**  
MATERIAL LOCATION: **Rooms 101-104**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/28/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUIDLING ID: **3800**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Harvard School** INSPECTION DATE: **8/29/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28**  
MATERIAL DESCRIPTION: **Grey Roll Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Staircase Landing 2nd & 3rd Floor**  
MATERIAL QUANTITY: **240** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/29/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUIDLING ID: **3800**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Harvard School** REVIEW DATE: **9/28/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **28**  
MATERIAL DESCRIPTION: **Grey Roll Tile Mastic**  
MATERIAL LOCATION: **Staircase Landing 2nd & 3rd Floor**  
MATERIAL QUANTITY: **240** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/28/2019**



# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUIDLING ID: **3800**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Harvard School** INSPECTION DATE: **8/29/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **29**  
MATERIAL DESCRIPTION: **9"x9" Tan w/Brown Streaks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **107B Storage Room**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/29/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUIDLING ID: **3800**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Harvard School** REVIEW DATE: **9/28/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **29**  
MATERIAL DESCRIPTION: **9"x9" Tan w/Brown Streaks VFT**  
MATERIAL LOCATION: **107B Storage Room**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/28/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUIDLING ID: **3800**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Harvard School** INSPECTION DATE: **8/29/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **29A**  
MATERIAL DESCRIPTION: **9"x9" Tan w/Brown Streaks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **107B Storage Room**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/29/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUIDLING ID: **3800**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Harvard School** REVIEW DATE: **9/28/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **29A**  
MATERIAL DESCRIPTION: **9"x9" Tan w/Brown Streaks VFT Mastic**  
MATERIAL LOCATION: **107B Storage Room**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/28/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUIDLING ID: **3800**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Harvard School** INSPECTION DATE: **8/29/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **B**  
MATERIAL DESCRIPTION: **Cementitious Pipe Fittings**  
HISTORICAL AHERA DAMAGE CATEGORY **1 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Original Building**  
MATERIAL QUANTITY: **140** MATERIAL UNITS: **FITTING**  
DAMAGE QUANTITY: **20** DAMAGE UNITS: **FITTING**

COMMENTS: **Damage in Basement Switch Gear Rm., Pump Rm., Boiler Rm., Boiler Rm. Bathroom**

Inspector's Signature: \_\_\_\_\_ Date: 08/29/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUIDLING ID: **3800**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Harvard School** REVIEW DATE: **9/28/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **B**  
MATERIAL DESCRIPTION: **Cementitious Pipe Fittings**  
MATERIAL LOCATION: **Original Building**  
MATERIAL QUANTITY: **140** MATERIAL UNITS: **FITTING**  
DAMAGE QUANTITY: **20** DAMAGE UNITS: **FITTING**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/28/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUILDING ID: **3800**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Harvard School** INSPECTION DATE: **8/29/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **C**  
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **1 Damaged or significantly damaged friable thermal system insulating ACBM**  
HISTORICAL DAMAGE REASON: **Deterioration Water**  
HISTORICAL RESPONSE ACTION: **Repair**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON: **Deterioration Water**  
DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Original Building**  
MATERIAL QUANTITY: **710** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **25** DAMAGE UNITS: **LF**  
COMMENTS: **Damage in Basement Switch Gear Rm., Pump Rm., Boiler Rm., Boiler Rm. Bathroom**

Inspector's Signature: \_\_\_\_\_ Date: **08/29/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUIDLING ID: **3800**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Harvard School** REVIEW DATE: **9/28/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **C**  
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**  
MATERIAL LOCATION: **Original Building**  
MATERIAL QUANTITY: **710** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **25** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/28/2019**



# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUILDING ID: **3800**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Harvard School** INSPECTION DATE: **8/29/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **CM-1**  
MATERIAL DESCRIPTION: **Carpet Mastic-NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **1959 Building- Office, Teachers Lounge; Main Building- Room 205**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not Observed Multiple Years**

Inspector's Signature: \_\_\_\_\_ Date: 08/29/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUIDLING ID: **3800**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Harvard School** REVIEW DATE: **9/28/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **CM-1**  
MATERIAL DESCRIPTION: **Carpet Mastic-NOT OBSERVED**  
MATERIAL LOCATION: **1959 Building- Office, Teachers Lounge; Main Building- Room 205**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/28/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUIDLING ID: **3800**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Harvard School** INSPECTION DATE: **8/29/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **D**  
MATERIAL DESCRIPTION: **Aircell Fittings**  
HISTORICAL AHERA DAMAGE CATEGORY **1 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Original Building**

MATERIAL QUANTITY: **132**

MATERIAL UNITS: **FITTING**

DAMAGE QUANTITY: **15**

DAMAGE UNITS: **FITTING**

COMMENTS: **Damage in Basement Switch Gear Rm., Pump Rm., Boiler Rm., Boiler Rm. Bathroom**

Inspector's Signature: \_\_\_\_\_

Date: 08/29/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUIDLING ID: **3800**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Harvard School** REVIEW DATE: **9/28/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **D**  
MATERIAL DESCRIPTION: **Aircell Fittings**  
MATERIAL LOCATION: **Original Building**  
MATERIAL QUANTITY: **132** MATERIAL UNITS: **FITTING**  
DAMAGE QUANTITY: **15** DAMAGE UNITS: **FITTING**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/28/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUIDLING ID: **3800**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Harvard School** INSPECTION DATE: **8/29/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **E**  
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **1 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Original Building**

MATERIAL QUANTITY: **850**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **20**

DAMAGE UNITS: **LF**

COMMENTS: **Damage in Basement Switch Gear Rm., Pump Rm.**

Inspector's Signature: \_\_\_\_\_

Date: 08/29/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUILDING ID: **3800**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Harvard School** REVIEW DATE: **9/28/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **E**  
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**  
MATERIAL LOCATION: **Original Building**  
MATERIAL QUANTITY: **850** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **20** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/28/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUILDING ID: **3800**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Harvard School** INSPECTION DATE: **8/29/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FT-1**  
MATERIAL DESCRIPTION: **12x12 Crème w/White Flakes Floor Tile ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **Original Building- Staircase Landing and Assistant Principal's Office**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **08/29/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUIDLING ID: **3800**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Harvard School** REVIEW DATE: **9/28/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **FT-1**  
MATERIAL DESCRIPTION: **12x12 Crème w/White Flakes Floor Tile ABATED**  
MATERIAL LOCATION: **Original Building- Staircase Landing and Assistant Principal's Office**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/28/2019**



# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUIDLING ID: **3800**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Harvard School** INSPECTION DATE: **8/29/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FT-2**  
MATERIAL DESCRIPTION: **12x12 Orange Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Original Building- Auditorium Balcony**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/29/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUIDLING ID: **3800**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Harvard School** REVIEW DATE: **9/28/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **FT-2**  
MATERIAL DESCRIPTION: **12x12 Orange Floor Tile**  
MATERIAL LOCATION: **Original Building- Auditorium Balcony**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/28/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUIDLING ID: **3800**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Harvard School** INSPECTION DATE: **8/29/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FT-3**  
MATERIAL DESCRIPTION: **9x9 Checkboard Tan & Brown Floor Tile ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1959 Building- Patches in 112, 110, 108, Assistant Principal's Office**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **08/29/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUILDING ID: **3800**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Harvard School** REVIEW DATE: **9/28/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **FT-3**  
MATERIAL DESCRIPTION: **9x9 Checkboard Tan & Brown Floor Tile ABATED**  
MATERIAL LOCATION: **1959 Building- Patches in 112, 110, 108, Assistant Principal's Office**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/28/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUILDING ID: **3800**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Harvard School** INSPECTION DATE: **8/29/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FT-4**  
MATERIAL DESCRIPTION: **12x12 Checkerboard White & Tan ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1959 Building- Teachers' Bathroom and Hallway Patch**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **08/29/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUILDING ID: **3800**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Harvard School** REVIEW DATE: **9/28/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **FT-4**  
MATERIAL DESCRIPTION: **12x12 Checkerboard White & Tan ABATED**  
MATERIAL LOCATION: **1959 Building- Teachers' Bathroom and Hallway Patch**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/28/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUIDLING ID: **3800**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Harvard School** INSPECTION DATE: **8/29/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FT-5**  
MATERIAL DESCRIPTION: **12x12 Checkerboard Tan Floor Tile-NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1959 Main building - Engineer's Office**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not Observed Multiple Years - New HA is 30**

Inspector's Signature: \_\_\_\_\_ Date: 08/29/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUIDLING ID: **3800**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Harvard School** REVIEW DATE: **9/28/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **FT-5**  
MATERIAL DESCRIPTION: **12x12 Checkerboard Tan Floor Tile-NOT OBSERVED**  
MATERIAL LOCATION: **1959 Main building - Engineer's Office**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/28/2019**



# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUILDING ID: **3800**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Harvard School** INSPECTION DATE: **8/29/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FT-6**  
MATERIAL DESCRIPTION: **12x12 Taupe Floor Tile ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Annex- Corridors; Main Building- Classrooms A & B**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **08/29/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUILDING ID: **3800**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Harvard School** REVIEW DATE: **9/28/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **FT-6**  
MATERIAL DESCRIPTION: **12x12 Taupe Floor Tile ABATED**  
MATERIAL LOCATION: **Annex- Corridors; Main Building- Classrooms A & B**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/28/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUIDLING ID: **3800**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Harvard School** INSPECTION DATE: **8/29/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FT-7**  
MATERIAL DESCRIPTION: **12x12 Maroon Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Main Building- Kitchen**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/29/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUILDING ID: **3800**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Harvard School** REVIEW DATE: **9/28/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **FT-7**  
MATERIAL DESCRIPTION: **12x12 Maroon Floor Tile**  
MATERIAL LOCATION: **Main Building- Kitchen**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/28/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUIDLING ID: **3800**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Harvard School** INSPECTION DATE: **8/29/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FT-8**  
MATERIAL DESCRIPTION: **12x12 Beige w/Cream Specks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Annex- 108 Patch; Main Building- Lunchroom**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/29/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUIDLING ID: **3800**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Harvard School** REVIEW DATE: **9/28/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **FT-8**  
MATERIAL DESCRIPTION: **12x12 Beige w/Cream Specks Floor Tile**  
MATERIAL LOCATION: **Annex- 108 Patch; Main Building- Lunchroom**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/28/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUIDLING ID: **3800**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Harvard School** INSPECTION DATE: **8/29/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FT-9**  
MATERIAL DESCRIPTION: **12x12 White w/Tan Specks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Annex- 1/2 of Room 105**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/29/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUIDLING ID: **3800**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Harvard School** REVIEW DATE: **9/28/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **FT-9**  
MATERIAL DESCRIPTION: **12x12 White w/Tan Specks Floor Tile**  
MATERIAL LOCATION: **Annex- 1/2 of Room 105**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/28/2019**



# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUIDLING ID: **3800**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Harvard School** INSPECTION DATE: **8/29/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FTM-1**  
MATERIAL DESCRIPTION: **12x12 Mastic Crème w/White Flakes Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Original Building- Staircase Landing**  
MATERIAL QUANTITY: **80** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/29/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUIDLING ID: **3800**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Harvard School** REVIEW DATE: **9/28/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **FTM-1**  
MATERIAL DESCRIPTION: **12x12 Mastic Crème w/White Flakes Floor Tile**  
MATERIAL LOCATION: **Original Building- Staircase Landing**  
MATERIAL QUANTITY: **80** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/28/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUILDING ID: **3800**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Harvard School** INSPECTION DATE: **8/29/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FTM-2**  
MATERIAL DESCRIPTION: **12x12 Orange Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Original Building- Auditorium Balcony**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/29/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUIDLING ID: **3800**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Harvard School** REVIEW DATE: **9/28/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **FTM-2**  
MATERIAL DESCRIPTION: **12x12 Orange Floor Tile Mastic**  
MATERIAL LOCATION: **Original Building- Auditorium Balcony**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/28/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUILDING ID: **3800**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Harvard School** INSPECTION DATE: **8/29/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FTM-3**  
MATERIAL DESCRIPTION: **9x9 Checkboard Tan & Brown Floor Tile Mastic ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1959 Building- Patches in 112, 110, 108**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **08/29/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUIDLING ID: **3800**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Harvard School** REVIEW DATE: **9/28/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **FTM-3**  
MATERIAL DESCRIPTION: **9x9 Checkboard Tan & Brown Floor Tile Mastic ABATED**  
MATERIAL LOCATION: **1959 Building- Patches in 112, 110, 108**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/28/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUIDLING ID: **3800**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Harvard School** INSPECTION DATE: **8/29/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FTM-4**  
MATERIAL DESCRIPTION: **12x12 Checkerboard White & Tan-ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1959 Building- Teachers' Bathroom and Hallway Patch**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/29/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUIDLING ID: **3800**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Harvard School** REVIEW DATE: **9/28/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **FTM-4**  
MATERIAL DESCRIPTION: **12x12 Checkerboard White & Tan-ABATED**  
MATERIAL LOCATION: **1959 Building- Teachers' Bathroom and Hallway Patch**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/28/2019**



# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUIDLING ID: **3800**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Harvard School** INSPECTION DATE: **8/29/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FTM-5**  
MATERIAL DESCRIPTION: **12x12 Checkerboard Tan Floor Tile Mastic-NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1959 Building- Room 105, Teachers' Lounge Washroom; Main Building- Engineer's Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed Multiple Years**

Inspector's Signature: \_\_\_\_\_ Date: 08/29/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUIDLING ID: **3800**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Harvard School** REVIEW DATE: **9/28/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **FTM-5**  
MATERIAL DESCRIPTION: **12x12 Checkerboard Tan Floor Tile Mastic-NOT OBSERVED**  
MATERIAL LOCATION: **1959 Building- Room 105, Teachers' Lounge Washroom; Main Building- Engineer's Office**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/28/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUILDING ID: **3800**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Harvard School** INSPECTION DATE: **8/29/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FTM-6**  
MATERIAL DESCRIPTION: **12x12 Taupe Floor Tile Mastic ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Annex- Corridors; Main Building- Classrooms A & B**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **08/29/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUIDLING ID: **3800**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Harvard School** REVIEW DATE: **9/28/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **FTM-6**

MATERIAL DESCRIPTION: **12x12 Taupe Floor Tile Mastic ABATED**

MATERIAL LOCATION: **Annex- Corridors; Main Building- Classrooms A & B**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/28/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUIDLING ID: **3800**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Harvard School** INSPECTION DATE: **8/29/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FTM-7**  
MATERIAL DESCRIPTION: **12x12 Maroon Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Main Building- Kitchen**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/29/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUILDING ID: **3800**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Harvard School** REVIEW DATE: **9/28/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **FTM-7**  
MATERIAL DESCRIPTION: **12x12 Maroon Floor Tile Mastic**  
MATERIAL LOCATION: **Main Building- Kitchen**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/28/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUIDLING ID: **3800**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Harvard School** INSPECTION DATE: **8/29/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FTM-8**  
MATERIAL DESCRIPTION: **12x12 Beige w/Cream Specks Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Annex- 108 Patch; Main Building- Lunchroom**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/29/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUIDLING ID: **3800**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Harvard School** REVIEW DATE: **9/28/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **FTM-8**  
MATERIAL DESCRIPTION: **12x12 Beige w/Cream Specks Floor Tile Mastic**  
MATERIAL LOCATION: **Annex- 108 Patch; Main Building- Lunchroom**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/28/2019**



# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUIDLING ID: **3800**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Harvard School** INSPECTION DATE: **8/29/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FU-1**  
MATERIAL DESCRIPTION: **12x12 Yellow VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Lunchroom A & B, Annex Corridors**  
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/29/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUIDLING ID: **3800**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Harvard School** REVIEW DATE: **9/28/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **FU-1**  
MATERIAL DESCRIPTION: **12x12 Yellow VFT**  
MATERIAL LOCATION: **Lunchroom A & B, Annex Corridors**  
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/28/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUIDLING ID: **3800**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Harvard School** INSPECTION DATE: **8/29/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FU-10**  
MATERIAL DESCRIPTION: **12x12 OrangeVFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Principal's Office**  
MATERIAL QUANTITY: **360** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/29/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUILDING ID: **3800**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Harvard School** REVIEW DATE: **9/28/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **FU-10**  
MATERIAL DESCRIPTION: **12x12 OrangeVFT Mastic**  
MATERIAL LOCATION: **Principal's Office**  
MATERIAL QUANTITY: **360** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/28/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUIDLING ID: **3800**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Harvard School** INSPECTION DATE: **8/29/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FU-11**  
MATERIAL DESCRIPTION: **12x12 Grey Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Original Building- Staircase Landing**  
MATERIAL QUANTITY: **240** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/29/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUIDLING ID: **3800**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Harvard School** REVIEW DATE: **9/28/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **FU-11**  
MATERIAL DESCRIPTION: **12x12 Grey Tile**  
MATERIAL LOCATION: **Original Building- Staircase Landing**  
MATERIAL QUANTITY: **240** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/28/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUIDLING ID: **3800**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Harvard School** INSPECTION DATE: **8/29/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FU-12**  
MATERIAL DESCRIPTION: **12x12 Grey VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Original Building- Staircase Landing**  
MATERIAL QUANTITY: **240** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/29/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUIDLING ID: **3800**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Harvard School** REVIEW DATE: **9/28/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **FU-12**  
MATERIAL DESCRIPTION: **12x12 Grey VFT Mastic**  
MATERIAL LOCATION: **Original Building- Staircase Landing**  
MATERIAL QUANTITY: **240** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/28/2019**



# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUIDLING ID: **3800**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Harvard School** INSPECTION DATE: **8/29/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FU-13**  
MATERIAL DESCRIPTION: **12x12 Brown Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1959 Building- Teacher's Lounge Washroom, Engineer's Office**  
MATERIAL QUANTITY: **350** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/29/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUIDLING ID: **3800**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Harvard School** REVIEW DATE: **9/28/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **FU-13**  
MATERIAL DESCRIPTION: **12x12 Brown Tile**  
MATERIAL LOCATION: **1959 Building- Teacher's Lounge Washroom, Engineer's Office**  
MATERIAL QUANTITY: **350** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/28/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUIDLING ID: **3800**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Harvard School** INSPECTION DATE: **8/29/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FU-14**  
MATERIAL DESCRIPTION: **12x12 Brown VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1959 Building- Teacher's Lounge Washroom, Engineer's Office**  
MATERIAL QUANTITY: **350** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/29/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUIDLING ID: **3800**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Harvard School** REVIEW DATE: **9/28/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **FU-14**  
MATERIAL DESCRIPTION: **12x12 Brown VFT Mastic**  
MATERIAL LOCATION: **1959 Building- Teacher's Lounge Washroom, Engineer's Office**  
MATERIAL QUANTITY: **350** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/28/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUIDLING ID: **3800**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Harvard School** INSPECTION DATE: **8/29/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FU-2**  
MATERIAL DESCRIPTION: **12x12 Yellow VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Lunchroom A & B, Annex Corridors**  
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/29/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUILDING ID: **3800**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Harvard School** REVIEW DATE: **9/28/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **FU-2**  
MATERIAL DESCRIPTION: **12x12 Yellow VFT Mastic**  
MATERIAL LOCATION: **Lunchroom A & B, Annex Corridors**  
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/28/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUIDLING ID: **3800**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Harvard School** INSPECTION DATE: **8/29/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FU-3**  
MATERIAL DESCRIPTION: **12x12 Orange Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Lunchroom A & B, Annex Corridors**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/29/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUIDLING ID: **3800**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Harvard School** REVIEW DATE: **9/28/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **FU-3**  
MATERIAL DESCRIPTION: **12x12 Orange Tile**  
MATERIAL LOCATION: **Lunchroom A & B, Annex Corridors**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/28/2019**



# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUIDLING ID: **3800**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Harvard School** INSPECTION DATE: **8/29/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FU-4**  
MATERIAL DESCRIPTION: **12x12 Orange Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Lunchroom A & B, Annex Corridors**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/29/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUIDLING ID: **3800**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Harvard School** REVIEW DATE: **9/28/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **FU-4**  
MATERIAL DESCRIPTION: **12x12 Orange Mastic**  
MATERIAL LOCATION: **Lunchroom A & B, Annex Corridors**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/28/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUIDLING ID: **3800**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Harvard School** INSPECTION DATE: **8/29/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FU-5**  
MATERIAL DESCRIPTION: **12x12 Blue Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1959 Building- All Rooms and Corridors on 1st & 2nd Floors**  
MATERIAL QUANTITY: **3985** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS: **15 SF Abated in Rm. 108 for cabinet replacement June 2019**

Inspector's Signature: \_\_\_\_\_ Date: 08/29/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUIDLING ID: **3800**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Harvard School** REVIEW DATE: **9/28/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **FU-5**  
MATERIAL DESCRIPTION: **12x12 Blue Tile**  
MATERIAL LOCATION: **1959 Building- All Rooms and Corridors on 1st & 2nd Floors**  
MATERIAL QUANTITY: **3985** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/28/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUIDLING ID: **3800**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Harvard School** INSPECTION DATE: **8/29/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FU-6**  
MATERIAL DESCRIPTION: **12x12 Blue Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1959 Building- All Rooms and Corridors on 1st & 2nd Floors**  
MATERIAL QUANTITY: **3985** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS: **15 SF Abated in Rm. 108 for cabinet replacement 2019**

Inspector's Signature: \_\_\_\_\_ Date: 08/29/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUIDLING ID: **3800**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Harvard School** REVIEW DATE: **9/28/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **FU-6**  
MATERIAL DESCRIPTION: **12x12 Blue Mastic**  
MATERIAL LOCATION: **1959 Building- All Rooms and Corridors on 1st & 2nd Floors**  
MATERIAL QUANTITY: **3985** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/28/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUIDLING ID: **3800**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Harvard School** INSPECTION DATE: **8/29/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FU-7**  
MATERIAL DESCRIPTION: **12x12 Yellow Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1959 Building- All Rooms and Corridors on 1st & 2nd Floors**  
MATERIAL QUANTITY: **1700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/29/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUILDING ID: **3800**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Harvard School** REVIEW DATE: **9/28/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **FU-7**  
MATERIAL DESCRIPTION: **12x12 Yellow Tile**  
MATERIAL LOCATION: **1959 Building- All Rooms and Corridors on 1st & 2nd Floors**  
MATERIAL QUANTITY: **1700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/28/2019**



# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUIDLING ID: **3800**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Harvard School** INSPECTION DATE: **8/29/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FU-8**  
MATERIAL DESCRIPTION: **12x12 Yellow VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1959 Building- 1st & 2nd Floor, All Rooms & Corridors**  
MATERIAL QUANTITY: **1700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/29/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUIDLING ID: **3800**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Harvard School** REVIEW DATE: **9/28/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **FU-8**  
MATERIAL DESCRIPTION: **12x12 Yellow VFT Mastic**  
MATERIAL LOCATION: **1959 Building- 1st & 2nd Floor, All Rooms & Corridors**  
MATERIAL QUANTITY: **1700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/28/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUIDLING ID: **3800**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Harvard School** INSPECTION DATE: **8/29/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FU-9**  
MATERIAL DESCRIPTION: **12x12 Orange Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Principal's Office**  
MATERIAL QUANTITY: **360** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/29/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUILDING ID: **3800**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Harvard School** REVIEW DATE: **9/28/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **FU-9**  
MATERIAL DESCRIPTION: **12x12 Orange Tile**  
MATERIAL LOCATION: **Principal's Office**  
MATERIAL QUANTITY: **360** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/28/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUIDLING ID: **3800**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Harvard School** INSPECTION DATE: **8/29/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **G**  
MATERIAL DESCRIPTION: **Mag Pipe Insulation ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Basement- Fan Houses Piping**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **08/29/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUIDLING ID: **3800**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Harvard School** REVIEW DATE: **9/28/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **G**

MATERIAL DESCRIPTION: **Mag Pipe Insulation ABATED**

MATERIAL LOCATION: **Basement- Fan Houses Piping**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/28/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUIDLING ID: **3800**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Harvard School** INSPECTION DATE: **8/29/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **H**  
MATERIAL DESCRIPTION: **Mag Fittings**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Basement - Fan Houses Piping**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**  
COMMENTS: **Tank Room**

Inspector's Signature: \_\_\_\_\_ Date: 08/29/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUIDLING ID: **3800**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Harvard School** REVIEW DATE: **9/28/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **H**  
MATERIAL DESCRIPTION: **Mag Fittings**  
MATERIAL LOCATION: **Basement - Fan Houses Piping**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/28/2019**



# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUIDLING ID: **3800**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Harvard School** INSPECTION DATE: **8/29/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **J**  
MATERIAL DESCRIPTION: **Mag Tank Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Tankroom**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/29/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUIDLING ID: **3800**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Harvard School** REVIEW DATE: **9/28/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **J**  
MATERIAL DESCRIPTION: **Mag Tank Insulation**  
MATERIAL LOCATION: **Tankroom**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/28/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUIDLING ID: **3800**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Harvard School** INSPECTION DATE: **8/29/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **N**  
MATERIAL DESCRIPTION: **Cementious Fittings**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1959 Addition**  
MATERIAL QUANTITY: **95** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/29/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUIDLING ID: **3800**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Harvard School** REVIEW DATE: **9/28/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **N**  
MATERIAL DESCRIPTION: **Cementious Fittings**  
MATERIAL LOCATION: **1959 Addition**  
MATERIAL QUANTITY: **95** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/28/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUIDLING ID: **3800**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Harvard School** INSPECTION DATE: **8/29/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **0**  
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1959 Addition**  
MATERIAL QUANTITY: **95** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **08/29/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUIDLING ID: **3800**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Harvard School** REVIEW DATE: **9/28/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **0**  
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**  
MATERIAL LOCATION: **1959 Addition**  
MATERIAL QUANTITY: **95** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/28/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUIDLING ID: **3800**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Harvard School** INSPECTION DATE: **8/29/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **Q**  
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1959 Addition**  
MATERIAL QUANTITY: **150** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/29/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUIDLING ID: **3800**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Harvard School** REVIEW DATE: **9/28/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **Q**  
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**  
MATERIAL LOCATION: **1959 Addition**  
MATERIAL QUANTITY: **150** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/28/2019**



# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUIDLING ID: **3800**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Harvard School** INSPECTION DATE: **8/29/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **R**  
MATERIAL DESCRIPTION: **Cardboard Fittings**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1959 Building**  
MATERIAL QUANTITY: **25** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/29/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUIDLING ID: **3800**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Harvard School** REVIEW DATE: **9/28/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **R**  
MATERIAL DESCRIPTION: **Cardboard Fittings**  
MATERIAL LOCATION: **1959 Building**  
MATERIAL QUANTITY: **25** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/28/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUILDING ID: **3800**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Harvard School** INSPECTION DATE: **8/29/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **WC-1**  
MATERIAL DESCRIPTION: **Window Caulking ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1959 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **08/29/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUILDING ID: **3800**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Harvard School** REVIEW DATE: **9/28/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **WC-1**

MATERIAL DESCRIPTION: **Window Caulking ABATED**

MATERIAL LOCATION: **1959 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/28/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUIDLING ID: **3800**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Harvard School** INSPECTION DATE: **8/29/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **WG-1**  
MATERIAL DESCRIPTION: **Window Glazing ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **1959 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **08/29/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23581** BUIDLING ID: **3800**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Harvard School** REVIEW DATE: **9/28/2019**  
ADDRESS: **7525 S. Harvard** IDPH LICENSE NO: **100-07839**

---

HOMOGENEOUS AREA: **WG-1**  
MATERIAL DESCRIPTION: **Window Glazing ABATED**  
MATERIAL LOCATION: **1959 Building**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/28/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
*2019 AHERA REINSPECTION*

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **23581**      BUILDING ID: **3800**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Harvard School**      INSPECTION DATE: **8/29/2019**  
ADDRESS: **7525 S. Harvard**      IDPH LICENSE NO: **100-07839**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **30A**  
MATERIAL DESCRIPTION: **12" X 12" Grey Floor Tile Mastic**  
MATERIAL LOCATION: **Boiler Room Bathroom**  
MATERIAL QUANTITY: **200**      MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**      FRIABLE:  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**      CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**      DAMAGE REASON:  
DAMAGE QUANTITY: **0**      DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:  
Damaged VFT in Boiler Room

Inspector's Signature: \_\_\_\_\_ Date: **08/29/2019**



# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **23581**      BUILDING ID: **3800**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Harvard School**      REVIEW DATE: **9/28/2019**  
ADDRESS: **7525 S. Harvard**      IDPH LICENSE NO: **100-07839**

HOMOGENEOUS AREA: **30A**  
MATERIAL DESCRIPTION: **12" X 12" Grey Floor Tile Mastic**  
MATERIAL LOCATION: **Boiler Room Bathroom**  
MATERIAL QUANTITY: **200**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **09/28/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **23581**      BUILDING ID: **3800**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **Lisa Laney**  
SCHOOL NAME: **Harvard School**      INSPECTION DATE: **8/29/2019**  
ADDRESS: **7525 S. Harvard**      IDPH LICENSE NO: **100-07839**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **30**  
MATERIAL DESCRIPTION: **12" X 12" Gray Floor Tile**  
MATERIAL LOCATION: **Boiler Room Bathroom**  
MATERIAL QUANTITY: **200**      MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**      FRIABLE:  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **MODERATE**      CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**      DAMAGE REASON:  
DAMAGE QUANTITY: **30**      DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **08/29/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **23581**      BUILDING ID: **3800**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Harvard School**      REVIEW DATE: **9/28/2019**  
ADDRESS: **7525 S. Harvard**      IDPH LICENSE NO: **100-07839**

HOMOGENEOUS AREA: **30**  
MATERIAL DESCRIPTION: **12" X 12" Gray Floor Tile**  
MATERIAL LOCATION: **Boiler Room Bathroom**  
MATERIAL QUANTITY: **200**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **30**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **09/28/2019**

# APPENDIX B

## Inspector and Management Planner Licenses

---

2019



**OCCUPATIONAL TRAINING & SUPPLY, INC.**

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900 ♦ www.otssafety.com

# Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

**Lisa Laney**


has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 4/5/2019

Exam Date: 4/5/2019

Expiration Date: 4/5/2020

Certificate Number: BIR1904051198



---

Kathy DeSalvo, Director

Miss Nancy

# CERTIFICATE OF ACHIEVEMENT

## ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that SHAWN L. BROWN  
has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the  
examination on 03/18/2019 with a minimum score of 70% or better. Training was in accordance  
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:  
Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.

03/18/2019

Course Dates:

03/18/2020

Expires:

1903BIR03

Certificate Number:



**PUBLIC HEALTH & SAFETY** Inc.

Environmental and Occupational Services  
37 S. Ashland Ave., Chicago, IL 60607

[www.public-health-safety.com](http://www.public-health-safety.com)

Office: 312-491-0081  
Fax: 312-421-2901

Director of Training

Nicholas J. Penelf

Doctor of Public Health

Phone: 312-491-0081

FORM # A-010B

# CERTIFICATE OF ACHIEVEMENT ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that SHAWN L. BROWN  
has completed the Asbestos Management Planner Refresher course and passed the examination  
on 03/18/2019 with a minimum score of 70% or better. Training was in accordance with U.S.  
E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools: Model  
Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.

03/18/2019

Course Dates:

03/18/2020

Expires:

1903MPR01

Certificate Number:



**PUBLIC HEALTH & SAFETY** inc.

Environmental and Occupational Services  
371 S. Ashland Ave., Chicago, IL 60607

[www.public-health-safety.com](http://www.public-health-safety.com)

Office: 312-491-0081  
Fax: 312-421-2501

Director of Training

Nicholas J. Peneff

Doctor of Public Health

Phone: 312-491-0081

FORM # A-011



# COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

	<b>ASBESTOS PROFESSIONAL LICENSE</b>	<b>ENDORSEMENTS</b>	<b>TC EXPIRES</b>
		INSPECTOR	3/19/2019
<b>ID NUMBER</b>	<b>ISSUED</b>	<b>EXPIRES</b>	
100 - 02950	3/6/2019	05/15/2020	
<b>KEITH CLOUGH</b>			
524 HOMELAND RD			
MATTESON, IL 60443			
Environmental Health			
		PROJECT MANAGER	4/9/2019
		AIR SAMPLING PROFESSIONAL	
		<b>Alteration of this license shall result in legal action</b> This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	

# APPENDIX C

## Laboratory Accreditations

---

# APPENDIX D

## Laboratory Results

---

# APPENDIX E

## Chain of Custody Forms

---

## Three-Year Reinspection Key to Terms

	<b>CODE</b>	<b>KEY</b>
<b>MATERIAL</b>		
	ACBM	Asbestos Containing Building Materials
<b>MATERIAL CATEGORY</b>		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
<b>MATERIAL UNITS</b>		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
<b>DAMAGE TYPE</b>		
	Loc	Localized
	Dist	Distributed