

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM**

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-2263
SCHOOL NAME: Herzl School
ADDRESS OF SCHOOL: 3711 W. Douglas Blvd
CITY: Chicago, IL, 60623

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED 2/22/2016

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II (Please type or print)

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 10/1/2019 ENROLLMENT 488
IDPH INSPECTOR LICENSE NUMBER: 100-09969
IDPH LICENSED INSPECTOR NAME(Please Print): Dionne Carey
IDPH MP LICENSE NUMBER: 100-19466
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Evan Christian

DESIGNATED PERSON (Please Print): Robert Christlieb PHONE: (773) 553-3197



10/1/2019

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Herzl School

3711 W. Douglas Blvd
Chicago, IL, 60623

Unit: 23771
Building ID: 3970

IDPH ID Number: 14-016-2990-2263

REPORT DATE:

Tuesday, October 01, 2019

Prepared for:

**Chicago Public Schools
42 West Madison Street
Chicago, IL 60602**

Prepared by:

Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Chicago, Il, 60607

Phone (312) 762-2900

Fax (312) 782-5145

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

April 12, 2019

Mr. Glen E. Garner
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2019 Three-Year Reinspections

Dear Mr. Glen:

Carnow, Conibear and Associates, Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 3, 4 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 23771 Region: 03 IDPH ID:14-016-2990-2263

School: Herzl School Building ID: 3970

Address: 3711 W. Douglas Blvd
Chicago, IL, 60623

Building Contact: Contact Phone:

Current Building Owners: Chicago Public Schools

Review Date: 05/03/2019

Inspector: Dionne Carey Inspector IDPH License: 100-09969
Management Planner: Evan Christian Management Planner IDPH License: 100-19466

If you have any questions or comments, please contact us at (312) 762-2900

Sincerely,
Carnow, Conibear and Associates

Evan Christian
100-19466

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: April 12, 2019

RE: Herzl School, Unit 23771
3711 W. Douglas Blvd
Chicago, IL, 60623

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2019 asbestos three year re-inspection has been completed at Herzl School, following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at Herzl School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Robert Christlieb, the designated Local Education Authority's Designated Person at (773) 553-3197 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Herzl School
Address: 3711 W. Douglas Blvd
IDPH ID: 14-016-2990-2263
Contact:

Unit: 23771
Chicago, IL, 60623
Building ID: 3970
Phone:

Region: 03

2. Description of Facility

Original Construction:
Total Square Footage:
Current Occupancy: 488

Additional Construction:
No of Floors:

3. LEA Designated Person

Contact: Robert Christlieb
Address: 42 West Madison Street
Chicago, IL 60602

Phone: (773) 553-3197

4. Managing Environmental Consultant

MEC: Carnow, Conibear and Associates
Contact: Doug McCormick
Address 600 West Van Buren St., Ste 500
Chicago, IL, 60607
Phone: (312) 762-2900

Fax: (312) 782-5145

5. Inspector

Inspector Name: Dionne Carey

Inspector IDPH license # 100-09969

Signature:
Date: 4/12/2019

6. Management Planner

Management Planner Name: Evan Christian

Management Planner IDPH license # 100-19466

Signature:
Date: 05/03/2019

7. Review Date:05/03/2019

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature:



Date: 10/1/2019

Name: Robert Christlieb

II. EXECUTIVE SUMMARY

Carnow, Conibear and Associates was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Herzl School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.85 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas(HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 3970:

60	12"x12" Light Beige w/Light Spots FT
65	12" x 12" Gray and White Mottled Floor Tile
66	12" x 12" Gray and White Mottled Floor Tile Mastic
67	2' x 2' White Fissured Ceiling Tile
68	12" x 12" Brown Floor Tile
69	12" x 12" Brown Floor Tile Mastic
D	Hard Joint Compound on Fiberglass Pipe Insulation
F	Cardboard Pipe Insulation
J	Aircell Pipe Insulation

K	Aircell Pipe Fitting
L	Fittings on Fiberglass Pipe Insulation
M	Cardboard Pipe Insulation
N	Hard Joint Compound on Cardboard Pipe Insulation
O	Preformed Pipe Insulation
P	Preformed Pipe Joint Insulation
Q	Aircell Pipe Insulation
R	Hard Joint Compound on Aircell Pipe Insulation

B. The following new homogenous areas have been identified for Building 3970:

- | | |
|----|-----------------------------------|
| 68 | 12" x 12" Brown Floor Tile |
| 69 | 12" x 12" Brown Floor Tile Mastic |

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

013	1' x 1' Acoustical Ceiling Tile
018	Vibration Isolation Cloth
019	Boiler Gaskets
020	Linoleum Mastic
026	12" x 12" White Floor Tile w/ Gray Flecks
027	12" x 12" White Floor Tile w/ Gray Flecks Mastic
039	12" x 12" Light Blue Floor Tile w/ White Specks
040	12"x12" Light Blue Floor Tile w/ White Spks Mastic
041	Vault Door Liner
042	Gray Carpet Mastic
047	Lab Table Tops
048	12" x 12" White w/Multi-Color Streaks Floor Tile
049	12" x 12" White w/Multi-Color Streaks FT Mastic
14	Chalk Boards
52	12"x12" Light Blue w/Marbling Streaks Floor Tile
54	Blue White Ceramic Floor Tile Grout
55	Blue, White Ceramic Floor Tile Adhesive
56	12"x12" Beige w/Grey Spots
57	12"x12" Light Grey w/Dark grey Spots
58	12"x12" Light Grey w/Dark grey Spots Mastic
59	Carpet Square Glue
60	12"x12" Light Beige w/Light Spots FT
61	12"x12" Light Beige w/Light Spots FT Mastic
65	12" x 12" Gray and White Mottled Floor Tile
66	12" x 12" Gray and White Mottled Floor Tile Mastic
67	2' x 2' White Fissured Ceiling Tile
68	12" x 12" Brown Floor Tile
69	12" x 12" Brown Floor Tile Mastic

The following areas were deemed to be inaccessible:

020	Linoleum Mastic
040	12"x12" Light Blue Floor Tile w/ White Spks Mastic
041	Vault Door Liner
042	Gray Carpet Mastic
55	Blue, White Ceramic Floor Tile Adhesive
58	12"x12" Light Grey w/Dark grey Spots Mastic
59	Carpet Square Glue

61	12"x12" Light Beige w/Light Spots FT Mastic
66	12" x 12" Gray and White Mottled Floor Tile Mastic
69	12" x 12" Brown Floor Tile Mastic
F	Cardboard Pipe Insulation
H	Preformed Pipe Insulation
I	Preformed Pipe Joint Insulation
L	Fittings on Fiberglass Pipe Insulation
Q	Aircell Pipe Insulation
R	Hard Joint Compound on Aircell Pipe Insulation

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Dionne Carey, IDPH License # 100-09969. The Management Plan was updated by Evan Christian, IDPH License # 100-19466. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Herzl School Building 3970 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Herzl School Unit 23771 Building ID 3970

Address 3711 W. Douglas Blvd Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
012.2	12" x 12" White Floor Tile w/Gray Specks			Rooms 310 and Kitchen	ABATED	MISC								
012.3	12" x 12" Gray Floor Tile w/ White Speckles			Room 209	ABATED	MISC								
013	1' x 1' Acoustical Ceiling Tile			Auditorium not observed 1x1" but present	ASSUMED	MISC								
014.1	9"x9" Brown/Tan Floor Tile w/Red/Brn Specks Mastic			Rooms 307	ABATED	MISC								
014.2	9"x9" Off White Floor Tile w/Bl & Brn Spks Mastic			Room 309	ABATED	MISC								
014.3	9"x9" Dark Brown & Red Floor (Checkerboard) Mastic			1st Floor Corridor, 208	ABATED	MISC		None						Low
014.4	18" x 18" Black Floor Tile Mastic			1st Floor Corridor	ABATED	MISC		None						Low
014.5	9" x 9" Green Floor Tile w/White Streaks Mastic			Room 107	ABATED	MISC		None						Low
014.6	9"x9" Gray/Tan Floor Tile Mastic			Room 212	ABATED	MISC		None						Low
015.1	12"x12" Off White Floor Tile w/Brn Streaks Mastic			Rooms 110, 111, 308, 315, and 316	ABATED	MISC								
015.2	12" x 12" White Floor Tile w/Gray Specks Mastic			Kitchen	ABATED	MISC								
015.3	12" x 12" Gray Floor Tile w/White Specks Mastic			Room 209	ABATED	MISC		None						Low
016.1	9"x9" Brn/Tan Floor Tile w/Red & Brn Specks Mastic			Room 300	ABATED	MISC								
016.2	Bottom Layer of Floor Tile Mastic			Room 300	ABATED	MISC								
016.3	9"x9" Brn/Tan Floor Tile w/Brn & Wh Specks Mastic			Room 202	ABATED	MISC		None						Low
016.4	9"x9" Off White Floor Tile w/Brn,Blk & Red Mastic			Room 203	ABATED	MISC		None						Low
017.1	12" x 12" Off White Floor Tile w/Brn Specks Mastic			Rooms 301, 304-306, 318-323	ABATED	MISC								
017.2	12"x12" Off Wh Floor Tile w/Brn & Gray Spks Mastic			Room 302	ABATED	MISC								
017.3	12"x12" Off White Floor Tile w/Blue Specks Mastic			2nd Floor North Central Office	ABATED	MISC		None						Low
017.4	12"x12" Off-White Floor Tile w/White Spkles Mastic			2nd Floor Meeting Room	ABATED	MISC		None						Low
017.5	12" x 12" Red - Brn Floor (Checkerboard) Mastic			1st Floor Corridor	ABATED	MISC		None						
017.6	18" x 18" Black Floor Tile Mastic			1st Floor Corridor	ABATED	MISC		None						Low
017.7	12"x12" Off White FloorTile w/Wh & Brn Spks Mastic			Room 101	ABATED	MISC		None						Low
018	Vibration Isolation Cloth	12	SF	1st Floor Kitchen	ASSUMED	MISC	N	NONE	0		No	ACBM with the		LOW

Chicago Public Schools

School Herzl School Unit 23771 Building ID 3970

Address 3711 W. Douglas Blvd Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
												potential for damage		
019	Boiler Gaskets	10	SF	Boiler Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
020	Linoleum Mastic	200	SF	3rd Floor Janitor's Closet and 3rd Floor Storage Closet (no access)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
021	Incinerator Fire Brick			Boiler Room	NO_ACBM	MISC								
022	Building Brick - Not AHERA			Exterior of 1914 Building	NO_ACBM	MISC								
023	Brick Mortar -Not AHERA			Exterior of 1914 Building	NO_ACBM	MISC								
024	Building Brick - Not AHERA			Exterior of 1921 Building	NO_ACBM	MISC								
025	Brick Mortar - Not AHERA			Exterior of 1921 Building	NO_ACBM	MISC								
026	12" x 12" White Floor Tile w/ Gray Flecks			Room 324	ASSUMED	MISC								
027	12" x 12" White Floor Tile w/ Gray Flecks Mastic			Room 324 (not observed)	ASSUMED	MISC								
028	4" Gray Vinyl Baseboard			Room 324	NO_ACBM	MISC								
029	4" Gray Vinyl Baseboard Mastic			Room 324	NO_ACBM	MISC								
030	12" x 12" Beige Floor Tile w/ White Flecks			Room 224 and Speech Asst. Room	ABATED	MISC								
031	12" x 12" Beige Floor Tile w/ White Flecks Mastic			Room 224 and Speech Asst. Room	ABATED	MISC		None						Low
032	4" Brown Vinyl Baseboard			Room 224 and Speech Asst. Room	NO_ACBM	MISC								
033	4" Brown Vinyl Baseboard Mastic			Room 224 and Speech Asst. Room	NO_ACBM	MISC								
034	Ceramic Wall Tile Adhesive			Room 224 Washrooms and 324 Washrooms	NO_ACBM	MISC								
035	4" Black Vinyl Baseboard			Auditorium	NO_ACBM	MISC								
036	4" Black Vinyl Baseboard Mastic			Auditorium	NO_ACBM	MISC								
037	9" x 9" Lt. Brown Floor Tile w/Dk Brn Streaks			Room 120	ABATED	MISC		None						Low
038	9"x9" Lt. Brown Floor Tile w/Dk Brn Streaks Mastic			Room 120	ABATED	MISC		None						Low
039	12" x 12" Light Blue Floor Tile w/ White Specks	1,500	SF	Auditorium	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
040	12"x12" Light Blue Floor Tile w/ White Spks Mastic	1,500	SF	Auditorium	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
041	Vault Door Liner	32	SF	Third Floor Across From 310 (no	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Herzl School Unit 23771 Building ID 3970

Address 3711 W. Douglas Blvd Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				access)										
042	Gray Carpet Mastic	672	SF	Auditorium	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
043	12" x 12" Blue Mix Floor Tile			Room 128 and Office by 118	ABATED	MISC								
044	12" x 12" Blue Mix Floor Tile Mastic			Room 128 and Office by 118	ABATED	MISC		None						Low
045	12" x 12" Blue/White Checkerboard Floor Tile			Main Office	ABATED	MISC		None						Low
046	12"x12" Blue/White Checkerboard Floor Tile Mastic			Main Office	ABATED	MISC		None						Low
047	Lab Table Tops	80	SF	Room 322, 303, 320 (not observed in 322)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
048	12" x 12" White w/Multi-Color Streaks Floor Tile	837	SF	Rooms 303 and 317	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
049	12" x 12" White w/Multi-Color Streaks FT Mastic	837	SF	Rooms 303 and 317	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
050	12" x 12" White w/Colored Streaks Floor Tile			1st Floor North Vestibules	ABATED	MISC		None						Low
051	12" x 12" White w/Colored Streaks FT Mastic			1st Floor North Vestibules	ABATED	MISC		None						Low
14	Chalk Boards	3,645	SF	Rooms 301-310,102,104-110,201-210 (not observed)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
52	12"x12" Light Blue w/Marbling Streaks Floor Tile			Room 317 (not observed)	ASSUMED	MISC								
53	12"x12" Lt Blue w/Marbling Strks Floor Tile Mastic			Room 317	ABATED	MISC								
54	Blue White Ceramic Floor Tile Grout	5,400	SF	1st, 2nd, 3rd, Floor-Boys/Girls Wash Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
55	Blue, White Ceramic Floor Tile Adhesive	5,400	SF	1st, 2nd, 3rd, Floors-Boys/Girls Wash Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
56	12"x12" Beige w/Grey Spots	350	SF	Room 119	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
57	12"x12" Light Grey w/Dark grey Spots	10,000	SF	1st Floor Hallways	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
58	12"x12" Light Grey w/Dark grey Spots Mastic	10,000	SF	1st Floor Hallways	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
59	Carpet Square Glue	1,500	SF	Main Offices	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Herzl School Unit 23771 Building ID 3970

Address 3711 W. Douglas Blvd Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
60	12"x12" Light Beige w/Light Spots FT	32,000	SF	1st and 2nd Floor Classrooms	ASSUMED	MISC	N	LOC	3		Yes	ACBM with the potential for damage	5	HIGH
61	12"x12" Light Beige w/Light Spots FT Mastic	32,000	SF	1st and 2nd Floor Classrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
62	Brown Flooring Under Wood Floor			3rd Floor Gymnasium	NO_ACBM	MISC								
63	Paper Under Wood Underlayment			Rooms 108, 109, 110, 114, 118, 123, 207, 210, 211, 212, and 2nd Floor Offices (not observed)	NO_ACBM	MISC								
64	Paper Under Wood Underlayment			Rooms 107, 116, 204, 205, 208, 209, and 244 (not observed)	CHR	MISC								
65	12" x 12" Gray and White Mottled Floor Tile	20,000	SF	Classrooms Throughout 3rd Floor	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
66	12" x 12" Gray and White Mottled Floor Tile Mastic	20,000	SF	Classrooms Throughout 3rd Floor	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
67	2' x 2' White Fissured Ceiling Tile	1,750	SF	Room 124, Auditorium	ASSUMED	MISC	Y	NONE	0		Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
68	12" x 12" Brown Floor Tile	120	SF	Engineers Office	ASSUMED	MISC	N	LOC	120		Yes	ACBM with the potential for damage	5	MODERATE
69	12" x 12" Brown Floor Tile Mastic	120	SF	Engineer's office	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
A	Fiberglass Insulation on Boiler			Boiler Room	NO_ACBM	MISC								
B	Fiberglass Tank Insulation			Pump Room	NO_ACBM	MISC								
C	Fiberglass Pipe Insulation			Throughout Facility	NO_ACBM	MISC								
D	Hard Joint Compound on Fiberglass Pipe Insulation	15	LF	Throughout 1914 Facility including Kitchen & Pipe Chases	CHR	TSI	Y	NONE	5		Yes	Any remaining friable ACBM or friable suspect ACBM	5	HIGH
E	Water Meter Packing - Abated			Basement	ABATED	TSI		None						
F	Cardboard Pipe Insulation	1,500	LF	Above 1st Floor ceiling (not observed)	CHR	TSI	Y	LOC	30		Yes	Damaged or significantly damaged friable thermal system insulating ACBM	3	LOW
G	Hard Joint Compound on Cardboard Pipe Insulation	150	EA	Above 1st Floor Ceiling (not observed)	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Herzl School Unit 23771 Building ID 3970

Address 3711 W. Douglas Blvd Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
H	Preformed Pipe Insulation	100	LF	Tunnel	AMO_CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
I	Preformed Pipe Joint Insulation	25	SF	Tunnel	AMO_CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
J	Aircell Pipe Insulation	500	LF	Throughout 1914 Facility	CHR	TSI	Y	NONE	0		Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
K	Aircell Pipe Fitting	50	EA	Throughout 1914 Facility	AMO_CHR	TSI	Y	NONE	0		Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
L	Fittings on Fiberglass Pipe Insulation	100	SF	Throughout 1921 Facility	CHR	TSI	Y	NONE	0		Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
M	Cardboard Pipe Insulation	300	LF	1st Floor	CHR	TSI	Y	LOC	5		Yes	Damaged or significantly damaged friable thermal system insulating ACBM	5	LOW
N	Hard Joint Compound on Cardboard Pipe Insulation	30	SF	1st Floor	CHR	TSI	Y	NONE	0		Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
O	Preformed Pipe Insulation	5	LF	1st Floor	AMO_CHR	TSI	Y	NONE	0		Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
P	Preformed Pipe Joint Insulation	10	LF	1st Floor	AMO_CHR	TSI	Y	NONE	0		Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
Q	Aircell Pipe Insulation	100	LF	Throughout 1921 Facility	CHR	TSI	Y	LOC	20		Yes	Damaged or significantly damaged friable thermal system insulating ACBM	5	LOW
R	Hard Joint Compound on Aircell Pipe Insulation	25	SF	Throughout 1921 Facility & Tunnel	CHR	TSI	Y	LOC	6		Yes	Damaged or significantly damaged friable thermal system insulating ACBM	5	LOW

Chicago Public Schools

School Herzl School Unit 23771 Building ID 3970

Address 3711 W. Douglas Blvd Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

Reinspection Date 4/12/2019
Inspector Name Dionne Carey
100-09969 5/15/2020
Inspector's IDPH License Number / Expiration Date

Inspector's Comments

HA Number:	Inspector Comments:
001	
002	
003	
004	
005.1	
005.2	Abated 2016
005.3	Not observed 2019
005.4	
006.1	
006.2	
006.3	
006.4	
006.5	
006.6	
006.7	
008	
009	
010	
011.1	
011.2	
011.3	
011.4	
011.5	

Chicago Public Schools

School Herzl School Unit 23771 Building ID 3970

Address 3711 W. Douglas Blvd Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
011.6	
012.1	
012.2	
012.3	
013	2x2' CT mismeasured
014.1	
014.2	
014.3	
014.4	
014.5	
014.6	
015.1	
015.2	
015.3	
016.1	
016.2	
016.3	
016.4	
017.1	
017.2	
017.3	
017.4	
017.5	
017.6	
017.7	
018	
019	
020	No access
021	

Chicago Public Schools

School Herzl School Unit 23771 Building ID 3970

Address 3711 W. Douglas Blvd Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
022	
023	
024	
025	
026	Not observed 2016 - same
027	Not observed 2016 - same
028	
029	
030	
031	
032	
033	
034	
035	
036	
037	
038	
039	
040	
041	
042	
043	
044	
045	
046	
047	
048	
049	
050	

Chicago Public Schools

School Herzl School Unit 23771 Building ID 3970

Address 3711 W. Douglas Blvd Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
051	
14	
52	Not observed 2016 - Removed/Abated - same
53	
54	
55	
56	
57	
58	
59	
60	
61	
62	
63	
64	Not observed - Abated - same
65	
66	
67	
68	12x12" Tan VFT engineer's office 120 sf
69	
A	
B	
C	
D	Not observed in kitchen
E	
F	Not observed in basement - Abated
G	Basement Abated - same
H	Basement Abated - same
I	Basement Abated - same

Chicago Public Schools

School Herzl School Unit 23771 Building ID 3970

Address 3711 W. Douglas Blvd Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
J	
K	
L	
M	
N	
O	
P	
Q	
R	

Table II

Management Planner's Review

Chicago Public Schools

School Herzl School
Address 3711 W. Douglas Blvd

Unit 23771
Chicago, IL, 60623

Building ID 3970
Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
001	Hardcoat Plaster			Throughout 1914 Building	No ACBM	SURFACE					
002	2' x 4' Lay In Ceiling Panels			Rooms 322 & 323	No ACBM	MISC					
003	1' x 1' Ceiling Tile			Rooms 302 and 303	No ACBM	MISC					
004	Blown In Insulation			Attic	No ACBM	TSI					
005.1	9" x 9" Brn/Tan Floor Tile w/Red & Brn Specks			Room 300, Office	Abated	MISC					
005.2	Bottom Layer of Floor Tile			Room 300	Abated	MISC					
005.3	9"x 9" Brown/Tan Floor Tile w/Brown & White Specks			Room 202	Abated	MISC					
005.4	9"x9" Off White Floor Tile w/Blk,Brn & Red Streaks			Room 203	Abated	MISC					
006.1	12" x 12" Off White Floor Tile w/Brn Specks Mastic			Rooms 301, 304-306, 318-323	Abated	MISC					
006.2	12" x 12" Off-White Floor Tile w/Brn & Gray Specks			Rooms 302	Abated	MISC					
006.3	12" x 12" Off White Floor Tile w/Blue Specks			2nd Floor North Central Office	Abated	MISC					
006.4	12" x 12" Off-White Floor Tile w/White Speckles			2nd Floor Meeting Room	Abated	MISC					
006.5	12" x 12" Red/Brown Floor Tile w/White Specks			1st Floor Corridor	Abated	MISC					
006.6	18" x 18" Black Floor Tile			1st Floor Corridor	Abated	MISC					
006.7	12" x 12" Off White FloorTile w/Wh & Brn Specks			Room 101	Abated	MISC					
008	Linoleum			3rd Floor Janitor's Closet, Storage Closet 3rd Floor.	No ACBM	MISC					
009	2' x 4' Ceiling Tile (Tectum)			1st Floor Auditorium (323)	No ACBM	MISC					
010	Hardcoat Plaster			Throughout 1921 Building	No ACBM	SURFACE					
011.1	9" x 9" Brown/Tan Floor Tile w/Red/Brn Speckles			Room 307	Abated	MISC					
011.2	9" x 9" Off White Floor Tile w/ Blue & Brn Specks			Room 309	Abated	MISC					
011.3	9"x9" Dark Brown and Red Floor Tile (Checkerboard)			1st Floor Corridor & 208	Abated	MISC					
011.4	18" x 18" Black Floor Tile			1st Floor Corridor	Abated	MISC					
011.5	9" x 9" Green Floor Tile w/White Streaks			Room 107	Abated	MISC					
011.6	9"x9" Gray/Tan Floor Tile			212	Abated	MISC					
012.1	12" x 12" Off White Floor Tile w/ Brown Specks			Rooms 110,111	Abated	MISC					
012.2	12" x 12" White Floor Tile w/Gray Specks			Rooms 310 and Kitchen	Abated	MISC					
012.3	12" x 12" Gray Floor Tile w/ White Speckles			Room 209	Abated	MISC					
013	1' x 1' Acoustical Ceiling Tile			Auditorium not observed 1x1" but	Assumed	MISC					

Chicago Public Schools

School Herzl School
Address 3711 W. Douglas Blvd

Unit 23771
Chicago, IL, 60623

Building ID 3970
Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				present							
014.1	9"x9" Brown/Tan Floor Tile w/Red/Brn Specks Mastic			Rooms 307	Abated	MISC					
014.2	9"x9" Off White Floor Tile w/BI & Brn Spks Mastic			Room 309	Abated	MISC					
014.3	9"x9" Dark Brown & Red Floor (Checkerboard) Mastic			1st Floor Corridor, 208	Abated	MISC					
014.4	18" x 18" Black Floor Tile Mastic			1st Floor Corridor	Abated	MISC					
014.5	9" x 9" Green Floor Tile w/White Streaks Mastic			Room 107	Abated	MISC					
014.6	9"x9" Gray/Tan Floor Tile Mastic			Room 212	Abated	MISC					
015.1	12"x12" Off White Floor Tile w/Brn Streaks Mastic			Rooms 110, 111, 308, 315, and 316	Abated	MISC					
015.2	12" x 12" White Floor Tile w/Gray Specks Mastic			Kitchen	Abated	MISC					
015.3	12" x 12" Gray Floor Tile w/White Specks Mastic			Room 209	Abated	MISC					
016.1	9"x9" Brn/Tan Floor Tile w/Red & Brn Specks Mastic			Room 300	Abated	MISC					
016.2	Bottom Layer of Floor Tile Mastic			Room 300	Abated	MISC					
016.3	9"x9" Brn/Tan Floor Tile w/Brn & Wh Specks Mastic			Room 202	Abated	MISC					
016.4	9"x9" Off White Floor Tile w/Brn,Blk & Red Mastic			Room 203	Abated	MISC					
017.1	12" x 12" Off White Floor Tile w/Brn Specks Mastic			Rooms301, 304-306, 318-323	Abated	MISC					
017.2	12"x12" Off Wh Floor Tile w/Brn & Gray Spks Mastic			Room 302	Abated	MISC					
017.3	12"x12" Off White Floor Tile w/Blue Specks Mastic			2nd Floor North Central Office	Abated	MISC					
017.4	12"x12" Off-White Floor Tile w/White Spkles Mastic			2nd Floor Meeting Room	Abated	MISC					
017.5	12" x 12" Red -Brn Floor (Checkerboard) Mastic			1st Floor Corridor	Abated	MISC					
017.6	18" x 18" Black Floor Tile Mastic			1st Floor Corridor	Abated	MISC					
017.7	12"x12" Off White FloorTile w/Wh & Brn Spks Mastic			Room 101	Abated	MISC					
018	Vibration Isolation Cloth	12	SF	1st Floor Kitchen	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
019	Boiler Gaskets	10	SF	Boiler Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
020	Linoleum Mastic	200	SF	3rd Floor Janitor's Closet and 3rd Floor Storage Closet (no access)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Herzl School
Address 3711 W. Douglas Blvd

Unit 23771
Chicago, IL, 60623

Building ID 3970
Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
021	Incinerator Fire Brick			Boiler Room	No ACBM	MISC					
022	Building Brick - Not AHERA			Exterior of 1914 Building	No ACBM	MISC					
023	Brick Mortar -Not AHERA			Exterior of 1914 Building	No ACBM	MISC					
024	Building Brick - Not AHERA			Exterior of 1921 Building	No ACBM	MISC					
025	Brick Mortar - Not AHERA			Exterior of 1921 Building	No ACBM	MISC					
026	12" x 12" White Floor Tile w/ Gray Flecks			Room 324	Assumed	MISC					
027	12" x 12" White Floor Tile w/ Gray Flecks Mastic			Room 324 (not observed)	Assumed	MISC					
028	4" Gray Vinyl Baseboard			Room 324	No ACBM	MISC					
029	4" Gray Vinyl Baseboard Mastic			Room 324	No ACBM	MISC					
030	12" x 12" Beige Floor Tile w/ White Flecks			Room 224 and Speech Asst. Room	Abated	MISC					
031	12" x 12" Beige Floor Tile w/ White Flecks Mastic			Room 224 and Speech Asst. Room	Abated	MISC					
032	4" Brown Vinyl Baseboard			Room 224 and Speech Asst. Room	No ACBM	MISC					
033	4" Brown Vinyl Baseboard Mastic			Room 224 and Speech Asst. Room	No ACBM	MISC					
034	Ceramic Wall Tile Adhesive			Room 224 Washrooms and 324 Washrooms	No ACBM	MISC					
035	4" Black Vinyl Baseboard			Auditorium	No ACBM	MISC					
036	4" Black Vinyl Baseboard Mastic			Auditorium	No ACBM	MISC					
037	9" x 9" Lt. Brown Floor Tile w/Dk Brn Streaks			Room 120	Abated	MISC					
038	9"x9" Lt. Brown Floor Tile w/Dk Brn Streaks Mastic			Room 120	Abated	MISC					
039	12" x 12" Light Blue Floor Tile w/ White Specks	1,500	SF	Auditorium	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
040	12"x12" Light Blue Floor Tile w/ White Spks Mastic	1,500	SF	Auditorium	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
041	Vault Door Liner	32	SF	Third Floor Across From 310 (no access)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
042	Gray Carpet Mastic	672	SF	Auditorium	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
043	12" x 12" Blue Mix Floor Tile			Room 128 and Office by 118	Abated	MISC					
044	12" x 12" Blue Mix Floor Tile Mastic			Room 128 and Office by 118	Abated	MISC					
045	12" x 12" Blue/White Checkerboard Floor Tile			Main Office	Abated	MISC					
046	12"x12" Blue/White Checkerboard Floor Tile Mastic			Main Office	Abated	MISC					
047	Lab Table Tops	80	SF	Room 322, 303, 320 (not observed in 322)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
048	12" x 12" White w/Multi-Color Streaks Floor Tile	837	SF	Rooms 303 and 317	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Herzl School
Address 3711 W. Douglas Blvd

Unit 23771
Chicago, IL, 60623

Building ID 3970
Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
049	12" x 12" White w/Multi-Color Streaks FT Mastic	837	SF	Rooms 303 and 317	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
050	12" x 12" White w/Colored Streaks Floor Tile			1st Floor North Vestibules	Abated	MISC					
051	12" x 12" White w/Colored Streaks FT Mastic			1st Floor North Vestibules	Abated	MISC					
14	Chalk Boards	3,645	SF	Rooms 301-310,102,104-110,201-210 (not observed)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
52	12"x12" Light Blue w/Marbling Streaks Floor Tile			Room 317 (not observed)	Assumed	MISC					
53	12"x12" Lt Blue w/Marbling Strks Floor Tile Mastic			Room 317	Abated	MISC					
54	Blue White Ceramic Floor Tile Grout	5,400	SF	1st, 2nd, 3rd, Floor-Boys/Girls Wash Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
55	Blue, White Ceramic Floor Tile Adhesive	5,400	SF	1st, 2nd, 3rd, Floors-Boys/Girls Wash Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
56	12"x12" Beige w/Grey Spots	350	SF	Room 119	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
57	12"x12" Light Grey w/Dark grey Spots	10,000	SF	1st Floor Hallways	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
58	12"x12" Light Grey w/Dark grey Spots Mastic	10,000	SF	1st Floor Hallways	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
59	Carpet Square Glue	1,500	SF	Main Offices	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
60	12"x12" Light Beige w/Light Spots FT	32,000	SF	1st and 2nd Floor Classrooms	Assumed	MISC	No	3	SF	6 ACBM with the potential for damage	Follow O&M Plan
61	12"x12" Light Beige w/Light Spots FT Mastic	32,000	SF	1st and 2nd Floor Classrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
62	Brown Flooring Under Wood Floor			3rd Floor Gymnasium	No ACBM	MISC					
63	Paper Under Wood Underlayment			Rooms 108, 109, 110, 114, 118, 123, 207, 210, 211, 212, and 2nd Floor Offices (not observed)	No ACBM	MISC					
64	Paper Under Wood Underlayment			Rooms 107, 116, 204, 205, 208, 209, and 244 (not observed)	Chrysotile	MISC					
65	12" x 12" Gray and White Mottled Floor Tile	20,000	SF	Classrooms Throughout 3rd Floor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
66	12" x 12" Gray and White Mottled Floor Tile Mastic	20,000	SF	Classrooms Throughout 3rd Floor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
67	2' x 2' White Fissured Ceiling Tile	1,750	SF	Room 124, Auditorium	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
68	12" x 12" Brown Floor Tile	120	SF	Engineers Office	Assumed	MISC	No	120	SF	6 ACBM with the potential for damage	Remove
69	12" x 12" Brown Floor Tile Mastic	120	SF	Engineer's office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Remove
A	Fiberglass Insulation on Boiler			Boiler Room	No ACBM	MISC					
B	Fiberglass Tank Insulation			Pump Room	No ACBM	MISC					
C	Fiberglass Pipe Insulation			Throughout Facility	No ACBM	MISC					
D	Hard Joint Compound on Fiberglass Pipe	15	LF	Throughout 1914 Facility including	Chrysotile	TSI	Yes	5	LF	7 Any remaining friable ACBM or friable	Repair

Chicago Public Schools

School Herzl School
Address 3711 W. Douglas Blvd

Unit 23771
Chicago, IL, 60623

Building ID 3970
Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
	Insulation			Kitchen & Pipe Chases						suspect ACBM	
E	Water Meter Packing - Abated			Basement	Abated	TSI					
F	Cardboard Pipe Insulation	1,500	LF	Above 1st Floor ceiling (not observed)	Chrysotile	TSI	Yes	30	LF	1 Damaged or significantly damaged friable thermal system insulating ACBM	Repair
G	Hard Joint Compound on Cardboard Pipe Insulation	150	EA	Above 1st Floor Ceiling (not observed)	Chrysotile	TSI	Yes	0	EA	6 ACBM with the potential for damage	Follow O&M Plan
H	Preformed Pipe Insulation	100	LF	Tunnel	Amosite, Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
I	Preformed Pipe Joint Insulation	25	SF	Tunnel	Amosite, Chrysotile	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
J	Aircell Pipe Insulation	500	LF	Throughout 1914 Facility	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
K	Aircell Pipe Fitting	50	EA	Throughout 1914 Facility	Amosite, Chrysotile	TSI	Yes	0	EA	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
L	Fittings on Fiberglass Pipe Insulation	100	SF	Throughout 1921 Facility	Chrysotile	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
M	Cardboard Pipe Insulation	300	LF	1st Floor	Chrysotile	TSI	Yes	5	LF	1 Damaged or significantly damaged friable thermal system insulating ACBM	Repair
N	Hard Joint Compound on Cardboard Pipe Insulation	30	SF	1st Floor	Chrysotile	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Repair
O	Preformed Pipe Insulation	5	LF	1st Floor	Amosite, Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
P	Preformed Pipe Joint Insulation	10	LF	1st Floor	Amosite, Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
Q	Aircell Pipe Insulation	100	LF	Throughout 1921 Facility	Chrysotile	TSI	Yes	20	LF	1 Damaged or significantly damaged friable thermal system insulating ACBM	Repair
R	Hard Joint Compound on Aircell Pipe Insulation	25	SF	Throughout 1921 Facility & Tunnel	Chrysotile	TSI	Yes	6	SF	1 Damaged or significantly damaged friable thermal system insulating ACBM	Repair

Chicago Public Schools

School Herzl School
Address 3711 W. Douglas Blvd

Unit 23771
 Chicago, IL, 60623

Building ID 3970
Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

Review Date	05/03/2019
Manager Planner Name	Evan Christian
100-19466	5/15/2020
Manager IDPH License No/Expiration	

HA Number	Management Comments
001	
002	
003	
004	
005.1	
005.2	
005.3	
005.4	
006.1	
006.2	

Chicago Public Schools

School Herzl School
Address 3711 W. Douglas Blvd

Unit 23771
 Chicago, IL, 60623

Building ID 3970
Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
006.3	
006.4	
006.5	
006.6	
006.7	
008	
009	
010	
011.1	
011.2	
011.3	
011.4	
011.5	
011.6	
012.1	
012.2	
012.3	
013	
014.1	
014.2	
014.3	
014.4	
014.5	
014.6	
015.1	
015.2	

Chicago Public Schools

School Herzl School
Address 3711 W. Douglas Blvd

Unit 23771
Chicago, IL, 60623

Building ID 3970
Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
015.3	
016.1	
016.2	
016.3	
016.4	
017.1	
017.2	
017.3	
017.4	
017.5	
017.6	
017.7	
018	
019	
020	
021	
022	
023	
024	
025	
026	
027	
028	
029	
030	
031	

Chicago Public Schools

School Herzl School
Address 3711 W. Douglas Blvd

Unit 23771
Chicago, IL, 60623

Building ID 3970
Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
032	
033	
034	
035	
036	
037	
038	
039	
040	
041	
042	
043	
044	
045	
046	
047	
048	
049	
050	
051	
14	
52	
53	
54	
55	
56	

Chicago Public Schools

School Herzl School
Address 3711 W. Douglas Blvd

Unit 23771
 Chicago, IL, 60623

Building ID 3970
Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
57	
58	
59	
60	
61	
62	
63	
64	
65	
66	
67	
68	Sample the damaged floor tile and associated mastic if positive for acbm remove and replace damaged floor tile and associated mastic
69	See HA 68
A	
B	
C	
D	Repair and/or remove
E	
F	Repair and/or remove damaged cardboard pipe insulation and continue O & M
G	
H	
I	
J	
K	
L	

Chicago Public Schools

School Herzl School
Address 3711 W. Douglas Blvd

Unit 23771
Chicago, IL, 60623

Building ID 3970
Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
M	Repair and/or remove damaged cardboard pipe insulation and continue O & M
N	See HA M
O	
P	
Q	Repair and/or remove damaged aircell pipe insulation and continue O & M
R	See HA Q

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUILDING ID: **3970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Herzl School** INSPECTION DATE: **4/12/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **001**
MATERIAL DESCRIPTION: **Hardcoat Plaster**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout 1914 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/12/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Herzl School** REVIEW DATE: **5/3/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **001**

MATERIAL DESCRIPTION: **Hardcoat Plaster**

MATERIAL LOCATION: **Throughout 1914 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Herzl School** INSPECTION DATE: **4/12/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **002**
MATERIAL DESCRIPTION: **2' x 4' Lay In Ceiling Panels**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 322 & 323**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/12/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Herzl School** REVIEW DATE: **5/3/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **002**

MATERIAL DESCRIPTION: **2' x 4' Lay In Ceiling Panels**

MATERIAL LOCATION: **Rooms 322 & 323**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Herzl School** INSPECTION DATE: **4/12/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **003**
MATERIAL DESCRIPTION: **1' x 1' Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 302 and 303**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/12/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Herzl School** REVIEW DATE: **5/3/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **003**
MATERIAL DESCRIPTION: **1' x 1' Ceiling Tile**
MATERIAL LOCATION: **Rooms 302 and 303**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Herzl School** INSPECTION DATE: **4/12/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **004**
MATERIAL DESCRIPTION: **Blown In Insulation**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Attic**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/12/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Herzl School** REVIEW DATE: **5/3/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **004**

MATERIAL DESCRIPTION: **Blown In Insulation**

MATERIAL LOCATION: **Attic**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Herzl School** INSPECTION DATE: **4/12/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **005.1**
MATERIAL DESCRIPTION: **9" x 9" Brn/Tan Floor Tile w/Red & Brn Specks**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 300, Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____

Date: **04/12/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Herzl School** REVIEW DATE: **5/3/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **005.1**

MATERIAL DESCRIPTION: **9" x 9" Brn/Tan Floor Tile w/Red & Brn Specks**

MATERIAL LOCATION: **Room 300, Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Herzl School** INSPECTION DATE: **4/12/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **005.2**
MATERIAL DESCRIPTION: **Bottom Layer of Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 300**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Abated 2016**

Inspector's Signature: _____ Date: **04/12/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Herzl School** REVIEW DATE: **5/3/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **005.2**

MATERIAL DESCRIPTION: **Bottom Layer of Floor Tile**

MATERIAL LOCATION: **Room 300**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Herzl School** INSPECTION DATE: **4/12/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **005.3**
MATERIAL DESCRIPTION: **9"x 9" Brown/Tan Floor Tile w/Brown & White Specks**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **Room 202**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2019**

Inspector's Signature: _____

Date: **04/12/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Herzl School** REVIEW DATE: **5/3/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **005.3**

MATERIAL DESCRIPTION: **9"x 9" Brown/Tan Floor Tile w/Brown & White Specks**

MATERIAL LOCATION: **Room 202**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUILDING ID: **3970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Herzl School** INSPECTION DATE: **4/12/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **005.4**
MATERIAL DESCRIPTION: **9"x9" Off White Floor Tile w/Blk,Brn & Red Streaks**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **Room 203**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/12/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Herzl School** REVIEW DATE: **5/3/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **005.4**

MATERIAL DESCRIPTION: **9"x9" Off White Floor Tile w/Blk,Brn & Red Streaks**

MATERIAL LOCATION: **Room 203**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Herzl School** INSPECTION DATE: **4/12/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **006.1**
MATERIAL DESCRIPTION: **12" x 12" Off White Floor Tile w/Brn Specks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 301, 304-306, 318-323**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/12/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Herzl School** REVIEW DATE: **5/3/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **006.1**

MATERIAL DESCRIPTION: **12" x 12" Off White Floor Tile w/Brn Specks Mastic**

MATERIAL LOCATION: **Rooms 301, 304-306, 318-323**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Herzl School** INSPECTION DATE: **4/12/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **006.2**
MATERIAL DESCRIPTION: **12" x 12" Off-White Floor Tile w/Brn & Gray Specks**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 302**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/12/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Herzl School** REVIEW DATE: **5/3/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **006.2**

MATERIAL DESCRIPTION: **12" x 12" Off-White Floor Tile w/Brn & Gray Specks**

MATERIAL LOCATION: **Rooms 302**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Herzl School** INSPECTION DATE: **4/12/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **006.3**
MATERIAL DESCRIPTION: **12" x 12" Off White Floor Tile w/Blue Specks**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **2nd Floor North Central Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____

Date: **04/12/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Herzl School** REVIEW DATE: **5/3/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **006.3**

MATERIAL DESCRIPTION: **12" x 12" Off White Floor Tile w/Blue Specks**

MATERIAL LOCATION: **2nd Floor North Central Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Herzl School** INSPECTION DATE: **4/12/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **006.4**
MATERIAL DESCRIPTION: **12" x 12" Off-White Floor Tile w/White Speckles**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **2nd Floor Meeting Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/12/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Herzl School** REVIEW DATE: **5/3/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **006.4**

MATERIAL DESCRIPTION: **12" x 12" Off-White Floor Tile w/White Speckles**

MATERIAL LOCATION: **2nd Floor Meeting Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Herzl School** INSPECTION DATE: **4/12/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **006.5**
MATERIAL DESCRIPTION: **12" x 12" Red/Brown Floor Tile w/White Specks**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **1st Floor Corridor**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/12/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Herzl School** REVIEW DATE: **5/3/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **006.5**

MATERIAL DESCRIPTION: **12" x 12" Red/Brown Floor Tile w/White Specks**

MATERIAL LOCATION: **1st Floor Corridor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Herzl School** INSPECTION DATE: **4/12/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **006.6**
MATERIAL DESCRIPTION: **18" x 18" Black Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **1st Floor Corridor**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/12/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Herzl School** REVIEW DATE: **5/3/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **006.6**

MATERIAL DESCRIPTION: **18" x 18" Black Floor Tile**

MATERIAL LOCATION: **1st Floor Corridor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Herzl School** INSPECTION DATE: **4/12/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **006.7**
MATERIAL DESCRIPTION: **12" x 12" Off White FloorTile w/Wh & Brn Specks**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 101**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/12/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Herzl School** REVIEW DATE: **5/3/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **006.7**

MATERIAL DESCRIPTION: **12" x 12" Off White FloorTile w/Wh & Brn Specks**

MATERIAL LOCATION: **Room 101**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Herzl School** INSPECTION DATE: **4/12/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **008**
MATERIAL DESCRIPTION: **Linoleum**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **3rd Floor Janitor's Closet, Storage Closet 3rd Floor.**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/12/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Herzl School** REVIEW DATE: **5/3/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **008**
MATERIAL DESCRIPTION: **Linoleum**
MATERIAL LOCATION: **3rd Floor Janitor's Closet, Storage Closet 3rd Floor.**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Herzl School** INSPECTION DATE: **4/12/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **009**
MATERIAL DESCRIPTION: **2' x 4' Ceiling Tile (Tectum)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st Floor Auditorium (323)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/12/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Herzl School** REVIEW DATE: **5/3/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **009**

MATERIAL DESCRIPTION: **2' x 4' Ceiling Tile (Tectum)**

MATERIAL LOCATION: **1st Floor Auditorium (323)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Herzl School** INSPECTION DATE: **4/12/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **010**
MATERIAL DESCRIPTION: **Hardcoat Plaster**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout 1921 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/12/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Herzl School** REVIEW DATE: **5/3/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **010**
MATERIAL DESCRIPTION: **Hardcoat Plaster**
MATERIAL LOCATION: **Throughout 1921 Building**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Herzl School** INSPECTION DATE: **4/12/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **011.1**
MATERIAL DESCRIPTION: **9" x 9" Brown/Tan Floor Tile w/Red/Brn Speckles**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 307**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____

Date: 04/12/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Herzl School** REVIEW DATE: **5/3/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **011.1**

MATERIAL DESCRIPTION: **9" x 9" Brown/Tan Floor Tile w/Red/Brn Speckles**

MATERIAL LOCATION: **Room 307**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Herzl School** INSPECTION DATE: **4/12/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **011.2**
MATERIAL DESCRIPTION: **9" x 9" Off White Floor Tile w/ Blue & Brn Specks**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **Room 309**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____

Date: **04/12/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Herzl School** REVIEW DATE: **5/3/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **011.2**

MATERIAL DESCRIPTION: **9" x 9" Off White Floor Tile w/ Blue & Brn Specks**

MATERIAL LOCATION: **Room 309**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Herzl School** INSPECTION DATE: **4/12/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **011.3**
MATERIAL DESCRIPTION: **9"x9" Dark Brown and Red Floor Tile (Checkerboard)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **1st Floor Corridor & 208**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____

Date: **04/12/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Herzl School** REVIEW DATE: **5/3/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **011.3**

MATERIAL DESCRIPTION: **9"x9" Dark Brown and Red Floor Tile (Checkerboard)**

MATERIAL LOCATION: **1st Floor Corridor & 208**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Herzl School** INSPECTION DATE: **4/12/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **011.4**
MATERIAL DESCRIPTION: **18" x 18" Black Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **1st Floor Corridor**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/12/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Herzl School** REVIEW DATE: **5/3/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **011.4**

MATERIAL DESCRIPTION: **18" x 18" Black Floor Tile**

MATERIAL LOCATION: **1st Floor Corridor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Herzl School** INSPECTION DATE: **4/12/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **011.5**
MATERIAL DESCRIPTION: **9" x 9" Green Floor Tile w/White Streaks**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **Room 107**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/12/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Herzl School** REVIEW DATE: **5/3/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **011.5**

MATERIAL DESCRIPTION: **9" x 9" Green Floor Tile w/White Streaks**

MATERIAL LOCATION: **Room 107**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Herzl School** INSPECTION DATE: **4/12/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **011.6**
MATERIAL DESCRIPTION: **9"x9" Gray/Tan Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **212**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____

Date: **04/12/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Herzl School** REVIEW DATE: **5/3/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **011.6**

MATERIAL DESCRIPTION: **9"x9" Gray/Tan Floor Tile**

MATERIAL LOCATION: **212**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Herzl School** INSPECTION DATE: **4/12/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **012.1**
MATERIAL DESCRIPTION: **12" x 12" Off White Floor Tile w/ Brown Specks**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 110,111**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____

Date: **04/12/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Herzl School** REVIEW DATE: **5/3/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **012.1**

MATERIAL DESCRIPTION: **12" x 12" Off White Floor Tile w/ Brown Specks**

MATERIAL LOCATION: **Rooms 110,111**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Herzl School** INSPECTION DATE: **4/12/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **012.2**
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile w/Gray Specks**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 310 and Kitchen**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/12/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Herzl School** REVIEW DATE: **5/3/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **012.2**

MATERIAL DESCRIPTION: **12" x 12" White Floor Tile w/Gray Specks**

MATERIAL LOCATION: **Rooms 310 and Kitchen**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Herzl School** INSPECTION DATE: **4/12/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **012.3**
MATERIAL DESCRIPTION: **12" x 12" Gray Floor Tile w/ White Speckles**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 209**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____

Date: **04/12/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Herzl School** REVIEW DATE: **5/3/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **012.3**

MATERIAL DESCRIPTION: **12" x 12" Gray Floor Tile w/ White Speckles**

MATERIAL LOCATION: **Room 209**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Herzl School** INSPECTION DATE: **4/12/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **013**
MATERIAL DESCRIPTION: **1' x 1' Acoustical Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Auditorium not observed 1x1" but present**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **2x2' CT mismeasured**

Inspector's Signature: _____ Date: **04/12/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Herzl School** REVIEW DATE: **5/3/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **013**

MATERIAL DESCRIPTION: **1' x 1' Acoustical Ceiling Tile**

MATERIAL LOCATION: **Auditorium not observed 1x1" but present**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Herzl School** INSPECTION DATE: **4/12/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **014.1**
MATERIAL DESCRIPTION: **9"x9" Brown/Tan Floor Tile w/Red/Brn Specks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 307**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/12/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Herzl School** REVIEW DATE: **5/3/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **014.1**

MATERIAL DESCRIPTION: **9"x9" Brown/Tan Floor Tile w/Red/Brn Specks Mastic**

MATERIAL LOCATION: **Rooms 307**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Herzl School** INSPECTION DATE: **4/12/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **014.2**
MATERIAL DESCRIPTION: **9"x9" Off White Floor Tile w/Bl & Brn Spks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 309**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/12/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Herzl School** REVIEW DATE: **5/3/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **014.2**

MATERIAL DESCRIPTION: **9"x9" Off White Floor Tile w/BI & Brn Spks Mastic**

MATERIAL LOCATION: **Room 309**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Herzl School** INSPECTION DATE: **4/12/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **014.3**
MATERIAL DESCRIPTION: **9"x9" Dark Brown & Red Floor (Checkerboard) Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **1st Floor Corridor, 208**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/12/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Herzl School** REVIEW DATE: **5/3/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **014.3**

MATERIAL DESCRIPTION: **9"x9" Dark Brown & Red Floor (Checkerboard) Mastic**

MATERIAL LOCATION: **1st Floor Corridor, 208**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Herzl School** INSPECTION DATE: **4/12/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **014.4**
MATERIAL DESCRIPTION: **18" x 18" Black Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **1st Floor Corridor**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/12/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Herzl School** REVIEW DATE: **5/3/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **014.4**

MATERIAL DESCRIPTION: **18" x 18" Black Floor Tile Mastic**

MATERIAL LOCATION: **1st Floor Corridor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUILDING ID: **3970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Herzl School** INSPECTION DATE: **4/12/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **014.5**
MATERIAL DESCRIPTION: **9" x 9" Green Floor Tile w/White Streaks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **Room 107**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/12/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Herzl School** REVIEW DATE: **5/3/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **014.5**

MATERIAL DESCRIPTION: **9" x 9" Green Floor Tile w/White Streaks Mastic**

MATERIAL LOCATION: **Room 107**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Herzl School** INSPECTION DATE: **4/12/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **014.6**
MATERIAL DESCRIPTION: **9"x9" Gray/Tan Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **Room 212**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/12/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Herzl School** REVIEW DATE: **5/3/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **014.6**

MATERIAL DESCRIPTION: **9"x9" Gray/Tan Floor Tile Mastic**

MATERIAL LOCATION: **Room 212**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Herzl School** INSPECTION DATE: **4/12/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **015.1**
MATERIAL DESCRIPTION: **12"x12" Off White Floor Tile w/Brn Streaks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 110, 111, 308, 315, and 316**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/12/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Herzl School** REVIEW DATE: **5/3/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **015.1**

MATERIAL DESCRIPTION: **12"x12" Off White Floor Tile w/Brn Streaks Mastic**

MATERIAL LOCATION: **Rooms 110, 111, 308, 315, and 316**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Herzl School** INSPECTION DATE: **4/12/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **015.2**
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile w/Gray Specks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Kitchen**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/12/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Herzl School** REVIEW DATE: **5/3/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **015.2**

MATERIAL DESCRIPTION: **12" x 12" White Floor Tile w/Gray Specks Mastic**

MATERIAL LOCATION: **Kitchen**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Herzl School** INSPECTION DATE: **4/12/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **015.3**
MATERIAL DESCRIPTION: **12" x 12" Gray Floor Tile w/White Specks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **Room 209**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/12/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Herzl School** REVIEW DATE: **5/3/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **015.3**

MATERIAL DESCRIPTION: **12" x 12" Gray Floor Tile w/White Specks Mastic**

MATERIAL LOCATION: **Room 209**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Herzl School** INSPECTION DATE: **4/12/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **016.1**
MATERIAL DESCRIPTION: **9"x9" Brn/Tan Floor Tile w/Red & Brn Specks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 300**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/12/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Herzl School** REVIEW DATE: **5/3/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **016.1**

MATERIAL DESCRIPTION: **9"x9" Brn/Tan Floor Tile w/Red & Brn Specks Mastic**

MATERIAL LOCATION: **Room 300**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Herzl School** INSPECTION DATE: **4/12/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **016.2**
MATERIAL DESCRIPTION: **Bottom Layer of Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 300**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____

Date: 04/12/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Herzl School** REVIEW DATE: **5/3/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **016.2**

MATERIAL DESCRIPTION: **Bottom Layer of Floor Tile Mastic**

MATERIAL LOCATION: **Room 300**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Herzl School** INSPECTION DATE: **4/12/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **016.3**
MATERIAL DESCRIPTION: **9"x9" Brn/Tan Floor Tile w/Brn & Wh Specks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **Room 202**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____

Date: 04/12/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Herzl School** REVIEW DATE: **5/3/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **016.3**

MATERIAL DESCRIPTION: **9"x9" Brn/Tan Floor Tile w/Brn & Wh Specks Mastic**

MATERIAL LOCATION: **Room 202**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Herzl School** INSPECTION DATE: **4/12/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **016.4**
MATERIAL DESCRIPTION: **9"x9" Off White Floor Tile w/Brn,Blk & Red Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **Room 203**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/12/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Herzl School** REVIEW DATE: **5/3/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **016.4**

MATERIAL DESCRIPTION: **9"x9" Off White Floor Tile w/Brn,Blk & Red Mastic**

MATERIAL LOCATION: **Room 203**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Herzl School** INSPECTION DATE: **4/12/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **017.1**
MATERIAL DESCRIPTION: **12" x 12" Off White Floor Tile w/Brn Specks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms301, 304-306, 318-323**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/12/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Herzl School** REVIEW DATE: **5/3/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **017.1**

MATERIAL DESCRIPTION: **12" x 12" Off White Floor Tile w/Brn Specks Mastic**

MATERIAL LOCATION: **Rooms301, 304-306, 318-323**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Herzl School** INSPECTION DATE: **4/12/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **017.2**
MATERIAL DESCRIPTION: **12"x12" Off Wh Floor Tile w/Brn & Gray Spks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 302**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____

Date: **04/12/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Herzl School** REVIEW DATE: **5/3/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **017.2**

MATERIAL DESCRIPTION: **12"x12" Off Wh Floor Tile w/Brn & Gray Spks Mastic**

MATERIAL LOCATION: **Room 302**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Herzl School** INSPECTION DATE: **4/12/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **017.3**
MATERIAL DESCRIPTION: **12"x12" Off White Floor Tile w/Blue Specks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **2nd Floor North Central Office**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/12/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Herzl School** REVIEW DATE: **5/3/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **017.3**

MATERIAL DESCRIPTION: **12"x12" Off White Floor Tile w/Blue Specks Mastic**

MATERIAL LOCATION: **2nd Floor North Central Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Herzl School** INSPECTION DATE: **4/12/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **017.4**
MATERIAL DESCRIPTION: **12"x12" Off-White Floor Tile w/White Spkles Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **2nd Floor Meeting Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/12/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Herzl School** REVIEW DATE: **5/3/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **017.4**

MATERIAL DESCRIPTION: **12"x12" Off-White Floor Tile w/White Spkles Mastic**

MATERIAL LOCATION: **2nd Floor Meeting Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Herzl School** INSPECTION DATE: **4/12/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **017.5**
MATERIAL DESCRIPTION: **12" x 12" Red -Brn Floor (Checkerboard) Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st Floor Corridor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____

Date: **04/12/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Herzl School** REVIEW DATE: **5/3/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **017.5**

MATERIAL DESCRIPTION: **12" x 12" Red -Brn Floor (Checkerboard) Mastic**

MATERIAL LOCATION: **1st Floor Corridor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Herzl School** INSPECTION DATE: **4/12/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **017.6**
MATERIAL DESCRIPTION: **18" x 18" Black Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **1st Floor Corridor**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/12/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Herzl School** REVIEW DATE: **5/3/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **017.6**

MATERIAL DESCRIPTION: **18" x 18" Black Floor Tile Mastic**

MATERIAL LOCATION: **1st Floor Corridor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Herzl School** INSPECTION DATE: **4/12/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **017.7**
MATERIAL DESCRIPTION: **12"x12" Off White FloorTile w/Wh & Brn Spks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **Room 101**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/12/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Herzl School** REVIEW DATE: **5/3/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **017.7**

MATERIAL DESCRIPTION: **12"x12" Off White FloorTile w/Wh & Brn Spks Mastic**

MATERIAL LOCATION: **Room 101**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Herzl School** INSPECTION DATE: **4/12/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **018**
MATERIAL DESCRIPTION: **Vibration Isolation Cloth**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st Floor Kitchen**
MATERIAL QUANTITY: **12** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/12/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Herzl School** REVIEW DATE: **5/3/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **018**
MATERIAL DESCRIPTION: **Vibration Isolation Cloth**
MATERIAL LOCATION: **1st Floor Kitchen**
MATERIAL QUANTITY: **12** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Herzl School** INSPECTION DATE: **4/12/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **019**
MATERIAL DESCRIPTION: **Boiler Gaskets**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Boiler Room**
MATERIAL QUANTITY: **10** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/12/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Herzl School** REVIEW DATE: **5/3/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **019**
MATERIAL DESCRIPTION: **Boiler Gaskets**
MATERIAL LOCATION: **Boiler Room**
MATERIAL QUANTITY: **10** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Herzl School** INSPECTION DATE: **4/12/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **020**
MATERIAL DESCRIPTION: **Linoleum Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **3rd Floor Janitor's Closet and 3rd Floor Storage Closet (no access)**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**
COMMENTS: **No access**

Inspector's Signature: _____ Date: 04/12/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Herzl School** REVIEW DATE: **5/3/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **020**
MATERIAL DESCRIPTION: **Linoleum Mastic**
MATERIAL LOCATION: **3rd Floor Janitor's Closet and 3rd Floor Storage Closet (no access)**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Herzl School** INSPECTION DATE: **4/12/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **021**
MATERIAL DESCRIPTION: **Incinerator Fire Brick**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____

Date: 04/12/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Herzl School** REVIEW DATE: **5/3/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **021**

MATERIAL DESCRIPTION: **Incinerator Fire Brick**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Herzl School** INSPECTION DATE: **4/12/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **022**
MATERIAL DESCRIPTION: **Building Brick - Not AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior of 1914 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/12/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Herzl School** REVIEW DATE: **5/3/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **022**
MATERIAL DESCRIPTION: **Building Brick - Not AHERA**
MATERIAL LOCATION: **Exterior of 1914 Building**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Herzl School** INSPECTION DATE: **4/12/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **023**
MATERIAL DESCRIPTION: **Brick Mortar -Not AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior of 1914 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/12/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Herzl School** REVIEW DATE: **5/3/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **023**
MATERIAL DESCRIPTION: **Brick Mortar -Not AHERA**
MATERIAL LOCATION: **Exterior of 1914 Building**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Herzl School** INSPECTION DATE: **4/12/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **024**
MATERIAL DESCRIPTION: **Building Brick - Not AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior of 1921 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____

Date: 04/12/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Herzl School** REVIEW DATE: **5/3/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **024**
MATERIAL DESCRIPTION: **Building Brick - Not AHERA**
MATERIAL LOCATION: **Exterior of 1921 Building**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Herzl School** INSPECTION DATE: **4/12/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **025**
MATERIAL DESCRIPTION: **Brick Mortar - Not AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior of 1921 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____

Date: **04/12/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Herzl School** REVIEW DATE: **5/3/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **025**
MATERIAL DESCRIPTION: **Brick Mortar - Not AHERA**
MATERIAL LOCATION: **Exterior of 1921 Building**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Herzl School** INSPECTION DATE: **4/12/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **026**
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile w/ Gray Flecks**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 324**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2016 - same**

Inspector's Signature: _____

Date: **04/12/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Herzl School** REVIEW DATE: **5/3/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **026**

MATERIAL DESCRIPTION: **12" x 12" White Floor Tile w/ Gray Flecks**

MATERIAL LOCATION: **Room 324**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Herzl School** INSPECTION DATE: **4/12/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **027**
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile w/ Gray Flecks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 324 (not observed)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2016 - same**

Inspector's Signature: _____ Date: **04/12/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Herzl School** REVIEW DATE: **5/3/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **027**

MATERIAL DESCRIPTION: **12" x 12" White Floor Tile w/ Gray Flecks Mastic**

MATERIAL LOCATION: **Room 324 (not observed)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Herzl School** INSPECTION DATE: **4/12/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **028**
MATERIAL DESCRIPTION: **4" Gray Vinyl Baseboard**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 324**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/12/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Herzl School** REVIEW DATE: **5/3/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **028**
MATERIAL DESCRIPTION: **4" Gray Vinyl Baseboard**
MATERIAL LOCATION: **Room 324**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Herzl School** INSPECTION DATE: **4/12/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **029**
MATERIAL DESCRIPTION: **4" Gray Vinyl Baseboard Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 324**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____

Date: **04/12/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Herzl School** REVIEW DATE: **5/3/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **029**

MATERIAL DESCRIPTION: **4" Gray Vinyl Baseboard Mastic**

MATERIAL LOCATION: **Room 324**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Herzl School** INSPECTION DATE: **4/12/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **030**
MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile w/ White Flecks**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 224 and Speech Asst. Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/12/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Herzl School** REVIEW DATE: **5/3/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **030**
MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile w/ White Flecks**
MATERIAL LOCATION: **Room 224 and Speech Asst. Room**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Herzl School** INSPECTION DATE: **4/12/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **031**
MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile w/ White Flecks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **Room 224 and Speech Asst. Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/12/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Herzl School** REVIEW DATE: **5/3/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **031**

MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile w/ White Flecks Mastic**

MATERIAL LOCATION: **Room 224 and Speech Asst. Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Herzl School** INSPECTION DATE: **4/12/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **032**
MATERIAL DESCRIPTION: **4" Brown Vinyl Baseboard**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 224 and Speech Asst. Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/12/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Herzl School** REVIEW DATE: **5/3/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **032**

MATERIAL DESCRIPTION: **4" Brown Vinyl Baseboard**

MATERIAL LOCATION: **Room 224 and Speech Asst. Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Herzl School** INSPECTION DATE: **4/12/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **033**
MATERIAL DESCRIPTION: **4" Brown Vinyl Baseboard Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 224 and Speech Asst. Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/12/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Herzl School** REVIEW DATE: **5/3/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **033**
MATERIAL DESCRIPTION: **4" Brown Vinyl Baseboard Mastic**
MATERIAL LOCATION: **Room 224 and Speech Asst. Room**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Herzl School** INSPECTION DATE: **4/12/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **034**
MATERIAL DESCRIPTION: **Ceramic Wall Tile Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 224 Washrooms and 324 Washrooms**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/12/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Herzl School** REVIEW DATE: **5/3/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **034**
MATERIAL DESCRIPTION: **Ceramic Wall Tile Adhesive**
MATERIAL LOCATION: **Room 224 Washrooms and 324 Washrooms**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Herzl School** INSPECTION DATE: **4/12/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **035**
MATERIAL DESCRIPTION: **4" Black Vinyl Baseboard**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Auditorium**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/12/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Herzl School** REVIEW DATE: **5/3/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **035**

MATERIAL DESCRIPTION: **4" Black Vinyl Baseboard**

MATERIAL LOCATION: **Auditorium**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Herzl School** INSPECTION DATE: **4/12/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **036**
MATERIAL DESCRIPTION: **4" Black Vinyl Baseboard Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Auditorium**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/12/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Herzl School** REVIEW DATE: **5/3/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **036**

MATERIAL DESCRIPTION: **4" Black Vinyl Baseboard Mastic**

MATERIAL LOCATION: **Auditorium**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Herzl School** INSPECTION DATE: **4/12/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **037**
MATERIAL DESCRIPTION: **9" x 9" Lt. Brown Floor Tile w/Dk Brn Streaks**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **Room 120**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____

Date: **04/12/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Herzl School** REVIEW DATE: **5/3/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **037**
MATERIAL DESCRIPTION: **9" x 9" Lt. Brown Floor Tile w/Dk Brn Streaks**
MATERIAL LOCATION: **Room 120**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Herzl School** INSPECTION DATE: **4/12/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **038**
MATERIAL DESCRIPTION: **9"x9" Lt. Brown Floor Tile w/Dk Brn Streaks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **Room 120**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____

Date: **04/12/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Herzl School** REVIEW DATE: **5/3/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **038**
MATERIAL DESCRIPTION: **9"x9" Lt. Brown Floor Tile w/Dk Brn Streaks Mastic**
MATERIAL LOCATION: **Room 120**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Herzl School** INSPECTION DATE: **4/12/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **039**
MATERIAL DESCRIPTION: **12" x 12" Light Blue Floor Tile w/ White Specks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Auditorium**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/12/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Herzl School** REVIEW DATE: **5/3/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **039**
MATERIAL DESCRIPTION: **12" x 12" Light Blue Floor Tile w/ White Specks**
MATERIAL LOCATION: **Auditorium**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Herzl School** INSPECTION DATE: **4/12/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **040**
MATERIAL DESCRIPTION: **12"x12" Light Blue Floor Tile w/ White Spks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Auditorium**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/12/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Herzl School** REVIEW DATE: **5/3/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **040**
MATERIAL DESCRIPTION: **12"x12" Light Blue Floor Tile w/ White Spks Mastic**
MATERIAL LOCATION: **Auditorium**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Herzl School** INSPECTION DATE: **4/12/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **041**
MATERIAL DESCRIPTION: **Vault Door Liner**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Third Floor Across From 310 (no access)**
MATERIAL QUANTITY: **32** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/12/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Herzl School** REVIEW DATE: **5/3/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **041**
MATERIAL DESCRIPTION: **Vault Door Liner**
MATERIAL LOCATION: **Third Floor Across From 310 (no access)**
MATERIAL QUANTITY: **32** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Herzl School** INSPECTION DATE: **4/12/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **042**
MATERIAL DESCRIPTION: **Gray Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Auditorium**
MATERIAL QUANTITY: **672** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/12/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Herzl School** REVIEW DATE: **5/3/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **042**
MATERIAL DESCRIPTION: **Gray Carpet Mastic**
MATERIAL LOCATION: **Auditorium**
MATERIAL QUANTITY: **672** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Herzl School** INSPECTION DATE: **4/12/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **043**
MATERIAL DESCRIPTION: **12" x 12" Blue Mix Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 128 and Office by 118**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/12/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Herzl School** REVIEW DATE: **5/3/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **043**
MATERIAL DESCRIPTION: **12" x 12" Blue Mix Floor Tile**
MATERIAL LOCATION: **Room 128 and Office by 118**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Herzl School** INSPECTION DATE: **4/12/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **044**
MATERIAL DESCRIPTION: **12" x 12" Blue Mix Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **Room 128 and Office by 118**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/12/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Herzl School** REVIEW DATE: **5/3/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **044**

MATERIAL DESCRIPTION: **12" x 12" Blue Mix Floor Tile Mastic**

MATERIAL LOCATION: **Room 128 and Office by 118**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Herzl School** INSPECTION DATE: **4/12/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **045**
MATERIAL DESCRIPTION: **12" x 12" Blue/White Checkerboard Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **Main Office**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/12/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Herzl School** REVIEW DATE: **5/3/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **045**

MATERIAL DESCRIPTION: **12" x 12" Blue/White Checkerboard Floor Tile**

MATERIAL LOCATION: **Main Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Herzl School** INSPECTION DATE: **4/12/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **046**
MATERIAL DESCRIPTION: **12"x12" Blue/White Checkerboard Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **Main Office**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/12/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Herzl School** REVIEW DATE: **5/3/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **046**

MATERIAL DESCRIPTION: **12"x12" Blue/White Checkerboard Floor Tile Mastic**

MATERIAL LOCATION: **Main Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Herzl School** INSPECTION DATE: **4/12/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **047**
MATERIAL DESCRIPTION: **Lab Table Tops**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 322, 303, 320 (not observed in 322)**
MATERIAL QUANTITY: **80** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/12/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Herzl School** REVIEW DATE: **5/3/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **047**
MATERIAL DESCRIPTION: **Lab Table Tops**
MATERIAL LOCATION: **Room 322, 303, 320 (not observed in 322)**
MATERIAL QUANTITY: **80** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Herzl School** INSPECTION DATE: **4/12/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **048**
MATERIAL DESCRIPTION: **12" x 12" White w/Multi-Color Streaks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 303 and 317**
MATERIAL QUANTITY: **837** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/12/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Herzl School** REVIEW DATE: **5/3/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **048**
MATERIAL DESCRIPTION: **12" x 12" White w/Multi-Color Streaks Floor Tile**
MATERIAL LOCATION: **Rooms 303 and 317**
MATERIAL QUANTITY: **837** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Herzl School** INSPECTION DATE: **4/12/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **049**
MATERIAL DESCRIPTION: **12" x 12" White w/Multi-Color Streaks FT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 303 and 317**
MATERIAL QUANTITY: **837** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/12/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Herzl School** REVIEW DATE: **5/3/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **049**
MATERIAL DESCRIPTION: **12" x 12" White w/Multi-Color Streaks FT Mastic**
MATERIAL LOCATION: **Rooms 303 and 317**
MATERIAL QUANTITY: **837** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Herzl School** INSPECTION DATE: **4/12/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **050**
MATERIAL DESCRIPTION: **12" x 12" White w/Colored Streaks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **1st Floor North Vestibules**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/12/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Herzl School** REVIEW DATE: **5/3/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **050**
MATERIAL DESCRIPTION: **12" x 12" White w/Colored Streaks Floor Tile**
MATERIAL LOCATION: **1st Floor North Vestibules**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Herzl School** INSPECTION DATE: **4/12/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **051**
MATERIAL DESCRIPTION: **12" x 12" White w/Colored Streaks FT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **1st Floor North Vestibules**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/12/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Herzl School** REVIEW DATE: **5/3/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **051**
MATERIAL DESCRIPTION: **12" x 12" White w/Colored Streaks FT Mastic**
MATERIAL LOCATION: **1st Floor North Vestibules**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Herzl School** INSPECTION DATE: **4/12/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14**
MATERIAL DESCRIPTION: **Chalk Boards**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 301-310,102,104-110,201-210 (not observed)**
MATERIAL QUANTITY: **3645** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/12/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Herzl School** REVIEW DATE: **5/3/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **14**
MATERIAL DESCRIPTION: **Chalk Boards**
MATERIAL LOCATION: **Rooms 301-310,102,104-110,201-210 (not observed)**
MATERIAL QUANTITY: **3645** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Herzl School** INSPECTION DATE: **4/12/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **52**
MATERIAL DESCRIPTION: **12"x12" Light Blue w/Marbling Streaks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 317 (not observed)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2016 - Removed/Abated - same**

Inspector's Signature: _____ Date: **04/12/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Herzl School** REVIEW DATE: **5/3/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **52**

MATERIAL DESCRIPTION: **12"x12" Light Blue w/Marbling Streaks Floor Tile**

MATERIAL LOCATION: **Room 317 (not observed)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Herzl School** INSPECTION DATE: **4/12/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **53**
MATERIAL DESCRIPTION: **12"x12" Lt Blue w/Marbling Strks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 317**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/12/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Herzl School** REVIEW DATE: **5/3/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **53**

MATERIAL DESCRIPTION: **12"x12" Lt Blue w/Marbling Strks Floor Tile Mastic**

MATERIAL LOCATION: **Room 317**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Herzl School** INSPECTION DATE: **4/12/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **54**
MATERIAL DESCRIPTION: **Blue White Ceramic Floor Tile Grout**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st, 2nd, 3rd, Floor-Boys/Girls Wash Room**
MATERIAL QUANTITY: **5400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/12/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Herzl School** REVIEW DATE: **5/3/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **54**
MATERIAL DESCRIPTION: **Blue White Ceramic Floor Tile Grout**
MATERIAL LOCATION: **1st, 2nd, 3rd, Floor-Boys/Girls Wash Room**
MATERIAL QUANTITY: **5400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Herzl School** INSPECTION DATE: **4/12/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **55**
MATERIAL DESCRIPTION: **Blue, White Ceramic Floor Tile Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st, 2nd, 3rd, Floors-Boys/Girls Wash Room**
MATERIAL QUANTITY: **5400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/12/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Herzl School** REVIEW DATE: **5/3/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **55**
MATERIAL DESCRIPTION: **Blue, White Ceramic Floor Tile Adhesive**
MATERIAL LOCATION: **1st, 2nd, 3rd, Floors-Boys/Girls Wash Room**
MATERIAL QUANTITY: **5400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Herzl School** INSPECTION DATE: **4/12/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **56**
MATERIAL DESCRIPTION: **12"x12" Beige w/Grey Spots**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 119**
MATERIAL QUANTITY: **350** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/12/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Herzl School** REVIEW DATE: **5/3/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **56**
MATERIAL DESCRIPTION: **12"x12" Beige w/Grey Spots**
MATERIAL LOCATION: **Room 119**
MATERIAL QUANTITY: **350** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Herzl School** INSPECTION DATE: **4/12/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **57**
MATERIAL DESCRIPTION: **12"x12" Light Grey w/Dark grey Spots**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st Floor Hallways**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/12/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Herzl School** REVIEW DATE: **5/3/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **57**
MATERIAL DESCRIPTION: **12"x12" Light Grey w/Dark grey Spots**
MATERIAL LOCATION: **1st Floor Hallways**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Herzl School** INSPECTION DATE: **4/12/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **58**
MATERIAL DESCRIPTION: **12"x12" Light Grey w/Dark grey Spots Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st Floor Hallways**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **04/12/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Herzl School** REVIEW DATE: **5/3/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **58**
MATERIAL DESCRIPTION: **12"x12" Light Grey w/Dark grey Spots Mastic**
MATERIAL LOCATION: **1st Floor Hallways**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Herzl School** INSPECTION DATE: **4/12/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **59**
MATERIAL DESCRIPTION: **Carpet Square Glue**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Main Offices**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/12/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Herzl School** REVIEW DATE: **5/3/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **59**
MATERIAL DESCRIPTION: **Carpet Square Glue**
MATERIAL LOCATION: **Main Offices**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Herzl School** INSPECTION DATE: **4/12/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **60**
MATERIAL DESCRIPTION: **12"x12" Light Beige w/Light Spots FT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Physical Damage**
DISTURBANCE POTENTIAL: **HIGH**
MATERIAL LOCATION: **1st and 2nd Floor Classrooms**
MATERIAL QUANTITY: **32000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **3** DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 04/12/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Herzl School** REVIEW DATE: **5/3/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **60**
MATERIAL DESCRIPTION: **12"x12" Light Beige w/Light Spots FT**
MATERIAL LOCATION: **1st and 2nd Floor Classrooms**
MATERIAL QUANTITY: **32000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **3** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Herzl School** INSPECTION DATE: **4/12/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **61**
MATERIAL DESCRIPTION: **12"x12" Light Beige w/Light Spots FT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st and 2nd Floor Classrooms**
MATERIAL QUANTITY: **32000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/12/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Herzl School** REVIEW DATE: **5/3/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **61**
MATERIAL DESCRIPTION: **12"x12" Light Beige w/Light Spots FT Mastic**
MATERIAL LOCATION: **1st and 2nd Floor Classrooms**
MATERIAL QUANTITY: **32000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUILDING ID: **3970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Herzl School** INSPECTION DATE: **4/12/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **62**
MATERIAL DESCRIPTION: **Brown Flooring Under Wood Floor**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **3rd Floor Gymnasium**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/12/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Herzl School** REVIEW DATE: **5/3/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **62**

MATERIAL DESCRIPTION: **Brown Flooring Under Wood Floor**

MATERIAL LOCATION: **3rd Floor Gymnasium**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Herzl School** INSPECTION DATE: **4/12/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **63**
MATERIAL DESCRIPTION: **Paper Under Wood Underlayment**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 108, 109, 110, 114, 118, 123, 207, 210, 211, 212, and 2nd Floor Offices (not observed)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/12/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Herzl School** REVIEW DATE: **5/3/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **63**
MATERIAL DESCRIPTION: **Paper Under Wood Underlayment**
MATERIAL LOCATION: **Rooms 108, 109, 110, 114, 118, 123, 207, 210, 211, 212, and 2nd Floor Offices (not observed)**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Herzl School** INSPECTION DATE: **4/12/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **64**
MATERIAL DESCRIPTION: **Paper Under Wood Underlayment**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 107, 116, 204, 205, 208, 209, and 244 (not observed)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not observed - Abated - same**

Inspector's Signature: _____ Date: **04/12/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Herzl School** REVIEW DATE: **5/3/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **64**

MATERIAL DESCRIPTION: **Paper Under Wood Underlayment**

MATERIAL LOCATION: **Rooms 107, 116, 204, 205, 208, 209, and 244 (not observed)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Herzl School** INSPECTION DATE: **4/12/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **65**
MATERIAL DESCRIPTION: **12" x 12" Gray and White Mottled Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Classrooms Throughout 3rd Floor**
MATERIAL QUANTITY: **20000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/12/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Herzl School** REVIEW DATE: **5/3/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **65**
MATERIAL DESCRIPTION: **12" x 12" Gray and White Mottled Floor Tile**
MATERIAL LOCATION: **Classrooms Throughout 3rd Floor**
MATERIAL QUANTITY: **20000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Herzl School** INSPECTION DATE: **4/12/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **66**
MATERIAL DESCRIPTION: **12" x 12" Gray and White Mottled Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Classrooms Throughout 3rd Floor**
MATERIAL QUANTITY: **20000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/12/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Herzl School** REVIEW DATE: **5/3/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **66**
MATERIAL DESCRIPTION: **12" x 12" Gray and White Mottled Floor Tile Mastic**
MATERIAL LOCATION: **Classrooms Throughout 3rd Floor**
MATERIAL QUANTITY: **20000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Herzl School** INSPECTION DATE: **4/12/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **67**
MATERIAL DESCRIPTION: **2' x 2' White Fissured Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 124, Auditorium**
MATERIAL QUANTITY: **1750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/12/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Herzl School** REVIEW DATE: **5/3/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **67**
MATERIAL DESCRIPTION: **2' x 2' White Fissured Ceiling Tile**
MATERIAL LOCATION: **Room 124, Auditorium**
MATERIAL QUANTITY: **1750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Herzl School** INSPECTION DATE: **4/12/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **A**
MATERIAL DESCRIPTION: **Fiberglass Insulation on Boiler**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/12/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Herzl School** REVIEW DATE: **5/3/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **A**

MATERIAL DESCRIPTION: **Fiberglass Insulation on Boiler**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUILDING ID: **3970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Herzl School** INSPECTION DATE: **4/12/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **B**
MATERIAL DESCRIPTION: **Fiberglass Tank Insulation**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Pump Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/12/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Herzl School** REVIEW DATE: **5/3/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **B**

MATERIAL DESCRIPTION: **Fiberglass Tank Insulation**

MATERIAL LOCATION: **Pump Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Herzl School** INSPECTION DATE: **4/12/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **C**
MATERIAL DESCRIPTION: **Fiberglass Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/12/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Herzl School** REVIEW DATE: **5/3/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **C**

MATERIAL DESCRIPTION: **Fiberglass Pipe Insulation**

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Herzl School** INSPECTION DATE: **4/12/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **D**
MATERIAL DESCRIPTION: **Hard Joint Compound on Fiberglass Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON: **Physical Damage**
DISTURBANCE POTENTIAL: **HIGH**
MATERIAL LOCATION: **Throughout 1914 Facility including Kitchen & Pipe Chases**
MATERIAL QUANTITY: **15** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **5** DAMAGE UNITS: **LF**
COMMENTS: **Not observed in kitchen**

Inspector's Signature: _____ Date: **04/12/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Herzl School** REVIEW DATE: **5/3/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **D**
MATERIAL DESCRIPTION: **Hard Joint Compound on Fiberglass Pipe Insulation**
MATERIAL LOCATION: **Throughout 1914 Facility including Kitchen & Pipe Chases**
MATERIAL QUANTITY: **15** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **5** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Repair and/or remove

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Herzl School** INSPECTION DATE: **4/12/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **E**
MATERIAL DESCRIPTION: **Water Meter Packing - Abated**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Basement**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/12/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Herzl School** REVIEW DATE: **5/3/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **E**

MATERIAL DESCRIPTION: **Water Meter Packing - Abated**

MATERIAL LOCATION: **Basement**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Herzl School** INSPECTION DATE: **4/12/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **F**
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **1 Damaged or significantly damaged friable thermal system insulating ACM**
HISTORICAL DAMAGE REASON: **Deterioration**
HISTORICAL RESPONSE ACTION: **Remove**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACM**

DAMAGE REASON: **Deterioration**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Above 1st Floor ceiling (not observed)**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **30** DAMAGE UNITS: **LF**
COMMENTS: **Not observed in basement - Abated**

Inspector's Signature: _____ Date: 04/12/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Herzl School** REVIEW DATE: **5/3/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **F**
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**
MATERIAL LOCATION: **Above 1st Floor ceiling (not observed)**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **30** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Remove

Comments:

Repair and/or remove damaged cardboard pipe insulation and continue O & M

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Herzl School** INSPECTION DATE: **4/12/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **G**
MATERIAL DESCRIPTION: **Hard Joint Compound on Cardboard Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Above 1st Floor Ceiling (not observed)**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **EA**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**
COMMENTS: **Basement Abated - same**

Inspector's Signature: _____ Date: 04/12/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Herzl School** REVIEW DATE: **5/3/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **G**
MATERIAL DESCRIPTION: **Hard Joint Compound on Cardboard Pipe Insulation**
MATERIAL LOCATION: **Above 1st Floor Ceiling (not observed)**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **EA**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Herzl School** INSPECTION DATE: **4/12/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **H**
MATERIAL DESCRIPTION: **Preformed Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY: **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Amosite, Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Tunnel**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**
COMMENTS: **Basement Abated - same**

Inspector's Signature: _____ Date: 04/12/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Herzl School** REVIEW DATE: **5/3/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **H**
MATERIAL DESCRIPTION: **Preformed Pipe Insulation**
MATERIAL LOCATION: **Tunnel**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Herzl School** INSPECTION DATE: **4/12/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **I**
MATERIAL DESCRIPTION: **Preformed Pipe Joint Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Amosite, Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Tunnel**
MATERIAL QUANTITY: **25** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**
COMMENTS: **Basement Abated - same**

Inspector's Signature: _____ Date: 04/12/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Herzl School** REVIEW DATE: **5/3/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **I**

MATERIAL DESCRIPTION: **Preformed Pipe Joint Insulation**

MATERIAL LOCATION: **Tunnel**

MATERIAL QUANTITY: **25**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Herzl School** INSPECTION DATE: **4/12/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **J**
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout 1914 Facility**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 04/12/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Herzl School** REVIEW DATE: **5/3/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **J**
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**
MATERIAL LOCATION: **Throughout 1914 Facility**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Herzl School** INSPECTION DATE: **4/12/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **K**
MATERIAL DESCRIPTION: **Aircell Pipe Fitting**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Amosite, Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout 1914 Facility**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **EA**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

COMMENTS:

Inspector's Signature: _____ Date: 04/12/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Herzl School** REVIEW DATE: **5/3/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **K**
MATERIAL DESCRIPTION: **Aircell Pipe Fitting**
MATERIAL LOCATION: **Throughout 1914 Facility**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **EA**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Herzl School** INSPECTION DATE: **4/12/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **L**
MATERIAL DESCRIPTION: **Fittings on Fiberglass Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout 1921 Facility**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/12/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Herzl School** REVIEW DATE: **5/3/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **L**

MATERIAL DESCRIPTION: **Fittings on Fiberglass Pipe Insulation**

MATERIAL LOCATION: **Throughout 1921 Facility**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Herzl School** INSPECTION DATE: **4/12/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **M**
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **1 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON: **Physical Damage**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st Floor**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **5** DAMAGE UNITS: **LF**
COMMENTS:

Inspector's Signature: _____ Date: 04/12/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Herzl School** REVIEW DATE: **5/3/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **M**
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**
MATERIAL LOCATION: **1st Floor**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **5** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Repair and/or remove damaged cardboard pipe insulation and continue O & M

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Herzl School** INSPECTION DATE: **4/12/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **N**
MATERIAL DESCRIPTION: **Hard Joint Compound on Cardboard Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1srt Floor**
MATERIAL QUANTITY: **30** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/12/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Herzl School** REVIEW DATE: **5/3/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **N**

MATERIAL DESCRIPTION: **Hard Joint Compound on Cardboard Pipe Insulation**

MATERIAL LOCATION: **1srt Floor**

MATERIAL QUANTITY: **30**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

See HA M

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Herzl School** INSPECTION DATE: **4/12/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **0**
MATERIAL DESCRIPTION: **Preformed Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Amosite, Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st Floor**
MATERIAL QUANTITY: **5** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 04/12/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Herzl School** REVIEW DATE: **5/3/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **0**

MATERIAL DESCRIPTION: **Preformed Pipe Insulation**

MATERIAL LOCATION: **1st Floor**

MATERIAL QUANTITY: **5**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Herzl School** INSPECTION DATE: **4/12/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **P**
MATERIAL DESCRIPTION: **Preformed Pipe Joint Insulation**
HISTORICAL AHERA DAMAGE CATEGORY: **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Amosite, Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st Floor**
MATERIAL QUANTITY: **10** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 04/12/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Herzl School** REVIEW DATE: **5/3/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **P**

MATERIAL DESCRIPTION: **Preformed Pipe Joint Insulation**

MATERIAL LOCATION: **1st Floor**

MATERIAL QUANTITY: **10**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Herzl School** INSPECTION DATE: **4/12/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **Q**
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **1 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON: **Physical Damage**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout 1921 Facility**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **20** DAMAGE UNITS: **LF**
COMMENTS:

Inspector's Signature: _____ Date: 04/12/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Herzl School** REVIEW DATE: **5/3/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **Q**
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**
MATERIAL LOCATION: **Throughout 1921 Facility**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **20** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Repair and/or remove damaged aircell pipe insulation and continue O & M

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Herzl School** INSPECTION DATE: **4/12/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **R**
MATERIAL DESCRIPTION: **Hard Joint Compound on Aircell Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **1 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON: **Physical Damage**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout 1921 Facility & Tunnel**
MATERIAL QUANTITY: **25** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **6** DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 04/12/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUIDLING ID: **3970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Herzl School** REVIEW DATE: **5/3/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **R**

MATERIAL DESCRIPTION: **Hard Joint Compound on Aircell Pipe Insulation**

MATERIAL LOCATION: **Throughout 1921 Facility & Tunnel**

MATERIAL QUANTITY: **25**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **6**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

See HA Q

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUILDING ID: **3970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Herzl School** REVIEW DATE: **5/3/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **69**
MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile Mastic**
MATERIAL LOCATION: **Engineer's office**
MATERIAL QUANTITY: **120** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

See HA 68

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23771** BUILDING ID: **3970**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Herzl School** REVIEW DATE: **5/3/2019**
ADDRESS: **3711 W. Douglas Blvd** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **68**
MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile**
MATERIAL LOCATION: **Engineers Office**
MATERIAL QUANTITY: **120** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **120** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Sample the damaged floor tile and associated mastic if positive for acbm remove and replace damaged floor tile and associated mastic

Management Planner's Signature: _____ Date: **05/03/2019**

APPENDIX B

Inspector and Management Planner Licenses



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • www.dph.illinois.gov

4/18/2016

DIONNE L CAREY WALKER

211 Somerset Drive
Streamwood, IL 60107

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 09969

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

ASBESTOS PROFESSIONAL LICENSE			ENDORSEMENTS	TC EXPIRES
	ID NUMBER 100 - 09969	ISSUED 4/18/2016	INSPECTOR	3/11/2017
DIONNE L CAREY WALKER 211 Somerset Drive Streamwood, IL 60107 Environmental Health	EXPIRES 05/15/2017		PROJECT MANAGER AIR SAMPLING PROFESSIONAL	3/12/2017
Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.				

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH, IMPROVING LIVES

Nationally Accredited by PHAB


has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Course Date: 1/4/2019

Exam Date: 1/4/2019

Expiration Date: 1/4/2020

Certificate Number: BIR1901040041


Kathy Desalvo, Director

Occupational Training & Supply, Inc. certifies that
Dionne L.C. Walker

Asbestos Building Inspector Refresher


OCCUPATIONAL TRAINING & SUPPLY, INC.
7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900 ♦ www.otsafety.com




2019



525-535 West Jefferson Street • Springfield, Illinois 62761

DIONNE L CAREY WALKER
 211 SOMERSET DRIVE
 STREAMWOOD, IL 60107

1/18/2019



ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 09969

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

 <p>ASBESTOS PROFESSIONAL LICENSE</p>			<p>ENDORSEMENTS</p>		<p>TC EXPIRES</p>
<p>ID NUMBER 100 - 09969</p>	<p>ISSUED 1/18/2019</p>	<p>EXPIRES 05/15/2020</p>	<p>INSPECTOR</p>		<p>1/4/2020</p>
<p>DIONNE L CAREY WALKER 211 SOMERSET DRIVE STREAMWOOD, IL 60107 Environmental Health</p> 			<p>PROJECT MANAGER AIR SAMPLING PROFESSIONAL</p>		<p>1/5/2020</p>
<p>Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.</p>					

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
 EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH, IMPROVING LIVES
Nationally Accredited by PHAB

JAINA ASSOCIATES

THIS IS TO CERTIFY
THAT

DIONNE L. CAREY

HAS SUCCESSFULLY COMPLETED THE SAMPLING AND EVALUATING ASBESTOS AIRBORNE
DUST - NIOSH 582 EQUIVALENT TRAINING COURSE, AND PASSED THE EXAMINATION WITH
A SCORE OF 70% OR ABOVE FOR THE PURPOSE OF CERTIFICATION.

COURSE DATE: May 14 to 17, 2005

EXAM DATE: May 17, 2005

LOCATION: GSG Environmental, Inc.
855 West Adams Street, Suite 200
Chicago, Illinois 60607

DIRECTOR
OF TRAINING:

SANJIV JAIN

CERTIFICATE No.: 05JA-051405
IDPH COURSE PROVIDER No.: 038

2015



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Evan Christian

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 12/2/2015

Exam Date: 12/2/2015

Expiration Date: 12/2/2016

Certificate Number: BIR1512024159


Katy DeSalvo, Director

Reliable
Environmental
Solutions, Inc. **RES**

This is to certify that **Evan Christian**

*has on January 28 & 29, 2016, in Springfield, Illinois,
completed the requirements for asbestos accreditation under Section 206 of TSCA Title II*

Asbestos Management Planner Initial Training

*as accredited by the State of Illinois and approved by the U.S.E.P.A. under 40 CFR 763 (AHERA)
and passed the associated examination with a score of 70% or higher*

Course Date: January 28 & 29, 2016

Examination Date: January 29, 2016

Expiration Date: January 29, 2017

Certificate Number: MP/0103

William S. Williams

Training Program Manager, William S. Williams

4211 Westgate Drive, Springfield, Illinois ☐ 217.787.9800 ☐ 217.787.9801 FAX ☐ www.ReliableEnv.com

2019



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900 ♦ www.otssafety.com

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that
Evan Christian

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/19/2019

Exam Date: 11/19/2019

Expiration Date: 11/19/2020

Certificate Number: BIR1911192384


Kathy DeSalvo, Director



**ASBESTOS
PROFESSIONAL
LICENSE**

ID NUMBER
100 - 19466

ISSUED
4/12/2019

EXPIRES
05/15/2020

EVAN I CHRISTIAN
3024 N RACINE AVE, APT 2
CHICAGO, IL 60657



Environmental Health

ENDORSEMENTS

TC EXPIRES

INSPECTOR

11/28/2019

MANAGEMENT PLANNER

1/5/2019

PROJECT MANAGER

2/5/2020

AIR SAMPLING PROFESSIONAL

Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois
Department of Public Health

This license is valid only when accompanied by a valid
training course certificate.

2019



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900 ♦ www.otssafety.com

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Evan Christian

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Course Date: 1/7/2019

Exam Date: 1/7/2019

Expiration Date: 1/7/2020


Certificate Number: MPR1901070063



Kathy DeSalvo, Director

Evan Christian

Illinois Licensed Project Manager, and Air Sampling Professional



ENDORSEMENTS	TC EXPIRES
PROJECT MANAGER AIR SAMPLING PROFESSIONAL	12/12/2015
Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	

**CARNOW
CONIBEAR**

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL		
	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE		
	Loc	Localized
	Dist	Distributed