

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM**

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-2275
SCHOOL NAME: Hoyne School
ADDRESS OF SCHOOL: 8905 S Crandon
CITY: Chicago, IL, 60617

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **3/21/2016**

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II *(Please type or print)*

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 10/1/2019 ENROLLMENT 235
IDPH INSPECTOR LICENSE NUMBER: 100-11070
IDPH LICENSED INSPECTOR NAME(Please Print): Mallory Jones
IDPH MP LICENSE NUMBER: 100-00746
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Amy Williams

DESIGNATED PERSON (Please Print): Robert Christlieb PHONE: (773) 553-3197



10/1/2019

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Hoyne School

8905 S Crandon
Chicago, IL, 60617

Unit: 23871
Building ID: 4080

IDPH ID Number: 14-016-2990-2275

REPORT DATE:

Tuesday, October 01, 2019

Prepared for:

**Chicago Public Schools
42 West Madison Street
Chicago, IL 60602**

Prepared by:

TEM Environmental, Inc.

174 N. Brandon Drive

Glendale Heights, IL, 60139

Phone 630-790-0880

Fax 630-790-0882

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

September 20, 2019

Mr. Glen E. Garner
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2019 Three-Year Reinspections

Dear Mr. Glen:

TEM Environmental, Inc. , Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 5, 6 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 23871 Region: 06 IDPH ID:14-016-2990-2275

School: Hoyne School Building ID: 4080

Address: 8905 S Crandon

Chicago, IL, 60617

Building Contact: Hayes, Jamelle

Contact Phone:

Current Building Owners: Chicago Public Schools

Review Date: 10/19/2019

Inspector: Mallory Jones

Inspector IDPH License: 100-11070

Management Planner: Amy Williams

Management Planner IDPH License: 100-00746

If you have any questions or comments, please contact us at 630-790-0880

Sincerely,
TEM Environmental, Inc.

Amy Williams
100-00746

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: September 20, 2019

RE: Hoyne School, Unit 23871
8905 S Crandon
Chicago, IL, 60617

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2019 asbestos three year re-inspection has been completed at Hoyne School, following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at Hoyne School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Robert Christlieb, the designated Local Education Authority's Designated Person at (773) 553-3197 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School:	Hoyne School	Unit:	23871	Region:	06
Address:	8905 S Crandon		Chicago, IL, 60617		
IDPH ID:	14-016-2990-2275	Building ID:	4080		
Contact:	Hayes, Jamelle	Phone:			

2. Description of Facility

Original Construction:	1998	Additional Construction:	1955
Total Square Footage:	10125	No of Floors:	1
Current Occupancy:	235		

3. LEA Designated Person

Contact:	Robert Christlieb	Phone:	(773) 553-3197
Address:	42 West Madison Street		
	Chicago, IL 60602		

4. Managing Environmental Consultant

MEC:	TEM Environmental, Inc.		
Contact:	Steven Geneser		
Address	174 N. Brandon Drive		
	Glendale Heights, IL, 60139		
Phone:	630-790-0880	Fax:	630-790-0882

5. Inspector

Inspector Name: Mallory Jones

Inspector IDPH license # 100-11070

Signature:
Date: 9/20/2019

6. Management Planner

Management Planner Name: Amy Williams

Management Planner IDPH license # 100-00746

Signature:
Date: 10/19/2019

7. Review Date:10/19/2019

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature:



Date: 10/1/2019

Name: Robert Christlieb

II. EXECUTIVE SUMMARY

TEM Environmental, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Hoyne School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.85 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 4080:

B. The following new homogenous areas have been identified for Building 4080:

40	Ceramic Baseboard Grout
41	12" Gray Mottled Vinyl Floor Tile
42	12" Gray Mottled Vinyl Floor Tile Mastic
43	12" Tan Mottled Vinyl Floor Tile
44	12" Tan Mottled Vinyl Floor Tile Mastic
45	12" Orange Mottled Vinyl Floor Tile
46	12" Orange Vinyl Floor Tile Mastic

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

17	Black Vinyl Baseboard Mastic
19	Gray Vinyl Baseboard Mastic
24	1 x 1 White Ceiling Tile
25	Beige and Tan Ceramic Tile Grout
26	Beige and Tan Ceramic Tile Adhesive
27	12 x 12 Light Grey Floor Tile
27M	12 x 12 Light Grey Floor Tile Mastic
28	12 x 12 Beige and White Checkerboard Floor Tile
28M	12 x 12 Beige and White Checkerboard Floor Tile Mastic
29	Carpet Adhesive
30	Insulation in Vault Door
31	2 x 2 White Lay-In Ceiling Tile
32	9 x 9 Beige Floor Tile
32M	9 x 9 Beige Floor Tile Mastic
33	2 x 4 Yellow Lay-In Ceiling Panels
34	2 x 4 White Lay-In Ceiling Tile
35	5" x 5" Brown Ceramic Floor Tile Grout
36	5" x 5" Brown Ceramic Floor Tile Adhesive
37	Gray Vinyl Baseboard Panels
38	Black Fire Retardent
39	Plaster Ceiling
40	Ceramic Baseboard Grout
41	12" Gray Mottled Vinyl Floor Tile
42	12" Gray Mottled Vinyl Floor Tile Mastic
43	12" Tan Mottled Vinyl Floor Tile
44	12" Tan Mottled Vinyl Floor Tile Mastic
45	12" Orange Mottled Vinyl Floor Tile
46	12" Orange Vinyl Floor Tile Mastic

The following areas were deemed to be inaccessible:

08FT1	12"x12" Gray Floor Tile Mastic
08FT2	12x12 Beige Floor Tile Mastic
26	Beige and Tan Ceramic Tile Adhesive
27M	12 x 12 Light Grey Floor Tile Mastic
28M	12 x 12 Beige and White Checkerboard Floor Tile Mastic
29	Carpet Adhesive
30	Insulation in Vault Door

32M	9 x 9 Beige Floor Tile Mastic
36	5" x 5" Brown Ceramic Floor Tile Adhesive
42	12" Gray Mottled Vinyl Floor Tile Mastic
44	12" Tan Mottled Vinyl Floor Tile Mastic
46	12" Orange Vinyl Floor Tile Mastic

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Mallory Jones, IDPH License # 100-11070. The Management Plan was updated by Amy Williams, IDPH License # 100-00746. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates: 7/5/2019
7/5/2019

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Hoyne School Building 4080 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Hoyne School Unit 23871 Building ID 4080

Address 8905 S Crandon Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
04FT1	12x12 Gray Floor Tile	3,000	SF	Classrooms & Hallways of 1955 Building, including Rooms 105, 107, 109, and 111	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
04FT2	12x12 Beige Floor Tile	2,000	SF	Classrooms of 1955 Building, including Rooms 110, 112, 113, 114, Office Vault Room	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
04FT3	12x12 White Floor Tile			Main Office, West, South Halls, Room 101, 103, 115, 116 and Gym Office	NO_ACBM	MISC								
05FT1	9x9 Dark Gray Floor Tile	936	SF	1959 Building-Rooms 102 and 103	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
05FT2	12x12 Beige Floor Tile	900	SF	1959 Building-Rooms 101 and 104	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
06	Wall Boards (NOT OBSERVED)					MISC								
07	Beige Multi-Colored Linoleum	1,500	SF	1955 Building-Room 106	NO_ACBM	MISC								
08FT1	12"x12" Gray Floor Tile Mastic	3,000	SF	Classrooms & Hallways of 1955 Building, including Rooms 105, 107, 109, 111	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
08FT2	12x12 Beige Floor Tile Mastic	2,000	SF	Classrooms of 1955 Building, including Rooms 110, 112, 114	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
08FT3	12x12 White Floor Tile Mastic			Main Office, Rooms 101 and 104, West and South Halls	NO_ACBM	MISC								
09FT1	9x9 Dark Gray Floor Tile Mastic			1959 Building-Rooms 102 and 103	NO_ACBM	MISC								
09FT2	12x12 Beige Floor Tile Mastic			1959 Building-Rooms 101 and 104	NO_ACBM	MISC								
10	Black Vinyl Baseboard-NOT OBSERVED			1955 Building-Rooms 105, 107, 108, 109, 110, 112, 114	NO_ACBM	MISC								
11	Black Vinyl Baseboard Mastic-NOT OBSERVED			1955 Building, Rooms 105, 107, 108, 109, 110, 112,	NO_ACBM	MISC								

Chicago Public Schools

School Hoyne School Unit 23871 Building ID 4080

Address 8905 S Crandon Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				114										
12	Firebrick ABATED			Boiler Room	ABATED	TSI								
13	Incinerator Door			Boiler Room	NO_ACBM	TSI								
14	Light Beige Linoleum	2,020	SF	Room 106, Kitchen	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
16	Black Vinyl Baseboard			1939 Bldg. Rooms 101, 102, 103, 104, 111	NO_ACBM	MISC								LOW
17	Black Vinyl Baseboard Mastic	100	LF	1939 Building-Rooms 101, 102, 103, 104	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
18	Light Beige Linoleum Adhesive			Room 106, Kitchen	NO_ACBM									
19	Gray Vinyl Baseboard Mastic	210	LF	1959 Building-Room 101, 102, 103, 104, 111	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
20	Linoleum ABATED			1959 Building-Rooms 101, 102, 103, 104	ABATED	MISC								
22	Boiler Gaskets ABATED			Boiler Room	ABATED	TSI								
23	Plaster ABATED			Throughout School	ABATED	SURFACE								
24	1 x 1 White Ceiling Tile	9,824	SF	North and West Corridors, Rooms 105, 106, 107, 108, 109, 110, 111, 112, 113, 114	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
25	Beige and Tan Ceramic Tile Grout	996	SF	East Girls and Boys Washrooms, East and West Entrances	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
26	Beige and Tan Ceramic Tile Adhesive	996	SF	East Girls and Boys Washrooms, East and West Entrances	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
27	12 x 12 Light Grey Floor Tile	2,728	SF	Multipurpose Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
27M	12 x 12 Light Grey Floor Tile Mastic	2,728	SF	Multipurpose Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
28	12 x 12 Beige and White Checkerboard Floor Tile	120	SF	Main Office Restroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
28M	12 x 12 Beige and White Checkerboard Floor Tile Mastic	120	SF	Main Office Restroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
29	Carpet Adhesive	748	SF	Main Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
30	Insulation in Vault Door	1	EA	Main Office	ASSUMED	TSI	N	NONE	0		No	ACBM with the potential for damage		LOW
31	2 x 2 White Lay-In Ceiling Tile	4,484	SF	Main Office, Rooms	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable		LOW

Chicago Public Schools

School Hoyne School Unit 23871 Building ID 4080

Address 8905 S Crandon Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				101, 103, 115 and 116								ACBM or friable suspect ACBM		
32	9 x 9 Beige Floor Tile	936	SF	Room 104	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
32M	9 x 9 Beige Floor Tile Mastic	936	SF	Room 104	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
33	2 x 4 Yellow Lay-In Ceiling Panels	1,020	SF	Kitchen 118	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
34	2 x 4 White Lay-In Ceiling Tile	216	SF	Principal's Office	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
35	5" x 5" Brown Ceramic Floor Tile Grout	96	SF	NE Courtyard Entrance	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
36	5" x 5" Brown Ceramic Floor Tile Adhesive	96	SF	NE Courtyard Entrance	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
37	Gray Vinyl Baseboard Panels	210	LF	1959 Building-Rooms 101-104 and 111	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
38	Black Fire Retardent	1,500	SF	Throughout 1959 Addition	ASSUMED	SURFACE	N	NONE	0		No	ACBM with the potential for damage		LOW
39	Plaster Ceiling	600	SF	Boys and Girls Toilets and Janitor Closet - 1998 Addition	ASSUMED	SURFACE	N	NONE	0		No	ACBM with the potential for damage		LOW
40	Ceramic Baseboard Grout	1,200	SF	Halls and Classrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
41	12" Gray Mottled Vinyl Floor Tile	525	SF	Room 108	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
42	12" Gray Mottled Vinyl Floor Tile Mastic	525	SF	Room 108	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
43	12" Tan Mottled Vinyl Floor Tile	150	SF	Room 108	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
44	12" Tan Mottled Vinyl Floor Tile Mastic	150	SF	Room 108	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
45	12" Orange Mottled Vinyl Floor Tile	75	SF	Room 108	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
46	12" Orange Vinyl Floor Tile Mastic	75	SF	Room 108	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Hoyne School Unit 23871 Building ID 4080
Address 8905 S Crandon Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

Reinspection Date	<u>9/20/2019</u>
Inspector Name	<u>Mallory Jones</u>
<u>100-11070</u>	<u>5/15/2020</u>
Inspector's IDPH License Number / Expiration Date	

Inspector's Comments

HA Number:	Inspector Comments:
04FT1	
04FT2	Room 108 Abated 2019
04FT3	
05FT1	
05FT2	
06	Not Observed Multiple Years
07	
08FT1	
08FT2	Room 108 Abated 2019
08FT3	
09FT1	Not Observed- No ACBM
09FT2	
10	Not Observed 2019- Has Cream Ceramic Baseboard
11	Not Observed 2019 - Has Cream Ceramic Baseboards
12	
13	
14	
16	
17	
18	
19	
20	
22	

Chicago Public Schools

School Hoyne School **Unit** 23871 **Building ID** 4080
Address 8905 S Crandon **Region** 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
23	
24	
25	
26	
27	
27M	
28	
28M	
29	
30	
31	
32	
32M	
33	
34	
35	
36	
37	
38	
39	
40	Throughout- Beneath Vinyl where Vinyl is Present
41	
42	
43	
44	
45	
46	

Chicago Public Schools

School Hoyne School **Unit** 23871 **Building ID** 4080
Address 8905 S Crandon **Region** 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

Table II

Management Planner's Review

Chicago Public Schools

School Hoyne School
Address 8905 S Crandon

Unit 23871
Chicago, IL, 60617

Building ID 4080
Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
04FT1	12x12 Gray Floor Tile	3,000	SF	Classrooms & Hallways of 1955 Building, including Rooms 105, 107, 109, and 111	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
04FT2	12x12 Beige Floor Tile	2,000	SF	Classrooms of 1955 Building, including Rooms 110, 112, 113, 114, Office Vault Room	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
04FT3	12x12 White Floor Tile			Main Office, West, South Halls, Room 101, 103, 115, 116 and Gym Office	No ACBM	MISC					
05FT1	9x9 Dark Gray Floor Tile	936	SF	1959 Building- Rooms 102 and 103	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
05FT2	12x12 Beige Floor Tile	900	SF	1959 Building- Rooms 101 and 104	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
06	Wall Boards (NOT OBSERVED)				MISC						
07	Beige Multi-Colored Linoleum	1,500	SF	1955 Building- Room 106	No ACBM	MISC			SF		
08FT1	12"x12" Gray Floor Tile Mastic	3,000	SF	Classrooms & Hallways of 1955 Building, including Rooms 105, 107, 109, 111	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
08FT2	12x12 Beige Floor Tile Mastic	2,000	SF	Classrooms of 1955 Building, including Rooms 110, 112, 114	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
08FT3	12x12 White Floor Tile Mastic			Main Office, Rooms 101 and 104, West and South Halls	No ACBM	MISC					
09FT1	9x9 Dark Gray Floor Tile Mastic			1959 Building- Rooms 102 and 103	No ACBM	MISC					
09FT2	12x12 Beige Floor Tile Mastic			1959 Building- Rooms 101 and 104	No ACBM	MISC					
10	Black Vinyl Baseboard-NOT OBSERVED			1955 Building Rooms 105, 107, 108, 109, 110, 112, 114	No ACBM	MISC					
11	Black Vinyl Baseboard Mastic-NOT OBSERVED			1955 Building, Rooms 105, 107, 108, 109, 110, 112, 114	No ACBM	MISC					
12	Firebrick ABATED			Boiler Room	Abated	TSI					
13	Incinerator Door			Boiler Room	No ACBM	TSI					
14	Light Beige Linoleum	2,020	SF	Room 106, Kitchen	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
16	Black Vinyl Baseboard			1939 Bldg. Rooms 101, 102, 103, 104, 111	No ACBM	MISC					
17	Black Vinyl Baseboard Mastic	100	LF	1939 Building- Rooms 101, 102, 103, 104	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
18	Light Beige Linoleum Adhesive			Room 106, Kitchen	No ACBM						
19	Gray Vinyl Baseboard Mastic	210	LF	1959 Building- Room 101, 102, 103, 104, 111	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Hoyne School
Address 8905 S Crandon

Unit 23871
Chicago, IL, 60617

Building ID 4080
Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
20	Linoleum ABATED			1959 Building- Rooms 101, 102, 103, 104	Abated	MISC					
22	Boiler Gaskets ABATED			Boiler Room	Abated	TSI					
23	Plaster ABATED			Throughout School	Abated	SURFACE					
24	1 x 1 White Ceiling Tile	9,824	SF	North and West Corridors, Rooms 105, 106, 107, 108, 109, 110, 111, 112, 113, 114	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
25	Beige and Tan Ceramic Tile Grout	996	SF	East Girls and Boys Washrooms, East and West Entrances	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
26	Beige and Tan Ceramic Tile Adhesive	996	SF	East Girls and Boys Washrooms, East and West Entrances	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
27	12 x 12 Light Grey Floor Tile	2,728	SF	Multipurpose Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
27M	12 x 12 Light Grey Floor Tile Mastic	2,728	SF	Multipurpose Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
28	12 x 12 Beige and White Checkerboard Floor Tile	120	SF	Main Office Restroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
28M	12 x 12 Beige and White Checkerboard Floor Tile Mastic	120	SF	Main Office Restroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
29	Carpet Adhesive	748	SF	Main Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
30	Insulation in Vault Door	1	EA	Main Office	Assumed	TSI	No	0	EA	6 ACBM with the potential for damage	Follow O&M Plan
31	2 x 2 White Lay-In Ceiling Tile	4,484	SF	Main Office, Rooms 101, 103, 115 and 116	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
32	9 x 9 Beige Floor Tile	936	SF	Room 104	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
32M	9 x 9 Beige Floor Tile Mastic	936	SF	Room 104	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
33	2 x 4 Yellow Lay-In Ceiling Panels	1,020	SF	Kitchen 118	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
34	2 x 4 White Lay-In Ceiling Tile	216	SF	Principal's Office	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
35	5" x 5" Brown Ceramic Floor Tile Grout	96	SF	NE Courtyard Entrance	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
36	5" x 5" Brown Ceramic Floor Tile Adhesive	96	SF	NE Courtyard Entrance	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
37	Gray Vinyl Baseboard Panels	210	LF	1959 Building- Rooms 101-104 and 111	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
38	Black Fire Retardent	1,500	SF	Throughout 1959 Addition	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
39	Plaster Ceiling	600	SF	Boys and Girls Toilets and Janitor Closet - 1998 Addition	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
40	Ceramic Baseboard Grout	1,200	SF	Halls and Classrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Hoyne School
Address 8905 S Crandon

Unit 23871
Chicago, IL, 60617

Building ID 4080
Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
41	12" Gray Mottled Vinyl Floor Tile	525	SF	Room 108	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
42	12" Gray Mottled Vinyl Floor Tile Mastic	525	SF	Room 108	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
43	12" Tan Mottled Vinyl Floor Tile	150	SF	Room 108	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
44	12" Tan Mottled Vinyl Floor Tile Mastic	150	SF	Room 108	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
45	12" Orange Mottled Vinyl Floor Tile	75	SF	Room 108	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
46	12" Orange Vinyl Floor Tile Mastic	75	SF	Room 108	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Hoyne School
Address 8905 S Crandon

Unit 23871
Chicago, IL, 60617

Building ID 4080
Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

Review Date	10/19/2019
Manager Planner Name	Amy Williams
100-00746	5/15/2020
Manager IDPH License No/Expiration	

HA Number	Management Comments
04FT1	
04FT2	
04FT3	
05FT1	
05FT2	
06	
07	
08FT1	
08FT2	
08FT3	
09FT1	
09FT2	
10	
11	
12	
13	
14	
16	
17	
18	
19	
20	
22	
23	
24	

Chicago Public Schools

School Hoyne School
Address 8905 S Crandon

Unit 23871
Chicago, IL, 60617

Building ID 4080
Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.
174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
25	
26	
27	
27M	
28	
28M	
29	
30	
31	
32	
32M	
33	
34	
35	
36	
37	
38	
39	
40	
41	
42	
43	
44	
45	
46	

Chicago Public Schools

School

Hoyne School

Unit

23871

Building ID

4080

Address

8905 S Crandon

Chicago, IL, 60617

Region

06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC)

TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone:

630-790-0880

Fax:

630-790-0882

Management Planner's Comments Summarized at the End of the Report

Chicago Public Schools

TEM Environmental, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23871	BUILDING ID:	4080
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Hoyne School	INSPECTION DATE:	9/20/2019		
ADDRESS:	8905 S Crandon	IDPH LICENSE NO:	100-11070		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	04FT1		
MATERIAL DESCRIPTION:	12x12 Gray Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Classrooms & Hallways of 1955 Building, including Rooms 105, 107, 109, and 111		
MATERIAL QUANTITY:	3000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/20/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23871	BUILDING ID:	4080
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Hoyne School	REVIEW DATE:	10/19/2019		
ADDRESS:	8905 S Crandon	IDPH LICENSE NO:	100-11070		

HOMOGENEOUS AREA:	04FT1				
MATERIAL DESCRIPTION:	12x12 Gray Floor Tile				
MATERIAL LOCATION:	Classrooms & Hallways of 1955 Building, including Rooms 105, 107, 109, and 111				
MATERIAL QUANTITY:	3000	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 10/19/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23871	BUILDING ID:	4080
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Hoyne School	INSPECTION DATE:	9/20/2019		
ADDRESS:	8905 S Crandon	IDPH LICENSE NO:	100-11070		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	04FT2		
MATERIAL DESCRIPTION:	12x12 Beige Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Classrooms of 1955 Building, including Rooms 110, 112, 113, 114, Office Vault Room		
MATERIAL QUANTITY:	2000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:	Room 108 Abated 2019		

Inspector's Signature: _____ Date: 09/20/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23871	BUILDING ID:	4080
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Hoyne School	REVIEW DATE:	10/19/2019		
ADDRESS:	8905 S Crandon	IDPH LICENSE NO:	100-11070		

HOMOGENEOUS AREA:	04FT2				
MATERIAL DESCRIPTION:	12x12 Beige Floor Tile				
MATERIAL LOCATION:	Classrooms of 1955 Building, including Rooms 110, 112, 113, 114, Office Vault Room				
MATERIAL QUANTITY:	2000	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/19/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23871	BUILDING ID:	4080
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Hoyne School	INSPECTION DATE:	9/20/2019		
ADDRESS:	8905 S Crandon	IDPH LICENSE NO:	100-11070		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	04FT3	
MATERIAL DESCRIPTION:	12x12 White Floor Tile	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Main Office, West, South Halls, Room 101, 103, 115, 116 and Gym Office

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 09/20/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23871	BUILDING ID:	4080
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Hoyne School	REVIEW DATE:	10/19/2019		
ADDRESS:	8905 S Crandon	IDPH LICENSE NO:	100-11070		

HOMOGENEOUS AREA:	04FT3
MATERIAL DESCRIPTION:	12x12 White Floor Tile
MATERIAL LOCATION:	Main Office, West, South Halls, Room 101, 103, 115, 116 and Gym Office
MATERIAL QUANTITY:	MATERIAL UNITS:
DAMAGE QUANTITY:	DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/19/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23871	BUILDING ID:	4080
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Hoyne School	INSPECTION DATE:	9/20/2019		
ADDRESS:	8905 S Crandon	IDPH LICENSE NO:	100-11070		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	05FT1		
MATERIAL DESCRIPTION:	9x9 Dark Gray Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1959 Building- Rooms 102 and 103		
MATERIAL QUANTITY:	936	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/20/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23871	BUILDING ID:	4080
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Hoyne School	REVIEW DATE:	10/19/2019		
ADDRESS:	8905 S Crandon	IDPH LICENSE NO:	100-11070		

HOMOGENEOUS AREA:	05FT1		
MATERIAL DESCRIPTION:	9x9 Dark Gray Floor Tile		
MATERIAL LOCATION:	1959 Building- Rooms 102 and 103		
MATERIAL QUANTITY:	936	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/19/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23871	BUILDING ID:	4080
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Hoyne School	INSPECTION DATE:	9/20/2019		
ADDRESS:	8905 S Crandon	IDPH LICENSE NO:	100-11070		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	05FT2		
MATERIAL DESCRIPTION:	12x12 Beige Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1959 Building- Rooms 101 and 104		
MATERIAL QUANTITY:	900	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/20/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23871	BUILDING ID:	4080
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Hoyne School	REVIEW DATE:	10/19/2019		
ADDRESS:	8905 S Crandon	IDPH LICENSE NO:	100-11070		

HOMOGENEOUS AREA: 05FT2

MATERIAL DESCRIPTION: 12x12 Beige Floor Tile

MATERIAL LOCATION: 1959 Building- Rooms 101 and 104

MATERIAL QUANTITY: 900 MATERIAL UNITS: SF

DAMAGE QUANTITY: 0 DAMAGE UNITS: SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 10/19/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23871	BUILDING ID:	4080
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Hoyne School	INSPECTION DATE:	9/20/2019		
ADDRESS:	8905 S Crandon	IDPH LICENSE NO:	100-11070		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	06
MATERIAL DESCRIPTION:	Wall Boards (NOT OBSERVED)
HISTORICAL AHERA DAMAGE CATEGORY	
HISTORICAL DAMAGE REASON:	
HISTORICAL RESPONSE ACTION:	Follow O&M Plan
ASBESTOS TYPE:	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION:

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Not Observed Multiple Years

Inspector's Signature: _____ Date: 09/20/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23871	BUILDING ID:	4080
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Hoyne School	REVIEW DATE:	10/19/2019		
ADDRESS:	8905 S Crandon	IDPH LICENSE NO:	100-11070		

HOMOGENEOUS AREA: 06

MATERIAL DESCRIPTION: Wall Boards (NOT OBSERVED)

MATERIAL LOCATION:

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 10/19/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23871	BUILDING ID:	4080
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Hoyne School	INSPECTION DATE:	9/20/2019		
ADDRESS:	8905 S Crandon	IDPH LICENSE NO:	100-11070		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	07	
MATERIAL DESCRIPTION:	Beige Multi-Colored Linoleum	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1955 Building- Room 106

MATERIAL QUANTITY: 1500

MATERIAL UNITS: SF

DAMAGE QUANTITY:

DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature: _____ Date: 09/20/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23871	BUILDING ID:	4080
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Hoyne School	REVIEW DATE:	10/19/2019		
ADDRESS:	8905 S Crandon	IDPH LICENSE NO:	100-11070		

HOMOGENEOUS AREA: **07**

MATERIAL DESCRIPTION: **Beige Multi-Colored Linoleum**

MATERIAL LOCATION: **1955 Building- Room 106**

MATERIAL QUANTITY: **1500**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/19/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23871	BUILDING ID:	4080
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Hoyne School	INSPECTION DATE:	9/20/2019		
ADDRESS:	8905 S Crandon	IDPH LICENSE NO:	100-11070		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	08FT1		
MATERIAL DESCRIPTION:	12"x12" Gray Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Classrooms & Hallways of 1955 Building, including Rooms 105, 107, 109, 111		
MATERIAL QUANTITY:	3000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/20/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23871	BUILDING ID:	4080
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Hoyne School	REVIEW DATE:	10/19/2019		
ADDRESS:	8905 S Crandon	IDPH LICENSE NO:	100-11070		

HOMOGENEOUS AREA:	08FT1				
MATERIAL DESCRIPTION:	12"x12" Gray Floor Tile Mastic				
MATERIAL LOCATION:	Classrooms & Hallways of 1955 Building, including Rooms 105, 107, 109, 111				
MATERIAL QUANTITY:	3000	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/19/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23871	BUILDING ID:	4080
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Hoyne School	INSPECTION DATE:	9/20/2019		
ADDRESS:	8905 S Crandon	IDPH LICENSE NO:	100-11070		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	08FT2		
MATERIAL DESCRIPTION:	12x12 Beige Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Classrooms of 1955 Building, including Rooms 110, 112, 114		
MATERIAL QUANTITY:	2000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:	Room 108 Abated 2019		

Inspector's Signature: _____ Date: 09/20/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23871	BUILDING ID:	4080
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Hoyne School	REVIEW DATE:	10/19/2019		
ADDRESS:	8905 S Crandon	IDPH LICENSE NO:	100-11070		

HOMOGENEOUS AREA:	08FT2		
MATERIAL DESCRIPTION:	12x12 Beige Floor Tile Mastic		
MATERIAL LOCATION:	Classrooms of 1955 Building, including Rooms 110, 112, 114		
MATERIAL QUANTITY:	2000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 10/19/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23871	BUILDING ID:	4080
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Hoyne School	INSPECTION DATE:	9/20/2019		
ADDRESS:	8905 S Crandon	IDPH LICENSE NO:	100-11070		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	08FT3	
MATERIAL DESCRIPTION:	12x12 White Floor Tile Mastic	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Main Office, Rooms 101 and 104, West and South Halls

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 09/20/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23871	BUILDING ID:	4080
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Hoyne School	REVIEW DATE:	10/19/2019		
ADDRESS:	8905 S Crandon	IDPH LICENSE NO:	100-11070		

HOMOGENEOUS AREA: **08FT3**

MATERIAL DESCRIPTION: **12x12 White Floor Tile Mastic**

MATERIAL LOCATION: **Main Office, Rooms 101 and 104, West and South Halls**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/19/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23871	BUILDING ID:	4080
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Hoyne School	INSPECTION DATE:	9/20/2019		
ADDRESS:	8905 S Crandon	IDPH LICENSE NO:	100-11070		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	09FT1	
MATERIAL DESCRIPTION:	9x9 Dark Gray Floor Tile Mastic	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1959 Building- Rooms 102 and 103

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Not Observed- No ACBM

Inspector's Signature: _____ Date: 09/20/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23871	BUILDING ID:	4080
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Hoyne School	REVIEW DATE:	10/19/2019		
ADDRESS:	8905 S Crandon	IDPH LICENSE NO:	100-11070		

HOMOGENEOUS AREA: **09FT1**

MATERIAL DESCRIPTION: **9x9 Dark Gray Floor Tile Mastic**

MATERIAL LOCATION: **1959 Building- Rooms 102 and 103**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/19/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23871	BUILDING ID:	4080
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Hoyne School	INSPECTION DATE:	9/20/2019		
ADDRESS:	8905 S Crandon	IDPH LICENSE NO:	100-11070		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	09FT2	
MATERIAL DESCRIPTION:	12x12 Beige Floor Tile Mastic	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1959 Building- Rooms 101 and 104

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 09/20/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23871	BUILDING ID:	4080
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Hoyne School	REVIEW DATE:	10/19/2019		
ADDRESS:	8905 S Crandon	IDPH LICENSE NO:	100-11070		

HOMOGENEOUS AREA: **09FT2**

MATERIAL DESCRIPTION: **12x12 Beige Floor Tile Mastic**

MATERIAL LOCATION: **1959 Building- Rooms 101 and 104**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/19/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23871	BUILDING ID:	4080
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Hoyne School	INSPECTION DATE:	9/20/2019		
ADDRESS:	8905 S Crandon	IDPH LICENSE NO:	100-11070		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	10	
MATERIAL DESCRIPTION:	Black Vinyl Baseboard-NOT OBSERVED	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1955 Building Rooms 105, 107, 108, 109, 110, 112, 114

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Not Observed 2019- Has Cream Ceramic Baseboard

Inspector's Signature: _____ Date: 09/20/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23871	BUILDING ID:	4080
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Hoyne School	REVIEW DATE:	10/19/2019		
ADDRESS:	8905 S Crandon	IDPH LICENSE NO:	100-11070		

HOMOGENEOUS AREA: **10**

MATERIAL DESCRIPTION: **Black Vinyl Baseboard-NOT OBSERVED**

MATERIAL LOCATION: **1955 Building Rooms 105, 107, 108, 109, 110, 112, 114**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/19/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23871	BUILDING ID:	4080
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Hoyne School	INSPECTION DATE:	9/20/2019		
ADDRESS:	8905 S Crandon	IDPH LICENSE NO:	100-11070		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	11	
MATERIAL DESCRIPTION:	Black Vinyl Baseboard Mastic-NOT OBSERVED	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1955 Building, Rooms 105, 107, 108, 109, 110, 112, 114

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Not Observed 2019 - Has Cream Ceramic Baseboards

Inspector's Signature: _____ Date: 09/20/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23871	BUILDING ID:	4080
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Hoyne School	REVIEW DATE:	10/19/2019		
ADDRESS:	8905 S Crandon	IDPH LICENSE NO:	100-11070		

HOMOGENEOUS AREA: **11**

MATERIAL DESCRIPTION: **Black Vinyl Baseboard Mastic-NOT OBSERVED**

MATERIAL LOCATION: **1955 Building, Rooms 105, 107, 108, 109, 110, 112, 114**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/19/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23871** BUILDING ID: **4080**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**
SCHOOL NAME: **Hoyne School** INSPECTION DATE: **9/20/2019**
ADDRESS: **8905 S Crandon** IDPH LICENSE NO: **100-11070**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12**
MATERIAL DESCRIPTION: **Firebrick ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **09/20/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23871	BUILDING ID:	4080
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Hoyne School	REVIEW DATE:	10/19/2019		
ADDRESS:	8905 S Crandon	IDPH LICENSE NO:	100-11070		

HOMOGENEOUS AREA: **12**

MATERIAL DESCRIPTION: **Firebrick ABATED**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/19/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23871	BUILDING ID:	4080
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Hoyne School	INSPECTION DATE:	9/20/2019		
ADDRESS:	8905 S Crandon	IDPH LICENSE NO:	100-11070		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	13	
MATERIAL DESCRIPTION:	Incinerator Door	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Boiler Room

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 09/20/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23871	BUILDING ID:	4080
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Hoyne School	REVIEW DATE:	10/19/2019		
ADDRESS:	8905 S Crandon	IDPH LICENSE NO:	100-11070		

HOMOGENEOUS AREA: **13**

MATERIAL DESCRIPTION: **Incinerator Door**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/19/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23871	BUILDING ID:	4080
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Hoyne School	INSPECTION DATE:	9/20/2019		
ADDRESS:	8905 S Crandon	IDPH LICENSE NO:	100-11070		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	14		
MATERIAL DESCRIPTION:	Light Beige Linoleum		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 106, Kitchen		
MATERIAL QUANTITY:	2020	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/20/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23871	BUILDING ID:	4080
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Hoyne School	REVIEW DATE:	10/19/2019		
ADDRESS:	8905 S Crandon	IDPH LICENSE NO:	100-11070		

HOMOGENEOUS AREA:	14		
MATERIAL DESCRIPTION:	Light Beige Linoleum		
MATERIAL LOCATION:	Room 106, Kitchen		
MATERIAL QUANTITY:	2020	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/19/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23871	BUILDING ID:	4080
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Hoyne School	INSPECTION DATE:	9/20/2019		
ADDRESS:	8905 S Crandon	IDPH LICENSE NO:	100-11070		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	16	
MATERIAL DESCRIPTION:	Black Vinyl Baseboard	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1939 Bldg. Rooms 101, 102, 103, 104, 111**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **09/20/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23871	BUILDING ID:	4080
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Hoyne School	REVIEW DATE:	10/19/2019		
ADDRESS:	8905 S Crandon	IDPH LICENSE NO:	100-11070		

HOMOGENEOUS AREA: **16**

MATERIAL DESCRIPTION: **Black Vinyl Baseboard**

MATERIAL LOCATION: **1939 Bldg. Rooms 101, 102, 103, 104, 111**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/19/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23871	BUILDING ID:	4080
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Hoyne School	INSPECTION DATE:	9/20/2019		
ADDRESS:	8905 S Crandon	IDPH LICENSE NO:	100-11070		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	17		
MATERIAL DESCRIPTION:	Black Vinyl Baseboard Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1939 Building- Rooms 101, 102, 103, 104		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature: _____ Date: 09/20/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23871	BUILDING ID:	4080
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Hoyne School	REVIEW DATE:	10/19/2019		
ADDRESS:	8905 S Crandon	IDPH LICENSE NO:	100-11070		

HOMOGENEOUS AREA:	17		
MATERIAL DESCRIPTION:	Black Vinyl Baseboard Mastic		
MATERIAL LOCATION:	1939 Building- Rooms 101, 102, 103, 104		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/19/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23871	BUILDING ID:	4080
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Hoyne School	INSPECTION DATE:	9/20/2019		
ADDRESS:	8905 S Crandon	IDPH LICENSE NO:	100-11070		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	18	
MATERIAL DESCRIPTION:	Light Beige Linoleum Adhesive	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 106, Kitchen

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 09/20/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23871	BUILDING ID:	4080
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Hoyne School	REVIEW DATE:	10/19/2019		
ADDRESS:	8905 S Crandon	IDPH LICENSE NO:	100-11070		

HOMOGENEOUS AREA: **18**

MATERIAL DESCRIPTION: **Light Beige Linoleum Adhesive**

MATERIAL LOCATION: **Room 106, Kitchen**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/19/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23871	BUILDING ID:	4080
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Hoyne School	INSPECTION DATE:	9/20/2019		
ADDRESS:	8905 S Crandon	IDPH LICENSE NO:	100-11070		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	19		
MATERIAL DESCRIPTION:	Gray Vinyl Baseboard Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1959 Building- Room 101, 102, 103, 104, 111		
MATERIAL QUANTITY:	210	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature: _____ Date: 09/20/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23871	BUILDING ID:	4080
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Hoyne School	REVIEW DATE:	10/19/2019		
ADDRESS:	8905 S Crandon	IDPH LICENSE NO:	100-11070		

HOMOGENEOUS AREA: **19**

MATERIAL DESCRIPTION: **Gray Vinyl Baseboard Mastic**

MATERIAL LOCATION: **1959 Building- Room 101, 102, 103, 104, 111**

MATERIAL QUANTITY:	210	MATERIAL UNITS:	LF
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/19/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23871	BUILDING ID:	4080
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Hoyne School	INSPECTION DATE:	9/20/2019		
ADDRESS:	8905 S Crandon	IDPH LICENSE NO:	100-11070		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	20	
MATERIAL DESCRIPTION:	Linoleum ABATED	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Abated	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1959 Building- Rooms 101, 102, 103, 104

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 09/20/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23871	BUILDING ID:	4080
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Hoyne School	REVIEW DATE:	10/19/2019		
ADDRESS:	8905 S Crandon	IDPH LICENSE NO:	100-11070		

HOMOGENEOUS AREA: **20**

MATERIAL DESCRIPTION: **Linoleum ABATED**

MATERIAL LOCATION: **1959 Building- Rooms 101, 102, 103, 104**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/19/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23871	BUILDING ID:	4080
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Hoyne School	INSPECTION DATE:	9/20/2019		
ADDRESS:	8905 S Crandon	IDPH LICENSE NO:	100-11070		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	22	
MATERIAL DESCRIPTION:	Boiler Gaskets ABATED	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Abated	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Boiler Room

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 09/20/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23871	BUILDING ID:	4080
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Hoyne School	REVIEW DATE:	10/19/2019		
ADDRESS:	8905 S Crandon	IDPH LICENSE NO:	100-11070		

HOMOGENEOUS AREA: **22**

MATERIAL DESCRIPTION: **Boiler Gaskets ABATED**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/19/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23871	BUILDING ID:	4080
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Hoyne School	INSPECTION DATE:	9/20/2019		
ADDRESS:	8905 S Crandon	IDPH LICENSE NO:	100-11070		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	23	
MATERIAL DESCRIPTION:	Plaster ABATED	
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Abated	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throughout School

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 09/20/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23871	BUILDING ID:	4080
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Hoyne School	REVIEW DATE:	10/19/2019		
ADDRESS:	8905 S Crandon	IDPH LICENSE NO:	100-11070		

HOMOGENEOUS AREA: **23**

MATERIAL DESCRIPTION: **Plaster ABATED**

MATERIAL LOCATION: **Throughout School**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/19/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23871	BUILDING ID:	4080
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Hoyne School	INSPECTION DATE:	9/20/2019		
ADDRESS:	8905 S Crandon	IDPH LICENSE NO:	100-11070		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	24		
MATERIAL DESCRIPTION:	1 x 1 White Ceiling Tile		
HISTORICAL AHERA DAMAGE CATEGORY	7 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	North and West Corridors, Rooms 105, 106, 107, 108, 109, 110, 111, 112, 113, 114		
MATERIAL QUANTITY:	9824	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/20/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23871	BUILDING ID:	4080
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Hoyne School	REVIEW DATE:	10/19/2019		
ADDRESS:	8905 S Crandon	IDPH LICENSE NO:	100-11070		

HOMOGENEOUS AREA:	24				
MATERIAL DESCRIPTION:	1 x 1 White Ceiling Tile				
MATERIAL LOCATION:	North and West Corridors, Rooms 105, 106, 107, 108, 109, 110, 111, 112, 113, 114				
MATERIAL QUANTITY:	9824	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 10/19/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23871	BUILDING ID:	4080
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Hoyne School	INSPECTION DATE:	9/20/2019		
ADDRESS:	8905 S Crandon	IDPH LICENSE NO:	100-11070		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	25		
MATERIAL DESCRIPTION:	Beige and Tan Ceramic Tile Grout		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	East Girls and Boys Washrooms, East and West Entrances		
MATERIAL QUANTITY:	996	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/20/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23871	BUILDING ID:	4080
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Hoyne School	REVIEW DATE:	10/19/2019		
ADDRESS:	8905 S Crandon	IDPH LICENSE NO:	100-11070		

HOMOGENEOUS AREA:	25		
MATERIAL DESCRIPTION:	Beige and Tan Ceramic Tile Grout		
MATERIAL LOCATION:	East Girls and Boys Washrooms, East and West Entrances		
MATERIAL QUANTITY:	996	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/19/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23871	BUILDING ID:	4080
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Hoyne School	INSPECTION DATE:	9/20/2019		
ADDRESS:	8905 S Crandon	IDPH LICENSE NO:	100-11070		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	26		
MATERIAL DESCRIPTION:	Beige and Tan Ceramic Tile Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	East Girls and Boys Washrooms, East and West Entrances		
MATERIAL QUANTITY:	996	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/20/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23871	BUILDING ID:	4080
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Hoyne School	REVIEW DATE:	10/19/2019		
ADDRESS:	8905 S Crandon	IDPH LICENSE NO:	100-11070		

HOMOGENEOUS AREA:	26		
MATERIAL DESCRIPTION:	Beige and Tan Ceramic Tile Adhesive		
MATERIAL LOCATION:	East Girls and Boys Washrooms, East and West Entrances		
MATERIAL QUANTITY:	996	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 10/19/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23871	BUILDING ID:	4080
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Hoyne School	INSPECTION DATE:	9/20/2019		
ADDRESS:	8905 S Crandon	IDPH LICENSE NO:	100-11070		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	27		
MATERIAL DESCRIPTION:	12 x 12 Light Grey Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Multipurpose Room		
MATERIAL QUANTITY:	2728	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/20/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23871	BUILDING ID:	4080
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Hoyne School	REVIEW DATE:	10/19/2019		
ADDRESS:	8905 S Crandon	IDPH LICENSE NO:	100-11070		

HOMOGENEOUS AREA: 27

MATERIAL DESCRIPTION: 12 x 12 Light Grey Floor Tile

MATERIAL LOCATION: Multipurpose Room

MATERIAL QUANTITY: 2728

MATERIAL UNITS: SF

DAMAGE QUANTITY: 0

DAMAGE UNITS: SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 10/19/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23871	BUILDING ID:	4080
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Hoyne School	INSPECTION DATE:	9/20/2019		
ADDRESS:	8905 S Crandon	IDPH LICENSE NO:	100-11070		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	27M		
MATERIAL DESCRIPTION:	12 x 12 Light Grey Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Multipurpose Room		
MATERIAL QUANTITY:	2728	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/20/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23871	BUILDING ID:	4080
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Hoyne School	REVIEW DATE:	10/19/2019		
ADDRESS:	8905 S Crandon	IDPH LICENSE NO:	100-11070		

HOMOGENEOUS AREA:	27M		
MATERIAL DESCRIPTION:	12 x 12 Light Grey Floor Tile Mastic		
MATERIAL LOCATION:	Multipurpose Room		
MATERIAL QUANTITY:	2728	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/19/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23871	BUILDING ID:	4080
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Hoyne School	INSPECTION DATE:	9/20/2019		
ADDRESS:	8905 S Crandon	IDPH LICENSE NO:	100-11070		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	28		
MATERIAL DESCRIPTION:	12 x 12 Beige and White Checkerboard Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Main Office Restroom		
MATERIAL QUANTITY:	120	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/20/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23871	BUILDING ID:	4080
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Hoyne School	REVIEW DATE:	10/19/2019		
ADDRESS:	8905 S Crandon	IDPH LICENSE NO:	100-11070		

HOMOGENEOUS AREA:	28		
MATERIAL DESCRIPTION:	12 x 12 Beige and White Checkerboard Floor Tile		
MATERIAL LOCATION:	Main Office Restroom		
MATERIAL QUANTITY:	120	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 10/19/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23871	BUILDING ID:	4080
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Hoyne School	INSPECTION DATE:	9/20/2019		
ADDRESS:	8905 S Crandon	IDPH LICENSE NO:	100-11070		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	28M		
MATERIAL DESCRIPTION:	12 x 12 Beige and White Checkerboard Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Main Office Restroom		
MATERIAL QUANTITY:	120	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/20/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23871	BUILDING ID:	4080
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Hoyne School	REVIEW DATE:	10/19/2019		
ADDRESS:	8905 S Crandon	IDPH LICENSE NO:	100-11070		

HOMOGENEOUS AREA:	28M				
MATERIAL DESCRIPTION:	12 x 12 Beige and White Checkerboard Floor Tile Mastic				
MATERIAL LOCATION:	Main Office Restroom				
MATERIAL QUANTITY:	120	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/19/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23871	BUILDING ID:	4080
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Hoyne School	INSPECTION DATE:	9/20/2019		
ADDRESS:	8905 S Crandon	IDPH LICENSE NO:	100-11070		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	29		
MATERIAL DESCRIPTION:	Carpet Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Main Office		
MATERIAL QUANTITY:	748	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/20/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23871	BUILDING ID:	4080
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Hoyne School	REVIEW DATE:	10/19/2019		
ADDRESS:	8905 S Crandon	IDPH LICENSE NO:	100-11070		

HOMOGENEOUS AREA: 29

MATERIAL DESCRIPTION: Carpet Adhesive

MATERIAL LOCATION: Main Office

MATERIAL QUANTITY:	748	MATERIAL UNITS:	SF
--------------------	-----	-----------------	----

DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
------------------	---	---------------	----

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 10/19/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23871	BUILDING ID:	4080
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Hoyne School	INSPECTION DATE:	9/20/2019		
ADDRESS:	8905 S Crandon	IDPH LICENSE NO:	100-11070		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	30		
MATERIAL DESCRIPTION:	Insulation in Vault Door		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Main Office		
MATERIAL QUANTITY:	1	MATERIAL UNITS:	EA
DAMAGE QUANTITY:	0	DAMAGE UNITS:	EA
COMMENTS:			

Inspector's Signature: _____ Date: 09/20/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23871	BUILDING ID:	4080
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Hoyne School	REVIEW DATE:	10/19/2019		
ADDRESS:	8905 S Crandon	IDPH LICENSE NO:	100-11070		

HOMOGENEOUS AREA: **30**

MATERIAL DESCRIPTION: **Insulation in Vault Door**

MATERIAL LOCATION: **Main Office**

MATERIAL QUANTITY: **1**

MATERIAL UNITS: **EA**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **EA**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/19/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23871	BUILDING ID:	4080
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Hoyne School	INSPECTION DATE:	9/20/2019		
ADDRESS:	8905 S Crandon	IDPH LICENSE NO:	100-11070		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	31		
MATERIAL DESCRIPTION:	2 x 2 White Lay-In Ceiling Tile		
HISTORICAL AHERA DAMAGE CATEGORY	7 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Main Office, Rooms 101, 103, 115 and 116		
MATERIAL QUANTITY:	4484	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/20/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23871	BUILDING ID:	4080
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Hoyne School	REVIEW DATE:	10/19/2019		
ADDRESS:	8905 S Crandon	IDPH LICENSE NO:	100-11070		

HOMOGENEOUS AREA:	31		
MATERIAL DESCRIPTION:	2 x 2 White Lay-In Ceiling Tile		
MATERIAL LOCATION:	Main Office, Rooms 101, 103, 115 and 116		
MATERIAL QUANTITY:	4484	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/19/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23871	BUILDING ID:	4080
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Hoyne School	INSPECTION DATE:	9/20/2019		
ADDRESS:	8905 S Crandon	IDPH LICENSE NO:	100-11070		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	32		
MATERIAL DESCRIPTION:	9 x 9 Beige Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 104		
MATERIAL QUANTITY:	936	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/20/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23871	BUILDING ID:	4080
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Hoyne School	REVIEW DATE:	10/19/2019		
ADDRESS:	8905 S Crandon	IDPH LICENSE NO:	100-11070		

HOMOGENEOUS AREA:	32		
MATERIAL DESCRIPTION:	9 x 9 Beige Floor Tile		
MATERIAL LOCATION:	Room 104		
MATERIAL QUANTITY:	936	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/19/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23871	BUILDING ID:	4080
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Hoyne School	INSPECTION DATE:	9/20/2019		
ADDRESS:	8905 S Crandon	IDPH LICENSE NO:	100-11070		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	32M		
MATERIAL DESCRIPTION:	9 x 9 Beige Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 104		
MATERIAL QUANTITY:	936	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/20/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23871	BUILDING ID:	4080
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Hoyne School	REVIEW DATE:	10/19/2019		
ADDRESS:	8905 S Crandon	IDPH LICENSE NO:	100-11070		

HOMOGENEOUS AREA: **32M**

MATERIAL DESCRIPTION: **9 x 9 Beige Floor Tile Mastic**

MATERIAL LOCATION: **Room 104**

MATERIAL QUANTITY:	936	MATERIAL UNITS:	SF
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/19/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23871	BUILDING ID:	4080
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Hoyne School	INSPECTION DATE:	9/20/2019		
ADDRESS:	8905 S Crandon	IDPH LICENSE NO:	100-11070		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	33		
MATERIAL DESCRIPTION:	2 x 4 Yellow Lay-In Ceiling Panels		
HISTORICAL AHERA DAMAGE CATEGORY	7 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Kitchen 118		
MATERIAL QUANTITY:	1020	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/20/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23871	BUILDING ID:	4080
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Hoyne School	REVIEW DATE:	10/19/2019		
ADDRESS:	8905 S Crandon	IDPH LICENSE NO:	100-11070		

HOMOGENEOUS AREA: **33**

MATERIAL DESCRIPTION: **2 x 4 Yellow Lay-In Ceiling Panels**

MATERIAL LOCATION: **Kitchen 118**

MATERIAL QUANTITY: **1020**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/19/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23871	BUILDING ID:	4080
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Hoyne School	INSPECTION DATE:	9/20/2019		
ADDRESS:	8905 S Crandon	IDPH LICENSE NO:	100-11070		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	34		
MATERIAL DESCRIPTION:	2 x 4 White Lay-In Ceiling Tile		
HISTORICAL AHERA DAMAGE CATEGORY	7 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Principal's Office		
MATERIAL QUANTITY:	216	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/20/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23871	BUILDING ID:	4080
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Hoyne School	REVIEW DATE:	10/19/2019		
ADDRESS:	8905 S Crandon	IDPH LICENSE NO:	100-11070		

HOMOGENEOUS AREA:	34		
MATERIAL DESCRIPTION:	2 x 4 White Lay-In Ceiling Tile		
MATERIAL LOCATION:	Principal's Office		
MATERIAL QUANTITY:	216	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 10/19/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23871	BUILDING ID:	4080
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Hoyne School	INSPECTION DATE:	9/20/2019		
ADDRESS:	8905 S Crandon	IDPH LICENSE NO:	100-11070		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	35		
MATERIAL DESCRIPTION:	5" x 5" Brown Ceramic Floor Tile Grout		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	NE Courtyard Entrance		
MATERIAL QUANTITY:	96	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/20/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23871	BUILDING ID:	4080
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Hoyne School	REVIEW DATE:	10/19/2019		
ADDRESS:	8905 S Crandon	IDPH LICENSE NO:	100-11070		

HOMOGENEOUS AREA:	35		
MATERIAL DESCRIPTION:	5" x 5" Brown Ceramic Floor Tile Grout		
MATERIAL LOCATION:	NE Courtyard Entrance		
MATERIAL QUANTITY:	96	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 10/19/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23871	BUILDING ID:	4080
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Hoyne School	INSPECTION DATE:	9/20/2019		
ADDRESS:	8905 S Crandon	IDPH LICENSE NO:	100-11070		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	36		
MATERIAL DESCRIPTION:	5" x 5" Brown Ceramic Floor Tile Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	NE Courtyard Entrance		
MATERIAL QUANTITY:	96	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/20/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23871	BUILDING ID:	4080
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Hoyne School	REVIEW DATE:	10/19/2019		
ADDRESS:	8905 S Crandon	IDPH LICENSE NO:	100-11070		

HOMOGENEOUS AREA:	36		
MATERIAL DESCRIPTION:	5" x 5" Brown Ceramic Floor Tile Adhesive		
MATERIAL LOCATION:	NE Courtyard Entrance		
MATERIAL QUANTITY:	96	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 10/19/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23871	BUILDING ID:	4080
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Hoyne School	INSPECTION DATE:	9/20/2019		
ADDRESS:	8905 S Crandon	IDPH LICENSE NO:	100-11070		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	37		
MATERIAL DESCRIPTION:	Gray Vinyl Baseboard Panels		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1959 Building- Rooms 101-104 and 111		
MATERIAL QUANTITY:	210	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature: _____ Date: 09/20/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23871	BUILDING ID:	4080
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Hoyne School	REVIEW DATE:	10/19/2019		
ADDRESS:	8905 S Crandon	IDPH LICENSE NO:	100-11070		

HOMOGENEOUS AREA:	37		
MATERIAL DESCRIPTION:	Gray Vinyl Baseboard Panels		
MATERIAL LOCATION:	1959 Building- Rooms 101-104 and 111		
MATERIAL QUANTITY:	210	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/19/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23871	BUILDING ID:	4080
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Hoyne School	INSPECTION DATE:	9/20/2019		
ADDRESS:	8905 S Crandon	IDPH LICENSE NO:	100-11070		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	38		
MATERIAL DESCRIPTION:	Black Fire Retardent		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout 1959 Addition		
MATERIAL QUANTITY:	1500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/20/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23871	BUILDING ID:	4080
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Hoyne School	REVIEW DATE:	10/19/2019		
ADDRESS:	8905 S Crandon	IDPH LICENSE NO:	100-11070		

HOMOGENEOUS AREA:	38		
MATERIAL DESCRIPTION:	Black Fire Retardant		
MATERIAL LOCATION:	Throughout 1959 Addition		
MATERIAL QUANTITY:	1500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/19/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23871	BUILDING ID:	4080
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Hoyne School	INSPECTION DATE:	9/20/2019		
ADDRESS:	8905 S Crandon	IDPH LICENSE NO:	100-11070		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	39		
MATERIAL DESCRIPTION:	Plaster Ceiling		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Boys and Girls Toilets and Janitor Closet - 1998 Addition		
MATERIAL QUANTITY:	600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/20/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23871	BUILDING ID:	4080
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Hoyne School	REVIEW DATE:	10/19/2019		
ADDRESS:	8905 S Crandon	IDPH LICENSE NO:	100-11070		

HOMOGENEOUS AREA:	39		
MATERIAL DESCRIPTION:	Plaster Ceiling		
MATERIAL LOCATION:	Boys and Girls Toilets and Janitor Closet - 1998 Addition		
MATERIAL QUANTITY:	600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/19/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23871	BUILDING ID:	4080
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Hoyne School	INSPECTION DATE:	9/20/2019		
ADDRESS:	8905 S Crandon	IDPH LICENSE NO:	100-11070		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	40		
MATERIAL DESCRIPTION:	Ceramic Baseboard Grout		
MATERIAL LOCATION:	Halls and Classrooms		
MATERIAL QUANTITY:	1200	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Barely Reachable	DAMAGE REASON:	
		DAMAGE REASON:	
DAMAGE QUANTITY:	0	DAMAGE REASON:	
		DAMAGE UNITS:	SF

COMMENTS:
Throughout- Beneath Vinyl where Vinyl is Present

Inspector's Signature: _____ Date: **09/20/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23871	BUILDING ID:	4080
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Hoyne School	REVIEW DATE:	10/19/2019		
ADDRESS:	8905 S Crandon	IDPH LICENSE NO:	100-11070		

HOMOGENEOUS AREA:	40		
MATERIAL DESCRIPTION:	Ceramic Baseboard Grout		
MATERIAL LOCATION:	Halls and Classrooms		
MATERIAL QUANTITY:	1200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **10/19/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23871	BUILDING ID:	4080
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Hoyne School	INSPECTION DATE:	9/20/2019		
ADDRESS:	8905 S Crandon	IDPH LICENSE NO:	100-11070		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	45		
MATERIAL DESCRIPTION:	12" Orange Mottled Vinyl Floor Tile		
MATERIAL LOCATION:	Room 108		
MATERIAL QUANTITY:	75	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE REASON:	
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/20/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23871	BUILDING ID:	4080
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Hoyne School	REVIEW DATE:	10/19/2019		
ADDRESS:	8905 S Crandon	IDPH LICENSE NO:	100-11070		

HOMOGENEOUS AREA: **45**

MATERIAL DESCRIPTION: **12" Orange Mottled Vinyl Floor Tile**

MATERIAL LOCATION: **Room 108**

MATERIAL QUANTITY: **75**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **10/19/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23871	BUILDING ID:	4080
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Hoyne School	INSPECTION DATE:	9/20/2019		
ADDRESS:	8905 S Crandon	IDPH LICENSE NO:	100-11070		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	46		
MATERIAL DESCRIPTION:	12" Orange Vinyl Floor Tile Mastic		
MATERIAL LOCATION:	Room 108		
MATERIAL QUANTITY:	75	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Not Reachable	DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE REASON:	
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/20/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23871** BUILDING ID: **4080**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Hoyne School** REVIEW DATE: **10/19/2019**
ADDRESS: **8905 S Crandon** IDPH LICENSE NO: **100-11070**

HOMOGENEOUS AREA: **46**
MATERIAL DESCRIPTION: **12" Orange Vinyl Floor Tile Mastic**
MATERIAL LOCATION: **Room 108**
MATERIAL QUANTITY: **75** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **10/19/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23871	BUILDING ID:	4080
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Hoyne School	INSPECTION DATE:	9/20/2019		
ADDRESS:	8905 S Crandon	IDPH LICENSE NO:	100-11070		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	44		
MATERIAL DESCRIPTION:	12" Tan Mottled Vinyl Floor Tile Mastic		
MATERIAL LOCATION:	Room 108		
MATERIAL QUANTITY:	150	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Not Reachable	DAMAGE REASON:	
		DAMAGE REASON:	
DAMAGE QUANTITY:	0	DAMAGE REASON:	
		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: **09/20/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23871	BUILDING ID:	4080
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Hoyne School	REVIEW DATE:	10/19/2019		
ADDRESS:	8905 S Crandon	IDPH LICENSE NO:	100-11070		

HOMOGENEOUS AREA: **44**

MATERIAL DESCRIPTION: **12" Tan Mottled Vinyl Floor Tile Mastic**

MATERIAL LOCATION: **Room 108**

MATERIAL QUANTITY: **150**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **10/19/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23871	BUILDING ID:	4080
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Hoyne School	INSPECTION DATE:	9/20/2019		
ADDRESS:	8905 S Crandon	IDPH LICENSE NO:	100-11070		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	43		
MATERIAL DESCRIPTION:	12" Tan Mottled Vinyl Floor Tile		
MATERIAL LOCATION:	Room 108		
MATERIAL QUANTITY:	150	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE REASON:	
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/20/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23871** BUILDING ID: **4080**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Hoyne School** REVIEW DATE: **10/19/2019**
ADDRESS: **8905 S Crandon** IDPH LICENSE NO: **100-11070**

HOMOGENEOUS AREA: **43**
MATERIAL DESCRIPTION: **12" Tan Mottled Vinyl Floor Tile**
MATERIAL LOCATION: **Room 108**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **10/19/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23871	BUILDING ID:	4080
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Hoyne School	INSPECTION DATE:	9/20/2019		
ADDRESS:	8905 S Crandon	IDPH LICENSE NO:	100-11070		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	41		
MATERIAL DESCRIPTION:	12" Gray Mottled Vinyl Floor Tile		
MATERIAL LOCATION:	Room 108		
MATERIAL QUANTITY:	525	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE REASON:	
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/20/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23871** BUILDING ID: **4080**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Hoyne School** REVIEW DATE: **10/19/2019**
ADDRESS: **8905 S Crandon** IDPH LICENSE NO: **100-11070**

HOMOGENEOUS AREA: **41**
MATERIAL DESCRIPTION: **12" Gray Mottled Vinyl Floor Tile**
MATERIAL LOCATION: **Room 108**
MATERIAL QUANTITY: **525** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **10/19/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23871	BUILDING ID:	4080
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Hoyne School	INSPECTION DATE:	9/20/2019		
ADDRESS:	8905 S Crandon	IDPH LICENSE NO:	100-11070		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	42		
MATERIAL DESCRIPTION:	12" Gray Mottled Vinyl Floor Tile Mastic		
MATERIAL LOCATION:	Room 108		
MATERIAL QUANTITY:	525	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Not Reachable	DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE REASON:	
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 09/20/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23871	BUILDING ID:	4080
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Hoyne School	REVIEW DATE:	10/19/2019		
ADDRESS:	8905 S Crandon	IDPH LICENSE NO:	100-11070		

HOMOGENEOUS AREA: **42**

MATERIAL DESCRIPTION: **12" Gray Mottled Vinyl Floor Tile Mastic**

MATERIAL LOCATION: **Room 108**

MATERIAL QUANTITY: **525**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **10/19/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

APPENDIX B

Inspector and Management Planner Licenses

CERTIFICATE OF ACHIEVEMENT ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that MALLORY L. JONES
has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the
examination on 03/18/2019 with a minimum score of 70% or better. Training was in accordance
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:
Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.

03/18/2019

Course Dates:

03/18/2020

Expires:

1903BIR10

Certificate Number:



PUBLIC HEALTH & SAFETY inc.

Environmental and Occupational Services
37 S. Ashland Ave., Chicago, IL 60607

www.public-health-safety.com

Office: 312-491-0081
Fax: 312-421-2901

Director of Training

Nicholas J. Peneff

Doctor of Public Health


Phone: 312-491-0081

FORM # A-010B

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License



ASBESTOS PROFESSIONAL LICENSE

ID NUMBER

100 - 11070

ISSUED

3/6/2019

EXPIRES

05/15/2020

MALLORY JONES

524 HOMELAND ROAD

MATTESON, IL 60443

Environmental Health



ENDORSEMENTS

SUPERVISOR/WORKER

INSPECTOR

TC EXPIRES

4/9/2019

3/19/2019

PROJECT MANAGER

4/9/2019

AIR SAMPLING PROFESSIONAL

Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois
Department of Public Health
This license is valid only when accompanied by a valid
training course certificate.

Reliable
Environmental
Solutions, Inc. **RES**

This is to certify that **Amy J. Williams**

*has on 04/03/19, in Springfield, Illinois,
completed the requirements for asbestos accreditation under Section 206 of TSCA Title II*

Asbestos Building Inspector Refresher Training

*as accredited by the State of Illinois and approved by the U.S.E.P.A. under 40 CFR 763 (AHERA)
and passed the associated examination with a score of 70% or higher*

Course Date: April 03, 2019

COURSE LENGTH: 4 HOURS

Examination Date: April 03, 2019

Expiration Date: April 03, 2020

Certificate Number: BIR/0808

William S. Williams

Training Program Manager, William S. Williams

4211 Westgate Drive, Springfield, Illinois ☐ 217.787.9800 ☐ 217.787.9801 FAX ☐ www.ReliableEnv.com



2539 Vandalia Street, Collinsville, IL 62234 * Phone: 618-855-8764

Environmental and Occupational Safety & Health Training

Does hereby certify

William Williams

4211 Westgate Drive, Springfield, IL 62711

*Has successfully completed and passed the course examination with at least
70% for re-accreditation under AHERA (Title II)*

Asbestos Management Planner Refresher


Class Date: 02/15/2019
Examination Date: 02/15/2019
STC Certificate Number: STC-20190215-000527AMPR
Certification Expiration: 02/15/2020

David M. Mendoza – President/Training Director
Certified Environmental Specialist
OSHA Authorized Instructor

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License



ASBESTOS PROFESSIONAL LICENSE

ENDORSEMENTS

TC EXPIRES

INSPECTOR

4/21/2019

ID NUMBER

ISSUED

EXPIRES

100 - 00746

4/11/2019

05/15/2020

MANAGEMENT PLANNER

4/21/2019

PROJECT MANAGER

4/2/2020


AIR SAMPLING PROFESSIONAL

AMY J WILLIAMS

1408 S CLAY

JACKSONVILLE, IL 62650

Environmental Health



Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois
Department of Public Health
This license is valid only when accompanied by a valid
training course certificate.

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL		
	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE		
	Loc	Localized
	Dist	Distributed