

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH  
AHERA THREE YEAR REINSPECTION  
ASBESTOS ABATEMENT PROGRAM  
SCHOOL INFORMATION FORM**

**SECTION I**

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299  
SCHOOL ID NUMBER: 14-016-2990-2317  
SCHOOL NAME: Locke School  
ADDRESS OF SCHOOL: 2845 N. Newcastle Avenue  
CITY: Chicago, IL, 60634

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **3/30/2016**

**If the address on this form is different than the address of the building, submit a written explanation.**

---

**SECTION II** *(Please type or print)*

**PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:**

DATE REINSPECTION COMPLETED: 10/1/2019 ENROLLMENT 1265  
IDPH INSPECTOR LICENSE NUMBER: 100-11089  
IDPH LICENSED INSPECTOR NAME(Please Print): Panfilo Carrazco  
IDPH MP LICENSE NUMBER: 100-07342  
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Jigar Shah

DESIGNATED PERSON (Please Print): Robert Christlieb PHONE: (773) 553-3197



10/1/2019

*Signature of Designated Person*

*Date*

**SECTION III**

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: \_\_\_\_\_

School has been closed. Date closed: \_\_\_\_\_

School building has been demolished. Date: \_\_\_\_\_

School building is asbestos free since last reinspection: \_\_\_\_\_

**Please explain in writing why the school building is now asbestos free and include the supporting documentation.**

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

**Explain in writing if the address of the building is different than the address on this form:**

---

---

---

**THREE-YEAR REINSPECTION**

**CHICAGO SCHOOL DIST 299**

**Locke School**

2845 N. Newcastle Avenue  
Chicago, IL, 60634

Unit: 24231  
Building ID: 4510

IDPH ID Number: 14-016-2990-2317

**REPORT DATE:**

Tuesday, October 01, 2019

**Prepared for:**

**Chicago Public Schools  
42 West Madison Street  
Chicago, IL 60602**

**Prepared by:**

**GSG-Probe Consulting, Inc.**

2942 W. Van Buren

Chicago, IL, 60612

Phone 3123197575

Fax

**DO NOT REMOVE FROM SCHOOL  
REQUIRED BY FEDERAL LAW**

October 3, 2019

Mr. Glen E. Garner  
Asbestos Program  
Illinois Department of Public Health  
525 West Jefferson Street  
Springfield, Illinois 62761

Re: Chicago Public Schools - 2019 Three-Year Reinspections

Dear Mr. Glen:

GSG-Probe Consulting, Inc., Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 1, 2 Elementary Schools. Please update your records with the following information.

School District: 299          Unit: 24231          Region: 02          IDPH ID:14-016-2990-2317

School: Locke School          Building ID: 4510

Address: 2845 N. Newcastle Avenue  
Chicago, IL, 60634

Building Contact:          Contact Phone:

Current Building Owners: Chicago Public Schools

Review Date: 11/22/2019

Inspector: Panfilo Carrazco          Inspector IDPH License: 100-11089  
Management Planner: Jigar Shah          Management Planner IDPH License: 100-07342

If you have any questions or comments, please contact us at 3123197575

Sincerely,  
GSG-Probe Consulting, Inc.

Jigar Shah  
100-07342

## **Environmental Notification to Occupants**

To: Faculty, Staff and Parents  
From: Chicago Public Schools  
Date: October 03, 2019

RE: Locke School, Unit 24231  
2845 N. Newcastle Avenue  
Chicago, IL, 60634

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2019 asbestos three year re-inspection has been completed at Locke School, following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at Locke School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Robert Christlieb, the designated Local Education Authority's Designated Person at (773) 553-3197 .

## **Table of Contents**

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

### **APPENDICES:**

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

## SCHOOL AND INSPECTION INFORMATION

### 1. School Information

School: Locke School Unit: 24231 Region: 02  
Address: 2845 N. Newcastle Avenue Chicago, IL, 60634  
IDPH ID: 14-016-2990-2317 Building ID: 4510  
Contact: Phone:

### 2. Description of Facility

Original Construction: 1998 Additional Construction:  
Total Square Footage: 40248 No of Floors: 3  
Current Occupancy: 1265

### 3. LEA Designated Person

Contact: Robert Christlieb Phone: (773) 553-3197  
Address: 42 West Madison Street  
Chicago, IL 60602

### 4. Managing Environmental Consultant

MEC: GSG-Probe Consulting, Inc.  
Contact: Jigar Shah  
Address 2942 W. Van Buren  
Chicago, IL, 60612  
Phone: 3123197575 Fax:

### 5. Inspector

Inspector Name: Panfilo Carrazco

Inspector IDPH license # 100-11089

Signature:  
Date: 10/3/2019

### 6. Management Planner

Management Planner Name: Jigar Shah

Management Planner IDPH license # 100-07342

Signature:  
Date: 11/22/2019

### 7. Review Date:11/22/2019

### 8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature:



Date: 10/1/2019

Name: Robert Christlieb

## II. EXECUTIVE SUMMARY

GSG-Probe Consulting, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Locke School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.85 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 4510:

B. The following new homogenous areas have been identified for Building 4510:



C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

01	Hard Coat Plaster
02	12"x12" White Vinyl Floor Tile
09	12"x12" White Vinyl Floor Tile Mastic
33	Red Linoleum (Not Observed)
35	2'x2' White Ceiling Tile
36	Hard Coat Plaster
41	2'x4' Ceiling Tile
50	12"x12" Green w/ Specks Floor Tile
51	12"x12" Green w/ Specks Floor Tile Mastic
52	12"x12" Blue Floor Tile
53	12"x12" Blue Floor Tile Mastic
65	Terrazzo
66	Carpet Mastic
67	2' x 4' Dot Ceiling Tile (with 2' x 2' Layout)
68	Terrazzo
69	12"x12" Gold Mottled Floor Tile
70	12"x12" Gold Mottled Floor Tile Mastic
71	12"x12" Gold Floor Tile
72	12"x12" Gold Floor Tile Mastic
73	12" x 12" Blue Floor Tile
73M	12" x 12" Blue Floor Tile Adhesive
74	12" x 12" Tan Multicolored Floor Tile
74M	12" x 12" Tan Multicolored Floor Tile Adhesive
75	2'x4' Grooved Ceiling Tile
76	CMU Wall Mortar
77	Brown ceramic tile
77A	Brown ceramic tile Mastic
78	12" x 12" Cream speckled VFT
78A	12" x 12" Cream speckled VFT Mastic
79	Textured plaster
80	12" x 12" Gray speckled VFT
80A	12" x 12" Gray speckled VFT Mastic
81	12" x 12" Blue speckled VFT
81A	12" x 12" Blue speckled VFT Mastic

The following areas were deemed to be inaccessible:

Materials were also listed as "assumed" if they were in good condition and sampling was not

conducted to avoid damage.

This reinspection was conducted by Panfilo Carrazco, IDPH License # 100-11089. The Management Plan was updated by Jigar Shah, IDPH License # 100-07342. Inspector and Management Planner Licenses are included in Appendix B.

### **III. METHODOLOGY**

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

### **IV. ABATEMENT HISTORY**

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

### **V. REASSESSMENTS AND RECOMMENDATIONS**

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

### **VI. CONCLUSIONS**

The Locke School Building 4510 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

**Table I**  
**Inspector's Reinspection Findings**

---

# Chicago Public Schools

School Locke School Unit 24231 Building ID 4510

Address 2845 N. Newcastle Avenue Region 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
01	Hard Coat Plaster	80,000	SF	Throughout - 1926	ASSUMED	SURFACE	N	NONE	0		No	ACBM with the potential for damage		MODERATE
02	12"x12" White Vinyl Floor Tile	900	SF	Main Office - 1926	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
03	9"x9" Black Vinyl Floor Tile - ABATED			1st & 2nd Floor Corridors, Engineer's Office - 1926	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
05	Textured Plaster			Throughout - 1926	NO_ACBM						No			
09	12"x12" White Vinyl Floor Tile Mastic	900	SF	Main Office - 1926	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
10	9"x9" Black Vinyl Floor Tile Mastic - ABATED			1st & 2nd Floor Corridors, Engineer's Office - 1926	ABATED	MISC					No	Any remaining friable ACBM or friable suspect ACBM		
11	9"x9" Black Vinyl Floor Tile - ABATED			1st & 2nd Floor Corridors - 1936	ABATED	MISC					No	Any remaining friable ACBM or friable suspect ACBM		
12	9"x9" Black Vinyl Floor Tile Mastic - ABATED			1st & 2nd Floor Corridors - 1936	ABATED	MISC					No	Any remaining friable ACBM or friable suspect ACBM		
13	9"x9" Maroon Vinyl Floor Tile - ABATED			1st & 2nd Floor Corridors, Engineer's Office - 1926	ABATED	MISC					No	Any remaining friable ACBM or friable suspect ACBM		
14	9"x9" Maroon Vinyl Floor Tile Mastic - ABATED			1st & 2nd Floor Corridors, Engineer's Office - 1926	ABATED	MISC					No	Any remaining friable ACBM or friable suspect ACBM		
15	9"x9" Brown w/ White Streaks Vinyl Floor Tile - ABATED			1st & 2nd Floor Corridors - 1926	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
16	9"x9" Brown w/ White Streaks Floor Tile Mastic - ABATED			1st & 2nd Floor Corridors - 1926	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
17	9"x9" Black w/ White Streaks Vinyl Floor Tile - ABATED			1st & 2nd Floor Corridors - 1926	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
18	9"x9" Black w/ White Streaks Floor Tile Mastic - ABATED			1st & 2nd Floor Corridors - 1926	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
19	9"x9" Maroon Vinyl Floor Tile - ABATED			1st & 2nd Floor Corridors - 1936	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		

# Chicago Public Schools

School Locke School Unit 24231 Building ID 4510

Address 2845 N. Newcastle Avenue Region 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
20	9"x9" Maroon Vinyl Floor Tile Mastic - ABATED			1st & 2nd Floor Corridors - 1936	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
21	6"x18" Black Vinyl Floor Tile - ABATED			1st & 2nd Floor Corridors - 1936	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
22	6"x18" Black Vinyl Floor Tile Mastic - ABATED			1st & 2nd Floor Corridors - 1936	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
23	9"x9" Brown w/ Red & White Streaks Floor Tile - ABATED			1st & 2nd Floor Corridors - 1926	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
24	9"x9" Brown w/ Red & White Streaks Floor Tile Mastic - ABATED			1st & 2nd Floor Corridors - 1926	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
25	12"x12" Purple Vinyl Floor Tile - ABATED			1st Floor Corridor - 1926	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
26	12"x12" Purple Vinyl Floor Tile Mastic - ABATED			1st Floor Corridor - 1926	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
27	12"x12" Black w/ White Streaks Vinyl Floor Tile - ABATED			1st Floor Corridor - 1926	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
28	12"x12" Black w/ White Streaks Floor Tile Mastic - ABATED			1st Floor Corridor - 1926	ABATED	MISC						ACBM with the potential for damage		
29	12"x12" White w/ Tan Streaks Floor Tile	2,400	SF	Rooms 119, 122, & 124 - 1926	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
30	12"x12" White w/ Tan Streaks Floor Tile Mastic	2,400	SF	Rooms 119, 122, & 124 - 1926	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
33	Red Linoleum (Not Observed)	1,200	SF	Auditorium - 1926	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
34	Red Linoleum Mastic (Not Observed)	1,200	SF	Auditorium - 1926	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
35	2'x2' White Ceiling Tile	600	SF	Room 225 - 1926	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
36	Hard Coat Plaster	60,000	SF	Throughout - 1936	ASSUMED	SURFACE	N	NONE	0		No	ACBM with the potential for damage		LOW
37	12"x12" Black Vinyl Floor Tile - ABATED			Engineer's Office - 1926	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
38	12"x12" Black Vinyl Floor Tile Mastic - ABATED			Engineer's Office - 1926	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		

# Chicago Public Schools

School Locke School Unit 24231 Building ID 4510

Address 2845 N. Newcastle Avenue Region 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
39	12"x12" Maroon Vinyl Floor Tile - ABATED			Engineer's Office - 1926	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
40	12"x12" Maroon Vinyl Floor Tile Mastic - ABATED			Engineer's Office - 1926	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
41	2'x4' Ceiling Tile	500	SF	Engineer's Office - 1926	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
50	12"x12" Green w/ Specks Floor Tile	8,000	SF	Throughout - 1998	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
51	12"x12" Green w/ Specks Floor Tile Mastic	8,000	SF	Throughout - 1998	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
52	12"x12" Blue Floor Tile	3,000	SF	Rooms 223, 225, 226, 227, 228, 229, 230, 231, 136, 128, 133, 135, 137 - 1998	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
53	12"x12" Blue Floor Tile Mastic	3,000	SF	Rooms 223, 225, 226, 227, 228, 229, 230, 231, 136, 128, 133, 135, 137 - 1998	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
54	2'x4' White w/ Grooves Ceiling Tile			Throughout - 1998	NO_ACBM	MISC								LOW
55	Green Linoleum			Cafeteria, Kitchen - 1998	NO_ACBM	MISC								
56	Green Linoleum Mastic			Cafeteria, Kitchen - 1998	NO_ACBM	MISC								
57	Blue Linoleum			Cafeteria, Kitchen - 1998	NO_ACBM	MISC								
57A	Blue Linoleum Mastic			Cafeteria, Kitchen - 1998	NO_ACBM	MISC								
58	Drywall			Throughout - 1998	NO_ACBM	MISC								
59	Drywall Compound			Throughout - 1998	NO_ACBM	MISC								
60	Vinyl Baseboards			Throughout - 1998	NO_ACBM	MISC								
61	Vinyl Baseboard Mastic			Throughout - 1998	NO_ACBM	MISC								
62	Spray-On Insulation			Above Ceiling 1st Floor - 1998	NO_ACBM	SURFACE								
63	Carpet Mastic			Main Office Area, Library - 1998	NO_ACBM	MISC								
64	2'x4' White Smooth Ceiling Tile			Kitchen & Storage - 1998	NO_ACBM	MISC								
65	Terrazzo	4,000	SF	Stair Wells and Stairs Throughout 1st and 2nd Floor Corridors	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
66	Carpet Mastic	500	SF	Room 108	ASSUMED	MISC	N	NONE	0		No	ACBM with the		LOW

# Chicago Public Schools

School Locke School Unit 24231 Building ID 4510

Address 2845 N. Newcastle Avenue Region 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
												potential for damage		
67	2' x 4' Dot Ceiling Tile (with 2' x 2' Layout)	4,000	SF	Rooms 108, 119, 121, and Old 2nd Floor Girl's Locker Room.	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
68	Terrazzo	5,000	SF	Corridors and Toilets (1998)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
69	12"x12" Gold Mottled Floor Tile	750	SF	Old 2nd Floor Girl's Locker Room.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
70	12"x12" Gold Mottled Floor Tile Mastic	750	SF	Old 2nd Floor Girl's Locker Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
71	12"x12" Gold Floor Tile	2,000	SF	Throughout Classrooms in 1998 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
72	12"x12" Gold Floor Tile Mastic	2,000	SF	Throughout Classrooms in 1998 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
73	12" x 12" Blue Floor Tile	4,000	SF	1st and 2nd Floor Corridors	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
73M	12" x 12" Blue Floor Tile Adhesive	4,000	SF	1st and 2nd Floor Corridors	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
74	12" x 12" Tan Multicolored Floor Tile	1,200	SF	Engineer's Office, Rooms 117 and 112	ASSUMED	MISC	N	LOC	7		No	ACBM with potential for significant damage		MODERATE
74M	12" x 12" Tan Multicolored Floor Tile Adhesive	1,200	SF	Engineer's Office, Rooms 117 and 122	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
75	2'x4' Grooved Ceiling Tile	600	SF	Room 222	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		
76	CMU Wall Mortar			1998 Addition Throughout	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
77	Brown ceramic tile	2,400	SF	1st + 2nd Floor boys and girls toilets -1926 bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
77A	Brown ceramic tile Mastic	2,400	SF	1st + 2nd Floor boys and girls toilets -1926 bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
78	12" x 12" Cream speckled VFT	1,400	SF	Auditorium	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
78A	12" x 12" Cream speckled VFT Mastic	14,000	SF	Auditorium	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
79	Textured plaster	45,000	SF	Auditorium & Balcony	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		
80	12" x 12" Gray speckled VFT	500	SF	Room 108	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
80A	12" x 12" Gray speckled VFT Mastic	500	SF	Room 108	ASSUMED	MISC	N	NONE	0		No	ACBM with the		LOW



# Chicago Public Schools

School Locke School Unit 24231 Building ID 4510

Address 2845 N. Newcastle Avenue Region 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
												potential for damage		
81	12" x 12" Blue speckled VFT	900	SF	Room 115, 122	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
81A	12" x 12" Blue speckled VFT Mastic	900	SF	Room 115, 122	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
L	Spray-on Insulation			Throughout Above Ceilings in Attic - 1926	NO_ACBM						No			

# Chicago Public Schools

School Locke School Unit 24231 Building ID 4510

Address 2845 N. Newcastle Avenue Region 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

*Inspector's Comments are Summarized at the End of the Report*

Reinspection Date <b>10/3/2019</b>
Inspector Name <b>Panfilo Carrazco</b>
<b>100-11089</b> <b>5/15/2020</b>
Inspector's IDPH License Number / Expiration Date

### Inspector's Comments

HA Number:	Inspector Comments:
01	
02	
03	
05	
09	
10	
11	
12	
13	
14	
15	
16	
17	
18	
19	
20	
21	
22	
23	
24	
25	
26	
27	

# Chicago Public Schools

School Locke School Unit 24231 Building ID 4510

Address 2845 N. Newcastle Avenue Region 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
28	
29	
30	
33	
34	
35	
36	
37	
38	
39	
40	
41	
50	
51	
52	
53	
54	
55	
56	
57	
57A	
58	
59	
60	
61	
62	
63	
64	
65	

# Chicago Public Schools

School Locke School Unit 24231 Building ID 4510

Address 2845 N. Newcastle Avenue Region 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
66	
67	
68	
69	
70	
71	
72	
73	
73M	
74	Damaged observed in Engineer's Office
74M	
75	
76	
77	
77A	
78	
78A	
79	
80	
80A	
81	
81A	
L	

# Chicago Public Schools

**School** Locke School **Unit** 24231 **Building ID** 4510

**Address** 2845 N. Newcastle Avenue **Region** 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

*Inspector's Comments are Summarized at the End of the Report*

---

**Table II**

**Management Planner's Review**

---

# Chicago Public Schools

**School** Locke School  
**Address** 2845 N. Newcastle Avenue

**Unit** 24231  
Chicago, IL, 60634

**Building ID** 4510  
**Region** 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575

Fax:

### Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
01	Hard Coat Plaster	80,000	SF	Throughout - 1926	Assumed	SURFACE	No	0		6 ACBM with the potential for damage	Follow O&M Plan
02	12"x12" White Vinyl Floor Tile	900	SF	Main Office - 1926	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
03	9"x9" Black Vinyl Floor Tile - ABATED			1st & 2nd Floor Corridors, Engineer's Office - 1926	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
05	Textured Plaster			Throughout - 1926	No ACBM						
09	12"x12" White Vinyl Floor Tile Mastic	900	SF	Main Office - 1926	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
10	9"x9" Black Vinyl Floor Tile Mastic - ABATED			1st & 2nd Floor Corridors, Engineer's Office - 1926	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
11	9"x9" Black Vinyl Floor Tile - ABATED			1st & 2nd Floor Corridors - 1936	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
12	9"x9" Black Vinyl Floor Tile Mastic - ABATED			1st & 2nd Floor Corridors - 1936	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
13	9"x9" Maroon Vinyl Floor Tile - ABATED			1st & 2nd Floor Corridors, Engineer's Office - 1926	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
14	9"x9" Maroon Vinyl Floor Tile Mastic - ABATED			1st & 2nd Floor Corridors, Engineer's Office - 1926	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
15	9"x9" Brown w/ White Streaks Vinyl Floor Tile - ABATED			1st & 2nd Floor Corridors - 1926	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
16	9"x9" Brown w/ White Streaks Floor Tile Mastic - ABATED			1st & 2nd Floor Corridors - 1926	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
17	9"x9" Black w/ White Streaks Vinyl Floor Tile - ABATED			1st & 2nd Floor Corridors - 1926	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
18	9"x9" Black w/ White Streaks Floor Tile Mastic - ABATED			1st & 2nd Floor Corridors - 1926	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
19	9"x9" Maroon Vinyl Floor Tile - ABATED			1st & 2nd Floor Corridors - 1936	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
20	9"x9" Maroon Vinyl Floor Tile Mastic - ABATED			1st & 2nd Floor Corridors - 1936	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
21	6"x18" Black Vinyl Floor Tile - ABATED			1st & 2nd Floor Corridors - 1936	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
22	6"x18" Black Vinyl Floor Tile Mastic - ABATED			1st & 2nd Floor Corridors - 1936	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
23	9"x9" Brown w/ Red & White Streaks Floor Tile - ABATED			1st & 2nd Floor Corridors - 1926	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
24	9"x9" Brown w/ Red & White Streaks Floor Tile			1st & 2nd Floor Corridors - 1926	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan

# Chicago Public Schools

**School** Locke School  
**Address** 2845 N. Newcastle Avenue

**Unit** 24231  
Chicago, IL, 60634

**Building ID** 4510  
**Region** 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575

Fax:

### Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
	Mastic - ABATED									suspect ACBM	
25	12"x12" Purple Vinyl Floor Tile - ABATED			1st Floor Corridor - 1926	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
26	12"x12" Purple Vinyl Floor Tile Mastic - ABATED			1st Floor Corridor - 1926	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
27	12"x12" Black w/ White Streaks Vinyl Floor Tile - ABATED			1st Floor Corridor - 1926	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
28	12"x12" Black w/ White Streaks Floor Tile Mastic - ABATED			1st Floor Corridor - 1926	Abated	MISC				6 ACBM with the potential for damage	Follow O&M Plan
29	12"x12" White w/ Tan Streaks Floor Tile	2,400	SF	Rooms 119, 122, & 124 - 1926	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
30	12"x12" White w/ Tan Streaks Floor Tile Mastic	2,400	SF	Rooms 119, 122, & 124 - 1926	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
33	Red Linoleum (Not Observed)	1,200	SF	Auditorium - 1926	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
34	Red Linoleum Mastic (Not Observed)	1,200	SF	Auditorium - 1926	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
35	2'x2' White Ceiling Tile	600	SF	Room 225 - 1926	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
36	Hard Coat Plaster	60,000	SF	Throughout - 1936	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
37	12"x12" Black Vinyl Floor Tile - ABATED			Engineer's Office - 1926	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
38	12"x12" Black Vinyl Floor Tile Mastic - ABATED			Engineer's Office - 1926	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
39	12"x12" Maroon Vinyl Floor Tile - ABATED			Engineer's Office - 1926	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
40	12"x12" Maroon Vinyl Floor Tile Mastic - ABATED			Engineer's Office - 1926	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
41	2'x4' Ceiling Tile	500	SF	Engineer's Office - 1926	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
50	12"x12" Green w/ Specks Floor Tile	8,000	SF	Throughout - 1998	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
51	12"x12" Green w/ Specks Floor Tile Mastic	8,000	SF	Throughout - 1998	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
52	12"x12" Blue Floor Tile	3,000	SF	Rooms 223, 225, 226, 227, 228, 229, 230, 231, 136, 128, 133, 135, 137 - 1998	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
53	12"x12" Blue Floor Tile Mastic	3,000	SF	Rooms 223, 225, 226, 227, 228, 229, 230, 231, 136, 128, 133, 135, 137 - 1998	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
54	2'x4' White w/ Grooves Ceiling Tile			Throughout - 1998	No ACBM	MISC					
55	Green Linoleum			Cafeteria, Kitchen - 1998	No ACBM	MISC					



# Chicago Public Schools

**School** Locke School  
**Address** 2845 N. Newcastle Avenue

**Unit** 24231  
Chicago, IL, 60634

**Building ID** 4510  
**Region** 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575

Fax:

### Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
56	Green Linoleum Mastic			Cafeteria, Kitchen - 1998	No ACBM	MISC					
57	Blue Linoleum			Cafeteria, Kitchen - 1998	No ACBM	MISC					
57A	Blue Linoleum Mastic			Cafeteria, Kitchen - 1998	No ACBM	MISC					
58	Drywall			Throughout - 1998	No ACBM	MISC					
59	Drywall Compound			Throughout - 1998	No ACBM	MISC					
60	Vinyl Baseboards			Throughout - 1998	No ACBM	MISC					
61	Vinyl Baseboard Mastic			Throughout - 1998	No ACBM	MISC					
62	Spray-On Insulation			Above Ceiling 1st Floor - 1998	No ACBM	SURFACE					
63	Carpet Mastic			Main Office Area, Library - 1998	No ACBM	MISC					
64	2'x4' White Smooth Ceiling Tile			Kitchen & Storage - 1998	No ACBM	MISC					
65	Terrazzo	4,000	SF	Stair Wells and Stairs Throughout 1st and 2nd Floor Corridors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
66	Carpet Mastic	500	SF	Room 108	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
67	2' x 4' Dot Ceiling Tile (with 2' x 2' Layout)	4,000	SF	Rooms 108, 119, 121, and Old 2nd Floor Girl's Locker Room.	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
68	Terrazzo	5,000	SF	Corridors and Toilets (1998)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
69	12"x12" Gold Mottled Floor Tile	750	SF	Old 2nd Floor Girl's Locker Room.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
70	12"x12" Gold Mottled Floor Tile Mastic	750	SF	Old 2nd Floor Girl's Locker Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
71	12"x12" Gold Floor Tile	2,000	SF	Throughout Classrooms in 1998 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
72	12"x12" Gold Floor Tile Mastic	2,000	SF	Throughout Classrooms in 1998 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
73	12" x 12" Blue Floor Tile	4,000	SF	1st and 2nd Floor Corridors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
73M	12" x 12" Blue Floor Tile Adhesive	4,000	SF	1st and 2nd Floor Corridors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
74	12" x 12" Tan Multicolored Floor Tile	1,200	SF	Engineer's Office, Rooms 117 and 112	Assumed	MISC	No	7	SF	5 ACBM with potential for significant damage	Follow O&M Plan
74M	12" x 12" Tan Multicolored Floor Tile Adhesive	1,200	SF	Engineer's Office, Rooms 117 and 122	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
75	2'x4' Grooved Ceiling Tile	600	SF	Room 222	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
76	CMU Wall Mortar			1998 Addition Throughout	Assumed	MISC	No	0		6 ACBM with the potential for damage	Follow O&M Plan
77	Brown ceramic tile	2,400	SF	1st + 2nd Floor boys and girls toilets -1926 bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
77A	Brown ceramic tile Mastic	2,400	SF	1st + 2nd Floor boys and girls toilets -1926 bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
78	12" x 12" Cream speckled VFT	1,400	SF	Auditorium	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Locke School

**Unit** 24231

**Building ID** 4510

**Address** 2845 N. Newcastle Avenue

Chicago, IL, 60634

**Region** 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575

Fax:

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
78A	12" x 12" Cream speckled VFT Mastic	14,000	SF	Auditorium	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
79	Textured plaster	45,000	SF	Auditorium & Balcony	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
80	12" x 12" Gray speckled VFT	500	SF	Room 108	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
80A	12" x 12" Gray speckled VFT Mastic	500	SF	Room 108	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
81	12" x 12" Blue speckled VFT	900	SF	Room 115, 122	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
81A	12" x 12" Blue speckled VFT Mastic	900	SF	Room 115, 122	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
L	Spray-on Insulation			Throughout Above Ceilings in Attic - 1926	No ACBM						

# Chicago Public Schools

**School** Locke School  
**Address** 2845 N. Newcastle Avenue

**Unit** 24231  
 Chicago, IL, 60634

**Building ID** 4510  
**Region** 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG-Probe Consulting, Inc.  
 2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

### *Management Planner's Comments Summarized at the End of the Report*

Review Date	11/22/2019
Manager Planner Name	Jigar Shah
100-07342	5/15/2020
Manager IDPH License No/Expiration	

HA Number	Management Comments
01	
02	
03	
05	
09	
10	
11	
12	
13	
14	
15	
16	
17	
18	
19	
20	
21	
22	
23	
24	
25	
26	
27	
28	
29	

# Chicago Public Schools

**School** Locke School  
**Address** 2845 N. Newcastle Avenue

**Unit** 24231  
Chicago, IL, 60634

**Building ID** 4510  
**Region** 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG-Probe Consulting, Inc.  
2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
30	
33	
34	
35	
36	
37	
38	
39	
40	
41	
50	
51	
52	
53	
54	
55	
56	
57	
57A	
58	
59	
60	
61	
62	
63	
64	

# Chicago Public Schools

**School** Locke School  
**Address** 2845 N. Newcastle Avenue

**Unit** 24231  
 Chicago, IL, 60634

**Building ID** 4510  
**Region** 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG-Probe Consulting, Inc.  
 2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
65	
66	
67	
68	
69	
70	
71	
72	
73	
73M	
74	replace damaged tiles
74M	
75	
76	
77	
77A	
78	
78A	
79	
80	
80A	
81	
81A	
L	

# Chicago Public Schools

**School** Locke School  
**Address** 2845 N. Newcastle Avenue

**Unit** 24231  
Chicago, IL, 60634

**Building ID** 4510  
**Region** 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG-Probe Consulting, Inc.  
2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575

Fax:

*Management Planner's Comments Summarized at the End of the Report*

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Locke School** INSPECTION DATE: **10/3/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **01**  
MATERIAL DESCRIPTION: **Hard Coat Plaster**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Throughout - 1926**  
MATERIAL QUANTITY: **80000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/03/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Locke School** REVIEW DATE: **11/22/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **01**  
MATERIAL DESCRIPTION: **Hard Coat Plaster**  
MATERIAL LOCATION: **Throughout - 1926**  
MATERIAL QUANTITY: **80000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/22/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Locke School** INSPECTION DATE: **10/3/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **02**  
MATERIAL DESCRIPTION: **12"x12" White Vinyl Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Main Office - 1926**  
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/03/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Locke School** REVIEW DATE: **11/22/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **02**  
MATERIAL DESCRIPTION: **12"x12" White Vinyl Floor Tile**  
MATERIAL LOCATION: **Main Office - 1926**  
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/22/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Locke School** INSPECTION DATE: **10/3/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **03**  
MATERIAL DESCRIPTION: **9"x9" Black Vinyl Floor Tile - ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st & 2nd Floor Corridors, Engineer's Office - 1926**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/03/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Locke School** REVIEW DATE: **11/22/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **03**

MATERIAL DESCRIPTION: **9"x9" Black Vinyl Floor Tile - ABATED**

MATERIAL LOCATION: **1st & 2nd Floor Corridors, Engineer's Office - 1926**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/22/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Locke School** INSPECTION DATE: **10/3/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **05**  
MATERIAL DESCRIPTION: **Textured Plaster**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout - 1926**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/03/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUILDING ID: **4510**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Locke School** REVIEW DATE: **11/22/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **05**

MATERIAL DESCRIPTION: **Textured Plaster**

MATERIAL LOCATION: **Throughout - 1926**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/22/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Locke School** INSPECTION DATE: **10/3/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **09**  
MATERIAL DESCRIPTION: **12"x12" White Vinyl Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Main Office - 1926**  
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/03/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Locke School** REVIEW DATE: **11/22/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **09**  
MATERIAL DESCRIPTION: **12"x12" White Vinyl Floor Tile Mastic**  
MATERIAL LOCATION: **Main Office - 1926**  
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/22/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Locke School** INSPECTION DATE: **10/3/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10**  
MATERIAL DESCRIPTION: **9"x9" Black Vinyl Floor Tile Mastic - ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st & 2nd Floor Corridors, Engineer's Office - 1926**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/03/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Locke School** REVIEW DATE: **11/22/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **10**

MATERIAL DESCRIPTION: **9"x9" Black Vinyl Floor Tile Mastic - ABATED**

MATERIAL LOCATION: **1st & 2nd Floor Corridors, Engineer's Office - 1926**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: 11/22/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Locke School** INSPECTION DATE: **10/3/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11**  
MATERIAL DESCRIPTION: **9"x9" Black Vinyl Floor Tile - ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st & 2nd Floor Corridors - 1936**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/03/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Locke School** REVIEW DATE: **11/22/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **11**

MATERIAL DESCRIPTION: **9"x9" Black Vinyl Floor Tile - ABATED**

MATERIAL LOCATION: **1st & 2nd Floor Corridors - 1936**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/22/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Locke School** INSPECTION DATE: **10/3/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12**  
MATERIAL DESCRIPTION: **9"x9" Black Vinyl Floor Tile Mastic - ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st & 2nd Floor Corridors - 1936**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/03/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Locke School** REVIEW DATE: **11/22/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **12**

MATERIAL DESCRIPTION: **9"x9" Black Vinyl Floor Tile Mastic - ABATED**

MATERIAL LOCATION: **1st & 2nd Floor Corridors - 1936**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/22/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Locke School** INSPECTION DATE: **10/3/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13**  
MATERIAL DESCRIPTION: **9"x9" Maroon Vinyl Floor Tile - ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st & 2nd Floor Corridors, Engineer's Office - 1926**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/03/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Locke School** REVIEW DATE: **11/22/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **13**

MATERIAL DESCRIPTION: **9"x9" Maroon Vinyl Floor Tile - ABATED**

MATERIAL LOCATION: **1st & 2nd Floor Corridors, Engineer's Office - 1926**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/22/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Locke School** INSPECTION DATE: **10/3/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14**  
MATERIAL DESCRIPTION: **9"x9" Maroon Vinyl Floor Tile Mastic - ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st & 2nd Floor Corridors, Engineer's Office - 1926**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/03/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Locke School** REVIEW DATE: **11/22/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **14**

MATERIAL DESCRIPTION: **9"x9" Maroon Vinyl Floor Tile Mastic - ABATED**

MATERIAL LOCATION: **1st & 2nd Floor Corridors, Engineer's Office - 1926**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/22/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Locke School** INSPECTION DATE: **10/3/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15**  
MATERIAL DESCRIPTION: **9"x9" Brown w/ White Streaks Vinyl Floor Tile - ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st & 2nd Floor Corridors - 1926**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 10/03/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Locke School** REVIEW DATE: **11/22/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **15**

MATERIAL DESCRIPTION: **9"x9" Brown w/ White Streaks Vinyl Floor Tile - ABATED**

MATERIAL LOCATION: **1st & 2nd Floor Corridors - 1926**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/22/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Locke School** INSPECTION DATE: **10/3/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16**  
MATERIAL DESCRIPTION: **9"x9" Brown w/ White Streaks Floor Tile Mastic - ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st & 2nd Floor Corridors - 1926**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 10/03/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Locke School** REVIEW DATE: **11/22/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **16**

MATERIAL DESCRIPTION: **9"x9" Brown w/ White Streaks Floor Tile Mastic - ABATED**

MATERIAL LOCATION: **1st & 2nd Floor Corridors - 1926**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/22/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Locke School** INSPECTION DATE: **10/3/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17**  
MATERIAL DESCRIPTION: **9"x9" Black w/ White Streaks Vinyl Floor Tile - ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st & 2nd Floor Corridors - 1926**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/03/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Locke School** REVIEW DATE: **11/22/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **17**

MATERIAL DESCRIPTION: **9"x9" Black w/ White Streaks Vinyl Floor Tile - ABATED**

MATERIAL LOCATION: **1st & 2nd Floor Corridors - 1926**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: 11/22/2019



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **24231**    BUILDING ID: **4510**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Locke School**    INSPECTION DATE: **10/3/2019**  
ADDRESS: **2845 N. Newcastle Avenue**    IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18**  
MATERIAL DESCRIPTION: **9"x9" Black w/ White Streaks Floor Tile Mastic - ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated**    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st & 2nd Floor Corridors - 1926**

MATERIAL QUANTITY:    MATERIAL UNITS:

DAMAGE QUANTITY:    DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/03/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Locke School** REVIEW DATE: **11/22/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **18**

MATERIAL DESCRIPTION: **9"x9" Black w/ White Streaks Floor Tile Mastic - ABATED**

MATERIAL LOCATION: **1st & 2nd Floor Corridors - 1926**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: 11/22/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Locke School** INSPECTION DATE: **10/3/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19**  
MATERIAL DESCRIPTION: **9"x9" Maroon Vinyl Floor Tile - ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st & 2nd Floor Corridors - 1936**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/03/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Locke School** REVIEW DATE: **11/22/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **19**

MATERIAL DESCRIPTION: **9"x9" Maroon Vinyl Floor Tile - ABATED**

MATERIAL LOCATION: **1st & 2nd Floor Corridors - 1936**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/22/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Locke School** INSPECTION DATE: **10/3/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**  
MATERIAL DESCRIPTION: **9"x9" Maroon Vinyl Floor Tile Mastic - ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st & 2nd Floor Corridors - 1936**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/03/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUILDING ID: **4510**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Locke School** REVIEW DATE: **11/22/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **20**

MATERIAL DESCRIPTION: **9"x9" Maroon Vinyl Floor Tile Mastic - ABATED**

MATERIAL LOCATION: **1st & 2nd Floor Corridors - 1936**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: 11/22/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Locke School** INSPECTION DATE: **10/3/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21**  
MATERIAL DESCRIPTION: **6"x18" Black Vinyl Floor Tile - ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st & 2nd Floor Corridors - 1936**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/03/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Locke School** REVIEW DATE: **11/22/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **21**

MATERIAL DESCRIPTION: **6"x18" Black Vinyl Floor Tile - ABATED**

MATERIAL LOCATION: **1st & 2nd Floor Corridors - 1936**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/22/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Locke School** INSPECTION DATE: **10/3/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22**  
MATERIAL DESCRIPTION: **6"x18" Black Vinyl Floor Tile Mastic - ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st & 2nd Floor Corridors - 1936**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/03/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Locke School** REVIEW DATE: **11/22/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **22**

MATERIAL DESCRIPTION: **6"x18" Black Vinyl Floor Tile Mastic - ABATED**

MATERIAL LOCATION: **1st & 2nd Floor Corridors - 1936**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/22/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Locke School** INSPECTION DATE: **10/3/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23**  
MATERIAL DESCRIPTION: **9"x9" Brown w/ Red & White Streaks Floor Tile - ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st & 2nd Floor Corridors - 1926**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/03/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Locke School** REVIEW DATE: **11/22/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **23**

MATERIAL DESCRIPTION: **9"x9" Brown w/ Red & White Streaks Floor Tile - ABATED**

MATERIAL LOCATION: **1st & 2nd Floor Corridors - 1926**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/22/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Locke School** INSPECTION DATE: **10/3/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **24**  
MATERIAL DESCRIPTION: **9"x9" Brown w/ Red & White Streaks Floor Tile Mastic - ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st & 2nd Floor Corridors - 1926**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/03/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Locke School** REVIEW DATE: **11/22/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **24**

MATERIAL DESCRIPTION: **9"x9" Brown w/ Red & White Streaks Floor Tile Mastic - ABATED**

MATERIAL LOCATION: **1st & 2nd Floor Corridors - 1926**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: 11/22/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Locke School** INSPECTION DATE: **10/3/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25**  
MATERIAL DESCRIPTION: **12"x12" Purple Vinyl Floor Tile - ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st Floor Corridor - 1926**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/03/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Locke School** REVIEW DATE: **11/22/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **25**

MATERIAL DESCRIPTION: **12"x12" Purple Vinyl Floor Tile - ABATED**

MATERIAL LOCATION: **1st Floor Corridor - 1926**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/22/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Locke School** INSPECTION DATE: **10/3/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26**  
MATERIAL DESCRIPTION: **12"x12" Purple Vinyl Floor Tile Mastic - ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st Floor Corridor - 1926**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/03/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Locke School** REVIEW DATE: **11/22/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **26**

MATERIAL DESCRIPTION: **12"x12" Purple Vinyl Floor Tile Mastic - ABATED**

MATERIAL LOCATION: **1st Floor Corridor - 1926**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/22/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Locke School** INSPECTION DATE: **10/3/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27**  
MATERIAL DESCRIPTION: **12"x12" Black w/ White Streaks Vinyl Floor Tile - ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st Floor Corridor - 1926**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/03/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Locke School** REVIEW DATE: **11/22/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **27**

MATERIAL DESCRIPTION: **12"x12" Black w/ White Streaks Vinyl Floor Tile - ABATED**

MATERIAL LOCATION: **1st Floor Corridor - 1926**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/22/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Locke School** INSPECTION DATE: **10/3/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28**  
MATERIAL DESCRIPTION: **12"x12" Black w/ White Streaks Floor Tile Mastic - ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY **6**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st Floor Corridor - 1926**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 10/03/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Locke School** REVIEW DATE: **11/22/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **28**

MATERIAL DESCRIPTION: **12"x12" Black w/ White Streaks Floor Tile Mastic - ABATED**

MATERIAL LOCATION: **1st Floor Corridor - 1926**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/22/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Locke School** INSPECTION DATE: **10/3/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **29**  
MATERIAL DESCRIPTION: **12"x12" White w/ Tan Streaks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Rooms 119, 122, & 124 - 1926**  
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/03/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Locke School** REVIEW DATE: **11/22/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **29**  
MATERIAL DESCRIPTION: **12"x12" White w/ Tan Streaks Floor Tile**  
MATERIAL LOCATION: **Rooms 119, 122, & 124 - 1926**  
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/22/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Locke School** INSPECTION DATE: **10/3/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **30**  
MATERIAL DESCRIPTION: **12"x12" White w/ Tan Streaks Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 119, 122, & 124 - 1926**  
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/03/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Locke School** REVIEW DATE: **11/22/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **30**  
MATERIAL DESCRIPTION: **12"x12" White w/ Tan Streaks Floor Tile Mastic**  
MATERIAL LOCATION: **Rooms 119, 122, & 124 - 1926**  
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/22/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Locke School** INSPECTION DATE: **10/3/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **33**  
MATERIAL DESCRIPTION: **Red Linoleum (Not Observed)**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Auditorium - 1926**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/03/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Locke School** REVIEW DATE: **11/22/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **33**  
MATERIAL DESCRIPTION: **Red Linoleum (Not Observed)**  
MATERIAL LOCATION: **Auditorium - 1926**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/22/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Locke School** INSPECTION DATE: **10/3/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **34**  
MATERIAL DESCRIPTION: **Red Linoleum Mastic (Not Observed)**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Auditorium - 1926**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/03/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Locke School** REVIEW DATE: **11/22/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **34**  
MATERIAL DESCRIPTION: **Red Linoleum Mastic (Not Observed)**  
MATERIAL LOCATION: **Auditorium - 1926**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/22/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Locke School** INSPECTION DATE: **10/3/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **35**  
MATERIAL DESCRIPTION: **2'x2' White Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 225 - 1926**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/03/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Locke School** REVIEW DATE: **11/22/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **35**  
MATERIAL DESCRIPTION: **2'x2' White Ceiling Tile**  
MATERIAL LOCATION: **Room 225 - 1926**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/22/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Locke School** INSPECTION DATE: **10/3/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **36**  
MATERIAL DESCRIPTION: **Hard Coat Plaster**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout - 1936**  
MATERIAL QUANTITY: **60000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/03/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Locke School** REVIEW DATE: **11/22/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **36**  
MATERIAL DESCRIPTION: **Hard Coat Plaster**  
MATERIAL LOCATION: **Throughout - 1936**  
MATERIAL QUANTITY: **60000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/22/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Locke School** INSPECTION DATE: **10/3/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37**  
MATERIAL DESCRIPTION: **12"x12" Black Vinyl Floor Tile - ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Engineer's Office - 1926**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/03/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Locke School** REVIEW DATE: **11/22/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **37**

MATERIAL DESCRIPTION: **12"x12" Black Vinyl Floor Tile - ABATED**

MATERIAL LOCATION: **Engineer's Office - 1926**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/22/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Locke School** INSPECTION DATE: **10/3/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **38**  
MATERIAL DESCRIPTION: **12"x12" Black Vinyl Floor Tile Mastic - ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Engineer's Office - 1926**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/03/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Locke School** REVIEW DATE: **11/22/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **38**

MATERIAL DESCRIPTION: **12"x12" Black Vinyl Floor Tile Mastic - ABATED**

MATERIAL LOCATION: **Engineer's Office - 1926**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/22/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Locke School** INSPECTION DATE: **10/3/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **39**  
MATERIAL DESCRIPTION: **12"x12" Maroon Vinyl Floor Tile - ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Engineer's Office - 1926**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/03/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Locke School** REVIEW DATE: **11/22/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **39**

MATERIAL DESCRIPTION: **12"x12" Maroon Vinyl Floor Tile - ABATED**

MATERIAL LOCATION: **Engineer's Office - 1926**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/22/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Locke School** INSPECTION DATE: **10/3/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **40**  
MATERIAL DESCRIPTION: **12"x12" Maroon Vinyl Floor Tile Mastic - ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Engineer's Office - 1926**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/03/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Locke School** REVIEW DATE: **11/22/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **40**

MATERIAL DESCRIPTION: **12"x12" Maroon Vinyl Floor Tile Mastic - ABATED**

MATERIAL LOCATION: **Engineer's Office - 1926**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/22/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Locke School** INSPECTION DATE: **10/3/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **41**  
MATERIAL DESCRIPTION: **2'x4' Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Engineer's Office - 1926**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/03/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Locke School** REVIEW DATE: **11/22/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **41**  
MATERIAL DESCRIPTION: **2'x4' Ceiling Tile**  
MATERIAL LOCATION: **Engineer's Office - 1926**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/22/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Locke School** INSPECTION DATE: **10/3/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **50**  
MATERIAL DESCRIPTION: **12"x12" Green w/ Specks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Throughout - 1998**  
MATERIAL QUANTITY: **8000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/03/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Locke School** REVIEW DATE: **11/22/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **50**  
MATERIAL DESCRIPTION: **12"x12" Green w/ Specks Floor Tile**  
MATERIAL LOCATION: **Throughout - 1998**  
MATERIAL QUANTITY: **8000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/22/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Locke School** INSPECTION DATE: **10/3/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **51**  
MATERIAL DESCRIPTION: **12"x12" Green w/ Specks Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout - 1998**  
MATERIAL QUANTITY: **8000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/03/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Locke School** REVIEW DATE: **11/22/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **51**  
MATERIAL DESCRIPTION: **12"x12" Green w/ Specks Floor Tile Mastic**  
MATERIAL LOCATION: **Throughout - 1998**  
MATERIAL QUANTITY: **8000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/22/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Locke School** INSPECTION DATE: **10/3/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **52**  
MATERIAL DESCRIPTION: **12"x12" Blue Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Rooms 223, 225, 226, 227, 228, 229, 230, 231, 136, 128, 133, 135, 137 - 1998**  
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/03/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Locke School** REVIEW DATE: **11/22/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **52**  
MATERIAL DESCRIPTION: **12"x12" Blue Floor Tile**  
MATERIAL LOCATION: **Rooms 223, 225, 226, 227, 228, 229, 230, 231, 136, 128, 133, 135, 137 - 1998**  
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/22/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Locke School** INSPECTION DATE: **10/3/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **53**  
MATERIAL DESCRIPTION: **12"x12" Blue Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 223, 225, 226, 227, 228, 229, 230, 231, 136, 128, 133, 135, 137 - 1998**  
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/03/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Locke School** REVIEW DATE: **11/22/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **53**  
MATERIAL DESCRIPTION: **12"x12" Blue Floor Tile Mastic**  
MATERIAL LOCATION: **Rooms 223, 225, 226, 227, 228, 229, 230, 231, 136, 128, 133, 135, 137 - 1998**  
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/22/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Locke School** INSPECTION DATE: **10/3/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **54**  
MATERIAL DESCRIPTION: **2'x4' White w/ Grooves Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Throughout - 1998**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/03/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Locke School** REVIEW DATE: **11/22/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **54**

MATERIAL DESCRIPTION: **2'x4' White w/ Grooves Ceiling Tile**

MATERIAL LOCATION: **Throughout - 1998**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/22/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Locke School** INSPECTION DATE: **10/3/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **55**  
MATERIAL DESCRIPTION: **Green Linoleum**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Cafeteria, Kitchen - 1998**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/03/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Locke School** REVIEW DATE: **11/22/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **55**

MATERIAL DESCRIPTION: **Green Linoleum**

MATERIAL LOCATION: **Cafeteria, Kitchen - 1998**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: 11/22/2019



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Locke School** INSPECTION DATE: **10/3/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **56**  
MATERIAL DESCRIPTION: **Green Linoleum Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Cafeteria, Kitchen - 1998**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/03/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Locke School** REVIEW DATE: **11/22/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **56**  
MATERIAL DESCRIPTION: **Green Linoleum Mastic**  
MATERIAL LOCATION: **Cafeteria, Kitchen - 1998**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: 11/22/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Locke School** INSPECTION DATE: **10/3/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **57**  
MATERIAL DESCRIPTION: **Blue Linoleum**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Cafeteria, Kitchen - 1998**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **10/03/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Locke School** REVIEW DATE: **11/22/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **57**

MATERIAL DESCRIPTION: **Blue Linoleum**

MATERIAL LOCATION: **Cafeteria, Kitchen - 1998**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/22/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Locke School** INSPECTION DATE: **10/3/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **57A**  
MATERIAL DESCRIPTION: **Blue Linoleum Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Cafeteria, Kitchen - 1998**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **10/03/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Locke School** REVIEW DATE: **11/22/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **57A**

MATERIAL DESCRIPTION: **Blue Linoleum Mastic**

MATERIAL LOCATION: **Cafeteria, Kitchen - 1998**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: 11/22/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Locke School** INSPECTION DATE: **10/3/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **58**  
MATERIAL DESCRIPTION: **Drywall**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout - 1998**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **10/03/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Locke School** REVIEW DATE: **11/22/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **58**

MATERIAL DESCRIPTION: **Drywall**

MATERIAL LOCATION: **Throughout - 1998**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/22/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Locke School** INSPECTION DATE: **10/3/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **59**  
MATERIAL DESCRIPTION: **Drywall Compound**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout - 1998**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **10/03/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Locke School** REVIEW DATE: **11/22/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **59**

MATERIAL DESCRIPTION: **Drywall Compound**

MATERIAL LOCATION: **Throughout - 1998**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/22/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Locke School** INSPECTION DATE: **10/3/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **60**  
MATERIAL DESCRIPTION: **Vinyl Baseboards**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout - 1998**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **10/03/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Locke School** REVIEW DATE: **11/22/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **60**

MATERIAL DESCRIPTION: **Vinyl Baseboards**

MATERIAL LOCATION: **Throughout - 1998**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/22/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Locke School** INSPECTION DATE: **10/3/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **61**  
MATERIAL DESCRIPTION: **Vinyl Baseboard Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout - 1998**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **10/03/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Locke School** REVIEW DATE: **11/22/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **61**  
MATERIAL DESCRIPTION: **Vinyl Baseboard Mastic**  
MATERIAL LOCATION: **Throughout - 1998**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/22/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Locke School** INSPECTION DATE: **10/3/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **62**  
MATERIAL DESCRIPTION: **Spray-On Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Above Ceiling 1st Floor - 1998**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **10/03/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUILDING ID: **4510**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Locke School** REVIEW DATE: **11/22/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **62**

MATERIAL DESCRIPTION: **Spray-On Insulation**

MATERIAL LOCATION: **Above Ceiling 1st Floor - 1998**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/22/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Locke School** INSPECTION DATE: **10/3/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **63**  
MATERIAL DESCRIPTION: **Carpet Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Main Office Area, Library - 1998**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **10/03/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Locke School** REVIEW DATE: **11/22/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **63**

MATERIAL DESCRIPTION: **Carpet Mastic**

MATERIAL LOCATION: **Main Office Area, Library - 1998**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: 11/22/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Locke School** INSPECTION DATE: **10/3/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **64**  
MATERIAL DESCRIPTION: **2'x4' White Smooth Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Kitchen & Storage - 1998**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **10/03/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Locke School** REVIEW DATE: **11/22/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **64**

MATERIAL DESCRIPTION: **2'x4' White Smooth Ceiling Tile**

MATERIAL LOCATION: **Kitchen & Storage - 1998**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/22/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Locke School** INSPECTION DATE: **10/3/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **65**  
MATERIAL DESCRIPTION: **Terrazzo**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Stair Wells and Stairs Throughout 1st and 2nd Floor Corridors**  
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/03/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Locke School** REVIEW DATE: **11/22/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **65**  
MATERIAL DESCRIPTION: **Terrazzo**  
MATERIAL LOCATION: **Stair Wells and Stairs Throughout 1st and 2nd Floor Corridors**  
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/22/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Locke School** INSPECTION DATE: **10/3/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **66**  
MATERIAL DESCRIPTION: **Carpet Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 108**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/03/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Locke School** REVIEW DATE: **11/22/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **66**  
MATERIAL DESCRIPTION: **Carpet Mastic**  
MATERIAL LOCATION: **Room 108**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/22/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Locke School** INSPECTION DATE: **10/3/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **67**  
MATERIAL DESCRIPTION: **2' x 4' Dot Ceiling Tile (with 2' x 2' Layout)**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 108, 119, 121, and Old 2nd Floor Girl's Locker Room.**  
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/03/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Locke School** REVIEW DATE: **11/22/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **67**  
MATERIAL DESCRIPTION: **2' x 4' Dot Ceiling Tile (with 2' x 2' Layout)**  
MATERIAL LOCATION: **Rooms 108, 119, 121, and Old 2nd Floor Girl's Locker Room.**  
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/22/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Locke School** INSPECTION DATE: **10/3/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **68**  
MATERIAL DESCRIPTION: **Terrazzo**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Corridors and Toilets (1998)**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/03/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUILDING ID: **4510**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Locke School** REVIEW DATE: **11/22/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **68**  
MATERIAL DESCRIPTION: **Terrazzo**  
MATERIAL LOCATION: **Corridors and Toilets (1998)**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/22/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Locke School** INSPECTION DATE: **10/3/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **69**  
MATERIAL DESCRIPTION: **12"x12" Gold Mottled Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Old 2nd Floor Girl's Locker Room.**  
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/03/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Locke School** REVIEW DATE: **11/22/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **69**  
MATERIAL DESCRIPTION: **12"x12" Gold Mottled Floor Tile**  
MATERIAL LOCATION: **Old 2nd Floor Girl's Locker Room.**  
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/22/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Locke School** INSPECTION DATE: **10/3/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **70**  
MATERIAL DESCRIPTION: **12"x12" Gold Mottled Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Old 2nd Floor Girl's Locker Room**  
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/03/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Locke School** REVIEW DATE: **11/22/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **70**  
MATERIAL DESCRIPTION: **12"x12" Gold Mottled Floor Tile Mastic**  
MATERIAL LOCATION: **Old 2nd Floor Girl's Locker Room**  
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/22/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Locke School** INSPECTION DATE: **10/3/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **71**  
MATERIAL DESCRIPTION: **12"x12" Gold Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Throughout Classrooms in 1998 Building**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/03/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUILDING ID: **4510**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Locke School** REVIEW DATE: **11/22/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **71**  
MATERIAL DESCRIPTION: **12"x12" Gold Floor Tile**  
MATERIAL LOCATION: **Throughout Classrooms in 1998 Building**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/22/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Locke School** INSPECTION DATE: **10/3/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **72**  
MATERIAL DESCRIPTION: **12"x12" Gold Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout Classrooms in 1998 Building**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/03/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Locke School** REVIEW DATE: **11/22/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **72**  
MATERIAL DESCRIPTION: **12"x12" Gold Floor Tile Mastic**  
MATERIAL LOCATION: **Throughout Classrooms in 1998 Building**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/22/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Locke School** INSPECTION DATE: **10/3/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **73**  
MATERIAL DESCRIPTION: **12" x 12" Blue Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **1st and 2nd Floor Corridors**  
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/03/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Locke School** REVIEW DATE: **11/22/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **73**  
MATERIAL DESCRIPTION: **12" x 12" Blue Floor Tile**  
MATERIAL LOCATION: **1st and 2nd Floor Corridors**  
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/22/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Locke School** INSPECTION DATE: **10/3/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **73M**  
MATERIAL DESCRIPTION: **12" x 12" Blue Floor Tile Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st and 2nd Floor Corridors**  
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/03/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Locke School** REVIEW DATE: **11/22/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **73M**  
MATERIAL DESCRIPTION: **12" x 12" Blue Floor Tile Adhesive**  
MATERIAL LOCATION: **1st and 2nd Floor Corridors**  
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/22/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Locke School** INSPECTION DATE: **10/3/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **74**  
MATERIAL DESCRIPTION: **12" x 12" Tan Multicolored Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **5 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Engineer's Office, Rooms 117 and 112**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **7** DAMAGE UNITS: **SF**

COMMENTS: **Damaged observed in Engineer's Office**

Inspector's Signature: \_\_\_\_\_ Date: 10/03/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Locke School** REVIEW DATE: **11/22/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **74**  
MATERIAL DESCRIPTION: **12" x 12" Tan Multicolored Floor Tile**  
MATERIAL LOCATION: **Engineer's Office, Rooms 117 and 112**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **7** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

replace damaged tiles

Management Planner's Signature: \_\_\_\_\_ Date: **11/22/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Locke School** INSPECTION DATE: **10/3/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **74M**  
MATERIAL DESCRIPTION: **12" x 12" Tan Multicolored Floor Tile Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Engineer's Office, Rooms 117 and 122**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/03/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUILDING ID: **4510**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Locke School** REVIEW DATE: **11/22/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **74M**  
MATERIAL DESCRIPTION: **12" x 12" Tan Multicolored Floor Tile Adhesive**  
MATERIAL LOCATION: **Engineer's Office, Rooms 117 and 122**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/22/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Locke School** INSPECTION DATE: **10/3/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **75**  
MATERIAL DESCRIPTION: **2'x4' Grooved Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 222**

MATERIAL QUANTITY: **600**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/03/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Locke School** REVIEW DATE: **11/22/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **75**  
MATERIAL DESCRIPTION: **2'x4' Grooved Ceiling Tile**  
MATERIAL LOCATION: **Room 222**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/22/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Locke School** INSPECTION DATE: **10/3/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **76**  
MATERIAL DESCRIPTION: **CMU Wall Mortar**  
HISTORICAL AHERA DAMAGE CATEGORY **6**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1998 Addition Throughout**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY: **0**

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/03/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Locke School** REVIEW DATE: **11/22/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **76**

MATERIAL DESCRIPTION: **CMU Wall Mortar**

MATERIAL LOCATION: **1998 Addition Throughout**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY: **0**

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/22/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Locke School** INSPECTION DATE: **10/3/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **77**  
MATERIAL DESCRIPTION: **Brown ceramic tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **1st + 2nd Floor boys and girls toilets -1926 bldg**  
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/03/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Locke School** REVIEW DATE: **11/22/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **77**  
MATERIAL DESCRIPTION: **Brown ceramic tile**  
MATERIAL LOCATION: **1st + 2nd Floor boys and girls toilets -1926 bldg**  
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/22/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Locke School** INSPECTION DATE: **10/3/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **77A**  
MATERIAL DESCRIPTION: **Brown ceramic tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st + 2nd Floor boys and girls toilets -1926 bldg**  
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/03/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Locke School** REVIEW DATE: **11/22/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **77A**  
MATERIAL DESCRIPTION: **Brown ceramic tile Mastic**  
MATERIAL LOCATION: **1st + 2nd Floor boys and girls toilets -1926 bldg**  
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/22/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Locke School** INSPECTION DATE: **10/3/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **78**  
MATERIAL DESCRIPTION: **12" x 12" Cream speckled VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Auditorium**  
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/03/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Locke School** REVIEW DATE: **11/22/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **78**  
MATERIAL DESCRIPTION: **12" x 12" Cream speckled VFT**  
MATERIAL LOCATION: **Auditorium**  
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/22/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Locke School** INSPECTION DATE: **10/3/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **78A**  
MATERIAL DESCRIPTION: **12" x 12" Cream speckled VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Auditorium**  
MATERIAL QUANTITY: **14000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/03/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUILDING ID: **4510**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Locke School** REVIEW DATE: **11/22/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **78A**  
MATERIAL DESCRIPTION: **12" x 12" Cream speckled VFT Mastic**  
MATERIAL LOCATION: **Auditorium**  
MATERIAL QUANTITY: **14000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/22/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Locke School** INSPECTION DATE: **10/3/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **79**  
MATERIAL DESCRIPTION: **Textured plaster**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Auditorium & Balcony**

MATERIAL QUANTITY: **45000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/03/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Locke School** REVIEW DATE: **11/22/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **79**  
MATERIAL DESCRIPTION: **Textured plaster**  
MATERIAL LOCATION: **Auditorium & Balcony**  
MATERIAL QUANTITY: **45000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/22/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Locke School** INSPECTION DATE: **10/3/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **80**  
MATERIAL DESCRIPTION: **12" x 12" Gray speckled VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Room 108**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/03/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Locke School** REVIEW DATE: **11/22/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **80**  
MATERIAL DESCRIPTION: **12" x 12" Gray speckled VFT**  
MATERIAL LOCATION: **Room 108**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/22/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Locke School** INSPECTION DATE: **10/3/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **80A**  
MATERIAL DESCRIPTION: **12" x 12" Gray speckled VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 108**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/03/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Locke School** REVIEW DATE: **11/22/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **80A**  
MATERIAL DESCRIPTION: **12" x 12" Gray speckled VFT Mastic**  
MATERIAL LOCATION: **Room 108**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/22/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Locke School** INSPECTION DATE: **10/3/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **81**  
MATERIAL DESCRIPTION: **12" x 12" Blue speckled VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Room 115, 122**  
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/03/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUILDING ID: **4510**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Locke School** REVIEW DATE: **11/22/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **81**  
MATERIAL DESCRIPTION: **12" x 12" Blue speckled VFT**  
MATERIAL LOCATION: **Room 115, 122**  
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/22/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Locke School** INSPECTION DATE: **10/3/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **81A**  
MATERIAL DESCRIPTION: **12" x 12" Blue speckled VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 115, 122**  
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/03/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Locke School** REVIEW DATE: **11/22/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **81A**  
MATERIAL DESCRIPTION: **12" x 12" Blue speckled VFT Mastic**  
MATERIAL LOCATION: **Room 115, 122**  
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/22/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Locke School** INSPECTION DATE: **10/3/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **L**  
MATERIAL DESCRIPTION: **Spray-on Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Above Ceilings in Attic - 1926**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **10/03/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24231** BUIDLING ID: **4510**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Locke School** REVIEW DATE: **11/22/2019**  
ADDRESS: **2845 N. Newcastle Avenue** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **L**

MATERIAL DESCRIPTION: **Spray-on Insulation**

MATERIAL LOCATION: **Throughout Above Ceilings in Attic - 1926**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/22/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.

*2019 AHERA REINSPECTION*

# APPENDIX B

## Inspector and Management Planner Licenses

---

# CERTIFICATE OF ACHIEVEMENT ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that PANFILO CARRAZCO  
has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the  
examination on 02/13/2016 with a minimum score of 70% or better. Training was in accordance  
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:  
Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.

02/13/2016

Course Dates:

02/13/2017

Expires:

1602BIR10

Certificate Number:



**PUBLIC HEALTH & SAFETY** inc.

Environmental and Occupational Services  
103 S. Ashland Ave., Chicago, IL 60607

Director of Training

Nicholas J. Penneff

Doctor of Public Health

Phone: 312-491-0081

FORM # A-010B



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • [www.dph.illinois.gov](http://www.dph.illinois.gov)

**PANFILO CARRAZCO**  
855 W ADAMS STREET, SUITE 200  
CHICAGO, IL 60607

4/28/2017

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 11089

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

**COPY OF THE ASBESTOS PROFESSIONAL LICENSE**

Front of License

Back of License

		<b>ASBESTOS PROFESSIONAL LICENSE</b>		<b>ENDORSEMENTS</b>	<b>TC EXPIRES</b>
<b>ID NUMBER</b> 100 - 11089	<b>ISSUED</b> 4/28/2017	<b>EXPIRES</b> 05/15/2018		INSPECTOR	2/11/2018
<b>PANFILO CARRAZCO</b> 855 W ADAMS STREET, SUITE CHICAGO, IL 60607 Environmental Health:				PROJECT MANAGER AIR SAMPLING PROFESSIONAL	2/4/2018
				<b>Alteration of this license shall result in legal action</b> This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: [dph.illinois.gov/topics-services/environmental-health-protection/asbestos](http://dph.illinois.gov/topics-services/environmental-health-protection/asbestos)  
EMAIL Address: [dph.asbestos@illinois.gov](mailto:dph.asbestos@illinois.gov)

**PROTECTING HEALTH, IMPROVING LIVES**

*Nationally Accredited by PHAB*



# CERTIFICATE OF ACHIEVEMENT ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that PANILO CARRAZCO  
has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the  
examination on 02/09/2019 with a minimum score of 70% or better. Training was in accordance  
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:  
Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.



02/09/2019

Course Dates:

02/09/2020

Expires:

1902BIR08

Certificate Number:

*Nicholas J. Peneff*

Director of Training  
Nicholas J. Peneff  
Doctor of Public Health

Phone: 312-491-0081

FORM # A-010B



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • [www.dph.illinois.gov](http://www.dph.illinois.gov)

**PANFILO CARRAZCO**  
2942 W VAN BUREN ST  
CHICAGO, IL 60612

4/19/2019

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 11089

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

**COPY OF THE ASBESTOS PROFESSIONAL LICENSE**

Front of License

Back of License

 <b>ASBESTOS PROFESSIONAL LICENSE</b>			<b>ENDORSEMENTS</b>	<b>TC EXPIRES</b>
<b>ID NUMBER</b> 100 - 11089	<b>ISSUED</b> 4/19/2019	<b>EXPIRES</b> 05/15/2020	INSPECTOR	2/9/2020
<b>PANFILO CARRAZCO</b> 2942 W VAN BUREN ST CHICAGO, IL 60612 Environmental Health			PROJECT MANAGER AIR SAMPLING PROFESSIONAL	2/2/2020
			<b>Alteration of this license shall result in legal action</b> This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: [dph.illinois.gov/topics-services/environmental-health-protection/asbestos](http://dph.illinois.gov/topics-services/environmental-health-protection/asbestos)  
EMAIL Address: [dph.asbestos@illinois.gov](mailto:dph.asbestos@illinois.gov)

**PROTECTING HEALTH, IMPROVING LIVES**  
*Nationally Accredited by PHAB*



535-535 West Jefferson Street • Springfield, Illinois 62761-0201 • [www.dph.illinois.gov](http://www.dph.illinois.gov)

4/18/2016

**PANFILO CARRAZCO**  
855 W ADAMS STREET, SUITE 200  
CHICAGO, IL 60607

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 11089

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

**COPY OF THE ASBESTOS PROFESSIONAL LICENSE**

Front of License

Back of License

ASBESTOS PROFESSIONAL LICENSE			ENDORSEMENTS	TC EXPIRES
ID NUMBER	ISSUED	EXPIRES	INSPECTOR	2/13/2017
100 - 11089	4/18/2016	05/15/2017	PROJECT MANAGER	2/6/2017
PANFILO CARRAZCO 855 W ADAMS STREET, SUITE CHICAGO, IL 60607 Environmental Health			AIR SAMPLING PROFESSIONAL <b>Alteration of this license shall result in legal action</b> This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: [dph.illinois.gov/topics-services/environmental-health-protection/asbestos](http://dph.illinois.gov/topics-services/environmental-health-protection/asbestos)  
EMAIL Address: [dph.asbestos@illinois.gov](mailto:dph.asbestos@illinois.gov)

**PROTECTING HEALTH. IMPROVING LIVES**  
*Nationally Accredited by PHAB*

2019



**OCCUPATIONAL TRAINING & SUPPLY, INC.**

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900 ♦ [www.otssafety.com](http://www.otssafety.com)

# Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

**Jigar Shah**

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 2/28/2019

Exam Date: 2/28/2019

Expiration Date: 2/28/2020

Certificate Number: MPR1902280695

  
Kathy DeSalvo, Director



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • [www.dph.illinois.gov](http://www.dph.illinois.gov)

**JIGAR M SHAH**  
2942 W VAN BUREN ST  
CHICAGO, IL 60612

4/19/2019




ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 07342

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

**COPY OF THE ASBESTOS PROFESSIONAL LICENSE**

Front of License

Back of License

ASBESTOS PROFESSIONAL LICENSE			ENDORSEMENTS	TC EXPIRES
			INSPECTOR	2/28/2020
ID NUMBER	ISSUED	EXPIRES	PROJECT DESIGNER	3/15/2020
100 - 07342	4/19/2019	05/15/2020	MANAGEMENT PLANNER	2/28/2020
<b>JIGAR M SHAH</b>			PROJECT MANAGER	2/22/2020
2942 W VAN BUREN ST			AIR SAMPLING PROFESSIONAL	
CHICAGO, IL 60612			<b>Alteration of this license shall result in legal action</b>	
Environmental Health			This license issued under authority of the State of Illinois	
			Department of Public Health	
			This license is valid only when accompanied by a valid training course certificate.	

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: [dph.illinois.gov/topics-services/environmental-health-protection/asbestos](http://dph.illinois.gov/topics-services/environmental-health-protection/asbestos)  
EMAIL Address: [dph.asbestos@illinois.gov](mailto:dph.asbestos@illinois.gov)

**PROTECTING HEALTH, IMPROVING LIVES**  
*Nationally Accredited by PHAB*

# APPENDIX C

## Laboratory Accreditations

---

# APPENDIX D

## Laboratory Results

---

# APPENDIX E

## Chain of Custody Forms

---



## Three-Year Reinspection Key to Terms

	<b>CODE</b>	<b>KEY</b>
<b>MATERIAL</b>		
	ACBM	Asbestos Containing Building Materials
<b>MATERIAL CATEGORY</b>		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
<b>MATERIAL UNITS</b>		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
<b>DAMAGE TYPE</b>		
	Loc	Localized
	Dist	Distributed