

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM**

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-2323
SCHOOL NAME: Lyon School
ADDRESS OF SCHOOL: 2941 N. McVicker Avenue
CITY: Chicago, IL, 60634

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED 2/18/2016

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II *(Please type or print)*

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 10/1/2019 ENROLLMENT 1315
IDPH INSPECTOR LICENSE NUMBER: 100-11255
IDPH LICENSED INSPECTOR NAME(Please Print): Esteban Nunez
IDPH MP LICENSE NUMBER: 100-04019
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Arturo Saenz

DESIGNATED PERSON (Please Print): Robert Christlieb PHONE: (773) 553-3197



10/1/2019

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Lyon School

2941 N. McVicker Avenue
Chicago, IL, 60634

Unit: 24281
Building ID: 4560

IDPH ID Number: 14-016-2990-2323

REPORT DATE:

Tuesday, October 01, 2019

Prepared for:

**Chicago Public Schools
42 West Madison Street
Chicago, IL 60602**

Prepared by:

GSG-Probe Consulting, Inc.

2942 W. Van Buren

Chicago, IL, 60612

Phone 3123197575

Fax

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

September 16, 2019

Mr. Glen E. Garner
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2019 Three-Year Reinspections

Dear Mr. Glen:

GSG-Probe Consulting, Inc., Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 1, 2 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 24281 Region: 02 IDPH ID:14-016-2990-2323

School: Lyon School Building ID: 4560

Address: 2941 N. McVicker Avenue
Chicago, IL, 60634

Building Contact: Contact Phone:

Current Building Owners: Chicago Public Schools

Review Date: 10/11/2019

Inspector: Esteban Nunez Inspector IDPH License: 100-11255
Management Planner: Arturo Saenz Management Planner IDPH License: 100-04019

If you have any questions or comments, please contact us at 3123197575

Sincerely,
GSG-Probe Consulting, Inc.

Arturo Saenz
100-04019

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: September 16, 2019

RE: Lyon School, Unit 24281
2941 N. McVicker Avenue
Chicago, IL, 60634

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2019 asbestos three year re-inspection has been completed at Lyon School, following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at Lyon School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Robert Christlieb, the designated Local Education Authority's Designated Person at (773) 553-3197 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Lyon School Unit: 24281 Region: 02
Address: 2941 N. McVicker Avenue Chicago, IL, 60634
IDPH ID: 14-016-2990-2323 Building ID: 4560
Contact: Phone:

2. Description of Facility

Original Construction: 1998 Additional Construction: 1926
Total Square Footage: 53326 No of Floors: 2
Current Occupancy: 1315

3. LEA Designated Person

Contact: Robert Christlieb Phone: (773) 553-3197
Address: 42 West Madison Street
Chicago, IL 60602

4. Managing Environmental Consultant

MEC: GSG-Probe Consulting, Inc.
Contact: Jigar Shah
Address 2942 W. Van Buren
Chicago, IL, 60612
Phone: 3123197575 Fax:

5. Inspector

Inspector Name: Esteban Nunez

Inspector IDPH license # 100-11255

Signature:
Date: 9/16/2019

6. Management Planner

Management Planner Name: Arturo Saenz

Management Planner IDPH license # 100-04019

Signature:
Date: 10/11/2019

7. Review Date:10/11/2019

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature:



Date: 10/1/2019

Name: Robert Christlieb

II. EXECUTIVE SUMMARY

GSG-Probe Consulting, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Lyon School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.85 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 4560:

B. The following new homogenous areas have been identified for Building 4560:

- 69 White Terrazzo
- 70 Blue Terrazzo
- 71 Maroon Terrazzo

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

04	12"x12" Sand & Brown Spotted VFT
06	12"x12" Sand & Brown Spotted VFT Mastic
18	12"x12" Sand & Brown Spotted VFT
19	12"x12" Sand & Brown Spotted VFT Mastic
21	12"x12" Off White VFT Mastic
23	9"x9" Beige VFT Mastic - NOT OBSERVED
27	12"x12" Gray w/ Color Specs VFT
28	12"x12" Gray w/ Color Specs VFT Mastic
29	12"x12" Blue VFT
30	12"x12" Blue VFT Mastic
31	12"x12" Red VFT
32	12"x12" Red VFT Mastic
43	Hardcoat Plaster
44	Hardcoat Plaster
45	Grey Terrazzo
46	Grey Terrazzo
47	2' x 4' Fissured Ceiling Tile
48	2' x 4' Fissured Ceiling Tile
49	Brownish Grey Carpet Adhesive
50	9" x 9" Tan and White Specs VFT
50M	9" x 9" Tan and White Specs VFT Mastic
51	9" x 9" Tan and White Specs VFT
51M	9" x 9" Tan and White Specs VFT Mastic
52	2' x 4' Acoustical Ceiling Tile
53	Glue Dots Behind Chalk Board
54	Glue Dots Behind Chalk Board
55	White Ceramic Tile Grout
56	White Ceramic Tile Adhesive
57	12" x 12" Multi-Color VFT
57M	12" x 12" Multi-Color VFT Mastic
58	12" x 12" Multi-Color VFT
58M	12" x 12" Multi-Color VFT Mastic
59	White Ceramic Tile Grout
60	White Ceramic Tile Adhesive
61	Brown Ceramic Tile Grout
62	Brown Ceramic Tile Adhesive
63	Carpet Mastic (Gray)
64	12" x 12" Multi Color VFT
65	12" x 12" Multi Color VFT Mastic
66	Carpet Mastic (Red) NOT OBSERVED
67	12" x 12" White w/ Beige Streaks VFT
68	12" x 12" White w/ Beige Streaks VFT MASTIC

69	White Terrazzo
70	Blue Terrazzo
71	Maroon Terrazzo
Q	MJP E/F/V on Fiberglass Pipe Insulation

The following areas were deemed to be inaccessible:

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Esteban Nunez, IDPH License # 100-11255. The Management Plan was updated by Arturo Saenz, IDPH License # 100-04019. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Lyon School Building 4560 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Lyon School Unit 24281 Building ID 4560

Address 2941 N. McVicker Avenue Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
04	12"x12" Sand & Brown Spotted VFT	1,900	SF	1st Floor Corridor - 1926 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
05	9"x9" Black w/ White Streaks VFT - NOT OBSERVED	1,900	SF	2nd Floor Corridor - 1926 Bldg. - Not Observed	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
06	12"x12" Sand & Brown Spotted VFT Mastic	1,900	SF	1st Floor Corridor - 1926 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
07	9"x9" Black w/ White Streaks VFT Mastic - NOT OBSERVED	1,200	SF	2nd Floor Corridor - 1926 Bldg. - Not Observed	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
08	9"x9" Black VFT - NOT OBSERVED	1,200	SF	2nd Floor Corridor - 1936 Bldg. - Not Observed	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
09	9"x9" Black VFT Mastic - NOT OBSERVED	1,200	SF	2nd Floor Corridor - 1936 Bldg. - Not Observed	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
14	12"x12" White VFT	900	SF	Room 205 (under carpet) - 1926 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
15	12"x12" White VFT Mastic	900	SF	Room 205 (under carpet) - 1926 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
18	12"x12" Sand & Brown Spotted VFT	750	SF	1st Floor Corridor - 1936 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
19	12"x12" Sand & Brown Spotted VFT Mastic	750	SF	1st Floor Corridor - 1936 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
20	12"x12" Off White VFT	750	SF	Room 104 - 1926 Bldg.	CHR	MISC	N	UNKNO WN	0		No	ACBM with the potential for damage		LOW
21	12"x12" Off White VFT Mastic	750	SF	Room 104 - 1926 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
22	9"x9" Beige VFT - NOT OBSERVED	600	SF	PTA Room & Room 104B & Toilet - 1926 Bldg. - Not Observed	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
23	9"x9" Beige VFT Mastic - NOT OBSERVED	600	SF	PTA Room & Room 104B & Toilet - 1926 Bldg. - 1926 Bldg. - Not Observed	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
24	12"x12" Beige VFT	600	SF	Main Office - 1926 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
25	12"x12" Beige VFT Mastic	600	SF	Main Office - 1926 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
26	2'x4' White w/ Grooves Ceiling Tile			Throughout 1999 Building	NO_ACBM						No			
27	12"x12" Gray w/ Color Specs VFT	15,000	SF	Throughout 1999	ASSUMED	MISC	N	NONE	0		No	ACBM with the		LOW

Chicago Public Schools

School Lyon School Unit 24281 Building ID 4560

Address 2941 N. McVicker Avenue Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Building								potential for damage		
28	12"x12" Gray w/ Color Specs VFT Mastic	15,000	SF	Throughout 1999 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
29	12"x12" Blue VFT	2,500	SF	Throughout 1999 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
30	12"x12" Blue VFT Mastic	2,500	SF	Throughout 1999 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
31	12"x12" Red VFT	2,500	SF	Throughout 1999 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
32	12"x12" Red VFT Mastic	2,500	SF	Throughout 1999 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
33	2'x4' Smooth White Ceiling Tile			Kitchen: Office, Toilet, Storage, Serving Area, & Corridor, 118B - 1999 Building	NO_ACBM						No			
34	Vinyl Baseboard			Throughout 1999 Building	NO_ACBM						No			
35	Vinyl Baseboard Mastic			Throughout 1999 Building	NO_ACBM						No			
36	Drywall			Throughout 1999 Building	NO_ACBM						No			
37	Drywall Compound			Throughout 1999 Building	NO_ACBM						No			
38	Carpet Mastic			Main Office Area, Library & Room 123, Room 121 Office - 1999 Building	NO_ACBM						No			
39	Cream Linoleum			Serving Area, Multipurpose Room - 1999 Building	NO_ACBM						No			
40	Cream Linoleum Mastic			Serving Area, Multipurpose Room - 1999 Building	NO_ACBM						No			
41	Blue Linoleum			Serving Area, Multipurpose Room - 1999 Building	NO_ACBM						No			
42	Blue Linoleum Mastic			Serving Area, Multipurpose Room - 1999 Building	NO_ACBM						No			
43	Hardcoat Plaster	56,000	SF	Throughout - 1926 Bldg.	ASSUMED	SURFACE	N	NONE	0		No	ACBM with the potential for damage		LOW
44	Hardcoat Plaster	20,000	SF	Throughout - 1936	ASSUMED	SURFACE	N	NONE	0		No	ACBM with the		LOW

Chicago Public Schools

School Lyon School Unit 24281 Building ID 4560

Address 2941 N. McVicker Avenue Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Bldg.								potential for damage		
45	Grey Terrazzo	2,500	SF	108 Restroom, All Stairways, Corridor Border - 1926 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
46	Grey Terrazzo	1,200	SF	Stage Stairs, Stairway, Corridor Border, Room 211A - 1936 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
47	2' x 4' Fissured Ceiling Tile	20,000	SF	Throughout 2nd Floor - 1926 Bldg.	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
48	2' x 4' Fissured Ceiling Tile	5,000	SF	Throughout 2nd Floor - 1936 Bldg.	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
49	Brownish Grey Carpet Adhesive	110	SF	Principal's Office - 1926 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
50	9" x 9" Tan and White Specs VFT	1,000	SF	Room 105 - 1926 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
50M	9" x 9" Tan and White Specs VFT Mastic	1,000	SF	Room 105 - 1926 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
51	9" x 9" Tan and White Specs VFT	500	SF	Room 111A - 1926 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
51M	9" x 9" Tan and White Specs VFT Mastic	500	SF	Room 111A - 1926 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
52	2' x 4' Acoustical Ceiling Tile	2,000	SF	Gymnasium - 1926 Bldg.	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
53	Glue Dots Behind Chalk Board	1,700	SF	All Classrooms - 1926 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
54	Glue Dots Behind Chalk Board	300	SF	All Classrooms - 1936 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
55	White Ceramic Tile Grout	300	SF	Assembly Hall Washrooms - 1936 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
56	White Ceramic Tile Adhesive	300	SF	Assembly Hall Washrooms - 1936 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
57	12" x 12" Multi-Color VFT	1,900	SF	2nd Floor Hallway, Rooms 205, 104, and Principal's Office - 1926 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
57M	12" x 12" Multi-Color VFT Mastic	1,900	SF	2nd Floor Hallway, Rooms 205, 104, and Principal's Office - 1926 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
58	12" x 12" Multi-Color VFT	750	SF	1st Floor Hall - 1936 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Lyon School Unit 24281 Building ID 4560

Address 2941 N. McVicker Avenue Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
58M	12" x 12" Multi-Color VFT Mastic	750	SF	1st Floor Hall - 1936 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
59	White Ceramic Tile Grout	267	SF	Room 214A, Kindergarten Bathroom, 1st Floor Copy Room - 1926 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
60	White Ceramic Tile Adhesive	267	SF	Room 214A, Kindergarten Bathroom, 1st Floor Copy Room - 1926 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
61	Brown Ceramic Tile Grout	1,200	SF	1st and 2nd Floor Boys and Girls Restrooms - 1926 and 1936 Buildings	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
62	Brown Ceramic Tile Adhesive	1,200	SF	1st and 2nd Floor Boys and Girls Restrooms - 1936 Bldgs.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
63	Carpet Mastic (Gray)	1,200	SF	Room 205 and 205A - 1926 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
64	12" x 12" Multi Color VFT	1,900	SF	1st Floor Corridor - 1926 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
65	12" x 12" Multi Color VFT Mastic	1,900	SF	1st Floor Corridor - 1926 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
66	Carpet Mastic (Red) NOT OBSERVED	600	SF	Room 105A - 1926 Bldg. - Not Observed	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
67	12" x 12" White w/ Beige Streaks VFT	600	SF	Room 105A - 1926 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
68	12" x 12" White w/ Beige Streaks VFT MASTIC	600	SF	Room 105A - 1926 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
69	White Terrazzo	1,200	SF	1st and 2nd Floor Corridors, Stairwells, Boy's and Girl's Restrooms - 1999 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
70	Blue Terrazzo	800	SF	2nd Floor Corridor, 2nd Floor Boy's and Girl's Restrooms - 1999 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
71	Maroon Terrazzo	800	SF	1st Floor Corridor; 1st & 2nd Floor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Lyon School Unit 24281 Building ID 4560

Address 2941 N. McVicker Avenue Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Boy's and Girl's Restrooms - 1999 Building										
C	Cardboard Pipe Insulation	1,600	LF	Boiler Room, Basement Corridor, Tunnel to Boiler Room, Air Tunnels, Pipe Chases, & Girl's Locker Room - 1926 Bldg.	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
D	MJP E/F/V on Cardboard Pipe Insulation	300	EA	Boiler Room, Basement Corridor, Tunnel to Boiler Room, Air Tunnels, Pipe Chases, & Girl's Locker Room - 1926 Bldg.	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
E	Aircell Pipe Insulation	1,600	LF	Boiler Room, Air Tunnels, & Unexcavated Areas - 1926 Bldg.	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
F	MJP E/F/V on Aircell Pipe Insulation	450	EA	Boiler Room, Air Tunnels, & Unexcavated Areas - 1926 Bldg.	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
G	Mag Block Pipe Insulation	2,500	LF	Engine Room, Boiler Room, Tunnel to Boiler Room & Air Tunnels - 1926 Bldg.	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
H	MJP E/F/V on Mag Block Pipe Insulation	75	EA	Engine Room, Boiler Room, & Air Tunnels - 1926 Bldg.	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
I	Aircell Duct Insulation	3,000	SF	Unexcavated Areas - 1926 Bldg.	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
J	Tank Insulation	256	SF	Boiler Room - 1926 Bldg.	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
K	Boiler Breeching	128	SF	Boiler Room - 1926 Bldg.	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
L	Boiler Mag	900	SF	Boiler Room - 1926 Bldg.	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
M	MJP E/F/V on Cardboard Pipe Insulation	50	EA	Air Tunnel, Crawlspace - 1936	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Lyon School Unit 24281 Building ID 4560

Address 2941 N. McVicker Avenue Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
N	Aircell Pipe Insulation	1,600	LF	Bldg. Air Tunnel, Crawlspace - 1936 Bldg.	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
O	MJP E/F/V on Aircell Pipe Insulation	150	EA	Air Tunnel, Crawlspace - 1936 Bldg.	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
Q	MJP E/F/V on Fiberglass Pipe Insulation	20	EA	Air Tunnel - 1936 Bldg.	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Lyon School Unit 24281 Building ID 4560

Address 2941 N. McVicker Avenue Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

Inspector's Comments are Summarized at the End of the Report

Reinspection Date 9/16/2019
Inspector Name Esteban Nunez
100-11255 5/15/2020
Inspector's IDPH License Number / Expiration Date

Inspector's Comments

HA Number:	Inspector Comments:
04	
05	
06	
07	
08	
09	
14	
15	
18	
19	
20	
21	
22	
23	
24	
25	
26	
27	
28	
29	
30	
31	
32	

Chicago Public Schools

School Lyon School Unit 24281 Building ID 4560

Address 2941 N. McVicker Avenue Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
33	
34	
35	
36	
37	
38	
39	
40	
41	
42	
43	
44	
45	
46	
47	
48	
49	
50	
50M	
51	
51M	
52	
53	
54	
55	
56	
57	Not Observed in Room 205
57M	
58	

Chicago Public Schools

School Lyon School Unit 24281 Building ID 4560

Address 2941 N. McVicker Avenue Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
58M	
59	
60	
61	
62	
63	
64	
65	
66	
67	
68	
69	
70	
71	
C	
D	
E	
F	
G	
H	
I	
J	
K	
L	
M	
N	
O	
Q	

Chicago Public Schools

School Lyon School Unit 24281 Building ID 4560

Address 2941 N. McVicker Avenue Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

Inspector's Comments are Summarized at the End of the Report

Table II

Management Planner's Review

Chicago Public Schools

School Lyon School
Address 2941 N. McVicker Avenue

Unit 24281
Chicago, IL, 60634

Building ID 4560
Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575

Fax:

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
04	12"x12" Sand & Brown Spotted VFT	1,900	SF	1st Floor Corridor - 1926 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
05	9"x9" Black w/ White Streaks VFT - NOT OBSERVED	1,900	SF	2nd Floor Corridor - 1926 Bldg. - Not Observed	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
06	12"x12" Sand & Brown Spotted VFT Mastic	1,900	SF	1st Floor Corridor - 1926 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
07	9"x9" Black w/ White Streaks VFT Mastic - NOT OBSERVED	1,200	SF	2nd Floor Corridor - 1926 Bldg. - Not Observed	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
08	9"x9" Black VFT - NOT OBSERVED	1,200	SF	2nd Floor Corridor - 1936 Bldg. - Not Observed	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
09	9"x9" Black VFT Mastic - NOT OBSERVED	1,200	SF	2nd Floor Corridor - 1936 Bldg. - Not Observed	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
14	12"x12" White VFT	900	SF	Room 205 (under carpet) - 1926 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
15	12"x12" White VFT Mastic	900	SF	Room 205 (under carpet) - 1926 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
18	12"x12" Sand & Brown Spotted VFT	750	SF	1st Floor Corridor - 1936 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
19	12"x12" Sand & Brown Spotted VFT Mastic	750	SF	1st Floor Corridor - 1936 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
20	12"x12" Off White VFT	750	SF	Room 104 - 1926 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
21	12"x12" Off White VFT Mastic	750	SF	Room 104 - 1926 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
22	9"x9" Beige VFT - NOT OBSERVED	600	SF	PTA Room & Room 104B & Toliet - 1926 Bldg. - Not Observed	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
23	9"x9" Beige VFT Mastic - NOT OBSERVED	600	SF	PTA Room & Room 104B & Toliet - 1926 Bldg. - 1926 Bldg. - Nor Observed	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
24	12"x12" Beige VFT	600	SF	Main Office - 1926 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
25	12"x12" Beige VFT Mastic	600	SF	Main Office - 1926 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
26	2'x4' White w/ Grooves Ceiling Tile			Throughout 1999 Building	No ACBM						
27	12"x12" Gray w/ Color Specs VFT	15,000	SF	Throughout 1999 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
28	12"x12" Gray w/ Color Specs VFT Mastic	15,000	SF	Throughout 1999 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
29	12"x12" Blue VFT	2,500	SF	Throughout 1999 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
30	12"x12" Blue VFT Mastic	2,500	SF	Throughout 1999 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
31	12"x12" Red VFT	2,500	SF	Throughout 1999 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
32	12"x12" Red VFT Mastic	2,500	SF	Throughout 1999 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
33	2'x4' Smooth White Ceiling Tile			Kitchen: Office, Toliet, Storage, Serving Area, & Corridor, 118B - 1999 Building	No ACBM						
34	Vinyl Baseboard			Throughout 1999 Building	No ACBM						
35	Vinyl Baseboard Mastic			Throughout 1999 Building	No ACBM						
36	Drywall			Throughout 1999 Building	No ACBM						

Chicago Public Schools

School Lyon School
Address 2941 N. McVicker Avenue

Unit 24281
Chicago, IL, 60634

Building ID 4560
Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575

Fax:

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
37	Drywall Compound			Throughout 1999 Building	No ACBM						
38	Carpet Mastic			Main Office Area, Library & Room 123, Room 121 Office - 1999 Building	No ACBM						
39	Cream Linoleum			Serving Area, Multipurpose Room - 1999 Building	No ACBM						
40	Cream Linoleum Mastic			Serving Area, Multipurpose Room - 1999 Building	No ACBM						
41	Blue Linoleum			Serving Area, Multipurpose Room - 1999 Building	No ACBM						
42	Blue Linoleum Mastic			Serving Area, Multipurpose Room - 1999 Building	No ACBM						
43	Hardcoat Plaster	56,000	SF	Throughout - 1926 Bldg.	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
44	Hardcoat Plaster	20,000	SF	Throughout - 1936 Bldg.	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
45	Grey Terrazzo	2,500	SF	108 Restroom, All Stairways, Corridor Border - 1926 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
46	Grey Terrazzo	1,200	SF	Stage Stairs, Stairway, Corridor Border, Room 211A - 1936 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
47	2' x 4' Fissured Ceiling Tile	20,000	SF	Throughout 2nd Floor - 1926 Bldg.	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
48	2' x 4' Fissured Ceiling Tile	5,000	SF	Throughout 2nd Floor - 1936 Bldg.	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
49	Brownish Grey Carpet Adhesive	110	SF	Principal's Office - 1926 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
50	9" x 9" Tan and White Specs VFT	1,000	SF	Room 105 - 1926 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
50M	9" x 9" Tan and White Specs VFT Mastic	1,000	SF	Room 105 - 1926 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
51	9" x 9" Tan and White Specs VFT	500	SF	Room 111A - 1926 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
51M	9" x 9" Tan and White Specs VFT Mastic	500	SF	Room 111A - 1926 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
52	2' x 4' Acoustical Ceiling Tile	2,000	SF	Gymnasium - 1926 Bldg.	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
53	Glue Dots Behind Chalk Board	1,700	SF	All Classrooms - 1926 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
54	Glue Dots Behind Chalk Board	300	SF	All Classrooms - 1936 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
55	White Ceramic Tile Grout	300	SF	Assembly Hall Washrooms - 1936 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
56	White Ceramic Tile Adhesive	300	SF	Assembly Hall Washrooms - 1936 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
57	12" x 12" Multi-Color VFT	1,900	SF	2nd Floor Hallway, Rooms 205, 104, and Principal's Office - 1926 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
57M	12" x 12" Multi-Color VFT Mastic	1,900	SF	2nd Floor Hallway, Rooms 205, 104,	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Lyon School
Address 2941 N. McVicker Avenue

Unit 24281
Chicago, IL, 60634

Building ID 4560
Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575

Fax:

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				and Principal's Office - 1926 Bldg.							
58	12" x 12" Multi-Color VFT	750	SF	1st Floor Hall - 1936 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
58M	12" x 12" Multi-Color VFT Mastic	750	SF	1st Floor Hall - 1936 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
59	White Ceramic Tile Grout	267	SF	Room 214A, Kindergarten Bathroom, 1st Floor Copy Room - 1926 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
60	White Ceramic Tile Adhesive	267	SF	Room 214A, Kindergarten Bathroom, 1st Floor Copy Room - 1926 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
61	Brown Ceramic Tile Grout	1,200	SF	1st and 2nd Floor Boys and Girls Restrooms - 1926 and 1936 Buildings	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
62	Brown Ceramic Tile Adhesive	1,200	SF	1st and 2nd Floor Boys and Girls Restrooms - 1936 Bldgs.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
63	Carpet Mastic (Gray)	1,200	SF	Room 205 and 205A - 1926 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
64	12" x 12" Multi Color VFT	1,900	SF	1st Floor Corridor - 1926 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
65	12" x 12" Multi Color VFT Mastic	1,900	SF	1st Floor Corridor - 1926 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
66	Carpet Mastic (Red) NOT OBSERVED	600	SF	Room 105A - 1926 Bldg. - Not Observed	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
67	12" x 12" White w/ Beige Streaks VFT	600	SF	Room 105A - 1926 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
68	12" x 12" White w/ Beige Streaks VFT MASTIC	600	SF	Room 105A - 1926 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
69	White Terrazzo	1,200	SF	1st and 2nd Floor Corridors, Stairwells, Boy's and Girl's Restrooms - 1999 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
70	Blue Terrazzo	800	SF	2nd Floor Corridor, 2nd Floor Boy's and Girl's Restrooms - 1999 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
71	Maroon Terrazzo	800	SF	1st Floor Corridor; 1st & 2nd Floor Boy's and Girl's Restrooms - 1999 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
C	Cardboard Pipe Insulation	1,600	LF	Boiler Room, Basement Corridor, Tunnel to Boiler Room, Air Tunnels, Pipe Chases, & Girl's Locker Room - 1926 Bldg.	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
D	MJP E/F/V on Cardboard Pipe Insulation	300	EA	Boiler Room, Basement Corridor, Tunnel to Boiler Room, Air Tunnels, Pipe Chases, & Girl's Locker Room - 1926 Bldg.	Chrysotile	TSI	Yes	0	EA	6 ACBM with the potential for damage	Follow O&M Plan
E	Aircell Pipe Insulation	1,600	LF	Boiler Room, Air Tunnels, &	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Lyon School
Address 2941 N. McVicker Avenue

Unit 24281
 Chicago, IL, 60634

Building ID 4560
Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575

Fax:

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				Unexcavated Areas - 1926 Bldg.							
F	MJP E/F/V on Aircell Pipe Insulation	450	EA	Boiler Room, Air Tunnels, & Unexcavated Areas - 1926 Bldg.	Chrysotile	TSI	Yes	0	EA	6 ACBM with the potential for damage	Follow O&M Plan
G	Mag Block Pipe Insulation	2,500	LF	Engine Room, Boiler Room, Tunnel to Boiler Room & Air Tunnels - 1926 Bldg.	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
H	MJP E/F/V on Mag Block Pipe Insulation	75	EA	Engine Room, Boiler Room, & Air Tunnels - 1926 Bldg.	Chrysotile	TSI	Yes	0	EA	6 ACBM with the potential for damage	Follow O&M Plan
I	Aircell Duct Insulation	3,000	SF	Unexcavated Areas - 1926 Bldg.	Chrysotile	TSI	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
J	Tank Insulation	256	SF	Boiler Room - 1926 Bldg.	Chrysotile	TSI	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
K	Boiler Breeching	128	SF	Boiler Room - 1926 Bldg.	Chrysotile	TSI	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
L	Boiler Mag	900	SF	Boiler Room - 1926 Bldg.	Chrysotile	TSI	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
M	MJP E/F/V on Cardboard Pipe Insulation	50	EA	Air Tunnel, Crawlspace - 1936 Bldg.	Chrysotile	TSI	Yes	0	EA	6 ACBM with the potential for damage	Follow O&M Plan
N	Aircell Pipe Insulation	1,600	LF	Air Tunnel, Crawlspace - 1936 Bldg.	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
O	MJP E/F/V on Aircell Pipe Insulation	150	EA	Air Tunnel, Crawlspace - 1936 Bldg.	Chrysotile	TSI	Yes	0	EA	6 ACBM with the potential for damage	Follow O&M Plan
Q	MJP E/F/V on Fiberglass Pipe Insulation	20	EA	Air Tunnel - 1936 Bldg.	Assumed	MISC	Yes	0	EA	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Lyon School
Address 2941 N. McVicker Avenue

Unit 24281
 Chicago, IL, 60634

Building ID 4560
Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.
 2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

Management Planner's Comments Summarized at the End of the Report

Review Date	10/11/2019
Manager Planner Name	Arturo Saenz
100-04019	5/15/2020
Manager IDPH License No/Expiration	

HA Number	Management Comments
04	
05	
06	
07	
08	
09	
14	
15	
18	
19	
20	
21	
22	
23	
24	
25	
26	
27	
28	
29	
30	

Chicago Public Schools

School Lyon School
Address 2941 N. McVicker Avenue

Unit 24281
Chicago, IL, 60634

Building ID 4560
Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.
2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
31	
32	
33	
34	
35	
36	
37	
38	
39	
40	
41	
42	
43	
44	
45	
46	
47	
48	
49	
50	
50M	
51	
51M	
52	
53	
54	

Chicago Public Schools

School Lyon School
Address 2941 N. McVicker Avenue

Unit 24281
 Chicago, IL, 60634

Building ID 4560
Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.
 2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
55	
56	
57	
57M	
58	
58M	
59	
60	
61	
62	
63	
64	
65	
66	
67	
68	
69	
70	
71	
C	
D	
E	
F	
G	
H	
I	

Chicago Public Schools

School Lyon School
Address 2941 N. McVicker Avenue

Unit 24281
Chicago, IL, 60634

Building ID 4560
Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.
2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
J	
K	
L	
M	
N	
O	
Q	

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUILDING ID: **4560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Lyon School** INSPECTION DATE: **9/16/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **04**
MATERIAL DESCRIPTION: **12"x12" Sand & Brown Spotted VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st Floor Corridor - 1926 Bldg.**

MATERIAL QUANTITY: **1900**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **09/16/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lyon School** REVIEW DATE: **10/11/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **04**
MATERIAL DESCRIPTION: **12"x12" Sand & Brown Spotted VFT**
MATERIAL LOCATION: **1st Floor Corridor - 1926 Bldg.**
MATERIAL QUANTITY: **1900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/11/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Lyon School** INSPECTION DATE: **9/16/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **05**
MATERIAL DESCRIPTION: **9"x9" Black w/ White Streaks VFT - NOT OBSERVED**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **2nd Floor Corridor - 1926 Bldg. - Not Observed**
MATERIAL QUANTITY: **1900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **09/16/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lyon School** REVIEW DATE: **10/11/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **05**
MATERIAL DESCRIPTION: **9"x9" Black w/ White Streaks VFT - NOT OBSERVED**
MATERIAL LOCATION: **2nd Floor Corridor - 1926 Bldg. - Not Observed**
MATERIAL QUANTITY: **1900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/11/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Lyon School** INSPECTION DATE: **9/16/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **06**
MATERIAL DESCRIPTION: **12"x12" Sand & Brown Spotted VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st Floor Corridor - 1926 Bldg.**
MATERIAL QUANTITY: **1900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 09/16/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lyon School** REVIEW DATE: **10/11/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **06**
MATERIAL DESCRIPTION: **12"x12" Sand & Brown Spotted VFT Mastic**
MATERIAL LOCATION: **1st Floor Corridor - 1926 Bldg.**
MATERIAL QUANTITY: **1900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/11/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Lyon School** INSPECTION DATE: **9/16/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **07**
MATERIAL DESCRIPTION: **9"x9" Black w/ White Streaks VFT Mastic - NOT OBSERVED**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **2nd Floor Corridor - 1926 Bldg. - Not Observed**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **09/16/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lyon School** REVIEW DATE: **10/11/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **07**
MATERIAL DESCRIPTION: **9"x9" Black w/ White Streaks VFT Mastic - NOT OBSERVED**
MATERIAL LOCATION: **2nd Floor Corridor - 1926 Bldg. - Not Observed**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/11/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Lyon School** INSPECTION DATE: **9/16/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **08**
MATERIAL DESCRIPTION: **9"x9" Black VFT - NOT OBSERVED**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **2nd Floor Corridor - 1936 Bldg. - Not Observed**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **09/16/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lyon School** REVIEW DATE: **10/11/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **08**
MATERIAL DESCRIPTION: **9"x9" Black VFT - NOT OBSERVED**
MATERIAL LOCATION: **2nd Floor Corridor - 1936 Bldg. - Not Observed**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/11/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Lyon School** INSPECTION DATE: **9/16/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **09**
MATERIAL DESCRIPTION: **9"x9" Black VFT Mastic - NOT OBSERVED**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **2nd Floor Corridor - 1936 Bldg. - Not Observed**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 09/16/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lyon School** REVIEW DATE: **10/11/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **09**
MATERIAL DESCRIPTION: **9"x9" Black VFT Mastic - NOT OBSERVED**
MATERIAL LOCATION: **2nd Floor Corridor - 1936 Bldg. - Not Observed**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/11/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Lyon School** INSPECTION DATE: **9/16/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14**
MATERIAL DESCRIPTION: **12"x12" White VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 205 (under carpet) - 1926 Bldg.**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 09/16/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lyon School** REVIEW DATE: **10/11/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **14**
MATERIAL DESCRIPTION: **12"x12" White VFT**
MATERIAL LOCATION: **Room 205 (under carpet) - 1926 Bldg.**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/11/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Lyon School** INSPECTION DATE: **9/16/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15**
MATERIAL DESCRIPTION: **12"x12" White VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 205 (under carpet) - 1926 Bldg.**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 09/16/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lyon School** REVIEW DATE: **10/11/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **15**
MATERIAL DESCRIPTION: **12"x12" White VFT Mastic**
MATERIAL LOCATION: **Room 205 (under carpet) - 1926 Bldg.**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/11/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Lyon School** INSPECTION DATE: **9/16/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18**
MATERIAL DESCRIPTION: **12"x12" Sand & Brown Spotted VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st Floor Corridor - 1936 Bldg.**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 09/16/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lyon School** REVIEW DATE: **10/11/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **18**
MATERIAL DESCRIPTION: **12"x12" Sand & Brown Spotted VFT**
MATERIAL LOCATION: **1st Floor Corridor - 1936 Bldg.**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/11/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Lyon School** INSPECTION DATE: **9/16/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19**
MATERIAL DESCRIPTION: **12"x12" Sand & Brown Spotted VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st Floor Corridor - 1936 Bldg.**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **09/16/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lyon School** REVIEW DATE: **10/11/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **19**
MATERIAL DESCRIPTION: **12"x12" Sand & Brown Spotted VFT Mastic**
MATERIAL LOCATION: **1st Floor Corridor - 1936 Bldg.**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/11/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Lyon School** INSPECTION DATE: **9/16/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**
MATERIAL DESCRIPTION: **12"x12" Off White VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 104 - 1926 Bldg.**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 09/16/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lyon School** REVIEW DATE: **10/11/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **20**
MATERIAL DESCRIPTION: **12"x12" Off White VFT**
MATERIAL LOCATION: **Room 104 - 1926 Bldg.**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/11/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Lyon School** INSPECTION DATE: **9/16/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21**
MATERIAL DESCRIPTION: **12"x12" Off White VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 104 - 1926 Bldg.**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **09/16/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lyon School** REVIEW DATE: **10/11/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **21**
MATERIAL DESCRIPTION: **12"x12" Off White VFT Mastic**
MATERIAL LOCATION: **Room 104 - 1926 Bldg.**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/11/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Lyon School** INSPECTION DATE: **9/16/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22**
MATERIAL DESCRIPTION: **9"x9" Beige VFT - NOT OBSERVED**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **PTA Room & Room 104B & Toliet - 1926 Bldg. - Not Observed**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 09/16/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lyon School** REVIEW DATE: **10/11/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **22**
MATERIAL DESCRIPTION: **9"x9" Beige VFT - NOT OBSERVED**
MATERIAL LOCATION: **PTA Room & Room 104B & Toliet - 1926 Bldg. - Not Observed**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/11/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Lyon School** INSPECTION DATE: **9/16/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23**
MATERIAL DESCRIPTION: **9"x9" Beige VFT Mastic - NOT OBSERVED**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **PTA Room & Room 104B & Toliet - 1926 Bldg. - 1926 Bldg. - Nor Observed**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 09/16/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lyon School** REVIEW DATE: **10/11/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **23**
MATERIAL DESCRIPTION: **9"x9" Beige VFT Mastic - NOT OBSERVED**
MATERIAL LOCATION: **PTA Room & Room 104B & Toliet - 1926 Bldg. - 1926 Bldg. - Nor Observed**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/11/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Lyon School** INSPECTION DATE: **9/16/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **24**
MATERIAL DESCRIPTION: **12"x12" Beige VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Main Office - 1926 Bldg.**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **09/16/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lyon School** REVIEW DATE: **10/11/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **24**
MATERIAL DESCRIPTION: **12"x12" Beige VFT**
MATERIAL LOCATION: **Main Office - 1926 Bldg.**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/11/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Lyon School** INSPECTION DATE: **9/16/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25**
MATERIAL DESCRIPTION: **12"x12" Beige VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Main Office - 1926 Bldg.**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **09/16/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lyon School** REVIEW DATE: **10/11/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **25**
MATERIAL DESCRIPTION: **12"x12" Beige VFT Mastic**
MATERIAL LOCATION: **Main Office - 1926 Bldg.**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/11/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Lyon School** INSPECTION DATE: **9/16/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26**
MATERIAL DESCRIPTION: **2'x4' White w/ Grooves Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout 1999 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____

Date: **09/16/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lyon School** REVIEW DATE: **10/11/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **26**

MATERIAL DESCRIPTION: **2'x4' White w/ Grooves Ceiling Tile**

MATERIAL LOCATION: **Throughout 1999 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/11/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Lyon School** INSPECTION DATE: **9/16/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27**
MATERIAL DESCRIPTION: **12"x12" Gray w/ Color Specs VFT**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout 1999 Building**
MATERIAL QUANTITY: **15000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **09/16/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lyon School** REVIEW DATE: **10/11/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **27**
MATERIAL DESCRIPTION: **12"x12" Gray w/ Color Specs VFT**
MATERIAL LOCATION: **Throughout 1999 Building**
MATERIAL QUANTITY: **15000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/11/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Lyon School** INSPECTION DATE: **9/16/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28**
MATERIAL DESCRIPTION: **12"x12" Gray w/ Color Specs VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout 1999 Building**
MATERIAL QUANTITY: **15000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **09/16/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lyon School** REVIEW DATE: **10/11/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **28**
MATERIAL DESCRIPTION: **12"x12" Gray w/ Color Specs VFT Mastic**
MATERIAL LOCATION: **Throughout 1999 Building**
MATERIAL QUANTITY: **15000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/11/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Lyon School** INSPECTION DATE: **9/16/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **29**
MATERIAL DESCRIPTION: **12"x12" Blue VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout 1999 Building**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **09/16/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lyon School** REVIEW DATE: **10/11/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **29**
MATERIAL DESCRIPTION: **12"x12" Blue VFT**
MATERIAL LOCATION: **Throughout 1999 Building**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/11/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Lyon School** INSPECTION DATE: **9/16/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **30**
MATERIAL DESCRIPTION: **12"x12" Blue VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout 1999 Building**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **09/16/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lyon School** REVIEW DATE: **10/11/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **30**
MATERIAL DESCRIPTION: **12"x12" Blue VFT Mastic**
MATERIAL LOCATION: **Throughout 1999 Building**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/11/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Lyon School** INSPECTION DATE: **9/16/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **31**
MATERIAL DESCRIPTION: **12"x12" Red VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout 1999 Building**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 09/16/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lyon School** REVIEW DATE: **10/11/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **31**
MATERIAL DESCRIPTION: **12"x12" Red VFT**
MATERIAL LOCATION: **Throughout 1999 Building**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/11/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Lyon School** INSPECTION DATE: **9/16/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **32**
MATERIAL DESCRIPTION: **12"x12" Red VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout 1999 Building**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **09/16/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lyon School** REVIEW DATE: **10/11/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **32**
MATERIAL DESCRIPTION: **12"x12" Red VFT Mastic**
MATERIAL LOCATION: **Throughout 1999 Building**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/11/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Lyon School** INSPECTION DATE: **9/16/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **33**
MATERIAL DESCRIPTION: **2'x4' Smooth White Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Kitchen: Office, Toliet, Storage, Serving Area, & Corridor, 118B - 1999 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **09/16/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lyon School** REVIEW DATE: **10/11/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **33**
MATERIAL DESCRIPTION: **2'x4' Smooth White Ceiling Tile**
MATERIAL LOCATION: **Kitchen: Office, Toliet, Storage, Serving Area, & Corridor, 118B - 1999 Building**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/11/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Lyon School** INSPECTION DATE: **9/16/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **34**
MATERIAL DESCRIPTION: **Vinyl Baseboard**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout 1999 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **09/16/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lyon School** REVIEW DATE: **10/11/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **34**

MATERIAL DESCRIPTION: **Vinyl Baseboard**

MATERIAL LOCATION: **Throughout 1999 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/11/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUILDING ID: **4560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Lyon School** INSPECTION DATE: **9/16/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **35**
MATERIAL DESCRIPTION: **Vinyl Baseboard Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout 1999 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____

Date: 09/16/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lyon School** REVIEW DATE: **10/11/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **35**

MATERIAL DESCRIPTION: **Vinyl Baseboard Mastic**

MATERIAL LOCATION: **Throughout 1999 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/11/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUILDING ID: **4560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Lyon School** INSPECTION DATE: **9/16/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **36**
MATERIAL DESCRIPTION: **Drywall**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout 1999 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **09/16/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lyon School** REVIEW DATE: **10/11/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **36**
MATERIAL DESCRIPTION: **Drywall**
MATERIAL LOCATION: **Throughout 1999 Building**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/11/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUILDING ID: **4560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Lyon School** INSPECTION DATE: **9/16/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37**
MATERIAL DESCRIPTION: **Drywall Compound**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout 1999 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **09/16/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lyon School** REVIEW DATE: **10/11/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **37**
MATERIAL DESCRIPTION: **Drywall Compound**
MATERIAL LOCATION: **Throughout 1999 Building**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/11/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUILDING ID: **4560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Lyon School** INSPECTION DATE: **9/16/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **38**
MATERIAL DESCRIPTION: **Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Main Office Area, Library & Room 123, Room 121 Office - 1999 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **09/16/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lyon School** REVIEW DATE: **10/11/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **38**
MATERIAL DESCRIPTION: **Carpet Mastic**
MATERIAL LOCATION: **Main Office Area, Library & Room 123, Room 121 Office - 1999 Building**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/11/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Lyon School** INSPECTION DATE: **9/16/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **39**
MATERIAL DESCRIPTION: **Cream Linoleum**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Serving Area, Multipurpose Room - 1999 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **09/16/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lyon School** REVIEW DATE: **10/11/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **39**

MATERIAL DESCRIPTION: **Cream Linoleum**

MATERIAL LOCATION: **Serving Area, Multipurpose Room - 1999 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/11/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Lyon School** INSPECTION DATE: **9/16/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **40**
MATERIAL DESCRIPTION: **Cream Linoleum Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Serving Area, Multipurpose Room - 1999 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **09/16/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lyon School** REVIEW DATE: **10/11/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **40**

MATERIAL DESCRIPTION: **Cream Linoleum Mastic**

MATERIAL LOCATION: **Serving Area, Multipurpose Room - 1999 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/11/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Lyon School** INSPECTION DATE: **9/16/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **41**
MATERIAL DESCRIPTION: **Blue Linoleum**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Serving Area, Multipurpose Room - 1999 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **09/16/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lyon School** REVIEW DATE: **10/11/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **41**

MATERIAL DESCRIPTION: **Blue Linoleum**

MATERIAL LOCATION: **Serving Area, Multipurpose Room - 1999 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/11/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Lyon School** INSPECTION DATE: **9/16/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **42**
MATERIAL DESCRIPTION: **Blue Linoleum Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Serving Area, Multipurpose Room - 1999 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **09/16/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lyon School** REVIEW DATE: **10/11/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **42**
MATERIAL DESCRIPTION: **Blue Linoleum Mastic**
MATERIAL LOCATION: **Serving Area, Multipurpose Room - 1999 Building**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/11/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Lyon School** INSPECTION DATE: **9/16/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **43**
MATERIAL DESCRIPTION: **Hardcoat Plaster**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout - 1926 Bldg.**
MATERIAL QUANTITY: **56000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **09/16/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lyon School** REVIEW DATE: **10/11/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **43**
MATERIAL DESCRIPTION: **Hardcoat Plaster**
MATERIAL LOCATION: **Throughout - 1926 Bldg.**
MATERIAL QUANTITY: **56000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/11/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Lyon School** INSPECTION DATE: **9/16/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **44**
MATERIAL DESCRIPTION: **Hardcoat Plaster**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout - 1936 Bldg.**
MATERIAL QUANTITY: **20000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **09/16/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lyon School** REVIEW DATE: **10/11/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **44**
MATERIAL DESCRIPTION: **Hardcoat Plaster**
MATERIAL LOCATION: **Throughout - 1936 Bldg.**
MATERIAL QUANTITY: **20000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/11/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Lyon School** INSPECTION DATE: **9/16/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **45**
MATERIAL DESCRIPTION: **Grey Terrazzo**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **108 Restroom, All Stairways, Corridor Border - 1926 Bldg.**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 09/16/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lyon School** REVIEW DATE: **10/11/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **45**
MATERIAL DESCRIPTION: **Grey Terrazzo**
MATERIAL LOCATION: **108 Restroom, All Stairways, Corridor Border - 1926 Bldg.**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/11/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Lyon School** INSPECTION DATE: **9/16/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **46**
MATERIAL DESCRIPTION: **Grey Terrazzo**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Stage Stairs, Stairway, Corridor Border, Room 211A - 1936 Bldg.**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **09/16/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lyon School** REVIEW DATE: **10/11/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **46**
MATERIAL DESCRIPTION: **Grey Terrazzo**
MATERIAL LOCATION: **Stage Stairs, Stairway, Corridor Border, Room 211A - 1936 Bldg.**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/11/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Lyon School** INSPECTION DATE: **9/16/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **47**
MATERIAL DESCRIPTION: **2' x 4' Fissured Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout 2nd Floor - 1926 Bldg.**
MATERIAL QUANTITY: **20000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **09/16/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lyon School** REVIEW DATE: **10/11/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **47**
MATERIAL DESCRIPTION: **2' x 4' Fissured Ceiling Tile**
MATERIAL LOCATION: **Throughout 2nd Floor - 1926 Bldg.**
MATERIAL QUANTITY: **20000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/11/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Lyon School** INSPECTION DATE: **9/16/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **48**
MATERIAL DESCRIPTION: **2' x 4' Fissured Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout 2nd Floor - 1936 Bldg.**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 09/16/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lyon School** REVIEW DATE: **10/11/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **48**
MATERIAL DESCRIPTION: **2' x 4' Fissured Ceiling Tile**
MATERIAL LOCATION: **Throughout 2nd Floor - 1936 Bldg.**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/11/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Lyon School** INSPECTION DATE: **9/16/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **49**
MATERIAL DESCRIPTION: **Brownish Grey Carpet Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Principal's Office - 1926 Bldg.**
MATERIAL QUANTITY: **110** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **09/16/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lyon School** REVIEW DATE: **10/11/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **49**
MATERIAL DESCRIPTION: **Brownish Grey Carpet Adhesive**
MATERIAL LOCATION: **Principal's Office - 1926 Bldg.**
MATERIAL QUANTITY: **110** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/11/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Lyon School** INSPECTION DATE: **9/16/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **50**
MATERIAL DESCRIPTION: **9" x 9" Tan and White Specs VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 105 - 1926 Bldg.**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **09/16/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lyon School** REVIEW DATE: **10/11/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **50**
MATERIAL DESCRIPTION: **9" x 9" Tan and White Specs VFT**
MATERIAL LOCATION: **Room 105 - 1926 Bldg.**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/11/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Lyon School** INSPECTION DATE: **9/16/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **50M**
MATERIAL DESCRIPTION: **9" x 9" Tan and White Specs VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 105 - 1926 Bldg.**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 09/16/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lyon School** REVIEW DATE: **10/11/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **50M**
MATERIAL DESCRIPTION: **9" x 9" Tan and White Specs VFT Mastic**
MATERIAL LOCATION: **Room 105 - 1926 Bldg.**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/11/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Lyon School** INSPECTION DATE: **9/16/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **51**
MATERIAL DESCRIPTION: **9" x 9" Tan and White Specs VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 111A - 1926 Bldg.**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 09/16/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lyon School** REVIEW DATE: **10/11/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **51**
MATERIAL DESCRIPTION: **9" x 9" Tan and White Specs VFT**
MATERIAL LOCATION: **Room 111A - 1926 Bldg.**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/11/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Lyon School** INSPECTION DATE: **9/16/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **51M**
MATERIAL DESCRIPTION: **9" x 9" Tan and White Specs VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 111A - 1926 Bldg.**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **09/16/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lyon School** REVIEW DATE: **10/11/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **51M**
MATERIAL DESCRIPTION: **9" x 9" Tan and White Specs VFT Mastic**
MATERIAL LOCATION: **Room 111A - 1926 Bldg.**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/11/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Lyon School** INSPECTION DATE: **9/16/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **52**
MATERIAL DESCRIPTION: **2' x 4' Acoustical Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Gymnasium - 1926 Bldg.**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **09/16/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lyon School** REVIEW DATE: **10/11/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **52**
MATERIAL DESCRIPTION: **2' x 4' Acoustical Ceiling Tile**
MATERIAL LOCATION: **Gymnasium - 1926 Bldg.**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/11/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Lyon School** INSPECTION DATE: **9/16/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **53**
MATERIAL DESCRIPTION: **Glue Dots Behind Chalk Board**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **All Classrooms - 1926 Bldg.**
MATERIAL QUANTITY: **1700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **09/16/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lyon School** REVIEW DATE: **10/11/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **53**
MATERIAL DESCRIPTION: **Glue Dots Behind Chalk Board**
MATERIAL LOCATION: **All Classrooms - 1926 Bldg.**
MATERIAL QUANTITY: **1700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/11/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Lyon School** INSPECTION DATE: **9/16/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **54**
MATERIAL DESCRIPTION: **Glue Dots Behind Chalk Board**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **All Classrooms - 1936 Building**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 09/16/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lyon School** REVIEW DATE: **10/11/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **54**
MATERIAL DESCRIPTION: **Glue Dots Behind Chalk Board**
MATERIAL LOCATION: **All Classrooms - 1936 Building**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/11/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Lyon School** INSPECTION DATE: **9/16/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **55**
MATERIAL DESCRIPTION: **White Ceramic Tile Grout**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Assembly Hall Washrooms - 1936 Building**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 09/16/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lyon School** REVIEW DATE: **10/11/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **55**
MATERIAL DESCRIPTION: **White Ceramic Tile Grout**
MATERIAL LOCATION: **Assembly Hall Washrooms - 1936 Building**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/11/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Lyon School** INSPECTION DATE: **9/16/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **56**
MATERIAL DESCRIPTION: **White Ceramic Tile Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Assembly Hall Washrooms - 1936 Building**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 09/16/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lyon School** REVIEW DATE: **10/11/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **56**
MATERIAL DESCRIPTION: **White Ceramic Tile Adhesive**
MATERIAL LOCATION: **Assembly Hall Washrooms - 1936 Building**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/11/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Lyon School** INSPECTION DATE: **9/16/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **57**
MATERIAL DESCRIPTION: **12" x 12" Multi-Color VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **2nd Floor Hallway, Rooms 205, 104, and Principal's Office - 1926 Bldg.**
MATERIAL QUANTITY: **1900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS: **Not Observed in Room 205**

Inspector's Signature: _____ Date: **09/16/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lyon School** REVIEW DATE: **10/11/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **57**
MATERIAL DESCRIPTION: **12" x 12" Multi-Color VFT**
MATERIAL LOCATION: **2nd Floor Hallway, Rooms 205, 104, and Principal's Office - 1926 Bldg.**
MATERIAL QUANTITY: **1900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/11/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Lyon School** INSPECTION DATE: **9/16/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **57M**
MATERIAL DESCRIPTION: **12" x 12" Multi-Color VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **2nd Floor Hallway, Rooms 205, 104, and Principal's Office - 1926 Bldg.**
MATERIAL QUANTITY: **1900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **09/16/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lyon School** REVIEW DATE: **10/11/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **57M**
MATERIAL DESCRIPTION: **12" x 12" Multi-Color VFT Mastic**
MATERIAL LOCATION: **2nd Floor Hallway, Rooms 205, 104, and Principal's Office - 1926 Bldg.**
MATERIAL QUANTITY: **1900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/11/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Lyon School** INSPECTION DATE: **9/16/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **58**
MATERIAL DESCRIPTION: **12" x 12" Multi-Color VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st Floor Hall - 1936 Bldg.**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **09/16/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lyon School** REVIEW DATE: **10/11/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **58**
MATERIAL DESCRIPTION: **12" x 12" Multi-Color VFT**
MATERIAL LOCATION: **1st Floor Hall - 1936 Bldg.**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/11/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Lyon School** INSPECTION DATE: **9/16/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **58M**
MATERIAL DESCRIPTION: **12" x 12" Multi-Color VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st Floor Hall - 1936 Bldg.**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **09/16/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lyon School** REVIEW DATE: **10/11/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **58M**
MATERIAL DESCRIPTION: **12" x 12" Multi-Color VFT Mastic**
MATERIAL LOCATION: **1st Floor Hall - 1936 Bldg.**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/11/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Lyon School** INSPECTION DATE: **9/16/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **59**
MATERIAL DESCRIPTION: **White Ceramic Tile Grout**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 214A, Kindergarten Bathroom, 1st Floor Copy Room - 1926 Bldg.**
MATERIAL QUANTITY: **267** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 09/16/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lyon School** REVIEW DATE: **10/11/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **59**
MATERIAL DESCRIPTION: **White Ceramic Tile Grout**
MATERIAL LOCATION: **Room 214A, Kindergarten Bathroom, 1st Floor Copy Room - 1926 Bldg.**
MATERIAL QUANTITY: **267** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/11/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Lyon School** INSPECTION DATE: **9/16/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **60**
MATERIAL DESCRIPTION: **White Ceramic Tile Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 214A, Kindergarten Bathroom, 1st Floor Copy Room - 1926 Bldg.**
MATERIAL QUANTITY: **267** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **09/16/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lyon School** REVIEW DATE: **10/11/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **60**
MATERIAL DESCRIPTION: **White Ceramic Tile Adhesive**
MATERIAL LOCATION: **Room 214A, Kindergarten Bathroom, 1st Floor Copy Room - 1926 Bldg.**
MATERIAL QUANTITY: **267** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/11/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Lyon School** INSPECTION DATE: **9/16/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **61**
MATERIAL DESCRIPTION: **Brown Ceramic Tile Grout**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st and 2nd Floor Boys and Girls Restrooms - 1926 and 1936 Buildings**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **09/16/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lyon School** REVIEW DATE: **10/11/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **61**
MATERIAL DESCRIPTION: **Brown Ceramic Tile Grout**
MATERIAL LOCATION: **1st and 2nd Floor Boys and Girls Restrooms - 1926 and 1936 Buildings**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/11/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Lyon School** INSPECTION DATE: **9/16/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **62**
MATERIAL DESCRIPTION: **Brown Ceramic Tile Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st and 2nd Floor Boys and Girls Restrooms - 1936 Bldgs.**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 09/16/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lyon School** REVIEW DATE: **10/11/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **62**
MATERIAL DESCRIPTION: **Brown Ceramic Tile Adhesive**
MATERIAL LOCATION: **1st and 2nd Floor Boys and Girls Restrooms - 1936 Bldgs.**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/11/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Lyon School** INSPECTION DATE: **9/16/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **63**
MATERIAL DESCRIPTION: **Carpet Mastic (Gray)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 205 and 205A - 1926 Bldg.**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **09/16/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lyon School** REVIEW DATE: **10/11/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **63**
MATERIAL DESCRIPTION: **Carpet Mastic (Gray)**
MATERIAL LOCATION: **Room 205 and 205A - 1926 Bldg.**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/11/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Lyon School** INSPECTION DATE: **9/16/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **64**
MATERIAL DESCRIPTION: **12" x 12" Multi Color VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st Floor Corridor - 1926 Bldg.**
MATERIAL QUANTITY: **1900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **09/16/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lyon School** REVIEW DATE: **10/11/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **64**
MATERIAL DESCRIPTION: **12" x 12" Multi Color VFT**
MATERIAL LOCATION: **1st Floor Corridor - 1926 Bldg.**
MATERIAL QUANTITY: **1900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/11/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Lyon School** INSPECTION DATE: **9/16/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **65**
MATERIAL DESCRIPTION: **12" x 12" Multi Color VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st Floor Corridor - 1926 Bldg.**
MATERIAL QUANTITY: **1900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 09/16/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lyon School** REVIEW DATE: **10/11/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **65**
MATERIAL DESCRIPTION: **12" x 12" Multi Color VFT Mastic**
MATERIAL LOCATION: **1st Floor Corridor - 1926 Bldg.**
MATERIAL QUANTITY: **1900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/11/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Lyon School** INSPECTION DATE: **9/16/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **66**
MATERIAL DESCRIPTION: **Carpet Mastic (Red) NOT OBSERVED**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 105A - 1926 Bldg. - Not Observed**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **09/16/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lyon School** REVIEW DATE: **10/11/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **66**
MATERIAL DESCRIPTION: **Carpet Mastic (Red) NOT OBSERVED**
MATERIAL LOCATION: **Room 105A - 1926 Bldg. - Not Observed**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/11/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Lyon School** INSPECTION DATE: **9/16/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **67**
MATERIAL DESCRIPTION: **12" x 12" White w/ Beige Streaks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 105A - 1926 Bldg.**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 09/16/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lyon School** REVIEW DATE: **10/11/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **67**
MATERIAL DESCRIPTION: **12" x 12" White w/ Beige Streaks VFT**
MATERIAL LOCATION: **Room 105A - 1926 Bldg.**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/11/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Lyon School** INSPECTION DATE: **9/16/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **68**
MATERIAL DESCRIPTION: **12" x 12" White w/ Beige Streaks VFT MASTIC**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 105A - 1926 Bldg.**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 09/16/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lyon School** REVIEW DATE: **10/11/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **68**
MATERIAL DESCRIPTION: **12" x 12" White w/ Beige Streaks VFT MASTIC**
MATERIAL LOCATION: **Room 105A - 1926 Bldg.**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/11/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Lyon School** INSPECTION DATE: **9/16/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **C**
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Boiler Room, Basement Corridor, Tunnel to Boiler Room, Air Tunnels, Pipe Chases, & Girl's Locker Room - 1926 Bldg.**

MATERIAL QUANTITY: **1600**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____

Date: 09/16/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUILDING ID: **4560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lyon School** REVIEW DATE: **10/11/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **C**
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**
MATERIAL LOCATION: **Boiler Room, Basement Corridor, Tunnel to Boiler Room, Air Tunnels, Pipe Chases, & Girl's Locker Room - 1926 Bldg.**
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/11/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Lyon School** INSPECTION DATE: **9/16/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **D**
MATERIAL DESCRIPTION: **MJP E/F/V on Cardboard Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Boiler Room, Basement Corridor, Tunnel to Boiler Room, Air Tunnels, Pipe Chases, & Girl's Locker Room - 1926 Bldg.**

MATERIAL QUANTITY: **300** MATERIAL UNITS: **EA**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

COMMENTS:

Inspector's Signature: _____ Date: 09/16/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lyon School** REVIEW DATE: **10/11/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **D**
MATERIAL DESCRIPTION: **MJP E/F/V on Cardboard Pipe Insulation**
MATERIAL LOCATION: **Boiler Room, Basement Corridor, Tunnel to Boiler Room, Air Tunnels, Pipe Chases, & Girl's Locker Room - 1926 Bldg.**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **EA**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/11/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Lyon School** INSPECTION DATE: **9/16/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **E**
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Boiler Room, Air Tunnels, & Unexcavated Areas - 1926 Bldg.**
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: **09/16/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lyon School** REVIEW DATE: **10/11/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **E**
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**
MATERIAL LOCATION: **Boiler Room, Air Tunnels, & Unexcavated Areas - 1926 Bldg.**
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/11/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Lyon School** INSPECTION DATE: **9/16/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **F**
MATERIAL DESCRIPTION: **MJP E/F/V on Aircell Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Boiler Room, Air Tunnels, & Unexcavated Areas - 1926 Bldg.**
MATERIAL QUANTITY: **450** MATERIAL UNITS: **EA**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

COMMENTS:

Inspector's Signature: _____ Date: 09/16/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lyon School** REVIEW DATE: **10/11/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **F**
MATERIAL DESCRIPTION: **MJP E/F/V on Aircell Pipe Insulation**
MATERIAL LOCATION: **Boiler Room, Air Tunnels, & Unexcavated Areas - 1926 Bldg.**
MATERIAL QUANTITY: **450** MATERIAL UNITS: **EA**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/11/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Lyon School** INSPECTION DATE: **9/16/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **G**
MATERIAL DESCRIPTION: **Mag Block Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Engine Room, Boiler Room, Tunnel to Boiler Room & Air Tunnels - 1926 Bldg.**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 09/16/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lyon School** REVIEW DATE: **10/11/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **G**
MATERIAL DESCRIPTION: **Mag Block Pipe Insulation**
MATERIAL LOCATION: **Engine Room, Boiler Room, Tunnel to Boiler Room & Air Tunnels - 1926 Bldg.**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/11/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Lyon School** INSPECTION DATE: **9/16/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **H**
MATERIAL DESCRIPTION: **MJP E/F/V on Mag Block Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Engine Room, Boiler Room, & Air Tunnels - 1926 Bldg.**
MATERIAL QUANTITY: **75** MATERIAL UNITS: **EA**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

COMMENTS:

Inspector's Signature: _____ Date: **09/16/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lyon School** REVIEW DATE: **10/11/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **H**
MATERIAL DESCRIPTION: **MJP E/F/V on Mag Block Pipe Insulation**
MATERIAL LOCATION: **Engine Room, Boiler Room, & Air Tunnels - 1926 Bldg.**
MATERIAL QUANTITY: **75** MATERIAL UNITS: **EA**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/11/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Lyon School** INSPECTION DATE: **9/16/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **I**
MATERIAL DESCRIPTION: **Aircell Duct Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Unexcavated Areas - 1926 Bldg.**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **09/16/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lyon School** REVIEW DATE: **10/11/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **I**
MATERIAL DESCRIPTION: **Aircell Duct Insulation**
MATERIAL LOCATION: **Unexcavated Areas - 1926 Bldg.**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/11/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Lyon School** INSPECTION DATE: **9/16/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **J**
MATERIAL DESCRIPTION: **Tank Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Boiler Room - 1926 Bldg.**
MATERIAL QUANTITY: **256** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **09/16/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lyon School** REVIEW DATE: **10/11/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **J**
MATERIAL DESCRIPTION: **Tank Insulation**
MATERIAL LOCATION: **Boiler Room - 1926 Bldg.**
MATERIAL QUANTITY: **256** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/11/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Lyon School** INSPECTION DATE: **9/16/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **K**
MATERIAL DESCRIPTION: **Boiler Breeching**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Boiler Room - 1926 Bldg.**
MATERIAL QUANTITY: **128** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 09/16/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lyon School** REVIEW DATE: **10/11/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **K**
MATERIAL DESCRIPTION: **Boiler Breeching**
MATERIAL LOCATION: **Boiler Room - 1926 Bldg.**
MATERIAL QUANTITY: **128** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/11/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Lyon School** INSPECTION DATE: **9/16/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **L**
MATERIAL DESCRIPTION: **Boiler Mag**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Boiler Room - 1926 Bldg.**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 09/16/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lyon School** REVIEW DATE: **10/11/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **L**
MATERIAL DESCRIPTION: **Boiler Mag**
MATERIAL LOCATION: **Boiler Room - 1926 Bldg.**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/11/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Lyon School** INSPECTION DATE: **9/16/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **M**
MATERIAL DESCRIPTION: **MJP E/F/V on Cardboard Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Air Tunnel, Crawlspace - 1936 Bldg.**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **EA**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

COMMENTS:

Inspector's Signature: _____ Date: **09/16/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lyon School** REVIEW DATE: **10/11/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **M**
MATERIAL DESCRIPTION: **MJP E/F/V on Cardboard Pipe Insulation**
MATERIAL LOCATION: **Air Tunnel, Crawlspace - 1936 Bldg.**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **EA**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/11/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Lyon School** INSPECTION DATE: **9/16/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **N**
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Air Tunnel, Crawlspace - 1936 Bldg.**
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: **09/16/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lyon School** REVIEW DATE: **10/11/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **N**
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**
MATERIAL LOCATION: **Air Tunnel, Crawlspace - 1936 Bldg.**
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/11/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Lyon School** INSPECTION DATE: **9/16/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **0**
MATERIAL DESCRIPTION: **MJP E/F/V on Aircell Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Air Tunnel, Crawlspace - 1936 Bldg.**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **EA**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

COMMENTS:

Inspector's Signature: _____ Date: 09/16/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lyon School** REVIEW DATE: **10/11/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **0**
MATERIAL DESCRIPTION: **MJP E/F/V on Aircell Pipe Insulation**
MATERIAL LOCATION: **Air Tunnel, Crawlspace - 1936 Bldg.**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **EA**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/11/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Lyon School** INSPECTION DATE: **9/16/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **Q**
MATERIAL DESCRIPTION: **MJP E/F/V on Fiberglass Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Air Tunnel - 1936 Bldg.**
MATERIAL QUANTITY: **20** MATERIAL UNITS: **EA**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

COMMENTS:

Inspector's Signature: _____ Date: **09/16/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUIDLING ID: **4560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lyon School** REVIEW DATE: **10/11/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **Q**
MATERIAL DESCRIPTION: **MJP E/F/V on Fiberglass Pipe Insulation**
MATERIAL LOCATION: **Air Tunnel - 1936 Bldg.**
MATERIAL QUANTITY: **20** MATERIAL UNITS: **EA**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/11/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUILDING ID: **4560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Lyon School** INSPECTION DATE: **9/16/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **69**
MATERIAL DESCRIPTION: **White Terrazzo**
MATERIAL LOCATION: **1st and 2nd Floor Corridors, Stairwells, Boy's and Girl's Restrooms - 1999 Building**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE:
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 09/16/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUILDING ID: **4560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lyon School** REVIEW DATE: **10/11/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **69**
MATERIAL DESCRIPTION: **White Terrazzo**
MATERIAL LOCATION: **1st and 2nd Floor Corridors, Stairwells, Boy's and Girl's Restrooms - 1999 Building**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **10/11/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUILDING ID: **4560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Lyon School** INSPECTION DATE: **9/16/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **70**
MATERIAL DESCRIPTION: **Blue Terrazzo**
MATERIAL LOCATION: **2nd Floor Corridor, 2nd Floor Boy's and Girl's Restrooms - 1999 Building**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE:
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 09/16/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUILDING ID: **4560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lyon School** REVIEW DATE: **10/11/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **70**
MATERIAL DESCRIPTION: **Blue Terrazzo**
MATERIAL LOCATION: **2nd Floor Corridor, 2nd Floor Boy's and Girl's Restrooms - 1999 Building**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **10/11/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUILDING ID: **4560**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Lyon School** INSPECTION DATE: **9/16/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **71**
MATERIAL DESCRIPTION: **Maroon Terrazzo**
MATERIAL LOCATION: **1st Floor Corridor; 1st & 2nd Floor Boy's and Girl's Restrooms - 1999 Building**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE:
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 09/16/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24281** BUILDING ID: **4560**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**
SCHOOL NAME: **Lyon School** REVIEW DATE: **10/11/2019**
ADDRESS: **2941 N. McVicker Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **71**
MATERIAL DESCRIPTION: **Maroon Terrazzo**
MATERIAL LOCATION: **1st Floor Corridor; 1st & 2nd Floor Boy's and Girl's Restrooms - 1999 Building**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **10/11/2019**

APPENDIX B

Inspector and Management Planner Licenses

CERTIFICATE OF ACHIEVEMENT ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that ESTEBAN NUNEZ
has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the
examination on 02/09/2019 with a minimum score of 70% or better. Training was in accordance
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:
Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.

02/09/2019

Course Dates:

02/09/2020

Expires:

1902BIR20

Certificate Number:



Office: 312-491-0081
Fax: 312-421-2901

Director of Training
Nicholas J. Peneff
Doctor of Public Health

Phone: 312-491-0081

FORM # A-010B



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • www.dph.illinois.gov

ESTEBAN NUNEZ
2942 W VAN BUREN ST
CHICAGO, IL 60612

4/19/2019

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 11255

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

FRONT OF LICENSE			BACK OF LICENSE	
	ASBESTOS PROFESSIONAL LICENSE		ENDORSEMENTS	TC EXPIRES
ID NUMBER 100 - 11255	ISSUED 4/19/2019	EXPIRES 05/15/2020	INSPECTOR	2/9/2020
ESTEBAN NUNEZ 2942 W VAN BUREN ST CHICAGO, IL 60612 Environmental Health			PROJECT MANAGER AIR SAMPLING PROFESSIONAL	9/15/2019
			Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH, IMPROVING LIVES
Nationally Accredited by PHAB

2019



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900 ♦ www.otssafety.com

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Arturo Saenz

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 2/28/2019

Exam Date: 2/28/2019

Expiration Date: 2/28/2020

Certificate Number: MPR1902280693

Kathy DeSalvo, Director



**ASBESTOS
PROFESSIONAL
LICENSE**

ID NUMBER	ISSUED	EXPIRES
100 - 04019	4/30/2019	05/15/2020

ARTURO SAENZ
2942 W VAN BUREN ST
CHICAGO, IL 60612
Environmental Health



ENDORSEMENTS	TC EXPIRES
---------------------	-------------------

INSPECTOR	2/28/2020
MANAGEMENT PLANNER	2/28/2020

AIR SAMPLING PROFESSIONAL

Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois
Department of Public Health
This license is valid only when accompanied by a valid
training course certificate.

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL		
	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE		
	Loc	Localized
	Dist	Distributed