

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM**

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-2334
SCHOOL NAME: Mason School
ADDRESS OF SCHOOL: 4217 W. 18th St.
CITY: Chicago, IL, 60623

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED 2/25/2016

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II *(Please type or print)*

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 10/1/2019 ENROLLMENT 315
IDPH INSPECTOR LICENSE NUMBER: 100-09969
IDPH LICENSED INSPECTOR NAME(Please Print): Dionne Carey
IDPH MP LICENSE NUMBER: 100-19466
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Evan Christian

DESIGNATED PERSON (Please Print): Robert Christlieb PHONE: (773) 553-3197



10/1/2019

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Mason School

4217 W. 18th St.
Chicago, IL, 60623

Unit: 24381
Building ID: 4650

IDPH ID Number: 14-016-2990-2334

REPORT DATE:

Tuesday, October 01, 2019

Prepared for:

**Chicago Public Schools
42 West Madison Street
Chicago, IL 60602**

Prepared by:

Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Chicago, Il, 60607

Phone (312) 762-2900

Fax (312) 782-5145

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

April 16, 2019

Mr. Glen E. Garner
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2019 Three-Year Reinspections

Dear Mr. Glen:

Carnow, Conibear and Associates, Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 3, 4 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 24381 Region: 03 IDPH ID:14-016-2990-2334

School: Mason School Building ID: 4650

Address: 4217 W. 18th St.
Chicago, IL, 60623

Building Contact: Contact Phone:

Current Building Owners: Chicago Public Schools

Review Date: 04/30/2019

Inspector: Dionne Carey Inspector IDPH License: 100-09969
Management Planner: Evan Christian Management Planner IDPH License: 100-19466

If you have any questions or comments, please contact us at (312) 762-2900

Sincerely,
Carnow, Conibear and Associates

Evan Christian
100-19466

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: April 16, 2019

RE: Mason School, Unit 24381
4217 W. 18th St.
Chicago, IL, 60623

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2019 asbestos three year re-inspection has been completed at Mason School, following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at Mason School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Robert Christlieb, the designated Local Education Authority's Designated Person at (773) 553-3197 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Mason School
Address: 4217 W. 18th St.
IDPH ID: 14-016-2990-2334
Contact:

Unit: 24381
Chicago, IL, 60623
Building ID: 4650
Phone:

Region: 03

2. Description of Facility

Original Construction: 1958
Total Square Footage: 58257
Current Occupancy: 315

Additional Construction: 1922,1964
No of Floors: 3

3. LEA Designated Person

Contact: Robert Christlieb
Address: 42 West Madison Street
Chicago, IL 60602

Phone: (773) 553-3197

4. Managing Environmental Consultant

MEC: Carnow, Conibear and Associates
Contact: Doug McCormick
Address 600 West Van Buren St., Ste 500
Chicago, IL, 60607
Phone: (312) 762-2900

Fax: (312) 782-5145

5. Inspector

Inspector Name: Dionne Carey

Inspector IDPH license # 100-09969

Signature:
Date: 4/16/2019

6. Management Planner

Management Planner Name: Evan Christian

Management Planner IDPH license # 100-19466

Signature:
Date: 04/30/2019

7. Review Date:04/30/2019

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature:



Date: 10/1/2019

Name: Robert Christlieb

II. EXECUTIVE SUMMARY

Carnow, Conibear and Associates was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Mason School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.85 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas(HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 4650:

11	9"x 9" Green Floor Tile
12	12" x 12" Light Brown Mix Floor Tile
13	Mastic on 12"x12" Brown Floor Tile w/White Specks
35	Insulation Inside of Vault Door
4	9" x 9" Tan Floor Tile
48	12" x 12" Ceiling Tile
5	12" x 12" Brown Floor Tile w/White Specks
6	Plaster (Sampled in 1983 & 1992)
7	Plaster (Sampled in 1983 & 1992)

J

Hard joint compound on fiberglass

B. The following new homogenous areas have been identified for Building 4650:

J Hard joint compound on fiberglass

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

34 A	Orange Carpet Mastic
34 B	Gray Carpet Mastic
34 C	Blue Carpet Mastic
34 D	Brown Carpet Mastic
34 F	Green Carpet Mastic
34 G	Blue Carpet Mastic
34 H	Brown Carpet Mastic
35	Insulation Inside of Vault Door
36	Boiler Interior
37	Exterior Brick - Non Ahera
38	Exterior Brick Mortar - Non Ahera
39	Exterior Brick - Non Ahera
40	Exterior Brick Mortar - Non Ahera
41	Incinerator Components
42	12" x 12" Brown Floor Tile
43	12" x 12" Brown Floor Tile Mastic
44	12"x12" White Floor Tile
45	12" x 12" White Floor Tile Mastic
46	4" Black Vinyl Baseboard
47	4" Black Vinyl Baseboard Mastic
48	12" x 12" Ceiling Tile
49	12" x 12" Ceiling Tile Adhesive
50	12" x 12" Light Purple Floor Tile
51	12" x 12" Light Purple Floor Tile Mastic
53	9" x 9" White Floor Tile Mastic (patching)
54	Beige w/ Red Pattern Linoleum Flooring
55	Beige w/Red Pattern Linoleum Flooring Adhesive
56	12" x 12" Lt. Blue w/Blue & Gray Specks Floor Tile
57	12" x 12" Lt. Blue w/Blue & Gray Specks FT Mastic
58	12" X 12" White Floor Tile
59	12" X 12" White Floor Tile Mastic
6	Plaster (Sampled in 1983 & 1992)
60	12" X 12" White Floor Tile
61	12" X 12" White Floor Tile Mastic
62	9" X 9" Lt Gray Floor Tile
63	9" X 9" Lt Gray Floor Tile Mastic
64	9" X 9" Dark Brown Floor Tile
65	9" X 9" Dark Brown Floor Tile Mastic
66	12" X 12" Lt Purple Floor Tile
67	12" X 12" Lt Purple Floor Tile Mastic
68	12" X 12" White Floor Tile (Patching)

69	12" X 12" White Floor Tile Mastic (Patching)
7	Plaster (Sampled in 1983 & 1992)
70	Blue-White Ceramic Wall Grout
70M	Blue-White Ceramic Wall Grout Adhesive
71	Green and Black Terrazzo
72	Brown Carpet Adhesive
73	Brown Ceramic Tile Grout
73M	Brown Ceramic Tile Grout Adhesive
74	12"x12" White w/Brown Floor Tile
I	Transite Pipe
J	Hard joint compound on fiberglass

The following areas were deemed to be inaccessible:

19	Mastic on 9"x9" Bluish Grn/Blk Checker Floor Tile
23	Mastic on 12"x12" Dark Brown Floor Tile
31	Mastic on 9" x 9" Light Brown Mix Floor Tile
34 A	Orange Carpet Mastic
34 B	Gray Carpet Mastic
34 C	Blue Carpet Mastic
34 D	Brown Carpet Mastic
34 F	Green Carpet Mastic
34 G	Blue Carpet Mastic
34 H	Brown Carpet Mastic
35	Insulation Inside of Vault Door
41	Incinerator Components
43	12" x 12" Brown Floor Tile Mastic
45	12" x 12" White Floor Tile Mastic
47	4" Black Vinyl Baseboard Mastic
49	12" x 12" Ceiling Tile Adhesive
51	12" x 12" Light Purple Floor Tile Mastic
53	9" x 9" White Floor Tile Mastic (patching)
55	Beige w/Red Pattern Linoleum Flooring Adhesive
57	12" x 12" Lt. Blue w/Blue & Gray Specks FT Mastic
59	12" X 12" White Floor Tile Mastic
61	12" X 12" White Floor Tile Mastic
63	9" X 9" Lt Gray Floor Tile Mastic
65	9" X 9" Dark Brown Floor Tile Mastic
67	12" X 12" Lt Purple Floor Tile Mastic
69	12" X 12" White Floor Tile Mastic (Patching)
70M	Blue-White Ceramic Wall Grout Adhesive
72	Brown Carpet Adhesive
73M	Brown Ceramic Tile Grout Adhesive
74M	12"x12" White w/Brown Floor Tile Mastic
8	Mastic on 9"x9" Tan Floor Tile

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Dionne Carey, IDPH License # 100-09969. The Management Plan was updated by Evan Christian, IDPH License # 100-19466. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Mason School Building 4650 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Mason School Unit 24381 Building ID 4650

Address 4217 W. 18th St. Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
1-3	Numbers Skipped				UNDEFINE D									
10	Mastic on 12"x12" Light Brown Mix Floor Tile	5,000	SF	1958 Building - First Floor Corridor	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
11	9"x 9" Green Floor Tile	10,000	SF	1958 Building - Men's Lounge, 119, S.R., 123, 131, 225, 2nd & 3rd Floor Corridors	CHR	MISC	N	DIST	225		Yes	Damaged or significantly damaged friable misc. ACBM	5	LOW
12	12" x 12" Light Brown Mix Floor Tile	5,000	SF	1958 Building - First Floor Corridor	CHR	MISC	N	DIST	150		Yes	Damaged or significantly damaged friable misc. ACBM	5	LOW
13	Mastic on 12"x12" Brown Floor Tile w/White Specks	2,040	SF	1919 Building - 106 (Engineer's Office) & 2nd Floor Teacher's Washroom	CHR	MISC	N	NONE	100		Yes	ACBM with the potential for damage		LOW
14	12" x 12" White/Brown Floor Tile	400	SF	1919 Building - Assembly Hall	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
15	Mastic on 12" x 12" White/Brown Floor Tile	400	SF	1919 Building - Assembly Hall	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
16	9" x 9" Red/Black Checker Patterned Floor Tile	832	SF	1919 Building - Room 116 (not observed)	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
17	Mastic on 9"x9" Red/Black Checker Pattern FT	832	SF	1919 Building - Room 116 (not observed)	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
18	9" x 9" Bluish Grn/Blk Checker Pattern Floor Tile- Removed			1919 Building - 2nd and 3rd Floor Corridors	ABATED	MISC								
19	Mastic on 9"x9" Bluish Grn/Blk Checker Floor Tile	4,000	SF	1919 Building - 2nd and 3rd Floor Corridors - Removed	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
20	9" x 9" Gray/Black Floor Tile	3,600	SF	1958 Building - Rooms 128, 228, 328	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
21	Mastic on 9" x 9" Gray/Black Floor Tile	3,600	SF	1958 Building - Rooms 128, 228, 328	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
22	12" x 12" Dark Brown Floor Tile	3,600	SF	1958 Building - Lunch Room and Kitchen	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
23	Mastic on 12"x12" Dark Brown Floor Tile	3,600	SF	1958 Building - Lunch Room and	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Mason School Unit 24381 Building ID 4650

Address 4217 W. 18th St. Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Kitchen										
24	9" x 9" White Floor Tile- Removed			1958 Building - Rooms 117 & 119	ABATED	MISC								
25	Mastic on 9" x 9" White Floor Tile- Removed			1958 Building - Rooms 117 & 119	ABATED	MISC								
26	9" x 9" Brown Mix Floor Tile	6,200	SF	1958 Building - Office, and Rooms 121, 220, 223, 320, 317	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
27	Mastic on 9" x 9" Brown Mix Floor Tile	5,700	SF	1958 Building - Office, and Rooms 220, 223, 320, 317	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
28	9" x 9" White/Green Floor Tile	3,000	SF	1958 Building - Rooms 119, 123, 131, 225, 325	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
29	Mastic on 9" x 9" White/Green Floor Tile	3,000	SF	1958 Building - Rooms 119, 123, 131, 225, 325	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
30	9" x 9" Light Brown Mix Floor Tile	12,000	SF	1958 Building - Rooms 118, 124, 125, 226, 224, 221, 318, 321, 324, 326	CHR	MISC	N	LOC	700		No	Damaged or significantly damaged friable misc. ACBM	5	LOW
31	Mastic on 9" x 9" Light Brown Mix Floor Tile	12,000	SF	1958 Building - Rooms 118,124, 125, 226, 224, 221, 318, 321, 324, 326	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
32	9" x 9" Gray/Red Mix Floor Tile	13,200	SF	1958 Building - Rooms 117, 127, 217, 218, 219, 222, 227, 318, 319, 322, 327	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
33	Mastic on 9"x9" Gray/Red Mix Floor Tile	13,200	SF	1958 Building - Rooms 117, 127, 217, 218, 219, 222, 227,318, 319, 322, 327	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
34 A	Orange Carpet Mastic	1,050	SF	1919 Building - Rooms 101, 103	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
34 B	Gray Carpet Mastic	900	SF	1919 Building - Rooms 104 & 111	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
34 C	Blue Carpet Mastic	1,120	SF	1919 Building - Rooms 105 & Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
34 D	Brown Carpet Mastic	1,500	SF	1919 Building - Rooms 113, 114 &	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Mason School Unit 24381 Building ID 4650

Address 4217 W. 18th St. Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				115										
34 E	Blue Carpet Mastic- Repeat of HS 34 C				UNDEFINE D									
34 F	Green Carpet Mastic	300	SF	1919 Building - North Building Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
34 G	Blue Carpet Mastic	1,200	SF	1958 Building - Rooms 117, 118, & 119	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
34 H	Brown Carpet Mastic	1,120	SF	1919 Building - Asst. Principal's Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
35	Insulation Inside of Vault Door	64	SF	1919 Building - Main Office & Room 105 (not observed)	ASSUMED	TSI	Y	NONE	0		Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
36	Boiler Interior			1919 Building - Boiler Room (not observed)	ASSUMED	MISC								
37	Exterior Brick - Non Ahera			1919 Building	ASSUMED	MISC								
38	Exterior Brick Mortar - Non Ahera			1919 Building	ASSUMED	MISC								
39	Exterior Brick - Non Ahera			1958 Building	ASSUMED	MISC								
4	9" x 9" Tan Floor Tile	1,632	SF	1919 Building - Room 108, Boiler Room, Room 252	CHR	MISC	N	NONE	600		Yes	Damaged or significantly damaged friable misc. ACBM	5	LOW
40	Exterior Brick Mortar - Non Ahera			1958 Building	ASSUMED	MISC								
41	Incinerator Components	250	SF	Boiler Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
42	12" x 12" Brown Floor Tile	495	SF	Room 307	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
43	12" x 12" Brown Floor Tile Mastic	495	SF	Room 307	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
44	12"x12" White Floor Tile	495	SF	Room 307	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
45	12" x 12" White Floor Tile Mastic	495	SF	Room 307	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
46	4" Black Vinyl Baseboard	500	LF	Throughout 1958 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
47	4" Black Vinyl Baseboard Mastic	500	LF	Throughout 1958 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
48	12" x 12" Ceiling Tile	2,500	SF	North Building Corridors	ASSUMED	MISC	Y	LOC	100		Yes	Damaged or significantly damaged friable misc. ACBM	10	LOW
49	12" x 12" Ceiling Tile Adhesive	2,500	SF	North Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the		LOW

Chicago Public Schools

School Mason School Unit 24381 Building ID 4650

Address 4217 W. 18th St. Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Corridors								potential for damage		
5	12" x 12" Brown Floor Tile w/White Specks	2,040	SF	1919 Building - Rooms 106 (Engineer's Office) & 2nd Floor Teacher's Washroom	CHR	MISC	N	LOC	100		Yes	Damaged or significantly damaged friable misc. ACBM	5	LOW
50	12" x 12" Light Purple Floor Tile	1,700	SF	Rooms 116 and 119 (not observed)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
51	12" x 12" Light Purple Floor Tile Mastic	1,700	SF	Rooms 116 and 119 (not observed)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
52	9" x 9" White Floor Tile (patching)	71	SF	Rooms 228, 126 (not observed)	ACT	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
53	9" x 9" White Floor Tile Mastic (patching)	71	SF	Rooms 228, 126 (not observed)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
54	Beige w/ Red Pattern Linoleum Flooring	100	SF	2nd Floor North Stairwell Washroom (not observed)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
55	Beige w/Red Pattern Linoleum Flooring Adhesive	100	SF	2nd Floor North Stairwell Washroom (not observed)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
56	12" x 12" Lt. Blue w/Blue & Gray Specks Floor Tile	2,000	SF	1919 Building - 2nd & 3rd Floor Corridors	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
57	12" x 12" Lt. Blue w/Blue & Gray Specks FT Mastic	2,000	SF	1919 Building - 2nd & 3rd Floor Corridors	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
58	12" X 12" White Floor Tile	5,000	SF	1919 Bldg 2nd and 3rd Floor Corridors	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
59	12" X 12" White Floor Tile Mastic	5,000	SF	1919 Bldg 2nd and 3rd Floor Corridors	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
6	Plaster (Sampled in 1983 & 1992)	10,000	SF	1919 Building	ASSUMED	SURFACE	Y	NONE	0		Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
60	12" X 12" White Floor Tile	2,250	SF	1958 Bldg Rooms 117, 119 and 121 (not observed)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
61	12" X 12" White Floor Tile Mastic	2,250	SF	1958 Bldg Rooms 117, 119 and 121 (not observed)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
62	9" X 9" Lt Gray Floor Tile	50	SF	1958 Bldg Room 117 closet (not observed)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
63	9" X 9" Lt Gray Floor Tile Mastic	50	SF	1958 Bldg Room 117 closet (not observed)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Mason School Unit 24381 Building ID 4650

Address 4217 W. 18th St. Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				observed)										
64	9" X 9" Dark Brown Floor Tile	150	SF	Room 119 Closet and 121 Store Room (not observed)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
65	9" X 9" Dark Brown Floor Tile Mastic	150	SF	Room 119 Closet and Room 121 Store Room (not observed)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
66	12" X 12" Lt Purple Floor Tile	1,400	SF	Rooms 116 and 119 (not observed)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
67	12" X 12" Lt Purple Floor Tile Mastic	1,400	SF	Rooms 116 and 119 (not observed)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
68	12" X 12" White Floor Tile (Patching)	14	SF	Room 106 Engineer's Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
69	12" X 12" White Floor Tile Mastic (Patching)	14	SF	Room 106 Engineer's Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
7	Plaster (Sampled in 1983 & 1992)	10,000	SF	1958 Building	ASSUMED	MISC	Y	DIST	1,000		Yes	Damaged or significantly damaged friable misc. ACBM	10	LOW
70	Blue-White Ceramic Wall Grout	600	SF	Entry of School and 4 columns	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
70M	Blue-White Ceramic Wall Grout Adhesive	600	SF	Entry of School and 4 Columns	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
71	Green and Black Terrazzo	1,500	SF	1st, 2nd and 3rd Floor Stairwells and Landings	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
72	Brown Carpet Adhesive	300	SF	Room 129 (not observed)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
73	Brown Ceramic Tile Grout	2,000	SF	1st, 2nd and 3rd Floor Boy's and Girl's Toilet	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
73M	Brown Ceramic Tile Grout Adhesive	2,000	SF	1st, 2nd, and 3rd Floor Boy's and Girl's Toilet	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
74	12"x12" White w/Brown Floor Tile	1,125	SF	Room 206	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
74M	12"x12" White w/Brown Floor Tile Mastic	1,125	SF	Room 206	ANT	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
8	Mastic on 9"x9" Tan Floor Tile	832	SF	1919 Building - Room 108	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
9	9"x 9" Green Floor Tile Mastic	10,000	SF	1958 Building - Men's Lounge, Rooms 119, S.R., 123, 131, 225, 2nd	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Mason School Unit 24381 Building ID 4650

Address 4217 W. 18th St. Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				& 3rd Floor Corridors , 217, 325										
A-B	Numbers Skipped				UNDEFINED									
C	Cardboard Pipe Insulation			Possibly In Inaccessible Areas Throughout Facility	CHR	TSI		None						
D	Hard Joint Compound on Cardboard Pipe Insulation			Possibly In Inaccessible Areas Throughout Facility	CHR	TSI								
E	Aircell Pipe Insulation			Possibly In Inaccessible Areas Throughout Facility	CHR	TSI								
F	Hard Joint Compound on Aircell Pipe Insulation			Possibly In Inaccessible Areas Throughout Facility	CHR	TSI								
G	Tank Insulation (abated between 1995-1998)			Boiler Room	ABATED	MISC								
H	Boiler Breeching (Abated between 1995-1998)			Boiler Room	ABATED	MISC								
I	Transite Pipe			1919 Building - Boiler Room (not observed)	ASSUMED	TSI								
J	Hard joint compound on fiberglass	10	SF	janitor's closet adjacent to lunchroom on 1st floor	ASSUMED	TSI	Y	LOC	10		Yes	Damaged or significantly damaged friable thermal system insulating ACBM	5	MODERATE

Chicago Public Schools

School Mason School Unit 24381 Building ID 4650

Address 4217 W. 18th St. Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

Reinspection Date 4/16/2019
Inspector Name Dionne Carey
100-09969 5/15/2020
Inspector's IDPH License Number / Expiration Date

Inspector's Comments

HA Number:	Inspector Comments:
1-3	
10	
11	Physical Damage and deterioration was observed on the 2nd and 3rd floor corridor, not observed in 119
12	
13	
14	
15	
16	Not observed in 2019
17	Not observed in 2019
18	
19	
20	
21	
22	
23	
24	
25	
26	
27	
28	
29	
30	
31	

Chicago Public Schools

School Mason School Unit 24381 Building ID 4650

Address 4217 W. 18th St. Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
32	
33	
34 A	
34 B	
34 C	
34 D	
34 E	
34 F	
34 G	
34 H	
35	Not observed 2019
36	Not observed 2016 - same
37	
38	
39	
4	Basement boiler room and room throughout have damaged 9" VFT with soot from flooding
40	
41	
42	
43	
44	
45	
46	
47	
48	
49	
5	Damage is located in engineer's office
50	Not observed 2019

Chicago Public Schools

School Mason School Unit 24381 Building ID 4650

Address 4217 W. 18th St. Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
51	Not observed 2019
52	Not observed 2019
53	Not observed 2019
54	Not observed 2019
55	Not observed 2019
56	
57	
58	
59	
6	
60	
61	
62	
63	
64	
65	
66	
67	
68	
69	
7	Room 257
70	
70M	
71	
72	Not observed 2019
73	
73M	
74	Not observed 2019
74M	Not observed 2019

Chicago Public Schools

School Mason School Unit 24381 Building ID 4650

Address 4217 W. 18th St. Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
8	
9	
A-B	
C	Not observed 2016 - same 2019
D	Not observed 2016 - same 2019
E	Not observed 2016 - same 2019
F	JC Cafe
G	
H	
I	Not observed 2016 - same 2019
J	Hard joint on FG, JC near lunchroom 1st floor

Table II

Management Planner's Review

Chicago Public Schools

School Mason School
Address 4217 W. 18th St.

Unit 24381
Chicago, IL, 60623

Building ID 4650
Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
1-3	Numbers Skipped				Undefined						
10	Mastic on 12"x12" Light Brown Mix Floor Tile	5,000	SF	1958 Building - First Floor Corridor	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
11	9"x 9" Green Floor Tile	10,000	SF	1958 Building - Men's Lounge, 119, S. R., 123, 131, 225, 2nd & 3rd Floor Corridors	Chrysotile	MISC	No	225	SF	4 Damaged or significantly damaged friable misc. ACBM	Remove
12	12" x 12" Light Brown Mix Floor Tile	5,000	SF	1958 Building - First Floor Corridor	Chrysotile	MISC	No	150	SF	4 Damaged or significantly damaged friable misc. ACBM	Repair
13	Mastic on 12"x12" Brown Floor Tile w/White Specks	2,040	SF	1919 Building - 106 (Engineer's Office) & 2nd Floor Teacher's Washroom	Chrysotile	MISC	No	100	SF	6 ACBM with the potential for damage	Repair
14	12" x 12" White/Brown Floor Tile	400	SF	1919 Building - Assembly Hall	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
15	Mastic on 12" x 12" White/Brown Floor Tile	400	SF	1919 Building - Assembly Hall	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
16	9" x 9" Red/Black Checker Patterned Floor Tile	832	SF	1919 Building - Room 116 (not observed)	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
17	Mastic on 9"x9" Red/Black Checker Pattern FT	832	SF	1919 Building - Room 116 (not observed)	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
18	9" x 9" Bluish Grn/Blk Checker Pattern Floor Tile- Removed			1919 Building - 2nd and 3rd Floor Corridors	Abated	MISC					
19	Mastic on 9"x9" Bluish Grn/Blk Checker Floor Tile	4,000	SF	1919 Building - 2nd and 3rd Floor Corridors - Removed	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
20	9" x 9" Gray/Black Floor Tile	3,600	SF	1958 Building - Rooms 128, 228, 328	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
21	Mastic on 9" x 9" Gray/Black Floor Tile	3,600	SF	1958 Building - Rooms 128, 228, 328	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
22	12" x 12" Dark Brown Floor Tile	3,600	SF	1958 Building - Lunch Room and Kitchen	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
23	Mastic on 12"x12" Dark Brown Floor Tile	3,600	SF	1958 Building - Lunch Room and Kitchen	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
24	9" x 9" White Floor Tile- Removed			1958 Building - Rooms 117 & 119	Abated	MISC					
25	Mastic on 9" x 9" White Floor Tile- Removed			1958 Building - Rooms 117 & 119	Abated	MISC					
26	9" x 9" Brown Mix Floor Tile	6,200	SF	1958 Building - Office, and Rooms 121, 220, 223, 320, 317	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
27	Mastic on 9" x 9" Brown Mix Floor Tile	5,700	SF	1958 Building - Office, and Rooms 220, 223, 320, 317	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
28	9" x 9" White/Green Floor Tile	3,000	SF	1958 Building - Rooms 119, 123, 131, 225, 325	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
29	Mastic on 9" x 9" White/Green Floor Tile	3,000	SF	1958 Building - Rooms 119, 123, 131, 225, 325	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Mason School
Address 4217 W. 18th St.

Unit 24381
Chicago, IL, 60623

Building ID 4650
Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
30	9" x 9" Light Brown Mix Floor Tile	12,000	SF	1958 Building - Rooms 118, 124, 125, 226, 224, 221, 318, 321, 324, 326	Chrysotile	MISC	No	700	SF	4 Damaged or significantly damaged friable misc. ACBM	Follow O&M Plan
31	Mastic on 9" x 9" Light Brown Mix Floor Tile	12,000	SF	1958 Building - Rooms 118,124, 125, 226, 224, 221, 318, 321, 324, 326	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
32	9" x 9" Gray/Red Mix Floor Tile	13,200	SF	1958 Building - Rooms 117, 127, 217, 218, 219, 222, 227, 318, 319, 322, 327	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
33	Mastic on 9"x9" Gray/Red Mix Floor Tile	13,200	SF	1958 Building - Rooms 117, 127, 217, 218, 219, 222, 227,318, 319, 322, 327	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
34 A	Orange Carpet Mastic	1,050	SF	1919 Building - Rooms 101, 103	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
34 B	Gray Carpet Mastic	900	SF	1919 Building - Rooms 104 & 111	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
34 C	Blue Carpet Mastic	1,120	SF	1919 Building - Rooms 105 & Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
34 D	Brown Carpet Mastic	1,500	SF	1919 Building - Rooms 113, 114 & 115	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
34 E	Blue Carpet Mastic- Repeat of HS 34 C				Undefined						Follow O&M Plan
34 F	Green Carpet Mastic	300	SF	1919 Building - North Building Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
34 G	Blue Carpet Mastic	1,200	SF	1958 Building - Rooms 117, 118, & 119	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
34 H	Brown Carpet Mastic	1,120	SF	1919 Building - Asst. Principal's Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
35	Insulation Inside of Vault Door	64	SF	1919 Building - Main Office & Room 105 (not observed)	Assumed	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
36	Boiler Interior			1919 Building - Boiler Room (not observed)	Assumed	MISC					Follow O&M Plan
37	Exterior Brick - Non Ahera			1919 Building	Assumed	MISC					
38	Exterior Brick Mortar - Non Ahera			1919 Building	Assumed	MISC					
39	Exterior Brick - Non Ahera			1958 Building	Assumed	MISC					
4	9" x 9" Tan Floor Tile	1,632	SF	1919 Building - Room 108, Boiler Room, Room 252	Chrysotile	MISC	No	600	SF	4 Damaged or significantly damaged friable misc. ACBM	Remove
40	Exterior Brick Mortar - Non Ahera			1958 Building	Assumed	MISC					
41	Incinerator Components	250	SF	Boiler Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
42	12" x 12" Brown Floor Tile	495	SF	Room 307	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
43	12" x 12" Brown Floor Tile Mastic	495	SF	Room 307	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
44	12"x12" White Floor Tile	495	SF	Room 307	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
45	12" x 12" White Floor Tile Mastic	495	SF	Room 307	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
46	4" Black Vinyl Baseboard	500	LF	Throughout 1958 Building	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
47	4" Black Vinyl Baseboard Mastic	500	LF	Throughout 1958 Building	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
48	12" x 12" Ceiling Tile	2,500	SF	North Building Corridors	Assumed	MISC	Yes	100	SF	4 Damaged or significantly damaged	Follow O&M Plan

Chicago Public Schools

School Mason School
Address 4217 W. 18th St.

Unit 24381
Chicago, IL, 60623

Building ID 4650
Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
										friable misc. ACBM	
49	12" x 12" Ceiling Tile Adhesive	2,500	SF	North Building Corridors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
5	12" x 12" Brown Floor Tile w/White Specks	2,040	SF	1919 Building - Rooms 106 (Engineer's Office) & 2nd Floor Teacher's Washroom	Chrysotile	MISC	No	100	SF	4 Damaged or significantly damaged friable misc. ACBM	Remove
50	12" x 12" Light Purple Floor Tile	1,700	SF	Rooms 116 and 119 (not observed)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
51	12" x 12" Light Purple Floor Tile Mastic	1,700	SF	Rooms 116 and 119 (not observed)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
52	9" x 9" White Floor Tile (patching)	71	SF	Rooms 228, 126 (not observed)	Actinolite	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
53	9" x 9" White Floor Tile Mastic (patching)	71	SF	Rooms 228, 126 (not observed)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
54	Beige w/ Red Pattern Linoleum Flooring	100	SF	2nd Floor North Stairwell Washroom (not observed)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
55	Beige w/Red Pattern Linoleum Flooring Adhesive	100	SF	2nd Floor North Stairwell Washroom (not observed)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
56	12" x 12" Lt. Blue w/Blue & Gray Specks Floor Tile	2,000	SF	1919 Building - 2nd & 3rd Floor Corridors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
57	12" x 12" Lt. Blue w/Blue & Gray Specks FT Mastic	2,000	SF	1919 Building - 2nd & 3rd Floor Corridors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
58	12" X 12" White Floor Tile	5,000	SF	1919 Bldg 2nd and 3rd Floor Corridors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
59	12" X 12" White Floor Tile Mastic	5,000	SF	1919 Bldg 2nd and 3rd Floor Corridors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
6	Plaster (Sampled in 1983 & 1992)	10,000	SF	1919 Building	Assumed	SURFACE	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
60	12" X 12" White Floor Tile	2,250	SF	1958 Bldg Rooms 117, 119 and 121 (not observed)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
61	12" X 12" White Floor Tile Mastic	2,250	SF	1958 Bldg Rooms 117, 119 and 121 (not observed)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
62	9" X 9" Lt Gray Floor Tile	50	SF	1958 Bldg Room 117 closet (not observed)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
63	9" X 9" Lt Gray Floor Tile Mastic	50	SF	1958 Bldg Room 117 closet (not observed)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
64	9" X 9" Dark Brown Floor Tile	150	SF	Room 119 Closet and 121 Store Room (not observed)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
65	9" X 9" Dark Brown Floor Tile Mastic	150	SF	Room 119 Closet and Room 121 Store Room (not observed)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
66	12" X 12" Lt Purple Floor Tile	1,400	SF	Rooms 116 and 119 (not observed)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Mason School
Address 4217 W. 18th St.

Unit 24381
Chicago, IL, 60623

Building ID 4650
Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
67	12" X 12" Lt Purple Floor Tile Mastic	1,400	SF	Rooms 116 and 119 (not observed)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
68	12" X 12" White Floor Tile (Patching)	14	SF	Room 106 Engineer's Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
69	12" X 12" White Floor Tile Mastic (Patching)	14	SF	Room 106 Engineer's Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
7	Plaster (Sampled in 1983 & 1992)	10,000	SF	1958 Building	Assumed	MISC	Yes	1,000	SF	4 Damaged or significantly damaged friable misc. ACBM	Repair
70	Blue-White Ceramic Wall Grout	600	SF	Entry of School and 4 columns	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
70M	Blue-White Ceramic Wall Grout Adhesive	600	SF	Entry of School and 4 Columns	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
71	Green and Black Terrazzo	1,500	SF	1st, 2nd and 3rd Floor Stairwells and Landings	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
72	Brown Carpet Adhesive	300	SF	Room 129 (not observed)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
73	Brown Ceramic Tile Grout	2,000	SF	1st, 2nd and 3rd Floor Boy's and Girl's Toilet	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
73M	Brown Ceramic Tile Grout Adhesive	2,000	SF	1st, 2nd, and 3rd Floor Boy's and Girl's Toilet	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
74	12"x12" White w/Brown Floor Tile	1,125	SF	Room 206	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
74M	12"x12" White w/Brown Floor Tile Mastic	1,125	SF	Room 206	Anthophyllite	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
8	Mastic on 9"x9" Tan Floor Tile	832	SF	1919 Building - Room 108	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
9	9"x 9" Green Floor Tile Mastic	10,000	SF	1958 Building - Men's Lounge, Rooms 119, S.R., 123, 131, 225, 2nd & 3rd Floor Corridors , 217, 325	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
A-B	Numbers Skipped				Undefined						
C	Cardboard Pipe Insulation			Possibly In Inaccessible Areas Throughout Facility	Chrysotile	TSI					Follow O&M Plan
D	Hard Joint Compound on Cardboard Pipe Insulation			Possibly In Inaccessible Areas Throughout Facility	Chrysotile	TSI					Follow O&M Plan
E	Aircell Pipe Insulation			Possibly In Inaccessible Areas Throughout Facility	Chrysotile	TSI					Follow O&M Plan
F	Hard Joint Compound on Aircell Pipe Insulation			Possibly In Inaccessible Areas Throughout Facility	Chrysotile	TSI					Follow O&M Plan
G	Tank Insulation (abated between 1995-1998)			Boiler Room	Abated	MISC					
H	Boiler Breeching (Abated between 1995- 1998)			Boiler Room	Abated	MISC					
I	Transite Pipe			1919 Building - Boiler Room (not observed)	Assumed	TSI					Follow O&M Plan

Chicago Public Schools

School Mason School
Address 4217 W. 18th St.

Unit 24381
 Chicago, IL, 60623

Building ID 4650
Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
J	Hard joint compound on fiberglass	10	SF	janitor's closet adjacent to lunchroom on 1st floor	Assumed	TSI	Yes	10	SF	1 Damaged or significantly damaged friable thermal system insulating ACBM	Remove

Review Date	04/30/2019
Manager Planner Name	Evan Christian

HA Number	Management Comments
1-3	

Chicago Public Schools

School Mason School
Address 4217 W. 18th St.

Unit 24381
 Chicago, IL, 60623

Building ID 4650
Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

100-19466	5/15/2020
Manager IDPH License No/Expiration	

HA Number	Management Comments
10	
11	
12	
13	
14	
15	
16	
17	
18	
19	
20	
21	
22	
23	
24	
25	
26	
27	
28	
29	
30	
31	
32	
33	
34 A	
34 B	

Chicago Public Schools

School Mason School
Address 4217 W. 18th St.

Unit 24381
 Chicago, IL, 60623

Building ID 4650
Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
34 C	
34 D	
34 E	
34 F	
34 G	
34 H	
35	
36	
37	
38	
39	
4	
40	
41	
42	
43	
44	
45	
46	
47	
48	
49	
5	Remove and replace the Ceiling Tile located in the engineer's office
50	
51	
52	

Chicago Public Schools

School Mason School
Address 4217 W. 18th St.

Unit 24381
 Chicago, IL, 60623

Building ID 4650
Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
53	
54	
55	
56	
57	
58	
59	
6	
60	
61	
62	
63	
64	
65	
66	
67	
68	
69	
7	
70	
70M	
71	
72	
73	
73M	
74	

Chicago Public Schools

School Mason School
Address 4217 W. 18th St.

Unit 24381
Chicago, IL, 60623

Building ID 4650
Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
74M	
8	
9	
A-B	
C	
D	
E	
F	
G	
H	
I	
J	

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Mason School** INSPECTION DATE: **4/16/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **1-3**
MATERIAL DESCRIPTION: **Numbers Skipped**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Undefined** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION:

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Mason School** REVIEW DATE: **4/30/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **1-3**

MATERIAL DESCRIPTION: **Numbers Skipped**

MATERIAL LOCATION:

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/30/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Mason School** INSPECTION DATE: **4/16/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10**
MATERIAL DESCRIPTION: **Mastic on 12"x12" Light Brown Mix Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1958 Building - First Floor Corridor**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/16/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Mason School** REVIEW DATE: **4/30/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **10**

MATERIAL DESCRIPTION: **Mastic on 12"x12" Light Brown Mix Floor Tile**

MATERIAL LOCATION: **1958 Building - First Floor Corridor**

MATERIAL QUANTITY: **5000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/30/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Mason School** INSPECTION DATE: **4/16/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11**
MATERIAL DESCRIPTION: **9"x 9" Green Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **4 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **4. Damaged or significantly damaged friable misc. ACBM**

DAMAGE REASON: **Physical Damage
Deterioration**

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1958 Building - Men's Lounge, 119, S.R., 123, 131, 225, 2nd & 3rd Floor Corridors**

MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **225** DAMAGE UNITS: **SF**

COMMENTS: **Physical Damage and deterioration was observed on the 2nd and 3rd floor corridor, not observed in 119**

Inspector's Signature: _____ Date: 04/16/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Mason School** REVIEW DATE: **4/30/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **11**
MATERIAL DESCRIPTION: **9"x 9" Green Floor Tile**
MATERIAL LOCATION: **1958 Building - Men's Lounge, 119, S.R., 123, 131, 225, 2nd & 3rd Floor Corridors**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **225** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/30/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Mason School** INSPECTION DATE: **4/16/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12**
MATERIAL DESCRIPTION: **12" x 12" Light Brown Mix Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **4 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **4. Damaged or significantly damaged friable misc. ACBM**

DAMAGE REASON: **Physical Damage**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1958 Building - First Floor Corridor**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **150** DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: **04/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Mason School** REVIEW DATE: **4/30/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **12**
MATERIAL DESCRIPTION: **12" x 12" Light Brown Mix Floor Tile**
MATERIAL LOCATION: **1958 Building - First Floor Corridor**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **150** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/30/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUILDING ID: **4650**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Mason School** INSPECTION DATE: **4/16/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13**
MATERIAL DESCRIPTION: **Mastic on 12"x12" Brown Floor Tile w/White Specks**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1919 Building - 106 (Engineer's Office) & 2nd Floor Teacher's Washroom**
MATERIAL QUANTITY: **2040** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **100** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/16/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Mason School** REVIEW DATE: **4/30/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **13**

MATERIAL DESCRIPTION: **Mastic on 12"x12" Brown Floor Tile w/White Specks**

MATERIAL LOCATION: **1919 Building - 106 (Engineer's Office) & 2nd Floor Teacher's Washroom**

MATERIAL QUANTITY: **2040**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **100**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/30/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Mason School** INSPECTION DATE: **4/16/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14**
MATERIAL DESCRIPTION: **12" x 12" White/Brown Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1919 Building - Assembly Hall**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/16/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Mason School** REVIEW DATE: **4/30/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **14**

MATERIAL DESCRIPTION: **12" x 12" White/Brown Floor Tile**

MATERIAL LOCATION: **1919 Building - Assembly Hall**

MATERIAL QUANTITY: **400**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/30/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Mason School** INSPECTION DATE: **4/16/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15**
MATERIAL DESCRIPTION: **Mastic on 12" x 12" White/Brown Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1919 Building - Assembly Hall**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/16/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Mason School** REVIEW DATE: **4/30/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **15**

MATERIAL DESCRIPTION: **Mastic on 12" x 12" White/Brown Floor Tile**

MATERIAL LOCATION: **1919 Building - Assembly Hall**

MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/30/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Mason School** INSPECTION DATE: **4/16/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16**
MATERIAL DESCRIPTION: **9" x 9" Red/Black Checker Patterned Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1919 Building - Room 116 (not observed)**
MATERIAL QUANTITY: **832** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**
COMMENTS: **Not observed in 2019**

Inspector's Signature: _____ Date: 04/16/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Mason School** REVIEW DATE: **4/30/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **16**

MATERIAL DESCRIPTION: **9" x 9" Red/Black Checker Patterned Floor Tile**

MATERIAL LOCATION: **1919 Building - Room 116 (not observed)**

MATERIAL QUANTITY: **832** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/30/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Mason School** INSPECTION DATE: **4/16/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17**
MATERIAL DESCRIPTION: **Mastic on 9"x9" Red/Black Checker Pattern FT**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1919 Building - Room 116 (not observed)**
MATERIAL QUANTITY: **832** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**
COMMENTS: **Not observed in 2019**

Inspector's Signature: _____ Date: 04/16/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Mason School** REVIEW DATE: **4/30/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **17**

MATERIAL DESCRIPTION: **Mastic on 9"x9" Red/Black Checker Pattern FT**

MATERIAL LOCATION: **1919 Building - Room 116 (not observed)**

MATERIAL QUANTITY: **832** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/30/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Mason School** INSPECTION DATE: **4/16/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18**
MATERIAL DESCRIPTION: **9" x 9" Bluish Grn/Blk Checker Pattern Floor Tile- Removed**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1919 Building - 2nd and 3rd Floor Corridors**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Mason School** REVIEW DATE: **4/30/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **18**

MATERIAL DESCRIPTION: **9" x 9" Bluish Grn/Blk Checker Pattern Floor Tile- Removed**

MATERIAL LOCATION: **1919 Building - 2nd and 3rd Floor Corridors**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/30/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Mason School** INSPECTION DATE: **4/16/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19**
MATERIAL DESCRIPTION: **Mastic on 9"x9" Bluish Grn/Blk Checker Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1919 Building - 2nd and 3rd Floor Corridors - Removed**
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/16/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Mason School** REVIEW DATE: **4/30/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **19**
MATERIAL DESCRIPTION: **Mastic on 9"x9" Bluish Grn/Blk Checker Floor Tile**
MATERIAL LOCATION: **1919 Building - 2nd and 3rd Floor Corridors - Removed**
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/30/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Mason School** INSPECTION DATE: **4/16/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**
MATERIAL DESCRIPTION: **9" x 9" Gray/Black Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1958 Building - Rooms 128, 228, 328**
MATERIAL QUANTITY: **3600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/16/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Mason School** REVIEW DATE: **4/30/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **20**

MATERIAL DESCRIPTION: **9" x 9" Gray/Black Floor Tile**

MATERIAL LOCATION: **1958 Building - Rooms 128, 228, 328**

MATERIAL QUANTITY: **3600**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/30/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Mason School** INSPECTION DATE: **4/16/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21**
MATERIAL DESCRIPTION: **Mastic on 9" x 9" Gray/Black Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1958 Building - Rooms 128, 228, 328**
MATERIAL QUANTITY: **3600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/16/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Mason School** REVIEW DATE: **4/30/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **21**
MATERIAL DESCRIPTION: **Mastic on 9" x 9" Gray/Black Floor Tile**
MATERIAL LOCATION: **1958 Building - Rooms 128, 228, 328**
MATERIAL QUANTITY: **3600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/30/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Mason School** INSPECTION DATE: **4/16/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22**
MATERIAL DESCRIPTION: **12" x 12" Dark Brown Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1958 Building - Lunch Room and Kitchen**
MATERIAL QUANTITY: **3600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/16/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Mason School** REVIEW DATE: **4/30/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **22**
MATERIAL DESCRIPTION: **12" x 12" Dark Brown Floor Tile**
MATERIAL LOCATION: **1958 Building - Lunch Room and Kitchen**
MATERIAL QUANTITY: **3600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/30/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Mason School** INSPECTION DATE: **4/16/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23**
MATERIAL DESCRIPTION: **Mastic on 12"x12" Dark Brown Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1958 Building - Lunch Room and Kitchen**
MATERIAL QUANTITY: **3600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **04/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Mason School** REVIEW DATE: **4/30/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **23**
MATERIAL DESCRIPTION: **Mastic on 12"x12" Dark Brown Floor Tile**
MATERIAL LOCATION: **1958 Building - Lunch Room and Kitchen**
MATERIAL QUANTITY: **3600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/30/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Mason School** INSPECTION DATE: **4/16/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **24**
MATERIAL DESCRIPTION: **9" x 9" White Floor Tile- Removed**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1958 Building - Rooms 117 & 119**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Mason School** REVIEW DATE: **4/30/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **24**

MATERIAL DESCRIPTION: **9" x 9" White Floor Tile- Removed**

MATERIAL LOCATION: **1958 Building - Rooms 117 & 119**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/30/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Mason School** INSPECTION DATE: **4/16/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25**
MATERIAL DESCRIPTION: **Mastic on 9" x 9" White Floor Tile- Removed**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1958 Building - Rooms 117 & 119**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Mason School** REVIEW DATE: **4/30/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **25**

MATERIAL DESCRIPTION: **Mastic on 9" x 9" White Floor Tile- Removed**

MATERIAL LOCATION: **1958 Building - Rooms 117 & 119**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/30/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Mason School** INSPECTION DATE: **4/16/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26**
MATERIAL DESCRIPTION: **9" x 9" Brown Mix Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1958 Building - Office, and Rooms 121, 220, 223, 320, 317**
MATERIAL QUANTITY: **6200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/16/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Mason School** REVIEW DATE: **4/30/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **26**

MATERIAL DESCRIPTION: **9" x 9" Brown Mix Floor Tile**

MATERIAL LOCATION: **1958 Building - Office, and Rooms 121, 220, 223, 320, 317**

MATERIAL QUANTITY: **6200**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/30/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Mason School** INSPECTION DATE: **4/16/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27**
MATERIAL DESCRIPTION: **Mastic on 9" x 9" Brown Mix Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1958 Building - Office, and Rooms 220, 223, 320, 317**
MATERIAL QUANTITY: **5700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/16/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Mason School** REVIEW DATE: **4/30/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **27**
MATERIAL DESCRIPTION: **Mastic on 9" x 9" Brown Mix Floor Tile**
MATERIAL LOCATION: **1958 Building - Office, and Rooms 220, 223, 320, 317**
MATERIAL QUANTITY: **5700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/30/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Mason School** INSPECTION DATE: **4/16/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28**
MATERIAL DESCRIPTION: **9" x 9" White/Green Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1958 Building - Rooms 119, 123, 131, 225, 325**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/16/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Mason School** REVIEW DATE: **4/30/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **28**

MATERIAL DESCRIPTION: **9" x 9" White/Green Floor Tile**

MATERIAL LOCATION: **1958 Building - Rooms 119, 123, 131, 225, 325**

MATERIAL QUANTITY: **3000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/30/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Mason School** INSPECTION DATE: **4/16/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **29**
MATERIAL DESCRIPTION: **Mastic on 9" x 9" White/Green Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1958 Building - Rooms 119, 123, 131, 225, 325**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/16/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Mason School** REVIEW DATE: **4/30/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **29**

MATERIAL DESCRIPTION: **Mastic on 9" x 9" White/Green Floor Tile**

MATERIAL LOCATION: **1958 Building - Rooms 119, 123, 131, 225, 325**

MATERIAL QUANTITY: **3000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/30/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Mason School** INSPECTION DATE: **4/16/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **30**
MATERIAL DESCRIPTION: **9" x 9" Light Brown Mix Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **4 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **4. Damaged or significantly damaged friable misc. ACBM**

DAMAGE REASON: **Physical Damage**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1958 Building - Rooms 118, 124, 125, 226, 224, 221, 318, 321, 324, 326**
MATERIAL QUANTITY: **12000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **700** DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: **04/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Mason School** REVIEW DATE: **4/30/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **30**
MATERIAL DESCRIPTION: **9" x 9" Light Brown Mix Floor Tile**
MATERIAL LOCATION: **1958 Building - Rooms 118, 124, 125, 226, 224, 221, 318, 321, 324, 326**
MATERIAL QUANTITY: **12000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **700** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/30/2019**

Chicago Public Schools

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUILDING ID: **4650**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Mason School** INSPECTION DATE: **4/16/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **31**
MATERIAL DESCRIPTION: **Mastic on 9" x 9" Light Brown Mix Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1958 Building - Rooms 118,124, 125, 226, 224, 221, 318, 321, 324, 326**
MATERIAL QUANTITY: **12000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/16/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Mason School** REVIEW DATE: **4/30/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **31**
MATERIAL DESCRIPTION: **Mastic on 9" x 9" Light Brown Mix Floor Tile**
MATERIAL LOCATION: **1958 Building - Rooms 118,124, 125, 226, 224, 221, 318, 321, 324, 326**
MATERIAL QUANTITY: **12000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/30/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Mason School** INSPECTION DATE: **4/16/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **32**
MATERIAL DESCRIPTION: **9" x 9" Gray/Red Mix Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1958 Building - Rooms 117, 127, 217, 218, 219, 222, 227, 318, 319, 322, 327**
MATERIAL QUANTITY: **13200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/16/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Mason School** REVIEW DATE: **4/30/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **32**
MATERIAL DESCRIPTION: **9" x 9" Gray/Red Mix Floor Tile**
MATERIAL LOCATION: **1958 Building - Rooms 117, 127, 217, 218, 219, 222, 227, 318, 319, 322, 327**
MATERIAL QUANTITY: **13200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/30/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUILDING ID: **4650**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Mason School** INSPECTION DATE: **4/16/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **33**
MATERIAL DESCRIPTION: **Mastic on 9"x9" Gray/Red Mix Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1958 Building - Rooms 117, 127, 217, 218, 219, 222, 227,318, 319, 322, 327**
MATERIAL QUANTITY: **13200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/16/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Mason School** REVIEW DATE: **4/30/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **33**
MATERIAL DESCRIPTION: **Mastic on 9"x9" Gray/Red Mix Floor Tile**
MATERIAL LOCATION: **1958 Building - Rooms 117, 127, 217, 218, 219, 222, 227,318, 319, 322, 327**
MATERIAL QUANTITY: **13200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/30/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Mason School** INSPECTION DATE: **4/16/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **34 A**
MATERIAL DESCRIPTION: **Orange Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1919 Building - Rooms 101, 103**
MATERIAL QUANTITY: **1050** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/16/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Mason School** REVIEW DATE: **4/30/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **34 A**
MATERIAL DESCRIPTION: **Orange Carpet Mastic**
MATERIAL LOCATION: **1919 Building - Rooms 101, 103**
MATERIAL QUANTITY: **1050** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/30/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Mason School** INSPECTION DATE: **4/16/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **34 B**
MATERIAL DESCRIPTION: **Gray Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1919 Building - Rooms 104 & 111**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/16/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Mason School** REVIEW DATE: **4/30/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **34 B**

MATERIAL DESCRIPTION: **Gray Carpet Mastic**

MATERIAL LOCATION: **1919 Building - Rooms 104 & 111**

MATERIAL QUANTITY: **900**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/30/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Mason School** INSPECTION DATE: **4/16/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **34 C**
MATERIAL DESCRIPTION: **Blue Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1919 Building - Rooms 105 & Office**
MATERIAL QUANTITY: **1120** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/16/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Mason School** REVIEW DATE: **4/30/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **34 C**

MATERIAL DESCRIPTION: **Blue Carpet Mastic**

MATERIAL LOCATION: **1919 Building - Rooms 105 & Office**

MATERIAL QUANTITY: **1120**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/30/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Mason School** INSPECTION DATE: **4/16/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **34 D**
MATERIAL DESCRIPTION: **Brown Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1919 Building - Rooms 113, 114 & 115**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/16/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Mason School** REVIEW DATE: **4/30/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **34 D**
MATERIAL DESCRIPTION: **Brown Carpet Mastic**
MATERIAL LOCATION: **1919 Building - Rooms 113, 114 & 115**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/30/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Mason School** INSPECTION DATE: **4/16/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **34 E**
MATERIAL DESCRIPTION: **Blue Carpet Mastic- Repeat of HS 34 C**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Undefined** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION:

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/16/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Mason School** REVIEW DATE: **4/30/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **34 E**

MATERIAL DESCRIPTION: **Blue Carpet Mastic- Repeat of HS 34 C**

MATERIAL LOCATION:

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/30/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Mason School** INSPECTION DATE: **4/16/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **34 F**
MATERIAL DESCRIPTION: **Green Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1919 Building - North Building Office**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/16/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Mason School** REVIEW DATE: **4/30/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **34 F**
MATERIAL DESCRIPTION: **Green Carpet Mastic**
MATERIAL LOCATION: **1919 Building - North Building Office**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/30/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Mason School** INSPECTION DATE: **4/16/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **34 G**
MATERIAL DESCRIPTION: **Blue Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1958 Building - Rooms 117, 118, & 119**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/16/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Mason School** REVIEW DATE: **4/30/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **34 G**
MATERIAL DESCRIPTION: **Blue Carpet Mastic**
MATERIAL LOCATION: **1958 Building - Rooms 117, 118, & 119**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/30/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Mason School** INSPECTION DATE: **4/16/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **34 H**
MATERIAL DESCRIPTION: **Brown Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1919 Building - Asst. Principal's Office**
MATERIAL QUANTITY: **1120** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/16/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Mason School** REVIEW DATE: **4/30/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **34 H**
MATERIAL DESCRIPTION: **Brown Carpet Mastic**
MATERIAL LOCATION: **1919 Building - Asst. Principal's Office**
MATERIAL QUANTITY: **1120** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/30/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Mason School** INSPECTION DATE: **4/16/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **35**
MATERIAL DESCRIPTION: **Insulation Inside of Vault Door**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1919 Building - Main Office & Room 105 (not observed)**
MATERIAL QUANTITY: **64** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**
COMMENTS: **Not observed 2019**

Inspector's Signature: _____ Date: 04/16/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Mason School** REVIEW DATE: **4/30/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **35**

MATERIAL DESCRIPTION: **Insulation Inside of Vault Door**

MATERIAL LOCATION: **1919 Building - Main Office & Room 105 (not observed)**

MATERIAL QUANTITY: **64**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/30/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Mason School** INSPECTION DATE: **4/16/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **36**
MATERIAL DESCRIPTION: **Boiler Interior**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1919 Building - Boiler Room (not observed)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not observed 2016 - same**

Inspector's Signature: _____ Date: **04/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Mason School** REVIEW DATE: **4/30/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **36**

MATERIAL DESCRIPTION: **Boiler Interior**

MATERIAL LOCATION: **1919 Building - Boiler Room (not observed)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/30/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUILDING ID: **4650**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Mason School** INSPECTION DATE: **4/16/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37**
MATERIAL DESCRIPTION: **Exterior Brick - Non Ahera**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1919 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Mason School** REVIEW DATE: **4/30/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **37**

MATERIAL DESCRIPTION: **Exterior Brick - Non Ahera**

MATERIAL LOCATION: **1919 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/30/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Mason School** INSPECTION DATE: **4/16/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **38**
MATERIAL DESCRIPTION: **Exterior Brick Mortar - Non Ahera**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1919 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Mason School** REVIEW DATE: **4/30/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **38**

MATERIAL DESCRIPTION: **Exterior Brick Mortar - Non Ahera**

MATERIAL LOCATION: **1919 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/30/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUILDING ID: **4650**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Mason School** INSPECTION DATE: **4/16/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **39**
MATERIAL DESCRIPTION: **Exterior Brick - Non Ahera**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1958 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Mason School** REVIEW DATE: **4/30/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **39**

MATERIAL DESCRIPTION: **Exterior Brick - Non Ahera**

MATERIAL LOCATION: **1958 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/30/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Mason School** INSPECTION DATE: **4/16/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **4**
MATERIAL DESCRIPTION: **9" x 9" Tan Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **4 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **4. Damaged or significantly damaged friable misc. ACBM**

DAMAGE REASON: **Physical Damage
Deterioration
Water**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1919 Building - Room 108, Boiler Room, Room 252**
MATERIAL QUANTITY: **1632** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **600** DAMAGE UNITS: **SF**
COMMENTS: **Basement boiler room and room throughout have damaged 9" VFT with soot from flooding**

Inspector's Signature: _____ Date: 04/16/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Mason School** REVIEW DATE: **4/30/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **4**

MATERIAL DESCRIPTION: **9" x 9" Tan Floor Tile**

MATERIAL LOCATION: **1919 Building - Room 108, Boiler Room, Room 252**

MATERIAL QUANTITY: **1632**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **600**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/30/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUILDING ID: **4650**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Mason School** INSPECTION DATE: **4/16/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **40**
MATERIAL DESCRIPTION: **Exterior Brick Mortar - Non Ahera**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1958 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/16/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Mason School** REVIEW DATE: **4/30/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **40**

MATERIAL DESCRIPTION: **Exterior Brick Mortar - Non Ahera**

MATERIAL LOCATION: **1958 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/30/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Mason School** INSPECTION DATE: **4/16/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **41**
MATERIAL DESCRIPTION: **Incinerator Components**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Boiler Room**
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/16/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Mason School** REVIEW DATE: **4/30/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **41**

MATERIAL DESCRIPTION: **Incinerator Components**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: **250**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/30/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Mason School** INSPECTION DATE: **4/16/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **42**
MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 307**
MATERIAL QUANTITY: **495** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/16/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Mason School** REVIEW DATE: **4/30/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **42**

MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile**

MATERIAL LOCATION: **Room 307**

MATERIAL QUANTITY: **495**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/30/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Mason School** INSPECTION DATE: **4/16/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **43**
MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 307**
MATERIAL QUANTITY: **495** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/16/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Mason School** REVIEW DATE: **4/30/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **43**

MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile Mastic**

MATERIAL LOCATION: **Room 307**

MATERIAL QUANTITY: **495**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/30/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Mason School** INSPECTION DATE: **4/16/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **44**
MATERIAL DESCRIPTION: **12"x12" White Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 307**
MATERIAL QUANTITY: **495** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/16/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Mason School** REVIEW DATE: **4/30/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **44**

MATERIAL DESCRIPTION: **12"x12" White Floor Tile**

MATERIAL LOCATION: **Room 307**

MATERIAL QUANTITY: **495**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/30/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Mason School** INSPECTION DATE: **4/16/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **45**
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 307**
MATERIAL QUANTITY: **495** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/16/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Mason School** REVIEW DATE: **4/30/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **45**

MATERIAL DESCRIPTION: **12" x 12" White Floor Tile Mastic**

MATERIAL LOCATION: **Room 307**

MATERIAL QUANTITY: **495**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/30/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Mason School** INSPECTION DATE: **4/16/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **46**
MATERIAL DESCRIPTION: **4" Black Vinyl Baseboard**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout 1958 Building**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 04/16/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Mason School** REVIEW DATE: **4/30/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **46**

MATERIAL DESCRIPTION: **4" Black Vinyl Baseboard**

MATERIAL LOCATION: **Throughout 1958 Building**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/30/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Mason School** INSPECTION DATE: **4/16/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **47**
MATERIAL DESCRIPTION: **4" Black Vinyl Baseboard Mastic**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout 1958 Building**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 04/16/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Mason School** REVIEW DATE: **4/30/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **47**

MATERIAL DESCRIPTION: **4" Black Vinyl Baseboard Mastic**

MATERIAL LOCATION: **Throughout 1958 Building**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/30/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Mason School** INSPECTION DATE: **4/16/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **48**
MATERIAL DESCRIPTION: **12" x 12" Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY **4 Damaged or significantly damaged friable misc. ACBM**
HISTORICAL DAMAGE REASON: **Water**
HISTORICAL RESPONSE ACTION: **Repair**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **4. Damaged or significantly damaged friable misc. ACBM**

DAMAGE REASON: **Water**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **North Building Corridors**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **100** DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: **04/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Mason School** REVIEW DATE: **4/30/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **48**
MATERIAL DESCRIPTION: **12" x 12" Ceiling Tile**
MATERIAL LOCATION: **North Building Corridors**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **100** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Management Planner's Signature: _____ Date: **04/30/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Mason School** INSPECTION DATE: **4/16/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **49**
MATERIAL DESCRIPTION: **12" x 12" Ceiling Tile Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **North Building Corridors**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/16/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Mason School** REVIEW DATE: **4/30/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **49**
MATERIAL DESCRIPTION: **12" x 12" Ceiling Tile Adhesive**
MATERIAL LOCATION: **North Building Corridors**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/30/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Mason School** INSPECTION DATE: **4/16/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **5**
MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile w/White Specks**
HISTORICAL AHERA DAMAGE CATEGORY **4 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **4. Damaged or significantly damaged friable misc. ACBM**

DAMAGE REASON: **Physical Damage
Deterioration**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1919 Building - Rooms 106 (Engineer's Office) & 2nd Floor Teacher's Washroom**
MATERIAL QUANTITY: **2040** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **100** DAMAGE UNITS: **SF**
COMMENTS: **Damage is located in engineer's office**

Inspector's Signature: _____ Date: 04/16/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Mason School** REVIEW DATE: **4/30/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **5**
MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile w/White Specks**
MATERIAL LOCATION: **1919 Building - Rooms 106 (Engineer's Office) & 2nd Floor Teacher's Washroom**
MATERIAL QUANTITY: **2040** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **100** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Remove and replace the Ceiling Tile located in the engineer's office

Management Planner's Signature: _____ Date: **04/30/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Mason School** INSPECTION DATE: **4/16/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **50**
MATERIAL DESCRIPTION: **12" x 12" Light Purple Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 116 and 119 (not observed)**
MATERIAL QUANTITY: **1700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**
COMMENTS: **Not observed 2019**

Inspector's Signature: _____ Date: 04/16/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Mason School** REVIEW DATE: **4/30/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **50**
MATERIAL DESCRIPTION: **12" x 12" Light Purple Floor Tile**
MATERIAL LOCATION: **Rooms 116 and 119 (not observed)**
MATERIAL QUANTITY: **1700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/30/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Mason School** INSPECTION DATE: **4/16/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **51**
MATERIAL DESCRIPTION: **12" x 12" Light Purple Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 116 and 119 (not observed)**
MATERIAL QUANTITY: **1700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**
COMMENTS: **Not observed 2019**

Inspector's Signature: _____ Date: 04/16/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Mason School** REVIEW DATE: **4/30/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **51**
MATERIAL DESCRIPTION: **12" x 12" Light Purple Floor Tile Mastic**
MATERIAL LOCATION: **Rooms 116 and 119 (not observed)**
MATERIAL QUANTITY: **1700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/30/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Mason School** INSPECTION DATE: **4/16/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **52**
MATERIAL DESCRIPTION: **9" x 9" White Floor Tile (patching)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Actinolite** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 228, 126 (not observed)**
MATERIAL QUANTITY: **71** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**
COMMENTS: **Not observed 2019**

Inspector's Signature: _____ Date: 04/16/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Mason School** REVIEW DATE: **4/30/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **52**

MATERIAL DESCRIPTION: **9" x 9" White Floor Tile (patching)**

MATERIAL LOCATION: **Rooms 228, 126 (not observed)**

MATERIAL QUANTITY: **71**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/30/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Mason School** INSPECTION DATE: **4/16/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **53**
MATERIAL DESCRIPTION: **9" x 9" White Floor Tile Mastic (patching)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 228, 126 (not observed)**
MATERIAL QUANTITY: **71** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**
COMMENTS: **Not observed 2019**

Inspector's Signature: _____ Date: 04/16/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Mason School** REVIEW DATE: **4/30/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **53**

MATERIAL DESCRIPTION: **9" x 9" White Floor Tile Mastic (patching)**

MATERIAL LOCATION: **Rooms 228, 126 (not observed)**

MATERIAL QUANTITY: **71**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/30/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Mason School** INSPECTION DATE: **4/16/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **54**
MATERIAL DESCRIPTION: **Beige w/ Red Pattern Linoleum Flooring**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **2nd Floor North Stairwell Washroom (not observed)**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**
COMMENTS: **Not observed 2019**

Inspector's Signature: _____ Date: 04/16/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Mason School** REVIEW DATE: **4/30/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **54**

MATERIAL DESCRIPTION: **Beige w/ Red Pattern Linoleum Flooring**

MATERIAL LOCATION: **2nd Floor North Stairwell Washroom (not observed)**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/30/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Mason School** INSPECTION DATE: **4/16/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **55**
MATERIAL DESCRIPTION: **Beige w/Red Pattern Linoleum Flooring Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **2nd Floor North Stairwell Washroom (not observed)**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**
COMMENTS: **Not observed 2019**

Inspector's Signature: _____ Date: **04/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Mason School** REVIEW DATE: **4/30/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **55**
MATERIAL DESCRIPTION: **Beige w/Red Pattern Linoleum Flooring Adhesive**
MATERIAL LOCATION: **2nd Floor North Stairwell Washroom (not observed)**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/30/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Mason School** INSPECTION DATE: **4/16/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **56**
MATERIAL DESCRIPTION: **12" x 12" Lt. Blue w/Blue & Gray Specks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1919 Building - 2nd & 3rd Floor Corridors**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/16/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Mason School** REVIEW DATE: **4/30/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **56**
MATERIAL DESCRIPTION: **12" x 12" Lt. Blue w/Blue & Gray Specks Floor Tile**
MATERIAL LOCATION: **1919 Building - 2nd & 3rd Floor Corridors**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/30/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Mason School** INSPECTION DATE: **4/16/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **57**
MATERIAL DESCRIPTION: **12" x 12" Lt. Blue w/Blue & Gray Specks FT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1919 Building - 2nd & 3rd Floor Corridors**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/16/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Mason School** REVIEW DATE: **4/30/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **57**
MATERIAL DESCRIPTION: **12" x 12" Lt. Blue w/Blue & Gray Specks FT Mastic**
MATERIAL LOCATION: **1919 Building - 2nd & 3rd Floor Corridors**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/30/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Mason School** INSPECTION DATE: **4/16/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **58**
MATERIAL DESCRIPTION: **12" X 12" White Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1919 Bldg 2nd and 3rd Floor Corridors**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/16/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Mason School** REVIEW DATE: **4/30/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **58**
MATERIAL DESCRIPTION: **12" X 12" White Floor Tile**
MATERIAL LOCATION: **1919 Bldg 2nd and 3rd Floor Corridors**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/30/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Mason School** INSPECTION DATE: **4/16/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **59**
MATERIAL DESCRIPTION: **12" X 12" White Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1919 Bldg 2nd and 3rd Floor Corridors**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/16/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Mason School** REVIEW DATE: **4/30/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **59**
MATERIAL DESCRIPTION: **12" X 12" White Floor Tile Mastic**
MATERIAL LOCATION: **1919 Bldg 2nd and 3rd Floor Corridors**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/30/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Mason School** INSPECTION DATE: **4/16/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **6**
MATERIAL DESCRIPTION: **Plaster (Sampled in 1983 & 1992)**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1919 Building**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/16/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Mason School** REVIEW DATE: **4/30/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **6**
MATERIAL DESCRIPTION: **Plaster (Sampled in 1983 & 1992)**
MATERIAL LOCATION: **1919 Building**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/30/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Mason School** INSPECTION DATE: **4/16/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **60**
MATERIAL DESCRIPTION: **12" X 12" White Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1958 Bldg Rooms 117, 119 and 121 (not observed)**
MATERIAL QUANTITY: **2250** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/16/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Mason School** REVIEW DATE: **4/30/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **60**

MATERIAL DESCRIPTION: **12" X 12" White Floor Tile**

MATERIAL LOCATION: **1958 Bldg Rooms 117, 119 and 121 (not observed)**

MATERIAL QUANTITY: **2250**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/30/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Mason School** INSPECTION DATE: **4/16/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **61**
MATERIAL DESCRIPTION: **12" X 12" White Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1958 Bldg Rooms 117, 119 and 121 (not observed)**
MATERIAL QUANTITY: **2250** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/16/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Mason School** REVIEW DATE: **4/30/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **61**
MATERIAL DESCRIPTION: **12" X 12" White Floor Tile Mastic**
MATERIAL LOCATION: **1958 Bldg Rooms 117, 119 and 121 (not observed)**
MATERIAL QUANTITY: **2250** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/30/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Mason School** INSPECTION DATE: **4/16/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **62**
MATERIAL DESCRIPTION: **9" X 9" Lt Gray Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1958 Bldg Room 117 closet (not observed)**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/16/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Mason School** REVIEW DATE: **4/30/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **62**

MATERIAL DESCRIPTION: **9" X 9" Lt Gray Floor Tile**

MATERIAL LOCATION: **1958 Bldg Room 117 closet (not observed)**

MATERIAL QUANTITY: **50**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/30/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Mason School** INSPECTION DATE: **4/16/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **63**
MATERIAL DESCRIPTION: **9" X 9" Lt Gray Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1958 Bldg Room 117 closet (not observed)**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/16/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Mason School** REVIEW DATE: **4/30/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **63**

MATERIAL DESCRIPTION: **9" X 9" Lt Gray Floor Tile Mastic**

MATERIAL LOCATION: **1958 Bldg Room 117 closet (not observed)**

MATERIAL QUANTITY: **50**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/30/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Mason School** INSPECTION DATE: **4/16/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **64**
MATERIAL DESCRIPTION: **9" X 9" Dark Brown Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 119 Closet and 121 Store Room (not observed)**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/16/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Mason School** REVIEW DATE: **4/30/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **64**
MATERIAL DESCRIPTION: **9" X 9" Dark Brown Floor Tile**
MATERIAL LOCATION: **Room 119 Closet and 121 Store Room (not observed)**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/30/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Mason School** INSPECTION DATE: **4/16/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **65**
MATERIAL DESCRIPTION: **9" X 9" Dark Brown Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 119 Closet and Room 121 Store Room (not observed)**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/16/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Mason School** REVIEW DATE: **4/30/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **65**
MATERIAL DESCRIPTION: **9" X 9" Dark Brown Floor Tile Mastic**
MATERIAL LOCATION: **Room 119 Closet and Room 121 Store Room (not observed)**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/30/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Mason School** INSPECTION DATE: **4/16/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **66**
MATERIAL DESCRIPTION: **12" X 12" Lt Purple Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 116 and 119 (not observed)**
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/16/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Mason School** REVIEW DATE: **4/30/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **66**
MATERIAL DESCRIPTION: **12" X 12" Lt Purple Floor Tile**
MATERIAL LOCATION: **Rooms 116 and 119 (not observed)**
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/30/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Mason School** INSPECTION DATE: **4/16/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **67**
MATERIAL DESCRIPTION: **12" X 12" Lt Purple Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 116 and 119 (not observed)**
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/16/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Mason School** REVIEW DATE: **4/30/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **67**
MATERIAL DESCRIPTION: **12" X 12" Lt Purple Floor Tile Mastic**
MATERIAL LOCATION: **Rooms 116 and 119 (not observed)**
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/30/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Mason School** INSPECTION DATE: **4/16/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **68**
MATERIAL DESCRIPTION: **12" X 12" White Floor Tile (Patching)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 106 Engineer's Office**
MATERIAL QUANTITY: **14** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/16/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Mason School** REVIEW DATE: **4/30/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **68**

MATERIAL DESCRIPTION: **12" X 12" White Floor Tile (Patching)**

MATERIAL LOCATION: **Room 106 Engineer's Office**

MATERIAL QUANTITY: **14**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/30/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Mason School** INSPECTION DATE: **4/16/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **69**
MATERIAL DESCRIPTION: **12" X 12" White Floor Tile Mastic (Patching)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 106 Engineer's Office**
MATERIAL QUANTITY: **14** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **04/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Mason School** REVIEW DATE: **4/30/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **69**

MATERIAL DESCRIPTION: **12" X 12" White Floor Tile Mastic (Patching)**

MATERIAL LOCATION: **Room 106 Engineer's Office**

MATERIAL QUANTITY: **14**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/30/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Mason School** INSPECTION DATE: **4/16/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **7**
MATERIAL DESCRIPTION: **Plaster (Sampled in 1983 & 1992)**
HISTORICAL AHERA DAMAGE CATEGORY **4 Any remaining friable ACM or friable suspect ACM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **4. Damaged or significantly damaged friable misc. ACM**

DAMAGE REASON: **Water**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1958 Building**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **1000** DAMAGE UNITS: **SF**
COMMENTS: **Room 257**

Inspector's Signature: _____ Date: 04/16/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Mason School** REVIEW DATE: **4/30/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **7**

MATERIAL DESCRIPTION: **Plaster (Sampled in 1983 & 1992)**

MATERIAL LOCATION: **1958 Building**

MATERIAL QUANTITY: **10000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **1000**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/30/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Mason School** INSPECTION DATE: **4/16/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **70**
MATERIAL DESCRIPTION: **Blue-White Ceramic Wall Grout**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Entry of School and 4 columns**

MATERIAL QUANTITY: **600**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 04/16/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Mason School** REVIEW DATE: **4/30/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **70**
MATERIAL DESCRIPTION: **Blue-White Ceramic Wall Grout**
MATERIAL LOCATION: **Entry of School and 4 columns**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/30/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Mason School** INSPECTION DATE: **4/16/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **70M**
MATERIAL DESCRIPTION: **Blue-White Ceramic Wall Grout Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Entry of School and 4 Columns**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/16/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Mason School** REVIEW DATE: **4/30/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **70M**
MATERIAL DESCRIPTION: **Blue-White Ceramic Wall Grout Adhesive**
MATERIAL LOCATION: **Entry of School and 4 Columns**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/30/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Mason School** INSPECTION DATE: **4/16/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **71**
MATERIAL DESCRIPTION: **Green and Black Terrazzo**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st, 2nd and 3rd Floor Stairwells and Landings**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/16/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Mason School** REVIEW DATE: **4/30/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **71**

MATERIAL DESCRIPTION: **Green and Black Terrazzo**

MATERIAL LOCATION: **1st, 2nd and 3rd Floor Stairwells and Landings**

MATERIAL QUANTITY: **1500**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/30/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Mason School** INSPECTION DATE: **4/16/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **72**
MATERIAL DESCRIPTION: **Brown Carpet Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 129 (not observed)**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**
COMMENTS: **Not observed 2019**

Inspector's Signature: _____ Date: 04/16/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Mason School** REVIEW DATE: **4/30/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **72**
MATERIAL DESCRIPTION: **Brown Carpet Adhesive**
MATERIAL LOCATION: **Room 129 (not observed)**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/30/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Mason School** INSPECTION DATE: **4/16/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **73**
MATERIAL DESCRIPTION: **Brown Ceramic Tile Grout**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st, 2nd and 3rd Floor Boy's and Girl's Toilet**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/16/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Mason School** REVIEW DATE: **4/30/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **73**
MATERIAL DESCRIPTION: **Brown Ceramic Tile Grout**
MATERIAL LOCATION: **1st, 2nd and 3rd Floor Boy's and Girl's Toilet**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/30/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Mason School** INSPECTION DATE: **4/16/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **73M**
MATERIAL DESCRIPTION: **Brown Ceramic Tile Grout Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st, 2nd, and 3rd Floor Boy's and Girl's Toilet**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/16/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Mason School** REVIEW DATE: **4/30/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **73M**
MATERIAL DESCRIPTION: **Brown Ceramic Tile Grout Adhesive**
MATERIAL LOCATION: **1st, 2nd, and 3rd Floor Boy's and Girl's Toilet**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/30/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Mason School** INSPECTION DATE: **4/16/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **74**
MATERIAL DESCRIPTION: **12"x12" White w/Brown Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 206**
MATERIAL QUANTITY: **1125** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**
COMMENTS: **Not observed 2019**

Inspector's Signature: _____ Date: 04/16/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Mason School** REVIEW DATE: **4/30/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **74**

MATERIAL DESCRIPTION: **12"x12" White w/Brown Floor Tile**

MATERIAL LOCATION: **Room 206**

MATERIAL QUANTITY: **1125**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/30/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Mason School** INSPECTION DATE: **4/16/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **74M**
MATERIAL DESCRIPTION: **12"x12" White w/Brown Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Anthophyllite** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 206**
MATERIAL QUANTITY: **1125** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**
COMMENTS: **Not observed 2019**

Inspector's Signature: _____ Date: 04/16/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Mason School** REVIEW DATE: **4/30/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **74M**
MATERIAL DESCRIPTION: **12"x12" White w/Brown Floor Tile Mastic**
MATERIAL LOCATION: **Room 206**
MATERIAL QUANTITY: **1125** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/30/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Mason School** INSPECTION DATE: **4/16/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **8**
MATERIAL DESCRIPTION: **Mastic on 9"x9" Tan Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1919 Building - Room 108**
MATERIAL QUANTITY: **832** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/16/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Mason School** REVIEW DATE: **4/30/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **8**

MATERIAL DESCRIPTION: **Mastic on 9"x9" Tan Floor Tile**

MATERIAL LOCATION: **1919 Building - Room 108**

MATERIAL QUANTITY: **832**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/30/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Mason School** INSPECTION DATE: **4/16/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **9**
MATERIAL DESCRIPTION: **9"x 9" Green Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1958 Building - Men's Lounge, Rooms 119, S.R., 123, 131, 225, 2nd & 3rd Floor Corridors , 217, 325**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/16/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Mason School** REVIEW DATE: **4/30/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **9**
MATERIAL DESCRIPTION: **9"x 9" Green Floor Tile Mastic**
MATERIAL LOCATION: **1958 Building - Men's Lounge, Rooms 119, S.R., 123, 131, 225, 2nd & 3rd Floor Corridors , 217, 325**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/30/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Mason School** INSPECTION DATE: **4/16/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **A-B**
MATERIAL DESCRIPTION: **Numbers Skipped**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Undefined** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION:

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/16/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Mason School** REVIEW DATE: **4/30/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **A-B**

MATERIAL DESCRIPTION: **Numbers Skipped**

MATERIAL LOCATION:

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/30/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Mason School** INSPECTION DATE: **4/16/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **C**
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Possibly In Inaccessible Areas Throughout Facility**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not observed 2016 - same 2019**

Inspector's Signature: _____ Date: **04/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Mason School** REVIEW DATE: **4/30/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **C**

MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**

MATERIAL LOCATION: **Possibly In Inaccessible Areas Throughout Facility**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/30/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Mason School** INSPECTION DATE: **4/16/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **D**
MATERIAL DESCRIPTION: **Hard Joint Compound on Cardboard Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Possibly In Inaccessible Areas Throughout Facility**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not observed 2016 - same 2019**

Inspector's Signature: _____ Date: **04/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Mason School** REVIEW DATE: **4/30/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **D**

MATERIAL DESCRIPTION: **Hard Joint Compound on Cardboard Pipe Insulation**

MATERIAL LOCATION: **Possibly In Inaccessible Areas Throughout Facility**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/30/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Mason School** INSPECTION DATE: **4/16/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **E**
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Possibly In Inaccessible Areas Throughout Facility**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not observed 2016 - same 2019**

Inspector's Signature: _____ Date: **04/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Mason School** REVIEW DATE: **4/30/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **E**

MATERIAL DESCRIPTION: **Aircell Pipe Insulation**

MATERIAL LOCATION: **Possibly In Inaccessible Areas Throughout Facility**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/30/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Mason School** INSPECTION DATE: **4/16/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **F**
MATERIAL DESCRIPTION: **Hard Joint Compound on Aircell Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Possibly In Inaccessible Areas Throughout Facility**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **JC Cafe**

Inspector's Signature: _____ Date: 04/16/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Mason School** REVIEW DATE: **4/30/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **F**

MATERIAL DESCRIPTION: **Hard Joint Compound on Aircell Pipe Insulation**

MATERIAL LOCATION: **Possibly In Inaccessible Areas Throughout Facility**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/30/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Mason School** INSPECTION DATE: **4/16/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **G**
MATERIAL DESCRIPTION: **Tank Insulation (abated between 1995-1998)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____

Date: 04/16/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Mason School** REVIEW DATE: **4/30/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **G**

MATERIAL DESCRIPTION: **Tank Insulation (abated between 1995-1998)**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/30/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Mason School** INSPECTION DATE: **4/16/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **H**
MATERIAL DESCRIPTION: **Boiler Breeching (Abated between 1995- 1998)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Mason School** REVIEW DATE: **4/30/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **H**

MATERIAL DESCRIPTION: **Boiler Breaching (Abated between 1995- 1998)**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/30/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Mason School** INSPECTION DATE: **4/16/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **I**
MATERIAL DESCRIPTION: **Transite Pipe**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1919 Building - Boiler Room (not observed)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not observed 2016 - same 2019**

Inspector's Signature: _____ Date: **04/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUIDLING ID: **4650**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Mason School** REVIEW DATE: **4/30/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **I**

MATERIAL DESCRIPTION: **Transite Pipe**

MATERIAL LOCATION: **1919 Building - Boiler Room (not observed)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/30/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUILDING ID: **4650**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**
SCHOOL NAME: **Mason School** INSPECTION DATE: **4/16/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **J**

MATERIAL DESCRIPTION: **Hard joint compound on fiberglass**

MATERIAL LOCATION: **janitor's closet adjacent to lunchroom on 1st floor**

MATERIAL QUANTITY: **10** MATERIAL UNITS: **SF**

MATERIAL CATEGORY: **TSI** FRIABLE:

ASBESTOS TYPE: **Assumed**

DISTURBANCE POTENTIAL: **MODERATE** CONDITION:

AHERA DAMAGE CATEGORY: **1 Damaged or significantly damaged friable thermal system insulating ACBM**

ACCESSIBILITY: **Barely Reachable** DAMAGE REASON:
DAMAGE REASON:
DAMAGE REASON:

DAMAGE QUANTITY: **10** DAMAGE UNITS: **SF**

COMMENTS:
Hard joint on FG, JC near lunchroom 1st floor

Inspector's Signature: _____ Date: **04/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24381** BUILDING ID: **4650**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Mason School** REVIEW DATE: **4/30/2019**
ADDRESS: **4217 W. 18th St.** IDPH LICENSE NO: **100-09969**

HOMOGENEOUS AREA: **J**
MATERIAL DESCRIPTION: **Hard joint compound on fiberglass**
MATERIAL LOCATION: **janitor's closet adjacent to lunchroom on 1st floor**
MATERIAL QUANTITY: **10** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **10** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **04/30/2019**

APPENDIX B

Inspector and Management Planner Licenses



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • www.dph.illinois.gov

4/18/2016

DIONNE L CAREY WALKER

211 Somerset Drive
Streamwood, IL 60107

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 09969

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

ASBESTOS PROFESSIONAL LICENSE			ENDORSEMENTS	TC EXPIRES
	ID NUMBER 100 - 09969	ISSUED 4/18/2016	INSPECTOR	3/11/2017
DIONNE L CAREY WALKER 211 Somerset Drive Streamwood, IL 60107 Environmental Health	EXPIRES 05/15/2017		PROJECT MANAGER AIR SAMPLING PROFESSIONAL	3/12/2017
Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.				

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH, IMPROVING LIVES
Nationally Accredited by PHAB


has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Course Date: 1/4/2019

Exam Date: 1/4/2019

Expiration Date: 1/4/2020

Certificate Number: BIR1901040041


Kathy Desalvo, Director

Occupational Training & Supply, Inc. certifies that
Dionne L.C. Walker

Asbestos Building Inspector Refresher


OCCUPATIONAL TRAINING & SUPPLY, INC.
7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900 ♦ www.otsafety.com




2019



525-535 West Jefferson Street • Springfield, Illinois 62761

DIONNE L CAREY WALKER
211 SOMERSET DRIVE
STREAMWOOD, IL 60107

1/18/2019



ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 09969

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

 <p>ASBESTOS PROFESSIONAL LICENSE</p>			<p>ENDORSEMENTS</p>		<p>TC EXPIRES</p>
<p>ID NUMBER 100 - 09969</p>	<p>ISSUED 1/18/2019</p>	<p>EXPIRES 05/15/2020</p>	<p>INSPECTOR</p>		<p>1/4/2020</p>
<p>DIONNE L CAREY WALKER 211 SOMERSET DRIVE STREAMWOOD, IL 60107 Environmental Health</p> 			<p>PROJECT MANAGER AIR SAMPLING PROFESSIONAL</p>		<p>1/5/2020</p>
<p>Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.</p>					

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH, IMPROVING LIVES
Nationally Accredited by PHAB

JAINA ASSOCIATES

THIS IS TO CERTIFY
THAT

DIONNE L. CAREY

HAS SUCCESSFULLY COMPLETED THE SAMPLING AND EVALUATING ASBESTOS AIRBORNE
DUST - NIOSH 582 EQUIVALENT TRAINING COURSE, AND PASSED THE EXAMINATION WITH
A SCORE OF 70% OR ABOVE FOR THE PURPOSE OF CERTIFICATION.

COURSE DATE: May 14 to 17, 2005

EXAM DATE: May 17, 2005

LOCATION: GSG Environmental, Inc.
855 West Adams Street, Suite 200
Chicago, Illinois 60607

DIRECTOR
OF TRAINING:


SANJIV JAIN

CERTIFICATE No.: 05JA-051405
IDPH COURSE PROVIDER No.: 038

2015



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Evan Christian

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 12/2/2015

Exam Date: 12/2/2015

Expiration Date: 12/2/2016

Certificate Number: BIR1512024159


Katy DeSalvo, Director

Reliable
Environmental
Solutions, Inc. **RES**

This is to certify that **Evan Christian**

*has on January 28 & 29, 2016, in Springfield, Illinois,
completed the requirements for asbestos accreditation under Section 206 of TSCA Title II*

Asbestos Management Planner Initial Training

*as accredited by the State of Illinois and approved by the U.S.E.P.A. under 40 CFR 763 (AHERA)
and passed the associated examination with a score of 70% or higher*

Course Date: January 28 & 29, 2016

Examination Date: January 29, 2016

Expiration Date: January 29, 2017

Certificate Number: MP/0103

William S. Williams

Training Program Manager, William S. Williams

4211 Westgate Drive, Springfield, Illinois ☐ 217.787.9800 ☐ 217.787.9801 FAX ☐ www.ReliableEnv.com

2019



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900 ♦ www.otssafety.com

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that
Evan Christian

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/19/2019

Exam Date: 11/19/2019

Expiration Date: 11/19/2020

Certificate Number: BIR1911192384


Kathy DeSalvo, Director



**ASBESTOS
PROFESSIONAL
LICENSE**

ID NUMBER
100 - 19466

ISSUED
4/12/2019

EXPIRES
05/15/2020

EVAN I CHRISTIAN
3024 N RACINE AVE, APT 2
CHICAGO, IL 60657

Environmental Health



ENDORSEMENTS

TC EXPIRES

INSPECTOR

11/28/2019

MANAGEMENT PLANNER

1/5/2019

PROJECT MANAGER

2/5/2020

AIR SAMPLING PROFESSIONAL

Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois
Department of Public Health

This license is valid only when accompanied by a valid
training course certificate.

2019



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900 ♦ www.otssafety.com

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Evan Christian

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Course Date: 1/7/2019

Exam Date: 1/7/2019


Expiration Date: 1/7/2020

Certificate Number: MPR1901070063


Kathy DeSalvo, Director

Evan Christian

Illinois Licensed Project Manager, and Air Sampling Professional



ENDORSEMENTS	TC EXPIRES
PROJECT MANAGER AIR SAMPLING PROFESSIONAL	12/12/2015
Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	

**CARNOW
CONIBEAR**

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL		
	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE		
	Loc	Localized
	Dist	Distributed